

Chevron U.S.A. Inc.

2410 Camino Ramon, San Ramon, California • Phone (415) 842-9500 Mail Address PO Box 5004, San Ramon, CA 94583-0804

91 MAY 31 Will: 23

Marketing Operations

R B Beilinger Manager, Operations S L Patterson Area, Manager, Operations C G Trimbach Manager, Engineering

May 29, 1991

Mr. Gil Wister Xuman Alameda County
Environmental Health
80 Swan Way, Room 200
Oakland, California 94621

Re: Chevron Service Station #9-1583 5509 Martin Luther King Way Oakland, CA 94609

Dear Mr. Wister:

Enclosed we are forwarding the results of the Quarterly Ground-water Sampling performed by our consultant Geraghty & Miller, Inc. dated May 20, 1991, for the above referenced site. As indicated in the report, groundwater samples collected were analyzed for total petroleum hydrocarbons as gasoline (TPH-G) and BTEX. Benzene concentrations were detected in monitor wells #1, #2, and #3 at 200, 5, and 2100 ppb, respectively. These concentrations are significantly lower than the previous concentrations reported last quarter. Depth to water is approximately 9 to 13 feet, and the direction of flow is to the west-northwest.

Chevron will sample this site two (2) additional quarters. At this time we will evaluate the data to assess if the on-site wells have been purged of any surface contamination that may have infiltrated into the wells prior to the well head replacement. At that time we will recommend appropriate next actions.

If you have any questions or comments please do not hesitate to contact me at (415) 842-9581.

Very truly yours, CHEVRON U.S.A. INCA-

I a /M

Nancy Vukelich

Environmental Engineer

Enclosure

CC: Mr. Rich Hiett, RWQCB-Bay Area
Mr. W.T. Scudder
File (#9-1583Q3 Listing)



Ground Water

Engineering

Hydrocarbon

Remediation

Education

May 20, 1991 Project No. RC02604

Ms. Nancy Vukelich Chevron U.S.A., Inc. West Central Marketing 2410 Camino Ramon San Ramon, California 94583-0804

SUBJECT: Quarterly Ground-Water Sampling Results, May 1991, Service Station #9-

1583, 5509 Martin Luther King Jr., Way, Oakland, California.

Dear Ms. Vukelich:

This letter presents the quarterly ground-water sampling results for the Chevron U.S.A. Inc. (Chevron) service station referenced above (see Figure 1). The scope of work for this project was presented to Chevron in a previous letter from Geraghty & Miller, Inc. (Geraghty & Miller) dated January 11, 1991.

#### FIELD AND LABORATORY PROCEDURES

The quarterly ground-water sampling was performed on May 8, 1991. Water samples were collected from each of the seven existing monitor wells (Monitor Wells #1 through #3, MW-4, MW-5, and MW-6). Prior to sampling, depth-to-water and total well depth measurements were obtained and each well was checked for the presence of liquid-phase hydrocarbons. Liquid-phase hydrocarbons were not observed during the quarterly sampling. A minimum of three casing volumes of water was purged from each well prior to sampling using a surface diaphragm pump. All equipment that entered the well was washed in a solution of tri-sodium phosphate (TSP) and water then triple rinsed in deionized water prior to sampling each well. Purged water was monitored for pH, temperature, and specific conductance. The field sampling results are presented in Table 1. Following purging, ground-water samples were collected using a polyethylene disposable bailer. A new bailer was used for each well. The purged water was stored in 55-gallon drums and retained on-site for subsequent disposal by Chevron.

Ground-water samples for laboratory analysis were placed in the appropriate USEPA approved containers, placed on ice, and transported to Superior Analytical Laboratories, Inc., located in Martinez, California. One trip blank consisting of laboratory grade water which accompanied the sample bottles from the laboratory, into the field, and back to the laboratory was also analyzed. The water samples were analyzed for total petroleum hydrocarbons (TPH) as gasoline (USEPA Method 8015, modified) and benzene, toluene, ethylbenzene, and xylenes (BTEX) (USEPA Method 8020).

## RESULTS OF QUARTERLY SAMPLING

#### **DEPTH TO WATER**

A summary of the depth-to-water measurements is presented in Table 2. A ground-water contour map is presented in Figure 2. Based on the data collected during May 1991, the direction of shallow ground-water flow in the vicinity of the site is toward the west-northwest.

#### GROUND-WATER ANALYTICAL RESULTS

A summary of the ground-water analytical results is presented in Table 3. Copies of the certified laboratory reports and chain-of-custody documentation are included in Attachment 1.

If you have any questions regarding this letter report, please do not hesitate to call.

Sincerely,

GERAGHTY & MILLER, INC.

freyw. Hawkins

Jeffrey W. Hawkins, R.G.

Senior Geologist

Gary W. Keyes, P.E.

Principal Engineer/Associate

Attachments

Table 1 Summary of Field Sampling Data

Table 2 Summary of Depth-to-Water and Water Elevation Data

Table 3 Ground-Water Analytical Results

Figure 1 Site Location Map

Figure 2 Ground-Water Contour Map, May 1991

Attachment 1 Copies of Certified Analytical Reports and Chain of

Custody Documentation

Table 1 - Summary of Field Sampling Data Chevron Service Station #9-1583, Oakland, California

Well	Date	Calculated Purge Volume (B) (gallons)	Actual Purge Volume (gallons)	рН	Stabilized SC (ms/cm)	Temperature (F)	Depth to Water (A) (feet)	Measured Depth of Well (A) (feet)	Casing Diamete (inches
AAGII	Date	(gallons)	(galions)	<del>P</del> II	(ms/cm)	(1)	(1861)	(leet)	(IIICH <del>O</del> S
Well #1	12-Mar-90	10.83	13	6.61	62	73.4	10.08	19.13	3
	8-Feb-91	11.00	19	6.35	69	65	10.11	19.30	
	8-May-91	10.77	10.5	6.32	6330	63.5	10.45	19.45	
Well #2	12-Mar-90	9.58	13	6.28	51	74.4	11.02	19.02	3
	8-Feb-91	9.53	15	6.70	61	67	11.05	19.01	
	8-May-91	9.59	10	6.79	4790	66.6	11.36	19.37	
Well #3	12-Mar-90	8.45	13	6.48	75	75.6	12.14	19.20	3
	8-Feb-91	9.13	23	6.70	88	67	12,18	19.81	
	8-May-91	8.77	9	6.53	6400	64.8	12.52	19.85	
MW-4	31-Oct-90	5.81	3 (C)	8.10	93	78	13.90	24.82	2
	8-Feb-91	6.69	9	7.90	59	65	12.32	24.90	
	8-May-91	6.90	6.5	6.63	5570	68.8	12.23	25.20	
MW-5	31-Oct-90	4.87	16	7.20	35	81	10.63	19.79	2
	8-Feb-91	5.69	10	6.90	46	64	9.17	19.87	
	8-May-91	6.08	7	7.21	3990	63.2	8.68	20.11	
MW-6	31-Oct-90	5.35	13	7.80	36	78	9.69	19.74	2
(D)	8-Feb-91		NA	NA	NA	NA	NA	NA	
, ,	8-May-91	5.64	9	6.68	4220	62.6	9.54	20.15	

### Notes:

<sup>(</sup>A) Measured from top of PVC casing.(B) Based on three casing volumes.

<sup>(</sup>C) Monitor Well MW-4 was dry after pumping 3 gallons during purging, October 31, 1990. (D) Access to well was prevented by parked automobile.

NA = Not Analyzed. SC = Specific conductance.

Table 2 - Summary of Depth-to-Water and Water Elevation Data Chevron Service Station #9-1583, Oakland, California

Well	Date	Depth to Water (1) (feet)	Top of Casin Elevation (feet)	g	Water Level Elevation (feet)
Well #1	22-Dec-83 30-Dec-83 12-Mar-90 25-Mar-90	10.25 9.17 10.08 10.46	81.97	(A)	71.72 72.80 71.90 71.51
	16-Nov-90 8-Feb-91 8-May-91	11.58 10.11 10.45	82.42	(B)	70.84 72.31 71.97
Well #2	22-Dec-83 30-Dec-83 12-Mar-90 25-Mar-90	10.50 9.92 11.02 11.33	83.48	(A)	72.98 73.56 72.46 72.15
	16-Nov-90 8-Feb-91 8-May-91	12.31 11.05 11.36	83.48	(B)	71.17 72.43 72.12
Well #3	22-Dec-83 30-Dec-83 12-Mar-90 25-Mar-90	11.58 11.17 12.14 12.55	84.36	(A)	72.22 71.81 70.74 72.18
	16-Nov-90 8-Feb-91 8-May-91	13.62 12.18 12.52	84.38	(B)	70.76 72.20 71.86
MW-4	18-Oct-90 31-Oct-90 16-Nov-90 8-Feb-91 8-May-91	15.75 13.90 14.25 12.32 12.23	84.25	(B)	68.50 70.35 70.00 71.93 72.02
MW-5	18-Oct-90 31-Oct-90 16-Nov-90 8-Feb-91 8-May-91	10.78 10.63 10.68 9.17 8.68	81.95	(B)	71.17 71.32 71.27 72.78 73.27

Table 2 - Summary of Depth-to-Water and Water Elevation Data Chevron Service Station #9-1583, Oakland, California

Well	Date	Depth to Water (1) (feet)	Top of Casing Elevation (feet)	J	Water Level Elevation (feet)
MW-6	18-Oct-90	9.79	80.60	(B)	70.81
	31-Oct-90	9.69		• •	70.91
	16-Nov-90	9.74			70.86
	8-Feb-91	NA			
	8-May-91	9.54			71.06

#### Notes:

- (1) Measured from top of casing.
- (A) Surveyed March 26, 1990, by Geraghty & Miller Inc..
- (B) Surveyed November 30, 1990, by Bates & Bailey Land Surveyors.
- Elevations are reported in feet above mean sea level.
- -- Elevations were measured relative to City of Oakland Bench Mark #1967 located on at the southwest corner of 55th Street and Martin Luther King Way. Reported elevation bench mark is 84.457 feet above mean sea level.

Table 3 - Ground-Water Analytical Results Chevron Service Station #9-1583, Oakland, California.

Sample	Date	TPH (A)	Benzene (B)	Toluene (B)	Xylenes (Β) μg/l	Ethylbenzene (B)
Sample	Date	μg/l	μg/l	μg/l	<u> </u>	μg/l
Well #1 (C)	12-Mar-90	50,000	3,000	7,300	18,000	1,900
	8-Feb-91	100,000	4,200	8,400	2,600	16,000
	8-May-91	31,000	200	66	2,000	670
Well #2	12-Mar-90	800	400	22	55	18
	8-Feb-91	4,600	820	440	210	720
	8-May-91	ND(<50)	5	ND(<0.5)	ND(<0.5)	ND(<0.5)
Well #3	12-Mar-90	47,000	1,000	9,900	9,800	1,700
	8-Feb-91	58,000	4,900	5,200	2,000	9,500
	8-May-91	50,000	2,100	1,400	9,400	2,000
Well MW-4	31-Oct-90	ND(<50)	ND(<0.5)	ND(<0.5)	1	ND(<0.5)
	8-Feb-91	60	17	2	ND<0.5	12
	8-May-91	65	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
Well MW-5	31-Oct-90	110	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	8-Feb-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	8-May-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
Well MW-6	31-Oct-90	ND(<50)	ND(<0.5)	ND(<0.5)	3	ND(<0.5)
	8-Feb-91	ŇC ´	NC	NC	NC	NC
	8-May-91	56	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)

Table 3 - Ground-Water Analytical Results
Chevron Service Station #9-1583, Oakland, California.

Sample	Date	TPH (A) μg/l	Benzene (B) μg/l	Toluene (Β) μg/l	Xylenes (Β) μg/l	Ethylbenzene (Β) μg/l
Trip Blank	12-Mar-90	ND(<50)	ND(<0.3)	ND(<0.3)	ND(<0.6)	ND(<0.3)
	8-Feb-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	8-May-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
Field Blank	31-Oct-90	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	8-Feb-91	NC	NC	NC	NC	NC

#### Notes:

Project No. RC02604

<sup>(</sup>A) TPH - Total petroleum hydrocarbons as gasoline. Analyzed by USEPA 8015, modified.

<sup>(</sup>B) BTEX analyzed by USEPA 8020.

<sup>(</sup>C) Wells #1, #2, and #3 were installed by Gettler Ryan, Inc., December 1983.

ND - Not detected

NC - Not Collected.

<sup>( ) =</sup> Detection limit.



Contour Interval 40 Feet Contours and Elevations in Feet 1 Mile 1:24,000



Reference: USGS 7.5' Quadrangle; Oakland West, California




SITE LOCATION MAP

CHEVRON STATION #9-1583 5509 Martin Luther King Way Oakland, California 1

FIGURE

Proj. No.RCO2604



## ATTACHMENT 1

# COPIES OF CERTIFIED ANALYTICAL REPORTS AND CHAIN OF CUSTODY DOCUMENTATION

# SUPERIOR ANALYTICAL LABORATORY, INC.

1555 BURKE, UNIT I · SAN FRANCISCO, CA 94124 · PHONE (415) 647-2081

DHS #1332

CERTIFICATE OF ANALYSIS

LABORATORY NO.: 11832

DATE RECEIVED: 05/08/91

CLIENT: Geraghty & Miller Inc.

DATE REPORTED: 05/16/91

CLIENT JOB NO.: RCO2604

raye rot -	Page	1	of	2
------------	------	---	----	---

Lab Number	Customer	Sample Id	entificati	on	Date Sampl		Date Analyzed
11832- 1 11832- 2 11832- 3 11832- 4 11832- 5 11832- 6 11832- 7	MW-4 MW-6 MW-5 MW-2 MW-1 MW-3 TRIP BLA	NK			05/08 05/08 05/08 05/08 05/08 05/08	/91 /91 /91 /91 /91	05/14/91 05/14/91 05/14/91 05/14/91 05/14/91 05/14/91 05/15/91
Laboratory N	lumber:	11832	11832 2	11832 3	11832 4		332
ANALYTE LIST		Amounts/	'Quantitati	on Limits	(ug/L)		
OIL AND GREASE: TPH/GASOLINE RANGE: TPH/DIESEL RANGE: BENZENE: TOLUENE: ETHYL BENZENE: XYLENES:		NA 65* NA ND<0.5 ND<0.5 ND<0.5	NA 56* NA ND<0.5 ND<0.5 ND<0.5	ND<0.5	NA ND<50 NA 5 ND<0.5 ND<0.5	NA 200	000 0
Laboratory Number:		11832 6	11832 7				
ANALYTE LIST	······································	Amounts/	'Quantitati	on Limits	(ug/L)		
OIL AND GREASE: TPH/GASOLINE RANGE: TPH/DIESEL RANGE: BENZENE: TOLUENE: CTHYL BENZENE: XYLENES:		NA 50000 NA 2100 1400 2000 9400	NA ND(50 NA ND(0.5 ND(0.5 ND(0.5 ND(0.5				

# SUPERIOR ANALYTICAL LABORATORY, INC.

1555 BURKL, UNIT I · SAN FRANCISCO, CA 94124 · PHONE (415) 647-2081

DHS #1332

CERTIFICATE OF ANALYSIS

ANALYSIS FOR TOTAL PETROLEUM HYDROCARBONS

Page 2 of 2 QA/QC INFORMATION SET: 11832

NA = ANALYSIS NOT REQUESTED

ND = ANALYSIS NOT DETECTED ABOVE QUANTITATION LIMIT

ug/l = part per billion (ppb)

OIL AND GREASE ANALYSIS By Standard Methods Method 503E: Minimum Detection Limit in Water: 5000ug/L

Modified EPA-SW846 Method 8015 for Extractable Hydrocarbons: Minimum Quantitation Limit for Diesel in Water: 50ug/1 Standard Reference: NA

EPA-SW846 Method 8015/5030 Total Purgable Petroleum Hydrocarbons: Minimum Quantitation Limit for Gasoline in Water: 50ug/1 Standard Reference: 08/24/90

SW-846 Method 8020/BTXE

Minimum Quantitation Limit in Water: 0.5ug/1

Standard Reference: 04/09/91

ANALYTE	REFERENCE	SPIKE LEVEL	MS/MSD RECOVERY	RPD	CONTROL LIMIT
Oil & Crease		NA	NA	NA	NA
Diesel		NA	NA	NA	NA
Gasoline		200ng	93/97	4.1	63 111
Benzene		200ng	73/85	15.2	72-113
Toluene		200ng	72/85	16.0	70-116
Ethyl Benzene		200ng	74/87	16.3	73-119
Total Xylene		600ng	74/87	16.8	71-110

\* Does not match typical gasoline pattern.

Richard Srna, Ph.D.

Ohy A Now (fir)
Laboratory Director

Chevron Facility Number 9-1583 11832 Chevron Contact (Name) \_ Facility Address 5509 Thanting Luther King fr. way (Phone)\_\_ Cheyron U.S.A. Inc. Consultant Project Number RCO 2 604 Supering LABS P.O. BOX 5004 Laboratory Name \_ Consultant Name Geraghty & Miller 444 6580 San Ramon, CA 94583 Laboratory Release Number \_\_\_\_ Samples Collected by (Name) RICKY SPENCER 1050 Marina Way South, Richmond, CA 94804 FAX (415)842-9591 Project Contact (Name) TEFF HAWKING 5-8-91 Collection Date \_\_ Ricky & Spence (Phone)(415) 233-320QFox Number) 415 233-3204 Stanature \_\_ At Charcoal Analyses To Be Performed Grab Composite Discrete Containers BTEX + TPH GAS (8020 + 8015) # I **∀** ∪ Non Chlorinated (8020) Oil and Grease (5520) Chlorinated HC (8010) Total Lead
(M)
Metals
Cd.Cr.Pb.Zn.Ni
(KCAP or M) Matrix S = Soll W = Water 1 1 1 Þ ဖပဓ 1,75 Time Remarks  $C^{\lambda}$ MW-4 1351 HCL YES Please initial: Mw-6 1454 HCL W YE5 <del>Sample: Storda in ite</del> Mw-5 1530 W HCL YES Appropliate dontainers. G Samples preserved. mw - 2 W 1610 HCL VES VOA's without headspace G 1647 mw -1 S HCL VES MW -3 TRIP OLANK 1725 14 CC W VES W. C حعد Cattodh 100 DS100 Date/Time 10: 25 Received By (Signature) Relinquished By (Signature) Organization Organization Date/Time Turn Around Time (Circle Choice) 5-9-91 GAM Exoress. 77 24 Hrs. Organization Reilaguished By (Signature) Organization Date/Time Date/Time Received By (Signature) 48 Hrs. 5-9-91 12/5 Express I+ Express+17 5/9/9, 1117 5 Days 10 Days Relinaylahed By (Slepeture) Organization 5/3 Date/Time

5 x pr. ess-175/9/9//1/140 Recleyed For Laborates By (Signature) As Contracted