

Chevron U.S.A. Inc.

2410 Camino Ramon, San Ramon, California • Phone (510) 842-9500 Mail Address PO Box 5004, San Ramon, CA 94583-0804

911-11-11-19

arion (ser)

Marketing Department

December 10, 1991

DIR

Mr. Rafat Shahid Alameda County Health Care Services 80 Swan Way, Room 200 Oakland, CA 94621

Re: Chevron Service Station #9-1583

5509 Martin Luther King Way, Oakland

Dear Mr. Shahid:

Enclosed we are forwarding the Quarterly Ground Water Sampling Report dated November 26, 1991, prepared by our consultant Geraghty & Miller, Inc. for the above referenced site. As indicated in the report, ground water samples collected were analyzed for total petroleum hydrocarbons as gasoline and BTEX. Benzene was detected in monitor wells #1 and #3 only at concentrations of 24 and 1000 ppb, respectively. These concentrations are significantly lower than the previous concentrations reported last quarter. Depth to ground water was measured at approximately 9 to 13-feet below grade, and the direction of flows to the northwest.

Chevron will continue to sample this site and report findings on a quarterly basis. It appears that subsequent sampling events of monitor wells #1, #2 and #3 continue to purge these wells of subsurface contaminants that infiltrated into the wells prior to the well head replacements.

If you have any questions or comments, please do not hesitate to contact me at (510) 842-9581.

Nancy Vukelich

Very truly yours

Environmental Engineer

CHEVRON U.S.A. INC

Enclosure

cc: Mr. Eddy So, RWQCB-Bay Area Mr. W.T. Scudder File (9-1583Q2)



Ground Water

Engineering

Hydrocarbon

Remediation

Education

November 26, 1991 Project No. RC02604

Ms. Nancy Vukelich Chevron U.S.A. Inc. West Central Marketing 2410 Camino Ramon San Ramon, California 94583-0804

Subject:

Quarterly Ground-Water Sampling Results, November 1991, Service Station

#9-1583, 5509 Martin Luther King Jr. Way, Oakland, California.

Dear Ms. Vukelich:

This letter presents the quarterly ground-water sampling results for the Chevron U.S.A. Inc. (Chevron) service station referenced above. The scope of work for this project was presented to Chevron in a previous letter from Geraghty & Miller, Inc. (Geraghty & Miller) dated January 11, 1991.

FIELD AND LABORATORY PROCEDURES

The quarterly ground-water sampling was performed on November 7, 1991. Water samples were collected from each of the seven existing monitor wells (Monitor Wells #1 through #3, MW-4, MW-5, and MW-6). Prior to sampling, depth to water was measured, and each well was checked for the presence of liquid-phase hydrocarbons. Liquid-phase hydrocarbons were not observed during the quarterly sampling. A minimum of three casing volumes of water was purged from each well prior to sampling using a surface diaphragm pump. The equipment that entered the well was washed in a solution of MicroTM (a phosphate-free detergent) and water and then triple rinsed in deionized water prior to sampling each well. The field sampling results are presented in Table 1. Following purging, ground-water samples were collected using a disposable polyethylene bailer. A new bailer was used for each well. The purged water was stored in 55-gallon drums and retained on-site for subsequent disposal by Chevron.

Ground-water samples for laboratory analysis were placed in the appropriate USEPA-approved containers, placed on ice, and transported to Superior Precision Analytical, Inc., located in Martinez, California. One trip blank consisting of laboratory-grade water, which accompanied the sample bottles from the laboratory, into the field, and back to the laboratory, was also analyzed. The water samples were analyzed for total petroleum hydrocarbons as gasoline (USEPA Method 8015, modified) and benzene, toluene, ethylbenzene, and xylenes (USEPA Method 8020).

RESULTS OF QUARTERLY SAMPLING

DEPTH TO WATER

A summary of the depth-to-water measurements is presented in Table 2. A ground-water contour map is presented in Figure 1. Based on the data collected during November 1991, the direction of shallow ground-water flow in the vicinity of the site is toward the west-northwest.

GROUND-WATER ANALYTICAL RESULTS

A summary of the ground-water analytical results is presented in Table 3. Copies of the certified laboratory reports and chain-of-custody documentation are included in Attachment 1.

If you have any questions regarding this letter report, please call the undersigned at (510) 233-3200.

Sincerely,

GERAGHTY & MILLER, INC.

JoEllen Kuszmaul

Senior Geologist/Project Manager

Principal Engineer/Project Officer

Prò∰ct No. RC02604

Enclosures: Table 1

Summary of Field Sampling Data Summary of Depth-to-Water and Water-Elevation Data Ground-Water Analytical Results Table 2

Table 3

Figure 1 Ground-Water Contour Map, November 1991

Attachment 1: Copies of Chain-of-Custody Documentation and Certified Analytical Reports

GERAGHTY & MILLER, INC.

Table 1: Summary of Field Sampling Data Chevron Service Station #9-1583, 5509 Martin Luther King Jr. Way, Oakland, California,

Well	Date	Calculated Purge Volume (a) (gallons)	Actual Purge Volume (gallons)	Depth to Water (b) (feet)	Measured Depth of Well (b) (feet)	Casing Diameter (inches)
Well #1	7-Nov-91	9.76	10	10.70	19.50	3
Well #2	7-Nov-91	8.76	9	11.50	19.40	3
Well #3	7-Nov-91	6.97	NA	12.81	19.09	3
MW-4	7-Nov-91	5.65	6	13.42	25.20	2
MW-5	7-Nov-91	4.92	5	9.76	20.01	2
MW-6	7-Nov-91	5.42	5.5	8.89	20.20	2

⁽a) Based on three casing volumes.

NA = Not analyzed

⁽b) Measured from top of PVC casing.

Table 2: Summary of Depth-to-Water and Water-Elevation Data Chevron Service Station #9-1583, 5509 Martin Luther King Jr. Way, Oakland, California,

Well	Date	Depth to Water (feet)	Top of Casing Elevation (feet)		Water Level Elevation (feet)
Well #1	22-Dec-83	10.25	81.97	(a)	71.72
	30-Dec-83	9.17	W = 7,7 ·	(11)	72.80
	12-Mar-90	10.08			71.90
	25-Mar-90	10.46			71.51
	16-Nov-90	11.58	82.42	(b)	70.84
	8-Feb-91	10.11		` /	72.31
	8-May-91	10.45			71.97
	12-Aug-91	11.23			71.19
	7-Nov-91	10.70			71.72
Well #2	22-Dec-83	10.50	83.48	(a)	72.98
	30-Dec-83	9.92			73.56
	12-Mar-90	11.02			72.46
	25-Mar-90	11.33			72.15
	16-Nov-90	12.31	83.48	(b)	71.17
	8-Feb-91	11.05			72.43
	8-May-91	11.36			72.12
	12-Aug-91	11.97			71.51
	7-Nov-91	11.50			71.98
Well #3	22-Dec-83	11.58	84.36	(a)	72.22
	30-Dec-83	11.17			71.81
	12-Mar-90	12.14			70.74
	25-Mar-90	12.55			72.18
	16-Nov-9()	13.62	84.38	(b)	70.76
	8-Feb-91	12.18			72.20
	8-May-91	12.52			71.86
	12-Aug-91	13.27			71.11
	7-Nov-91	12.81			71.57
MW-4	18-Oct-90	15.75	84.25	(b)	68.50
	31-Oct-90	13.90			70.35
	16-Nov-90	14.25			70.00
	8-Feb-91	12.32			71.93
	8-May-91	12.23			72.02
	12-Aug-91	13.93			70.32
	7-Nov-91	13.42			70.83

Table 2: Summary of Depth-to-Water and Water-Elevation Data Chevron Service Station #9-1583, 5509 Martin Luther King Jr. Way, Oakland, California,

Well	Date	Depth to Water (feet)	Top of Casing Elevation (feet)		Water Level Elevation (feet)
MW-5	18-Oct-90	10.78	81.95	(b)	71.17
	31-Oct-90	10.63	01.70	(0)	71.32
	16-Nov-90	10.68			71.27
	8-Feb-91	9.17			72.78
	8-May-91	8.68			73.27
	12-Aug-91	10.33			71.62
	7-Nov-91	9.76			72.19
MW-6	18-Oct-90	9.79	80.60	(b)	70.81
	31-Oct-90	9.69		` ′	70.91
	16-Nov-90	9.74			70.86
	8-Feb-91	NA			
	8-May-91	9.54			71.06
	12-Aug-91	9.50			71.10
	7-Nov-91	8.89			71.71

⁽a) Surveyed March 26, 1990, by Geraghty & Miller Inc..

Elevations are reported in feet above mean sea level.

⁽b) Surveyed November 30, 1990, by Bates & Bailey Land Surveyors.

Table 3: Ground-Water Analytical Results
Chevron Service Station #9-1583,
5509 Martin Luther King Jr. Way, Oakland, California,

Well	Date	TPH (a) μg/L	Benzene (b) μg/L	Toluene (b) µg/L	Ethylbenzene (b) µg/L	Xylenes (b) μg/L
Well #1 (c)	12-Mar-90	50,000	3,000	7,300	1,900	18,000
` ,	8-Feb-91	100,000	4,200	8,400	16,000	2,600
	8-May-91	31,000	200	66	670	2,000
	12-Aug-91	17,000	81	7.2	270	710
	7-Nov-91	7,100	24	6	130	170
Well #2 (c)	12-Mar-90	800	400	22	18	55
` ,	8-Feb-91	4,600	820	440	720	210
	8-May-91	ND(<50)	5	ND(<0.5)	ND(<0.5)	ND(<0.5)
	12-Aug-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	1-Nov-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
Well #3 (c)	12-Mar-90	47,000	1,000	9,900	1,700	9,800
` ,	8-Feb-91	58,000	4,900	5,200	9,500	2,000
	8-May-91	50,000	2,100	1,400	2,000	9,400
	12-∧ug-91	15,000	1,300	160	920	1,900
	7-Nov-91	26,000	1,000	310	1,900	5,900
MW-4	31-Oct-90	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	1
	8-Feb-91	60	17	2	12	ND(<0.5)
	8-May-91	65	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	12-Aug-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
,	7-Nov-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
MW-5	31-Oct-90	110	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	8-Feb-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	8-May-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	12-Aug-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	/ 7-Nov-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
MW-6	31-Oct-90	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	3
	8-Feb-91	NC	NC	NC	NC	NC
	8-May-91	56	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
	12-Aug-91	ND(<5())	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
į	7-Nov-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)

Table 3: Ground-Water Analytical Results
Chevron Service Station #9-1583,
5509 Martin Luther King Jr. Way, Oakland, California,

Well Trip Blank	Date 12-Mar-90 8-Feb-91 8-May-91 12-Aug-91	TPH (a) μg/L ND(<50) ND(<50) ND(<50) ND(<50)	Benzene (b) μg/L ND(<0.3) ND(<0.5) ND(<0.5) ND(<0.5)	Toluene (b) μg/L ND(<0.3) ND(<0.5) ND(<0.5) ND(<0.5)	Ethylbenzene (b) µg/L ND(<0.3) ND(<0.5) ND(<0.5) ND(<0.5)	Xylenes (b) μg/L ND(<0.6) ND(<0.5) ND(<0.5) ND(<0.5)
	7-Nov-91	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)
Field Blank	31-Oct-90	ND(<50)	ND(<0.5)	ND(<0.5)	ND(<0.5)	ND(<0.5)

⁽a) TPH - Total petroleum hydrocarbons as gasoline. Analyzed by USEPA Method 8015, modified.

μg/L - micrograms/liter.


ND - Not detected.

NC - Not collected; wellhead blocked by parked vehicle.

() = Detection limit.

⁽b) BTEX analyzed by USEPA Method 8020.

⁽c) Wells #1, #2, and #3 were installed by Gettler-Ryan, Inc., December 1983.



ATTACHMENT 1

COPIES OF CERTIFIED ANALYTICAL REPORT AND CHAIN-OF-CUSTODY DOCUMENTATION



825 Arnold Drive, Suite 114 • Martinez, California 94553 • (510) 229-1512 / fax (510) 229-1526

CERTIFICATE OF ANALYSIS

LABORATORY NO.: 84336 CLIENT: Geraghty & Miller CLIENT JOB NO.: RCO2604 DATE RECEIVED: 11/08/91 DATE REPORTED: 11/15/91

Page 1 of 2

Lab Number Customer Sample Identification 84336- 1					11/07/91 1 11/07/91 1 11/07/91 1 11/07/91 1 11/07/91 1 11/07/91 1		Date Analyzed 11/14/91 11/14/91 11/15/91 11/14/91 11/14/91 11/15/91
Laboratory	Number:	84336 1 .	84336 2	84336 3	84336 4		336
ANALYTE LIS	ST	Amounts/	Quantıtati	on Limits	(ug/L)		
OIL AND GREASE: TPH/GASOLINE RANGE: TPH/DIESEL RANGE: BENZENE: TOLUENE: ETHYL BENZENE: XYLENES:		NA ND<50 NA ND<0.5 ND<0.5 ND<0.5	NA ND<50 NA ND<0.5 ND<0.5 ND<0.5 ND<0.5	NA ND<50 NA ND<0.5 ND<0.5 ND<0.5	NA ND<50 NA ND<0.5 ND<0.5 ND<0.5	NA 260 NA 100 310 190 590	0 0 0 ,
Laboratory	Number:	84336 6	84336 7				
ANALYTE LIST		Amounts	Quantitat	ion Limits	(ug/L)		
OIL AND GRETPH/GASOLINTPH/DIESELBENZENE: TOLUENE: ETHYL BENZEN	NE RANGE: RANGE:	NA 7100 NA 24 6 130 170	NA ND<50 NA ND<0.5 ND<0.5 ND<0.5				

825 Arnold Drive, Suite 114 • Martinez, California 94553 • (510) 229-1512 / fax (510) 229-1526

CERTIFICATE OF ANALYSIS

ANALYSIS FOR TOTAL PETROLEUM HYDROCARBONS

Page 2 of 2 QA/QC INFORMATION SET: 84336

NA = ANALYSIS NOT REQUESTED

ND = ANALYSIS NOT DETECTED ABOVE QUANTITATION LIMIT

ug/L = part per billion (ppb)

OIL AND GREASE ANALYSIS By Standard Methods Method 5520F: Minimum Detection Limit in Water: 5000ug/L

Modified EPA-SW846 Method 8015 for Extractable Hydrocarbons: Minimum Quantitation Limit for Diesel in Water: 50ug/L Standard Reference: NA

EPA-SW846 Method 8015/5030 Total Purgable Petroleum Hydrocarbons:
Minimum Quantitation Limit for Gasoline in Water: 50ug/L
Standard Reference: 10/04/91

SW-846 Method 8020/BTXE

Minimum Quantitation Limit in Water: 0.5ug/L

Standard Reference: 10/11/91

ANALYTE	REFERENCE	SPIKE LEVEL	MS/MSD RECOVERY	RPD 	CONTROL LIMIT
Oil & Grease Diesel Gasoline Benzene Toluene Ethyl Benzene Total Xylene		NA NA 200 ng 200 ng 200 ng 200 ng 200 ng	NA NA 90/93 96/100 94/96 92/94 97/100	NA NA 4 4 3 2 3	NA NA 70-130 70-130 70-130 70-130

Richard Srna, Ph.D.

Yaboratory Director

Fax copy of Lab Report and COC to Chevron Contact: \$\square\$No \$\square\$9336 <u>Chain-of-Custody-Record</u> NAWCY VUKELICH Chevron Focility Number # 9-1583 Chevron Contact (Name) ____ FOOILTY ADDRESS 5509 MARTEN LUTHER KING WAY (Phone). Chevron U.S.A. Inc. Consultant Project Number RCO 2604 Laboratory Name ___ SUPERIOR P.O. BOX 5004 Consultant Name CTERAGHTY + MILLER INX. 4446580 Laboratory Release Number San Ramon, CA 94583 Samples Collected by (Name) ALEX RIOS MIGGORD 1050 MARINA WAY SOUTH, RICHMOND CL 94804 FAX (415)842-9591 Collection Date 11-07-9 Signature Live River de Project Contact (Name) JO ELLEN KUSZMAUL (Phone) (415) 233-3200 (Fox Number) (415) 233-3204 Analyses To Be Performed ^ourgeable Halocarbons (8010) Extractable Organics (8270) BTEX + TPH CAS (8020 + 8015) 11 Oil and Gream (5520) Matuhx S = Soli ¥ = Water 0 J 3 TPH Diesed (8015) ဖြပ္ရ Remarks MW-2 HCL W HCL MW-5 12:28 W MW-4 14:04 MCL W 3 HCL MW-6 13:35 W MW-3 15:28 MCL W HCL MW-1 15:04 W TRIP BLANK Earspies Stored in ide. Appropriate containers Columnents: . Received By (Signature) CORDUZ, Turn Around Time (Circle Cholce) Date/Time 11-08-91 Date/Time Organization Relinquished By (Signature) Organization GETCAOUTY a will Ex 24 Hrs. 48 Hrs. Organization Date/Time Relinquished By (Signature) Date/Time Received By (Signature) Organization 5 Days Date/Time 1325 Relinquished By (Signature) -Regieved For Laboratory By (Signature) Organization Date/Time As Contracted