

Ro4

Chan, Barney, Env. Health

From: Chan, Barney, Env. Health
Sent: Wednesday, March 10, 2004 9:52 AM
To: Mike Bowery (E-mail)
Subject: Former Thrifty Oil Co. Station#49, 3400 San Pablo Ave., Oakland, RO 4

Mr. Bowery:
I have a couple of questions regarding this site:

- Our office received the October 21, 2003 Production Well and Utility Conduit Survey. The report is not conclusive. It gives typical construction standards for the sanitary sewer line, not actual. Also what about the storm drain lines? I don't know if the utilities are a conduit or not.
- Please resend your 4th qtr 2003 Status report submitted 12/18/03. Our office has not received it as yet. I noticed that MW3 reported elevated TPHg and MTBE, how do you explain the sudden appearance of this contamination?
- When will you submit the recent soil and gw investigation report? Are you waiting for MW(s) installation?

Sincerely,

Barney M. Chan
Hazardous Materials Specialist
Alameda County Environmental Health
510-567-6765