

March 13, 1994

Alameda County Health Care Services Agency
Division of Hazardous Materials
Attention Mr. Ron Owcarz
80 Swan Way, Room 200,
Oakland, CA 94621

California Regional Water Quality Control Board Attention Mr. Eddie So San Francisco Bay Region 2101 Webster Street, Suite 500 Oakland, CA 94612

RE: BP Oil Site No. 11132 3201 35th Street Oakland, CA

Greetings:

Attached please find a Groundwater Sampling and Monitoring Report dated January 10, 1994. You should note that we have lowered the elevation of the pump intake in RW-1, and this appears to have enlarged the associated cone of depression. This should enhance migration control, and may obviate the need for an additional recovery well. I have also directed Alisto Engineering Group to perform additional manual bailing as an interim measure. An oil-water separator is also being added to the remediation system.

Please give me a call in the event you wish to discuss this matter further. I can be reached at (206) 251-0689.

Sincerely,

/ Scott T. Hooton

Environmental Resources Management

attachment

cc: site file

B. Nagle - Alisto



