

RECEIVED

11:21 am, Jun 19, 2012

Alameda County Environmental Health

Reference:

Rodding Cleaning Services 2585 Nicholson Street, San Leandro, CA Fuel Leak Case No. RO00000020 Versar Project No. 104422.4422.007

PERJURY STATEMENT

As the Responsible Party (RP) for this Site, I declare under penalty of perjury that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge.

Fred Schifferle - Manager, Sketchley Trust

Responsible Party



June 30, 1999

Ms. Juliet Shin Hazardous Materials Specialist Alameda County Environmental Health Services 1131 Harbor Bay Parkway #250 Alameda, California 94502-6577

Reference: Monitoring Well Installation and Groundwater Monitoring Report

2585 Nicholson Street in San Leandro, California

Versar Project No. 4422-001

Dear Ms. Shin:

Versar, Inc. (Versar) is pleased to provide, on behalf of Bank of America NT&SA, the enclosed *Monitoring Well Installation and Groundwater Monitoring Report*. Should you wish to discuss the information presented herein, please feel free to call me at (916) 863-9325, or Mr. John Schovanec with Bank of America at (949) 260-5812.

Sincerely,

Scott Allin, R.E.A.

Senior Program Manager

cc: Mr. John Schovanec - Bank of America

Mr. Michael Bakaldin - City of San Leandro

1759-99/4422-001/JUN30'99



MONITORING WELL INSTALLATION AND GROUNDWATER MONITORING REPORT

2585 Nicholson Street San Leandro, California

ESD Number 305582

Prepared for:

BANK OF AMERICA, N.T. & S.A.

Environmental Services Department, No. 24122 4000 MacArthur Boulevard, Suite 100 Newport Beach, California 92660

Prepared by:

Wershing.

7844 Madison Avenue, Suite 167 Fair Oaks, California 95628

Versar Project No. 4422-001

June 30, 1999

1759-99/4422-001/JUN30'99



FOREWORD

This Monitoring Well Installation and Groundwater Monitoring Report was prepared by Versar, Inc. for Bank of America. Mr. Philip Cox, Senior Associate Geologist prepared this report. Mr. Scott Allin reviewed this report and Mr. Tim Berger, California Registered Geologist No. 5225, supervised the field activities and the preparation of this report.

Prepared By:

Philip Cox

Senior Associate Geologist

Environmental Management Division

Approved for Release By:

Tim Berger, R.G. 5225

Senior Geologist

Environmental Management Division

Reviewed By:

Scott Allin, REA

Senior Program Manager



TABLE OF CONTENTS

Secti	on No.	<u>I</u>	Page N	0
	FOR	EWORD		. j
1.0	INTF 1.1 1.2 1.3	RODUCTION Scope of Work Site Location Background	• • • •	1
2.0	MET 2.1 2.2 2.3 2.4 2.5	Permitting . Underground Utilities Well Installation and Development Surveying . Groundwater Sampling and Analysis .	• • • • • • • • • • • • • • • • • • • •	3 3 4
3.0	INVE 3.1 3.2 3.3	Groundwater Flow Direction and Gradient Groundwater Analytical Results Investigation-Derived Waste Disposal		5 5
4.0	PENI	DING ACTIVITIES	• • • • •	6
5.0	REFE	ERENCES		6
6.0	STAT	TEMENT OF LIMITATIONS		7



LIST OF FIGURES

Figure 1	Site Location
Figure 2	Site Layout and Monitoring Well Location Map
Figure 3	Groundwater Contour Map - April 29, 1999
Figure 4	Laboratory Analytical Results for Groundwater Samples - April 29, 1999

LIST OF TABLES

Table 1	Groundwater Elevation Data
Table 2	Analytical Results for Groundwater Samples

LIST OF APPENDICES

Appendix A	Well Installation and Encroachment Permits
Appendix B	Drilling Logs
Appendix C	Groundwater Monitoring Well Development Tables
Appendix D	Surveyor's Report
Appendix E	Groundwater Monitoring Well Purge Tables
Appendix F	Laboratory Analytical Report and Chain-of-Custody Documentation



1.0 INTRODUCTION

Versar, Inc. (Versar) has prepared this Well Installation and Groundwater Monitoring Report on behalf of Bank of America, NT&SA (BofA) summarizing work performed at the property located at 2585 Nicholson Street in San Leandro, California (Site). Figures 1 and 2 show the Site location and Site layout, respectively. The following sections describe the scope of work, site location, and site background.

1.1 Scope of Work

The objectives of this well installation and groundwater sampling was to assess the lateral distribution of petroleum hydrocarbons and related constituents in groundwater originating from the Site, and to determine the groundwater flow direction and gradient. To meet these objectives, the following primary activities were performed:

- Performance of pre-well installation activities including; obtaining appropriate permits, clearance of underground utilities, and preparation of a Site specific health and safety plan;
- Installation, development, and sampling of four new groundwater monitoring wells;
- Survey the top of the well casings to a common datum point to allow for the calculation of groundwater gradient and flow direction;
- Sampling of the one existing groundwater monitoring well;
- Laboratory analysis of groundwater samples; and
- Prepare this report documenting the well installation and groundwater sampling activities at the Site.

The scope of work for the well installation and groundwater sampling was originally proposed in Versar's workplan dated November 4, 1998 (Versar, 1998a). An addendum to the Workplan was presented in a letter dated December 23, 1998 (Versar, 1998b) and was prepared in response to Alameda County Environmental Health Services (ACEHS) letter dated November 17, 1998 (ACEHS, 1998a), which provided comments on the original workplan. Comments on the workplan addendum were presented in the ACEHS letters dated January 4, 1999 (ACEHS, 1999a), and February 1, 1999 (ACEHS, 1999b).



1.2 Site Location

The Site is located at 2585 Nicholson Street in San Leandro, California. The nearest cross street is Republic Avenue. The Site is currently occupied by Crane Works and consists of a single-story commercial office building at the north end of the property, and covered parking/work area over the western and southern edges of the property. The parking/work areas are covered with 6-inch concrete.

1.3 Background

According to information presented in the McLaren/Hart soil and groundwater characterization report (McLaren/Hart, 1998), two underground storage tanks (USTs) were removed from the Site in 1991. Reportedly, overexcavation was performed during UST removal activities. Soil and groundwater samples collected during the UST removal activities identified total petroleum hydrocarbons (TPH) as diesel and gasoline in both media. In 1992, Hageman-Aguiar (HA) performed an on-site soil and groundwater investigation. The results of the investigation identified elevated levels of TPH on-site in soil and groundwater. During the investigation, HA installed one monitoring well (MW-1) on the central portion of the Site. Between 1992 and 1995, ten groundwater samples were collected by HA from MW-1. These groundwater results are summarized in Table 2. HA identified free-floating product in MW-1 during some of the sampling events, at a maximum thickness of 1.25 inches.

In 1998, McLaren/Hart performed a limited investigation of soil and groundwater, both on and off-site. The investigation consisted of collecting soil samples from 8 borings, and groundwater samples from 15 borings. McLaren/Hart concluded that adequate definition of petroleum hydrocarbons in soil and groundwater had been completed, and that the contaminant plume was relatively stable with minimal off-site migration of petroleum hydrocarbons. McLaren/Hart recommended installation of additional monitoring wells to confirm the direction of groundwater flow beneath the Site.

2.0 METHODOLOGY

The primary objective of this section is to present the tasks and methodology associated with the well installation activities. The following section describes permitting, underground utilities, well installation, surveying, and groundwater sampling and analysis.



2.1 Permitting

Permits for the new monitoring wells were obtained from the Alameda County Public Works Department. An encroachment permit was also obtained from the City of San Leandro for monitoring well MW-2. Copies of the permits are included as Appendix A.

2.2 Underground Utilities

Versar contracted CU Survey to clear underground utilities prior to drilling. The following underground utilities were identified in the vicinity of the monitoring wells installed during this investigation by CU Survey:

- A natural gas line runs parallel with Nicholson Street, approximately three feet northeast of MW-2;
- An electrical line is located approximately three feet northwest of MW-4; and
- A storm sewer is located approximately 5 feet southwest of MW-5.

2.3 Well Installation and Development

On April 15 and 16, 1999, the four new monitoring wells were installed by Cal-Nev Geoexplorations, C57 Licence No. 582696 (Figure 2). The boreholes were drilled using 8-inch diameter hollow-stem augers to a depth of approximately 14 to 15 feet below ground surface (bgs). The monitoring wells were constructed inside the hollow-stem augers using approximately 10 feet of pre-cleaned, two-inch diameter, Schedule 40 PVC slotted casing with 0.010-inch slots, with approximately 4 to 5 feet of flush-jointed, two-inch diameter, Schedule 40 PVC casing to the surface. A sand pack consisting of clean, 2/12 sand was placed in the annular space around the casing from the bottom of the borehole to approximately one foot above the top of the screen. A minimum two-foot bentonite seal was placed above the sand pack and hydrated. The remaining annular space was filled to just below surface with a cement/bentonite seal.



The monitoring wells were sealed with a locking well cap. The well cap and well cover are labeled with the well identification code and the words "Monitoring Well." The drilling logs, including the well construction details are included in Appendix B.

Soil cuttings, rinsate water from the drilling and sampling equipment decontamination, and development water were placed in seven (four soil and three water) 55-gallon Department of Transportation (DOT) 17E&H steel drums and temporarily stored on-site. Based on the field screening results, the drums were labeled as non-hazardous waste with the date, source, and generator.

On April 26, 1999, the four newly installed wells were developed. This was accomplished by surging, then bailing approximately 10 well volumes of water from each well. Temperature, pH, and electrical conductivity readings were collected to monitor groundwater stabilization within the wells during development. The groundwater monitoring well development tables are included in Appendix C.

2.4 Surveying

On April 26, 1999, the top of each new well and the existing well casing was horizontally and vertically surveyed to a horizontal accuracy of 1 foot and a vertical accuracy of 0.01 foot by Morrow Surveying, Incorporated. The survey data was used in conjunction with the groundwater level measurements to produce groundwater elevation contour maps and to calculate the groundwater gradient across the Site. The groundwater elevation data are presented in Table 1. The surveyor's report is included in Appendix D.

2.5 Groundwater Sampling and Analysis

On April 29, 1999, groundwater samples were collected from monitoring wells MW-2 through MW-5, and depth to water measurements were collected from all five monitoring wells. Groundwater samples were collected from monitoring well MW-1 on May 7, 1999. Prior to sampling, each well was purged of approximately three well casing volumes of groundwater. Following purging, the water level was allowed to recover to at least 80 percent of the pre-purge level. During purging, temperature, pH, conductivity, and dissolved oxygen were measured and a visual note of turbidity was recorded on groundwater monitoring well purge tables. The purge tables are presented in Appendix E.

Groundwater samples collected from monitoring wells MW-2 through MW-5 were submitted to Kemron Environmental Services for TPH as gasoline (TPH-G), TPH as diesel (TPH-D), TPH as motor oil (TPH-MO) by Environmental Protection Agency (EPA) Method 8015, and benzene, toluene, ethylbenzene, and xylenes (BTEX) by EPA Method 8021B. The samples were collected, placed in containers, preserved, and analyzed within the holding times consistent with applicable U.S. EPA, California EPA, and Regional Water Quality Control Board (RWQCB) procedures and



requirements. Samples were delivered under chain-of-custody protocol. Custody of the samples began at the time of sample collection and was maintained by the sampling team until the samples were relinquished to the laboratory.

3.0 INVESTIGATION RESULTS

3.1 Groundwater Flow Direction and Gradient

Using the survey data in conjunction with the groundwater level measurements collected on April 29, 1999, the groundwater gradient was calculated to be approximately 0.001 feet/foot and flowing in a southeasterly direction. The groundwater contour map for April 29, 1999 is included as Figure 3. Given the extremely flat groundwater gradient and shallow depth to groundwater beneath the Site, it is likely that the calculated groundwater flow direction will vary seasonally. Therefore, the average groundwater flow direction will be representative of the direction of groundwater flow over time.

3.2 Groundwater Analytical Results

The laboratory analytical results from the April and May 1999 monitoring event are summarized on Figure 4 and Table 2. The laboratory analytical report is included in Appendix F. The following is a summary of the analytical results detected above the laboratory reporting limits:

- ► TPH-G was detected in wells MW-1, MW-4, and MW-5 at 8,100 micrograms per liter (μ g/L), 110 μ g/L, and 270 μ g/L, respectively;
- TPH-D was only detected in well MW-3 at 540 μg/L; and
- BTEX compounds were only detected in well MW-1 at concentrations of 1,400 μ g/L, 31 μ g/L, 82 μ g/L, and 360 μ g/L, respectively.

These results are relatively consistent with previous investigation results, and indicate minimal off-site migration of TPH and BTEX compounds. Additional groundwater samples should be collected to evaluate the fate and transport of the contaminants for the purpose of obtaining future site closure.



3.3 Investigation-Derived Waste Disposal

Investigation derived wastes included soil and groundwater. A total of three drum of soil were generated during installation of the monitoring wells. A total of five drums of water were generated during well development, well purging, and equipment decontamination. The wastes are scheduled to be transported by Integrated Waste Management (IWM) to Seaport's facility in Redwood City, California (water), and to BFI Landfill in Livermore, California (soil).

4.0 PENDING ACTIVITIES

Versar recommends quarterly sampling of the groundwater monitoring wells to validate the results of the data presented herein. The next monitoring event is scheduled for July 1999. In addition to the analyses performed during this investigation, as requested by the ACEHS, samples from select monitoring wells will also be analyzed for fuel oxygenates by EPA Method 8260, and for semi-volatile organic compounds (SVOCs) by EPA Method 8270. Given the relatively high mobility of fuel oxygenates, Versar proposes analyzing for these constituents in both source and downgradient monitoring locations (MW-1, MW-3, MW-4 and MW-5). Given the relatively lower mobility of SVOCs, Versar proposes analyzing for SVOCs in source wells only (MW-1 and MW-3). Additional recommendations for the Site will be provided in subsequent quarterly monitoring reports.

5.0 REFERENCES

ACEHS, 1998, Workplan for investigation at 2585 Nicholson Street, San Leandro, CA, November 17, 1998.

ACEHS, 1999a, Addendum to workplan for investigation at 2585 Nicholson Street, San Leandro, CA, January 4, 1999.

ACEHS, 1999b, Addendum to workplan for investigation at 2585 Nicholson Street, San Leandro, CA, February 01, 1999.

McLaren/Hart, 1998, Soil and Groundwater Characterization, 2585 Nicholson Street, San Leandro, California, May 1, 1998.



Versar, 1998a, Workplan for Well Installation, Development, and Sampling, 2585 Nicholson Street in San Leandro, California. November 4, 1998.

Versar, 1998b. Addendum to the Workplan for Well Installation, Development, and Sampling 2585 Nicholson Street in San Leandro, California. December 23, 1998.


6.0 STATEMENT OF LIMITATIONS


The conclusions presented above are based on the agreed-upon scope of work outlined in Section 1.1. Versar makes no warranties or guarantees as to the accuracy or completeness of information provided or compiled by others and used by Versar. It is possible that information exists beyond the scope of this investigation. Also, changes in Site use may have occurred sometime in the past due to variations in rainfall, temperature, water usage, economic, agricultural, or other factors. Additional information that was not found or available to Versar at the time of the writing of this report may result in a modification of the conclusions presented. This report is not a legal opinion.


The services performed by Versar have been conducted in a manner consistent with the level of care ordinarily exercised by members of our profession currently practicing under similar conditions. No other warranty expressed or implied is made.




FIGURES











TABLES

Table 1
Groundwatwer Elevation Data
2585 Nicholson Street
San Leandro, California

			Grou	ndwater Monitorin	g Well		Hydraulic gradient	General gradient	
		MW-1	MW-1 MW-2 M		MW-4	MW-5	magnitude (ft/ft)	direction	
Well casing eleva	ation (feet amsl)	15.27	13.69	15.88	15.25	16.46			
April 29, 1999	Depth to groundwater (feet bgs)	5.33	3.76	5.88	5.40	6.64			
	Groundwater Elevation (feet amsl)	9.94	9.93	10.00	9.85	9.82	0.001	Southeast	






Table 2
Analytical Results for Groundwater Samples
2585 Nicholson Street
San Leandro, California

					C	nemicals of Cond	ern			
Monitoring		TPH-G	TPH-D	ТРН-МО	Benzene	Toluene	Ethylbenzene	Total Xylenes		TPH-SS
Well No.	Date	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	TPH-K (mg/L)	(µg/L)
MW-1	June 6, 1992	10,000	ND	NA	110	81	62	280	NA	NA
	November 9, 1992	9,800	ND	NA	23	14	22	96	NA	NA
	April 23,1993	18,000	560	ND	42	47	50	190	ND	370
	July 28, 1993	27,000	ND	ND	40	45	63	190	ND	ND
	December 10, 1993	7,800	3,800	ND	13	16	20	77	ND	ND
	March 14, 1994	280,000	620	ND	970	880	620	1,700	ND	3,300
	June 30, 1994	8,500	ND	ND	23	13	8.5	19	ND	ND
	September 14, 1994	2,400	52	ND	5.3	2.6	2.5	6	ND	ND
	December 14, 1994	4,800	1,300	ND	32	32	16	50	ND	1,000
	April 20, 1995	74,000	3,700	ND	320	350	350	940	ND	570
	September 5, 1995	33,000	46,000	ND	140	270	260	1,100	ND	4,900
	May 7, 1999	8,100	ND	ND	1,400	31	82	360	NA	NA
MW-2	April 29, 1999	ND	ND	ND	ND	ND	ND	ND	NA	NA
MW-3	April 29, 1999	ND	540	ND	ND	ND	ND	ND	NA	NA
MW-4	April 29, 1999	110	ND	ND	ND	ND	ND	ND	NA	NA
MW-5	April 29, 1999	270	ND	ND	ND	ND	ND	ND	NA	NA

Notes and Abbreviations:

TPH-G = total petroleum hydrocarbons as gasoline.

TPH-K = total petroleum hydrocarbons as kerosene.

TPH-SS = total petroleum hydrocarbons as stoddard solvent.

μg/L = micrograms per litter, equivalent to parts per billion (ppb).

mg/L = milligrams per litter, equivalent to parts per million (ppm).

ND = not detected at or above the methods reporting limit.

NA = not analysed





APPENDIX A

Well Installation and Encroachment Permits

VERSAR, INC.



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION 951 TURNER COURT, SUITE 300, HAYWARD, CA 94545-2651 PHONE (4)0) 670-5579 ANDREAS GODFREY FAX (\$10) 670-5262 (510) 678-5248 ALVIN KAN

DRILLING	PERMIT APPLICATION
FOR APPLICANT TO COMPLETE LOCATION OF PROJECT 2585 NICHOLION ST., SAN LEANORD	FOR OFFICE USE PERMIT NUMBER 99 W R 154 WELL NUMBER 150
California Coordinates Source CCA (i. CCE fi. Accuracy = 1.	PERMIT CONDITIONS Circled Permit Requirements Apply
CLIENT NAME BANK OF AMERICA Address 4000 MCARTHUR BLVN Phone (AME) 260-581 CITY MELIPORT BETICH ZIP F 2660 APPLICANT NAME VERSAR INC. (SOTT ALLIN) Address TRUM MADILON AUF, FTE 16 Phone (916) 867-972 CITY FAIR OAKS ZIP 97728	A. GENERAL 1. A permit application should be submitted so as to arrive as the ACPWA office flive days prior to proposed starting date. 2. Submit to ACPWA within 60 days after completion of permitted work the original Department of Water Resources Water Well Drillers Report or adjuvation of well projectly, or drilling logs and location sketch for a section of permitted in the content of well projectly.
TYPE OF PROJECT Well Construction	3) Permit is vaid if project not begun within 90 days of approvat date. B. WATER SUPPLY WELLS 1. Minimum surface seal thickness is two inches of cement grout placed by themse. 2. Minimum seal depth is 50 fact for municipal and industrial wells or 20 fact for domestic and irrigation wells unless a lesser depth is spacially approved. C. GROUNDWATER MONITORING WELLS.
Municipal O Imagation O Industrial O Other C C Cable O Other C C	INCLUDING PIEZOMETERS 1. Minimum surface seal thickness is two inches of cament grout placed by romic. 2. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet. D. CEOTECHNICAL

E. CATHODIC

F. WELL DESTRUCTION See ausehed.

C. SPECIAL CONDITIONS

Cable Other ORILLER'S LICENSE NO C-57 582696

WELL PROJECTS Drill Hole Diameter Mumira)4 Casing Diameter Depih . Surface Seal Depth .. GEOTECHNICAL PROJECTS Number of Borings Maximum Hale Diameter ____

Depth ESTIMATED STARTING DATE ISTIMATED COMPLETION DATE

Accepy agree to comply with all requirements of this permit and Vameda County Ordinance No. 73-63.

Backfill bort hale with compacted cultings or heavy

benjanis and upper two feet with compacted material in areas of known or suspecied confamination, bemied cement grows shall be used in place of compacted cuttings.

Fill hold above anode zone with concrete placed by framia.

CARTICANT'S IGNATURE

CITY OF SAN LEANDRO APPLICATION TO PERFORM WORK IN THE PUBLIC RIGHT-OF-WAY

99140
Fermit Number
April 14,1999
Date Approved

Work Site: _	2585 NICHOLION	STREET	- -	adre Apployed
	Vame Scott Action	Address	7844 MADI 40	AVE, STEIGT, FAR OAKSTEI. (916) 87.47
	STAND SCHOUDANTC	Address	Hope macamin	BUVO, TE 100, GERCH TELETA) 260-58
Purpose of i	Permit:			Tel (149) 260-58
STRRET	TEAPPIL RATED 16" , APPROX. I'; N F	DIA, VAUIROM CUR	tter Sidewalk, Dr LLATIAN C LT COVER B	riveway & Other Monitoring W. of one monitoring were part on Nicholson
Plan Submit	ted: Yes No _	×	Profile Subn	nitted Yes No
Date Work to	be Started: 4/15		Date Mork +	nitted Yes No _X
Building Peri	mit No		State Fear	o be Completed by: 4/15
Oro Loma Pe	ermit No	***************************************		achment Permit No
Compliance	with State Labor Code: In accord	ance with Ca.	Marrieda Co	unty Ficod Control Permit No
☐ App	plicant has on file, with the City of S	an Leandre a	vidagas == -	
☐ App	plicant will not employ anyone so	an Leanury, e	vidence that wor	kman's compensation insurance is carried.
			. Ulass	
	plicant is exempt from the State C	Unitractors Li	canse Law for th	ne following reason(s):
	Signature:			needs hereby agree that all work beformed will be incations as adopted by the City. Further, the undersigne charges as billed by the City. Any misrepresentation of Date:
	PLEASE	CALL 577-33	08 FOR INSPECT	Tons
	SPECIAL PROVISION	45		
Backfill Require		NDARI) DE	TAILS & CREAS	PERMIT IS VALID WHEN SIGNED
Pavement Sect	fon Required		W. C. A. DACCZ	1 VI VIS BEITH ANV THE POPULATION I'M
Minimum Depth				complying with all requirements
Polica & Fire D	ept. to be notified 24 hours prior to start: AY TRAFFIC TO BE MAINTAI	YES	NO.X	1 66.46.46.46.6 OLGIDADOBS 3888 88 ===1:
TR TWO IN	MY MAPTIC 10 BE MAINTAI	NEDALAU	TIMES.	regulations, provisions, and specifications adopted by the City.
* Samo	LES REPORT LODY TO BE SUBM	14. TT - 1 TO L	C12 - 52	THE FOR CHY ENGINEER
HAS MAT	CORPUS REVERSE SIDE FOR GENERA APPLICABLE TO ALL PEDMI	MITTEDIOM	IKE BAKALDIN	MITTA
	APPLICABLE TO ALL PERMI	L PROVISIONS T WORK		ARU COM
	INSPECTION RECOR		· ·	
Date	Camments		1	FEES
	Continuents	insp.	Hrs. Charged	PERMIT FEE: 125,00 To Acct. #9206
		+		RESTORE/INSPECT DEPOSIT: To CN #
		1		STREET CUT FEE: TO ACCT #304
(DTC				TOTAL:
OTS: 1 hr, Mini. Gerinani	mum charge Hours forwarded from	ı reverse side: _		All charges collected at permit insurance
Y-ar letable	TOTAL HOURS CHAP	∂ ∕^ ‴⊃-		All charges to be billed to
	CHAP CHAP	40ED; _		CN #



APPENDIX B

Drilling Logs

7	ersar,	Inc	· ·		DRILLI	NG LOG	PROJECT NO. <u>4422-001</u>	
Supervising G	ologist	:	Ti	m Berger, R.	G. 5225	Site Name: B	ANK OF AMERICA - SAN LEANDE	80
Log By:			Aì	NETTE CO	RNELIUS	Boring No: M	1W-2	
Date:			Αŀ	PRIL 15, 199	9	Boring Diameter: 8	INCH	
Drilling Contr	ctor:		C.	AL-NEV GEO	DEXPLORATIONS	Boring Depth: 1	4 feet	
Contractor Lie	No.:		C5	7-582696		Boring Location: N	NICHOLSON STREET-WEST SIDE	
Rig Type:			CN	ME-55		P	ARKING LANE	
Driller:	NINE CONTRACTOR	- opowa	JA	MES FRIET	AS			
overed $\bar{\overline{\overline{\Delta}}}$	iction					SCS SOIL DESCRIP ON AND GEOLOGIC	TION INTERPRETATION	m)
Depth (ft) Advanced/Recovered Retained Blow Counts First Water/	Water Table 11	USCS Group	Lithology	SOIL TY PERCEN GEOLOG	TPE, COLOR, MOIST IT FINES, ROUNDIN GY: FILL, ALLUVIU	IG, SECONDARY PO	ENSITY, ODOR, SORTING, DROSITY	Headspace (ppm)
2	VAUL OX OX	F 70000	\otimes	Asphalt Roadbase	e/fill			-
		CL		CLAY:	very dark gray.			
		SM			•	wish brown, very r	noist, 30% silt, fine sand	
4	¥			S	ub-angular.			
6 \ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				Grades to	yellowish brown,	wet, sub-angular	with fine gravel	
8		CL		CLAY: da	ark gray, wet.			
10								
		SM		gra	avel sub-angular		ine sand, sub-angular, 5% fine	
12		CL		Grades to	ery dark gray, mois brown, with dark edium stiff to stiff.	brown and black s	staining, 10% fine gravel	
14				Grades to			nd with 15% fine sand ,	
		***************************************		•	at 14 feet below gr 2/12 mesh sand.	ound surface with	10 feet of 0.01" Slotted screen	
						1,		
						P-944		

	sing	r Geol					DRILLI	NG LOG	PROJECT NO. 4422-001	_					
Ву:	Supervising Geologist: Tim Berger, R.G. 5225							Site Name:	BANK OF AMERICA - SAN LEAND	RO					
	Log By: ANNETTE CORNELIUS								MW-3						
					Al	PRIL 16, 199	9	Boring Diameter:	8 INCH						
Drilling Contractor: CAL-NEV GEOEXPLORATIONS								Boring Depth:	14 feet						
trac	tor	Lic. N	o.:		C5	57-582696		Boring Location:	NORTHWEST CORNER OF SUBJECT	CT					
Тур	e:				Cì	ME-55			PROPERTY - UNDER CANOPY						
ler:	ī		1		JA	MES FRIET									
overed		ŽÃ	ıction							Headspace (ppm)					
Retained	Blow Counts	First Water/ Water Table	Well Constru	USCS Group	Lithology	SOIL TY PERCEN GEOLO	OIL TYPE, COLOR, MOISTURE, STAINING, DENSITY, ODOR, SORTING, ERCENT FINES, ROUNDING, SECONDARY POROSITY								
			VAULT	CL											
		<u>▼</u>		SM		SILTYS	AND: dark grayisl	ı brown, wet, po	oorly sorted, coarse sand to fine						
								Ü							
						Grades to	silty sand no grav	•	brown, odor. OVM readings	254					
				CL		SILTY C	LAY LENS			3.7					
				SM		SANDY	SILT: dark gray, v	wet, fine to medi	um sand.	3.7					
	ler:	Retained :	Retained Blow Counts First Water/ ' Water Table '	Retained Blow Counts First Water/ -			Solit TY PERCEN GEOLO Water Table First Water CL SILTY C Grades to Grades to Grades to Sp SM SILTY C SILTY C SILTY C	SOIL CONDITION SOIL CONDITION SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, COLOR, MOIST PERCENT FINES, ROUNDINGEOLOGY: FILL, ALLUVIU SOIL TYPE, SOIL TYPE, COLOR FILL FILL FILL FILL FILL FILL FILL FIL	JAMES FRIETAS USCS SOIL DESCR SOIL CONDITION AND GEOLOG SOIL TYPE, COLOR, MOISTURE, STAINING, PERCENT FINES, ROUNDING, SECONDARY GEOLOGY: FILL, ALLUVIUM, BEDROCK SILTY CLAY: very dark gray, moist, medi angular calcarious clastes-2mm SILTY SAND: dark grayish brown, wet, po graded with 25% medium gravel. Grades to silty sand with clay. Grades to silty sand no gravel, dark grayish sporadic SILTY CLAY LENS	SOIL TYPE, COLOR, MOISTURE, STAINING, DENSITY, ODOR, SORTING, PERCENT FINES, ROUNDING, SECONDARY POROSITY GEOLOGY: FILL, ALLUVIUM, BEDROCK SILTY CLAY: very dark gray, moist, medium stiff 15%, sub-angular to angular calcarious clastes-2mm SILTY SAND: dark grayish brown, wet, poorly sorted, coarse sand to fine graded with 25% medium gravel. Grades to silty sand with clay. Grades to silty sand no gravel, dark grayish brown, odor. OVM readings sporadic SILTY CLAY LENS					

Versar	Inc	•		DRILLI	NG LOG	PROJECT NO. 4422-001	-
Supervising Geologis	t:	Tir	n Berger, R.	G. 5225	Site Name: BA	ANK OF AMERICA - SAN LEANDI	RO
Log By:		AN	INETTE CO	RNELIUS	Boring No: M	W-4	
Date:		AP	RIL 15, 199	9	Boring Diameter: 8 I	NCH	
Drilling Contractor:		CA	L-NEV GEO	OEXPLORATIONS	Boring Depth: 15	feet	
Contractor Lic. No.:		C5	7-582696		Boring Location: 259	1 NICHOLSON STREET	
Rig Type:		CN	1E-55		CE	NTER OF PARKING AREA ADJA	CENT
Driller:		JA	MES FRIET			AND SOUTH OF SUBJECT PROP	ERTY
overed					SCS SOIL DESCRIPT ON AND GEOLOGIC		m)
Depth (ft) Advanced/Recovered Retained Blow Counts First Water/ '	USCS Group	Lithology	SOIL TY PERCEN GEOLO		IG, SECONDARY PO	NSITY, ODOR, SORTING, ROSITY	Headspace (ppm)
2			Asphalt Fill				
000) CL			•		o dry, 5% to 10% silt	
4			Grades to	very dark grayish	orown, medium st	iff, 5% sub-angular 3mm sand	
6			ì	o dark grayish brov ıb-angular 3mm sa		ing, stiff, silt sand, 5%	
8	SM		SILTY S	AND: dark yellow	rish brown, 10% sil	t, 5% sub-angular 3mm sand.	
	a		SILTY C	LAY: very dark g	ray, soft.		
10							
12							
14			CLAY:				
16			Well	set at 15 feet below screen in 2/12 n	_	with 10 feet of 0.010' Slotted	
A 9							
18							
		•					

	agamoonga ad	Ver	sar,	Inc	•		DRILLI	NG LOG	PROJECT NO	4422-001					
Superv	ising	g Geol	ogist:		Tin	n Berger, R.	G. 5225	Site Name: B	ANK OF AMERICA	A - SAN LEANDR	RO				
Log By	/ :				AN	NETTE CO	RNELIUS	Boring No: M	IW-5						
Date:					AP	RIL 15, 199	9	Boring Diameter: 8	INCH						
Drilling	g Co	ntracto	or:		CA	L-NEV GE	OEXPLORATIONS	Boring Depth: 1'	7 feet						
Contrac	ctor	Lic. N	o.:		C5	7-582696		Boring Location: W	/INTERLAND PRO REA	PERTY PARKING	G				
Rig Ty	pe:				CM	1E-55		A	KEA						
Driller:	<u>.</u>		-	T	JA	MES FRIET									
overed		ĀĀ	ıction					SCS SOIL DESCRIP ON AND GEOLOGIC		N	(mc				
Depth (ft) Advanced/Recovered	Ketained Blow Counts	First Water/ Water Table	Well Construction	USCS Group	Lithology	PERCEN	YPE, COLOR, MOIST NT FINES, ROUNDIN GY: FILL, ALLUVIU	IG, SECONDARY PO		RTING,	Headspace (ppm)				
2			VAULT	CL		Asphalt Fill									
				CL			CLAY: very dark, r	noist		HH14 H					
6						Grades to	rades to very dark grayish brown, moist, 5% 4mm sub-angular, 20% silt								
10		Y		SW	1	SAND: (olive, 90% sand								
12				CL		SILTY C	LAY: olive gray.				1.6				
14 16						collaps	le initially advance of borehole prevand well set at 15 screen in 2/12 mes	rented properly set feet bgs with 10 fe	ting well. Boreho	le advanced to					
							•								



APPENDIX C

Groundwater Monitoring Well Development Tables



Project Number: 4422-001		Site Name: Bank of America - San Leandro						
Well Number: MW Z			Date(s) Developed: 4/26/99					
OVA - Ambient:			Developmen	t Method: Dedic				
OVA - Vault: 22			Development Rate: 134 0/ mm					
OVA - Casing	OVA - Casing: Seq Water Level - Initial: 3.76' @ 1053 Water Level - Final: 3.9 @ 1446 Well Depth: 14.2			Developed By: Dale Anderson Free Product: NOI) Sheen: NONE Odor: NONE				
Water Level -								
Water Level -								
Well Depth: /								
Well Diameter			Well Casing	Volume: /	7 gal			
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pН	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity		
1037	, Z Ś	66.2	J. 76	949	Ne	mac		
1102	2	65.4	6.57	825	1/	Mac		
1107	4 C	65.1	G. 47	580	17	4		
1111	Ċ	64.9	6.41	830	17	1		
1116	· K	047	6.46	855	7.	1/		
1120	10	64.8	6.43	85-	11	1/		
1129	12	64.4	6.41	894	11	1/		
1134	14	64,2	6.43	807	1/	Þ		
1139	16	64,5	6.47	55/	//	11		
1144	.18	64.6	6.35	537	1 /	MOD		
,								
		ć.	es:		1			
Field Notes:								



Project Number: 4422-001			Site Name: Bank of America - San Leandro				
Well Number: Maj 3			Date(s) Developed: 4/26/99				
OVA - Ambient: O2, ppm			Development Method: Dedicated Disposable Bailer				
OVA - Vault: $2 ppn/$			Developmen	t Rate: 133	8/min		
OVA - Casing: 240 Water Level - Initial: 5.85@ 132 Water Level - Final: 6.0 @ 1018 Well Depth: 13.9			Developed By: Dale Anderson Free Product: U0				
			Odor:				
			•	r: 2 160/H	<u></u>	Well Casing	Volume: /
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pH	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity	
0936	, 2: 5	61.0	7.01	1268	NR	MOD	
0940	1	59.8	6.99	1000	10	1961+	
0943	ک	60.3	1.92	864	1/	11	
6948	· <i>4</i>	60.0	6.65	661	17	r	
0952	C	60.9	6.55	776	1 /	r	
958	\$	60.5	6.41	554	7 1	11	
1004	10	61.0	6-43	5/3	11	11	
1010	17.	41.0	\$6.20	488	11	11	
1013	- 13	60. 75°	6.11	539:	z. 11 .	. /	
1017	7.14	60,37	6.13	577	- //	W. T.	
4					and the second	1	
	Parace			**		The state of the s	
	*	1,484.		.21	الداملة الأثاث حاليا		
			÷	The state of the s		A. The State of th	



Decidet Number: 4422-001			Site Name: Bank of America - San Leandro				
1/1/4 . 1			Date(s) Developed: 4/26/99 Development Method: Dedicated Disposable Bailer				
OVA - Ambient: / PAM			Development 1		,	e Baller	
OVA - Vault:	2 PPW		Development				
OVA - Value			Developed By: Dale Anderson				
OVA - Casing.			Free Product:				
Water Level - Hittai.			Sheen:				
Water Level - Film.			Odor:		1		
Well Depth: /	. 7		Well Casing	Volume: 1, 4	But		
Well Diameter Time	Purge Water Removed (gal)	Temperature (degrees	pH	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity	
		Fahrenheit)	6.35	1809	NA	MOL	
1230	23	68.6	6.29	1263	1.7	HIGH	
1234	1	60,0	6.29	1423	1/	E.	
12-36	2	1.60.	6.25	1050	11	1	
1240	4	63.6	1.6.26	1088	11	11 "	
1244	6	165.5	1 44	1004	((1/	
1249	8	65,6	1 6.11	951	. (/	11	
123F	1.0	(1) 10	1007	10.60	71	11	
1258	1/2		77.70	984	In 1/ 3		
1303	14		389		14	5 1/3	
3/306	15	16077			100		
4,	4	THE RESERVE OF THE PARTY OF THE					
7		9.7		1 201 201			
					The state of the s	4 20 15	
	A		A STATE OF THE PARTY OF THE PAR		*		




Project Number: 4422-001			Site Name: Bank of America - San Leandro					
Well Number: Mw 5			Date(s) Developed: 4/26/99					
OVA - Ambient: O PPM			Development Method: Dedicated Disposable Bailer					
OVA - Vault: O DOW			Development Rate: ,439 /www					
OVA - Casing				Developed By: Dale Anderson				
Water Level -	Water Level - Initial: (0.60 @ /336			Free Product: None				
Water Level - Final: 8-8 @ 1421			Sheen: NONE					
Well Depth: / 5.55			Odor: NONE					
	Well Diameter: \nearrow			Well Casing Volume: 1.500				
Time .	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pН	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity		
1343	125	61.4	6.50	1620	NR	low		
1345	-/	61.9	6.50	1885	11	Holy		
1348	7	6/0	660	1698	1.7	//		
1353	4	NB	NR	1 VR	ſ Į	1/		
1358	. 6	65.4	6.61	1260	"tr	11		
1402	8	.WR	NR-	NR	NR	1 .		
44ac	310 ×	165.70	7,38	122/	11	11		
14/2	12	61.8	7.09	1140	11	11		
1476	/ 4	16019	6.86	1125	71	4 2		
1818	150	60.80	6.76	1104	17 6	4		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			**	A State of the sta	\$ "			
			**					
***)		5		NAME OF THE PROPERTY OF THE PR			
	x; 🗳	W at	3			-		
Field Notes:								



APPENDIX D

Surveyor's Report



DESCRIPTION	NORTHING	EASTING	ELEV (PVC)	ELEV (BOX)
WW-1	5000.0	5000.0	15.27	15.82
MW-2	5115.7	5068.6	13.69	14.10
MW-3	5037.9	4932.4	15.88	16.38
MW-4	4974.7	5095.8	15.25	15.68
MW-5	4867.8	4975.6	16.46	16.57

GRID IS ARBITRARY.

PROJECT ASSUMED NORTH 27" WEST IS THE IMPROVEMENTS ALONG NICHOLSON STREET.

ELEVATIONS BASED ON THE ENCASED MONUMENT AT THE INTERSECTION OF FAIRWAY AND NICHOLSON STREETS. ELEVATION 13.873 FEET.

120 180 SCALE IN FEET

2585 Nicholson Street San Leandro Alameda County California



1450 Harbor Boulevard Suite D West Sacramento, CA 95691 (916) 372-8124

Date: April 30, 1999 Scale: 1"=60' Sheet 1 of 1 Revised:

Book: 492 Drawing No. 8517-002



APPENDIX E

Groundwater Monitoring Well Purge Tables



Project Number:	4422-001		Site Name: Bank of America - San Leandro					
Well Number: Mul7			Date(s) Purged: 4/29/99					
OVA - Ambient:			Purge Method	: Dedicated Dispo	sable Bailer			
OVA - Vault:			Purge Rate:	.25 8/m	·~			
OVA - Casing:	NR		ŀ	Sampled: 4/29/99		1		
Water Level - Initial: 3,76 F@ 9.27			Purged & Sam	Purged & Sampled: Dale Anderson				
Water Level - Fi	nal: 3-8+6 /2	238	Sampling Meth	hod: Dedicated D	isposable Bailer			
Well Depth: / L	_		Free Product:	NONE				
Well Diameter: Z / N C H			Sheen: A	JOUÉ				
Well Casing Vol	ume: 1.7 #AL		1	IONÉ				
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pH	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity		
1223	. 25	78.6	7.61	1063	1.33	. clen		
1725	1,0	73-6	7.56	9 95.	1,0	MOU		
1228	7:00	72.1	7.33	982		MOR		
1279	3.0	70,5	7.36	976	-84	l /		
1230	3. <i>5</i>	69.5	7.30	972	,89	1/		
1232	4,0	69.5	7.26	978	,43	10		
1235	415	68,0	2.14	953	1.10	11		
1236	5,0	69.1	6.99	467	,87	17		
1237	5,5	68,8	6.98	966	73	11		
		-	_					
1245	Sough	69.7	7.23	968	2.45			
	<u> </u>							
Field Notes:	UNCAP WELL	9:00						



Project Number	: 4422-001		Site Name: Bank of America - San Leandro					
Well Number:	Well Number: MW3			Date(s) Purged: 4/29/99				
OVA - Ambient:	OVA - Ambient:			l: Dedicated Dispo	osable Bailer			
OVA - Vault:	NR			3 9/min				
OVA - Casing:	NR			Sampled: 4/29/99	/	2/1		
Water Level - In	uitial: 5,88 ® Ø	725	Purged & San	pled: Dale Ander	/			
Water Level - Fi	inal: 5.4' @ /-	348	t	hod: Dedicated D				
11	3.9'		Free Product:					
Well Diameter:	2"	***************************************	Į.	JONÉ				
Well Casing Vol	ume: 113 0/		Odor:	JONE				
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pН	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity		
1334	,25	67.9	7.43	462	1.93	clean		
1333	,5	64.2	7.26	567	1.03	MOD		
1337	110	62,7	6.90	C62	1, 2,3	- / /		
1339	1,5	61.9	6.98	553	1.55	2		
.1340	2.0	62.1	6.74	5 64	,94	1/		
1,342	2.5	61.5	6.68	563	1.23	<i>C</i> :		
1344	/ 3 o	61, 9	6.76	555	196	!/		
7345	3, {	61,5	6.89	548	んと	, .		
1347	.N.O	81.9	6.93	542	,87	12		
	1	· · · · · · · · · · · · · · · · · · ·						
1400	Sensol /	•						
,	1				7.			
Field Notes:	JOCAP WEZL 6	9:00			×			



Project Number	·: 4422-001		Site Name: B	ank of America - S	an Leandro	
Well Number:	h1 h . 4	₹.	:			V. II
OVA - Ambient	7770	•		l: Dedicated Dispo	osable Bailer	
OVA - Vault:	1)		Purge Rate:	,3 8/m,		
OVA - Casing:	()		Date & Time S	Sampled: 4/29/99	@ 114C)
	nitial: 5,40 @ 0		i	ipled: Dale Ander		
Water Level - F	inal: 5,75@ //	32	Sampling Met	hod: Dedicated D	isposable Bailer	
Well Depth:) [1,2		Free Product:	HONE		
Well Diameter:	2 INCH		Sheen:	JONE		
Well Casing Vol	lume: 1, 4 oxl		Odor: N	ONE		
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pН	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity
1115	,25	73.0	6.18	1350	1.29	Clear
1117	1.0	70.3	6.93	1309	2.11	416
1119	1.5	68.2	7-21	1214	1.35	11
1(2)	2.0	68.2	7.22	1205	1.36	2/
1123	2.5	e8.2	7-29	1168	1.46	Ł
1125	3.0	68.1	<u>).</u> 25	1153	1.62	11
1127	3-5	64,0	1.26	1158	1.21	1/
1129	4.0	67.8	7.22	1122	1,02	10
1129	4,3	67.8	7.26	[18]	1.25	4
1140	Sarple	71,9	7.4/	1289	2.76	
	UNGAP WEZZ	& 9:00				
Field Notes:	UNCH! WELL					
				र्केट के ब		
		ء.				
		f				

23



MONITORING WELL PURGE TABLE

, 			<u>,</u>				
Project Number	: 4422-001		Site Name: Bank of America - San Leandro				
Well Number:	MN 5		Date(s) Purged: 4/29/99				
OVA - Ambient:	No restand		Purge Method: Dedicated Disposable Bailer				
OVA - Vault:			Purge Rate:	.24 8/Mi	W		
OVA - Casing:			Date & Time S	Sampled: 4/29/99		.d	
Water Level - Initial: 6:64 @ 0948			Purged & Sam	ipled: Dale Ander	son		
Water Level - Final: 6 . 90 @ 101Z				hod: Dedicated D			
Well Depth: 17,55			Free Product:				
Well Diameter: 2 1/2044			Sheen:	NONE			
Well Casing Vol	ume: 1.75	žal	Odor:	NONE			
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pH	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity	
0450	, 25	66.7	7.38	1210	2.63	Clean	
0954	1.0	68.7	6.90	1770	3,08	Lou	
0957	1.5	69,1	6.93	1198	2,32	NON	
1000	2.0	67,3	7.08	1192	34.05	1/	
1001	2.5	66.1	7.10	113-1	Z. ZO	V	
1003	3.0	65.3	7,12	1167	3-08	11	
1005	3.5	65,3	7.11	1127	1.86	Y.	
1007	7.0	65.0	7.13	1147	2.52	1/	
1009	4.5	65.5	7,14	1146	2.23		
l			/	,			
1020	Say le		7.04	1210			
	,						
Field Notes:	VUCAP WER	2 @ 9:00 -	UNDER SLICHT	A S ESSUBE			

America .



Project Number: 4422-001			Site Name: B	Site Name: Bank of America - San Leandro				
Well Number:	Mu, 1		Date(s) Purge	Date(s) Purged: 4/29/99 5/7/99				
OVA - Ambient	: NE		Purge Method	I: Dedicated Dispo	SAC Pundosable Bailer	3		
OVA - Vault:	OVA - Vault: NE			1.6 8/m				
OVA - Casing:)			Date & Time S	Sampled: 4/29/99	7-99 •@			
Water Level - Initial: 5. 45 @ 11 00		Purged & San	npled: Dale Ander	cson				
Water Level - Final: 5.58 @ //53		Sampling Met	hod: Dedicated D	isposable Bailer				
Well Depth: 14		Free Product:	NO					
Well Diameter:		Sheen: M	1200					
Well Casing Volume: / 7.75				Latin April 14	TEO TI	1. 1-1-12-12		
Time	Purge Water Removed (gal)	Temperature (degrees Fahrenheit)	pН	Electrical Conductivity (umhos/cm)	Dissolved Oxygen (mg/l)	Turbidity		
1104	l	65.3	7.07	939	8.76	Low		
1117	10	67.2	6.91	968	7.92	17		
1114	17	66.0	6-82	983	5.63	y		
1121	25	65.0	6.74	974	7.41	11		
1124	30	64.1	6.52	969	5.56	سوروك		
1127	3<	64.3	6.93	957	5.23	11		
1131	40	64.2	6.84	954	C.23	1/		
1135	45	64.2	6.50	958	(7.33	1."		
1140	56.25	64-9	6 79	936	6.36	7		
	// ,	62, G	6.73	9.19	1.70	1/		



APPENDIX F

Laboratory Analytical Report and Chain-of-Custody Documentation

KEMRON Environmental Services 109 Starlite Park Marietta, Ohio 45750

Phone: (/40) 3/3-4071

Login #: L9904571 Report Date: 05/11/99

Date Received: 04/30/99

Work ID: 4422-001/BANK OF AMERICA

Versar, Inc. 7844 Madison Ave.

Suite 167

Fair Oaks, CA 95628

Attention: Mr. Scott Allin

PO Number:

Account Number: VERSAR-CA-503

SAMPLE IDENTIFICATION

Sample	Sample	Sample	Sample		
Number	Description	Number	Description		
L9904571-01	MW5	L9904571-02	MW4	-	
L9904571-03	MW2	L9904571-04	MW3		
L9904571-05	D5.D3.D1.D2/COMP.				

****REVISED REPORT****

All results on solids/sludges are reported on a dry weight basis, where applicable, unless otherwise specified. This report shall not be reproduced, except in full, without the written approval of KEMRON.

NYSBOH ELAP ID: 10861

Dennis S. Tepe



Order #99-04-571 May 11, 1999 13:44

KEMRON ENVIRONMENTAL SERVICES REPORT NARRATIVE

DIESEL RANGE ORGANICS - 8015:

Sample fraction 01 yielded % recoveries for both surrogates that were outside acceptable limits. There was insufficient sample remaining for re-extraction analysis.

Extended carbon range was analyzed on DRO to cover motor oil. The results are non-detect.

Login #L9904571 May 11, 1999 03:10 pm

Product: DRO - Diesel Range Organics (GC)

Sample Weight: N/A Dil. Type: N/A Lab Sample ID: L9904571-01 Extract Volume: N/A COC Info: N/A Client Sample ID: MW5

Site/Work ID: 4422-001/BANK OF AMERICA

% Solid: N/A Date Collected: 04/29/99 Matrix: Water

Method: 8015\3510 Instrument: HP8 TCLP Extract Date: N/A Run ID: R65110 Analyst: HV

Extract Date: 05/03/99 Batch: WG57096 Lab File ID: 005F0101 Analysis Date: 05/06/99 Time: 17:43

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution	
68334-30-5	Diesel Range Organics	ug/L		ND	110	1.05	
SURR	OGATES- In Percent Recovery: o-Terphenyl Octacosane	33.1 * 10.2 *	(49 - 174%) 26 - 152%)			

Product: 802-BETX1 - Volatile Organics (BETX)

Dil. Type: N/A COC Info: N/A Sample Weight: N/A Lab Sample ID: L9904571-01 Extract Volume: N/A Client Sample ID: MW5

Site/Work ID: 4422-001/BANK OF AMERICA Date Collected: 04/29/99 % Solid: N/A

Matrix: Water

Method: 8021B Instrument: HP12 TCLP Extract Date: N/A Analyst: MFB
Lab File ID: 010R0101 Run ID: R65015 Extract Date: N/A Batch: WG57004 Analysis Date: 05/03/99 Time: 15:14

CAS #	Compound	Units	Result Qualifiers	RL	Dilution	
100-41-4	Benzene Ethylbenzene Toluene Xylenes, Total	ug/L ug/L	ND ND ND	1.0 1.0 1.0	1 1 1	
SURR	ROGATES- In Percent Recovery: a,a,a-Trifluorotoluene	101	(82 123%)			

KEMRON ENVIRONMENTAL SERVICES

Login #L9904571 May 11, 1999 03:10 pm

Product: GRO - Gasoline Range Organics

Dil. Type: N/A COC Info: N/A Sample Weight: N/A Lab Sample ID: L9904571-01 Extract Volume: N/A Client Sample ID: MW5

Site/Work ID: 4422-001/BANK OF AMERICA Date Collected: 04/29/99 % Solid: N/A

Matrix: Water

Instrument: HP3 Method: 8015 TCLP Extract Date: N/A Run ID: R65049 Extract Date: N/A Analyst: VMN

Batch: WG57082 Analysis Date: 05/04/99 Time: 22:21 Lab File ID: 3G467

CAS #	Compound	Units	Result Qualifiers	RL	Dilution
8006-61-9	Gasoline Range Organics	ug/L	270	100	1
SURR	OGATES- In Percent Recovery: Chlorobenzene	80.2	(64 - 148%)		

Product: DRO - Diesel Range Organics (GC)

Dil. Type: N/A Sample Weight: N/A Lab Sample ID: L9904571-02 Client Sample ID: MW4
Site/Work ID: 4422-001/BANK OF AMERICA Extract Volume: N/A COC Info: N/A

% Solid: N/A Matrix: Water Date Collected: 04/29/99

Instrument: HP8 Method: 8015\3510 TCLP Extract Date: N/A Run ID: R65110 Extract Date: 05/03/99 Analyst: HV

Lab File ID: 006F0101 Batch: WG57096 Analysis Date: 05/06/99 Time: 20:09

CAS #	Compound	Units	Result Qualifiers	RL	Dilution	
68334-30-5	Diesel Range Organics	ug/L	ND	110	1.1	
	OGATES- In Percent Recovery: o-Terphenyl Octacosane		(49 - 174%) (26 - 152%)			

Login #L9904571 May 11, 1999 03:10 pm

KEMRON ENVIRONMENTAL SERVICES

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-02 Dil. Type: N/A Sample Weight: N/A Client Sample ID: MW4 COC Info: N/A Extract Volume: N/A

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water Date Collected: 04/29/99 % Solid: N/A

TCLP Extract Date: N/A Instrument: HP12 Method: 8021B Extract Date: N/A Analyst: MFB Run ID: R65015

Analysis Date: 05/03/99 Time: 15:52 Lab File ID: 011R0101 Batch: WG57004

CAS #	Compound	Units	Result Qualifiers	RL	Dilution	
100-41-4 108-88-3	Benzene. Ethylbenzene. Toluene. Xylenes, Total	ug/L ug/L	ND ND ND ND	1.0 1.0 1.0	1 1 1 1	
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	96.7	(82 - 123%)			

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-02 Dil. Type: N/A Sample Weight: N/A Client Sample ID: MW4 COC Info: N/A Extract Volume: N/A

ent Sample ID: MW4 COC Info: N/A Extract Volume: N/A Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water Date Collected: 04/29/99 % Solid: N/A

TCLP Extract Date: N/A Instrument: HP3 Method: 8015

 Extract Date: N/A
 Analyst: VMN
 Run ID: R65049

 Analysis Date: 05/04/99
 Time: 23:00
 Lab File ID: 3G468
 Batch: WG57082

CAS #	Compound	Units	Result	Qualifiers	\mathtt{RL}	Dilution	
8006-61-9	Gasoline Range Organics	ug/L	110		100	1	
SURR	OGATES- In Percent Recovery: Chlorobenzene	82.2	(64 - 148%)			

Login #L9904571 May 11, 1999 03:10 pm

TCLP Extract Date: N/A

Product: DRO - Diesel Range Organics (GC)

Lab Sample ID: L9904571-03

Client Sample ID: MW2 Site/Work ID: 4422-001/BANK OF AMERICA Matrix: Water

COC Info: N/A

Dil. Type: N/A

Sample Weight: N/A Extract Volume: N/A

Date Collected: 04/29/99

% Solid: N/A

Instrument: HP8

Method: 8015\3510 Run ID: R65110

Extract Date: 05/03/99 Analysis Date: 05/06/99 Time: 22:35 Analyst: HV Lab File ID: 007F0101

Batch: WG57096

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution	
68334~30-5	Diesel Range Organics	ug/L		ND	110	1.06	
SURR	OGATES- In Percent Recovery: o-Terphenyl Octacosane	53.0 21.5 *		49 - 174%) 26 - 152%)			

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-03

Client Sample ID: MW2

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

TCLP Extract Date: N/A Extract Date: N/A

Analysis Date: 05/03/99 Time: 16:29

Dil. Type: N/A COC Info: N/A

Date Collected: 04/29/99

Instrument: HP12

Analyst: MFB Lab File ID: 012R0101

Sample Weight: N/A Extract Volume: N/A

% Solid: N/A

Method: 8021B Run ID: R65015 Batch: WG57004

CAS #	Compound	Units	Result Qualifiers	RL	Dilution	
100-41-4 108-88-3	Benzene Ethylbenzene Toluene Xylenes, Total	ug/L ug/L	ND ND ND ND	1.0 1.0 1.0	1 1 1	
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	89.0	(82 - 123%)			

KEMRON ENVIRONMENTAL SERVICES

Login #L9904571 May 11, 1999 03:10 pm

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-03

Client Sample ID: MW2

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

TCLP Extract Date: N/A Extract Date: N/A

Analysis Date: 05/05/99 Time: 00:52

Dil. Type: N/A COC Info: N/A

Instrument: HP3

Lab File ID: 3G471

Analyst: VMN

Date Collected: 04/29/99

Sample Weight: N/A Extract Volume: N/A

% Solid: N/A

Method: 8015 Run ID: R65050

Batch: WG57082

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution	
8006-61-9	Gasoline Range Organics	ug/L		ND	100	1	
SURR	COGATES- In Percent Recovery: Chlorobenzene	80.5	(64 - 148%)			

Product: DRO - Diesel Range Organics (GC)

Lab Sample ID: L9904571-04 Client Sample ID: MW3

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

TCLP Extract Date: N/A

Extract Date: 05/03/99

Analysis Date: 05/07/99 Time: 01:01

Dil. Type: N/A COC Info: N/A

Date Collected: 04/29/99

Instrument: HP8 Analyst: HV

Lab File ID: 008F0101

Sample Weight: N/A Extract Volume: N/A

% Solid: N/A

Method: 8015\3510 Run ID: R65111 Batch: WG57096

CAS	#	Compound	Units	Result	Qualifiers	RL	Dilution	
68334	-30-5	Diesel Range Organics	ug/L	540		100	1.03	
	SURR	OGATES- In Percent Recovery: o-Terphenyl Octacosane	67.9 29.8	(49 - 174%) 26 - 152%)			•

Loqin #L9904571 May 11, 1999 03:10 pm

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-04

Client Sample ID: MW3 Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

TCLP Extract Date: N/A Extract Date: N/A

Analysis Date: 05/03/99 Time: 17:07

Dil. Type: N/A COC Info: N/A

Instrument: HP12

Analyst: MFB

Lab File ID: 013R0101

Date Collected: 04/29/99

Sample Weight: N/A Extract Volume: N/A

% Solid: N/A

Method: 8021B

Run ID: R65015 Batch: WG57004

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution
71-43-2	Benzene Ethylbenzene Toluene Xylenes, Total	ug/L ug/L		ND ND ND ND	1.0 1.0 1.0	1 1 1 1
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	113	(82 - 123%)		-

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-04

Client Sample ID: MW3

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

COC Info: N/A Date Collected: 04/29/99

Dil. Type: N/A

% Solid: N/A

Sample Weight: N/A

Extract Volume: N/A

TCLP Extract Date: N/A

Extract Date: N/A

Analysis Date: 05/05/99 Time: 01:30

Instrument: HP3 Analyst: VMN Lab File ID: 3G472 Method: 8015 Run ID: R65050 Batch: WG57082

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution
	Gasoline Range Organics	ug/L		ND	100	1
SURR	OGATES- In Percent Recovery: Chlorobenzene	87.9	(64 - 148%)		

RL = Reporting Limit

Login #L9904571 May 11, 1999 03:10 pm

KEMRON ENVIRONMENTAL SERVICES

Lab Sample ID: L9904571-05

Client Sample ID: D5,D3,D1,D2/COMP. Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Soil

Collected: 04/29/99 N/A

% Solid: 80 COC Info: N/A

Analyte	Units	Result	Qualifiers	RL	Dil	Туре	Analyst	Analysis Date	Time	Method
Percent Solids	% wt.	80		1.0	1	N/A	SMW	05/04/99	14:30	D2216-90
Lead, Total	mg/kg		ND	6.3	1	N/A	JYH	05/05/99	10:42	6010B\3050A
Petroleum Hydrocarbons	mg/kg		ND	31	1	N/A	MPM	05/04/99	19:50	418.1

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-05

Client Sample ID: D5,D3,D1,D2/COMP. Site/Work ID: 4422-001/BANK OF AMERICA Matrix: Soil

Dil. Type: N/A COC Info: N/A

Sample Weight: N/A

Extract Volume: N/A

Date Collected: 04/29/99

% Solid: 80

TCLP Extract Date: N/A

Extract Date: N/A

Analysis Date: 05/03/99 Time: 12:43

Instrument: HP5 Analyst: MFB

Lab File ID: 5G295

Method: 8021B Run ID: R64806 Batch: WG57000

CAS #	Compound	Units	Result Qualifiers	RL	Dilution
100-41-4 108-88-3	Benzene. Ethylbenzene. Toluene. Xylenes, Total	ug/kg ug/kg	ND ND 38 16	6.3 6.3 6.3	5 5 5 5
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	115	(34 - 175%)		

Order #: 99-04-571 May 11, 1999 03:10 pm

KEMRON ENVIRONMENTAL SERVICES WORK GROUPS

Work			Dil			Date	
Group	Run ID	Sample	Type Matrix	Product	Method	Collected	Department
WG56919	R65110	L9904571-01	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Extraction
WG56919	R65110	L9904571-02	Water	Diesel Range Organics (GC)		29-APR-1999	Extraction
WG56919	R65110	L9904571-03	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Extraction
WG56919	R65111	L9904571-04	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Extraction
WG57000	R64806	L9904571-05	Soil	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC
WG57004	R65015	L9904571-01	Water	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC
WG57004	R65015	L9904571-02	Water	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC
WG57004	R65015	L9904571-03	Water	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC
WG57004	R65015	L9904571-04	Water	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile ~ GC
WG57037	R64967	L9904571-05	Soil	Petroleum Hydrocarbons	418.1	29-APR-1999	Extraction
WG57054	R64934	L9904571-05	Soil	Lead, Total	6010B\3050A	29-APR-1999	Digestion
WG57073	R64952	L9904571-05	Soil	Percent Solids	D2216-90	29-APR-1999	Conventionals
WG57082	R65049	L9904571-01	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC
WG57082	R65049	L9904571-02	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC
WG57082	R65050	L9904571-03	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC
WG57082	R65050	L9904571-04	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile ~ GC
WG57087	R64934	L9904571-05	Soil	Lead, Total	6010B\3050A	29-APR-1999	Metals - ICP
WG57096	R65110	L9904571-01	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC
WG57096	R65110	L9904571-02	Water	Diesel Range Organics (GC)		29-APR-1999	Semivolatile - GC
WG57096	R65110	L9904571-03	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC
WG57096	R65111	L9904571-04	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC

KEMRON ANALYST LIST

Ohio Valley Laboratory

03/30/99

ALC - - Ann L. Clark BAD - - Becky A. Diehl CEB - - Chad E. Barnes CDB - - Christy D. Burton CMS - Crystal M. Stevens CRC - - Carla R. Cochran DIH - - Deanna I. Hesson DLN - - Deanna L. Norton DLP - - Dorothy L. Payne ECL - - Eric C. Lawson FEH - - Fay E. Harmon HV - - Hema Vilasagar JCR - - Jennifer C. Randall ILH - - Janice L. Holland JWR - - John W. Richards JYH - - Ji Y. Hu KHA - - Kim H. Archer KAS - - Kevin A. Stutler KRA - - Kathy R. Albertson MDA - - Mike D. Albertson

MDC - - Michael D. Cochran MES - - Mary E. Schiling MLS - - Michael L. Schimmel MMB - - Maren M. Beery RDC - - Rebecca D. Cutlip RDS - - Rebecca D. Sutton REF - - Ron E. Fertile REK - - Robert E. Kyer RSS - - Regina S. Simmons RWC - - Rodney W. Campbell SIK - - Sindy I. Kinney SJM - - Shawn J. Marshall SLP - - Sheri L. Pfalzgraf SLT - - Stephanie L. Tepe SMW - - Shauna M. Welch SPL - - Steve P. Learn SPS - - Steve P. Swatzel TRS - - Todd R. Stack VC -- Vicki Collier VMN - - Vincent M. Nedell

KEMRON Environmental Services, Inc. LIST OF VALID QUALIFIERS (qual) December 10, 1998

Quali	fier Description	Qualifier	Description
A NA + < > B C *	See the report narrative Not applicable Correlation coefficient for the MSA is less than 0.995 Less than Greater than Present in the method blank Confirmed by GC/MS Surrogate or spike compound out of range	N ND NF NFL NI NR NS P	Tentatively Identified Compound (TIC) Not detected at or above the reporting limit (RL) Not found No free liquid Non-ignitable Analyte is not required to be analyzed Not spiked Concentration > 25% difference between the two GC
CG D DL E F FL I J L	Confluent growth The analyte was quantified at a secondary dilution factor Surrogate or spike was diluted out Estimated concentration due to sample matrix interference Present below nominal reporting limit (AFCEE only) Free liquid Semiquantitative result, out of instrument calibration range Present below nominal reporting limit Sample reporting limits elevated due to matrix interference Duplicate injection precision not met	QNS R RA RE S SMI SP TNTC U W Z	Columns Quantity not sufficient to perform analysis Analyte exceeds regulatory limit Reanalysis confirms reported results Reanalysis confirms sample matrix interference Analyzed by method of standard addition Sample matrix interference on surrogate Reported results are for spike compounds only Too numerous to count Analyzed for but not detected Post-digestion spike for furnace AA out of control limits Can not be resolved from isomer. See below.

Special Notes for Organic Analytes

- 1. Acrolein and acrylonitrile by method 624 are semiquantitative screens only.
- 2. 1,2-Diphenylhydrazine is unstable and is reported as azobenzene.
- 3. N-nitrosodiphenylamine cannot be separated from diphenylamine.
- 4. 3-Methyphenol and 4-Methyphenol are unresolvable compounds.
- $5. \quad \text{m-Xylene and p-Xylene are unresolvable compounds}.$
- 6. The reporting limits for Appendix II/IX compounds by method 8270 are based on EPA estimated PQLs referenced in 40 CFR Part 264, Appendix IX. They are not always achievable for every compound and are matrix dependent.

KEMRON ENVIRONMENTAL SERVICES OHIO VALLEY LABORATORY QUALITY CONTROL SUMMARY

WORKGROUP: wg57087

wgsroor

RUN DATE: 5/5/99

METHOD:

6010B SOIL PREP DATE: 5/4/99

MATRIX: S

ANALYST: JYII

UNITS: INSTRUMENT:

MG/KG IRIS

										PERCENT										
	I						SAMPLE					LCS	LCS			MS	MS	REP	MS	RPD
ANALYTE	RDL.	Blank	T-LCS	LCS	REP1	REP2	RESULT	T-MS	MS	MSD	LCS	LCL	UCL	MS	MSD	LCL	UCL	RPD	RPD	UCL
011	2,000																			
Silver	2.000	ND	10.000	9.730	ND	ND	ИD	10.000	9.260	9.290	97.3	80.0	120.0	92.6	92,9	80.0	120.0	NA	0.32	20
Lead	5.000	ND	50.320	48.400	61.600	116.000	ND	50.000	49.300	49.400	96.2	80.0	120.0	98.6	98.8	80.0	120.0	61.26	0.20	20
Antimony	10.000	ND	50.000	46.500	ИD	ND	ND	50.000	30.400	28.800	93.0	80.0	120.0	60.8	57.6	80.0	120.0	NA	5.41	20
																		0.00	0.00	
		1																0.00	0.00	
		į																0.00	0.00	
		i																0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0 00	
																		0.00	0.00	
																		0.00	0.00	
		ı																0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
																		0.00	0.00	
										l								0.00	0.00	
																		0.00	0.00	
		Ĭ																0.00	0.00	
	1				•					1								0.00	0.00	

NOTES & DEFINITIONS :

RDL = REPORTING DETECTION LIMIT

NA = NOT APPLICABLE

ND = NOT DETECTED

DL = DILUTED OUT (Concentration

of sample > 4X spike concentration)

LCS = LABORATORY CONTROL SAMPLE

T-LCS = TRUE VALUE OF LCS

REP1 = UNSPIKED SAMPLE REPLICATE 1

REP2 = UNSPIKED SAMPLE REPLICATE 2

SAMPLE RESULT = CONCENTRATION OF UNSPIKED MATRIX

T-MS = TRUE VALUE OF MATRIX SPIKE

MS = MATRIX SPIKE

MSD = MATRIX SPIKE DUPLICATE

LCL = LOWER CONTROL LIMIT

UCL = UPPER CONTROL LIMIT

REP RPD = RELATIVE PERCENT DIFFERENCE OF SAMPLE REPLICATES
MS RPD = RELATIVE PERCENT DIFFERENCE OF MATRIX SPIKES

PROJECT NO.	PROJE	CT NAM	E			***************************************		,		7	7		PA	RAME	TERS	ys. V	·	INDUST HYGIENE	RIAL	26 5 7 7
4432-001	BAR	IK O	F	AN	BUCA	SAN L	EAND!	20	/	ا جي ا		./		497	/\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	/ /	- 	HTGIENE	SAMFLE	 €
SAMPLERS: (Signatur	9(1	1			(Printed)	_			CONTAIL		16/	10	T/u	8	(2,80)					
July	My	Moon	4		DALL	ANDERE	SON	/	/ ફ્રેં	/H	(48)	(g)			(5 ×	/ /	/	REMAI	RKS	
FIELD SAMPLE	DATE	TIME	OMP.	GRAB	S.	TATION LOCATION	v	/8	و م		M	1/6		(S S	<i>Y</i> /				33.47	
NUMBER	1999		8	Ü					<u> </u>	$\langle \mathcal{Q} \rangle$	In.		/ 7	× >		_		-		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
MW 5,00	129	1050		X				4				X				X	565	NOT	E	
MWH4		1140						5		_						ļ	11	[1		1
MWZ		1245						5									/ (11		
MW3		1400						5	A	₹	V					<u> </u>	<i>!</i> ("	.,.	
05		1440											X	+		C	OMP	05172	To	ONE
N3		1445	1		>0	COMPOSITE		, 1									11		12 1 1 1 , 1	为数数数
Di		1450				on one	3										1/			
02		145		Ø		ANALYSIS						री	4	4			11	20	न्यू पृथ ितः ।	
Cognition of the Control of the Cont			1									*								1 (1) (1) (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4
																		······································		
				 																
			-	ļ														X		
	<u>L</u>	1	<u> </u>	 	no Boo	ived by (Single	1	D. I	<u></u>	hed by	. (5				Date /	Time.	Dagain	ad buy (c)		1. T. E.
Relinquished by: (Sig	natura)	4/	24/	۱	00	ived by: (Signature,	•	Hei	inquis	neu by	'. (Sigi	nature	,		Date	i iiiie	neceiv.	ed by: (Sign	ature)	
(Printed)	4470-	-2:	11	140	(Print	ed)		(Prir	nted)								(Printed)		
DALE AN	DERS	OL			TO	FADED	又													
Relinquished by: (Sig			Date	e / Tir	ne Rece	ived for Laborator	y by:		Date	/ Tim	e P	Remar	ks S	TA	77	47			_	
								ļ		<u></u>		L	_01	N	DE	720	2770	NU A	LIM	河
(Printed)					(Print	ed)					(QUA	376 Co	PIUS	RESU	675, IN	INVOI	N 16 8-63	-93	25

KEMRON Environmental Services 109 Starlite Park Marietta, Ohio 45750

Phone: (740) 3/3-40/1

Versar, Inc. 7844 Madison Ave.

Suite 167 Fair Oaks, CA 95628

Attention: Mr. Scott Allin

Login #: L9904571 Report Date: 05/07/99

Work ID: 4422-001/BANK OF AMERICA

Date Received: 04/30/99

PO Number:

Account Number: VERSAR-CA-503

SAMPLE IDENTIFICATION

Sample	Sample	Sample	Sample		
Number	Description	Number	Description		
L9904571-01 L9904571-03 L9904571-05	MW5 MW2 D5,D3,D1,D2/COMP.	L9904571-02 L9904571-04	MW4 MW3		

All results on solids/sludges are reported on a dry weight basis, where applicable, unless otherwise specified. This report shall not be reproduced, except in full, without the written approval of KEMRON.

NYSDOH ELAP ID: 10861

Dennis S. Tepe



Order #99-04-571 May 7, 1999 16:13

KEMRON ENVIRONMENTAL SERVICES REPORT NARRATIVE

DIESEL RANGE ORGANICS - 8015:

Sample fraction 01 yielded % recoveries for both surrogates that were outside acceptable limits. There was insufficient sample remaining for re-extraction analysis.

KEMRON ENVIRONMENTAL SERVICES

Product: DRO - Diesel Range Organics (GC)

Lab Sample ID: L9904571-01 Dil. Type: N/A Sample Weight: N/A COC Info: N/A Client Sample ID: MW5 Extract Volume: N/A

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water Date Collected: 04/29/99 % Solid: N/A

TCLP Extract Date: N/A Instrument: HP8 Method: 8015\3510 Extract Date: 05/03/99 Analyst: HV Run ID: R65110

Analysis Date: 05/06/99 Time: 17:43 Lab File ID: 005F0101 Batch: WG57096

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution	
68334-30-5	Diesel Range Organics	ug/L		ND	110	1.05	
SURR	OGATES- In Percent Recovery: o-Terphenyl Octacosane	33.1 * 10.2 *	(49 - 174%) 26 - 152%)			

Product: 802-BETX1 - Volatile Organics (BETX)

Dil. Type: N/A COC Info: N/A Lab Sample ID: L9904571-01 Sample Weight: N/A Client Sample ID: MW5

Extract Volume: N/A Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water Date Collected: 04/29/99 % Solid: N/A

TCLP Extract Date: N/A Instrument: HP12 Method: 8021B Extract Date: N/A Analyst: MFB Run ID: R65015

Analysis Date: 05/03/99 Time: 15:14 Lab File ID: 010R0101 Batch : WG57004

CAS #	Compound	Units	Result Qualifiers	RL	Dilution
100-41-4 108-88-3	Benzene. Ethylbenzene. Toluene. Xylenes, Total	ug/L ug/L	ND ND ND ND	1.0 1.0 1.0	1 1 1 1
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	101	(82 - 123%)		

Login #L9904571 May 7, 1999 04:09 pm

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-01

Client Sample ID: MW5

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

Compound

COC Info: N/A Date Collected: 04/29/99

Dil. Type: N/A

Extract Volume: N/A

Sample Weight: N/A

% Solid: N/A

TCLP Extract Date: N/A

Instrument: HP3 Analyst: VMN

Lab File ID: 3G467

Method: 8015 Run ID: R65049

Batch: WG57082

Extract Date: N/A

CAS #

Analysis Date: 05/04/99 Time: 22:21

Units 8006-61-9 Gasoline Range Organics..... ug/L

Oualifiers Result 270

RL

100

Dilution

1

SURROGATES- In Percent Recovery:

Chlorobenzene.....

80.2

(64 - 148%)

Product: DRO - Diesel Range Organics (GC)

Lab Sample ID: L9904571-02

Client Sample ID: MW4

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

Dil. Type: N/A COC Info: N/A Sample Weight: N/A

Extract Volume: N/A

Date Collected: 04/29/99

% Solid: N/A

TCLP Extract Date: N/A

Extract Date: 05/03/99

Analysis Date: 05/06/99 Time: 20:09

Instrument: HP8 Analyst: HV

48.8 *

51.7

Lab File ID: 006F0101

Method: 8015\3510 Run ID: R65110

Batch : WG57096

CAS # Compound

Units 68334-30-5 Diesel Range Organics..... ug/L

Result

RL 110

Dilution 1.1

SURROGATES- In Percent Recovery:

o-Terphenyl..... Octacosane.....

(49 - 174%)(26 - 152%)

ND

Qualifiers

RL - Reporting Limit

Loqin #L9904571 May 7, 1999 04:09 pm

TCLP Extract Date: N/A

Extract Date: N/A

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-02

Client Sample ID: MW4

Analysis Date: 05/03/99 Time: 15:52

Matrix: Water

Site/Work ID: 4422-001/BANK OF AMERICA

Date Collected: 04/29/99

Dil. Type: N/A COC Info: N/A

Extract Volume: N/A

Sample Weight: N/A

% Solid: N/A

Instrument: HP12

Analyst: MFB

Method: 8021B Run ID: R65015

Lab File ID: 011R0101

Batch: WG57004

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution
100-41-4	Benzene	ug/L ug/L		ND ND ND ND	1.0 1.0 1.0	1 1 1
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	96.7	(82 - 123%)		

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-02

Client Sample ID: MW4

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

Dil. Type: N/A COC Info: N/A

Sample Weight: N/A Extract Volume: N/A

Date Collected: 04/29/99

% Solid: N/A

TCLP Extract Date: N/A

Extract Date: N/A Analysis Date: 05/04/99 Time: 23:00

Instrument: HP3 Analyst: VMN Lab File ID: 3G468 Method: 8015 Run ID: R65049

Batch: WG57082

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution	
8006-61-9	Gasoline Range Organics	ug/L	110		100	1	
SURR	OGATES- In Percent Recovery: Chlorobenzene	82.2	(64 - 148%)			

Login #L9904571 May 7, 1999 04:09 pm

TCLP Extract Date: N/A

Product: DRO - Diesel Range Organics (GC)

Lab Sample ID: L9904571-03

Client Sample ID: MW2 Site/Work ID: 4422-001/BANK OF AMERICA

Analysis Date: 05/06/99 Time: 22:35

Matrix: Water

Extract Date: 05/03/99

Date Collected: 04/29/99

Sample Weight: N/A Extract Volume: N/A

COC Info: N/A

Dil. Type: N/A

% Solid: N/A

Instrument: HP8

Analyst: HV

Method: 8015\3510 Run ID: R65110

Lab File ID: 007F0101

Batch: WG57096

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution
68334-30-5	Diesel Range Organics	ug/L		ND	110	1.06
	OGATES- In Percent Recovery: o-Terphenyl Octacosane	53.0 21.5 *	(49 - 174%) 26 - 152%)		

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-03

Client Sample ID: MW2

Extract Date: N/A

TCLP Extract Date: N/A

Site/Work ID: 4422-001/BANK OF AMERICA

Analysis Date: 05/03/99 Time: 16:29

Matrix: Water

COC Info: N/A

Extract Volume: N/A % Solid: N/A

Sample Weight: N/A

Date Collected: 04/29/99

Dil. Type: N/A

Instrument: HP12

Analyst: MFB Lab File ID: 012R0101 Method: 8021B Run ID: R65015

Batch: WG57004

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution
100-41-4 108-88-3	Benzene. Ethylbenzene. Toluene. Xylenes, Total.	ug/L ug/L		ND ND ND ND	1.0 1.0 1.0	1 1 1
SURR	OGATES- In Percent Recovery: a,a,a-Trifluorotoluene	89.0	(82 - 123%)		

RL Reporting Limit

Login #L9904571 May 7, 1999 04:09 pm

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-03

Client Sample ID: MW2

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

COC Info: N/A Date Collected: 04/29/99

Dil. Type: N/A

Sample Weight: N/A Extract Volume: N/A

TCLP Extract Date: N/A

Extract Date: N/A

Analysis Date: 05/05/99 Time: 00:52

Instrument: HP3 Analyst: VMN

Lab File ID: 3G471

% Solid: N/A Method: 8015

> RL100

Run ID: R65050

Batch: WG57082

Dilution

CAS #	Compound	Units	Result	Qualifiers
8006-61-9	Gasoline Range Organics	ug/L		ND

SURROGATES- In Percent Recovery:

Chlorobenzene.....

80.5

(64 - 148%)

Product: DRO - Diesel Range Organics (GC)

Lab Sample ID: L9904571-04

Client Sample ID: MW3

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

Date Collected: 04/29/99

% Solid: N/A

Sample Weight: N/A

Extract Volume: N/A

TCLP Extract Date: N/A

Extract Date: 05/03/99

Analysis Date: 05/07/99 Time: 01:01

Instrument: HP8

Dil. Type: N/A

COC Info: N/A

Analyst: HV Lab File ID: 008F0101 Method: 8015\3510

Run ID: R65111 Batch: WG57096

CAS #	Compound	Units	Result Qualifiers	RL	Dilution	
68334-30-5	Diesel Range Organics	ug/L	540	100	1.03	
SURR	OGATES- In Percent Recovery: o-Terphenyl Octacosane	67.9 29.8	(49 - 174%) (26 - 152%)			

KEMRON ENVIRONMENTAL SERVICES

Login #L9904571 May 7, 1999 04:09 pm

TCLP Extract Date: N/A

Extract Date: N/A

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-04

Client Sample ID: MW3 Site/Work ID: 4422-001/BANK OF AMERICA

Analysis Date: 05/03/99 Time: 17:07

Matrix: Water

Sample Weight: N/A Extract Volume: N/A

Date Collected: 04/29/99

Dil. Type: N/A

COC Info: N/A

% Solid: N/A

Instrument: HP12

Method: 8021B

Analyst: MFB

Run ID: R65015

Lab File ID: 013R0101

Batch: WG57004

CAS #	Compound	Units	Result Qualifiers	RL	Dilution
100-41-4 108-88-3	Benzene Ethylbenzene Toluene Xylenes, Total.	ug/L ug/L	ND ND ND ND	1.0 1.0 1.0	1 1 1
SURF	ROGATES- In Percent Recovery: a,a,a-Trifluorotoluene	113	(82 - 123%)		

Product: GRO - Gasoline Range Organics

Lab Sample ID: L9904571-04

Client Sample ID: MW3

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Water

Dil. Type: N/A COC Info: N/A

Sample Weight: N/A Extract Volume: N/A

Date Collected: 04/29/99

% Solid: N/A Method: 8015

TCLP Extract Date: N/A Extract Date: N/A

Analysis Date: 05/05/99 Time: 01:30

Instrument: HP3 Analyst: VMN Lab File ID: 3G472

Run ID: R65050 Batch: WG57082

CAS #	Compound	Units	Result	Qualifiers	RL	Dilution	
8006-61-9	Gasoline Range Organics	ug/L		ND	100	1	
SURR	OGATES- In Percent Recovery: Chlorobenzene	87.9	(64 - 148%)			

KEMRON ENVIRONMENTAL SERVICES

Login #L9904571 May 7, 1999 04:09 pm

Lab Sample ID: L9904571-05 Client Sample ID: D5,D3,D1,D2/COMP.

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Soil Collected: 04/29/99 N/A % Solid: 80 COC Info: N/A

Analyte	Units	Result	Qualifiers	RL	Dil	Туре	Analyst	Analysis Date	Time	Method
Percent Solids	% wt.	80		1.0	1	N/A	SMW	05/04/99	14:30	D2216-90
Lead, Total	mg/kg		ИD	6.3	1	N/A	JYH	05/05/99	10:42	6010B\3050A

Product: 802-BETX1 - Volatile Organics (BETX)

Lab Sample ID: L9904571-05

Client Sample ID: D5, D3, D1, D2/COMP.

Site/Work ID: 4422-001/BANK OF AMERICA

Matrix: Soil

Dil. Type: N/A COC Info: N/A

e solid.

Sample Weight: N/A Extract Volume: N/A

Date Collected: 04/29/99

% Solid: 80

TCLP Extract Date: N/A

Extract Date: N/A

Analysis Date: 05/03/99 Time: 12:43

Instrument: HP5
Analyst: MFB
Lab File ID: 5G295

Method: 8021B Run ID: R64806 Batch: WG57000

CAS #	Compound	Units	Result Qualifiers	RL	Dilution
100-41-4 108-88-3	Benzene Ethylbenzene Toluene Xylenes, Total	ug/kg ug/kg	ND ND 38 16	6.3 6.3 6.3	5 5 5 5
SURF	ROGATES- In Percent Recovery:	115	(34 - 175%)		

KEMRON ENVIRONMENTAL SERVICES WORK GROUPS

Work	Run ID Sample Dil Type Matrix			Product	Method	Date Collected	Department	
Group	Kun 11)							
WG56919	R65110	L9904571-01	Water	3 3		29-APR-1999	Extraction	
WG56919	R65110	L9904571-02	Water	Diesel Range Organics (GC)		29-APR-1999	Extraction	
WG56919	R65110	L9904571-03	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Extraction	
WG56919	R65111	1.9904571-04	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Extraction	
WG57000	R64806	L9904571-05	Soil	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC	
WG57004	R65015	L9904571-01	Water	Volatile Organics (BETX)	8021B	29~APR-1999	Volatile - GC	
WG57004	R65015	L9904571-02	Water	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC	
WG57004	R65015	L9904571-03	Water	Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC	
WG57004	R65015	L9904571-04		Volatile Organics (BETX)	8021B	29-APR-1999	Volatile - GC	
WG57054	R64934	L9904571-05	Soil	Lead, Total	6010B\3050A	29-APR-1999	Digestion	
WG57073	R64952	L9904571-05	Soil	Percent Solids	D2216-90	29-APR-1999	Conventionals	
WG57082	R65049	L9904571-01	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC	
WG57082	R65049	L9904571-02	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC	
WG57082	R65050	L9904571-03	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC	
WG57082	R65050	1.9904571-04	Water	Gasoline Range Organics	8015	29-APR-1999	Volatile - GC	
WG57087	R64934	L9904571-05	Soil	Lead, Total	6010B\3050A	29-APR-1999	Metals - ICP	
WG57096	R65110	L9904571-01	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC	
WG57096	R65110	L9904571-02	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC	
WG57096	R65110	L9904571-03	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC	
WG57096	R65111	L9904571-04	Water	Diesel Range Organics (GC)	8015\3510	29-APR-1999	Semivolatile - GC	

KEMRON ANALYST LIST

Ohio Valley Laboratory

03/30/99

ALC - - Ann L. Clark BAD - - Becky A. Diehl CEB - - Chad E. Barnes CDB - - Christy D. Burton CMS - - Crystal M. Stevens CRC - - Carla R. Cochran DIII - - Deanna I. Hesson DLN - - Deanna L. Norton DLP - - Dorothy L. Payne ECL - - Eric C. Lawson FEH - - Fay E. Harmon HV - - Hema Vilasagar JCR - - Jennifer C. Randall JLH - - Janice L. Holland JWR - - John W. Richards JYH - - Ji Y. Hu KHA - - Kim H. Archer KAS - - Kevin A. Stutler KRA - - Kathy R. Albertson

MDA - - Mike D. Albertson

MDC - - Michael D. Cochran MES - - Mary E. Schiling MLS - - Michael L. Schimmel MMB - - Maren M. Beery RDC - - Rebecca D. Cutlip RDS - - Rebecca D. Sutton REF - - Ron E. Fertile REK - - Robert E. Kyer RSS - - Regina S. Simmons RWC - - Rodney W. Campbell SJK - - Sindy J. Kinney SJM - - Shawn J. Marshall SLP - - Sheri L. Pfalzgraf SLT - - Stephanie L. Tepe SMW - - Shauna M. Welch SPL - - Steve P. Learn SPS - - Steve P. Swatzel TRS - - Todd R. Stack VC - - Vicki Collier VMN - - Vincent M. Nedeff

KEMRON Environmental Services, Inc. LIST OF VALID QUALIFIERS (qual) December 10, 1998

Quali	fier Description	Qualifier	Description					
A	See the report narrative	N	Tentatively Identified Compound (TIC)					
NA	Not applicable	ND	Not detected at or above the reporting limit (RL)					
+-	Correlation coefficient for the MSA is less than 0.995	NF	Not found					
<	Less than	NFL	No free liquid					
>	Greater than	NI	Non-ignitable Non-ignitable					
В	Present in the method blank	NR	Analyte is not required to be analyzed					
C	Confirmed by GC/MS	NS	Not spiked					
*	Surrogate or spike compound out of range	P	Concentration > 25% difference between the two GC columns					
CG	Confluent growth	QNS	Quantity not sufficient to perform analysis					
D	The analyte was quantified at a secondary dilution factor	R	Analyte exceeds regulatory limit					
DL	Surrogate or spike was diluted out	RA	Reanalysis confirms reported results					
Е	Estimated concentration due to sample matrix interference	RE	Reanalysis confirms sample matrix interference					
F	Present below nominal reporting limit (AFCEE only)	S	Analyzed by method of standard addition					
FL	Free liquid	SMI	Sample matrix interference on surrogate					
I	Semiquantitative result, out of instrument calibration range	SP	Reported results are for spike compounds only					
J	Present below nominal reporting limit	TNTO	C Too numerous to count					
L	Sample reporting limits elevated due to matrix interference	U	Analyzed for but not detected					
M	Duplicate injection precision not met	W	Post-digestion spike for furnace AA out of control limits					
		Z	Can not be resolved from isomer. See below.					

Special Notes for Organic Analytes

- 1. Acrolein and acrylonitrile by method 624 are semiquantitative screens only.
- 2. 1,2-Diphenylhydrazine is unstable and is reported as azobenzene.
- 3. N-nitrosodiphenylamine cannot be separated from diphenylamine.
- 4. 3-Methyphenol and 4-Methyphenol are unresolvable compounds.
- 5. m-Xylene and p-Xylene are unresolvable compounds.
- 6. The reporting limits for Appendix II/IX compounds by method 8270 are based on EPA estimated PQLs referenced in 40 CFR Part 264, Appendix IX. They are not always achievable for every compound and are matrix dependent.

INORGANIC QA/QC



KEMRON ENVIRONMENTAL SERVICES OHIO VALLEY LABORATORY QUALITY CONTROL SUMMARY

WORKGROUP: wg57087

6010B

RUN DATE: 5/5/99 PREP DATE: 5/4/99

METHOD: MATRIX:

SOIL MG/KG ANALYST: JYH

UNITS: INSTRUMENT:

IRIS

	CONCENTRATION PPM										PERCENT RECOVERY								PERCENT		
					- L		SAMPLE					LCS	LCS			MS	MS	REP	MS	RP	
ANALYTE	RDL	Blank	T-LCS	LCS	REP1	REP2	RESULT	T-MS	MS	MSD	LCS	LCL	UCL	MS	MSD	LCL	UCL	RPD	RPD	UC	
Silver	2.000	ND	10.000	9.730	ND	ND	ND	10.000	9.260	9.290	97.3	80.0	120.0	92.6	92.9	80.0	120.0	NA	0.32	2	
Lead	5.000	МD	50.320	48.400	61.600	116.000	ND	50.000	49.300	49.400	96.2	80.0	120.0	98.6	98.8	80.0	120.0	61.26	0.20	2	
Antimony	10.000	ИD	50.000	46.500	ND	ND	ND	50.000	30.400	28,800	93.0	80.0	120.0	60.8	57.6	80.0	120.0	NA	5.41	:	
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00	٠	
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
																		0.00	0.00		
					•													0.00	0.00		

NOTES & DEFINITIONS:

RDL = REPORTING DETECTION LIMIT

NA = NOT APPLICABLE

ND = NOT DETECTED

DL = DILUTED OUT (Concentration

of sample > 4X spike concentration)

LCS = LABORATORY CONTROL SAMPLE

T- LCS = TRUE VALUE OF LCS

REP1 = UNSPIKED SAMPLE REPLICATE 1

REP2 = UNSPIKED SAMPLE REPLICATE 2

SAMPLE RESULT = CONCENTRATION OF UNSPIKED MATRIX

T-MS = TRUE VALUE OF MATRIX SPIKE

MS = MATRIX SPIKE

MSD = MATRIX SPIKE DUPLICATE

LCL = LOWER CONTROL LIMIT

UCL = UPPER CONTROL LIMIT

REP RPD = RELATIVE PERCENT DIFFERENCE OF SAMPLE REPLICATES

MS RPD = RELATIVE PERCENT DIFFERENCE OF MATRIX SPIKES

ORGANIC QA/QC



Kemron Environmental Services

Volatile Quality Control Summary

Method 8021B

Run Date:	3-May-99	Blk Flnm	5G289
Instrument:	HP 5	LCS Flnm	5G288
Analyst:	MFB	Shift	АМ
Work Group:	WG57000		
Matrix	Soil		

Sample # 0	04-570-01
Flnm	5G290
MS Flnm	5G291
MSD Flnm	5G292
DF	1

Daily QA	Method			LCS					MS	MSD					С	utliers	;
Information	Detection	Method	LCS	Percent	Control	Sample	MS	MSD	Percent	Percent	Advisory	Percent	Advisory				
	Limit	Blank	20 ug/L	Recovery	Limits	Result	20 ug/L	20 ug/L	Recover	Recover	Limits	RPD	Limit	LCS	MS	MSD	%RPD
Analyte List	ug/kg	ug/kg	ug/kg	% Rec	% Rec	ug/kg	ug/kg	ug/kg	% Rec	% Rec	% Rec	% RPD	% RPD				
methyl-tert-butyl ether	0.898	NA	NA	NA	69 - 121	NA	NA	NA	NA	NA	69 - 121	NA	15				
benzene	0.419	ND	21.2	106.0	74 - 121	ND	19.2	17.3	95.9	86.5	74 - 121	10.4	20				
toluene	0.434	ND	19.3	96.6	74 - 120	ND	16.3	14.2	81.4	71.2	74 - 120	13.4	19			L	
chlorobenzene	0.398	NA	NA	NA	85 - 121	NA	NA	NA	NA	NA	85 - 121	NA	24				
ethylbenzene	0.406	ND	20.7	103.4	75 - 127	ND	16.4	14.1	81.8	70.6	75 - 127	14.7	19			L	
m+p-xylene	0.84	ND	41.8	104.5	76 - 125	ND	31.9	27.7	79.9	69.3	76 - 125	14.2	19			L	
o-xylene	0.84	ND	20.6	103.0	76 - 125	ND	16.7	15.1	83.6	75.5	76 - 125	10.3	19			L	
xylene (total)	0.84	ND	62.4	104.0	76 - 125	ND	48.7	42.8	81.1	71.3	76 - 125	12.9	19			L	
1,3-dichlorobenzene	0.389	NA	NA	NA	80 - 120	NA	NA	NA	NA	NA	80 - 120	NA	15				
1,4-dichlorobenzene	0.399	NA	NA	NA	80 - 120	NA	NA	NA	NA	NA	80 - 120	NA	15				
1,2-dichlorobenzene	0.649	NA	NA	NA	80 - 120	NA	NA	NA	NA	NA	80 - 120	NA	16				

Surrogate Recovery	Blank	% Rec	LCS	% Rec	SMPL	% Rec	MS	% Rec	MSD	% Rec	Recovery Limits	BLK	LCS	MP	MS	MSD
a,a,a-Trifluorotoluene	27.6	91.9	29.4	98.1	29.1	97.1	27.0	90.0	23.7	78.9	47 - 121					
p-Bromofluorobenzene	NA	NA	NA	NA	NA	NA	NA	. NA	NA	NA	47 - 121					

Notes and Definitions

MDL = Method Detection Limit

UPL = Upper Control Limit

DL = Diluted Out

BLK = Method Blank

SMPL = Sample Results

RPD = Relative Percent Difference

SS = Surrogate Standard

LCS = Laboratory Control Sample

ND = Not Detected NA = Not Applicable L = Low

H ≈ High

MS/MSD = Matrix Spike / Matrix Spike Duplicate

Kemron Environmental Services

Volatile Quality Control Summary

Method 8021B

Run Date:	3-May-99	Blk Flnm	008R0101
Instrument:	HP12	LCS Finm	009R0101
Analyst:	MFB	Shift	AM
Work Group:	WG57004		
Matrix	□ Water	1	

Sample #	04-571-01
Flnm	010R0101
MS Flnm	014R0101
MSD Flnm	015R0101
DF	1

Daily QA	Method			LCS					MS	MSD					C	Outliers	
Information	Detection	Method	LCS	Percent	Control	Sample	MS	MSD	Percent	Percent	Advisory	Percent	Advisory				
	Limit	Blank	20 ug/L	Recovery	Limits	Result	20 ug/L	20 ug/L	Recover	Recover	Limits	RPD	Limit	LCS	MS	MSD	%RPD
Analyte List	ug/L	ug/L	ug/L	% Rec	% Rec	ug/L	ug/L	ug/L	% Rec	% Rec	% Rec	% RPD	% RPD				
methyl-tert-butyl ether	0.453	NA	NA	NA	56 - 149	NA	NA	NA	NA	NA	56 - 149	NA	16				
benzene	0.339	ND	20.7	103.6	78 - 122	ND	19.9	22.3	99.4	111.7	78 - 122	11.6	15				
toluene	0.541	ND	20.5	102.3	78 - 123	ND	17.3	20.1	86.4	100.3	78 - 123	15.0	15				
chlorobenzene	0.418	NA	NA	NA	70 - 128	NA	NA	NA	NA	NA	70 - 128	NA	24				
ethylbenzene	0.43	ND	21.0	105.2	80 - 129	ND	17.9	20.7	89.7	103.3	80 - 129	14.1	16				
m+p-xylene	0.81	ND	40.7	101.9	80 - 124	ND	34.6	39.9	86.4	99.7	80 - 124	14.3	16				
o-xylene	0.81	ND	20.5	102.3	80 - 124	ND	17.6	20.2	88.2	100.8	80 - 124	13.3	16			1	
xylene (total)	0.81	ND	61.2	102.0	80 - 124	ND	52.2	60.1	87.0	100.1	80 - 124	14.0	16				
1,3-dichlorobenzene	0.385	NA	NA	NA	81 - 110	NA	NA	NA	NA	NA	81 - 110	NA	15				
1,4-dichlorobenzene	0.346	NA	NA	NA	78 - 107	NA	NA	NA	NA	NA	78 - 107	NA	16				
1,2-dichlorobenzene	0.352	NA	NA	NA	84 - 112	NA	NA	NA	NA	NA	84 - 112	NA	15				

Surrogate Recovery	Blank	% Rec	LCS	% Rec	SMPL	% Rec	MS	% Rec	MSD	% Rec	Recovery Limits	BLK	LCS	SMPL	MS	MSD
a,a,a-Trifluorotoluene	28.7	95.7	30.1	100.4	30.2	100.8	29.4	98.1	30.4	101.3	70 - 130					
p-Bromofluorobenzene	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	70 - 130					

Notes and Definitions

MDL = Method Detection Limit

UPL = Upper Control Limit

DL = Diluted Out

BLK = Method Blank

RPD = Relative Percent Difference

SS = Surrogate Standard

LCS = Laboratory Control Sample

ND = Not Detected

L = Low

SMPL = Sample Results

NA = Not Applicable

H = High

MS/MSD = Matrix Spike / Matrix Spike Duplicate

Kemron Environmental Services

Volatile Quality Control Summary Method 8015B

Workgroup	WG57082
RunDate	4-May-99
Matrix:	WATER
Instrument	HP 3
Analyst	VMN

BLK FLNM:	3G465
LCS FLNM:	3G466
SMPL Num:	04-571-02
SMPL FLNM:	3G468
MS FLNM:	3G469
MSD FLNM:	3G470

LCS DF:	1
SMPL DF:	1
MS DF:	1
MSD DF:	1

Daily QA				Concer	ntration,	PPB					Percent	Reco	very			% F	RPD	Outliers				
Information				LCS Spike				MS Spike		LCS				MS	6	мѕ	RPD					
	MDL	BLK	LCS	Level	SMPL	MS	MSD	Level	LCS	Limit	N	/IS	MSD	Lim	nit	RPD	UCL	LCS	мѕ	MSD	%F	RPD
Target Analytes	ug/L	ug/L	ug/L	ug/L	ug/L	ug/L	ug/L	ug/L	%	%	(%	%	%		%	%					
GRO	26.46	ND	938.8	900.0	113.4	1000.8	1012.1	900.0	104.3	84 - 11	5 9	8.6	99.9	84 -	115	1.1	15.0					
								SS Spike		_						Surr	ogate					-
		BLK	LCS		SMPL	MS	MSD	Level	BLK	LCS			SMPL	MS	MSD	Li	mit	BLK	LCS	SMPL	MS	MSD
Surrogate Standard		ug/L	ug/L		ug/L	ug/L	ug/L	ug/L	%	%			%	%	%	C	%					
chlorobenzene		23.9	34.3		24.7	32.5	31.5	30.0	79.5	114.4			82.2	108.3	104.9	74 -	- 138					

Notes and Definitions

MDL = Method Detection Limit

ND = Not Detected

BLK = Method Blank

NA = Not Applicable

LCS = Laboratory Control Sample

DF = Dilution Factor

SMPL = Sample Results

DL = Diluted Out

MS/MSD = Matrix Spike / Matrix Spike Duplicate

SS = Surrogate Standard

UPL = Upper Control Limit

L = Low

RPD = Relative Percent Difference

H = High

KEMRON ENVIRONMENTAL SERVICES, OVL SEMI-VOLATILES QUALITY CONTROL SUMMARY

ANAL WORK GRP: WG57096

EXT DATE: 05-03-99

RUN DATE: 05-03-99

METHOD: 8015 MATRIX: WATER EXT BENCH SHEET: V114-P51

SMPL ID: 04-571-01

CONCENTRATION UNITS: ug/I

BLK FILENAME: 004F0101

SMPL FLNM: 005F0101

LCS FILENAME: 005F0101

MS FLNM: 007F0101

PREP WORK GRP: WG56919

INSTRUMENT: HP 8

MSD FLNM: 008F0101

			C	ONCENTRA	ATION , ug/I									PERCENT	RECOVERY ,	%					PERCENT	
ANALYTE	RDL	BLANK	LCS SPIKE ADDED	LCS	LCS DUP	SAMPLE	MS SPIKE ADDED	мѕ	MSD	BLANK	LCS	LCS DUP	LCS LCL	LCS	SAMPLE	MS	MSD	MS LCL	MS UCL	DUP RPD	MSD RPD	RPD UCL
DIESEL	500	ND	1000	947	NA	ND	2000	1407	1693	NA	94.7	NA	51	154	NA	70.3	84.7	18	165	NA	18	20
URROGATE o-TERPHENI OCTACOSAI	/L	15 4 6 25	20	16 4 9 94	NA NA	6.95 2.13	42.6 42.6	24.8 8.29	25 6 12.3	76.8 31.3	81.9 49.7	NA NA	49 26	174 152	33.1 10.2	58.2 19.5	60.1 28.8	18 26	165 152	NA NA	3 39	20 20

21

NOTES & DEFINITIONS :

NA = NOT APPLICABLE

ND = NOT DETECTED

RDL=REPORTING DETECTION LIMIT

KEMRON ENVIRONMENTAL SERVICES OHIO VALLEY LABORATORY QUALITY CONTROL SUMMARY

WORKGROUP: WG57037

RUN DATE: 5/4/99

METHOD:

418 1

ANALYST MPM

MATRIX:

Soil

SPIKE: 04-571-05

UNITS:

mg/kg

SPIKE DUP: 04-571-05

1	·		· · · · · · · · · · · · · · · · · · ·														
											PERC	ENT RECO	VERY			PERCENT	r ppn
ANALYTE	RDL	Blank	T-LCS	LCS	SAMPLE RESULT	T-MS	MS	MSD	LCS	LCS LCL	LCS UCL	MS	MSD	MS LCL	MS UCL	REP RPD	RPD UCL
TPH	25 00	ND	250 00	213.27	ND	250 00	159.96	182.09	85.31	76.40	115.00	63.98	72.84	47.05	139.50	12.94	30.00
			¥ 7						L								

NOTES & DEFINITIONS:

RDL = REPORTING DETECTION LIMIT

DL = DILUTED OUT NA = NOT APPLICABLE ND =NOT DETECTED

NR = NOT REQUIRED

LCS = LABORATORY CONTROL SAMPLE

T- LCS = TRUE VALUE OF LCS

REP1 = UNSPIKED SAMPLE REPLICATE 1

REP2 = UNSPIKED SAMPLE REPLICATE 2 SAMPLE RESULT = CONCENTRATION OF UNSPIKED MATRIX

T-MS = TRUE VALUE OF MATRIX SPIKE

MS = MATRIX SPIKE

LCL = LOWER CONTROL LIMIT UCL = UPPER CONTROL LIMIT

REP RPD = RELATIVE PERCENT DIFFERENCE OF SAMPLE REPLICATES

CHAIN OF CUSTODY RECORD

PROJECT NO.		CT NAM		1				\mathcal{I}		PA	ARA	METE	RS		INDUSTRIA HYGIENE SAM	l B
1432-001		JK O	F	An	BEICA SAN LEANDE	20			\ <u>\\</u>	~/	19		7	7)	
SAMPLERS; (Signatu	7\L	1			DALE ANDGROON		A Y	7	16/2	3/4	60/				/	
	und	liso	n	<u> </u>	DALE ANDGOSON	/	(3) / H	/	/ 16°/	A	/ • \	/_/	/ /		REMARKS	5
FIELD SAMPLE NUMBER	DATE 1999	TIME	COMP.	GRAB	STATION LOCATION	\\ \frac{\sigma_0}{2}\\ \frack	Con such	N ON				XY				
Mn 5,00	129	०२०		X		4			X					X 52	2 NOVE	
MW#4		1140		1		5			- -						11 (1	
MWZ		1245	<u> </u>			5								l	(1 /	
MW3		1400				5	44	∇						ı	((/	
D5		1440		 -						X	X			C0)	M POS 172	to one
03		1445	_		COMPOSITE									1	1	
Di		1450			COMPOSITE) FOR ONE S ANALYSIS	,								1/	1	
02		145		\Diamond	ANALYS15				₹	B	-CX	14	1 1	7	1	
			1								(- A		19	4/30/	79	
																1
														G	& c Dla	led
															Sp unto	(ct
Relinquished by: (Sig	matur()	4,	Date	/ Tir	me Received by: (Signature)	Relin	nquished b	y: (Si	gnature)		Da	te / T	ime R	eceived by: (Signatur	
Dal (1	whi	2	24/9	9/6	00	ļ					ļ				9000	lmp510
(Printed)			/		(Printed)	(Prin	ted)							(P	rinted)	(bg)
DALE AN.	DERS	on_			TO FLOED	 	D / T'	- 1								
Relinquished by: (Sig	gnature)		Date	e / Tii 	me Received for Laboratory by: (Signature)	4/30	Date / Tin	- 1	Remar ♥ /			<i>\</i>		T 7	TON) /1	n1,7
(Printed)					(Printed)	1	וצוניון	1	DU	-() l	NV MS	l.	ת ישונ מוש	/25C/ -2 /AI	1016E TO	VI //
					Brenda Gregory				300	007	7	- 1	261	N 91	70N LII voice T d 6863-9	325

G	Work Order		<u> 571 Client V</u>	rer-ca	#of S	amples_5	Due Date_	5/7	Page	
Sample #	Analyses	Reason	Removed By ADT	Removed From	MovedTo	Reliq. By	Ret'd by ADT	Ret'd To	Rec'd By	Reason
0/504 1-4,556	DRU	JY?	NI 5/1/916 0800	wollin	SILD	610090	CSH SINGO DIAC	NIMOSTAR	76B	1.64.6
	BETX/CRO	ANAL	MYB 5/3/94 @ 0915	Login-VI	VOA	13102	CSH S/4/99 20085 5 SC 20035 53 57011 1-4mt MAB sho/1901500	walking Archie	1319	OISPOSAL Storage Storage Ar.
5 se Compiled	BETX	ANAL	144/13 5/3/85@1000	Walkin	VOA		MFB 5/10/99@1500	Arhive	HB	Archive
05	MET		STK0501990/300		MET		STILOSTUMA CIUST		B19	STORAGE
04	184		NH 5/4/4901500		5.143	1619	1811 5/5/99 8080	Active <	B190830	Archie
_ U 7	DPO	PEIXT	184 5/7/4460900	isakir	8.118	Drg)	5/10/57 COEYS	DIMISTER	Big	DISPOSAL
									<u> </u>	
										
										And the second s





1046 Olive Drive, Davis CA 95616 . 530-757-0920 . Fax 753-6091

Sample Log 19989 May 14, 1999

Scott Allin Versar, Inc. 7844 Madison Avenue, Suite 167 Fair Oaks, CA 95628

Subject:

1 Water sample

Project Name:

Bank of America, San Leandro

Project Number: 4422-001

Location:

San Leandro

Dear Mr. Allin,

Chemical analysis on the samples referenced above has been completed. Summaries of the data are contained on the following pages. Sample(s) were received under documented chain-of-custody. USEPA protocols for sample storage and preservation were followed.

Acculabs - Davis is certified by the State of Arizona (AZ0583) and the State of California (# 2330). If you have any questions regarding procedures or results, please call me at 530-757-0920.

Sincerely,

Tom Kwoka

Acculabs Inc.



1046 Olive Drive, Davis CA 95616 . 530-757-0920 . Fax 753-6091

Sample Log 19989

Sample: MW-1

From : Bank of America, San Leandro (Proj. # 4422-001)


Sampled: 05/07/99

Dilution: 1:50

Matrix : Water

Run Log: 4184J

Parameter	(MRL) ug/L	Measured Value ug/L
	0 all un est un au	
Benzene	(25)	1400
Toluene	(25)	31
Ethylbenzene	(25)	82
Total Xylenes	(25)	360
TPH as Gasoline	(2500)	8100
Surrogate Recovery	7	83 %



Tempe 🗷 Tucson 🗷 Flagstaff 🗷 Davis/Sacramento 🗷 Durango 🗷 Golden 🗷 Sparks/Reno

QC Report for EPA 602 & Modified EPA 8015
Run Log: 4184J
From: Bank of America, San Leandro (Proj. # 4422-001)

Sample(s) Received: 05/07/99

Parameter	Matrix Spike % Recovery	Matrix Spike Duplicate % Recovery	RPD *
Benzene	78	82	5
Ethylbenzene	86	92	6
TPH as Gasoline	94	107	13

^{*} RPD = Relative Percent Difference

Parameter	Laboratory Control Sample % Recovery
Benzene	81
Ethylbenzene	91
Gasoline	109

Parameter	Method Blank
Benzene Toluene Ethylbenzene Total Xylenes	<0.50 ug/L <0.50 ug/L <0.50 ug/L <0.50 ug/L
TPH as Gasoline	<50 ug/L

Acculabs Inc.



1046 Olive Drive, Davis CA 95616 . 530-757-0920 . Fax 753-6091

Sample Log 19989

Sample: MW-1


From : Bank of America, San Leandro (Proj. # 4422-001)

Sampled : 05/07/99

Extracted: 05/13/99 QC Batch : DW990502 Dilution : 1:1 Run Log : 7437C

Matrix : Water

Parameter	(MRL) ug/L	Measured Value ug/L
TPH as Diesel	(50)	<50
TPH as Motor Oil	(100)	<100



Tempe # Tucson # Flagstaff # Davis/Sacramento # Durango # Golden # Sparks/Reno

QC Report
TPH Diesel by 8015 Mod

QC Batch DW990502

Matrix: Water

Spike and Spike Duplicate Results

Parameter	Matrix	Matrix	RPD
	Spike (%Rec)	Spike Dup. (%Rec)	%
TPH as Diesel	Not enough sa See duplicate	ample for spiking. E LCS Data.	

Laboratory Control Spike

Parameter		tory Control Spike Dup. (%Rec)	RPD %
TPH as Diesel	91	81	12

Method Blank

Parameter	MDL(ug/L)	Measured Value(ug/L)	
TPH as Diesel	(50)	<50	

Tom Kwowa Lab Director

PROJECT NO.	PROJECT NAME									/ / PARAMETERS							INDUSTRIAL Y	
1422-001	BAN	K on	EICA SA	/ 5 F	-19/-	3/4		, , , ,	HYGIENI	SAMPLE								
SAMPLERS: (Signatu	re) A				STATION LOCATION					93.10), (0	/ /	/ /			/		
Vale andron					PALE ANDERSON &												DEMARKO	
FIELD					/6				(13/	\mathcal{F}_{0}		/ /			REMARKS			
SAMPLE NUMBER	1999	TIME	COMP	GRAB	STATIO	N LOCATION	/₹	R	\\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		"	/ /						
ΑΛ	577	1000		1			B	X X	, 1	. /		-	f = f		MYDARO	COORT SEE		\dashv
MW/	/	1200		X			$- \mathcal{O} $		X,	7					WATZ	√ \ SPE	NOTE	
		ļ	ļ															
																		and the state of t
					And the state of t			arms services										
			}	l									1					-
			ļ										 					
L																		
			ļ	 									┨──┤			 		
			ļ										<u> </u>					
																		MONTHLEME
		<u> </u>								-			1		· · · · · · · · · · · · · · · · · · ·			
Relinquished by: (Sig	natusel		Date	Tim	ne Received by	t: (Suppress)	Poli		and by				Date		l n			
			7/0/	14	?		, nem	Relinquished by: (Signature				Date / Time Red			eived by: (Sig	nature)		
(Printed)			/ //	1.10	(Printed)			(Printed)				(Pein			nted)			
Printed) DAZE AWARSON															16111	ricu)		Wedstead
Polinguished by Grand		ch_	Date / Time		Beceived for	Received for Laboratory by:		Date / Time									······································	
Relinquished by: (Signature)			Date		(Signature)			5/7/99 1430			emarks Byr 5	TD	TAT	Γ.		,		The CONTRACTOR OF
(0					(Printed)	(Printed)		· · · ·	עצוי	-	LOW PETERTIE					LIMIT!		
(Printed)						Steve Wood Fill					Remarks STD TAT LOW DETECTION LIN QUESTOUS, RESULTS, INVOISE Y/G						TO SCOTT FLUND	
					1216NE MO	ויח וסקי		*****							90	16 863	4525	