5500 Shellmound Street, Emeryville, CA 94608-2411

Fax: 510-547-5043 Phone: 510-547-5420

Susan Hugo
Alameda County Department of
Environmental Health
Hazardous Materials Division
80 Swan Way, Room 200
Oakland, CA 94621-1426

June 23, 1994

DA P 36/18

OF ALCOUNT BY ALL BY AL

Re: Shell Service Station WIC #204-5510-0303 5755 Broadway Oakland, California 94606 WA Job #81-619-104

Dear Ms. Hugo:

This letter describes recently completed and anticipated activities at the Shell service station referenced above (Figure 1). This status report satisfies the quarterly reporting requirements prescribed by California Administrative Code Title 23 Waters, Chapter 3, Subchapter 16, Article 5, Section 265.d. Included below are descriptions and results of activities performed in the second quarter 1994 and proposed work for the third quarter 1994.

#### Second Quarter 1994 Activities:

Hydroc	Hydrocarbon and Ground Water Removal Summary									
Type of Fluid	Hydrocarbons or Ground Water Removed by Sampling Date this Quarter (Gal)	Total Hydrocarbons or Ground Water Removed (Gal)								
Separate Phase Hydrocarbons	0.0	0.55								
Ground Water with dissolved hydrocarbons	11,038	48,838								



- Weiss Associates (WA) pumped a total of 11,038 gallons of ground water from tank backfill well T-1 on March 16, 1994, to maintain ground water more than 2.5 ft below ground surface, and to remediate possible hydrocarbons in ground water. The ground water was transported to the Shell refinery in Martinez, California, for recycling.
- Blaine Tech Services, Inc. (BTS) of San Jose, California measured ground water depths
  and collected ground water samples from the site wells. BTS' report describing these
  activities and the analytic report for the ground water samples are included as
  Attachment A.
- WA calculated ground water elevations, compiled the analytic data (Tables 1 and 2) and prepared a ground water elevation contour map (Figure 2).

## Anticipated Third Quarter 1994 Activities:


- Separate phase hydrocarbons, if detected, will be removed and its volume will be estimated and reported.
- WA will submit a report presenting the results of the third quarter 1994 ground water sampling and ground water depth measurements. The report will include tabulated chemical analytic results, ground water elevations and a ground water elevation contour map.

### Conclusion and Recommendations:

Total petroleum hydrocarbons as gasoline (TPH-G) concentrations detected in ground water samples collected from well S-2 decreased this quarter compared to the first quarter results. This decrease may be attributed to seasonal ground water elevation fluctuations. We will continue monitoring hydrocarbon concentrations.



Please call if you have any questions.



JMA/JWC:jma

J:\SHELL\600\QMRPTS\619QMJU4.WP

Attachments: A - Blaine Tech's Ground Water Monitoring Report

cc: Dan Kirk, Shell Oil Company, P.O. Box 5278, Concord, California 94520-9998 John Jang, Regional Water Quality Control Board - San Francisco Bay Region, 2101 Webster Street, Suite 500, Oakland, California 94612




Figure 1. Site Location Map - Shell Service Station WIC #204-5510-0303, 5755 Broadway, Oakland, California






Figure 2. Monitoring Well Locations and Ground Water Elevation Contours - May 4, 1994 - Shell Service Station WIC#204-2004-0204, 5755 Broadway, Oakland, California

Table 1. Ground Water Elevations - Shell Service Station WIC #204-5510-0303, 5755 Broadway, Oakland, California

Well ID	Date	Top-of-Casing Elevation*	Depth to Water (ft)	Ground Water Elevation (ft above msl)
S-1	06/03/91	100.00	3.51	96.49
9-1	08/30/91	100.00	4.24	95.76
	11/22/91		4.29	95.71
	03/13/92		2.87	97.13
	05/28/92		3.79	96.21
	08/19/92		4.43	95.57
	11/18/92		4.34	95.66
	02/10/93		4.20	95.80
	06/11/93		3,39	96.61
	08/03/93		3.69	96.31
	11/02/93		4.26	95.74
	12/16/93 <sup>a</sup>		2.73	97.27
	02/01/94		3.38	96.62
	05/04/94		3,00	97.00
S-2	06/03/91	98.92	4.02	94.90
	08/30/91		4.70	94.22
	11/22/91		4.72	94.20
	03/13/92		3.47	95.45
	05/28/92		4.45	94.45
	08/19/92		4.84	94.08
	11/18/92		4.73	94.19
	02/10/93		4.83	94.09
	06/11/93		3.74	95.18
	08/03/93		4.23	94.69
	11/02/93		4.72	94.20
	12/16/93 <sup>a</sup>		3.00	95.92
	02/01/94		3.48	95.44
	05/04/94		3.26	95.66
S-3	06/03/91	101.67	3.25	98.42
	08/03/91		4.73	96.94
	11/22/91		4.81	96.86
	03/13/92		2.29	99.38
	05/28/92		3.62	98.05
	08/19/92		4.66	97.01
	11/18/92		4.51	97.16
	02/10/93		4.36	97.31
	06/11/93		2.91	98.76
	08/03/93		3.70	97.97

Table 1. Ground Water Elevations - Shell Service Station WIC #204-5510-0303, 5755 Broadway, Oakland, California (continued)

Well ID	Date	Top-of-Casing Elevation*	Depth to Water (ft)	Ground Water Elevation (ft above msl)
	11/02/93 <sup>b</sup>			<del></del>
	12/16/93 <sup>a</sup>		2.12	99.55
	02/01/94		2.90	98.77
	05/04/94		2.54	99.13

#### Note:

<sup>\* =</sup> Top of casing elevations referenced to arbitrary elevation of 100 ft

a = Depth to water measured by Weiss Associates

b = Well inaccessible

Table 2.	Analytic Results for Gr	round Water, Shell S	ervice Station.	WIC #204-5510-0303.	5755 Broadway, Oaklar	nd. California	
Sample ID	Date	Depth to Water (ft)	TPH-G <	В	E parts per billion (	Τ μg/L) <b>-</b>	X >
S-1	06/03/91 08/30/91 11/22/91 03/13/92 05/28/92 08/19/92 11/18/92 02/10/93 02/10/93 06/11/93 08/03/93 11/02/93 02/01/94 05/84/94	3.51 4.24 4.29 2.87 3.79 4.43 4.34 4.20 3.39 3.69 4.26 3.38 3.00	<30 <30 <30 <30 <50 <50 <50 <50 50 50 <b>50</b> <b>50</b>	\$\text{\text{0.3}} \text{\text{\text{0.3}}} \text{2.3} \text{\text{\text{0.55}}} \text{\text{\text{0.55}}} \text{\text{\text{0.55}}} \text{\text{\text{0.55}}} \text{\text{\text{0.55}}} \text{\text{\text{0.55}}} \text{\text{\text{\text{0.55}}}} \text{\text{\text{0.55}}} \text{\text{0.55}} \	\$	3336 3346 43.55555555555555 4000 4000 4000 4000 4000	.3 .3.3.5 .0.5.5 .0.5.5 .5.5.5 .5.5.5 .5.5
S-2	06/03/91 08/30/91 11/22/91 03/13/92 05/28/92 08/19/92 11/18/92 02/10/93 06/11/93 08/03/93 08/03/93 11/02/93 dup 02/01/94 02/01/94 05/84/94 05/94/94	4.02 4.70 4.72 3.47 4.45 4.84 4.73 4.83 3.74 4.23 4.72 4.72 3.48 3.48 3.26 3.26	490 70 1,600 1,300 100 470 490 19,000 18,000 19,000 12,000 <sup>3</sup> 13,000 <sup>3</sup> 31,000 <sup>3</sup> 31,000 <sup>3</sup> 31,000 <sup>3</sup>	150 0.37 110 210 28 42 43 710 3.100 1.400 1.400 470 530 430 300 1.200	8.2 <0.3 29 34 <0.5 8.3 17 80 370 81 86 31 35 50 30 <b>53</b> <b>57</b>	2.7 <0.3 9.3 5.7 <0.5 <0.5 39 760 1.600 130 140 47 47 46 33 31 37	7 <0.3 150 79 <0.5 4.0 29 370 1.100 130 150 92 96 130 100 71
S-3	06/03/91 08/30/91 11/22/91 03/13/92 05/28/92 08/19/92 11/18/92 02/10/93 06/11/93 06/11/93 06/11/93 08/03/93 11/02/93 <sup>b</sup> 02/01/94 <b>05/04/94</b>	3.25 4.73 4.81 2.29 3.62 4.66 4.51 4.36 2.91 2.91 2.91 3.70	<30 <30 <30 <50 <50 <50 <50 <50 <50 < <b>50</b>	<pre></pre>	0.3 <0.3 <0.3 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	0.3 <0.3 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5	0.3 <0.3 <0.3 <0.5 <0.5 <0.5 <0.5 <0.5 < <b>0.5</b>

<sup>--</sup> Table 2 continues on next page --

Sample ID	Date	Depth to Water (ft)	TPH-G <	Вр	E arts per billion (µ	/g/L)	X >
Bailer Blank	08/19/92 11/22/91		<50 <50	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5	<0.5 <0.5
Trip Blank	03/13/92 05/28/92 08/19/92 11/18/92 02/10/93 08/03/93 11/02/93 02/01/94 <b>05/04/94</b>		√50 √50 √50 √50 √50 √50 √50 <b>√50</b>	3555555555 <0.555555555555555555555555555555555555	<pre>&lt;0.3 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5 &lt;0.5</pre>	<pre></pre>	<0.3 <0.5 <0.5 <0.5 <0.5 <0.5 <b>&lt;0.5</b>

#### Abbreviations:

TPH-G = Total petroleum hydrocarbons as gasoline by Modified EPA Method 8015

Method 8015
B = Benzene by EPA Method 8020
E = Ethylbenzene by EPA Method 8020
T = Toluene by EPA Method 8020
X = Xylenes by EPA Method 602 or 8020
--- = Not analyzed
DTSC MCLs = California Department of Toxic Substances Control maximum contaminant levels for drinking water
NE = Not detected at detection limits of n ppb

#### Notes:

- a = Concentrations reported as gasoline are primarily due to presence of a discrete peak not indicative of gasoline.
- b = Wells inaccessible.
- c = DTSC recommended action level for drinking water; MCL not established




Table 3. Separate Phase Hydrocarbon Removal - Shell Service Station WIC #204-5510-0303, 5755 Broadway, Oakland, California

Well ID	Date	Separate Phase Hydrocarbon Thickness (ft)	Volume of Hydrocarbons Removed (gal)	Cumulative Volume of Hydrocarbons Removed (gal)
T-1	02/10/93	< 0.01	0.01	0.01
	06/11/93	< 0.01	0.01	0.02
	08/03/93	0.01	0.01	0.03
	11/02/93	0.02	0.03	0.06
	02/01/94	0.00	0.01	0.07
	05/04/94	0.00	0.00	0.07
T-2	02/10/93	0.43	0.40	0.40
	06/11/93	< 0.01	0.01	0.41
	08/03/93	0.01	0.01	0.41
	11/02/93	0.02	0.02	0.43
	02/01/94	0.00	0.01	0.44
	05/04/94	0.00	0.00	0.44
T-3	08/03/93	0.03	0.02	0.02
	11/02/93	0.02	0.01	0.03
	02/01/94	0.03	0.01	0.04
	05/04/94	0.00	0.00	0.04
	Total Volu	me of Hydrocarbons	Removed:	0.55



## ATTACHMENT A

GROUND WATER MONITORING REPORT AND ANALYTIC REPORT



# BLAINE TECH SERVICES INC.

985 TIMOTHY DRIVE SAN JOSE, CA 95133 (408) 995-5535 FAX (408) 293-8773

May 31, 1994

Shell Oil Company P.O. Box 5278 Concord, CA 94520-9998

Attn: Daniel T. Kirk

SITE: Shell WIC #204-5510-0303 5755 Broadway Oakland, California

QUARTER: 2nd quarter of 1994

## QUARTERLY GROUNDWATER SAMPLING REPORT 940504-K-1

This report contains data collected during routine inspection, gauging and sampling of groundwater monitoring wells performed by Blaine Tech Services, Inc. in response to the request of the consultant who is overseeing work at this site on behalf of our mutual client, Shell Oil Company. Data collected in the course of our field work is presented in a TABLE OF WELL GAUGING DATA. The field information was collected during our preliminary gauging and inspection of the wells, the subsequent evacuation of each well prior to sampling, and at the time of sampling.

Measurements taken include the total depth of the well and the depth to water. The surface of water was further inspected for the presence of immiscibles which may be present as a thin film (a sheen on the surface of the water) or as a measurable free product zone (FPZ). At intervals during the evacuation phase, the purge water was monitored with instruments that measure electrical conductivity (EC), potential hydrogen (pH), temperature (degrees Fahrenheit), and turbidity (NTU). In the interest of simplicity, fundamental information is tabulated here, while the bulk of the information is turned over directly to the consultant who is making professional interpretations and evaluations of the conditions at the site.

#### STANDARD PROCEDURES

#### Evacuation

Groundwater wells are thoroughly purged before sampling to insure that the sample is collected from water that has been newly drawn into the well from the surrounding geologic formation. The selection of equipment to evacuate each well is based on the physical characteristics of the well and what is known about the performance of the formation in which the well has been installed. There are several suitable devices which can be used for evacuation. The most commonly employed devices are air or gas actuated pumps, electric submersible pumps, and hand or mechanically actuated bailers. Our personnel frequently employ USGS/Middleburg positive displacement pumps or similar air actuated pumps which do not agitate the water standing in the well.

Normal evacuation removes three case volumes of water from the well. More than three case volumes of water are in cases where more evacuation is needed to achieve stabilization of water parameters when requested by the local implementing agency. Less water may be removed in cases where the well dewaters and does not recharge to 80% of its original volume within two hours and any additional time our personnel have reason to remain at the site. In such cases, our personnel return to the site within twenty four hours and collect sample material from the water which has recharged into the well case.

#### Decontamination

All apparatus is brought to the site in clean and serviceable condition. The equipment is decontaminated after each use and before leaving the site. Effluent water from purging and on-site cleaning is collected and transported to Shell's Martinez Manufacturing Complex in Martinez, California.

#### Free Product Skimmer

The column headed, VOLUME OF IMMISCIBLES REMOVED (ml) is included in the TABLE OF WELL GAUGING DATA to cover situations where a free product skimming device must be removed from the well prior to gauging. Skimmers are installed in wells with a free product zone on the surface of the water. The skimmer is a free product recovery device which often prevents normal well gauging and free product zone measurements. The 2.0" and 3.0" PetroTraps fall into the category of devices that obstruct normal gauging. In cases where the consultant elects to have our personnel pull the skimmers out of the well and gauge the well, our personnel perform the additional task of draining the accumulated free product out of the PetroTrap before putting it back in the well. This

recovered free product is measured and logged in the VOLUME OF IMMISCIBLES REMOVED column. Gauging at such sites is performed in accordance with specific directions from the professional consulting firm overseeing work at the site on Shell's behalf.

#### Sample Containers

Sample material is collected in specially prepared containers which are provided by the laboratory that performs the analyses.

#### Sampling

Sample material is collected in stainless steel bailer type devices normally fitted with both a top and a bottom check valve. Water is promptly decanted into new sample containers in a manner which reduces the loss of volatile constituents and follows the applicable EPA standard for handling volatile organic and semi-volatile compounds.

Following collection, samples are promptly placed in an ice chest containing prefrozen blocks of an inert ice substitute such as Blue Ice or Super Ice. The samples are maintained in either an ice chest or a refrigerator until delivered into the custody of the laboratory.

#### Sample Designations

All sample containers are identified with a site designation and a discrete sample identification number specific to that particular groundwater well. Additional standard notations (e.g. time, date, sampler) are also made on the label.

### Chain of Custody

Samples are continuously maintained in an appropriate cooled container while in our custody and until delivered to the laboratory under a standard Shell Oil Company chain of custody. If the samples are taken charge of by a different party (such as another person from our office, a courier, etc.) prior to being delivered to the laboratory, appropriate release and acceptance records are made on the chain of custody (time, date, and signature of the person releasing the samples followed by the time, date and signature of the person accepting custody of the samples).

## **Hazardous Materials Testing Laboratory**

The samples obtained at this site were delivered to Sequoia Analytical Laboratory in Redwood City, California. Sequoia Analytical Laboratory is a California Department of Health Services certified Hazardous Materials Testing Laboratory and is listed as DOHS HMTL #1210.

#### **Objective Information Collection**

Blaine Tech Services, Inc. performs specialized environmental sampling and documentation as an independent third party. In order to avoid compromising the objectivity necessary for the proper and disinterested performance of this work, Blaine Tech Services, Inc. performs no consulting and does not become involved in the marketing or installation of remedial systems of any kind. Blaine Tech Services, Inc. is concerned only with the generation of objective information, not with the use of that information to support evaluations and recommendations concerning the environmental condition of the site. Even the straightforward interpretation of objective analytical data is better performed by interested regulatory agencies, and those engineers and geologists who are engaged in the work of providing professional opinions about the site and proposals to perform additional investigation or design remedial systems.

## Reportage

Submission of this report and the attached laboratory report to interested regulatory agencies is handled by the consultant in charge of the project. Any professional evaluations or recommendations will be made by the consultant under separate cover.

Please call if we can be of any further assistance.

Richard C. Blaine

RCB/lp

attachments: table of well gauging data

chain of custody

certified analytical report

cc: Weiss Associates 5500 Shellmound Street Emeryville, CA 94608-2411

ATTN: Michael Asport

## TABLE OF WELL GAUGING DATA

WELL I.D.	DATA COLLECTION DATE	MEASUREMENT REFERENCED TO	QUALITATIVE OBSERVATIONS	DEPTH TO FIRST IMMISCIBLES LIQUID (FPZ)	THICKNESS OF IMMISCIBLES LIQUID ZONE	VOLUME OF IMMISCIBLES REMOVED	DEPTH TO WATER	DEPTH TO WELL BOTTOM
			(sheen)	(feet)	(feet)	(ml)	(feet)	(feet)
S-1	5/4/94	TOC	-	NONE .	<u></u>	_	3.00	11.52
S-2 °	5/4/94	TOC	ODOR	NONE	••	-	3.26	9.43
S-3	5/4/94	TOC		NONE	••	_	2.54	9.53
T-1	5/4/94	TOC	SHEEN	_	••	_	2.21	13.46
T-2	5/4/94	TOC	SHEEN		-		1.38	12.98
T-3	5/4/94	TOC	SHEEN	***	_		0.02	9.54

<sup>\*</sup> Sample DUP was a duplicate sample taken from well S-2.

SHELL RETAIL E						۸G -	WE:	ST			СН	All So	lal N	F C	UST 7	101	Y ŠO	REC	ORD	Dale Page	
	Broad	way, Oa	ıkland		<u>.</u>					And	alys	is R	aqu!	lrec	1				LAB:	<u>٠.                                    </u>	Ç4.
VIC#: 204-5	510-0	303												•			•		CHECK OHE (1) FOX OHLY	CUOI	JIME CHUOSEA HEVT
hell Engineer: Dan Kirk Consultani Name & A Blaine Tech Serv 985 Timothy Driv Consultani Contact: Jim Keller Comments: Gampled by: Printed Name:	e s	an Jose	e, CA	9513	675=6 3 No.: (635 293=8	160	TPH (EPA 8015 Mod. Gas)	TPH (EPA 8015 Mod. Diesel).	BTEX (EPA 8020/602)	Volatile Organics (EPA \$240)	Test for Disposal	Combination TPH 8015 & BTEX 8020	-		Asbestos	Container Size	Preparation Used	Composite Y/N	SZe larestigation [ Sell Clossty/Disposal [ Wates Clossity/Disposal [ Sell/Ak Rem. et Sys. [		24 hours
5-/	9/4			$\omega$		3	:		Γ		-	X							9405297		-01
5'-2	1			W		3						Ź		_							-O7
S-3				W		3			$\Box$			Ï		_					,		-03
DUP			1	W		3						X			\						-04 E
	V	·		W		2						X									-05
elludgriped gå (rjäudine elludgriped gå (rjäudine	X.L	- Print	od Nam	vito	Bro	<u> </u>	Do Na	le:5* ne: //	4 (9 3 (9 3 (9 3 (4 3	S Roc	celye	q (ND	ratur e <i>utt</i> natur	o):	<u></u>			יוחודו	od Names C5 Fultche od Names	<u> </u> ev	Dale: 5-5-94 Time: 9:40 Dale: Time:
selludajzyeq BA (zjövajnte	);		ed Nam		Must	ROVIDS	Ilm A Co	10:	E Tim	1.	V.	٤٠.	NODY PODY		INVC	ne i		1/	ed Hame: ETH E. GRE	S5	Dale:050594 Time: 10:0

•


...

٠.

٠

**.** . .

· .. :



680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600

FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133 Attention: Jim Keller

Project: 940504-K1, Shell, 5755 Broadway

Enclosed are the results from 5 water samples received at Sequoia Analytical on May 5,1994. The requested analyses are listed below:


SAMPLE#	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
4E29701	Water, S-1	5/4/94	EPA 5030/8015 Mod./8020
4E29702	Water, S-2	5/4/94	EPA 5030/8015 Mod./8020
4E29703	Water, S-3	5/4/94	EPA 5030/8015 Mod./8020
4E29704	Water, DUP	5/4/94	EPA 5030/8015 Mod./8020
4E29705	Water, TB	5/4/94	EPA 5030/8015 Mod./8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Suzanne Chin **Project Manager** 



680 Chesapeake Drive 1900 Bates Avenue, Suite L 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834 (415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive San Jose, CA 95133 Client Project ID: Sample Matrix: 940504-K1, Shell, 5755 Broadway Water Sampled: Received: May 4, 1994 May 5, 1994

Attention: Jim Keller

Analysis Method:

EPA 5030/8015 Mod./8020

Reported:

May 13, 1994

First Sample #: 4E29701

## TOTAL PURGEABLE PETROLEUM HYDROCARBONS with BTEX DISTINCTION

Analyte	Reporting Limit μg/L	Sample I.D. 4E29701 S-1	Sample I.D. 4E29702 S-2	Sample I.D. 4E29703 S-3	Sample I.D. 4E29704 DUP	Sample 1.D. 4E29705 TB	
Purgeable Hydrocarbons	50	N.D.	3,900	N.D.	4,500	N.D.	
Benzene	0.50	1.1	1,200	N.D.	1,200	N.D.	r
Toluene	0.50	N.D.	31	N.D.	37	N.D.	
Ethyl Benzene	0.50	N.D.	53	N.D.	57	N.D.	
Total Xylenes	0.50	N.D.	71	N.D.	110	N.D.	
Chromatogram Pa	itern:	C6	C6 - C12	••	64 - C12	••	

**Quality Control Data** 

Report Limit Multiplication Factor:	1.0	50	1.0	20	1.0
Date Analyzed:	5/9/94	5/9/94	5/9/94	5/9/94	5/9/94
Instrument Identification:	GCHP-3	GCHP-2	GCHP-2	GCHP-17	GCHP-2
Surrogate Recovery, %: (QC Limits = 70-130%)	87	77	82	100	78

Purgeable Hydrocarbons are quantitated against a fresh gasoline standard.

Analytes reported as N.D. were not detected above the stated reporting limit.

**SEQUOIA ANALYTICAL** 

Suzanne Chin Project Manager

4E29701.BLA <1>



680 Chesapeake Drive 1900 Bates Avenue, Suite L 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834 (415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

Client Project ID:

940504-K1, Shell, 5755 Broadway

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller

QC Sample Group: 4E29701

Reported:

May 13, 1994


## **QUALITY CONTROL DATA REPORT**

ANALYTE	Benzene	Toluene	Ethyl Benzene	Xylenes	
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020	
Analyst:	J. Minkel	J. Minkel	J, Minkel	J. Minkel	
MS/MSD					
Batch#:	4E29703	4E29703	4E29703	4E29703	
Date Prepared:	•		•	-	
Date Analyzed:	5/9/94	5/9/94	5/9/94	5/9/94	
Instrument I.D.#:	GCHP-3	GCHP-3	GCHP-3	GCHP-3	
Conc. Spiked:	10 μg/L	10 μg/L	10 μg/L	30 μg/L	
Matrix Spike % Recovery:	99	98	99	97	
Matrix Spike Duplicate % Recovery:	100	100	99	100	
Relative % Difference:	1.0	2.0	0.0	3.0	
LCS Batch#:	-	-	*	-	
Date Prepared:	-	•	•	•	
Date Analyzed:	•	-	-	-	
Instrument LD.#:	•	-	-	•	
LCS % Recovery:	•		· -		
% Recovery Control Limits:	71-133	72-128	72-130	71-120	

**SEQUOIA ANALYTICAL** 

Suzanne Chin Project Manager Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.



680 Chesapeake Drive 1900 Bates Avenue, Suite L Concord, CA 94520 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

Client Project ID:

940504-K1, Shell, 5755 Broadway

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller 

QC Sample Group: 4E29702-03, 05

Reported:

May 13, 1994

## **QUALITY CONTROL DATA REPORT**

ANALYTE	Benzene	Toluene	Ethyl	Xylenes	
47.400.			Benzene	•	
				<b>TD 1 0005</b>	
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020	
Analyst:	A. Miraftab	A. Miraftab	A. Miraftab	A. Miraftab	
MS/MSD					
Batch#:	4E22801	4E22801	4E22801	4E22801	
Date Prepared:	•	-	-	-	
Date Analyzed:	5/8/94	5/8/94	5/8/94	5/8/94	
Instrument I.D.#:	GCHP-2	GCHP-2	GCHP-2	GCHP-2	
Conc. Spiked:	10 μg/L	10 μg/L	10 μg/L	30 μg/L	
Matrix Spike					
% Recovery:	99	100	100	100	
Matrix Spike					
Duplicate %					
Recovery:	98	97	99	97	
Relative %					
Difference:	1.0	3.0	1.0	3.0	
			a. aaadaaaada oo doodda da da da da da	orchide Labbi 1811, bala aalad	
LCS Batch#:		•	-	-	•
200 20101111					
Date Prepared:	•	-	-	•	
Date Analyzed:	-	•	•	-	•
Instrument I.D.#:	•	-	-	-	
LCS %					
Recovery:	_	•	-	-	
necovery.	-				
% Recovery					
Control Limits:	71-133	72-128	72-130	71-120	

**SEQUOIA ANALYTICAL** 

Suzanne Chin **Project Manager**  Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.

4E29701.BLA <3>



680 Chesapeake Drive 1900 Bates Avenue, Suite L 819 Striker Avenue, Suite 8

Redwood City, CA 94063 Concord, CA 94520 Sacramento, CA 95834

(415) 364-9600 (510) 686-9600 (916) 921-9600 FAX (415) 364-9233 FAX (510) 686-9689 FAX (916) 921-0100

Blaine Tech Services, Inc. 985 Timothy Drive

Client Project ID: 940504-K1, Shell, 5755 Broadway

Matrix:

Liquid

San Jose, CA 95133 Attention: Jim Keller 

QC Sample Group: 4E29704

Reported:

May 13, 1994

## QUALITY CONTROL DATA REPORT

ANALYTE	Benzene	Toluene	Ethyl Benzene	Xylenes	
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020	
Analyst:	J. Minkel	A. Miraftab	A. Miraftab	A, Miraftab	
MS/MSD Batch#:	4DH7901	4DH7901	4DH7901	4DH7901	•
Date Prepared: Date Analyzed: Instrument I.D.#:	- 5/9/94 GCHP-17	5/9/94 GCHP-17	5/9/94 GCHP-17	5/9/94 GCHP-17	
Conc. Spiked:	10 μg/L	10 μg/L	10 μg/L	30 μg/L	
Matrix Spike % Recovery:	99	100	98	100	
Matrix Spike Duplicate % Recovery:	94	94	91	93	
Relative % Difference:	5.2	6.2	7.4	7.3	
LCS Batch#:	•			•	
Date Prepared:	•	-	-	•	
Date Analyzed:	•	-	•	•	
Instrument I.D.#:	•	•	-	•	
LCS %		_		-	
Recovery:	-	-			
% Recovery Control Limits:	71-133	72-128	72-130	71-120	

**SEQUOIA ANALYTICAL** 

Suzanne Chin **Project Manager**  Please Note:

The LCS is a control sample of known, interferent free matrix that is analyzed using the same reagents, preparation, and analytical methods employed for the samples. The matrix spike is an aliquot of sample fortified with known quantities of specific compounds and subjected to the entire analytical procedure. If the recovery of analytes from the matrix spike does not fall within specified control limits due to matrix interference, the LCS recovery is to be used to validate the batch.