

ENVIRONMENTAL  
PROTECTION  
96 SEP 18 PM 4: 14



Ro - 027

Ms. Eva Chu  
Hazardous Materials Specialist  
Alameda County Health Care Services Agency  
Department of Environmental Health  
Hazardous Materials Division  
1131 Harbor Bay Parkway, 2nd Floor  
Alameda, California 94502-6577

September 17, 1996

RE: Soil stockpile sampling at 3884 Martin Luther King, Junior Way, Oakland, California.

Dear Ms. Chu;

Enclosed are copies of the laboratory report and chain-of-custody documentation for a random sample of the soil stockpile near the southern corner of the Lockett Property located at 3884 Martin Luther King, Junior Way, Oakland, California.

TPH-Gasoline and the aromatic hydrocarbons (benzene, toluene, ethylbenzene, and total xylene isomers) were below their respective laboratory detection limits.

Please do not hesitate to call me at (510) 373-9211 should you have any questions.

Sincerely,

Gary D. Lowe, R.G., C.E.G., C.H.  
Principal, Hydrogeologist  
Sole Proprietor



xc: Ms. Lillie Lockett, 4102 Lusk Street, Oakland, California 94608

925 / 888-5454 pgs

# CHROMALAB, INC.

Environmental Services (SDB)

September 6, 1996

Submission #: 9608338

H20GEOL

Atten: Gary Lowe

Project: LUCKETT PROPERTY  
Received: August 26, 1996

Project#: 3884 MARTIN LUTHER KING

re: 1 sample for Gasoline and BTEX compounds analysis.  
Method: EPA 5030/8015M/8020


Sampled: August 26, 1996 Matrix: SOIL  
Run#: 2976


Analyzed: September 5, 1996

Spl#	CLIENT SPL ID	Gasoline (mg/Kg)	Benzene (mg/Kg)	Toluene (mg/Kg)	Ethyl Benzene (mg/Kg)	Total Xylenes (mg/Kg)
97536	3884/0826-SP1	N.D.	N.D.	N.D.	N.D.	N.D.

Note: Estimated concentration: Low surrogate recovery due to matrix interference.

Reporting Limits	1.0	0.0050	0.0050	0.0050	0.0050
Blank Result	N.D.	N.D.	N.D.	N.D.	N.D.
Blank Spike Result (%)	110	102	100	102	100

  
June Zhao  
Chemist

  
Marianne Alexander  
Gas/BTEX Supervisor

