

**OXFORD**

FACSIMILE TRANSMITTAL	
TO	Jennifer Eberle
ATTENTION	Environmental Health
FROM	John Prall
DATE & TIME	July 11, 1996
FAX NUMBER	337-9335
NO. OF PAGES	3

re: TBCT Tank Poll, 707 Ferry St.

Jennifer:

The laboratory reports will follow by U.S. mail.

John Prall

**PORT OF OAKLAND**  
 Environmental Department  
 530 Water Street, 5th Floor  
 Oakland, CA 94607  
 FAX (510) 451-5916  
 PHONE (510) 272-1174



**PORT OF OAKLAND**


**DRAFT**

**Table 1**

**Laboratory Results for Confirmation Soil Samples  
TransBay Container Terminal, Berth 25  
Port of Oakland**

Sample I.D.	Date	TPH gas (mg/kg)	Benzene (µg/kg)	Toluene (µg/kg)	Ethylbenzene (µg/kg)	Xylenes (µg/kg)	TPH diesel (mg/kg)	Total Pb (mg/kg)
Tank A	6/21/96	1,900	270	16,000	<120	160,000	1,300	305
Tank B	6/21/96	600	<120	240	<120	13,000	960	<4.8
East Wall	6/21/96	<0.2	<1	1.1	<1	<1	<5	5.78
West Wall	6/21/96	<0.2	<1	3.5	<1	3.2	<500 <sup>(1)</sup>	188
Stockpile	6/21/96	0.33	<1	12	<1	37	27	27.9

<sup>(1)</sup> Matrix interference from high boiling point hydrocarbons in sample resulting in higher detection limit.



REMOVE EXISTING CONCRETE SLAB

WESTSIDE WALL  
Depth-7'  
5-10 ppm-PID

REMOVE EXISTING 1,000 GALLON FIBERGLASS TANKS

REMOVE EXISTIN AND CAP AT LIB

EXISTING DISPENSER ISLAND

TANK A  
depth-11'  
PID-25 ppm

TANK B  
depth-10'  
PID-112 ppm

SAWCUT

REMOVE VENT PIPES AND  
PATCH HOLES IN OVERHANG  
TO MATCH EXISTING SHEET  
METAL ROOF

East Side wall  
8' depth  
PID-8\*

Scale  
1" = 5'

BLDG. C-129