QUARTERLY GROUND WATER MONITORING REPORT JULY 1992 CLARK'S HOME AND GARDEN 23040 CLAWITER ROAD HAYWARD, CALIFORNIA

PROJECT 4983

for

Mr. Chester Clark 521 Triller Lane Grants Pass, Oregon 97527

bу

TERRATECH, INC. 1365 Vander Way San Jose, California 95112

July 30, 1992



THIRD QUARTERLY GROUND WATER MONITORING REPORT JULY 1992 CLARK'S HOME & GARDEN 23040 CLAWITER ROAD, HAYWARD

INTRODUCTION

This report describes the work performed for and the findings from Terratech's recent quarterly testing of the shallow ground water at Clark's Home & Garden Center, 23040 Clawiter Road in Hayward (see Figures 1 and 2). The work is being performed according to requirements of the Alameda County Health Agency (ACHA) for follow-up to a fuel leak discovered when two underground storage tanks were removed from the site in 1988.

Background information on this project is presented in Terratech's Project 4983 reports, "Initial Investigation of Ground Water Contamination, ...," dated September 5, 1991; "Follow-up Ground Water Testing, ...," dated November 12, 1991; and two subsequent Quarterly Ground Water Sampling and Analysis reports, dated February 26, 1992 and May 6, 1992.

WORK PERFORMED

On July 7, 1992 a member of Terratech's environmental department performed the quarterly sampling of on-site monitoring well MW-1. The depth to standing water in the well was first measured to the nearest 0.01-foot using an electronic probe. The well was then purged using a pre-cleaned Teflon bailer. During purging, temperature, pH and specific conductance measurements were recorded until stable (< 10% variation) readings were obtained. Approximately four well-volumes of water were removed from MW-1 prior to collecting a sample. The sampling technician logged field notes on a Well Sampling Data Sheet (see copy in appendix). Purged water was placed into a labeled drum and left on site.

After purging, ground water from MW-1 was carefully transferred from the bailer into a set of three 40-ml volatile organic analysis (VOA) vials, and a pair of 1-liter amber jars supplied by the testing laboratory. The VOA vials, which contained a small amount of hydrochloric acid preservative, were filled until a positive meniscus formed then sealed with a Teflon septum screw cap. The containers were inverted and tapped to confirm the absence of headspace or bubbles, then immediately labeled and iced. The amber jars were filled, capped labeled and iced.

The sample containers were kept iced or refrigerated from the time of collection until the time of analysis. Sample collection, handling and analytical requests were documented on a chain-of-custody record (appended).

The ground water sample was transferred to and analyzed by NET Pacific, a State-certified laboratory in Santa Rosa, for total petroleum hydrocarbons (TPH) as diesel using EPA Method 3510 extraction and GC-FID detection; TPH as

Project 4983 July 30, 1992

gasoline using EPA Method 5030 with GC-FID detection; and the specific fuel compounds - benzene, toluene, ethylbenzene and xylenes (BTEX) using a modified EPA Method 8020.

FINDINGS AND COMMENTS

Table 1 presents a summary of ground water level measurements in MW-1 to-date. The on-site ground water level fell approximately 1.10 feet during the period between the April 4, 1992 and July 7, 1992 quarterly sampling events. Based on previously reviewed information on surrounding fuel leak sites, the local ground water gradient direction is expected to be toward the west.

A prominent fuel odor and surface sheen on purged water were noticed by our sampling technician during the July sampling activities. Recent laboratory analyses of the MW-1 ground water sample detected concentrations of TPH generally similar to historic levels. Concentrations of BTEX, especially benzene, were generally lower than past levels and none appear to exceed state drinking water standards. It still appears that the ground water impact is from a mixture of gasoline and diesel, and possibly other petroleum fuel(s).

Ground water sample analyses results to date are summarized in Table 2. The July 1992 laboratory report is appended.

Pending further regulatory direction and mutual cooperation from the other parties with fuel leaks in this area, Terratech will be proceeded with a fourth round of quarterly monitoring in October, as contracted.

LIMITATIONS

This report and the associated work have been provided in accordance with the general principles and practices currently employed in the environmental consulting profession. This is in lieu of all warranties, express or implied. Our sampling and testing program is necessarily limited. PROFESSION

Report Prepared by:

TERRATECH, INC.

aff

Shiela M. Chrisley

Project Environmental Geol of 35

Neviewed by:

No. C042437

ERIC R. LAUTENBACH

EXP. 3/31/96

CIVIL

Eric R. Lautenbach

CE 42437

Juliette Chen - Alameda County Health Agency Eddy So - California Regional Water Quality Control Board Hugh Murphy - Hayward Fire Department Butch Voss - L.H. Voss Materials, Inc. Bob Price

TABLE 1

SUMMARY OF GROUND WATER DEPTH MEASUREMENTS

Clark's Home and Garden Center 23040 Clawiter Road Hayward, California

Location and Date	Depth to Ground Water (feet)
MW-1 08/07/91 09/05/91 10/15/91 01/07/92 04/08/92 07/07/92	17.44 17.72 17.92 17.23 15.57 16.67

July 30, 1992 Project 4983

TABLE 2

SUMMARY OF GROUND WATER SAMPLE ANALYSIS RESULTS

Clark's Home and Garden Center 23040 Clawiter Road Hayward, California

(Concentrations are in parts per billion (ppb))

Sample Location and Date	TPH as Diesel	TPH as Gasoline	Benzene	Toluene	Ethyl- benzene	Xylenes
MW-1 08/07/91 09/05/91 10/15/91 01/07/92 04/08/92 07/07/92	7,100 2,800* 13,000 9,000* 3,500 6,300	5,900 47,000 24,000 23,000** 8,100 7,000	45 <50 <50 <50 19 < 5	<25 <50 <50 <50 < 5 < 5	130 230 <50 270 350 190	520 660 390 800 210 170
Action Level/MCL			1	100	680	1,750

NOTES:


TPH = Total petroleum hydrocarbons

*Laboratory notes that petroleum hydrocarbon detected as diesel is due to both diesel and a petroleum hydrocarbon lighter than diesel.

**Laboratoy notes that petroleum hydrocarbon detected as gasoline does not appear to have a typical gasoline pattern.

Action Levels and Maximum Contaminant Levels (MCL) are for contaminants in drinking water, as established by the California Department of Health Services.

-- = Action Level or MCL not established for TPH in drinking water. Clean-up guidelines are established on a site-specific basis.






CLARK'S BUILDING MATERIALS 23040 CLAWITER ROAD HAYWARD, CALIFORNIA

SITE VICINITY MAP

FIGURE | PROJECT 4983





CLARK'S BUILDING MATERIALS 23040 CLAWITER ROAD HAYWARD, CALIFORNIA

SITE PLAN

FIGURE

2
PROJECT
4983

APPENDIX

WELL SAMPLING DATA SHEET, CHAIN-OF-CUSTODY RECORD AND ANALYTICAL REPORT



NATIONAL ENVIRONMENTAL TESTING, INC.

NET Pacific, Inc. 435 Tesconi Circle Santa Rosa, CA 95401

Tel: (707) 526-7200 Fax: (707) 526-9623

TERRATECH, INC.

JUL 3 1 1992

RECEIVED

Shiela Chrisley Terratech 1365 Vander Way San Jose, CA 95112 Date: 07/27/1992 NET Client Acct. No: 70400 NET Pacific Job No: 92.3811

Received: 07/09/1992

Client Reference Information

Project:4983

Sample analysis in support of the project referenced above has been completed and results are presented on following pages. Please refer to the enclosed "Key to Abbreviations" for definition of terms. Should you have questions regarding procedures or results, please feel welcome to contact Client Services.

Approved by:

Jules Skamarack Laboratory Manager

Enclosure(s)



Client Acct: 70400 Client Name: Terratech NET Job No: 92.3811 Date: 07/27/1992

Page: 2

Ref: Project:4983

SAMPLE DESCRIPTION: MW-1

Date Taken: 07/07/1992 Time Taken: 15:35 LAB Job No: (-128980)

TWR 100 NO: (-15888)	<i>)</i>			
		Reportin	ıg	
Parameter	Method	<u>Limit</u>	Results	Units
TPH (Gas/BTXE, Liquid)				
METHOD 5030 (GC, FID)				
DATE ANALYZED			07-18-92	
DILUTION FACTOR*			10	
as Gasoline	5030	0.05	7.0	mg/L
METHOD 8020 (GC, Liquid)				•
DATE ANALYZED			07-18-92	
DILUTION FACTOR*			10	
Benzene	8020	0.5	ND	ug/L
Ethylbenzene	8020	0.5	190	ug/L
Toluene	8020	0.5	ND	ug/L
Xylenes (Total)	8020	0.5	170	ug/L
SURROGATE RESULTS				
Bromofluorobenzene	5030		113	% Rec.
Bromoridorobenzene	3030		113	a Kec.
METHOD 3510 (GC,FID)				
DILUTION FACTOR*			5	
DATE EXTRACTED			07-13-92	
DATE ANALYZED			07-15-92	
as Diesel	3510	0.05	6.3	mg/L
	0010			9/ =



Client Acct: 70400 Client Name: Terratech NET Job No: 92.3811 Date: 07/27/1992

Page: 3

Ref: Project:4983

QUALITY CONTROL DATA

Parameter	Reporting Limits	Units	Cal Verf Stand % Recovery	Blank Data	Spike % Recovery	Duplicate Spike % Recovery	RPD
Gasoline	0.05	mg/L	116	ND	113	112	<1
Benzene	0.5	ug/L	107	ND	88	96	8.0
Toluene	0.5	ug/L	102	ND	101	100	1.0
Diesel	0.05	mg/L	89	ND	98	104	5.4
Motor Oil	0.5	mg/L	88	ND	N/A	N/A	N/A

COMMENT: Blank Results were ND on other analytes tested.



KEY TO ABBREVIATIONS and METHOD REFERENCES

<	:	Less than; When appearing in results column indicates analyte
		not detected at the value following. This datum supercedes
		the listed Reporting Limit.

: Reporting Limits are a function of the dilution factor for any given sample. To obtain the actual reporting limits for this sample, multiply the stated Reporting Limits by the dilution factor (but do not multiply reported values).

ICVS : Initial Calibration Verification Standard (External Standard).

mean : Average; sum of measurements divided by number of measurements.

mg/Kg (ppm): Concentration in units of milligrams of analyte per kilogram of sample,

wet-weight basis (parts per million).

mg/L : Concentration in units of milligrams of analyte per liter of sample.

mL/L/hr : Milliliters per liter per hour.

MPN/100 mL : Most probable number of bacteria per one hundred milliliters of sample.

N/A : Not applicable.

NA : Not analyzed.

ND : Not detected; the analyte concentration is less than applicable listed reporting limit.

NTU : Nephelometric turbidity units.

RPD : Relative percent difference, 100 [Value 1 - Value 2]/mean value.

SNA : Standard not available.

ug/Kg (ppb) : Concentration in units of micrograms of analyte per kilogram of sample,

wet-weight basis (parts per billion).

ug/L : Concentration in units of micrograms of analyte per liter of sample.

umhos/cm : Micromhos per centimeter.

Method References

Methods 100 through 493: see "Methods for Chemical Analysis of Water & Wastes", U.S. EPA, 600/4-79-020, rev. 1983.

Methods 601 through 625: see "Guidelines Establishing Test Procedures for the Analysis of Pollutants" U.S. EPA, 40 CFR, Part 136, rev. 1988.

Methods 1000 through 9999: see "Test Methods for Evaluating Solid Waste", U.S. EPA SW-846, 3rd edition, 1986.

 \underline{SM} : see "Standard Methods for the Examination of Water & Wastewater, 17th Edition, APHA, 1989.



CHAIN-OF-CUSTODY RECORD

P.O. NUMBER: 2893 TURNAROUND: 10-day

FAX reports upon completion to: (408) 297-7716 Mail reports to: TERRATECH, INC.							Analysis Required										
1	1365 VAN	DER WAY	san jos	E, CA 9511	2				٦٠.								
PROJECT NUMBER: 4983				tainers	Type of Containers		gasoline	\$ *	Diese (
SAMPLER INITIALS: GCB/DP			S S S	¿pa		45	1 1 1					Remarks					
Sample Number	Depth	Date	Time	Medium	Sample Location	Number	Number of Containers Type of Containers	Preserved?	TPH	ADA BTEX	19म वड	निन इ	']]				
MW-1	-	7/7/92	1535	water	MW-1	3	Homi Voa s	yes	X	X							
MW-1	-	7/7/12	1535	Water	M ω - 1	2	1 leten Arrberts	NO			X						
						ļ 											
										<u></u> .							
		j 															
		ž		- T- C -			•										
·		1316	YUY (DEAL	ED 7/8/92												
N.	رک	140	<u>U</u>	MM	ED 7/8/90 I sid intert												
	·																
Relinquished by (signature): Date/Time 7/8/92 Company or Agency: TERRATION, NC 9:00 AM Relinquished by (signature): Company or Agency: Company or Agency:		Received by (signature): Company or Agency: Company or Agency: Provinced by (signature):	Reline	Relinquished by (signature): Date/Time Recompany or Agency: Company or		Rece	pany e	(signature) UMUU									
Relinquished by (s Company or Agen	signature) cy: (CU	eani	Date/Tir		Received by (signature): Company or Agency:	Relinquished by (signature): Company or Agency: Date/Time Received for 7/4/7 2 0800 Company or		r Laboratory by (signature): (Approximate the state of t									

TERRATECH, INC. WELL SAMPLING DATA SHEET

PROJECT NAME: CLARK FUGL LEAK- HAYNARD DATE: 7/7/92 PROJECT NUMBER: 4893 WELL DESIGNATION: MW-1 SAMPLE NUMBER: MW-1											
CONDITION OF WELL HEAD/VAULT: TOP OF CASING ELEVATION: DEPTH TO GROUND WATER (initial): 16.67 DEPTH TO BOTTOM OF WELL: MEASURED											
CASING DIAMETER: 2" X 3" 4" OTHER											
CALCULATED WELL VOLUME: HWC x V = $6.93 \times 0.163 = 1.13$ gal Volume (V) of 2" well - 0.163 gal/ft											
ODOR gason	ارد SHEE	:N?	FL0/	ATING PRODUCT	THICKNESS	NO					
ODOR SHEEN FLOATING PRODUCT THICKNESS PUMP TYPE: PVC HAND BLADDER PNEUMATIC BAILER OTHER											
PUMP DEPTH:											
TIME	GALLONS PURGED	NO. OF WELL VOLUMES	CONDUCTIVITY (mmhos/cm or μmhos/cm)	TURBIDITY (NTU or visual)							
1515	1.2	21	1.78	67.670	4970						
1521	2.6	2 2	8.00	67.70*	4320 -						
1529	3.4	2 3	7,65	66.40°	3560						
1535	4.6	24	7.68	67.80°	4370						
RECHARGE RA	TE (qualita	tive): حص	<u>a</u> D								
DEPTH TO WA	TER (pre-sa	ample collec	tion): ત	-17'							
SAMPLER TYPE: TEFLON BAILER ACRYLIC BAILER ELECTRIC PNEUMATIC PUMP OTHER											
SAMPLES COLLECTED: PRESERVED VOA'S UNPRESERVED VOA'S UNPRESERVED LITERS UNPRESERVED LITERS SOO ml PLASTIC BOTTLE WITH PRESERVATIVE FOR METALS: FILTERED UNFILTERED UNFILTERED OTHER											
COMMENTS:											