## ALAMEDA COUNTY HEALTH CARE SERVICES

**AGENCY** 



7

DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

October 2, 2006

Mr. Richard Gold Lerer Brothers Transmission PO Box 117820 Burlingame, CA 94011-7820

Subject: Fuel Leak Case No. RO0000057, Lerer Brothers Transmission, 6340 Christie Avenue, Emeryville, CA

Dear Mr. Gold:

Alameda County Environmental Health Department (ACEH) staff have reviewed the case file and reports entitled, "Report for Additional Soil Borings and Quarterly Groundwater Monitoring" dated November 9, 1999 and prepared on your behalf by Aqua Science Inc. Groundwater sampling conducted during November 1999 confirmed the presence of petroleum hydrocarbon in monitoring well MW-1 up to 1,300  $\mu$ g/L total petroleum hydrocarbon as gasoline (TPHg) 71  $\mu$ g/L benzene, 7.2  $\mu$ g/L toluene, 100  $\mu$ g/L ethylbenzene, 210  $\mu$ g/L xylenes and <10  $\mu$ g/L MtBE. Moreover, an additional downgradient investigation detected minor concentrations of petroleum hydrocarbon constituents of up to 180  $\mu$ g/L TPHg, 1.5  $\mu$ g/L ethylbenzene, 9.1  $\mu$ g/L xylenes and <10  $\mu$ g/L MtBE.

Therefore, to continue the site closure process, ACEH requests that an additional round groundwater monitoring and sampling be completed at the site. Our request is based on the conclusion that the most recent groundwater monitoring data available in our files dates back to 1999. In addition, ACEH request a Well Survey is to be complete to satisfy this requirement for site closure. Considering the length of time since the site closure request was proposed, and in the interest of moving your site through the regulatory process we offer the following observations in the Technical Comments below.

Based on ACEH staff review of the case file, we request that you address the following technical comments and prepare a work plan detailing work to be performed, and send us the reports described below. Please provide 72-hour advance written notification to this office (e-mail preferred to <a href="mailto:steven.plunkett@acgov.org">steven.plunkett@acgov.org</a>) prior to the start of field activities.

#### TECHNICAL COMMENTS

- 1. Monitoring Well Rehabilitation and Redevelopment. ACEH requests that prior to monitoring well sampling, all onsite monitoring wells should be rehabilitated and/or redeveloped; allowing the collection of a representative sample of formation groundwater. Note that well redevelopment may require additional well volumes to be removed to assure that water quality parameters are satisfied. Please describe and present the results of the well redevelopment and rehabilitation activities in the report requested below.
- 2. **Groundwater Sampling**. Groundwater monitoring has not been conducted at the site since 1999. Please sample the existing monitoring wells in order to determine current groundwater

Richard Gold September 29, 2006 Page 2

conditions throughout the site. The water samples are to be analyzed for TPHg and TPHd by EPA Method 8015M or 8260, BTEX, EDB, EDC, MtBE, TAME, ETBE, DIPE, TBA and EtOH by EPA Method 8260 and total lead. If water quality data indicate that groundwater conditions are similar to historical conditions it is anticipated that the site will be moved toward regulatory closure. However, if groundwater quality data indicate that elevated concentrations of petroleum hydrocarbons exist, further investigation may be warranted or additional groundwater monitoring may be requested. Conversely, if water quality data indicate that groundwater conditions are similar to historical conditions it is likely that the site will be moved to closure. Please present the results from groundwater monitoring and sampling in the report requested below.

- 3. Well Survey. It appears that a well survey has not been completed for your site. The well survey shall include a detailed assessment of all wells (monitoring and production wells: active, inactive, standby decommissioned (sealed with concrete), abandoned, (improperly decommissioned or lost); and dewatering and cathodic protection wells) within a ½ mile radius of the subject site. The well survey should include well data from California Department of Water Resource well database and Alameda County Department of Public Works.
- 4. Geotracker EDF Submittals A review of the case file and the State Water Resources Control Board's (SWRCB) Geotracker website indicate that electronic copies of analytical data have not been submitted for your site. Pursuant to CCR Sections 2729 and 2729.1, beginning September 1, 2001, all analytical data, including monitoring well samples, submitted in a report to a regulatory agency as part of the LUFT program, must be transmitted electronically to the SWRCB Geotracker website via the internet. Additionally, beginning January 1, 2002, all permanent monitoring points utilized to collected groundwater samples (i.e. monitoring wells) and submitted in a report to a regulatory agency, must be surveyed (top of casing) to mean sea level and latitude and longitude accurate to within 1meter accuracy, using NAD 83, and transmitted electronically to the SWRCB Geotracker website. Beginning July 1, 2005, electronic submittal of a complete copy of all reports is required in Geotracker (in PDF format). In order to remain in regulatory compliance, please upload all analytical data (collected on or after September 1, 2001), to the SWRCB's Geotracker database website in accordance with the above-cited regulation. Please perform the electronic submittals for applicable data and submit verification to this Agency by October 30, 2006.

#### TECHNICAL REPORT REQUEST

Please submit technical reports to Alameda County Environmental Health (Attention: Mr. Steven Plunkett), according to the following schedule:

 November 15, 2006 –Groundwater Monitoring Well Rehabilitation Report and Sensitive Receptor Survey.

These reports are being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request.

Richard Gold September 29, 2006 Page 3

#### **ELECTRONIC SUBMITTAL OF REPORTS**

The Alameda County Environmental Cleanup Oversight Programs (LOP and SLIC) require submission of all reports in electronic form to the county's ftp site. Paper copies of reports will no longer be accepted. The electronic copy replaces the paper copy and will be used for all public information requests, regulatory review, and compliance/enforcement activities. Instructions for submission of electronic documents to the Alameda County Environmental Cleanup Oversight Program ftp site are provided on the attached "Electronic Report Upload (ftp) Instructions." Please do not submit reports as attachments to electronic mail.

Submission of reports to the Alameda County ftp site is an addition to existing requirements for electronic submittal of information to the State Water Resources Control Board (SWRCB) Geotracker website. Submission of reports to the Geotracker website does not fulfill the requirement to submit documents to the Alameda County ftp site. In September 2004, the SWRCB adopted regulations that require electronic submittal of information for groundwater cleanup programs. For several years, responsible parties for cleanup of leaks from underground storage tanks (USTs) have been required to submit groundwater analytical data, surveyed locations of monitor wells, and other data to the Geotracker database over the Internet. Beginning July 1, 2005, electronic submittal of a complete copy of all necessary reports was required in Geotracker (in PDF format). Please visit the SWRCB website for more information on these requirements (http://www.swrcb.ca.gov/ust/cleanup/electronic reporting).

#### PERJURY STATEMENT

All work plans, technical reports, or technical documents submitted to ACEH must be accompanied by a cover letter from the responsible party that states, at a minimum, the following: "I declare, under penalty of perjury, that the information and/or recommendations contained in the attached document or report is true and correct to the best of my knowledge." This letter must be signed by an officer or legally authorized representative of your company. Please include a cover letter satisfying these requirements with all future reports and technical documents submitted for this fuel leak case.

#### PROFESSIONAL CERTIFICATION & CONCLUSIONS/RECOMMENDATIONS

The California Business and Professions Code (Sections 6735, 6835, and 7835.1) requires that work plans and technical or implementation reports containing geologic or engineering evaluations and/or judgments be performed under the direction of an appropriately registered or certified professional. For your submittal to be considered a valid technical report, you are to present site specific data, data interpretations, and recommendations prepared by an appropriately licensed professional and include the professional registration stamp, signature, and statement of professional certification. Please ensure all that all technical reports submitted for this fuel leak case meet this requirement.

#### UNDERGROUND STORAGE TANK CLEANUP FUND

Please note that delays in investigation, later reports, or enforcement actions may result in your becoming ineligible to receive grant money from the state's Underground Storage Tank Cleanup Fund (Senate Bill 2004) to reimburse you for the cost of cleanup.

#### AGENCY OVERSIGHT

Richard Gold September 29, 2006 Page 4

If it appears as though significant delays are occurring or reports are not submitted as requested, we will consider referring your case to the Regional Board or other appropriate agency, including the County District Attorney, for possible enforcement actions. California Health and Safety Code, Section 25299.76 authorizes enforcement including administrative action or monetary penalties of up to \$10,000 per day for each day of violation.

Should you have any questions, do not hesitate to call me at (510) 383-1767.

Sincerely,

Steven Plunkett

Hazardous Materials Specialist

Enclosure: ACEH Electronic Report Upload (ftp) Instructions

cc: Robert Kitay

Aqua Science Inc

208 W. El Pintado, Suite 400

Danville, CA 94526

Donna Drogos, ACEH Steven Plunkett, ACEH

File

FILE OI	R }	) ENVELOPE	PLAN REVIEW	<b>,</b>		By	Date	۶. ا							Site 11	· ·
PER NO	p. ]	No of	\$300.		Rec'd.	7	-		Pre-Concrete/Gunite		Ву	Date		Pre-Covering	Ву	Date
☐ ow	NER LERGE	BROS.	No.	PI	ans Rec'd.	,	1-1988	1 7	Pre-Plaster				ANKS			-
,	ess 6340 Ct	<del>10005,</del>	Plans Approved	<u> </u>			1	L	Final	-			0.			
<b>*</b>			Layout Made				ţ	Z 0	Septic Tank				] ]	Final		
	$\Lambda$	653-7581	Rejected					Ĭ	Absorption Field				<b> </b>	rnoi		
	A [	the	Applicant Notifi	ed	<del></del>		Absorption Bed			1						
Addr	esto, Bx Sa	35	Plans Returned			<b>†</b>	7				1	··· <del>·</del> ··········	1			
San	Camon 94583	820-939/						House Sewer			-					
OTHE	R (Specify)		Permit Issued CONSTR	UCTION PRO	GRESS ACC	CEPTANO	F	FINAL	Septic Tank	<del></del>	-	<del></del>				
Addre	258		Pre-Plaster/	,					Absorption Field							
	Phone		O Pre-Final		*,		1,	~	Absorption Bed							
⊠ con	TACT FOR INVESTIGATIO	N	ľ	,	<del></del>		4 <sup>5</sup>	OTHER		<del></del>						
XR	2		Final			<u> </u>				T T						
*	***************************************		~	<u> </u>	<del>- , , </del>	<del></del>	REMAR	KS								
				Date	Ву		12.5 12.5 12.5 12.5 12.5 12.5 12.5 12.5	<u> </u>		LOC	ATION		ما	rocks		a '
	RE	MARKS		817/97 A	20De	bite	d De	NR	ef account				<u>/</u>	6340 Ch	stie	
Date 1 20/ 00	By 1 - 0						57	·			-			Emerina		
1-08.88	Clou Sent Clo	oure plan fe	run to					· · · · ·			<del>-,</del>	v	icinity A	Λ	(6)	
24	De comp	leted,					2	. `						•		
2-7	Kon Closure	Alun appor	oved		,		1 1	,		7						
	Conditio	7, Oly	:			`			. *	-		P <sub>rojs</sub>	PC/			Ú
25	CR. Questo to	observe Cu	test Cleans				100	٠ ١,٠,٠	s'	-		F00 P0		<22	-	
1/16 : 1	IR TOMARY F	The Ace ourses		·		-		· · ·		-		Doto	<i>"</i>	82 05 m	,	
i 1	CR Verbal	Jab report	recewel			<del></del>	1.37	` <u>`</u>				٠.	\	1000		
7	gane 1	en Car	Cec -		27	4	1 6	- ' <u>- '                               </u>	`	_				10.88 10.88	•	
		· · · · · · · · · · · · · · · · · · ·			_	<del>-</del>	1.	<u>,,-</u>		_	-					**-
th or flow							`,	,		_	<del></del>	<del></del>	~			
CELLAND SECTION										CONSISTENCE CONTRACTOR						
Agh Shown was	E C			(187)	and the same of th	<del></del>				Andrew Co. Co.						
	33.00			A SA PARTY P	entre Scinciona			No.		Tal / May 10 (A) Tal Andrews						

**AGENCY** 

DAVID J. KEARS, Agency Director



**ENVIRONMENTAL HEALTH SERVICES** 

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9395 (FAX)

November 5, 1999

Mr. Richard Gold Leher Brothers Transmission P.O. Box 117820 Burlingame, CA 94011-7820

RE: Leher Brothers Transmission (STID # 1247) 6340 Christie Avenue, Emeryville, California 94608

LANDOWNER NOTIFICATION AND PARTICIPATION REQUIREMENTS

Dear Mr. Gold:

This letter is to inform you of new legislative requirements pertaining to cleanup and closure of sites where an unauthorized release of hazardous substance, including petroleum, has occurred from an underground storage tank (UST). Section 25297.15(a) of Ch. 6.7 of the Health & Safety Code requires the primary or active responsible party to notify all current record owners of fee title to the site of: 1) a site cleanup proposal, 2) a site closure proposal, 3) a local agency intention to make a determination that no further action is required, and 4) a local agency intention to issue a closure letter. Section 25297.15(b) requires the local agency to take all reasonable steps to accommodate responsible landowners' participation in the cleanup or site closure process and to consider their input and recommendations.

For purposes of implementing these sections, you have been identified as the primary or active responsible party. Please provide to this agency, within twenty (20) calendar days of receipt of this notice, a complete mailing list of all current record owners of fee title to the site. You may use the enclosed "list of landowners" form (sample letter 2) as a template to comply with this requirement. If the list of current record owners of fee title to the site changes, you must notify the local agency of the change within 20 calendar days from when you are notified of the change.

If you are the sole landowner, please indicate that on the landowner list form. The following notice requirements do not apply to responsible parties who are the sole landowner for the site.

LANDOWNER NOTIFICATION

Re: 6340 Christie Avenue, Emeryville, CA

November 5, 1999

Page 2 of 2

In accordance with Section 25297.15(a) of Ch. 6.7 of the Health & Safety Code, you must certify to the local agency that all current record owners of fee title to the site have been informed of the proposed action before the local agency may do any of the following:

- 1) consider a cleanup proposal (corrective action plan)
- 2) consider a site closure proposal
- 3) make a determination that no further action is required
- 4) issue a closure letter

You may use the enclosed "notice of proposed action" form (sample letter 3) as a template to comply with this requirement. Before approving a cleanup proposal or site closure proposal, determining that no further action is required, or issuing a closure letter, the local agency will take all reasonable steps necessary to accommodate responsible landowner participation in the cleanup and site closure process and will consider all input and recommendations from any responsible landowner.

Please call me at (510) 567-6780 should you have any questions about the content of this letter.

Sincerely,

Lusan Z. Hugo Susan L. Hugo

Hazardous Materials Specialist

Attachments

cc:

Chuck Headlee, RWQCB


SH / files

SAMPLE LETTER (2): LIST OF LANDOWNERS FORM
Name of local agency Street address City
SUBJECT: CERTIFIED LIST OF RECORD FEE TITLE OWNERS FOR (Site Name and Address)
(Note: Fill out item 1 if there are multiple site landowners. If you are the sole site landowner, skip item 1 and fill out item 2.)
1. In accordance with section 25297.15(a) of Chapter 6.7 of the Health & Safety Code, I, (name of primary responsible party), certify that the following is a complete list of current record fee title owners and their mailing addresses for the above site:
2. In accordance with section 25297.15(a) of Chapter 6.7 of the Health & Safety Code, I, (name of primary responsible party), certify that I am the sole landowner for the above site.
Sincerely,
Signature of primary responsible party
Name of primary responsible party

SAMPLE LETTER 3: NOTICE OF PROPOSED ACTION SUBMITTED TO LOCAL AGENCY
Name of local agency Street address City
SUBJECT: NOTICE OF PROPOSED ACTION SUBMITTED TO LOCAL AGENCY FOR (Site Name and Address)
In accordance with section 25297,15(a) of Chapter 6.7 of the Health & Safety Code, I, ( <u>name of primary responsible party</u> ), certify that I have notified all responsible landowners of the enclosed proposed action. Check space for applicable proposed action(s):
cleanup proposal (corrective action plan)
site closure proposal
local agency intention to make a determination that no further action is required
local agency intention to issue a closure letter
Sincerely,
Signature of primary responsible party
Name of primary responsible party
cc: Names and addresses of all record fee title owners

AGENCY DAVID J. KEARS, Agency Director





99 NOV 15 PM 1:31 ENVIRONMENTAL HEALTH SERVICES

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

(510) 567-6700 (510) 337-9335 (FAX)

November 5, 1999

Mr. Richard Gold Leher Brothers Transmission P.O. Box 117820 Burlingame, CA 94011-7820

RE: Leher Brothers Transmission (STID # 1247)

6340 Christie Avenue, Emeryville, California 94608

#### LANDOWNER NOTIFICATION AND PARTICIPATION REQUIREMENTS

Dear Mr. Gold:

This letter is to inform you of new legislative requirements pertaining to cleanup and closure of sites where an unauthorized release of hazardous substance, including petroleum, has occurred from an underground storage tank (UST). Section 25297.15(a) of Ch. 6.7 of the Health & Safety Code requires the primary or active responsible party to notify all current record owners of fee title to the site of: 1) a site cleanup proposal, 2) a site closure proposal, 3) a local agency intention to make a determination that no further action is required, and 4) a local agency intention to issue a closure letter. Section 25297.15(b) requires the local agency to take all reasonable steps to accommodate responsible landowners' participation in the cleanup or site closure process and to consider their input and recommendations.

For purposes of implementing these sections, you have been identified as the primary or active responsible party. Please provide to this agency, within twenty (20) calendar days of receipt of this notice, a complete mailing list of all current record owners of fee title to the site. You may use the enclosed "list of landowners" form (sample letter 2) as a template to comply with this requirement. If the list of current record owners of fee title to the site changes, you must notify the local agency of the change within 20 calendar days from when you are notified of the change.

If you are the sole landowner, please indicate that on the landowner list form. The following notice requirements do not apply to responsible parties who are the sole landowner for the site.

### SAMPLE LETTER (2): LIST OF LANDOWNERS FORM

Name of local agency Ala. County Itealth Cara Street address City  Ala. County Itealth Cara  1131 Harbor Bay Barkway, Scite 250  Alameda 94502
SUBJECT: CERTIFIED LIST OF RECORD FEE TITLE OWNERS FOR (Site Name and Address) Lever Bros Transmission 6340 Christie Ave.  Emery Ville CA 94608
(Note: Fill out item 1 if there are multiple site landowners. If you are the sole site landowner, skip item 1 and fill out item 2.)  Parcel Number 49-1492-8
1. In accordance with section 25297.15(a) of Chapter 6.7 of the Health & Safety Code, I, <i>(name of primary responsible party)</i> , certify that the following is a complete list of current record fee title owners and their mailing addresses for the above site:
In accordance with section 25297.15(a) of Chapter 6.7 of the Health & Safety Code, I, (name of primary responsible party), certify that I am the sole landowner for the above site.  Richard + Beverly Gold
Signature of primary responsible party
Name of primary responsible party  Richard Gold



# State Water Resources Contre Board

#### Division of Clean Water Programs

Gray Davis

Winston H. Hickox Secretary for Environmental Protection 2014 T Street • Sacramento, California 95814 • (916) 227-4539

Mailing Address: P.O. Box 944212 • Sacramento, California • 94244-2120

FAX (916) 227-4530 • Internet Address: http://www.swrcb.ca.gov/~cwphome/ustcf

Gray Davis

APR 2.3 1999

Richard Gold Lerer Bros. P O Box 117820 Burlingame, CA 94011-7820

UNDERGROUND STORAGE TANK CLEANUP FUND, CLAIM NO. 013874, FOR SITE ADDRESS: 6340 CHRISTIE AVE, EMERYVILLE 94608

The State Water Resources Control Board (State Board) is able to issue, pursuant to applicable regulations, the enclosed Letter of Commitment (LOC) in an amount not to exceed \$15,000. This LOC is based upon our review of the corrective action costs you reported to have incurred to date. The LOC may be modified by the State Board.

It is very important that you read the terms and conditions listed in the enclosed LOC. Claims filed with the Underground Storage Tank Cleanup Fund far exceed the funding available and it is very important that you make use of the funding that has been committed to your cleanup in a timely manner.

You are reminded that you must comply with all regulatory agency time schedules and requirements and you must obtain three bids for any required corrective action. Only corrective action costs required by the regulatory agency to protect human health, safety and the environment can be claimed for reimbursement. Unless waived in writing, you are required to obtain preapproval of costs for all future corrective action work (form enclosed). If you have any questions on obtaining preapproval of your costs or the three bid requirement, please call Mark Owens, our Technical Reviewer assigned to claims in your Region, at (916) 227-7883. Failure to obtain preapproval of your future costs may result in the costs not being reimbursed.

The following documents needed to submit your reimbursement request are enclosed:

- "Reimbursement Request Instructions" package. Retain this package for future reimbursement requests. These instructions must be followed when seeking reimbursement for corrective action costs incurred after January 1, 1988. Included in the instruction package are samples of completed reimbursement request forms and spreadsheets.
- "Bid Summary Sheet" to list information on bids received which must be completed and returned.
- "Reimbursement Request" forms which you must use to request reimbursement of costs incurred.
- "Spreadsheet" forms which you must use in conjunction with your reimbursement request.

PROTECTION AL

99 APR 26 PH 2: 29

#### THIS IS IMPORTANT TO YOU, PLEASE NOTE:

You have 90 calendar days from the date of this letter to submit your first reimbursement request for incurred corrective action costs. NO EXTENSIONS CAN BE GRANTED. If you fail to do so, your LOC funds will automatically be reduced to zero (deobligated). Once this occurs, any future funds for this site are subject to availability when you submit your first reimbursement request. We continuously review the status of all active claims. You must continue to remain in compliance and submit a reimbursement request every 6 months. Failure to do so will result in the Fund taking steps to withdraw your LOC.

If you have any questions regarding the enclosed documents, please contact Anna Torres at (916) 227-4388.

Sincerely,

Dave Deaner, Manager UST Cleanup Fund Program

**Enclosures** 


cc: Mr. Thomas Peacock Alameda County EHD 1131 Harbor Bay Pkway, 2nd Fl. Alameda, CA 94502-6577



## State Water Resources Control Board

#### **Division of Clean Water Programs**

2014 T Street • Sacramento, California 95814 • (916) 227-4539 Mailing Address: P.O Box 944212 • Sacramento, California • 94244-2120 FAX (916) 227-4530 • Internet Address. http://www.swrcb.ca.gov/~cwphome/ustcf



Governor

Protection S 05 Tanuary 26, 1999 15th 5# 1247

Gold Truck Parts P O Box 117820 BurlingameCA 94011-7820

UNDERGROUND STORAGE TANK CLEANUP FUND PROGRAM, NOTICE OF ELIGIBILITY DETERMINATION: CLAIM NUMBER 013874; FOR SITE ADDRESS: 6340 CHRISTIE AVE, **EMERYVILLE** 

Your claim has been accepted for placement on the Priority List in Priority Class "B" with a deductible of \$5,000.

Compliance Review: After adoption of the Priority List, staff will review, verify, and process applications based on their priority and rank within a priority class. During this Compliance Review, staff may request additional information needed to verify eligibility. Once review of the application is complete and the claim is determined to be valid, a Letter of Commitment will be issued obligating funds toward the cleanup. After the compliance review, your claim may be rejected if Division staff determine that you have not complied with regulations governing site cleanup, you have not supplied necessary information or documentation, or your claim application contains a material error. In such event, you will be issued a Notice of Intended Removal from the Priority List, informed of the basis for the proposed removal of your claim, and provided an opportunity to correct the condition that is the basis for the proposed removal. Your claim will be barred from further participation in the Fund, however, if the claim application contains a material error resulting from fraud or intentional or negligent misrepresentation.

Record keeping: During your cleanup project you should keep complete and well organized records of all corrective action activity and payment transactions. If you are eventually issued a Letter of Commitment, you will be required to submit: (1) copies of detailed invoices for all corrective action activity performed (including subcontractor invoices), (2) copies of canceled checks used to pay for work shown on the invoices, (3) copies of technical documents (bids, narrative work description, reports), and (4) evidence that the claimant paid for the work performed (not paid by another party). These documents are necessary for reimbursement and failure to submit them could impact the amount of reimbursement made by the Fund. It is not necessary to submit these documents at this time; however, they will definitely be required prior to reimbursement.

Compliance with Corrective Action Requirements: In order to be reimbursed for your eligible costs of cleanup incurred after December 2, 1991, you must have complied with corrective action requirements of Article 11, Chapter 16, Division 3, Title 23, California Code of Regulations. Article 11 categorized the corrective action process into phases. In addition, Article 11 requires the responsible party to submit an investigative workplan/Corrective Action Plan (CAP) before performing any work. This phasing process and the workplan/CAP requirements were intended to:

help the responsible party undertake the necessary corrective action in a cost-effective, efficient and timely manner;

- 2. enable the regulatory agency to review and approve the proposed cost-effective corrective action alternative before any corrective action work was performed; and
- 3. ensure the Fund will only reimburse the most cost-effective corrective action alternative required by the regulatory agency to achieve the minimum cleanup necessary to protect human health, safety and the environment.

In some limited situations interim cleanup will be necessary to mitigate a demonstrated immediate hazard to public health, or the environment. Program regulations allow the responsible party to undertake interim remedial action after: (1) notifying the regulatory agency of the proposed action, and; (2) complying with any requirements that the regulatory agency may set. Interim remedial action should only be proposed when necessary to mitigate an immediate demonstrated hazard. Implementing interim remedial action does not eliminate the requirement for a CAP and an evaluation of the most cost-effective corrective action alternative.

Three bids and Cost Preapproval: Only corrective action costs required by the regulatory agency to protect human health, safety and the environment can be claimed for reimbursement. You must comply with all regulatory agency time schedules and requirements and you must obtain three bids for any required corrective action. Unless waived in writing, you are required to obtain preapproval of costs for all future corrective action work. If you do not obtain three bids and cost preapproval, reimbursement is not assured and costs may be rejected as ineligible.

If you have any questions, please contact me at (916) 227-4539.

Sincerely,

Claims Review Unit

Underground Storage Tank Cleanup Fund


cc: Mr. Thomas Peacock
Alameda County EHD
1131 Harbor Bay Pkway, 2nd Fl.
Alameda, CA 94502-6577





#### **Division of Clean Water Programs**

2014 T Street • Sacramento, California 95814 • (916) 227-4539
Mailing Address: P.O. Box 944212 • Sacramento, California • 94244-2120
FAX (916) 227-4530 • Internet Address: http://www.swrcb.ca.gov/~cwphome/ustcf



Stro# 1247 SH

January 6, 1999

Mr. Richard Gold Lerer Bros. P O Box 117820 Burlingame, CA 94011-7820

UNDERGROUND STORAGE TANK CLEANUP FUND PROGRAM, REQUEST FOR FURTHER DOCUMENTATION DURING INITIAL REVIEW: CLAIM NUMBER 013874; FOR SITE ADDRESS: 6340 CHRISTIE AVE, EMERYVILLE

After reviewing your claim application to the Cleanup Fund, we find that the following additional information is needed to determine your eligibility for placement on the Priority List:

- 1. A copy of the 1988 underground storage tank removal permit.
- 2. An explanation of why corrective action was not initiated until 10 years after the tank was removed.
- 3. Copies of 1995, 1996, and 1997 personal income tax returns (Form 1040) for Richard Gold and June Levy. These are needed because you share the controlling interest in the corporation. The Fund looks at all controlling interests when evaluating the total gross receipts limit. If there are any other partnerships or corporations that fall under either of the personal income tax returns, please also submit copies of those returns for the same control years.

**NOTE:** Failure to respond to this request within thirty (30) calendar days from the date of this letter may result in an ineligibility determination of your claim.

If you have any questions, please contact me at (916) 227-4539.

Sincerely.

Cheryl Goldon Claim Review Unit

Underground Storage Tank Cleanup Fund

cc: Mr. Thomas Peacock
Alameda County EHD
1131 Harbor Bay Pkway, 2nd Fl.
Alameda, CA 94502-6577

California Environmental Protection Agency

white -env.health yellow -facility pink -files

# ALAMEDA COUNTY, DEPARTMENT OF ENUIRONMENTAL HEALTH

1131 Harbor Bay Pkwy Alameda CA 94502 510/567-6700

Hazardous Materials Inspection Form

11, 111

Site ID #/447 Site Name Lever Brathers Line Shirt Store 1,21,99
Site Address 6340 Quistin Que.
City Emeryille zip 94608 Phone
MAX AMT stored > 500 lbs, 55 gal., 200 cft.?
Inspection Categories:I. Haz. Mat/Waste GENERATOR/TRANSPORTER
I. Haz. Mat/Waste GENERATOR/TRANSPORTER I. Hazar dous Materials Business Plan, Acutely Hazar dous Materials
III. Under gr ound Stor age Tanks
* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)
Comments: But of Habert Kitay (ASE)
Smilling 3 bowings, in Stall 3 Wells
Superfled sail agreemed to consist of fill marerial
(asphalt like tar) Site close to Market place
Will Subnice fregion in be days.
Contact
Title Inspector
Signature Signature Signature

#### **ALAMEDA COUNTY**

#### **HEALTH CARE SERVICES**



DAVID J. KEARS, Agency Director

**ENVIRONMENTAL HEALTH SERVICES** 

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9335 (FAX)

January 19, 1999

Mr. Richard Gold Lerer Brothers Transmission P.O. Box 117820 Burlingame, CA 94011-7820

Subject:

Lerer Brothers Transmission (STID # 1247) 6340 Christie Avenue, Emeryville, CA 94608

Dear Mr. Gold:

This agency has reviewed the Work Plan for Soil and Groundwater Assessment, dated January 14, 1999, prepared and submitted by Aqua Science Engineers Inc., for the above referenced site.

The work plan to determine the extent of petroleum hydrocarbon contamination in soil and groundwater related to the former underground storage tank (UST) removed at the site is acceptable provided the following items are addressed:

- 1. At a minimum, one soil sample must be collected from each boring, preferably at the soil / water interface. Both soil and groundwater samples collected from each boring must be analyzed for Total Petroleum Hydrocarbon (TPH) as gasoline, benzene, toluene, ethyl benzene, xylene, methyl tertiary butyl ether (MTBE) and lead.
- 2. Notify our office at least 72 hours in advance of any field activity at the site.

A report documenting the results of this investigation must be submitted to this office no later than 60 days after completion of the work plan implementation.

If you have any questions concerning this letter or the subject site, please contact me at (510) 567-6780.

Sincerely,

Hazardous Materials Specialist

cc:

Chuck Headlee, San Francisco Bay RWQCB

Robert Kitay, Aqua Science Engineers, 208 W. El Pintado Road, Danville, CA 94526

SH/ files

## ALAMEDA COUNTY HEALTH CARE SERVICES

**AGENCY** 

DAVID J. KEARS, Agency Director



ENVIRONMENTAL HEALTH SERVICES

1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 (510) 337-9335 (FAX)

December 7, 1998

Mr. Richard Gold Lerer Brothers Transmission P.O. Box 117820 Burlingame, CA 94011-7820

Subject:

Lerer Brothers Transmission (STID # 1247) 6340 Christie Avenue, Emeryville, CA 94608

Dear Mr. Gold:

This agency has reviewed the Soil and Groundwater Assessment Report, dated October 27, 1998, prepared and submitted by Aqua Science Engineers Inc., for the above referenced site. One 2,000 gallon steel underground storage tank (UST) used to store unleaded gasoline was reportedly removed from the subject property in 1988. Soil and groundwater investigation was conducted to characterize the extent of petroleum hydrocarbon contamination related to releases associated with the former UST at the site.

On October 9, 1998, five soil borings (BH-A to BH-E) were drilled at the site. One soil sample was collected from each boring at the capillary zone (between 3.5 to 6 feet depth). Hydrocarbon sheen was present in boring BH-A. Soil samples collected from the borings showed petroleum hydrocarbon contamination up to 1,400 ppm Total Petroleum Hydrocarbon (TPH) gasoline, 0.011 ppm benzene, 25 ppm toluene, 7.1 ppm ethyl benzene and 15 ppm xylenes. In addition, the grab water samples collected from the borings found dissolved petroleum hydrocarbon contamination at the following concentrations: up to 620,000 ppb TPH gasoline, 1,200 ppb benzene, 4,900 ppb toluene and 16,000 ppb ethyl benzene.

Based on the review of the data submitted for the site, the extent of the groundwater contamination has not been fully defined. Please submit a workplan to determine the extent of the groundwater contamination beneath the site. Your work plan should include at a minimum the installation of shallow groundwater monitoring wells and should be submitted no later than January 30, 1999.

If you have any questions concerning this letter or the subject site, please contact me at (510) 567-6780.

Sincerely,

Susan L. Hugo

Hazardous Materials Specialist

cc: Chuck Headlee, San Francisco Bay RWOCB

Dave Allen, Aqua Science Engineers, 208 W. El Pintado Road, Danville, CA 94526

SH/ files

#### LOP - RECORD CHANGE REQUEST FORM

printed: 12/02/98

Mark Out What Needs Changing and Hand to LOP Data Entry (Name/Address changes go to Annual Programs Data Entry)

Insp: SH

SUBSTANCE: 8006619 AGENCY # : 10000 SOURCE OF FUNDS: F

StID : 1247 LOC: -0-

SITE NAME: Lerer Brothers Transmission DATE REPORTED : 10/29/98 DATE CONFIRMED: 10/27/98 ADDRESS : 6340 -0 Christie Ave

MULTIPLE RPs : N CITY/ZIP: Emeryville 94608

#### SITE STATUS

CASE TYPE: U CONTRACT STATUS: 3 PRIOR CODE: 2B4 EMERGENCY RESP: -0-

DATE COMPLETED: 12/02/98 RP SEARCH: S

PRELIMINARY ASMNT: U DATE UNDERWAY: 10/06/98
REM INVESTIGATION: - DATE UNDERWAY: -0REMEDIAL ACTION: - DATE UNDERWAY: -0POST REMED ACT MON: - DATE UNDERWAY: -0-DATE COMPLETED: -0-DATE COMPLETED: -0-DATE COMPLETED: -0-DATE COMPLETED: -0-

ENFORCEMENT ACTION TYPE: 1 DATE ENFORCEMENT ACTION TAKEN: 12/02/98 LUFT FIELD MANUAL CONSID: 3HSCA

DATE CASE CLOSED: -0-CASE CLOSED: -

CASE CLOSED: - DATE CASE CLOSED

DATE EXCAVATION STARTED: -0- REMEDIAL ACTIONS TAKEN: ED-

#### RESPONSIBLE PARTY INFORMATION

RP#1-CONTACT NAME: Mr. Richard Gold

COMPANY NAME: Lerer Brothers Transmission

ADDRESS: P.o. Box 117820

CITY/STATE: Burlingame, Ca 94011-7820

	<del></del>		INSPECTOR VER	ON:	
NAME			SIGNATURE		DATE
Name/Address	Changes	Only	DATA ENTRY	INPUT:	Case Progress Changes
ANNPGMS	LOP		DATE		LOP DATE

need town of logg.

# Transfer of Eligible Local Oversight Case

STID 1247 Date transferred 12/1/98

Date:	il/24/98 From: SUSAN HUGO  ama: LERER BROTHERS TRANSMISSION SERVICE  HHTT: 6340 CHRISTIE AVE. City: EMERYVILLED: 94608
Addres	ss:City: EMERGVILLED: 94608
To be	eligible for LOP, case must meet 3 qualifications:
1(Y)	N Tanks Removed? # of removed? Date removed: undnown
2. Y	N Tanks Removed? # of removed? Date removed: undrown  N Samples received? Contamination level: ppm TPHg in #20  Type of test Contamination should be over 100 ppm TPH to qualify for LOP
3(Y)	N Petroleum? Circle Type(s): • Avgas •leaded •unleaded •fuel oil •jet • diesel •waste oil •kerosene •solvents
Proced	dure to follow should your site meet all the above qualifications:
1.	a. Close the deposit refund case. b. Account for ALL time you have spent on the case. c. Turn in account sheet to Leslie.  If there are funds still remaining it is still better to transfer the case to LOP as the rate for LOP allows more overhead. DO NOT attempt to continue to oversee the site simply because there are funds remaining!  Remaining DepRef \$'s:  DepRef Case Closed with Candyce/Leslie? Y N (If no, explain why below.)
2.	Submit the completed A and B permit application forms to NORMA.
3.	Give the entire case to the proper LOP staff.

# Transfer of Eligible Local Oversight Case

	STID <u>LL47</u> Date transferred
Date: Site Na 7 Addres	ill24/98 From: SUSAN HUGO  THE BROTHERS TRANSMISSION SERVICE  15: 6340 CHRISTIE AVE. City: EMERYVILLED: 94608
	eligible for LOP, case must meet 3 qualifications:
1 Y 1 2. Y 1	N Tanks Removed? # of removed? Tanks Removed: Turknown  N Samples received? Contamination level: 60 ppm TPHg in #20  Type of test  Contamination should be over 100 ppm TPH to qualify for LOP
· · · · · ·	N Petroleum? Circle Type(s): • Avgas •leaded •unleaded •fuel oil •jet • diesel •waste oil •kerosene •solvents
Proced	dure to follow should your site meet all the above qualifications:
,	a. Close the deposit refund case. b. Account for ALL time you have spent on the case. c. Turn in account sheet to Leslie.  If there are funds still remaining it is still better to transfer the case to LOP as the ra more overhead. DO NOT attempt oversee the site simply because the remaining!  Remaining DepRef \$'s:
	Remaining DepRef \$'s:
2.	Submit the completed A and B permit application LOP. Whocked to the
3.	Give the entire case to the proper LOP staff.  Starts.

RICHARD GOLD c/o Lerer Brothers 6340 Christie Ave. Emeryville, CA 94608

Ausan Hugo

Ola. County Health algeney

10/8/98
PROTECTION

98 OCT - 9 PM 3: 37

1131 Harbor Bay Parkway, 2 ND Floor

Olameda, CA. 94502

Dear Mrs. Hugo:

Enclosed plase find my check\*
1194 in the amount of \$500.00.
This is a deposit for a case review of 6340 Christie ave, Emeryville by Terry of Aqua Science Engineers.

If there are any problems please call me at 653-7587 during the day.

Thank you,

Parhand Dolf
Owner-Gold Truck Parts
don Jones Buss.

RICHARD GOLD c/o Lerer Brothers 6340 Christie Ave. Emeryville, CA 94608





	UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT							
	HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED?  YES NO							
1	M   M   Z o   4 o   9 v   8 v   SIGNED   SIGNATURE   SIGNATURE							
à	Robert Kitay 1925) 820-9391 Roll & Kitay							
PORTED	REPRESENTING OWNER/OPERATOR REGIONAL BOARD COMPANY OR AGENCY NAME  LOCAL AGENCY OTHER ENVIRONMENTAL CONSULTANT Agua Science Engiheers, Inc.							
2	ADDRESS 208 West El Pintado Road, Danville, CA 94526							
SBLE	NAME Lever Brothers Transmission UNKNOWN Richard Gold (650) 579-1919							
RESPON PAR	ADDRESS P.O. BOX 117820, Burlingame, UA 94011-7820							
	STREET CITY STATE ZIP FACILITY NAME (IF APPLICABLE)  OPERATOR  PHONE							
NOTA	Leter Brothers Transmission Richard Gold (650) 579-1919  ADDRESS 6340 Christie Ave Emeryville Alameda							
TE LO	STREET CITY COUNTY ZIP							
Ľ	RESIDENTIAL OTHER FARM OTHER Transmission 34							
SHING	LOCAL AGENCY AGENCY NAME CONTACT PERSON PHONE Alameda County Health Care Servicus Agency Susan Hugo (510) 567-6700							
MPLEM AGEN	San Francisco Bay Region Chuck Headler (S10) 622-2433							
88	(1) NAME QUANTITY LOST (GALLONS)							
UBSTAN	Unheaded gasoline \times unknown							
S E	DATE DISCOVERED INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS							
SATEME	1 M O M O D 9 V 8 V							
VERY/A	M M D D V V V S UNKNOWN REMOVE CONTENTS REPLACE TANK CLOSE TANK							
DISCOVE	HAS DISCHARGE BEEN STOPPED?    REPAIR TANK   REPAIR PIPING   CHANGE PROCEDURE							
AUSE	SOURCE OF DISCHARGE TANKS ONLY/CAPACITY MATERIAL CAUSE(S)							
SOURCE/CAUSE	PIPING LEAK  AGE YRS STEEL  CORROSION W UNKNOWN							
	OTHER UNKNOWN OTHER SPILL OTHER							
CASE	UNDETERMINED SOIL ONLY GROUNDWATER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)							
CURRENT	CHECK ONE ONLY  SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLEM) CLEANUP IN PROGRESS SIGNED OFF (CLEANUP COMPLETED OR UNNECESSARY)							
ଅନ	NO ACTION TAKEN POST CLEANUP MONITORING IN PROGRESS NO FUNDS AVAILABLE TO PROCEED EVALUATING CLEANUP ALTERNATIVES CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)							
REMEDIAL ACTION	CAP SITE (CD) EXCAVATE & DISPOSE (ED) REMOVE FREE PRODUCT (FP) ENHANCED BIO DEGRADATION (IT)							
A REA	CONTAINMENT BARRIER (CB) EXCAVATE & TREAT (ET) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS) TREATMENT AT HOOKUP (HU) NO ACTION REQUIRED (NA) OTHER (OT)							
Ę2								
COMMENTS								
X								

aqua science .... engineers inc. £8 007 29 PM 2: 34 October 27, 1998 SUD RAT

> o f SOIL AND GROUNDWATER ASSESSMENT ASE JOB NO. 3389 a t Lerer Brothers Transmission Service 6340 Christie Avenue Attri: Richard Gold (650)579-1919 P.O. Box 117820 \$160)5790774 Burlingame 94011-7820 Emeryville, California

Submitted by: AQUA SCIENCE ENGINEERS, INC. 208 W. El Pintado Road Danville, CA 94526 (925) 820-9391

REPORT

L	UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT
	HAS STATE OFFICE OF EMERGENCY SERVICES  FOR LOCAL AGENCY USE ONLY  HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT SMILOYEE AND THAT I HAVE  REPORTED THIS INFORMATION TO LOCAL AGENCY USE ONLY  REPORTED THIS INFORMATION TO LOCAL AGENCY USE ONLY
Ι.	M / M Z d 4 d 9 v 8 v Server S
) BY	NAME OF INDIVIDUAL FILING REPORT  ROBERT K: Tay  REPRESENTING  REPRESENT
EPORTED	LOCAL AGENCY OTHER Environmental consultant Aqua Science Engileers To
	NAME  ADDRESS 208 West El Pintado Road, Danville, CA 94526  STREET:  CONTACT PERSON  I PHONE
PONSIBLE	Lever Brothers Transmission UNKNOWN Richard Gold (650) 579-1919
AES .	ADDRESS P.O. BOX 117820, Burlingame, UA 94011-7820  STATE  TAGILITY NAME (IF APPLICABLE)  OPERATOR  OPERATOR  DELPAIS
CATION	Lever Brothers Transmission Richard Gold (650) 579-1919
SITELOX	CROSS STREET CITY COUNTY ZIP
g g	RESIDENTIAL   OTHER   FARM   OTHER Transmission 54
PLEMENT AGENCIE	Alameda County Health Care Services Agency Susan Hugo (510) 567-6700 REGIONAL BOARD PHONE
<u>₹</u>	San Francisco Bay Region Chuck Headles (510) 622-2433
SUBSTAN	Unheaded gasoline \\ \( \mathbb{Z} \) UNKNOWN
<del></del>	UNKNOWN
EMENT	DATE DISCOVERED   HOW DISCOVERED   INVENTORY CONTROL   SUBSURFACE MONITORING   NUISANCE CONDITIONS
ERY/ABATEMENT	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS  OTHER  DATE DISCHARGE BEGAN  METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)  WE WINNEY THAT APPLY DEPTH OF TANK OF
DISCOVERY/ABATEMENT	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS    M
	INVENTORY CONTROL  SUBSURFACE MONITORING  NUISANCE CONDITIONS  TANK TEST  TANK REMOVAL  OTHER  DATE DISCHARGE BEGAN  METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)  METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)  REMOVE CONTENTS  REPAIR TANK  REPAIR PIPING  CHANGE PROCEDURE  SOURCE OF DISCHARGE  TANK LEAK  UNKNOWN  TANK LEAK  UNKNOWN  TANK LEAK  OTHER  CAUSE(S)  CAUSE(S)
SOURCE/CAUSE	INVENTORY CONTROL  SUBSURFACE MONITORING  NUISANCE CONDITIONS  NUISANCE
CASE SOURCECAUSE	INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS  INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS  NUISANCE COND
TYPE SOURCECAUSE	MI O M O D O D O D O D O D O D O D O D O D
STATUS TYPE SOURCECAUSE	INVENTORY CONTROL   SUBSURFACE MONITORING   NUISANCE CONDITIONS
CASE SOURCECAUSE	INVENTORY CONTROL  SUBSURFACE MONITORING  NUISANCE CONDITIONS  INVENTORY CONTROL  SUBSURFACE MONITORING  NUISANCE CONDITIONS  NUISANCE CONTENTS  NEPLIC TANK REPAIR PIPING  CHANGE PROPERLY  NATER ANK  NEPAIR PIPING  NEPAIR PLAY  NEPAIR PLA
STATUS TYPE SOURCECAUSE	INVENTORY CONTROL  SUBSURFACE MONITORING  NUISANCE CONDITIONS  NUISANCE CONDITIONS  NUISANCE CONDITIONS  NUISANCE CONDITIONS  TANK REMOVAL  OTHER  METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY)  REMOVE CONTENTS  REPLACE TANK  CLOSE TANK  HAS DISCHARGE BEEN STOPPED?  NO IF YES, DATE  TANK SOLLY, CAPACITY  MATERIAL  CAUSE(S)  TANK LEAK  UNKNOWN  TANK SOLLY, CAPACITY  MATERIAL  CHECK ONE ONLY  GROUNDWATER  DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)  CHECK ONE ONLY  SITE INVESTIGATION IN PROGRESS (DEFINING EXTENT OF PROBLEM)  NO ACTION TAKEN  POST CLEANUP MONITORING IN PROGRESS  CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)  CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS)  CAPSTIE (CD)  REMOVE FREE PRODUCT (FP)  ENHANCED BIO DEGRADATION (IT)  REPLACE TANK  CLOSE TANK  CHARGE PROCEDURE  CHARGE PROCEDURE  CHECK ALL THAT APPLY)  REPLACE TANK  CLOSE TANK  CHARGE PROCEDURE  CHARGE PROCEDURE  CHARGE PROCEDURE  TANK REMOVE CONTENTS  REPLACE TANK  CLOSE TANK  CHARGE PROCEDURE  CHARGE PROCEDURE  CHARGE PROCEDURE  TANK REMOVE FREE PRODUCT (FP)  ENHANCED BIO DEGRADATION (IT)  REPLACE SUPPLY (RS)

## CITY OF LERYVILLE

NERYVILLE To di

### FIRE CODE PERMIT

No 1069

Ø 001

	Acus S					}
ISSION IS HEREBY GRAN	[ED	Science Engin		3 1		1   1000 m '
OPERATE MAINTAIN Remove	UG fuel tank	x(1,000-gals)		1		1069
STORE				} -\	Due Date:	
REMISES LOCATED AT	6340 Christ	ie Avenue			Original XX	
*				1 1	Renewal	1
DDIC INSPECTIONS ARE A	CONDITION OF THIS	PERMIT WHICH IS ISS	OF SAID CODE.	-		8
UNIFORM FIRE CODE, A	SPECIFIED IN SECTIO	N 41101		.]	Date: 2-4-	88
ITION REQUIREMENTS	Removal to c	omply w/requ	rements or		Fee S40	00
ameda County D	ept.of Healt	h Care Servi	ces redurianement		CashC	No.HS
. co. district # <b>6</b>	'.}	PATION DATE: 2 -	1-89		Receipt No	
, CO. DISTRICT #	PEDAAIT	APPROVED BY		<b>1</b> 1	Received by	7 2 -
THIS PERMIT MUST BE	1 -	*	2/4/88	·		
OSTED WITH BUSINESS LICENSE	15	us we	DATE	]		:
	FIRE MAR	SHAL	PAIC			
1.	· ·				1	d ·
Plans submitted?	Checke	d by:	(GROUP-TY	FE AND AREA)		1
Occupancy Group?	Other	Occupancies in Buildi	na?			-
					4	
Floor to be Used:	None on her Linear	er ft	Previous Occupancy?			<u>}</u>
*	Area to be Used?	sq. ft.	Previous Occupancy?	_ is there a	basement:	
BUILDING: Height	Area to be Used? Stories,ft.	sq. ft.  Type of Construct	Previous Occupancy?lon?Type of Protection	_ is there a	basement:	
BUILDING: Height Location-Exterior We	Area to be Used? Stories,ft. all Openings?	Type of Construct	Previous Occupancy? Ion? Type of Protect —Cellar? B	_ is there a	basement:S	tory?
Location-Exterior We is there 20 sq. ft. of	Area to be Used? Stories, ft. all Openings? Opening in every 50'	Type of Construct  Type of Construct  on one exterior wall in	Previous Occupancy?lon?Type of Protection?B	_ Is there a ction asement? ?	S West	lory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope	Area to be Used?  Stories,ft.  All Openings? Opening in every 50' inty Line on North?	Type of Construct on one exterior wall in South	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead to	_ Is there a stionasement?	West	tory?
Location-Exterior Website is there 20 sq. ft. of Distance from Prope EXITS: Number?	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' inty Line on North?  Total Width?	Type of Construct  on one exterior wall in  South  How far Apart?	Previous Occupancy?lon?Type of Protect —Cellar? B n? East Do Exits Lead t	_ is there a stion	S West	lory?
Location-Exterior Website is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Property Control o	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' inty Line on North?  Total Width? m Hezerdous Area (or	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Fxit Signs?	Previous Occupancy?	_ is there a stion asement? ? o Street? Panic Bars	S West	tory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' inty Line on North?  Total Width?  m Hazardous Area (or ?)	Type of Construct  Type of Construct  on one exterior wall in  South  How far Apart?  ver 200 sq. (t.)?  Exit Signs?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?	_ is there a stion asement? ? o Street? Panic Bars	West	lory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stairway Exterior Stairway or in the Control of Stairway	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' in Line on North?  Total Width?  m Hazardous Area (or ?)  rs? V  Fire Escape?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. ft.)? Exit Signs? Vidth? Where Located?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Distance	_ is there a stion asement? ? o Street? Panic Bars	West	lory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' in Line on North?  Total Width?  m Hazardous Area (or ?)  rs? V  Fire Escape?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. ft.)? Exit Signs? Vidth? Where Located?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Distance	_ is there a stion asement? ? o Street? Panic Bars	West	lory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stairway Exterior Stairway or FIRE PROTECTION: Sta	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' in Line on North?  Total Width?  m Hazardous Area (or ?)  rs? V  Fire Escape?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. ft.)? Exit Signs? Vidth? Where Located?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Distance	_ is there a stion asement? ? o Street? Panic Bars	West	lory?
EUILDING: Height Location-Exterior Weight is there 20 sq. ft. of Distance from Prope EXITS: Number? Number of Exits fro Do Doors Swing Out Number of Stainway Exterior Stainway or I FIRE PROTECTION: Stainway Other Fire Protection	Area to be Used?  Stories,ft.  all Openings?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signs? Vidth? Where Located?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?	_ is there a stion asement? ? o Street? Panic Bars	West	lory?
EUILDING: Height Location-Exterior Weight is there 20 sq. ft. of Distance from Prope EXITS: Number? Number of Exits fro Do Doors Swing Out Number of Stainway Exterior Stainway or I FIRE PROTECTION: Stainway Other Fire Protection	Area to be Used?  Stories,ft.  all Openings?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signs? Vidth? Where Located?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?	_ Is there a stionasement? o Street? Panic Bars	West	lory?
EUILDING: Height Location-Exterior Weight is there 20 sq. ft. of Distance from Prope EXITS: Number? Number of Exits fro Do Doors Swing Out Number of Stainway Exterior Stainway or I FIRE PROTECTION: Stainway Other Fire Protection	Area to be Used?  Stories,ft.  all Openings?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signs? Vidth? Where Located?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?	_ Is there a stionasement? o Street? Panic Bars	West	lory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stainway Exterior Stainway or FIRE PROTECTION: Stainway Other Fire Protection is Flameproofing Reference.	Area to be Used?  Stories,ft.  all Openings? Opening in every 50' inty Line on North?  Total Width? m Hazardous Area (or recommend)  Fire Escape? indpipes: Wet? ft Extinguishers? aquired?	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signs? Where Located? Dry? Is it Satisfactory?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?	_ Is there a stion	West	lory?
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stainway or Exterior Stainway or FIRE PROTECTION: Stainway of Stainway or Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection Control of Stainway or Dother Fire Protection Control of Stainway or Dother Fire Protection Control of Stainway or Dother Control of Stainway or Dother Fire Protection Control	Area to be Used?  Stories,ft.  all Openings? Opening in every 50'  Inty Line on North?  Total Width?  Provided State of the Company of the Com	sq. ft.  Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signa? Vidth? Uhere Located? Dry? Is it Satisfactory?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?  ameda County De	_ is there a stion	West  West  Health	Care
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stainway or Exterior Stainway or FIRE PROTECTION: Stainway of Stainway or Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother Fire Protection is Flameproofing Resident Control of Stainway or Dother	Area to be Used?  Stories,ft.  all Openings? Opening in every 50'  Inty Line on North?  Total Width?  Provided State of the Company of the Com	sq. ft.  Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signa? Vidth? Uhere Located? Dry? Is it Satisfactory?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?  ameda County De	_ is there a stion	West  West  Health	Care
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stainway or Exterior Stainway or Exterior Stainway or FIRE PROTECTION: Stainway or Its Flameproofing Resident Protection is Flameproofing Resident Protection: Remarks:  DATE OF INSPECTION: Remarks:  Services As	Area to be Used?  Stories,ft.  all Openings? Opening in every 50'  Inty Line on North? Total Width?  Total Width?  The Escape?	sq. ft.  Type of Construct on one exterior wall in South How far Apart? ver 200 sq. ft.)? Exit Signs? Vidth? Where Located? Dry? Is it Satisfactory?	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?	_ is there a stion	West  West  Health	Care
Location-Exterior We is there 20 sq. ft. of Distance from Prope EXITS: Number?  Number of Exits from Do Doors Swing Out Number of Stainway or Exterior Stainway or Exterior Stainway or FIRE PROTECTION: Stainway or Its Flameproofing Resident Protection is Flameproofing Resident Protection: Remarks:  DATE OF INSPECTION: Remarks:  Services As	Area to be Used?  Stories,ft.  all Openings? Opening in every 50'  Inty Line on North?  Total Width?  Provided State of the Company of the Com	Type of Construct on one exterior wall in South How far Apart? ver 200 sq. (t.)? Exit Signs? Where Located? Dry? Is it Satisfactory? mply with Alements. Notify	Previous Occupancy?  Ion?  Type of Protect  Cellar?  East  Do Exits Lead t  Illuminated?  Open or Enclosed?  Sprinklers?  Distance  Sprinklers?  Tre Preventi	_ is there a stion	Health (ice 24-hr	Care

RE PREVENTION BUREAU LA HOLLIS ATREST RESYVILLE, CA 94408 CIT	CODEPERMIT 1069	
<del></del>	Solence Engineers Inc.	
ERMISSION IS HEREBY GRANTED		
OPERATE O MAINTAIN REMOVE UG FUET STORE	arik (17,000-ggls) F.P.a. Permit No	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
ON PREMISES LOCATED AT 6340 Chr	Ordinal Control Contro	
PERIODIC INSPECTIONS ARE A CONDITION OF	LUC BERMIT WHICH IS ISSUED IN ACCORDANCE	
MITH UNIFORM FIRE CODE, AS SPECIFIED IN SE	TION 4. LUL ORSAID COUL	i i
ADDITION REQUIREMENTS Removal t	comply w/requirements of Care The Care Care Care Care Care Care Care Car	00
<b>/</b> ₽	FRANCIPATE CONTRACTOR OF THE PROPERTY OF THE P	
THIS PERMIT MUST BE POSTED WITH BUSINESS	AIT APPROVED BY 2//4/88	
Plans submitted?C		
Occupancy Group?	CROUPTYPE AND AREA	
Occupancy Group?	sed? sq. ft. Previous Occupancy?	
PIOOI TO DE USECT	tt. Type of Construction? is there a basement?	
7	Type of Protection	, 154 A
Location-Exterior Wall Openings?	Basement? St	<u> </u>
is there we sq. it. of Opening in every	South? East? West?	
EVITS: Number? Total Width?	How far Apart? Do Exits Lead to Street!	
Number of Exits from Hazardous Are	ia (over 200 sq. ft.)? Panic Bais?	
Do Doors Swing Out?	Exit Signs? Illuminated?	
Futneses Ctalanay of Fire Fee208?	Where Located? Distance from \$1881?	
FIRE PROTECTION: Standpipes: Wet?_	Dry? Sprinklers?	
Number and Type of Extinguishers?.		12. 发表《夏季》
Other Fire Protection?	Is it Satisfactory?	
In a construction of the c		
DATE OF INSPECTION: REMARKS	comply with Alameda County Dept. of Health C	
Services Agency requi	rements. Notify Fire Prevention office 24-hr	S DETOR & A P.
to removal of tank		
TO TAMOVAL OF TRANS	SignedFIRE INSPECTOR	No.
		Provide 4

11/29/98

#### ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

MEMORANDUM

TO file	FROM J. Kose	DATE 2/25/88"
SUBJECT Soils reports	- 6340 Chris	tie Emy. alled regarding to for sampling). To truck
Terry Carter, A	qua Science C	alled regarding
Ulhbal anal	gheal result	t for sampley)
(a) this site	Subsequent	to Tank
Memoral -	2	
- XIN	- Samples (a)	100,180 ppm
respecti	vily.	
Rinsate	sample 25	ppm (lab)
(1)		ppm (mobile/ab)
Suggested he	hobyly his.	Client regardes
mitigation.	Measures.	Jeller Will
300-CA-1-3/82 WI	her Juiel In	ppn (lab) ppn (mobile/ab) Geller well be copies receivel,
ALAME	EDA COUNTY HEALTH CARE SERVICES  MEMORANDIM	AGENCY Du geto minus
		70 minus
TO Sowell Miller / FI	LEFROM My Rape	- Tank Cleaning -
SUBJECT 6340 Christ	tie, Emeryprèle	- Tank Cleaning -
Kernoval -	'	
		~~~ · · · · · · · · · · · · · · · · · ·
On Feb 5, 1988 I obs	served the follow	oui procedures
On Feb 5, 1988 I obs unplemented by Aque	served the follow a Science in reg	rig procedures levence to the Closure
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were	served the follow a Scienes in reg also taken.	rui procedures levence to the Closure
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were 1. The tank was	Rumped out and	ric procedures levence to the Closure merted with chy ice.
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were 1. The tank was	Rumped out and	merted with they ce.
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were 1. The tank was	Rumped out and	merted with they ce.
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were 1. The tank was	Rumped out and	merted with they ce.
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were 1. The tank was	Rumped out and	merted with they ce.
On Feb 5, 1988 I obs unplemented by Aque plan. Photos were 1. The tank was	our with Agua S erry Cartes. Cast Yo. Cartes said us was drilled as	levence to the Closure  evence to the Closure  evenes bas Tech 1314  ech measured 3.5% Q  strung was Calibrate to her  el then the Cutting  Cropector from

ETD was also present. He wasnot familiar with their Cutting operation.

5. The cutting tool broke after about 3/4 of the hole had been cut.


7. Often grining access to the Tinside of the tank the Cleaning operations began-(See photos) Note: Personnel involved in the Culting operator which were standing inside the excavation which appeared to "be at least 6' deep. Respirator Cartordes appeared to be in very poor Condition.

PROJECT #<u>USOSS</u> 2 12/18

## ALAMEDA COUNTY HEALTH ENVIRONMENTAL HEALTH DEPT.

SERVICE REQUESTED: TEmen					
NAME OF SITE: LERER BROS STID  ADDRESS: 6340 Christie  FORER 1:118 94608					
ADDRESS POLBX 535 SAN PARS 945 PERS 1 820-939					
CONTACT PERSON: TEER CALLER TELE = 820 -9391					
AMOUNT OF DEPOSIT:\$ =00.00 DATE: 1.19 88					
DATE: ACTION TAKEN TIME HRS IN 0.1 X \$53.00 = IN OUT X \$53. BALANCE					
OVERHEAD 25% 75.00 \$ 225.00 1 3-4.86 Nection 130 3:00 1.5 79.50 145.50					
1012/5/88 Ou set: 10:00 11:30 1.5 79.50 66.00					
2/16/88 TO MARY FOR ACCOUNTING 0.1 5.30 60.70					
2/25/88 Tiles Carter 0.1 5.30 60.70 11/22/88 TO Mary in accounter					
PROJECT COMPLETED BY					
DATE: REFUND:\$ SENT TO ACCOUNTING: DATE: 12/62/82					
TO BE REPORTED WEEKLY TO ACCOUNTING FOR CASH FLOW					
ADJUSTMENT Project # U 505552					
Fco Paid Solv. OO					
Date					






SHELLMOUND STREET



not to scale

Lerer Bros. Transmission 6340 Christie Avenue Emeryville, California

figure 1



#### ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY DEPARTMENT OF ENVIRONMENTAL HEALTH HAZARDOUS MATERIALS DIVISION

DBVLL

DEPARTMENT OF ENVIRONMENTAL HEALTH 470 - 27th Street flurd Floor Oakland CA 91812

ACCEPTED

lelephonu: (415) 874 7237

Department are to a sine on thince with their and local laws. The project purposed his or is now in word for issu-

One copy of these accepted plans must be so-available to all contractors aid craftsman in

the construction and installative

ance of any required I update permits to

r T

able and escentally rect the contracts of State and local heath laws. Char a to corrolon: contract by this These plans have been removed and tound to be accopt

14. 12.7

Line and State and

HEATTH CARE

"Inch to this "separation of the Appetion Department of the Appetion Department of the Appetions of the Appetion of the Appe med powers 105th AINSARD sheh sue Wester outeld 1 strab or way ormy sy インプラグト へら<u>(</u>) ン ハ シアイシ زدرزدر 5 Ì. ٧ħ

UNDERGROUND TANK CLOSURE/MODIFICATION PLANS

1.	Business Name	LERER BROS. TRANSMISSION SERVICE				
	Business Owner	RICK GOLD				
2.	Site Address _	6340 CHRISTIE ST.				
		EMERYVILLE Zip 94608	Phone	(415) 653-7587		
3.	Mailing Addres	SAME AS ABOVE				
	City	Zip				
4.		LERER FAMILY PROPERTIES				
	Address City, State Zip					
5.	EPA I.D. No	CAC 0000 58029		•		
6.	ContractorAQUA SCIENCE ENGINEERS, INC.					
	Address	P.O. BOX 535	<u> </u>			
	City	City SAN RAMON, CA 94583		(415) 820-9391		
	License Type	ENGINEERING CONTRACTORS LIC. # 487000				
7.	Other (Specify) SAME AS ABOVE					
<b>ž</b> ,						

January 15, 1988

Liz Rose Alameda County Health Agency Hazardous Materials 470-27th Street Room 322 Oakland, CA 94612

RE: TANK REMOVAL AT LERER BROS. 6340 CHRISTIE, EMERYVILLE, CA

Dear Liz:

As a follow up to our recent conversation I am providing you with information concerning removal of a 2000 gallon gasoline tank.

#### GENERAL INFORMATION:

Business Name: Lerer Bros. Transmission Service

Business Address: 6340 Christie, Emeryville, CA 94608

Business Phone: 415-653-7587

Contact: Rick Gold

Contractors Name: Aqua Science Engineers Engineering Contractors Lic. #487000

Business Address: P.O. Box 535, San Ramon, CA 94583

Business Phone: 415-820-9391

Contact: Terrance Carter Manager, Engineering Services

Cal. Reg. Geologist 4202, Cal Reg. Professional Engineer #38738

Excavators Name: Tom Daniels Excavating Lic.#447475 Business Address: P.O. Box 335, Danville, CA 94526

Business Phone: 415-820-3558

Contact: Betty Castro

Hazardous Materials Waste Hauler: H & H Ship Service EPA # CAD 004771168

Business Address: 220 China Basin, San Francisco, CA 94107

Business Phone: 415-883-6425

Contact: Cleveland

Certified Testing Laboratory: WESCO Laboratories #148

Business Address: 14 Galli Drive, Novato, CA 94960 Project # 4508

Business Phone: 415-883-6425

EPA MANIFEST NUMBER: CAC 0000 58029

TANK: One 2000 gallon steel unleaded gasoline.

Date 1-19.88


CLEANING AND PURGING TANK: Prior to tank removal, the tank will be tripple rinsed using high pressure steam with a hydrocarbon cleaning additive. The residual material will be pumped via an air driven pump to approved Hazardous Waste Drums (17H). The rinsate will then be manifested as a hazardous waste to H & H Service. The day of removal, the tanks will be purged of explosive vapors and oxygen by placing 100 lbs. dry ice into the tank. When the LEL is below 20%, an entry will be made into the tanks for further cleaning. The tanks will be steamed again and all materials manifested. The tank will then be disposed of as scrap.

SAMPLING AND ANALYSIS: Two (2) soil samples and one (1) groundwater sample (if necessary) will be collected when the tank is removed. We anticipate groundwater to be encountered at about the 8 foot depth. Soil samples will be taken approximately 6-inches above the groundwater line if groundwater is encountered. Otherwise, soil samples will be taken from each end, approximately 2 feet below the tank bottom.

Analysis for both soil and water will be performed according to EPA Method 5020/8015/8020. The results will be forwarded to your office within 21 days of collection.

Sincerely,

Terry Cartar Terrance E. Carter Manager, Engineering Services



## ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY DEPARTMENT OF ENVIRONMENTAL HEALTH HAZARDOUS MATERIALS DIVISION

470 - 27TH ST., RM. 322 OAKLAND, 94612 CA PHONE NO. 415/874-7237



DEPARTMENT OF ENVIRONMENTAL HEALTH 470 - 27th Street Third Floor Oakland CA 94612 Telephone: (415) 874-7237 ACCEPTED

laws and One copy of these accepted plans must be on the obland accepted to all contractors and craftsman involved with the construction and installation.

Apply change or alteration of these plans and specifications may be submitted to this Department and to the Fire and Equaling Inspection Department to determine if such Marity this Department at least 48 hours prior to the lawing required inspections: able and essentially meet the requirements of State and local health laws. Chances to your plans, indireted by this **These plans have been veviewed and found to be acceptable and essentially** meet the requirements of State and Department are to assure compliance with State and local leval. The project proposed herein is now releasord for issue ance of any required building permits for construction. \_Pre-Coverna of Tank and Piping Final Inspection
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on
Final Manager of a permit to operate is dependent on the permit to operate is dea THERE IS A FINANCIAL PENALTY FOR NOT

1.	Business Name	LERER BROS. TRANSMISSION SERVICE			
	Business Owner	RICK GOLD		<del></del>	
2.	Site Address _	6340 CHRISTIE ST.		<del></del>	
	City	EMERYVILLE	Zip 94608	Phone	(415) 653-7587
з.	Mailing Addres	011/00 10 10 10 10 10 10 10 10 10 10 10 10 1			
	City	LEDED FAMILY DOCUMENT	Zip	Phone	
4.	Land Owner	LERER FAMILY PROPERTIES		- 110110	
	Address	CAC 0000 50000	ity, State		77 -
5.	EPA I.D. No	CAC 0000 38029			
6.	Contractor	AQUA SCIENCE ENGINEERS	, INC.		
	Address	P.O. BOX 535	· ·		
	City	SAN RAMON, CA 9458	33	Phone	(415) 820-9391
	License Type	ENGINEERING CONTRACTORS	S LIC. # 487000	LHOHE	
7.	Other (Specify)	SAME AS ABOVE			
	Address				
Address Phone					

ÜRAFT

٥.		Person for Investigation			
	Name _	TERRANCE CARTER	Title	Manager, Engir	neering Service
	Phone _	(415) 820-9391			
9.	Total No	o. of Tanks at facility _	1		
10.	Have per office?	rmit applications for all Yes [X]	tanks been No	submitted t	o this
11.	State Re	gistered Hazardous Waste	Transporte	cs/Facilitie	e
		uct/Waste Tranporter	-		-
		H & H Ship Service	ЕРА Т	CADO	04771168
	Addr	ess 220 China Basin		NO	
	City	San Francisco	State	A 941	07
	b) Rins	ate Transporter			
	Nam	e Same As Above	EPA I	.D. No	
	Add	ress			<del></del>
		Y			
	c) Tank	Transporter		<del>-</del> - <u></u>	
	Name	≥SEE ADDENDUM	EPA I	.D. No	
	Addı	ess			
				Zip	
đ		ninated Soil Transporter			
	Nam	ie	EPA I	.D. No	
	Add	ress			
	Cit	у	State	Zip	
12. Sa	ample Co				
		Personnel		•	•
		Aqua Science Engineers		**************************************	
	<del></del>	P.O. Box 535			
		San Ramon State	CA <b>Zip</b> 9458	33 <b>Phone</b> (4	115) 820-9391
				2TIOTIGE '	



# 13. Sampling Information for each tank or area

Tank or Area		Material sampled	Location & Depth
Capacity	Historic Contents (past 5 years)		
2000 gal.	Gasoline	Soil groundwater (if necessary)	6" above water table/ &/or 2" below tank bottom Approximately 8'

14.	Have ta	nks or pipes leaked in the past? Yes [ ] No [X]
	If yes,	describe.
15.	NFPA met	hods used for rendering tank inert? Yes [X] No []
	If yes,	describe. 100 lbs. of dry ice into 2000 gallon tank.
16.	Laborato	ries
	Name	WESCO Laboratories
	Address .	14 Galli Drive, Suite A
	City	Novato State CA Zip 94949
,	State Ce	tification No. 270-3452-7

# 17. Chemical Methods to be used for Analyzing Samples



Contaminant Sought	EPA, DHS, or Other Sample Preparation Method Number	EPA, DHS, or Other Analysis Number
Benzene. Tolaene & Xylene (BTX)	EPA 8020	
Gasoline, Total Petrole Hydrocarbons	um EPA 8015/5020	

- 18. Site Safety Plan submitted? Yes [X] No []
- 19. Workman's Compensation: Yes [X] No []

  Copy of Certificate enclosed? Yes [X] No []

  CNA Insurance

  Name of Insurer
- 20. Plot Plan submitted? Yes [X] No []
- 21. Deposit enclosed? Yes [X] No [ ]
- 22. Please forward to this office the following information within 60 days after receipt of sample results.
  - a) Chain of Custody Sheets
  - b) Original Signed Laboratory Reports
  - c) TSD to Generator copies of wastes shipped and received
  - d) Attachment A summarizing laboratory results



I declare that to the best of my knowledge and belief the statements and information provided above are correct and true. I understand that information in addition to that provided above may be needed in order to obtain an approval from the Department of Environmental Health and that no work is to begin on this project until this plan is approved.

I understand that any changes in design, materials or equipment will void this plan if prior approval is not obtained.

I will notify the Department of Environmental Health at least two (2) working days (48 hours) in advance to schedule any required inspections. I understand that site and worker safety are soley the responsibility of the property owner or his agent and that this responsibility is not shared nor assumed by the County of Alameda.

Signature of Contractor

Name (please type) AQUA SCIENCE ENGINEERS	
Signature Terrang E. Carter, Manager Engineering Services	
Date1-29-88	_
Signature of Site Owner or Operator  Name (please type) LERER BOS.  Signature Ruliand Bald   Janu Family Properties  Date 1/29/98	

#### NOTES:

- 1. Any changes in this document must be approved by this Department.
- Any leaks discovered must be submitted to this office on an underground storage tank unauthorized leak/contamination site report form within 5 days of its discovery.
- 3. Three (3) copies of this plan must be submitted to this Department. One copy must be at the construction site at all times.
- 4. A copy of your approved plan must be sent to the landowner.



# UNDERGROUND TANK CLOSURE/MODIFICATION PLANS

## ATTACHMENT A

#### SAMPLING RESULTS

Tank or Area	Contaminant	Location & Depth	Results (specify units)
		·	

# DAFT

#### INSTRUCTIONS

#### 2. SITE ADDRESS

Address at which closure or modification is taking place.

#### 5. EPA I.D. NO.

This number may be obtained from the State Department of Health Services, 916/324-1781.

#### 6. CONTRACTOR

Prime contractor for the project.

#### 7. OTHER

List professional consultants here.

#### 12. SAMPLE COLLECTOR

Persons who are collecting samples.

#### 13. SAMPLING INFORMATION

Historic contents - the principal product(s) used in the last 5 years.

Material sampled - i.e., water, oil, sludge, soil, etc.

#### 16. LABORATORIES

Laboratories used for chemical and geotechnical analyses.

#### 17. CHEMICAL METHODS:

All sample collection methods and analyses should conform to EPA or DHS methods.

Contaminant - Specify the chemical to be analyzed.

<u>Sample Preparation Method Number</u> - The means used to prepare the sample prior to analyses - i.e., digestion techniques, solvent extraction, etc. Specify number of method and reference if not an EPA or DHS method.

Analysis Method Number - The means used to analyze the sample - i.e., GC, GC-MS, AA, etc. Specify number of method and reference if not a DHS or EPA method.

#### NOTE:

Method Numbers are available from certified laboratories.

#### 18. SITE SAFETY PLAN

A plan outlining protective equipment and additional specialized personnel in the event that significant amount of hazardous materials are found. The plan should consider the availability of respirators, respirator cartridges, self-contained breathing apparatus (SCBA) and industrial hygienists.



#### 19. ATTACH COPY OF WORKMAN'S COMPENSATION

#### 20. PLOT PLAN

The plan should consists of a scaled view of the facility at which the tank(s) are located and should include the following information:

- a) Scale
- b) North Arrow
- c) Property Line
- d) Location of all Structures
- e) Location of all relevant existing equipment including tanks and piping to be removed
- f) Streets
- g) Underground conduits, sewers, water lines, utilities
- h) Existing wells (drinking, monitoring, etc.)
- i) Depth to ground water
- j) All existing tanks in addition to the ones being pulled



# AQUA SCIENCE ENGINEERS SITE SAFETY PLAN

#### A. GENERAL INFORMATION

Site: LERER BROS TRANSMISSION

Location: 6340 CHRISTIE, EMERYVILLE, CA

Plan Prepared By: TERRANCE E. CARTER

Date: 2-1-88

Plan Approved By:

Date:

Objectives : TANK CLEANING AND DISPOSAL OF TANK RINSATE

Proposed Date of investigation: 2-4-88

Background Review:

Complete:

Preliminary:

Documentation/Summary:

Overall Hazard:

Serious: Low:

Moderate: Unknown:

#### B. SITE/WASTE CHARACTERISTICS

Waste Type(s): Liquid: X Solid:

Sludge:

Gas:

Characteristic(s): GASOLINE TANK RINSATE

Facility Description: TRUCK REPAIR

Status:

Active: X Inactive:

Unknown:

History: (agency action, complaints, injuries, etc.)

N/A

#### C. HAZARD EVALUATION

Parameter:

TANK RINSATE

LEL

(ppm)

**(\$)** 

< 100

< 10

## Special Precautions and Comments:

- 1. USE SAFETY EQUIPMENT MASK RESPIRATOR EQUIPED WITH NIOSH APPROVED C-21 CARTRIDGE FOR ORGANIC VAPORS.
- 2. USE NIOSH APPROVED RUBBER GLOVES FOR HYDROCARBON LIQUID.
- 3. PUMP ALL RINSATE TO HAZARDOUS WASTE DRUMS 17-H.
- 4. HAVE DRY CHEMICAL MODEL PA-200 ABC FIRE EXTINGUISHER.
- 5. HAVE 100 LBS. SOLID-SORB AVAILABLE FOR POTENTIAL SPILLAGE.

#### D. SITE SAFETY WORK PLAN

Perimeter Establishment: N/A Map/Sketch Attached: YES

SITE Secured: FENCED YARD AND BARRICADES

Personal Protection:

Level of Protection: A X B X C X D

Modifications: NONE

Surveillance Equipment and Materials: Instrument: GAS-TECH Action Level: 20% LEL

Site Entry Procedures: BY OWNER

Decontamination Procedures: STEAM CLEAN TANK AT > 300 DEGREES F WITH SURFACTANT, PUMP TO DRUMS, MANIFEST RINSATE.

Personal: STEVE DEHOPE, GREG BURG

Equipment: TANK CLEANING TRUCK

First Ald: KIT AVAILABLE ON TRUCK

Work Limitations (time of day, weather, heat/cold stress): WORK TO PROCEED BETWEEN 8 AM AND 3:30 PM.

investigation-Derived Material Disposal: TANK RINSATE

#### E. EMERGENCY INFORMATION

#### Local Resources:

Ambulance: 911 OR 874-8010

Hospital Emergency Room: PROVIDANCE HOSPITAL 874-8010

Polson Control Center: 911 OR 476-6600

Police: 911 OR 653-5455

Fire Department: 911 OR 652-4575

Explosives Unit: 652-4575

Agency Contect: ALAMEDA COUNTY HEALTH CARE SERVICES - DEPT.
ENVIRONMENTAL HEALTH - LIZ ROSE, 874-7237

#### Site Resources:

Water Supply: OUTSIDE WATER SPIGET

Telephone: 653-7587

Radio: TERRY CARTER - 820-9391

Other: N/A

# Emergency Contacts: ASE

Name: WILLIAM RUSK

Phone: 820-9391

#### **Emergency Routes:**

Hospital: POWELL ST. TO 880 SOUTH TO 580 FREEWAY TO BROADWAY/WEBSTER OFF RAMP. LEFT ON WEBSTER, RIGHT ON HAWTHORN TO SUMMIT.

property line correte pad driveway dwnd tank fill property line existing building broperty tine 6340 Christie St., Emeryville, CA. scale in feet

Lerer Bros. Transmission Service

AQUA SCIENCE ENGINEERS

#### PARTICIPATING PROVISION


You shall participate in the earnings of the Company to the extent and upon the conditions determined by our Board of Directors in accordance with law and made applicable to this policy, provided that no dividend shall be payable hereunder unless you have complied with the terms of the policy in respect to the payment of premiums.

Under California Law it is unlawful for an insurer to promise the future payment of dividends under an unexpired Workers Compensation policy or to misrepresent the conditions for dividend payment. Dividends are payable only pursuant to the conditions determined by the Board of Directors or other governing board of the Company following policy expiration.

It is misdemeanor for any insurer or officer or agent thereof, or any insurance broker or solicitor, to promise the payment of future Workers Compensation dividends.

This endorsement, which forms a part of and is for attachment to the following described policy issued by the company designated therein, takes effect on the effective date of said policy, unless otherwise effective date is shown below, at the hour stated in said policy and expires concurrently with said policy.

Mus	st be Completed	Complete Only When This Endorse Or Is Not to be Effe	ment Is Not Prepared with the Policy ective with the Policy
ENDT. NO.	250 POLICY NO.	ISSUED TO	EFFECTIVE DATE OF THIS ENDORSEMENT
1	PWC 30 0943199	AQUA SCIENCE ENGINEERS	8-15-87
		10-15-87 JS/arm  American Casualty Company of	GLEN HANSEN  National Fire insurance Company



WILLIAM RUSK

(ED 3/84)

OWNER