

FILE OR

ENVELOPE

PL REVIEW

By

Date

PER NO.]

GW

No. of

\$ 498

Rec'd.

Am 8/1

No.

Plans Rec'd.

Plans Approved

Layout Made

Rejected

Applicant Notified

Plans Returned

Permit Issued

CONSTRUCTION PROGRESS ACCEPTANCE

FOOD

Pre-Plaster/drywall

Pre-Final

Final

OWNER

PFIZER

Address

4650 Shellmound

Emeryville

Phone

Contractor

Diablo Tank & Equip

Address

4030 Pacheco Blvd

Martinez

Phone

372-3342

OTHER (Specify)

Address

Phone

CONTACT FOR INVESTIGATION

PATRICK McSHANE

XR

372-3342

REM

Date

By

for wells & w.o. tank tanks) - 3 one well underway.

REMARKS

Date

By

8/21/89

GW

Review installation plan - needs more detailed drawing of piping and tank connections, as well as hold-down calculations. Contacted Diablo.

9/5

GW

Receive additional materials and approve plans; only 1 copy submitted, so must photocopy two other sets.

10/10

On-site for pressure test of all primary piping - all OK

3/5/90

GW

Review quarterly sampling report

		Date		By	Date
POOL	Pre-Concrete/Gunite		U.G. TANKS	Pre-Covering	
	Pre-Plaster				
	Final				
EXCAVATION	Septic Tank			Final	
	Absorption Field				
	Absorption Bed				
	House Sewer				
FINAL	Septic Tank				
	Absorption Field				
	Absorption Bed				
OTHER					

WORKS

*illed in and near the old
site of new gas/diesel
ree products found in
diesel) - investigation*

XOS

LOCATION

Vicinity Map

U.S.

Project # U552859
 Fee Paid \$498
 Date 8/17/89