By 1996

REMEDIAL WELL INSTALLATION REPORT ARCO SERVICE STATION 6148 OAKLAND, CALIFORNIA 02/01/96





1921 Ringwood Avenue • San Jose, California 95131-1721 • (408) 453-7300 • Fax (408) 437-9526

| | | | Date | February 1, 1996 |
|---|-------------------|---------------------------------|---------------------|---|
| | | | Project | t 20805-135.004 |
| To: | | | | |
| Mr. Michael ARCO Produ P.O. Box 612 San Jose, CA | icts Comp 2530 | pany | | DECIENVE N FEB 07 1996 |
| We are enclo | sing: | | | By_ |
| Copies1 | - - - | | l Installation Repo | |
| For your: | _X | Use Approval Review Information | Sent by: | X Regular Mail Standard Air Courier Other: Cert. Mail |
| Comments: Please cal | ll if you l | nave questions or co | omments. | |
| | | | | Rob Davis Staff Geologist |

cc: Susan Hugo - ACHCSA Kevin Graves - RWQCB



Date: February 1, 1996


Re: ARCO Station # 6148 • 5131 Shattuck Avenue, Oakland, CA Remedial Well Installation Report

"I declare, that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached proposal or report are true and correct."

Submitted by:

Michael R. Whelan Environmental Engineer

Michael R. Whelan





February 1, 1996 Project 20805-135.004

Mr. Michael Whelan ARCO Products Company 2155 South Bascom, Suite 202 Campbell, California 95008

Re: Remedial well installation report, ARCO service station 6148, Oakland, California

Dear Mr. Whelan:

This report documents the destruction of one combination AS/SVE well and the installation of eight soil-vapor-extraction (SVE) wells and four air-sparge (AS) wells by EMCON at ARCO Products Company (ARCO) service station 6148, 5131 Shattuck Avenue, Oakland, California (Figure 1). The installed wells form part of the soil and groundwater remediation system described in *Remedial Action Plan*, *Interim Soil and Groundwater Remediation* (RAP, EMCON, June 1995), as submitted to the California Regional Water Quality Control Board, San Francisco Bay Region (RWQCB), and the Alameda County Health Care Services Agency (ACHCSA) on June 8, 1995.

BACKGROUND

The project site is on the southwestern corner of the intersection of 52nd Street and Shattuck Avenue, Oakland, California (Figure 1). The relatively level site is at an elevation of approximately 110 feet above mean sea level (MSL). The site is described by Alameda County Assessor's Parcel Number 14-1216-31-2, with a total area of approximately 1/2 acre. The site is owned by ARCO and is currently an operating retail gasoline station. The current underground storage tank (UST) complex consists of three 12,000-gallon gasoline USTs at the site (one regular unleaded, one mid-grade, and one premium unleaded UST).

On June 1, 1987, Crosby and Oberton, and Erico Construction removed a waste-oil tank from the site. During tank removal, one soil sample was collected from the bottom of the waste-oil tank pit. After characterization of the sample, soil from the tank pit was excavated and transported to a landfill. Crosby and Oberton, and Erico Construction excavated and sampled additional soil from the waste-oil tank pit on June 3 and 10, 1987.

In December 1991, RESNA conducted a Phase I subsurface investigation of the former waste-oil tank area. The investigation included drilling four on-site soil borings (B-1 through B-4) in the immediate vicinity of the tank pit, and subsequently converting three

of the borings to groundwater monitoring wells MW-1, MW-2, and MW-3. Results of the investigation were summarized in an initial subsurface investigation report (RESNA, September 1992).

In October 1992, a Phase II investigation was conducted at the site by RESNA. This investigation included drilling four on-site soil borings, B-5 through B-8, and converting the borings to groundwater monitoring wells, MW-4 through MW-7. The investigation also included a 1/2-mile radius well and record search. Results of the investigation were summarized in an additional subsurface investigation report (RESNA, January 1993).

In April 1993, RESNA conducted a Phase III investigation, which included drilling test borings TB-1 through TB-11, and installing an AS well (AS-1) in test boring TB-6. Results of the investigation were summarized in an additional subsurface investigation report (RESNA, September 1993).

In July 1993, RESNA drilled three additional soil borings, B-9, B-10, and B-11, in the vicinity of the former waste-oil tank. The three borings were completed as combination AS/vapor extraction well, AS-2/VW-2, and vapor extraction wells, VW-1 and VW-3. In February 1994, RESNA conducted AS and SVE pilot tests at the site. Details of the well installations, and results of the AS and SVE pilot tests were summarized in a report (RESNA, June 1994).

Groundwater monitoring and sampling at the site were initiated in December 1991 and March 1992, respectively. Wells MW-1 through MW-7 are measured quarterly for depth to water. Wells MW-1 through MW-6 are sampled quarterly for petroleum hydrocarbons in groundwater. Well MW-7 is sampled semiannually, during the first and third quarters of the year.

Previous investigations have concluded that the extent of petroleum-hydrocarbon-impacted soils at the site were limited to three general areas: (1) in the immediate vicinity of the operating service station islands, (2) along the northern and south- southwestern edges of the USTs, and (3) in the vicinity of monitoring wells MW-1, MW-2, and MW-3 in the southern portion of the site (Figure 2). Generally, hydrocarbon-impacted soils at the site, result from hydrocarbons moving laterally along the top of the water table, and are limited to the capillary-fringe zone. Petroleum-hydrocarbon-impacted groundwater at the site has been delineated vertically and laterally north and east of the site.

In June, 1995 EMCON submitted a remedial action plan (RAP) to the RWQCB and ACHCSA. The RAP detailed the results of a February, 1994 SVE and AS pilot test performed at the site and proposed remedial measures for on-site petroleum-hydrocarbon-

impacted soils and groundwater. The purpose of this investigation is to install the AS and SVE wells required to implement the remedial measures recommended in the RAP.

CURRENT FIELD ACTIVITIES

Between July 31 and August 3, 1995, a total of twelve borings were drilled at the site with hollow-stem auger drilling equipment. Four of the borings were converted to air-sparge wells (AS-2 through AS-5) and eight borings were converted to SVE wells (VW-2 and VW-4 through VW-10). In addition, existing well AS-2/VW-2 was decommissioned because of problems caused by a defective seal. Locations of the new wells are shown in Figure 2. The exploratory borings for the wells were drilled and sampled under the supervision of an EMCON geologist working under the direct supervision of a California-registered geologist. Well construction details are summarized in Table 1. Please see notes on Table 1. Alameda County Flood Control and Water Conservation District, Zone 7 (ACFCWCD) well permits are presented in Appendix A. Procedures employed in drilling the exploratory borings, installing the wells, and sampling and storing drill cuttings and groundwater are described in Appendix B.

In September 1995, EMCON completed the installation of the Soil-Vapor Extraction (SVE) and Air-Sparge (AS) systems at the site. The SVE system consists of 12 on-site wells (VW-1 through VW-10, MW-1, and MW-5) that will be used for remediating petroleum-hydrocarbon-impacted vadose-zone and capillary-fringe soils. The AS system consists of 5 on-site wells (AS-1 through AS-5) that will be used to remediate impacted groundwater and saturated soils beneath the site.

Soil Sampling

Soil samples were collected with a 2-inch-diameter modified California split-spoon sampler. The sampler was equipped with brass liners, then driven into the undisturbed soil beyond the tip of the augers. Borings for the AS and SVE wells were sampled using a combination of sampling intervals that included continuous sampling, sampling every 2.5 feet, and sampling every 5 feet.

Soil samples were screened for volatiles in the field by sealing a discrete amount of soil in a plastic bag, and allowing it to stand for at least 15 minutes. A photoionization detector reading was then taken on the headspace of the bag, and recorded in the exploratory boring log. Selected soil samples within the capillary fringe and well screen intervals of the borings were collected, preserved on ice, and transported with chain-of-custody documentation to a state-certified laboratory for analysis. Drilling and sampling equipment were steam-cleaned before use at each boring location.

The drill cuttings were stockpiled on site and covered with Visqueen[®]. A composite sample of the drill cuttings was collected, preserved and transported as described above, and analyzed for petroleum-hydrocarbon content. After the analyses were completed, the drill cuttings were disposed of at the BFI Vasco Road Sanitary Landfill in Livermore, California. Procedures used in sampling and storing drill cuttings are described in Appendix B. Waste manifests are presented in Appendix C.

Well Installation

Air-sparge wells AS-2 through AS-5 were completed in 8-inch-diameter borings to depths of 22.0 to 28.5 feet BGS. The wells were constructed of flush-threaded, 2-inch-diameter, Schedule 40 polyvinyl chloride (PVC) casing, with 1.0 to 2.0 feet of 0.020-inch slotted screen placed at the bottom.

Soil-vapor-extraction wells VW-2 and VW-4 through VW-10 were each completed in 10-inch-diameter borings, to depths of 20.0 to 25.1 feet BGS. The wells were constructed of flush-threaded, 4-inch-diameter, Schedule 40 polyvinyl chloride (PVC) casing, with 9.0 to 14.0 feet of 0.020-inch slotted screen placed at the bottom. Well construction details are summarized in Table 1; the exploratory boring logs and well construction details are presented in Appendix D.

Steam-cleaning water used in decontaminating the drilling equipment was temporarily stored onsite in sealed and labeled 55-gallon drums. The steam-cleaning water generated during the field activities was disposed of at Seaport Environmental in Redwood City, California. Waste manifests are presented in Appendix C.

Well Development

Air-sparge wells AS-2 through AS-5 were developed on August 7, 1995 using a surge block and bailer. During development, the wells were checked for floating product and monitored for turbidity, conductivity, color, temperature, odor, and pH. Field data sheets documenting well development activities are presented in Appendix E.

Steam-cleaning water used in decontaminating the well development equipment and water generated during well development was transported by a licensed hauler and disposed of at Seaport Environmental in Redwood City, California.

Groundwater Sampling

On August 11, 1995, groundwater samples were collected from wells AS-2 through AS-5. During the third quarter 1995 groundwater monitoring event, groundwater samples were collected from wells MW-6 and MW-7 on August 24, 1995. The samples were collected with a Teflon® bailer and submitted to a state-certified laboratory with chain-of-custody documentation. Wells MW-1 through MW-5 could not be sampled during the event because of remediation system construction activities in the southern part of the site. Groundwater sampling field data sheets are presented in Appendix E.

Topographic Well Survey

EMCON contracted a California licensed land surveyor to survey the elevations and locations of the new wells. The well positions were surveyed to an accuracy of 0.02 foot. The well casing, rim, and ground elevations were surveyed to an accuracy of 0.01 foot. The well elevations were surveyed relative to mean sea level (MSL) using a City of Oakland benchmark. Figure 2 presents the current surveyed well locations.

LOCAL SUBSURFACE CONDITIONS

The site is located west of the East Bay Hills. This area lies within the Berkeley Alluvial Plain, which is a subarea of the East Bay Alluvial Plain. Soils in this area are mapped as older alluvium, which consists of a heterogeneous mixture of poorly consolidated to unconsolidated clay, silt, sand, and gravel units (Helley et al., 1979). The earth materials encountered beneath the site during this and previous subsurface investigations consisted primarily of silty clay to clayey sand and sandy gravel. Graphic interpretations of the soil stratigraphy encountered in the borings from previous investigations are shown in geologic cross sections A-A' and B-B', presented in Figures 3 and 4.

Groundwater in the East Bay Plain tends to flow towards the San Francisco Bay to the west and southwest (Hickenbottom and Muir, 1988). Average historical groundwater levels in site wells have ranged from approximately 11 feet BGS to 18 feet BGS (Table 2). During the third quarter groundwater monitoring event, the groundwater levels were within historical ranges, and the groundwater flow direction and gradient were consistent with previous events. Based on groundwater elevation data collected from wells MW-3, MW-5, and MW-7 groundwater at the site flows southwest at a gradient of 0.014 (Figure 5).

LABORATORY PROCEDURES

Selected soil samples from the AS and SVE well borings, soil samples collected from the soil stockpile, and groundwater samples from wells AS-2 through AS-5, were submitted to a state-certified laboratory and analyzed for total petroleum hydrocarbons as gasoline (TPHG), and benzene, toluene, ethylbenzene, and total xylenes (BTEX). groundwater samples were prepared for analysis by U.S. Environmental Protection Agency (USEPA) method 5030 (purge and trap). Soil was analyzed for TPHG by the methods accepted by the Department of Toxic Substances Control (DTSC) and referenced in Leaking Underground Fuel Tank (LUFT) Field Manual (State Water Resources Control Board, October 1989). Samples were analyzed for BTEX by USEPA method 8020, described in Test Methods for Evaluating Solid Waste: Physical/Chemical Methods (EPA SW-846, November 1986, third edition). These methods are recommended for use at petroleum-hydrocarbon-impacted sites in the Tri-Regional Board Staff Recommendations for Preliminary Evaluation and Investigation of Underground Tank Sites (August 10, 1990). Laboratory procedures are detailed in Appendix B.

LABORATORY RESULTS

Soil analytical data, groundwater analytical data, and historical groundwater analytical data are presented in Tables 2, 3, and 5. Certified analytical reports and chain-of-custody documentation for the soil and groundwater samples are presented in Appendix F.

TPHG and benzene were not detected in the soil samples collected from borings AS-5, VW-2, VW-4, VW-5, VW-8, and VW-10. TPGH and benzene were detected in the soil samples collected from borings AS-3, AS-4, VW-5 through VW-8, and VW-9. The detected TPHG concentrations ranged from 6 mg/kg (VW-9 at 16.5 feet) to 3,100 mg/kg (VW-6 at 6.0 feet). Benzene was detected at concentrations that ranged from 0.009 mg/kg (AS-4 at 14 feet) to 5.9 mg/kg (VW-6 at 16.0 feet).

TPHG and benzene were not detected in the groundwater samples collected from wells AS-4 and AS-5. Groundwater samples collected from wells AS-2 and AS-3 contained TPHG concentrations of 310 μ g/L and 10,000 μ g/L, respectively. Benzene was detected in the samples from AS-2 and AS-3 at 15 μ g/L and 1,700 μ g/L, respectively.

CONCLUSIONS

Based on the results of this and previous investigations, hydrocarbon-impacted soils at the site are limited to the capillary-fringe zone. Impacted soils at the site appear to be confined to the area around the operating service station island, along the northern and

southwestern edges of the USTs, and the area behind the service station building in the vicinity of wells MW-1 through MW-3. The four AS and eight SVE wells installed during this investigation were incorporated in an on-site remediation system which will be used to remediate hydrocarbon-impacted soil and groundwater at the site.

Hydrocarbon-impacted groundwater at the site appears to be limited to the capillary-fringe/groundwater interface zone in the south and southwestern portions of the site.

Please call if you have questions.

Sincerely,

EMCON

Rob Davis

Robert K

Staff Geologist

Lynn A. Gallagher, R

Project Geologist

er, RKG. 6090

Attachments: Limitations

Table 1 - Well Details

Table 2 - Historical Groundwater Elevation Data

Table 3 - Soil Analytical Data

Table 4 - Groundwater Analytical Data

Table 5 - Historical Groundwater Analytical Data

Figure 1 - Site Location

Figure 2 - Site Plan

Figure 3 - Geologic Cross Section A-A

Figure 4 - Geologic Cross Section B-B'

Figure 5 - Groundwater Data, Third Quarter 1995

Appendix A - Well Permits

Appendix B - Field and Laboratory Procedures

Appendix C - Waste Manifests

Appendix D - Exploratory Boring Logs and Well Construction Details

John C. Young Project Manager

Appendix E - Field Data Sheets

Appendix F - Certified Analytical Reports and Chain-of-Custody

Documentation

cc: Susan Hugo - ACHCSA Kevin Graves - RWQCB

Table 1

Well Details

ARCO Service Station 6148

| Well ID | Installation Date | Total Depth of Well (feet) | Casing Diameter (inches) | Screened Interval (feet) |
|------------|----------------------|-------------------------------|--------------------------|--------------------------|
| AS-2 | 7/31/95 | 22.0 | 2.0 | 20.5 - 21.5 |
| AS-3 | 8/2/95 | 22.5 | 2.0 | 19.6 - 21.6 |
| AS-4 | 8/2/95 | 28.5 | 2.0 | 25.6 - 27.6 |
| AS-5 | 8/2/95 | 27.4 | 2.0 | 24.6 - 26.6 |
| | | | | |
| VW-2 | 7/31/95 | 24.7 | 4.0 | 9.8 - 23.8 |
| VW-4 | 7/31/95 | 20.1 | 4.0 | 10.2 - 19.2 |
| VW-5 | 8/1/95 | 24.9 | 4.0 | 10.0 - 24.0 |
| VW-6 | 8/3/95 | 20.0 | 4.0 | 5.1 - 19.1 |
| VW-7 | 8/3/95 | 24.0 | 4.0 | 9.1 - 23.1 |
| VW-8 | 8/1/95 | 24.7 | 4.0 | 9.8 - 23.8 |
| VW-9 | 8/1/95 | 24.8 | 4.0 | 9.9 - 23.9 |
| VW-10 | 8/1/95 | 25.1 | 4.0 | 10.2 - 24.2 |

Table 2 Historical Groundwater Elevation Data

| Well Desig- nation | Water Level Field Date | TOC Elevation ft-MSL | Depth to Water feet | Ground- Water Elevation ft-MSL | Floating Product Thickness feet | Ground- Water Flow Direction MWN | Hydraulic Gradient foot/foot |
|--------------------------|---------------------------------|----------------------------|------------------------------|---|--|--|------------------------------------|
| MW-1 | 12-23-91 | 108.03 | 18.26 | 89.77 | Sheen | NR | NR |
| MW-1 | 01-07-92 | 108.03 | 17.44 | 90.59 | Sheen | NR | NR |
| MW-1 | 01-19-92 | 108.03 | 17.17 | 90.86 | ND | NR | NR |
| MW-1 | 02-19-92 | 108.03 | 16.52 | 91.51 | ND | NR | NR |
| MW-1 | 03-18-92 | 108.03 | 16.81 | 91.22 | ND | NR | NR |
| MW-1 | 04-20-92 | 108.03 | 17.56 | 90.47 | ND | NR | NR |
| MW-1 | 05-15-92 | 108.03 | 17.96 | 90.07 | ND | NR | NR |
| MW-I | 06-12-92 | 108.03 | 18.16 | 89.87 | ND | NR | NR |
| MW-1 | 07-15-92 | 108.03 | 18.32 | 89.71 | ND | NR | NR |
| MW-1 | 08-07-92 | 108.03 | 18.34 | 89.69 | ND | NR | NR |
| MW-1 | 09-14-92 | 108.03 | 18.46 | 89.57 | ND | NR | NR |
| MW-1 | 10-07-92 | 108.03 | 18.52 | 89.51 | ND | NR | NR |
| MW-I | 11-12-92 | 108.03 | 18.11 | 89.92 | ND | NR | NR |
| MW-1 | 12-09-92 | 108.03 | 17.10 | 90.93 | ND | NR | NR |
| MW-1 | 01-21-93 | 108,03 | 15.44 | 92.59 | ND | NR | NR |
| MW-1 | 02-22-93 | 108.03 | 16.54 | 91.49 | ND | NR | NR |
| MW-1 | 03-25-93 | 108.03 | 17.05 | 90.98 | ND | NR | NR |
| MW-1 | 04-14-93 | 108.03 | 17.45 | 90.58 | ND | NR | NR |
| MW-1 | 05-22-93 | 108.03 | 17.78 | 90.25 | ND | NR | NR |
| MW-I | 06-17-93 | 108.03 | 17.90 | 90.13 | ND | NR | NR |
| MW-1 | 07-27-93 | 108.03 | 18.10 | 89.93 | ND | NR | NR |
| MW-1 | 08-29-93 | 108.03 | 18.31 | 89.72 | ND | NR | NR |
| MW-1 | 09-30-93 | 108.03 | 18.24 | 89.79 | ND | NR | NR |
| MW-1 | 11-16-93 | 108.03 | 18.17 | 89.86 | ND | NR | NR |
| MW-1 | 02-02-94 | 108.03 | 17.31 | 90.72 | ND | NR | NR |
| MW-1 | 04-29-94 | 108.03 | 17,31 | 90.72 | ND | NR | NR |
| MW-1 | 08-02-94 | 108.03 | 17.95 | 90.08 | ND | SW | 0.017 |
| MW-1 | 11-16-94 | 108.03 | 17.04 | 90.99 | ND | sw | 0.02 |
| MW-1 | 03-20-95 | 108.03 | 15.75 | 92.28 | ND | SW | 0.02 |
| MW-1 | 06-06-95 | 108.03 | 17.68 | 90.35 | ND | sw | 0.016 |
| MW-1 | 08-24-95 | 107.80 | 17.45 | 90.35 | ND | sw | 0.014 |

Table 2 Historical Groundwater Elevation Data

| Well | Water Level | | Depth | Ground- | Floating | Ground- Water | |
|----------|----------------|-----------|--------|-----------|-----------|------------------|-----------|
| Desig- | Field | TOC | to | Water | Product | Flow | Hydraulic |
| nation | Date | Elevation | Water | Elevation | Thickness | Direction | Gradient |
| 11447-01 | | ft-MSL | feet | ft-MSL | feet | MWN | foot/foot |
| | | IL-MOL | 1001 | R-MSL | leet | MWN | 1001/1001 |
| MW-2 | 12-23-91 | 107.43 | 17.98 | 89,45 | Sheen | NR | NR |
| MW-2 | 01-07-92 | 107.43 | 17.15 | 90.28 | Sheen | NR | NR |
| MW-2 | 01-19-92 | 107.43 | 17.47 | 89.96 | ND | NR | NR |
| MW-2 | 02-19-92 | 107.43 | 16.28 | 91.15 | ND | NR | NR |
| MW-2 | 03-18-92 | 107.43 | 16.52 | 90.91 | ND | NR | NR |
| MW-2 | 04-20-92 | 107.43 | 17.27 | 90.16 | ND | NR | NR |
| MW-2 | 05-15-92 | 107.43 | 17.62 | 89.81 | ND | NR | NR |
| MW-2 | 06-12-92 | 107.43 | ^17.63 | ^89.80 | 0.05 | NR | NR |
| MW-2 | 07-15-92 | 107.43 | 17.65 | 89.78 | ND | NR | NR |
| MW-2 | 08-07-92 | 107.43 | 17.80 | 89.63 | ND | NR | NR |
| MW-2 | 09-14-92 | 107.43 | ^18.09 | ^89,34 | 0.55 | NR | NR |
| MW-2 | 10-07-92 | 107.43 | ^18.55 | ^88.88 | 0.31 | NR | NR |
| MW-2 | 11-12-92 | 107.43 | 17.95 | 89.48 | Sheen | NR | NR |
| MW-2 | 12-09-92 | 107.43 | ^16.85 | ^90.58 | 0.02 | NR | NR |
| MW-2 | 01-21-93 | 107.43 | ^15.08 | ^92,35 | 0.01 | NR | NR |
| MW-2 | 02-22-93 | 107.43 | ^16.20 | ^91,23 | 0.01 | NR | NR |
| MW-2 | 03-25-93 | 107.43 | ^16.72 | ^90.71 | 0.01 | NR | NR |
| MW-2 | 04-14-93 | 107.43 | ^17.15 | ^90.28 | ND | NR | NR |
| MW-2 | 05-22-93 | 107.43 | ^17.44 | ^89.99 | ND | NR | NR |
| MW-2 | 06-17-93 | 107.43 | 17.57 | 89.86 | ND | NR | NR |
| MW-2 | 07-27-93 | 107.43 | ^17.71 | ^89.72 | ND | NR | NR |
| MW-2 | 08-29-93 | 107.43 | ^18.20 | ^89.23 | ND | NR | NR |
| MW-2 | 09-30-93 | 107.43 | ^18.14 | ^89.29 | ND | NR | NR |
| MW-2 | 11-16-93 | 107.43 | ^17.85 | ^89.58 | ND | NR | NR |
| MW-2 | 02-02-94 | 107.43 | 16.96 | 90.47 | ND | NR | NR |
| MW-2 | 04-29-94 | 107.43 | 16.95 | 90.48 | ND | NR | NR |
| MW-2 | 08-02-94 | 107.43 | 17.59 | 89.84 | ND | SW | 0.017 |
| MW-2 | 11-16-94 | 107.43 | 16.73 | 90.70 | ND | SW | 0.02 |
| MW-2 | 03-20-95 | 107.43 | 15.50 | 91.93 | ND* | SW | 0.02 |
| MW-2 | 06-06-95 | 107.43 | 17.43 | 90.00 | ND | sw | 0.016 |
| MW-2 | 08-24-95 | 107.28 | 17.22 | 90.06 | ND | SW | 0.014 |

Table 2 Historical Groundwater Elevation Data

| Well Desig- nation | Water Level Field Date | TOC Elevation | Depth to Water | Ground- Water Elevation | Floating Product Thickness | Ground- Water Flow Direction | Hydraulic Gradient |
|--------------------------|---------------------------------|------------------|----------------------|-------------------------------|----------------------------------|---------------------------------------|-----------------------|
| | | ft-MSL | feet | ft-MSL | feet | MWN | foot/foot |
| MW-3 | 12-23-91 | 107.77 | 18.14 | 89.63 | Sheen | NR | NR |
| MW-3 | 01-07-92 | 107.77 | 17.26 | 90.51 | Sheen | NR | NR |
| MW-3 | 01-19-92 | 107.77 | 17.63 | 90.14 | ND | NR | NR |
| MW-3 | 02-19-92 | 107.77 | 16.34 | 91.43 | ND | NR | NR |
| MW-3 | 03-18-92 | 107.77 | 16.62 | 91.15 | ND | NR | NR |
| MW-3 | 04-20-92 | 107.77 | 17.38 | 90.39 | ND | NR | NR |
| MW-3 | 05-15-92 | 107.77 | 17.80 | 89.97 | ND | NR | NR |
| MW-3 | 06-12-92 | 107.77 | 18.01 | 89.76 | ND | NR | NR |
| MW-3 | 07-15-92 | 107.77 | 18.17 | 89.60 | ND | NR | NR |
| MW-3 | 08-07-92 | 107.77 | 18.23 | 89.54 | ND | NR | NR |
| MW-3 | 09-14-92 | 107.77 | 18.36 | 89.41 | ND | NR | NR |
| MW-3 | 10-07-92 | 107.77 | 18.90 | 88.87 | Sheen | NR | NR |
| MW-3 | 11-12-92 | 107.77 | 18.00 | 89.77 | Sheen | NR | NR |
| MW-3 | 12-09-92 | 107.77 | 16.85 | 90.92 | Droplets | NR | NR |
| MW-3 | 01-21-93 | 107.77 | 15.24 | 92.53 | ND | NR | NR |
| MW-3 | 02-22-93 | 107.77 | 16.36 | 91.41 | ND | NR | NR |
| MW-3 | 03-25-93 | 107.77 | 16.89 | 90.88 | ND | NR | NR |
| MW-3 | 04-14-93 | 107.77 | 17.29 | 90.48 | ND | NR | NR |
| MW-3 | 05-22-93 | 107.77 | 17.64 | 90.13 | ND | NR | NR |
| MW-3 | 06-17-93 | 107.77 | 17.75 | 90.02 | ND | NR | NR |
| MW-3 | 07-27-93 | 107.77 | 17.98 | 89.79 | ND | NR | NR |
| MW-3 | 08-29-93 | 107.77 | 18.14 | 89.63 | ND | NR | NR |
| MW-3 | 09-30-93 | 107.77 | 18.14 | 89.63 | ND | NR | NR |
| MW-3 | 11-16-93 | 107.77 | 18,30 | 89.47 | ND | NR | NR |
| MW-3 | 02-02-94 | 107.77 | 17.16 | 90.61 | ND | NR | NR |
| MW-3 | 04-29-94 | 107.77 | 17.14 | 90.63 | ND | NR | NR |
| MW-3 | 08-02-94 | 107.77 | 17.81 | 89.96 | ND | SW | 0.017 |
| MW-3 | 11-16-94 | 107.77 | 16.91 | 90.86 | ND | sw | 0.02 |
| MW-3 | 03-20-95 | 107.77 | 15.60 | 92.17 | ND | SW | 0.02 |
| MW-3 | 06-06-95 | 107.77 | 17.54 | 90.23 | ND | SW | 0.016 |
| MW-3 | 08-24-95 | 107.61 | 17.42 | 90.19 | ND | SW | 0.014 |

Table 2 Historical Groundwater Elevation Data

Date: 11-02-95

ARCO Service Station 6148
5131 Shattuck Avenue, Oakland, California

Water Ground-Well Level Depth Ground-Floating Water TOC Water Product Hydraulic Desig-Field Flow to nation Date Elevation Water Elevation Thickness Direction Gradient ft-MSL ft-MSL **MWN** feet feet foot/foot MW-4 11-12-92 106.58 16.08 90.50 ND NR NR MW-4 12-09-92 106.58 15.00 91.58 ND NR NR MW-4 01-21-93 106.58 13.35 93.23 NR ND NR MW-4 02-22-93 106.58 14.48 92,10 ND NR NR MW-4 03-25-93 106.58 15.06 91.52 ND NR NR MW-4 04-14-93 106.58 15.50 91.08 ND NR NR 106.58 90.79 MW-4 05-22-93 15.79 ND NR NR MW-4 06-17-93 106.58 14.90 91.68 ND NR NR MW-4 07-27-93 106.58 16.11 90.47 ND NR NR MW-4 08-29-93 106.58 16.21 90.37 ND NR NR MW-4 09-30-93 106.58 16.23 90.35 ND NR NR MW-4 11-16-93 106.58 16.30 90.28 ND NR NR MW-4 02-02-94 106.58 15.36 91.22 ND NR NR MW-4 04-29-94 106.58 15.36 91.22 ND NR NR MW-4 08-02-94 106.58 15.94 90.64 ND SW 0.017 MW-4 106.58 91.59 11-16-94 14.99 ND SW 0.02 MW-4 106.58 03-20-95 13.85 92.73 ND SW 0.02 MW-4 06-06-95 106.58 15.70 90.88 ND sw0.016 MW-4 08-24-95 106.71 15.86 90.85 ND SW 0.014

Table 2 Historical Groundwater Elevation Data

| Well Desig- nation | Water Level Field Date | TOC Elevation ft-MSL | Depth to Water feet | Ground- Water Elevation ft-MSL | Floating Product Thickness feet | Ground- Water Flow Direction MWN | Hydraulic Gradient foot/foot |
|--------------------------|---------------------------------|----------------------------|------------------------------|---|--|--|------------------------------------|
| MW-5 | 11-12-92 | 106.68 | 16.81 | 89.87 | ND | NR | NR |
| MW-5 | 1 2- 09- 92 | 106.68 | 16.40 | 90.28 | ND | NR | NR |
| MW-5 | 01-21-93 | 106.68 | 14.58 | 92.10 | ND | NR | NR |
| MW-5 | 02-22-93 | 106.68 | 15.65 | 91.03 | ND | NR | NR |
| MW-5 | 03-25-93 | 106.68 | 16.07 | 90.61 | ND | NR | NR |
| MW-5 | 04-14-93 | 106.68 | 16.34 | 90.34 | ND | NR | NR |
| MW-5 | 05-22-93 | 106.68 | 16.56 | 90.12 | ND | NR | NR |
| MW-5 | 06-17-93 | 106.68 Not | surveyed: | | | | |
| MW-5 | 07-27-93 | 106.68 | 16.80 | 89.88 | ND | NR | NR |
| MW-5 | 08-29-93 | 106.68 | 16.93 | 89.75 | ND | NR | NR |
| MW-5 | 09-30-93 | 106.68 | 16.97 | 89.71 | ND | NR | NR |
| MW-5 | 11-16-93 | 106.68 | 17.03 | 89.65 | ND | NR | NR |
| MW-5 | 02-02-94 | 106.68 | 16.38 | 90.30 | ND | NR | NR |
| MW-5 | 04-29-94 | 106.68 | 16.41 | 90.27 | ND | NR | NR |
| MW-5 | 08-02-94 | 106.68 | 16.81 | 89.87 | ND | sw | 0.017 |
| MW-5 | 11-16-94 | 106.68 | 16.12 | 90.56 | ND | sw | 0.02 |
| MW-5 | 03-20-95 | 106.68 | 14.92 | 91.76 | ND | sw | 0.02 |
| MW-5 | 06-06-95 | 106.68 | 16.61 | 90.07 | ND | sw | 0.016 |
| MW-5 | 08-24-95 | 106.60 | 16.47 | 90.13 | ND | sw | 0.014 |

Table 2 Historical Groundwater Elevation Data

| Well Desig- nation | Water Level Field Date | TOC Elevation ft-MSL | Depth to Water feet | Ground- Water Elevation ft-MSL | Floating Product Thickness feet | Ground- Water Flow Direction MWN | Hydraulic Gradient foot/foot |
|--------------------------|---------------------------------|----------------------------|------------------------------|---|--|--|------------------------------------|
| MW-6 | 11-12-92 | 105.16 | 14.05 | 91.11 | ND | NR | NR |
| MW-6 | 12-09-92 | 105.16 | 13.37 | 91.79 | ND | NR | NR |
| MW-6 | 01-21-93 | 105.16 | 11.76 | 93.40 | ND | NR | NR |
| MW-6 | 02-22-93 | 105.16 | 12.62 | 92.54 | ND | NR | NR |
| MW-6 | 03-25-93 | 105.16 | 13.04 | 92.12 | ND | NR | NR |
| MW-6 | 04-14-93 | 105.16 | 13.47 | 91.69 | ND | NR | NR |
| MW-6 | 05-22-93 | 105.16 | 13.80 | 91.36 | ND | NR | NR |
| MW-6 | 06-17-93 | 105.16 | 13.88 | 91.28 | ND | NR | NR |
| MW-6 | 07-27-93 | 105.16 | 14.13 | 91.03 | ND | NR | NR |
| MW-6 | 08-29-93 | 105.16 | 14.19 | 90.97 | ND | NR | NR |
| MW-6 | 09-30-93 | 105.16 | 14.34 | 90.82 | ND | NR | NR |
| MW-6 | 11-16-93 | 105.16 | 14.41 | 90.75 | ND | NR | NR |
| MW-6 | 02-02-94 | 105.16 | 13.60 | 91.56 | ND | NR | NR |
| MW-6 | 04-29-94 | 105.16 | 13.66 | 91.50 | ND | NR | NR |
| MW-6 | 08-02-94 | 105.16 | 13.99 | 91.17 | ND | SW | 0.017 |
| MW-6 | 11-16-94 | 105.16 | 13.11 | 92.05 | ND | SW | 0.02 |
| MW-6 | 03-20-95 | 105.16 | 12.13 | 93.03 | ND | SW | 0.02 |
| MW-6 | 06-06-95 | 105.16 | 13.95 | 91.21 | ND | SW | 0.016 |
| MW-6 | 08-24-95 | 105.13 | 14.07 | 91.06 | ND | SW | 0.014 |

Table 2 Historical Groundwater Elevation Data

| | Water | | | | | Ground- | |
|--------|----------|-----------|-------|-----------|-----------|-----------|-----------|
| Well | Level | | Depth | Ground- | Floating | Water | |
| Desig- | Field | TOC | Îto | Water | Product | Flow | Hydraulic |
| nation | Date | Elevation | Water | Elevation | Thickness | Direction | Gradient |
| | | ft-MSL | feet | ft-MSL | feet | MWN | foot/foot |
| MW-7 | 11-12-92 | 107.08 | 14.75 | 92.33 | ND | NR | NR |
| MW-7 | 12-09-92 | 107.08 | 12.55 | 94.53 | ND | NR | NR |
| MW-7 | 01-21-93 | 107.08 | 11.52 | 95.56 | ND | NR | NR |
| MW-7 | 02-22-93 | 107.08 | 12.82 | 94.26 | ND | NR | NR |
| MW-7 | 03-25-93 | 107.08 | 13.43 | 93.65 | ND | NR | NR |
| MW-7 | 04-14-93 | 107.08 | 13.98 | 93.10 | ND | NR | NR |
| MW-7 | 05-22-93 | 107.08 | 14.41 | 92.67 | ND | NR | NR |
| MW-7 | 06-17-93 | 107.08 | 14.50 | 92.58 | ND | NR | NR |
| MW-7 | 07-27-93 | 107.08 | 14.82 | 92.26 | ND | NR | NR |
| MW-7 | 08-29-93 | 107.08 | 15.05 | 92.03 | ND | NR | NR |
| MW-7 | 09-30-93 | 107.08 | 15.04 | 92.04 | ND | NR | NR |
| MW-7 | 11-16-93 | 107.08 | 15.12 | 91.96 | ND | NR | NR |
| MW-7 | 02-02-94 | 107.08 | 14.04 | 93.04 | ND | NR | NR |
| MW-7 | 04-29-94 | 107.08 | 14.10 | 92.98 | ND | NR | NR |
| MW-7 | 08-02-94 | 107.08 | 14.61 | 92,47 | ND | sw | 0.017 |
| MW-7 | 11-16-94 | 107.08 | 13.37 | 93.71 | ND | sw | 0.02 |
| MW-7 | 03-20-95 | 107.08 | 12.32 | 94.76 | ND | sw | 0.02 |
| MW-7 | 06-06-95 | 107.08 | 14.59 | 92,49 | ND | św | 0.016 |
| MW-7 | 08-24-95 | 107.05 | 14.64 | 92.41 | ND | sw | 0.014 |
| | | | | | | | |
| AS-1 | 09-30-93 | 107.71 | 18.31 | 89.40 | ND | NR | NR |
| AS-2 | 08-11-95 | 107.38 | 17.46 | 89.92 | ND | NR | NR |
| V AS-3 | 08-11-95 | 107.89 | 19.30 | 88.59 | ND | NR | NR |
| V AS-4 | 08-11-95 | 106.81 | 16.51 | 90.30 | ND | NR | NR |
| AS-5 | 08-11-95 | 106.24 | 16.52 | 89.72 | ND | NR | NR |

TOC: top of casing

ft-MSL: elevation in feet, relative to mean sea level

MWN: ground-water flow direction and gradient apply to the entire monitoring well network

NR: not reported; data not available

ND: none detected

SW: southwest

^{^:} groundwater elevation (GWE) and depth to water (DTW) adjusted to include 80 percent of the floating product thickness (FPT): [GWE: (TOC - DTW) + (FPT x 0.8)]

^{*:} floating product entered the well during purging

Table 3
Soil Analytical Data
ARCO Service Station 6148

| Sample Identification | Date Sampled | Depth (feet) | TPHG ² | Benzene | Toluene | Ethylbenzene | Xylenes |
|--------------------------|---------------------|-----------------|-------------------|-----------------|---------|--------------|---------|
| Soil Data (in m | g/kg ¹) | | | | | | <u></u> |
| AS-3 | 8/2/95 | 16 | <1 | 0.34 | <0.005 | <0.005 | <0.005 |
| AS-3 | 8/2/95 | 26.5 | <1 | <0.005 | <0.005 | <0.005 | 0.007 |
| AS-4 | 8/2/95 | 14 | <1 | 0.009 | <0.005 | <0.005 | 0.0045 |
| AS-4 | 8/2/95 | 26.5 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| AS-5 | 8/2/95 | 28.5 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-2 | 7/31/95 | 16.5 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-4 | 7/31/95 | 16 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-5 | 8/1/95 | 21.5 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-5 | 8/1/95 | 16 | 74 | 0.7 | <0.2* | 0.9 | 1.0 |
| VW-6 | 8/3/95 | 6 | 3,100 | <5 [*] | 86 | 63 | 430 |
| VW-6 | 8/3/95 | 8 | 2,300 | <5 [*] | 51 | 48 | 310 |
| VW-6 | 8/3/95 | 11.5 | 2,100 | <2* | 7.3 | 16 | 110 |
| VW-6 | 8/3/95 | 16 | 1,700 | 5.9 | 94 | 44 | 240 |
| VW-7 | 8/3/5 | 17 | 30 | 0.3 | 0.5 | 0.6 | 2.8 |
| VW-8 | 8/1/95 | 26 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-9 | 8/1/95 | 16.5 | 6 | <0.025* | <0.025* | <0.025* | 0.026 |
| VW-9 | 8/1/95 | 26 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-10 | 8/1/95 | 16 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |
| VW-10 | 8/1/95 | 21 | <1 | <0.005 | <0.005 | <0.005 | <0.005 |

l mg/kg = milligrams per kilogram

² TPHG = total petroleum hydrocarbons as gasoline

< indicates laboratory minimum reporting limit

raised MRL due to high analyte concentration requiring sample dilution

Table 4 Groundwater Analytical Data ARCO Service Station 6148

| Well Identification | Date Sampled | TPGH ¹ | Benzene | Toluene | Ethylbenzene | Xylenes |
|------------------------|-----------------|-------------------|---------|---------|--------------|---------|
| AS-2 | 8/11/95 | 310 | 15 | 2.6 | 5.9 | 44 |
| AS-3 | 8/11/95 | 10,000 | 1,700 | 380 | 490 | 1,600 |
| AS-4 | 8/11/95 | <50 | <0.5 | <0.5 | <0.5 | < 0.5 |
| AS-5 | 8/11/95 | <50 | <0.5 | <0.5 | <0.5 | <0.5 |

TPHG = total petroleum hydrocarbons as gasoline

μg/L = micrograms per liter
< indicates laboratory minimum reporting limit

Table 5
Historical Groundwater Analytical Data
Petroleum Hydrocarbons and Their Constituents

Date: 11-17-95

| | | | | | | | | | | | | · |
|------------------|----------------------------|--------------------|------------|--------------|---|----------------------------------|--------------------|--------------------|----------------|-------------------------------|------|---|
| Well Designation | Water Sample Field Date | TPHG S LUFT Method | EPA 8020 | Toluene | Ethylbenzene Se EPA 8020 | ਜ Total Xylenes ਵੁੱਚ EPA 8020 | MTBE P EPA 8020 | MTBE F EPA 8240 | B Oil & Grease | ы ТRРН үй ЕРА 418 1 | TPHD | |
| | | ~ | | | | | | | | | | |
| MW-1 | 03-18-92 | 790 | 310 | 26 | 12 | 44 | | | <0.5 | 1.4 | <50 | |
| MW-1 | 06-12-92 | 1000 | 290 | 15 | 10 | 30 | | | <0.5 | | <50 | |
| MW-I | 09-14-92 | 1000 | 370 | 6.5 | 6.5 | 17 | | | | 0.9 | <80 | |
| MW-1 | 10-07-92 | 590 | 200 | 19 | 6.7 | 19 | | | <0.5 | ••• | <50 | |
| MW-1 | 01-22-93 | 1200 | 370 | 57 | 18 | 39 | | | | •• | | |
| MW-1 | 04-14-93 | 140 | 46 | <2.5 | <2.5 | <25 | | | | | •- | |
| MW-1 | 09-30-93 | 220 | 64 | 0.9 | 2.2 | 4 | | | | | | |
| MW-1 | 11-16-93 | 180 | 53 | 0.7 | 1.7 | 4.1 | | | | | | |
| MW-1 | 02-02-94 | 250 | 93 | < 0.5 | 1.9 | 1 | | | | | | |
| MW-I | 04-29-94 | 350 | 99 | 1.3 | 3.9 | 11 | | | | | | |
| MW-1 | 08-02-94 | 210 | 82 | <1 | </td <td>2.5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | 2.5 | | | | | | |
| MW-1 | 11-16-94 | 650 | 260 | 38 | 61 | 15 | | | | | | |
| MW-1 | 03-20-95 | 830 | 140 | 5 | 41 | 110 | | | | | •• | |
| MW-1 | 06-06-95 | 210 | 30 | <0.5 | 7.3 | 16 | | | | | | |
| MW-I | | Not sampled: | well was i | | | struction | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| MW-2 | 03-18-92 | 8400 | 1400 | 1000 | 220 | 870 | | | 1.2 | 3 | 230* | |
| MW-2 | 06-12-92 | Not sampled: | well conta | tined floati | ng product | | | | | | | |
| MW-2 | 09-14-92 | Not sampled: | well conta | ined floatii | ng product | | | | | | | |
| MW-2 | 10-07-92 | Not sampled: | well conta | ined floatii | ng product | | | | | | | |
| MW-2 | 01-22-93 | Not sampled: | | | | | | | | | | |
| MW-2 | 04-14-93 | Not sampled. | | | | | | | | | | |
| MW-2 | 09-30-93 | Not sampled: | | | | | | | | | | |
| MW-2 | 11-16-93 | Not sampled: | | | | | | | | | | |
| MW-2 | 02-02-94 | 16000 | 1300 | 2500 | 540 | 2700 | | | | | •- | |
| MW-2 | 04-29-94 | 11000 | 1400 | 1200 | 360 | 1400 | | | | | | |
| MW-2 | 08-02-94 | 4900 | 800 | 290 | 120 | 620 | | | • | | | |
| MW-2 | 11-16-94 | 49000 | 3300 | 8300 | 1400 | 7200 | | | | | | |
| MW-2 | 03-20-95 | Not sampled: | | | | | | - | | | - • | |
| MW-2 | 06-06-95 | 1200 | 60 | 21 | 35 | 140 | ۰. | | | | | |
| MW-2 | 08-24-95 | Not sampled: | | | | | - | | | | | |
| ATT 11 4 | JU 21 /J | or onthibiton. | | | | | | | | | | |

Table 5
Historical Groundwater Analytical Data
Petroleum Hydrocarbons and Their Constituents

Date: 11-17-95

| MW-3 | | | | | | | | | | | | | |
|---|------------------|----------------------------|--------------|--------------|-------------|--------------|-------------|-----|----|-----|-----|--------|--|
| MW-3 06-12-92 46000 3400 4200 1300 5400 | Well Designation | Water Sample Field Date | - | | | | | | | | | | |
| MW-3 06-12-92 46000 3400 4200 1300 5400 | | | | | | * | | | | | | | |
| MW-3 09-14-92 53000 4300 5700 1300 7300 5.5 40000* MW-3 10-07-92 Not sampled: well contained floating product MW-3 01-22-93 35000 2100 1400 1200 4400 31 13000* MW-3 04-14-93 13000 1800 390 990 3500 26 <50 MW-3 09-30-93 79000 2400 3400 1900 8100 23 17000* MW-3 11-16-93 72000 1400 2100 1900 8300 38 MW-3 04-29-94 26000 1400 620 910 3400 10 7.7 7.8 MW-3 04-29-94 22000 1400 620 910 3400 10 6.6 MW-3 08-02-94 17000 530 410 720 2600 10 6.6 MW-3 03-20-95 29000 880 190 760 2900 16 2.3 MW-3 03-20-95 29000 880 190 760 2900 16 16 MW-3 06-06-95 22000 450 54 380 1300 16 7.1 MW-3 08-24-95 Not sampled: well was inaccessible due to construction | | | | | | | | - • | | 7.8 | 8.1 | 2800* | |
| MW-3 | | | | | | | | | | 16 | | 1600* | |
| MW-3 01-22-93 35000 2100 1400 1200 4400 - 31 31 - 13000* MW-3 04-14-93 13000 1800 390 990 3500 - 26 - <50 MW-3 09-30-93 79000 2400 3400 1900 8100 - 23 - 17000* MW-3 11-16-93 72000 1400 2100 1900 8300 - 38 MW-3 02-02-94 26000 1400 1200 1200 4400 - 7.7 7.8 - MW-3 02-02-94 26000 1400 620 910 3400 - 10 MW-3 08-02-94 17000 530 410 720 2600 6.6 - MW-3 08-02-94 18000 1400 560 790 2800 2.3 - MW-3 03-20-95 29000 880 190 760 2000 16 - MW-3 06-06-95 22000 450 54 380 1300 16 - MW-3 08-24-95 Not sampled: well was inaccessible due to construction MW-4 01-22-93 170 66 0.8 <0.5 | | | | | | | | | | | 5.5 | 40000* | |
| MW-3 04-14-93 13000 1800 390 990 3500 26 \$50 MW-3 09-30-93 79000 2400 3400 1900 8100 23 17000* MW-3 11-16-93 72000 1400 2100 1900 8300 38 17000* MW-3 02-02-94 26000 1400 1200 1200 4400 7,7 7,8 MW-3 04-29-94 22000 1400 620 910 3400 10 6.6 MW-3 08-02-94 17000 530 410 720 2600 6.6 MW-3 11-16-94 18000 1400 560 790 2800 2,3 MW-3 03-20-95 29000 880 190 760 2000 16 MW-3 06-06-95 22000 450 54 380 1300 16 MW-3 08-24-95 Not sampled: well was inaccessible due to construction MW-4 01-22-93 170 66 0.8 <0.5 <0.5 <0.5 <0.5 < MW-4 09-30-93 52 13 <0.5 <0.5 <0.5 <0.5 < MW-4 02-02-94 <50 3.9 <0.5 <0.5 <0.5 <0.5 < MW-4 02-02-94 <50 3.9 <0.5 <0.5 <0.5 <0.5 < MW-4 02-02-94 <50 3.8 <0.5 <0.5 <0.5 <0.5 < MW-4 08-02-94 <50 3.8 <0.5 <0.5 <0.5 <0.5 < MW-4 08-02-94 <50 3.8 <0.5 <0.5 <0.5 <0.5 <0.5 < MW-4 08-02-94 <50 3.8 <0.5 <0.5 <0.5 <0.5 <0.5 < | | | | | | | | | | | | | |
| MW-3 09-30-93 79000 2400 3400 1900 8100 - 233 - 17000* MW-3 11-16-93 72000 1400 2100 1900 8300 - 38 - 38 - 38 - 38 - 38 - 38 - | | - | | | | | | | | | | | |
| MW-3 11-16-93 72000 1400 2100 1900 8300 - 38 - 0 MW-3 02-02-94 26000 1400 1200 1200 4400 - 7.7 7.8 - MW-3 04-29-94 22000 1400 620 910 3400 - 10 - 6.6 - MW-3 08-02-94 17000 530 410 720 2600 6.6 - MW-3 11-16-94 18000 1400 560 790 2800 2.3 - 16 - MW-3 03-20-95 29000 880 190 760 2000 16 - MW-3 06-06-95 22000 450 54 380 1300 7.1 - MW-3 08-24-95 Not sampled: well was inaccessible due to construction | | | | | | | | | •• | | | | |
| MW-3 02-02-94 26000 1400 1200 1200 4400 7.7 7.8 MW-3 04-29-94 22000 1400 620 910 3400 10 6.6 MW-3 08-02-94 17000 530 410 720 2600 6.6 MW-3 11-16-94 18000 1400 560 790 2800 2.3 16 MW-3 03-09-5 22000 450 54 380 1300 16 MW-3 08-02-94 S0 MOV 3 08-02-95 Not sampled: well was inaccessible due to construction MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 <0.5 < MW-4 01-22-93 170 66 0.8 <0.5 <0.5 <0.5 < MW-4 01-22-93 170 66 0.8 <0.5 <0.5 <0.5 < MW-4 01-22-93 170 66 0.8 <0.5 <0.5 <0.5 <0.5 < | | | | | | | | | •• | | • - | 17000* | |
| MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-3 03-20-95 29000 880 190 760 2000 | | | | | | | | | | | | | |
| MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 | | | | | | | | | | | | •- | |
| MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 11-12-92 77 32 <0.5 <0.5 <0.5 ·· ·· ·· ·· ·· ·· ·· ·· ·· ·· ·· ·· ·· | | | | | | | | | | | 7.1 | | |
| MW-4 01-22-93 170 66 0.8 <0.5 1.5 | MW-3 | 08-24-95 | Not sampled | : well was i | naccessible | due to con | struction | | | | | | |
| MW-4 01-22-93 170 66 0.8 <0.5 1.5 | | | | | | | | | | | | | |
| MW-4 09-30-93 52 13 <0.5 <0.5 <0.5 | MW-4 | 01-22-93 | 170 | 66 | 0,8 | <0.5 | 1.5 | •• | | | | | |
| MW-4 11-16-93 230 34 <0.5 <0.5 <0.5 < | | | | | | | | | | | | | |
| MW-4 02-02-94 <50 3.9 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 04-29-94 <50 4.2 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 08-02-94 <50 3.8 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 11-16-94 110 31 <0.5 <0.5 <0.5 MW-4 03-20-95 88 1 <0.5 <0.5 <0.5 0.7 | | | | | | | | | | | | •- | |
| MW-4 03-20-95 88 1 <0.5 <0.5 0.7 MW-4 06-06-95 <50 <0.5 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| MW-4 06-06-95 <50 <0.5 <0.5 <0.5 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| MW-4 08-24-95 Not sampled: well was maccessible due to construction | | | | | | | | | | | • • | | |
| | MW-4 | 08-24-95 | Not sampled: | well was it | naccessible | due to cons | struction | | | | | | |

Table 5
Historical Groundwater Analytical Data
Petroleum Hydrocarbons and Their Constituents

Date: 11-17-95

| = | | | | | | | | | | | | | |
|---|------------------|----------------------------|--------------|-----------------------------------|--------------|--------------|-------------------------|--------------------|---------------------|--------------|------|---------------------------------------|--|
| _ | Well Designation | Water Sample Field Date | TPHG | ъ Веп <i>ге</i> пе ТЭ ЕРА 8020 | Toluene | Ethylbenzene | Total Xylenes EPA 8020 | MTBE E EPA 8020 | MTBE PB BPA 8240 | Dil & Grease | TRPH | TPHD | |
| = | | 4. 14.00 | *** | | | | | | | | | | |
| | MW-5 | 11-12-92 | 2900 | 1300 | 12 | 67 | 18 | | | | | | |
| | MW-5 | 01-22-93 | 17000 | 5000 | 780 | 260 | 330 | | | | - • | • • | |
| | MW-5 | 04-14-93 | 12000 | 4600 | <50 | 180 | 130 | | | | | | |
| | MW-5 | 09-30-93 | 4500 | 1100 | <10 | 39 | 16 | • • | | | • • | | |
| | MW-5 | 11-16-93 | 3300 | 700 | <10 | 22 | <10 | - • | • • | | | | |
| | MW-5 | 02-02-94 | 10000 | 3000 | 65 | 240 | 78 | | | | | | |
| | MW-5 | 04-29-94 | 7600 | 2400 | 27 | 130 | 44 | | | • • | | | |
| | MW-5 | 08-02-94 | 1900 | 680 | <10 | 24 | <10 | • • | | | | | |
| | MW-5 | 11-16-94 | 17000 | 5900 | 700 | 440 | 320 | | | | | | |
| | MW-5 | 03-20-95 | 21000 | 6900 | 450 | 800 | 1300 | • • | | | | | |
| | MW-5 | 06-06-95 | 6500 | 1700 | <20 | 120 | 69 | -• | •- | | - • | | |
| | MW-5 | 08-24-95 | Not sampled: | well was i | naccessible | due to con | struction | | | | | | |
| | | | | | | | | | | | | | |
| | MW-6 MW-6 | 11-12-92 01-22-93 | 51 <50 | 2.6 1.2 | <0.5 <0.5 | <0.5 <0.5 | <0.5 <0.5 | | | | •• | • • • • • • • • • • • • • • • • • • • | |
| | MW-6 | 04-14-93 | <50 | < 0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| | MW-6 | 09-30-93 | 74 | 2 | <0.5 | <0.5 | <0.5 | | | •- | -• | • • | |
| | MW-6 | 11-16-93 | 72 | 2.6 | < 0.5 | < 0.5 | < 0.5 | | | | | | |
| | MW-6 | 02-02-94 | 61 | 2.2 | <0.5 | <0.5 | < 0.5 | | | | | | |
| | MW-6 | 04-29-94 | <50 | 0.6 | <0.5 | < 0.5 | <0.5 | | | | - • | | |
| | MW-6 | 08-02-94 | <50 | <0.5 | < 0.5 | <0.5 | <0.5 | • - | | | | | |
| | MW-6 | 11-16-94 | <50 | 1.1 | <0.5 | <0.5 | <0.5 | | • - | | | | |
| | MW-6 | 03-20-95 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| | MW-6 | 06-06-95 | <50 | <0.5 | < 0.5 | <0.5 | < 0.5 | | | | | | |
| | MW-6 | 08-24-95 | <50 | <0.5 | <0.5 | < 0.5 | < 0.5 | <3 | •- | | •- | | |
| | | | | | | | | | | | | | |

Table 5
Historical Groundwater Analytical Data
Petroleum Hydrocarbons and Their Constituents

Date: 11-17-95

| Well Designation | Water Sample Field Date | TPHG LUFT Method | Benzene EPA 8020 | Toluene EPA 8020 | Ethylbenzene EPA 8020 | Total Xylenes EPA 8020 | MTBE EPA 8020 | MTBE EPA 8240 | Oil & Grease SM 5520C | TRPH EPA 418.1 | TPHD LUFT Method | |
|------------------|----------------------------|---------------------|---------------------|----------------------------|--------------------------|---------------------------|-------------------------|------------------|--------------------------|--------------------------|---------------------|-----|
| | | μg/L | µg/L | μg/L | μg/L | μg/L, | μg/L | μg/L | mg/L | mg/L | μg/L | |
| MW-7 | 11-12-92 | <50 | 1.8 | <0.5 | <0.5 | <0.5 | | | | | | *** |
| MW-7 | 01-22-93 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | •• | | | |
| MW-7 | 04-14-93 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | •- | | |
| MW-7 | 09-30-93 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | • • • | | | | | |
| MW-7 | 11-16-93 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| MW-7 | 02-02-94 | <50 | <0.5 | <05 | <0.5 | <0.5 | | | | | | |
| MW-7 | 04-29-94 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| MW-7 | 08-02-94 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| MW-7 | 11-16-94 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| MW-7 | 03-20-95 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | | | | | | |
| MW-7 | 06-06-95 | Not sampled | | | | | _ | | | • | | |
| MW-7 | 08-24-95 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <3 | | | | • - | |
| AS-1 | 09-30-93 | <50 | 1.2 | <0.5 | <0.5 | <0.5 | <u></u> | | •• | • | • | |
| AS-2 | 08-11-95 | 310 | 15 | 2.6 | 5.9 | 44 | • ~ | | | | | |
| AS-3 | 08-11-95 | 10000 | 1700 | 380 | 490 | 1600 | | | | | | |
| AS-4 | 08-11-95 | <50 | <0.5 | <05 | <0.5 | <0.5 | •• | | | • | | |
| AS-5 | 08-11-95 | <50 | <0.5 | <0.5 | <05 | <0.5 | • • | •- | | | •- | |

MTBE: Methyl-tert-butyl ether

SM: standard method

mg/L: milligrams per liter

TRPH total recoverable petroleum hydrocarbons

TPHD: total petroleum hydrocarbons as diesel, California DHS LUFT Method


TPHG: total petroleum hydrocarbons as gasoline, California DHS LUFT Method

μg/L: micrograms per liter

EPA: United Statest Environmental Protection Agency

^{- -:} not analyzed

^{*:} chromatogram does not match the typical diesel fingerprint, but appears to be weathered gasoline





ARCO PRODUCTS COMPANY SERVICE STATION 6148, 5131 SHATTUCK AVENUE QUARTERLY GROUNDWATER MONITORING OAKLAND, CALIFORNIA

SITE LOCATION

FIGURE


T

PROJECT NO.
805-135.03

EXPLANATION

- Groundwater monitoring well
- Vapor extraction well
- Soil boring
- Air-sparge well
- Ø Decommissioned well
- Existing underground gasoline storage tank
 - Line of geologic cross section

EMCON




ARCO PRODUCTS COMPANY SERVICE STATION 6148
5131 SHATTUCK AVENUE
OAKLAND, CALIFORNIA

SITE PLAN


FIGURE NO.

PROJECT NO. 805-135.04


G:\805-135\SITEPLAN REV 0 01/26/96 14:26:57 DD



J:\!\805135\SECAA REV 0 11/01/95 09:48:05 KM



J:\\\805135\\SECBB REV 0 11/01/95 09:48:05 KMM DJ



EXPLANATION

- Groundwater monitoring well
- Vapor extraction well
- Air-sparge well
- Ø Decommissioned well
- Existing underground gasoline storage tank
- (91.06) Groundwater elevation (Ft.-MSL) measured 8/24/95
- Groundwater elevation contour (Ft.—MSL)
 - TPHG concentration in groundwater (µg/L); sampled 8/24/95
 - Benzene concentration in groundwater (µg/L); sampled 8/24/95
 - S Not sampled due to construction activity
 - ND Not detected at or above the method reporting limit for TPHG (50 µg/L) or benzene (0.5 µg/L)
 - Air sparge wells AS-2 through AS-5 were installed on 8/2/95 and sampled on 8/11/95

EMCON

G:\805-135\G01 REV 0 11/17/95

SCALE: 0 30 60 FEET
(Approximate)

ARCO PRODUCTS COMPANY
SERVICE STATION 6148, 5131 SHATTUCK AVENUE
WELL INSTALLATION REPORT
OAKLAND, CALIFORNIA

GROUNDWATER DATA THIRD QUARTER 1995 FIGURE NO.

PROJECT NO.

PROJECT NO. 805-135.04

APPENDIX A WELL PERMITS



ZONE 7 WATER AGENCY

5997 PARKSIDE DRIVE

PLEASANTON, CALIFORNIA 94588

VOICE (510) 484-2600 FAX (510) 462-3914

DRILLING PERMIT APPLICATION

| FOR APPLICANT TO COMPLETE | FOR OFFICE USE | | | | | |
|--|--|--|--|--|--|--|
| LOCATION OF PROJECT ARCO SERVICE STATION # 6148 5131 Shattuck Avenue Oakland, CA | PERMIT NUMBER 95453 LOCATION NUMBER 18/4W 14R80 | | | | | |
| CLIENT Name ARCO PRODUCTS COMPANY Address 2000 Alameda de Las Pulgas Voice (445) 571-2400 City 80x 5811 Zip 94402 APPLICANT Name EMCON Fax (408) 437-9526 Address 1921 Ringwood Ave. Voice (408) 453-7300 City San Jose, (A Zip 95131 | PERMIT CONDITIONS Circled Permit Requirements Apply A. GENERAL 1. A permit application should be submitted so as to arrive at the Zone 7 office five days prior to proposed starting date. 2. Submit to Zone 7 within 60 days after completion of permitted | | | | | |
| TYPE OF PROJECT Well Construction Geotechnical Investigation Cathodic Protection General Water Supply Contamination Monitoring Well Destruction PROPOSED WATER SUPPLY WELL USE Domestic Industrial Other Municipal Irrigation DRILLING METHOD: Mud Rotary Air Rotary Auger X Cable Other DRILLER'S LICENSE NO. C-57 # 554979 | work the original Department of Water Resources Water Well Drillers Report or equivalent for well Projects, or drilling logs and location sketch for geotechnical projects. 3. Permit is void if project not begun within 90 days of approval date. B. WATER WELLS, INCLUDING PIEZOMETERS 1. Minimum surface seal thickness is two inches of cement grouplaced by tremie. 2. Minimum seal depth is 50 feet for municipal and industrial we or 20 feet for domestic and irrigation wells unless a lesser depth is specially approved. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet C. GEOTECHNICAL. Backfill bore hole with compacted cuttings or heavy bentonite and upper two feet with compacted material. In areas of known or suspected contamination, tremied cement grout shall be used in place of compacted cuttings. | | | | | |
| WELL PROJECTS Drill Hole Diameter in. Maximum Casing Diameter 2 in. Depth 25 ft. Surface Seal Depth 4 ft. Number 1 GEOTECHNICAL PROJECTS | D. CATHODIC. Fill hole above anode zone with concrete placed by tremie. E. WELL DESTRUCTION. See attached. | | | | | |
| Number of Borings Maximum Hole Diameter in. Depth tt. ESTIMATED STARTING DATE 7/30 / 95 | | | | | | |
| I hereby agree to comply with all requirements of this permit and Alameda County Ordinance No. 73-68. APPLICANTS Robert K. | Approved Wyman Hong Date 25 Jul 9 | | | | | |
| SIGNATURE EMCON Date 7/18/95 | 91992 | | | | | |



ZONE 7 WATER AGENCY

5997 PARKSIDE DRIVE


PLEASANTON, CALIFORNIA 94588

VOICE (510) 484-2600 FAX (510) 462-3914

DRILLING PERMIT APPLICATION

| FOR APPLICANT TO COMPLETE | FOR OFFICE USE | | | | | |
|---|---|--|--|--|--|--|
| LOCATION OF PROJECT ARCO SERVICE STATION # 6148 5131 Shattuck Avenue Oakland, CA | PERMIT NUMBER 95452 LOCATION NUMBER | | | | | |
| CLIENT Name ARCO PRODUCTS COMPANY Address 2000 Alameda de Las Pulgas Voice (415) 571-2400 City 30x 5311 San Mateo, A APPLICANT Name EMCON Fax (408) 437-9526 Address 1921 Pingwood Ave. Voice(408) 453-7360 City San Jose, (A Zip 95131 TYPE OF PROJECT Well Construction General Water Supply Contamination Water Supply Contamination Water Supply Hold Destruction PROPOSED WATER SUPPLY WELL USE Domestic Industrial Other Municipal Irrigation DRILLING METHOD: Mud Rotary Air Rotary Auger X Cable Other DRILLER'S LICENSE NO. C-57 554979 WELL PROJECTS Drill Hole Diameter 8 10 in. Maximum Casing Diameter 2 1 in. Depth 25 ft. Surface Seal Depth 4-20 ft. Number 12 | A. GENERAL 1. A permit application should be submitted so as to arrive at the Zone 7 office five days prior to proposed starting date. 2. Submit to Zone 7 within 60 days after completion of permitted work the original Department of Water Resources Water Well Drillers Report or equivalent for well Projects, or drilling logs and location sketch for geotechnical projects. 3. Permit is void if project not begun within 90 days of approval date. B. WATER WELLS, INCLUDING PIEZOMETERS 1. Minimum surface seal thickness is two inches of cement grout placed by tremie. 2. Minimum seal depth is 50 feet for municipal and industrial wells or 20 feet for domestic and irrigation wells unless a lesser depth is specially approved. Minimum seal depth for monitoring wells is the maximum depth practicable or 20 feet. C. GEOTECHNICAL. Backfill bore hole with compacted cuttings or heavy bentonite and upper two feet with compacted material. In areas of known or suspected contamination, tremied cement grout shall be used in place of compacted crittings. D. CATHODIC. Fill hole above anode zone with concrete placed by tremie. E. WELL DESTRUCTION. See attached. | | | | | |
| Number of Borings Maximum Hole Diameter in. Depth ft. ESTIMATED STARTING DATE ESTIMATED COMPLETION DATE 1 hereby agree to comply with all requirements of this permit and Alameda County Ordinance No. 73-68. APPLICANT'S SIGNATURE EMCON Date 7/18/95 | Approved Wyman Hong Date 25 Jul 95 Wyman Hong 91992 | | | | | |

APPENDIX B FIELD AND LABORATORY PROCEDURES



EXPLORATORY BORINGS AND SOIL SAMPLING

General procedures for drilling and sampling exploratory borings are discussed below.

Before a drilling rig is mobilized, access issues with private property owners are resolved and an underground utility locating service contracted to investigate proposed boring sites and arrange for site visits by public and private utility companies. The utility companies locate their installations with the aid of maps and the locating service verifies and marks the locations. Final boring locations are determined after these assessments are made. To confirm that no subsurface utilities will obstruct drilling, field personnel excavate the upper four feet of soil from each boring location with a posthole digger.

For sites characterized by relatively shallow (less than 100-feet-deep) groundwater, exploratory borings are drilled with 8- to 12-inch hollow-stem auger drilling equipment. The augers are steam-cleaned to prevent possible cross-contamination between boreholes. Where chemical analysis of samples is indicated, sampling equipment is also steam-cleaned between each sampling event.

Soil samples are collected at depths no farther apart than 5 feet using a modified California split-spoon sampler which is fitted with stainless-steel liners. As the sampler is driven into undisturbed soil ahead of the auger tip, soil accumulates in the liners. The sampler is retrieved from the ground and the liners are removed, sealed with TeflonG tape and polypropylene end-caps, and stored on ice pending selection for analysis and transport to the laboratory. Chain-of-custody documentation accompanies samples to the laboratory.

Field characterization of contamination is based on visual and olfactory observations and on the results of a headspace analysis, in which a soil sample is removed from the liner, sealed in a mason jar, and exposed to direct sunlight for 10 to 15 minutes. The jar is shaken to release volatile hydrocarbons into the headspace between the soil and the jar cover. The headspace is probed by a tube attached to a portable photoionization detector (PID), by which volatile hydrocarbon content is measured. A minimum of one sample, typically that having the highest PID reading from a boring, is submitted for chemical analysis.

A detailed boring log is maintained for each exploratory boring from auger-return material and representative soil samples. Soil is logged in the field according to the Unified Soil Classification System, and the logging supervised by a state-registered geologist. Borings not completed as wells are backfilled with a neat-cement slurry by the tremie method.

Drill cuttings are stockpiled on site and covered with plastic sheeting until the results of chemical analyses are known. The petroleum hydrocarbon content of the stockpile is determined by analysis of a composite formed from samples collected from the subsurface of the stockpile. Recommendations for disposal of the cuttings are made on the basis of the analysis, and the cuttings are disposed of by the client.

Sampling and Analysis Procedures

EMCON's sampling and analysis procedures for soils provide consistent and reproducible results and ensure that the objectives of the sampling program are met.

The following publications were used as guidelines for developing these procedures:

- Leaking Underground Fuel Tank (LUFT) Field Manual (State Water Resources Control Board, May 1988, revised October 1989)
- Test Methods for Evaluating Solid Waste: Physical/Chemical Methods (EPA, SW-846, 3rd edition, November 1986)

Sample Handling

Sample containers are labeled immediately after sample collection, and are kept in ice chests with ice which is replaced daily until the containers are received at the laboratory. As a sample is collected, it is logged on the chain-of-custody record that accompanies samples to the laboratory.

Samples are transferred from the site to EMCON's laboratory by EMCON field personnel. Laboratory personnel assign a different number to each sample container and the number is recorded on the chain-of-custody record and used to identify the sample on all subsequent internal chain-of-custody and analytical records. Within 24 hours of sample receipt, samples are routinely shipped from EMCON to laboratories performing the selected analyses. EMCON's laboratory manager ensures that the holding times for requested analyses are not exceeded.

Sample Documentation

The procedures for sample handling provide chain-of-custody control from collection through storage. Sample documentation includes the following:

- Labels for identifying individual samples
- · Chain-of-custody records for documenting possession and transfer of samples

• Laboratory analysis requests for documenting analyses to be performed

Labels

Sample labels contain the following information:

- Project number
- Sample number (i.e., boring designation)
- Sampler's initials
- Date and time of collection

Sampling and Analysis Chain-of-Custody Record

The sampling and analysis chain-of-custody record (Figure 1), initiated at the time of sampling, includes the boring number, sample type, analytical request, date of sampling, the name of the sampler, and other information deemed pertinent. The sampler signs his name and records the date and time on the record sheet when transferring the samples to another person. Custody transfers are recorded for every sample; for example, if samples are split and sent to more than one laboratory, a record sheet accompanies each sample. The number of custodians in the chain of possession is kept to a minimum. A copy of the sampling and analysis chain-of-custody record is returned to EMCON with the analytical results.

Soil Analysis Request

The Soil Analysis Request (Figure 2) or the purchase order that accompanies samples to the laboratory serves as official communication of the particular analysis(es) required for each sample and is evidence that the chain of custody is complete.

At a minimum, the soil analysis request includes the following:

- Date submitted
- Specific analytical parameters
- Boring number
- Sample source

Analytical Methods

Samples collected as part of the proposed sampling programs are analyzed by accepted analytical procedures. The same publications cited under "Sampling and Analysis Procedures are the primary references.

The laboratories performing the analyses are certified by the Department of Health Services (DHS) for hazardous waste testing.

Quality Control

Quality assurance measures confirm the integrity of field and laboratory data generated during the monitoring program. Procedures for assessing data quality are discussed in this section. Field and laboratory quality assurance data are evaluated in the technical reports.

Laboratory Quality Assurance

Laboratory quality assurance includes procedures required under the DHS Hazardous Waste Testing Program. For sites where Columbia Analytical Services conducts the chemical tests, quality assurance procedures include the reporting of surrogate recoveries, matrix spike recoveries, and matrix spike duplicates (or duplicate) results.

Method blanks are analyzed daily for the purpose of assessing the effect of the laboratory environment on analytical results, and are performed for each constituent analyzed.


Samples to be analyzed for organic constituents contain surrogate spike compounds. Surrogate recoveries are used to determine whether analytical instruments are operating within limits. Surrogate recoveries are compared with control limits established and updated by the laboratory on the basis of its historical operation.

Matrix spikes are analyzed at a frequency of approximately 10 percent. Matrix spike results are evaluated to determine whether the sample matrix is interfering with the laboratory analysis, and provide a measure of the accuracy of the analytical data. Matrix spike recoveries are compared with control limits established and updated by the laboratory on the basis of its historical operation.

Laboratory duplicates are analyzed at a frequency of approximately 10 percent. Spike duplicate results are evaluated to determine the reproducibility (precision) of the analytical method. Reproducibility values are compared with control limits established and updated by the laboratory on the basis of its historical operation.

Laboratory QC data included with the analytical results are method blanks, surrogate spike recoveries (for organic parameters only), matrix spike recoveries, and matrix spike duplicates.

When other state-certified laboratories conduct the testing, each laboratory will follow its own internal QA/QC program.




GROUNDWATER WELL INSTALLATION PROCEDURES

Well permits are obtained from local and state regulatory agencies preparatory to drilling exploratory borings that will be completed as groundwater wells.

The exploratory borings to be converted to verification monitoring wells or extraction wells are drilled no deeper than 20 feet into saturated soil, or until a layer at least 3 feet thick of relatively impermeable clayey material (aquitard) is encountered, whichever comes first. If the aquitard is sufficiently thick, it is backfilled with bentonite through a tremie pipe. Borings are converted to verification monitoring wells with 2-inch-diameter, flush-threaded, polyvinyl chloride (PVC) casing with a screened section of machine-perforated, 0.020-inch slots. For extraction wells, the boring is reamed with a 12-inch-diameter auger, and 6-inch-diameter casing is installed inside the enlarged borehole.

Boring depths and screen lengths are determined from geologic profiles of the boring. Screened sections of casing extend through the saturated interval as much as 5 feet above first-encountered groundwater. A well is completed by the placement of various materials in the annular space around the casing. The annulus is filled to approximately 2 feet above the screen with a sand pack of a grain size predetermined by sieve analysis of the soil. The sand pack is covered with a bentonite plug at least 1-foot thick, and the remaining annular space is sealed within 1 foot of the surface with a sanitary seal of neat cement in compliance with regulatory guidelines. The wells are completed to ground surface with PVC casing. The well heads are protected with traffic-proof vault boxes set in concrete and capped with water-tight locking devices. Well locations are surveyed and top-of-casing elevations measured to the nearest 0.01 foot. Detailed well completion diagrams are prepared. Water well drillers' reports containing geological data, well locations and construction details are submitted to the California Department of Water Resources.



GROUNDWATER SAMPLING AND ANALYSIS

EMCON's sampling and analysis procedures for water-quality monitoring are designed to provide consistent and reproducible results and ensure that the objectives of the monitoring program are met.

The following publications were used as guidelines for developing these procedures:

- Procedures Manual for Ground-Water Monitoring at Solid Waste Disposal Facilities (EPA-530/SW-611, August 1977)
- RCRA Ground-Water Monitoring Technical Enforcement Guidance Document (OSWER 9950.1, September 1986)
- Test Methods for Evaluating Solid Waste: Physical/Chemical Methods (EPA SW-846, 3rd edition, November 1986)
- Methods for Organic Chemical Analysis of Municipal and Industrial Wastewater (EPA-600/4-82-057, July 1982)
- Methods for Chemical Analysis of Water and Wastes (EPA-600/4-79-020, revised March 1983)

Sample Collection

Sample collection procedures include equipment cleaning, well purging, and water-level, floating-hydrocarbon thickness, and total well-depth measuring.

Equipment Cleaning

The bottles, caps, and septa used to hold samples for volatile and semivolatile organic analysis are triple-rinsed with high-purity deionized water and dried overnight, the bottles at 200°C, the caps and septa at 60°C. The bottles, caps, and septa are protected from solvent contact between drying and use at the site.

The plastic bottles and caps used to hold samples for metals analysis are soaked overnight in a 1 percent nitric acid solution, triple-rinsed with deionized water, and air-dried.

Equipment for sampling groundwater (i.e., pumps, bailers, etc.) is first disassembled, cleaned thoroughly with diluted detergent, and steam-rinsed with deionized water. Parts such as plastic pump valves and bladders, which may absorb contaminants, are cleaned before each use or replaced. The inside of the positive-displacement (bladder) pump tubing is cleaned overnight with a low-flow, inert air source heated to 120°C.

A pump blank made of organic-free water is pumped through the clean bladder-pump assembly, and the resulting effluent is sampled and analyzed by EPA Method 601 or 602. Analytical results must be below the method reporting limit for each constituent analyzed before the pump is used at the site.

The surfaces of well equipment that comes in contact with groundwater during well purging and sampling are steam-cleaned with deionized water between each use.

Water-Level, Floating Hydrocarbon, and Total Well-Depth Measurements

Water levels, floating-hydrocarbon thickness, and total well-depth are measured before wells are purged and sampled. An electric sounder, a bottom-filling, clear Teflon® bailer, or an oil-water interface probe is used to make these measurements. The electric sounder is a transistorized instrument with a reel-mounted, two-conductor, coaxial cable which connects the control panel to the sensor. The cable is stamped in 1-foot increments. The sensor is lowered into the well and as it makes contact with the water, which acts as an electrolyte, a low-current circuit is completed. The current is amplified and fed into an indicator light and an audible buzzer, which produce a signal as the sensor touches the water. A sensitivity control compensates for highly saline or conductive water. The sounder is decontaminated after each use with a deionized-water rinse. The bailer is lowered to a point just below the liquid level, retrieved, and inspected for floating hydrocarbon.

Alternately, an oil-water interface sonic probe can be used to measure floating-hydrocarbon thickness. The probe emits a continuous tone when immersed in a nonconductive fluid, such as oil or gasoline, and an intermittent tone when immersed in a conductive fluid, such as water. Fluid levels are recorded relative to which tone is emitted. The sonic probe is decontaminated after each use with a deionized-water rinse.

Fluid measurements are recorded to the nearest 0.01 foot in a field logbook. The groundwater elevation at the monitoring wells is calculated by subtracting the measured depth to water from the surveyed top-of-casing elevation. When possible, depth to water is measured in all wells on the same day. Water levels are converted to elevations above mean sea level (MSL) and contoured on a groundwater map. Total well depth, recorded to the nearest 0.5 foot, is measured by means of an electric sounder which is lowered to the bottom of a well. This measurement is used for calculating purge volumes and determining the degree to which silt may have obstructed the well screen.

Well Purging

Before a monitoring well is sampled, it is purged of standing water in the casing and gravel pack by one of several devices: a bladder pump, a pneumatic displacement pump, a centrifugal pump, or a Teflon bailer. Water will be evacuated from the well until the amount equals the calculate purge volume (as shown in Monitoring Well Purging Protocol, Figure 3), which will allow indicator parameters to stabilize, or until the well is evacuated to practical limits of dryness, if this occurs before the calculated purge volume is removed. These low-yield monitoring wells are allowed to recharge until the volume of water is sufficient for sampling, but not longer than 24 hours. If insufficient water has recharged after 24 hours, a monitoring well is recorded as dry for the sampling event.

The pH, specific conductance, and the temperature meter are calibrated daily before field activities are begun. Meter calibration is checked daily during field activities to verify performance. Field measurements are recorded on a water-sample field-data sheet (Figure 4) and kept in a waterproof logbook. Data sheets are reviewed by the sampling coordinator at the end of the sampling event.

Well Sampling

A Teflon bailer or a bladder pump is the only acceptable equipment for well sampling. When samples are collected for volatile organic compound (VOC) analysis with a bladder pump, the pump flow is regulated to approximately 100 milliliters per minute to minimize pump-effluent turbulence and aeration. Samples for VOC analysis are preserved in 40-milliliter glass bottles (or larger), which are fitted with Teflon-lined septa. The bottles are filled completely to force out air and to aid in forming a positive meniscus. Bottles are capped with convex Teflon septa to seal out air, and are inverted and tapped to verify that no air bubbles remain. Containers of samples to be analyzed for other constituents are filled, filtered as required, and capped.

When required, an appropriate field-filtration technique is used to determine dissolved concentrations of metals. When a Teflon bailer is used, the contents are emptied into a pressure transfer vessel. A disposable 0.45-micron acrylic copolymer filter is threaded onto the transfer vessel at the discharge point and the vessel is sealed. The vessel is pressurized with a hand pump and the filtrate directed into appropriate containers. Each filter is used once and discarded.

When a bladder pump is used to collect samples for dissolved constituents, a sample is filtered through a disposable 0.450-micron acrylic copolymer filter attached directly to the pump effluent line with a pressure fitting. As the pump cycles, the effluent is pressured through the filter and directed into an appropriate container. Each filter is used once and discarded.

Sample Preservation and Handling

Procedures for handling and preserving samples are consistent with the guidelines referenced in the Introduction. Sample containers vary depending on the type of analysis required (e.g., volatile organics, hydrocarbons, or dissolved metals) and are nonreactive with a given chemical.

Sample Handling

Sample containers are labeled immediately after sample collection, and are kept on cold packs which are replaced daily until the containers are received at the laboratory. As a sample is collected, it is logged on the chain-of-custody record that accompanies samples to the laboratory.

Samples are transferred from the site to EMCON's laboratory by the sampling team. Laboratory personnel assign a different number to each sample container and the number is recorded on the chain-of-custody record and used to identify the sample on all subsequent internal chain-of-custody and analytical records. Within 24 hours of sample receipt, samples are routinely shipped from EMCON to laboratories performing the selected analyses. EMCON's laboratory manager ensures that the holding times for requested analyses are not exceeded.

Sample Documentation

The procedures for sample handling provide chain-of-custody control from collection through storage. Sample documentation includes the following:

- Field logbooks for documenting sampling activities in the field
- Labels for identifying individual samples
- Chain-of-custody records for documenting possession and transfer of samples
- Laboratory analysis requests for documenting analyses to be performed

Field Logbook

In the field, the sampler records the following information on the water sample field data sheet (Figure 4) for each sample:

Project number

- Client name
- Location
- Sampler's name
- Date and time
- Well accessibility and integrity
- Pertinent well data (e.g., casing diameter, depth to water, well depth)
- Calculated and actual purge volumes
- Purging equipment
- Sampling equipment
- Appearance of each sample (e.g., color, turbidity, sediment)
- Results of field analyses (temperature, pH, specific conductance)
- General comments

The field logbooks are signed by the sampler.

Labels

Sample labels contain the following information:

- Project number
- Sample number (i.e., well designation)
- Sampler's initials
- Date and time of collection
- Type of preservative used (if any)

Sampling and Analysis Chain-of-Custody Record

The sampling and analysis chain-of-custody record (Figure 1), initiated at the time of sampling, includes the well number, sample type, analytical request, date of sampling, the

name of the sampler, and other information deemed pertinent. The sampler signs his name and records the date and time on the record sheet when transferring the samples to another person. Custody transfers are recorded for every sample; for example, if samples are split and sent to more than one laboratory, a record sheet accompanies each sample. The number of custodians in the chain of possession is kept to a minimum. A copy of the sampling and analysis chain-of-custody-record is returned to EMCON with the analytical results.

Groundwater Sampling and Analysis Request

The Groundwater Sampling and Analysis Request or the purchase order that accompanies samples to the laboratory serves as official communication of the particular analysis(es) required for each sample and is evidence that the chain of custody is complete (Figure 5).

At a minimum, the groundwater sampling and analysis request includes the following:

- Date submitted
- Specific analytical parameters
- Well number
- Sample source

Analytical Methods

Samples collected as part of the proposed monitoring programs are analyzed by accepted analytical procedures. The following publications are the primary references:

- Methods for Chemical Analysis of Water and Wastes (EPA-600/4-79-020, revised March 1983)
- Methods for Organic Chemical Analysis of Municipal and Industrial Wastewater (EPA-600/4-82-057), July 1982)
- Test Methods for Evaluating Solid Wastes: Physical/Chemical Methods (EPA SW-846, 3rd edition, November 1986)
- Leaking Underground Fuel Tank (LUFT) Manual, State Water Resources Control Board, State of California Leaking Underground Fuel Tank Task Force, May 1988

The laboratories performing the analyses are certified by the Department of Health services (DHS) for hazardous waste testing.

Quality Control

Quality assurance measures confirm the integrity of field and laboratory data generated during the monitoring program. Procedures for assessing data quality are discussed in this section. Field and laboratory quality assurance data are evaluated in the technical reports.

Field Quality Assurance

Field quality assurance for each monitoring event includes the documentation of field instrument calibration and collection and analysis of trip blanks, field blanks, and duplicate samples. Split samples may also be included in the monitoring program.

Trip and Field Blanks

Trip and field blanks are used to detect contamination introduced through sampling procedures, external field conditions, sample transportation, container preparation, sample storage, and the analytical process.

Trip blanks are prepared at the same time and location as the sample containers for a given sampling event. Trip blanks accompany the containers to and from that event, but are never opened or exposed to the air. One trip blank for volatile organic parameters is typically included for each sampling event.

Field blanks are prepared in the same manner as trip blanks, but are exposed to the ambient atmosphere at a specific monitoring point during sample collection for the purpose of determining the influence of external field conditions on sample integrity. One field blank for volatile organic parameters is typically included for each day of sampling.

Duplicate Samples

Duplicate samples are collected so that field precision can be documented. For each sampling event, a specified percentage (typically 5 percent) of monitoring well samples is collected in duplicate. Where possible, field duplicates are collected at sampling points known or suspected to contain constituents of interest. Duplicates are packed and shipped blind to the laboratory to be analyzed with the samples from that particular event (i.e., duplicates have no special markings indicating that they are quality control samples).

Laboratory Quality Assurance

Laboratory quality assurance includes procedures required under the DHS Hazardous Waste Testing Program. For sites where Columbia Analytical Services conducts the chemical tests, its quality assurance procedures include the reporting of surrogate recoveries, matrix spike recoveries, and matrix spike duplicates (or duplicate) results.

Method blanks are analyzed daily for the purpose of assessing the effect of the laboratory environment on analytical results, and are performed for each constituent analyzed.

Samples to be analyzed for organic constituents contain surrogate spike compounds. Surrogate recoveries are used to determine whether analytical instruments are operating within limits. Surrogate recoveries are compared with control limits established and updated by the laboratory on the basis of its historical operation.

Matrix spikes are analyzed at a frequency of approximately 10 percent. Matrix spike results are evaluated to determine whether the sample matrix is interfering with the laboratory analysis, and provide a measure of the accuracy of the analytical data. Matrix spike recoveries are compared with control limits established and updated by the laboratory on the basis of its historical operation.

Laboratory duplicates are analyzed at a frequency of approximately 10 percent. Spike duplicate results are evaluated to determine the reproducibility (precision) of the analytical method. Reproducibility values are compared with control limits established and updated by the laboratory on the basis of its historical operation.

Laboratory QC data included with the analytical results are method blanks, surrogate spike recoveries (for organic parameters only), matrix spike recoveries, and matrix spike duplicates.

When other state-certified laboratories conduct the testing, each laboratory will follow its own internal QA/QC program.

APPENDIX C WASTE MANIFESTS



NON-HAZARD US SPECIAL WASTE & SBESTOS MANIFEST

If waste is asbestos waste, complete Sections I, II, III and IV. No. 822973 If waste is NOT asbestos waste, complete only Sections I, II and III GENERATOR (Generator completes all of Section I) MORE PROGRESS COMMAND _ b. Generating Location: 2155 - 1000 ON NO c. Address: d. Address: Laweth III 1516 - 3 1- 515 $\nabla \cdot (g)$ 1. Phone No.: If owner of the generating facility differs from the generator, provide: - Arts Ergebutz g. Owner's Name: _ h. Owner's Phone No.: TYPE BFI WASTE CODE DM - METAL DRUM DP - PLASTIC DRUM B - BAG Containers Non-tha, is four-1: 11. Description of Waste: BA - 6 MIL. PLASTIC BAG or WRAP T - TRUCK O - OTHER k. Quantity GENERATOR'S CERTIFICATION: I hereby certify that the above named material is not a hazardous waste as defined by 40 CFR Part 261 or any applicable state law, has been properly described, classified and packaged, and is in proper condition for transportation according to UNITS applicable regulations; AND, if the waste is a treatment residue of a previously restricted hazardous waste subject to the Land Disposal POUNDS Y - YARDS M3 - CUBIC METERS Y3 - CUBIC YARDS Restrictions, I certify and warrant that the waste has been treated in accordance with the requirements of 40 CFR Part 288 and is no longer a hazardous waste as defined by 40 CFR Pari 26101. Belin 11 of LU Produces OTHER ···spica brake Generator Authorized Agent Name Signature Shipment Date Section II TRANSPORTER (Generalor complete a-d; Trans TRANSPORTER I TRANSPORTER II Dillard Trucking, inh. Name: P 0 Box 216 b. Address: i. Address: Byron CA 91711 c. Driver Name/Title: j. Driver Name/Title: (510) 634-6573 PRINT/TYPE d Phone No.: e. Truck No.: k. Phone No.: . f. Vehicle License No./State: _ m. Vehicle License No./State: Acknowledgement of Receipt of Materials. Acknowledgement of Receipt of Materials. Oriver Signature Driver Signature Section III DESTINATION (Generator completes and destination sits completes and) BF1 Vasio Kd Landf [11] 117-617 a Site Name: c. Phone No.: 1001 Touth Assessor Physical Address: . . . ! man has a local d. Mailing Address: Giverages Committee Control] 7 e. Discrepancy Indication Space: _ I hereby certify that the above named material has been accepted and to the best of my knowledge the foregoing is true and accurate. JOB# 1606-19 Name of Authorized Agent Signature Plus 101-2001; Section IV ASBESTOS (Generator complete and 1.2) Operator completes (1) a Operator's Name: b. Operator's* Phone No.: c Operator's* Address: _ d. Special Handling Instructions and additional information: OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are class packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and government regulations. e. Operator's* Name & Title: Name and Address of Responsible Agency: 3. Friable; Non-friable; Both _ _ % friable _

TRANSPORTER RETAIN

Operator refers to the company which owns, leases, operates, controls, or supervises the facility being demolished or renovated, or the demolition or renovation operation, or both.



260-7208 5/93



NON-HAZARO US SPECIAL WASTE & SBESTOS MANIFEST

If waste is asbestos waste, complete Sections I, II, III and IV.

If waste is NOT asbestos waste, complete only Sections I. II and

No. 822974

| Section in Contract of the Con | ASSISTANCE OF THE SECTION I. II and III. |
|--|--|
| - A WILL PRODUCTS Company | |
| a Addition 2155 S. Rascom Aug. 640 mont. | b. Generating Location: Arr o Stat for = 6118 |
| Campbell, CA 95008 | d. Address: Tim Shatteri, Ave # 52nd |
| 15101 939-6945 | Cakland Cy |
| if owner of the generating facility differs from the generator, provide: | f. Phone No.: NOIC |
| g. Owner's Name: Atro Products | |
| | h. Owner's Phone No.: Alic As Tree; |
| I. BFI WASTE CODE (A) A (B) O (B) O (B) O (B) O (B) O (B) O (C) O | Containers DM - METAL DRUM DP - PLASTIC DRUM |
| Description of Waste. Non Hazardons Soil (TFlig) | k. Quantity Units No. TYPE BA - 6 MIL. PLASTIC BAG |
| | T - TRUCK O - OTHER |
| GENERATOR'S CERTIFICATION: I hereby certify that the above named material is or any applicable state law, has been properly described, classified and packaged, at applicable regulations; AND, if the waste is a treatment residue of a previously real Restrictions, I certify and warrant that the waste has been treated in accordance with a hazardous waste as defined by 40 CFR Part 261 On herhall of NKO Jessica Druke | not a hazardous waste as defined by 40 CFR Part 261 uNITS stricted hazardous waste subject to the law P P POUNDS |
| Generator Authorized Agent Name Signature | Shipment Date |
| Section II TRANSPORTER (George of | Omplete a d . E trapporter Broombarra Q |
| Olliand Touch for | TRANSPORTER II |
| P.O. D 040 | h. Name: |
| Byron. CA 94511 | i. Address: |
| | |
| c. Driver Name/Title: SEFRY WISE DIVER | j. Driver Name/Title: |
| d. Phone No.: 1310) 634-6850 e. Truck No.: 89/ | k. Phone No |
| | m. Vehicle License No./State: |
| Acknowledgement of Receipt of Materials. | Acknowledgement of Receipt of Materials. |
| 087795 | |
| Shipment Date DESTINATION General Country BEI VASCO Rd. (2) d6 (1) | Driver Signature Shipment Date |
| Site Name: 8FI Vasco Rd. Landfill | |
| Physical Addréss: 1001 North Vasco Road | . c. Phone No.: (510) 117-0491 |
| | d. Mailing Address: 4001 North Vasco Road |
| | (1) Livermore 24 91550 |
| Discrepancy Indication Space: | |
| I hereby certify that the above named material has been accepted and to the | ne best of my knowledge the foregoing is true and accurate. |
| | |
| Name of Authorized Agent Signature | J08# 1006-19 Receipt Date P0# 09-20314 |
| Clouds The State of the State o | |
| Operator's Name: | b. Operator's* Phone No.: |
| Operator's* Address: | b. Operators Friorie No.: |
| Special Handling Instructions and additional information: | |
| ERATOR'S CERTIFICATION: 1 | are fully and accurately described above by proper shipping name and are classified, |
| | ghway according to applicable international and government regulations. |
| Operator's* Name & Title: Print/Type | |
| Name and Address of Responsible Agency: | Operator's * Signature Date |
| Friable; Non-friable; Both % friable | %/nonfriable |
| Operator refers to the company which owns, leases, operates, controls, or supervises the f | Ecility heing demolished or secure |
| | comp computation or renovated, or the demolition or renovation operation, or both. |
| TRANSPORTER RETAIN | 260-7208 5/93 |
| TONOFOR HE JAIN | —————————————————————————————————————— |

HFI

NON-HAZARD US SPECIAL WASTE & SBESTOS MANIFEST

If waste is sabestos waste, complete Sections I, II, III and IV if waste is $\underline{\mathsf{NOT}}$ asbestos waste, complete only Sections I, II and III

No. 822975

| Section I. GENERATOR (Gen | erator completes all of Section I) |
|--|--|
| Generator Name: MO.C. Products Company | o. Generating Location: <u>At t. v. St. et t. a. ≠ 6138</u> |
| 9157 5 1 morne No. Oct. 8306 | d. Address: TISE SHALLINK No. 18 Tun |
| Campbell CA 95008 | Onk Laure 11 |
| Phone No.: (510: 939-6945 | Phone No : Relate |
| owner of the generating facility differs from the generator, provide. | |
| Owner's Name: Vinco Products h | Owner's Phone No.: |
| BFI WASTE CODE C A 1 9 5 0 6 1 6 9 7 | Containers DM - METAL DRUM DP - PLASTIC DRUM B - BAG |
| Description of Waste: Non Hazardous Soil (TPHg) | k. Quantity Units No. TYPE BA - 6 Mil. PLASTIC BAG or WRAP T - TRUCK O - OTHER |
| GENERATOR'S CERTIFICATION: I hereby certify that the above named material is or any applicable state law, has been properly described, classified and packaged, a applicable regulations; AND, if the waste is a treatment residue of a previously reflections, I certify and warrant that the waste has been treated in accordance with a hazardous waste as defined by 40 CFR Part 2810n Behin If of NRCO Josefin Drake. | ind is in proper condition for transportation according to stricted hazardous waste subject to the Land Disposal Y - YARDS Y - YARDS A DISPOSAL TO THE REQUIREMENTS OF THE PROPERTY OF THE PRO |
| Generator Authorized Agent Name Signature | Shipment Date |
| ction I THANSPORTER (Generator | complete a-d: Transporter II complete - g |
| TRANSPORTER I Dillard Trucking, Inc. | (|
| P.O. Box 218 | h. Name: |
| Byron, CA 94511 | i. Address: |
| | |
| Print Type | j. Driver Name/Title:PRINY/TYPE |
| Phone No.: (510) 634-6850 e. Truck No.: 99/ | k. Phone No.: I. Truck No.: |
| Pehicle License No./State: SP28081 | m Vehicle License No./State: |
| cknowledgement of Receipt of Materials. | Acknowledgement of Receipt of Materials. |
| OR 205 | Driver Signature Shipment Date |
| | poletes a-d destination site completes a-d y |
| BFI Vasco Rd. Landfill | _ c. Phone No.: (510) 417~0491 |
| 4001 North Vasco Road | 4001 North Lave but |
| Livermore, CA 91530 | Livermore CV 91750 |
| · · · · · · · · · · · · · · · · · · · | CITETAIN CO. S. |
| iscrepancy Indication Space: | |
| hereby certify that the above named material has been accepted and to | the best of my knowledge the foregoing is true and accurate. |
| • | JOB# 1006-19 |
| ume of Authorized Agent Signature | Receipt Date PO# 09-20314 |
| tion IV. ASBESTOS (Generator como | |
| perator's* Name: | _ b. Operator's* Phone No.: |
| perator's* Address: | |
| pecial Handling Instructions and additional information: | |
| RATOR'S CERTIFICATION: I hereby declare that the contents of this consignment | ent are fully and accurately described above by proper shipping name and are classified |
| ed, marked, and labeled, and are in all respects in proper condition for transport b | y highway according to applicable international and government regulations. |
| perator's* Name & Title: | Operator's * Signature Date |
| ame and Address | obasera e editorna |
| f Responsible Agency: | |
| Triable; Non-friable; Both % friable | % nonfriable |
| operator refere to the company which owns lessess spension controls or espension | the facility being demolished or renovated, or the demolition or renovation operation, or both |
| politics retain to the continuity militar entires takens, operation, continues of appointmen | _ |
| TRANSPORTER RETA | AIN 200-7208 5/9 |
| | |



NON-HAZARD-JUS SPECIAL WASTE & SBESTOS MANIFEST

If waste is asbestos waste, complete Sections I, II, III and IV.
If waste is NOT asbestos waste, complete only Sections I, II and III

No. 822976

| Section I. GENERATOR (G | Senerator completes all of Section I) |
|---|--|
| ARCO Products Comment | b. Generating Location: |
| 9155 S. Baccom Atte. Sto. #209 | "I st married No. 6 " Paul |
| Address: Drawboll CA 93003 | d. Address. |
| (P4 * 357 AD 18 | |
| | f. Phone No.: |
| owner of the generating facility differs from the generator, provide: Owner's Name: Area Products | 350 t 1 1 1 |
| Owner's Name: | h. Owner's Phone No.: |
| BFI WASTE CODE (A) 1 0 5 0 8 1 6 9 | Containers DM - METAL DRUM DP - PLASTIC DRUM B - BAG |
| Description of Weste: Non Hazardous Soll / TPHg | k. Quantity Units No. TYPE BA - 6 MIL. PLASTIC BAC |
| GENERATOR'S CERTIFICATION: I hereby certify that the above named material or any applicable state law, has been properly described, classified and packaged applicable regulations; AND, if the waste is a treatment residue of a previously Restrictions, I certify and warrant that the waste has been treated in accordance was hazardous waste as defined by 40 CFR Part 281.011 Behalf of ARCO Jessica Drake | It is not a hazardous waste as defined by 40 CFR Part 281 d, and is in proper condition for transportation according to restricted hazardous waste subject to the Land Disposal with the requirements of AC CFR Part 281 V - YARDS M1 CHESTERS |
| | |
| • | Shipment Date |
| ection II THANSPORTER Generals | |
| TRANSPORTER I Dillard Trucking, Inc | TRANSPORTER II |
| Name:P.C Nox 218 | h. Name: |
| Address: Byron, CA 94511 | i. Address: (1.41 |
| byton. Ch. 54.741 | |
| Oriver Name/Title: PRINT/TYPE | j. Oriver Name/Title: PRINT/TYPE |
| Phone No.: (510) 631-6850 PRINT/TYPE 6. Truck No.: 385 | k. Phene No.: t. Truck No.: |
| /ehicle License No./State: SCISSS | m. Vehicle License No./State: |
| Acknowledgement of Receipt of Materials. | Acknowledgement of Receipt of Materials. |
| Orner Signature Sphoment Date | 5] n |
| | Onver Signature Shipment Date |
| Site Name: BFI Vasco Rd Landfill | (510) 117-0191 |
| 4001 North Vasce Road | c. Phone No.: |
| Livernore CA 64550 | d. Mailing Address: |
| | |
| Discrepancy Indication Space: | |
| hereby certify that the above named material has been accepted and | to the best of my knowledge the foregoing is true and accurate. |
| سنو | / JOB# 1006-19 |
| ame of Authorized Agens Signifiture | Receipt Date PO# 09-20311 |
| ILONE NA | To the second |
| ··· | b. Operator's* Phone No.: |
| perator's * Address; | U. Operator's Priorie No.: |
| · · · · · · · · · · · · · · · · · · · | |
| Special Handling Instructions and additional information: | |
| ed, marked, and labeled, and are in all respects in proper condition for transport | iment are fully and accurately described above by proper shipping name and are classified t by highway according to applicable international and government regulations. |
| perator's Name & Title: Pant/Type | |
| | Operator's Signature Date |
| ame and Address Responsible Agency: | |
| Friable; Non-friable; Both % friable | % nonfriable |
| perator refers to the company which owns, leases, operates, controls, or supervise | es the facility being demolished or renovated, or the demolition or renovation operation, or both. |
| ار | * * * * * * * * * * * * * * * * * * * |
| TRANSPORTER RETA | AIN 200-720B 6 |



NON-HAZAR JUS SPECIAL WASTE & ASBESTOS MANIFEST

If waste is asbestos waste, complete Sections I, II, III and IV. If waste is $\underline{\mathsf{NOT}}$ asbestos waste, complete only Sections I, II and III.

No. 822983

| Section 1. GENERATOR (G | |
|---|--|
| - the O Frentisct's Commany | |
| Contention realities | . D. Generating Location: |
| Campbell CA 95008 | d. Address: 7400 shattury No. 2 2nd |
| 7 F 4 D 3 A 40 I F | |
| e. Phone No.: | f. Phone No.: North |
| a Conservation Area Products | h Owner's Chang No. 136' 13' |
| g. Cantol & Hamle. | h. Owner's Phone No.: |
| i. BFI WASTE CODE C A 4 6 5 0 6 1 6 9 5 | Containers DM - METAL DRUM DP - PLASTIC DRUM |
| Description of Waste. Non-Haza redones Sort I TPHy: | B - BAG k. Quantity Units No. TYPE BA - 6 MIL. PLASTIC BA |
| | T - TRUCK |
| GENERATOR'S CERTIFICATION: I hereby certify that the above named material if | |
| | |
| spplicable regulations; AND, If the waste is a treatment residue of a previously restrictions, I certify and warrant that the waste has been treated in accordance with a hazardous waste as defined by 10,000 per certification. | Y - YARDS |
| a hazardous waste as defined by 40 CFR Part 281(m. furbuill of J.K." | Presents O - OTHER |
| Generator Authorized Agent Name Signature | |
| Section II TRANSPORTER Generator | Shipment Date |
| TRANSPORTER I | Complete s-d; Transporter II complete har |
| Name: Dilierd Trucking, Inc | TRANSPORTER II |
| Address: P.O. Box 218 | h. Name: |
| Byron. CA 94511 | i. Address: |
| | _ |
| Phone No. (510) 631-6850 PRINT/TYPE | J, Driver Name/Title: |
| Phone No.: (510) 631-6850 e. Truck No.: 387 | k. Phone No.: I. Truck No.: |
| Vehicle License No./State: SPINGS | m. Vehicle License No./State: |
| Acknowledgement of Receipt of Materials. | Acknowledgement of Receipt of Materials. |
| Driver Signature Shipment Date | J n |
| ection III DESTINATION (Generator Que | Orbina Classonia |
| ART Vapos Del Tamérici | |
| 1001 Kouth Vanco fired | c. Phone No.: (510) 147-0491 |
| | d. Malling Address: 1901 North Vasco Road |
| Livermore CA 94550 | Livermore CA 94550 |
| Discrepancy Indication Space: | |
| I hereby certify that the above named material has been accepted and to | o the best of my knowledge the foregoing is true and accurate |
| مثنين | |
| Name of Authorized Agenti Signature | JOB# 1006-19 PO# 09-20311 |
| etion IVA | A Lacorby DEIB |
| | Market (1) Sperato (Memberae 4) |
| Operator's* Name: | b. Operator's* Phone No.: |
| Operator's Address: | |
| Special Handling instructions and additional information: | |
| ERATOR'S CERTIFICATION: I hereby declare that the contents of this consignmented, marked/fairith/abbited; and are in all respects in proper condition for transport by | ent are fully and accurately described above by proper shipping name and are classified to hipping name and are classified to the proper shipping name and are classif |
| population and analysis of | y manney according to applicable international and government regulations. |
| Operator's Name & Title: Print/Type | Operator's* Signature Date |
| Name and Address of Responsible Agency: | |
| · · · · · · · · · · · · · · · · · · · | |
| Friable: Non-friable: Both % friable | % nonfriable |
| Operator refers to the company which owns, leases, operates, controls, or supervises t | the facility being demolished or renovated, or the demolition or renovation operation, or both |
| | , and the controlled of renovation operation, or both |
| TRANSPORTED DETAIL | 260-720B 5/9 |



y law,

NON-HAZARL_US SPECIAL WASTE &_SBESTOS MANIFEST

If waste is asbestos waste, complete Sections I, II, III and IV. If waste is $\underline{\text{NOT}}$ asbestos waste, complete only Sections I, II and III.

No. 822984


| ection I. GENERATOR (Gene | |
|--|---|
| Generator Name: ARCO Products Company b. | Generating Location. |
| 2155 ' Basiling Ave. 54c #200 | Address: |
| Cample-11, CA 95008 | val Guid - 2V |
| Phone No.: (5101-039-6945 f. | Phone No.: |
| owner of the generating facility differs from the generator, provide: | |
| Owner's Name: Argo Products h. | . Owner's Phone No.: |
| BFI WASTE CODE | Containers DM - METAL DRUM DP - PLASTIC DRUM B - BAG |
| Description of Waste: Non-Hazardous Soli (TPHg) | A. Quantity Units No. TYPE BA - 6 MIL. PLASTIC BAG or WRAP T - TRUCK O - OTHER |
| GENERATOR'S CERTIFICATION: I hereby certify that the above named material is a confusion of any applicable state law, has been properly described, classified and packaged, an applicable regulations: AND, if the weste is a treatment residue of a previously residuations, I certify and warrant that the waste has been treated in accordance with a hazardous waste as defined by 40 CFR Part 261011 Behalf If ARCO Jessica Drake | nd is in proper condition for transportation according to stricted hazardous weste subject to the Land Disposal the requirements of 40 CFR Part 268 and is no longer Products Products Products Products |
| Generator Authorized Agent Name /Signature | Shipment Date |
| ction II TRANSPORTER (Generator o | |
| TRANSPORTER I Dillard Trucking Inc. | TRANSPORTER II |
| Name: P.C. Box 218 | h. Name: |
| Address: Byron. CA 94511 | i. Address: |
| Driver Name/Title: SAALO N. C. | j, Driver Name/Title: PRINT/TYPE |
| Phone No.: (510) 634-6850 PRINT/TYPE e. Truck No.: (1) | k. Phone No.: I. Truck No.: |
| Vehicle License No./State: 5P23085 | m. Vehicle License No./State: |
| Acknowledgement of Receipt of Materials. | Acknowledgement of Receipt of Materials. |
| "YeA Wall to Falabera | |
| Oriver Signature Shipment Date | n. Oriver Signature Shipment Date |
| | plants a - 1 specialistic (See Company n. s.) |
| | c. Phone No.: |
| Physical Address: 4001 North Vasco Road | d. Mailing Address: |
| Livermore CA 94550 | Litermore CA 01570 |
| Discrepancy Indication Space: | |
| hereby certify that the above named material has been accepted and to | the best of my knowledge the foregoing is true and accurate. |
| | JOB: 1006-19 |
| | PO# 09-2031-1 |
| lame of Authorized Agent Signature | Receipt Date |
| CONTRACTOR COMMENTS CONTRACTOR COMMENTS CONTRACTOR CONT | |
| Operator's* Name: | b. Operator's* Phone No.: |
| Operator's Address: | |
| Special Handling Instructions and additional Information: | |
| RATOR'S CERTIFICATION: I hereby declare that the contents of this consignmed, marked, and labeled, and are in all respects in proper condition for transport b | ent are fully and accurately described above by proper shipping name and are classified by highway according to applicable international and government regulations. |
| Operator's* Name & Title: | Operator's * Signature Date |
| Name and Address of Responsible Agency: | , |
| Friable; Non-frieble; Both % friable | • |
| Operator refers to the company which owns, leases, operates, controls, or supervises | the facility being demolished or renovated, or the demolition or renovation operation, or both |
| TOANGBORTER BETA | 1N |
| TRANSPORTER RETA | AIN |

APPENDIX D EXPLORATORY BORING LOGS AND WELL CONSTRUCTION DETAILS

| M | AJOR DIVISIONS | SYMBOLS | TYPICAL SOIL DESCRIPTIONS |
|-------------------------|--|---------|--|
| SOILS OO sieve size) | (More than 1/2 of coarse fraction) no. 4 sieve size) | GW | Well graded gravels or gravel—sand mixtures, little or no fines |
| | | GP | Poorly graded gravels or gravel-sand mixtures, little or no fines |
| | | GM GM | Silty gravers, gravel-sand-silt mixtures |
| RAINED soil 2 no. 2 | | GC | Clayey gravels, gravel-sand-clay mixtures |
| ဖြင့် | | SW 🧐 | Well graded sands or gravelly sands, little or no fines |
| COARSE than 1/2 | SANDS (More than 1/2 of coarse fraction (no. 4 sieve size) | SP | Poorly graded sands or gravelly sands, little or no fines |
| C (More 1 | | SM | Silty sands, sand-silt mixtures |
| | | sc | Clayey sands, sand-clay mixtures |
| FRAINED SOILS | SILTS & CLAYS | L X | Inorganic silts and very fine sands, rock flour, silty or clayey fine sands or clayey silts with slight plasticity |
| | <u>LL (50</u> | cL | Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays |
| | | OL | Organic silts and organic silty clays of low plasticity |
| | SILTS & CLAYS | МН | Inorganic sitts, micaceous or diatomaceous fine sandy or sitty soils, elastic sitts |
| | | СН | Inorganic clays of high plasticity, fat clays |
| | | он | Organic clays of medium to high plasticity, organic silty clays, organic silts |
| н | IGHLY ORGANIC SOILS | Pt | Peat and other highly organic soils |

CLASSIFICATION CHART (Unified Soil Classification System)

| CLASSIFICATION | RANGE OF G | RAIN SIZES |
|----------------------------------|--|--|
| | US Standard Sieve Size | Grain Size in Millimeters |
| BOULDERS | Above 12" | Above 305 |
| COBBLES | 12" to 3" | 305 to 76.2 |
| GRAVEL coarse fine | 3" to No 4 3" to 3/4" 3/4" to No. 4 | 76.2 to 4.76 76.2 to 19.1 19.1 to 4.76 |
| SAND coarse medium fine | No 4 to No. 200 No 4 to No 10 No 10 to No 40 No. 40 to No 200 | 476 to 2 00 2.00 to 0 420 |
| SILT & CLAY | Below No 200 | Below 0 074 |



PLASTICITY CHART

GRAIN SIZE CHART


METHOD OF SOIL CLASSIFICATION





EXPLANATION OF SYMBOLS ON EXPLORATORY BORING LOGS

Well Details Column



Sample Column

BAG/BULK SAMPLES

FIVE-FOOT SPLIT BARREL SAMPLER (CONTINUOUS SAMPLER)

MODIFIED CALIFORNIA SPLIT SPOON

OTHER SAMPLERS (SEE REMARKS FOR TYPE AND SIZE)

PITCHER BARREL

ROCK CORE (SEE REMARKS FOR TYPE AND SIZE)

SHELBY TUBE SAMPLER

STANDARD PENETRATION TEST SPLIT SPOON SAMPLER (2" OD)

(OVER)

EXPLANATION OF SYMBOLS ON EXPLORATORY BORING LOGS (CONTINUED)

Ground-Water Level Column

DEPTH TO FIRST OBSERVED GROUND WATER

DEPTH TO STABILIZED GROUND WATER

Miscellaneous

2.5 YR 6/2 Color as field checked to Munsell Soil Color Chart (1975 Edition)

PENETRATION Blows required to drive sampler 1 foot into soil.

Standard drive hammer weight: 140 pounds.


Standard drop: 30 inches



| PROJECT NUMBER 0805-135.04 | |
|--------------------------------------|--|
| PROJECT NAME ARCO 6148 | |
| LOCATION 5131 Shattuck Ave., Oakland | |
| WELL DEDMIT NO 05452 | |

BORING / WELL NO. AS-2
TOP OF CASING ELEV. 107.38
GROUND SURFACE ELEV. 107.89
DATUM M.S.L.

INSTALLATION DATE 7/31/95



EXPLORATORY BORING

a. Total depth 30.0 ft.
b. Diameter 8.0 in.

Drilling method Hollow Stem Auger

WELL CONSTRUCTION

Material____

<u>22.1</u> ft. c. Total casing length Material Schedule 40 PVC 2.0 in. d. Diameter 20.5 ft. e. Depth to top perforations 1.0 ft. f. Perforated length 21.5 ft. Perforated interval from ____20.5 to _ Perforation type_ Machine Slotted 0.020 inch Perforation size____ g. Surface seal 1.0 ft. Concrete Material_____ 15.0 ft. h. Backfill Cement Material 3.0 ft. i. Seal Bentonite Material_ j. Gravel pack 2.5 ft. Gravel pack interval from 19.5 to 22.0 ft. #3 Sand Material____ 7.0 ft. k. Bottom seal/fill

Bentonite



| PROJECT N | UMBER | 0805-135.04 | |
|------------|--------|-------------------|------|
| PROJECT NA | ME_AR | CO 6148 | |
| LOCATION | 5131 S | hattuck Ave., Oak | land |

BORING / WELL NO. __AS-3


TOP OF CASING ELEV. __107.89

GROUND SURFACE ELEV. __108.34

DATUM _____ M.S.L.

WELL PERMIT NO. 95453 DATUM_____

INSTALLATION DATE 8/2/95



EXPLORATORY BORING

Drilling method Hollow Stem Auger

WELL CONSTRUCTION

c. Total casing length 22.0 ft.

Material Schedule 40 PVC

d. Diameter 2.0 in.

e. Depth to top perforations 19.6 ft.

f. Perforated length 2.0 ft.

Perforated interval from 19.6 to 21.6 ft.

Perforation type ___Machine Slotted

Perforation size 0.020 inch

g. Surface seal <u>1.0</u> ft.

Material Concrete

h. Backfill 16.0 ft.

Material Cement

i. Seal <u>2.0</u> ft.

Material Bentonite

j. Gravel pack <u>3.5</u> ft.

Gravel pack interval from 19.0 to 22.5 ft.

Material #3 Sand

k. Bottom seal/fill 6.5 ft.

Material Bentonite



| PROJECT NUMBER 08 | 05-135.04 | |
|---------------------|-------------------|---|
| PROJECT NAME_ARCO | 6148 | |
| LOCATION 5131 Shatt | uck Ave., Oakland | |
| WELL PERMIT NO | 95453 | 1 |

BORING / WELL NO. __AS-4

TOP OF CASING ELEV. __106.81

GROUND SURFACE ELEV. __107.26

DATUM ______ M.S.L.

INSTALLATION DATE __8/2/95

-TOC (Top of casing) Water-tight vault box (Std.) d h а С

EXPLORATORY BORING

| a. Total depth | |
|-----------------|-------------------|
| b. Diameter | 8.0in. |
| Drilling method | Hollow Stem Auger |

WELL CONSTRUCTION


| C. | Total casing length | | 20.2 | IL. |
|----|----------------------|---------------------|------|-----|
| | Material | Schedule 40 P | vc | |
| d. | Diameter | | 2.0 | in. |
| e. | Depth to top perfora | ations | 25.6 | ft. |
| f. | Perforated length | | 2.0 | ft. |
| | Perforated interval | from <u>25.6</u> to | 27.6 | ft. |
| | Perforation type | | | |
| | Perforation size | | | |
| g. | Surface seal | | 1.0 | ft. |
| | Material | Concrete | | |
| h. | Backfill | | 22.0 | ft. |
| | Material | Cement | | |
| i. | | | 2.0 | ft. |
| | MaterialBento | onite | | |
| j. | Gravel pack | | 4.0 | ft. |
| • | Gravel pack interva | I from 25.0 to | 29.0 | ft. |
| | Material | | | |
| k, | | | na | ft. |
| | Material | | | |



| PROJECT NUMBER_ | 0805-135.04 |
|------------------|-----------------------|
| PROJECT NAME ARC | CO 6148 |
| LOCATION 5131 St | nattuck Ave., Oakland |

BORING / WELL NO. AS-5 TOP OF CASING ELEV. __ 106.24 GROUND SURFACE ELEV. 106.69 WELL PERMIT NO. 95453 DATUM DATUM M.S.L.

INSTALLATION DATE 8/2/95



EXPLORATORY BORING

29.0_{__ft.} a. Total depth 8.0 in. b. Diameter Drilling method Hollow Stem Auger

<u>27.0</u> ft.

WELL CONSTRUCTION

c. Total casing length

Material ____ Schedule 40 PVC 2.0 in. d. Diameter 24.6 ft. e. Depth to top perforations 2.0 ft. f. Perforated length Perforated interval from 24.6 to 26.6 ft. Machine Slotted Perforation type___ Perforation size 0.020 inch 1.0 ft. g. Surface seal Material ____ Concrete 21.0 ft. h. Backfill Cement Material___ 2.0 ft. i. Seal **Bentonite** Material j. Gravel pack 4.0 ft. Gravel pack interval from $\underline{24.0}$ to $\underline{28.0}$ ft. Material____ #3 Sand 1.0__ ft. k. Bottom seal/fill Material Native Slough



| PROJECT NUMB | ER 0805-135.04 | | | |
|------------------------|---------------------------|--|--|--|
| PROJECT NAME ARCO 6148 | | | | |
| LOCATION 51 | 31 Shattuck Ave., Oakland | | | |
| WELL PERMIT NO | 95453 | | | |

BORING / WELL NO. __VW-2

TOP OF CASING ELEV. __na

GROUND SURFACE ELEV. __na

DATUM _____ M.S.L.

INSTALLATION DATE __7/31/95

TOC (Top of casing) Water-tight vault box (Std.) d h а C

EXPLORATORY BORING

a. Total depth 26.5 ft.
b. Diameter 10.0 in.

Drilling method Hollow Stem Auger

WELL CONSTRUCTION

| C. | i otal casing length | | н. | | |
|----|----------------------------------|------|-------------|--|--|
| | Material Schedule 40 PVC | | | | |
| d. | Diameter | 4.0 | in. | | |
| e. | Depth to top perforations | 9.8 | ft. | | |
| f. | Perforated length | 14.0 | ft. | | |
| | Perforated interval from 9.8 to | 23.8 | ft. | | |
| | Perforation type Machine Slotte | | | | |
| | Perforation size 0.020 inch | | | | |
| a. | Surface seal | 1.0 | ft. | | |
| J | Material Concrete | | | | |
| h. | | 4.0 | ft. | | |
| | Material Cement | | | | |
| i. | Seal | 2.0 | ft. | | |
| | Material Bentonite | | | | |
| j. | | 17.0 | ft. | | |
| J. | Gravel pack interval from 8.0 to | | | | |
| | Material #3 Sand | | ••• | | |
| l. | | 1.5 | | | |
| k. | Bottom seal/fill | | ft. | | |
| | Material Native Slough | | | | |



| PROJECT NUMBER 0 | 805-135.04 | BORING / WI | ELL NOV | V-4 |
|--------------------|--------------------|-------------|--------------------|-----|
| PROJECT NAME ARCC | 6148 | TOP OF CAS | ING ELEV. <u>r</u> | na |
| LOCATION 5131 Shat | tuck Ave., Oakland | GROUND SU | RFACE ELEV. | na |
| WELL PERMIT NO | 95453 | DATUM | <u>м.S.L.</u> | |

TOC (Top of casing) Water-tight vault box (Std.) е ď h а С

EXPLORATORY BORING

26.5_{_ft.} a. Total depth 10.0 in. b. Diameter Hollow Stem Auger Drilling method _____

INSTALLATION DATE 8/1/95

WELL CONSTRUCTION


c. Total casing length _20.2__ft. Schedule 40 PVC Material____ 4.0 in. d. Diameter 10.0 ft. e. Depth to top perforations 9.2 f. Perforated length 19.2 ft. Perforated interval from 10.0 to Perforation type___ Machine Slotted Perforation size____ 0.020 inch 1.0 ft. g. Surface seal Material ____ 5.5 ft. h. Backfill Material Cement i. Seal 2.0 ft. **Bentonite** Material_ j. Gravel pack 12.5 ft. Gravel pack interval from 9.0 to 21.5 ft. #3 Sand Material_ 5.0 k. Bottom seal/fill Material___ Native Slough



PROJECT NUMBER 0805-135.04 BORING / WELL NO. VW-5 PROJECT NAME ARCO 6148 LOCATION 5131 Shattuck Ave., Oakland GROUND SURFACE ELEV. na

_____ TOP OF CASING ELEV. ___a WELL PERMIT NO. 95453 DATUM____ M.S.L.

INSTALLATION DATE 8/1/95



EXPLORATORY BORING

26.5 ft. a. Total depth 10.0 in. b. Diameter

Drilling method Hollow Stem Auger

WELL CONSTRUCTION

Material____

k. Bottom seal/fill

c. Total casing length <u>24.5</u> ft. Material Schedule 40 PVC 4.0 in. d. Diameter 10.0 ft. e. Depth to top perforations 14.0 ft. f. Perforated length Perforated interval from 10.0 to 24.0 ft. Machine Slotted Perforation type__ Perforation size 0.020 inch <u>1.0</u> ft. g. Surface seal Material Concrete 5.5 ft. h. Backfill Cement Material_ 2.0 ft. i. Seal **Bentonite** Material j. Gravel pack <u>16.5</u> ft. Gravel pack interval from 8.5 to 25.0 ft.

#3 Sand

Material____Native Slough

1.5 ft.




PROJECT NUMBER 0805-135.04 BORING / WELL NO. VW-6 PROJECT NAME ARCO 6148

WELL PERMIT NO. 95453 DATUM DATUM

_____ TOP OF CASING ELEV. ___107.76 LOCATION 5131 Shattuck Ave., Oakland GROUND SURFACE ELEV. 108.16 M.S.L.

INSTALLATION DATE 8/3/95



EXPLORATORY BORING

20.0 ft. a. Total depth 10.0 in. b. Diameter Drilling method Hollow Stem Auger

WELL CONSTRUCTION

c. Total casing length <u>19.5</u> ft. Material Schedule 40 PVC 4.0 in. d. Diameter 5.1 ft. e. Depth to top perforations 14.0 ft. f. Perforated length Perforated interval from 5.1 to 19.1 ft. Machine Slotted Perforation type___ Perforation size 0.020 inch g. Surface seal 0.5 ft. Concrete Material____ 2.0 ft. h. Backfill Cement Material____ 2.0 ft. i. Seal Bentonite Material j. Gravel pack ___4.5__ft. Gravel pack interval from 4.5 to 20.0 ft. Material_____#3 Sand k. Bottom seal/fill na ft.

Material____



PROJECT NUMBER 0805-135.04 BORING / WELL NO. VW-7 PROJECT NAME ARCO 6148 LOCATION 5131 Shattuck Ave., Oakland GROUND SURFACE ELEV. 107.96

_____ TOP OF CASING ELEV. 107.52 WELL PERMIT NO, 95453 DATUM DATUM M.S.L.

INSTALLATION DATE 8/3/95

-TOC (Top of casing) Water-tight vault box (Std.) е d h C а f

EXPLORATORY BORING

25.0 ft. a. Total depth 10.0 in. b. Diameter Drilling method Hollow Stem Auger

WELL CONSTRUCTION

c. Total casing length <u>23.9</u> ft. Material ____ Schedule 40 PVC 4.0 in. d. Diameter 9.1 ft. e. Depth to top perforations 14.0 ft. f. Perforated length Perforated interval from 9.1 to 23.1 ft. Perforation type Machine Slotted Perforation size 0.020 inch <u>1.0</u> ft. g. Surface seal Material ____ Concrete 4.5 ft. h. Backfill Material Cement 2.0 ft. i. Seal Bentonite Material___ j. Gravel pack ___<u>17.5</u>_ ft. Gravel pack interval from 7.5 to 25.0 ft. Material____ #3 Sand k. Bottom seal/fill 1.5 ft.


Material Native Slough



PROJECT NUMBER 0805-135.04 PROJECT NAME ARCO 6148 LOCATION 5131 Shattuck Ave., Oakland GROUND SURFACE ELEV. 107.91

BORING / WELL NO. VW-8 _____ TOP OF CASING ELEV. <u>107.43</u> WELL PERMIT NO. 95453 DATUM M.S.L.

INSTALLATION DATE 8/3/95



EXPLORATORY BORING

25.0_{_ft.} a. Total depth 10.0 in. b. Diameter Drilling method Hollow Stem Auger

WELL CONSTRUCTION

Material_____

c. Total casing length <u>24.7</u> ft. Material ____ Schedule 40 PVC 4.0 in. d. Diameter 9.8 ft. e. Depth to top perforations 14.0 ft. f. Perforated length Perforated interval from 9.8 to 23.8 ft. Machine Slotted Perforation type___ Perforation size 0.020 inch 1.0 ft. g. Surface seal Material____ Concrete 6.0 ft. h. Backfill Cement Material ____ 2.0_ ft. i. Seal **Bentonite** Material__ j. Gravel pack __14.0__ft. Gravel pack interval from $\underline{9.0}$ to $\underline{25.0}$ ft. Material #3 Sand 1.5 __ ft. k. Bottom seal/fill

Native Slough



PROJECT NUMBER 0805-135.04 _____ BORING / WELL NO. VW-9 PROJECT NAME ARCO 6148 LOCATION 5131 Shattuck Ave., Oakland GROUND SURFACE ELEV. 106.54

_____ TOP OF CASING ELEV. <u>106.18</u> WELL PERMIT NO. 95453 DATUM DATUM M.S.L. **INSTALLATION DATE** 8/1/95

-TOC (Top of casing) Water-tight vault box (Std.) е h С а

EXPLORATORY BORING

25.0 ft. a. Total depth 10.0 in. b. Diameter Drilling method Hollow Stem Auger

WELL CONSTRUCTION

c. Total casing length <u>24,4</u> ft. Material Schedule 40 PVC 4.0 in. d. Diameter 9.9 ft. e. Depth to top perforations 14.0 ft. f. Perforated length Perforated interval from 9.9 to 23.9 ft. Perforation type Machine Slotted Perforation size 0.020 inch 1.0 ft. g. Surface seal Material ____ Concrete 5.5 ft. h. Backfill Material Cement 2.0 ft. i. Seal Bentonite Material_ 17.0 ft. j. Gravel pack Gravel pack interval from 8.0 to 25.0 ft. Material #3 Sand 1.5 ft. k. Bottom seal/fill Material Native Slough


WELL DETAILS



PROJECT NUMBER 0805-135.04 BORING / WELL NO. VW-10 PROJECT NAME ARCO 6148 LOCATION 5131 Shattuck Ave., Oakland GROUND SURFACE ELEV. 107.18

TOP OF CASING ELEV. 106,73 WELL PERMIT NO. 95453 DATUM_____ M.S.L.

INSTALLATION DATE 8/1/95



EXPLORATORY BORING

25.0 ft. a. Total depth 10.0 in. b. Diameter Drilling method Hollow Stem Auger

WELL CONSTRUCTION

Material____

c. Total casing length <u>24.6</u> ft. Material _____ Schedule 40 PVC 4.0 in. d. Diameter 10.2 ft. e. Depth to top perforations 14.0 ft. f. Perforated length Perforated interval from 10.2 to 24.2 ft. Machine Slotted Perforation type_ Perforation size 0.020 inch 1.0 ft. g. Surface seal Material Concrete 6.0 ft. h. Backfill Material Cement 2.0 ft. i. Seal **Bentonite** Material___ i. Gravel pack 16.0 ft. Gravel pack interval from 9.0 to 25.0 ft. #3 Sand Material 1.5 ft. k. Bottom seal/fill

Native Slough

Form prepared by R. Davis

PROJECT NUMBER

0805-135.04

BORING NO.

AS-2

PROJECT NAME

Arco Station #6148

PAGE

1 OF 2

| BY | R.K.D. | | DATE | 7/31 | /95 | SURFACE ELEV. | 107.89 | ft. | |
|-------------------------|--------------------|---------------------------------------|---|---------|-----------------------------|--|--------|--|--|
| PID Reading (ppm) | Sample Recovery | Penetra- tion (Blows per 6") | GROUND WATER LEVELS DEPTH IN FT | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WE DET | LL |
| | | | | | | ASPHALT. SANDY GRAVEL (GP), Aggregate roadbase. | | मानुस्तिक्षानित्रातिक्षातित्रातिक्षाति क्ष | |
| 0.0 | 9/18 | 16 23 29 | 5, | | | SANDY SILT (ML), mottled light olive brown (2.5Y, 5/4) and dark grayish brown (2.5Y, 3/2); 80-85% low-plasticity fines; 15-20% fine-grained sand; hard; damp; no hydrocarbon odor. | | ម្នាក់ក្រុមក្រុមក្រុមក្រុមក្រុមក្រុមក្រុមក្រុម | <u>សមានម្នៃផ្នែកក្រាមស្នាធាចេញសមាស្នាសាស្តាស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្តាស់ស្រាស</u> |
| 0.0 | 14/18 | 21 27 33 | | | | @10 to 11.5': As above; 65% low-plasticity fines; 20-25% fine-grained sand; 10-15% fine to coarse gravel. | | վերվեկմինյեկյանկորհիրներյանը մերաներ | |
| 12.0 | 16/18 | 16 16 19 | - - - - - - 7/31/95 | | | SILTY GRAVEL (GM), dark brown (10YR, 3/3); 30% low-plasticity fines; 50% fine to coarse-grained sand; 20% fine to coarse gravel (to 2" dia.); dense; moist (wet in fractures); hydrocarbon odor. | | ինի ինքորկիրներ | <u> Կիլիկիիիիի</u> |
| 45.0 | 16/18 | 26 30 40 | - \frac{}{} | | | CLAYEY GRAVEL (GC), as above; 30-35% medium-plasticity fines; hydrocarbon odor. | | | |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 20.5 to 21.5 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. AS-2 **PROJECT NAME** Arco Station #6148 **PAGE** 2 OF 2 BY R.K.D. DATE 7/31/95 SURFACE ELEV. 107.89 ft. PID Sample Penetra-GROUND WATER LEVELS DEPTH IN FT. LITHO-Reading Recovery tion WELL GRAPHIC DESCRIPTION (Blows DETAIL COLUMN (mgg) (in./in.) per 6") 0/18 23 CLAYEY GRAVEL (GC), continued. 27 33 18 SILTY CLAY (CL), yellowish brown (10YR, 5/4); 18/18 14 90-95% low to medium-plasticity fines; 5-10% 20 fine to coarse-grained sand; trace fine gravel; 30 stiff; moist; no hydrocarbon odor. CLAYEY SAND (SC), light olive brown (2.5Y, 5/4); 30% medium-plasticity fines; 40% fine to 14/18 35 coarse-grained sand; 30% fine to coarse gravel (to 50/5" 1" dia.); coarse sand and gravel clasts are subangular to angular; medium dense; wet; no hydrocarbon odor. CLAYEY GRAVEL (GC), light olive brown (2.5Y, 10/18 6 5/4); 10-30% medium-plasticity fines; 30% fine 20 to coarse-grained sand; 40% fine to coarse gravel; 20 dense; wet; no hydrocarbon odor. BORING TERMINATED AT 29 FEET BGS.



REMARK

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 20.5 to 21.5 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

AS-3

PROJECT NAME

Arco Station #6148

PAGE

1 OF 2

| BY | R.K.D. | | DAT | E 8 | /2/9 | 95 | SURFACE ELEV. 108.34 | ft. |
|-------------------------|---------------------------------|---|--|-----------------|------|-----------------------------|--|---|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND MATER LEVELS | DEPTH IN FT. | ١٣ | LITHO- GRAPHIC COLUMN | DESCRIPTION | WELL |
| |] | | | | _] | | _ ASPHALT. | |
| | | | | - | | | SANDY GRAVEL (GP), Aggregate roadbase. | Taitifal w |
| 0.0 | 18/18 | 7 10 13 7 9 14 | | 5 | | | CLAYEY SILT (ML), very dark grayish brown (10YR, 3/2); 85-90% low to medium-plasticity fines; 10-15% fine to coarse-grained sand; very stiff; damp; no hydrocarbon odor. @10': As above. | របស់ក្នុងក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្ សេខសេសសាសកម្មស្ថិតសម្រេសសាសកម្មការស្រាស់ក្នុងស្រាស់ក្នុងស្រាស់ក្នុងសាសកម្មការសេសក្នុងស្រាស់ក្នុងសាសកម្មការស្រ |
| 53.0 65.0 71.0 | 18/18 18/18 | 11 23 27 6 10 10 6 6 | - - - - - - - - - - - - | 15 | | | CLAYEY GRAVEL to CLAYEY SAND (GC-SC), 30% medium-plasticity fines; 30-40% fine to coarse-grained sand; 30-40% fine to coarse gravel (to 1.5" dia.); very dense; damp; hydrocarbon odor. SILTY CLAY (CL), mottled dark gray (2.5Y, 4/0) and light olive brown (2.5Y, 5/0); 90-95% low to medium-plasticity fines; 5-10% fine-grained sand; very stiff; moist (wet at 18'); hydrocarbon odor. | निर्मात्रमानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर्मानिर |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 19.6 to 21.6 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

AS-3

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

| BY | R.K.D. | | DATI | E 8 | /2/9 | 95 | SURFACE ELEV. | 108.34 | ft. |
|-------------------------|--------------------|---------------------------------------|---------------------------|-----------------|------|-----------------------------|---|--------|------|
| PID Reading (ppm) | Sample Recovery | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WELL |
| | 18/18 | 5 10 11 | - | | | | CLAYEY SAND (SC), yellowish brown (10YR, 5/4); 30% medium-plasticity fines; 70% fine to coarse-grained sand; medium dense; wet; no | | |
| | 24/24 | 12 4 4 9 6 | - - - - | - | | | hydrocarbon odor. SANDY CLAY (CL), yellowish brown (10YR, 5/4); 65% low to medium-plasticity fines; 35% fine to coarse-grained sand; medium dense; moist to wet; no hydrocarbon odor. | | |
| 0.0 | 18/18 | 8 13 17 | | 25- | | | SILT to SANDY SILT (ML), light yellowish brown (10YR, 5/4); 80-90% low to medium-plasticity fines; 10-20% fine to coarse-grained sand; very stiff; moist; no hydrocarbon odor. | | |
| | 18/18 | 12 12 23 | - | | | | CLAYEY GRAVEL (GC), yellowish brown (10YR, 5/4); 20-30% medium-plasticity fines; 20-30% fine to coarse-grained sand; 50% fine to coarse gravel (to 2" dia.), subangular; dense; wet; no hydrocarbon odor. | | |
| | | | - | 30- | _ | | BORING TERMINATED AT 29 FEET BGS. | | |
| | | | - | - | | | | | |
| | | | - - - | 35— | | | | | |
| | | i | - | - | | | | | |
| | | | - - | 40- | | | | | |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 19.6 to 21.6 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

AS-4

PROJECT NAME

Arco Station #6148

PAGE

E 1 OF 2

BY R.K.D.

DATE 8/2/95

SURFACE ELEV.

107.26 ft

| БІ | K.K.D. | | DAII | | 8121 | כעי | SURFACE ELEV. | 107.26 f | t. | |
|-------------------------|---------------------------------|---------------------------------------|--|-----------------|---------|-----------------------------|---|----------|--------------------------|----------|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | | | ELL |
| 0.0 | 13/18 | 5 6 7 | | 5- | | | SANDY CLAY (CL), dark grayish brown (10YR, 3/2); 60% medium-plasticity fines; 15-30% fine to coarse-grained sand. SILTY SAND (SM), dark brown (10YR, 3/3); 20-25% low-plasticity fines; 75-80% fine to coarse-grained sand; medium dense; damp; no hydrocarbon odor. | | | |
| 0.0 | 13/18 | 5 4 7 | | 10- | | | @10 to 10.8': As above; 10% fine to coarse gravel. CLAYEY SAND (SC), dark brown (10YR, 3/3); 30-40% medium-plasticity fines; 55-60% fine to coarse-grained sand; 5% fine gravel; firm; damp; | | | <u> </u> |
| 85.0 | 16/18 | 12 14 19 | - - - - | | | | no hydrocarbon odor. @12.5': mottled dark gray (2.5Y, 4/0) and light olive brown (2.5Y, 5/4); 25-30% medium-plasticity fines; 50% fine to coarse-grained sand; 20-25% fine to coarse gravel, subangular to angular; | | յույթյալիների արևանին ար | |
| 56.0 | 5/18 | 7 9 13 | | 15- | | | medium dense to dense; moist; no hydrocarbon odor. CLAYEY SAND to CLAYEY GRAVEL (SC-GC), light olive brown (2.5Y, 5/4) to dark grayish | | _ | |
| 11.0 | 8/18 | 10 20 20 | - \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ | 20- | | | brown (10YR, 3/2); 25% medium-plasticity fines; 35-40% fine to coarse-grained sand; 35-40% fine to coarse gravel; dense; moist to wet (water visible in pockets and fractures beginning at 16.5'); hydrocarbon odor. | / | | |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 25.6 to 27.6 feet bgs. Groundwater was encountered at 17.5 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

R.K.D.

0805-135.04

PROJECT NAME

BY

Arco Station #6148

DATE 8/2/95

BORING NO.

AS-4

PAGE

2 OF 2

SURFACE ELEV.

107.26 ft.

| | | | DAIL | 012193 | SURFACE ELEV. 107 | .26 ft. |
|-------------------------|---------------------------------|---------------------------------------|------------------------------------|---|---|---|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND WATER LEVELS DEPTH | SAMPLES COLL COLL COLL COLL | HIC DESCRIPTION | WELL |
| 0.0 | 17/18 | 11 13 17 | | | From 20 to 23.5': Interbedded, 30% SANDY SILT (ML) and 70% SILTY SAND (SM). SANDY SILT (ML), light yellowish brown (10YR, 5/4); 75-85% low to medium-plasticity fines; 15-25% fine-grained sand; trace fine gravel; stiff; wet; no hydrocarbon odor. | तिस्तर्भाताम् विद्यात्तरम् । स्तानस्य विद्यात्तरम् |
| •- | 14/18 | 7 9 9 11 12 | - - - 25 | | SILTY SAND (SM), yellowish brown (10YR, 5/4); 15-30% low-plasticity fines; 70-80% fine to coarse-grained sand; medium dense to dense; wet; no hydrocarbon odor. CLAYEY SAND (SC), light olive brown (2.5Y, 5/4); 30% medium-plasticity fines; 40% fine to | |
| | 12/18 | 12 14 18 | - - - - - | | coarse-grained sand; 30% fine to coarse gravel (to 1" dia.), subangular to angular clasts; medium dense; wet; no hydrocarbon odor. CLAYEY GRAVEL (GC), light olive brown (2.5Y, 5/4); 30% medium-plasticity fines; 30% fine to coarse-grained sand; 40% fine to coarse gravel; | |
| | | | - 30 - - - | | dense; wet; no hydrocarbon odor. BORING TERMINATED AT 29 FEET BGS. | _/ |
| | | | - - - - - 35 | | | |
| | | - | | | | |
| | | | 40 | | | |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 25.6 to 27.6 feet bgs. Groundwater was encountered at 17.5 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of thus log.

| | | |] | LO(| GΟ | F E | XPLORATORY BORING | | |
|-------------------------|--------------------|---------------------------------------|---------------------------|-----------------|-------|-------|--|--|-----|
| PRO | DJECT NU | IMBER | 0805 | -135. | 04 | | BORING NO. AS-5 | | |
| PRO | JECT NA | ME | Arco | Stati | on #6 | 5148 | PAGE 1 OF 2 | 2 | |
| BY | R.K.D. | | DAT | E . | 8/2/9 | 5 | SURFACE ELEV. 106.69 | ft. | |
| PID Reading (ppm) | Sample Recovery | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | 취임 | ITHO- | DESCRIPTION | | ELL |
| | | | | | | | ASPHALT. | <u>니</u> [편 | |
| 9 9 | | | - | | | | SANDY GRAVEL (GP), Aggregate roadbase. | क् भागवानातानाम्यात्राक्षात्रात्रात्रात्रात्रात्रात्रात्रात्र | |
| 0.0 | 8/18 | 13 6 8 | - | 3 — | | | FILL: Wood, brick and concrete fragments. SANDY CLAY (CL), dark brown (10YR, 3/3); 60% | સંપનુપોલામાં મુંગાના મુખ્યા માથે મુખ્ય માથે મુખ્યા મુખ્યા મુખ્યા મુખ્ય મુખ્ય મુખ્ય મુખ્ય મુખ્ય મુખ્ય મુખ્ય મુખ | |
| 0.0 | 15/18 | 8 8 15 | - - - | 10- | | | medium-plasticity fines; 30-35% fine to coarse-grained sand; 5-10% fine to coarse gravel (to 1.5" dia.); very stiff; damp; no hydrocarbon odor. | <u> </u> | |
| 125.0 | 5/18 | 10 20 22 | - - | | | | CLAYEY GRAVEL (GC), dark olive gray (5Y, 3/2); 25% medium-plasticity fines; 35-40% fine to coarse-grained sand; 35-40% fine to coarse gravel; medium dense; moist; hydrocarbon odor. | | |
| 58.0 | 6/18 | 12 15 15 | - - . 8/2/95 | 15 | | | @15': As above. | յորդերիկիիների | |
| 0.0 | 14/18 | 6 9 13 | · 🕎 | - | | | @17': Wet. CLAYEY SAND (SC), yellowish brown (10YR, 5/4); 15-25% medium-plasticity fines; 60% fine to coarse-grained sand; 15-25% fine to coarse gravel; medium dense; moist; no hydrocarbon odor. | ગુપાના મુખ્યાના તાલુકાના માના માત્રા માત્ર | |
| | DE | MARKS | | <u> 20 —</u> | - /// | III. | | 13. | =1_ |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 24.6 to 26.6 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

AS-5

PROJECT NAME

Arco Station #6148

PAGE

AGE 2 OF 2

BY R.K.D.

DATE 8/2/95

SURFACE ELEV.

106.69 ft

| БІ | K.K.D. | • | DAT | E 8/. | 2/95 | SURFACE ELEV. | 106.69 | ft. |
|-------------------------|--------------------|---------------------------------------|---------------------------|-----------------|-----------------------------|--|--------|----------------|
| PID Reading (ppm) | Sample Recovery | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WELL DETAIL |
| 0.0 | 12/18 | 6 11 | - | | | CLAYEY SAND (SC), continued. | | |
| | 18/18 | 7 12 11 | - - - - | - | | CLAYEY GRAVEL (GC), yellowish brown (10YR, 5/4); 20-30% medium-plasticity fines; 20-30% fine to coarse-grained sand; 50% fine to coarse gravel; dense; wet; no hydrocarbon odor. | | |
| | 18/18 | 20 20 23 | - | 25 | | @25': As above. | | |
| | 18/18 | 6 12 21 | - - | - | | @28': As above. | | |
| | | | | 30 | | BORING TERMINATED AT 29 FEET BGS. | | |



REMARKS

Boring drilled to a depth of 29 feet below grade surface (bgs) by West Hazmat using 8" dia. hollow-stem augers. Samples collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 2" dia. PVC air sparge well screened from 24.6 to 26.6 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

AS/VW-2

PROJECT NAME

Arco Station #6148

PAGE

1 OF 2

BY R.DAVIS

DATE 7/31/95

SURFACE ELEV.

NA ft.

| B1 | K.DA V | | DAIL | · //- | 91193 | SURFACE ELEV. | NA ft. | |
|-------------------------|--------------------|---------------------------------------|---------------------------------|--------|-----------------------------|---|--------|---------------|
| PID Reading (ppm) | Sample Recovery | Penetra- tion (Blows per 6") | GROUND HATER LEVELS | IN FT. | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WELL DETAI |
| | | | | 5- | | Well(s) drilled out to 28 fbg using a 12" dia. hollow-stem auger drill rig. The boring was backfilled with neat cement through augers, and capped at the surface with concrete. | | |
| | | | - - - - - - - | 10 — | | | | |
| | | | - - - - - - | | | | | |



REMARKS

Boring/well drilled out to 28 feet below grade surface (bgs) by West Hazmat using 12" dia. hollow-stem augers. No samples were collected for this boring. Backfilled to surface with neat cement through augers and capped with concrete. No groundwater was encountered. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

AS/VW-2

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

| BY | R.DAV | IS | DAT | E 7 | 7/31 | 1/95 | SURFACE ELEV. | NA ft. | |
|-------------------------|---------------------------------|--------|---------------------------|-----------------|---------|-----------------------------|-----------------------------------|--------|----------------|
| PID Reading (ppm) | Sample Recovery (in./in.) | (Blows | GROUND WATER LEVELS | DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WELL DETAIL |
| | | | | 35- | | | BORING TERMINATED AT 28 FEET BGS. | | |



REMARKS

Boring/well drilled out to 28 feet below grade surface (bgs) by West Hazmat using 12" dia. hollow-stem augets. No samples were collected for this boring. Backfilled to surface with neat cement through augers and capped with concrete. No groundwater was encountered. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

VW-2

PROJECT NAME

Arco Station #6148

PAGE

GE 1 OF 2

BY R.K.D.

DATE 7/31/95

SURFACE ELEV.

NA ft

| BY | R.K.D. | | DAT | E | 113. | 1/95 | SURFACE ELEV. NA ft. | |
|-------------------------|---------------------------------|---------------------------------------|--|------------------|---------|-----------------------------|--|---|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | WELL DETAII |
| | | | <u> </u> | | | | ASPHALT. | # + |
| | | | | - | | | FILL: SANDY GRAVEL (GP) to SANDY SILT (ML), occassional brick fragments; damp; no hydrocarbon odor. | निर्मानित्तिक विद्यानितित्ति । जिल्लामितितिति । जिल्लामिति । जिल्लामिति । जिल्लामिति । जिल्लामिति । जिल्लामित |
| 0.0 | 14/18 | 7 11 29 | | 5 | | | SANDY SILT (ML), dark olive gray (5Y, 3/2); 50% non to low-plasticity fines; 30% fine to coarse-grained sand; 20% fine to coarse gravel (to 1" dia.); damp; no hydrocarbon odor. | |
| 0.0 | 16/18 | 15 20 27 | - | 10- | | | @10': As above. | |
| 21.0 | 17/18 | 18 20 25 | - - - - ¥ - - - - - - | 5 ¹⁵⁻ | | | SILTY SAND (SM), dark brown (10YR, 3/3); 30% low-plasticity fines; 50% fine to coarse-grained sand; 20% fine to coarse gravel (to 2" dia.); dense; moist (wet in fractures); hydrocarbon odor. @15.5 to 16.5': mottled dark gray (2.5Y, 4/0) and light olive brown (2.5Y, 5/4). | |



REMARKS

Boring drilled to 26.5 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples were collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.8 to 23.8 feet bgs. Groundwater was encountered at 16 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-2 PROJECT NAME Arco Station #6148 **PAGE** 2 OF 2 R.K.D. DATE 7/31/95 SURFACE ELEV. NA ft. PID Sample Penetra-GROUND WATER LEVELS SAMPLES LITHO-DEPTH IN FT. WELL Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN per 6") (mqq) (in./in.) 0.0 17/18 12 SILTY SAND (SM), continued. 35.0 23 SILT (ML), light yellowish brown (10YR, 6/4); non 32 to low-plasticity fines; trace fine-grained sand; very stiff; wet; no hydrocarbon odor. SILTY GRAVEL (GM), yellowish brown (10YR, 5/4); 25-30% low-plasticity fines; 20% fine to coarse-grained sand; 50-55% fine to coarse gravel (to 1.5" dia.); very dense; wet; hydrocarbon odor. @25': As above; medium dense; hydrocarbon odor. 7 16/18 11 15 BORING TERMINATED AT 26.5 FEET BGS.



REMARKS

Boring drilled to 26.5 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples were collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.8 to 23.8 feet bgs. Groundwater was encountered at 16 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-4 PROJECT NAME Arco Station #6148 PAGE 1 OF 2 7/31/95 BY R.K.D. DATE SURFACE ELEV. NA ft. PID Sample Penetra-GROUND MATER LEVELS LITHO-DEPTH IN FT. WELL Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN per 6") (ppm) (in./in.) ASPHALT. FILL: Aggregate roadbase. CLAYEY SILT (ML), very dark grayish brown 0.0 18/18 17 (10YR, 3/2); 85-90% low to medium-plasticity 19 fines; very stiff; damp; no hydrocarbon odor. 24 @10': As above. 10-0.0 17/18 12 CLAYEY SAND (SC), yellowish brown (10YR, 5/6); 15 20-30% low to medium-plasticity fines; 60-70% 23 fine to coarse-grained sand; 10% fine gravel; dense; damp; no hydrocarbon odor. @15': As above; mottled dark gray (2.5Y, 4/0) and 0.0 10/12 26 light olive brown (2.5Y, 5/4); moist; no 50/4" hydrocarbon odor. 7/31/95 ∇ @17': Wet. 0.0 14/18 21 19 25

See the second s



REMARKS

Boring drilled to 26.5 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 10 to 19.2 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

VW-4

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

BY R.K.D.

DATE

7/31/95

SURFACE ELEV.

NA ft.

| | | | | | | SURFACE ELEV. NA ft. | • |
|-------------------------|---------------------------------|---------------------------------------|---------------------------|----------------------------|-----------------------------|---|--|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | WELL DETAIL |
| | 12/18 | 10 15 15 15 | - 3 - 3 3 | 25 | | CLAYEY SAND (SC), continued. CLAYEY SILT (ML), light yellowish brown (10YR, 6/4); 90-95% low to medium-plasticity fines; 5-10% fine-grained sand; stiff; wet; no hydrocarbon odor. CLAYEY GRAVEL (GC), yellowish brown (10YR, 5/4); 20-30% medium-plasticity fines; 30-35% fine to coarse-grained sand; 35-40% fine to coarse gravel; medium dense; wet; no hydrocarbon odor. @25': As above. BORING TERMINATED AT 26.5 FEET BGS. | الله في الله والله و الله والله وال |



REMARKS

Boring drilled to 26.5 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 10 to 19.2 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-5 PROJECT NAME Arco Station #6148 **PAGE** 1 OF 2 BY R.K.D. DATE 8/1/95 SURFACE ELEV. NA ft. PID Sample Penetra-GROUND WATER LEVELS LITHO-SAMPLES DEPTH IN FT. Reading WELL Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN per 6") (ppm) (in./in.) ASPHALT. FILL: SILTY to SANDY GRAVEL (GM), dark brown; aggregate base material. 0.5 16/18 10 21 24 SANDY SILT (ML), dark brown (7.5YR, 3/2); 60-65% low to medium-plasticity fines; 30% fine to coarse-grained sand; 5-10% fine to coarse gravel; very stiff; damp; no hydrocarbon odor. @10': As above. 0.8 14/18 7 11 12 SANDY CLAY (CL), dark olive gray (5Y, 3/2); 60-65% medium-plasticity fines; 25% fine to coarse-grained sand; 10-15% fine to coarse gravel 15 91.0 18/18 15 (to 1" dia.); very stiff; moist; hydrocarbon odor. 16 CLAYEY SAND (SC), yellowish brown (10YR, 5/4); 54.0 21 8/1/95 20-30% medium-plasticity fines; 60% fine to ∇ coarse-grained sand; 10-20% fine gravel; dense; moist; hydrocarbon odor.



REMARKS

Boring drilled to 26.5 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples were collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 10 to 24 feet gbs. Groundwater was encountered at 16.9 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

VW-5

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

BY R.K.D.

DATE 8/1/95

SURFACE ELEV.

NA ft.

| | | | | | | SORFACE ELEV. NA ft. | |
|-------------------------|---------------------------------|---------------------------------------|--|---------|-----------------------------|--|--|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND WATER LEVELS DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | WELL DETAIL |
| 38.0 2.1 | 9/18 | 7 11 11 6 12 18 | 25 | | | SANDY CLAY (CL), dark olive gray (5Y, 3/2); 60-70% medium-plasticity fines; 30-40% fine to coarse-grained sand; stiff; wet; hydrocarbon odor. CLAYEY GRAVEL (GC), yellowish brown (10YR, 5/4); 20% medium-plasticity fines; 30% fine to coarse-grained sand; 50% fine to coarse gravel (to 1.5" dia.); medium dense; wet; no hydrocarbon odor. CLAYEY SAND (SC), yellowish brown (10YR, 5/4); 20-30% medium-plasticity fines; 60% fine to coarse-grained sand; 10-20% fine gravel; dense; moist; no hydrocarbon odor. SANDY SILT (ML), yellowish brown (10YR, 5/4); 85% low-plasticity fines; 15% fine-grained sand; very stiff; wet; no hydrocarbon odor. CLAYEY GRAVEL (GC), yellowish brown (10YR, 5/4); 20% medium-plasticity fines; 30% fine to coarse-grained sand; 50% fine to coarse gravel (to 1.5: dia.); medium dense; wet; no hydrocarbon odor. BORING TERMINATED AT 26.5 FEET BGS. | 18 19 18 19 18 19 18 19 18 19 18 18 18 18 18 18 18 18 18 18 18 18 18 |
| | | | 40- | | | | L |



REMARKS

Boring drilled to 26.5 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples were collected using a 2" dia. modified- California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 10 to 24 feet gbs. Groundwater was encountered at 16.9 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-6 PROJECT NAME Arco Station #6148 PAGE | 1 OF 1 R.K.D. DATE 8/3/95 SURFACE ELEV. 108.16 ft. DIG Sample Penetra-GROUND WATER LEVELS SAMPLES LITHO-DEPTH IN FT. WELL Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN per 6") (ppm) (in./in.) CONCRETE. SANDY GRAVEL (GP), aggregate roadbase; very dense. @4.5': Hydrocarbon odors observed during hand augering. 540 16/18 SILTY SAND (SM), olive gray (5Y, 4/2); 30-40% 13 low-plasticity fines; 60-70% fine to 18 medium-grained sand; dense; moist; hydrocarbon 825 14/18 5 @7.5': As above; trace fine gravel; medium dense; moist; hydrocarbon odor. 8 12 GRAVEL (GP), mottled olive gray (5Y, 4/2) and 10 145 10/18 10 light olive brown (2.5Y, 5/4); 10% low to 12 medium-plasticity fines; 30% fine to 18 coarse-grained sand; 60% fine to coarse gravel, subangular, weathered, fractured; medium dense; damp; hydrocarbon odor. CLAYEY GRAVEL (GC), mottled olive brown (5Y, 300 9/12 29 4/4); and light olive brown (2.5Y, 5/4); 20-25% 50/5" medium-plasticity fines; 30-35% fine to coarse-grained sand; 45% fine to coarse gravel (to 2" dia.); very dense; moist; hydrocarbon odor. 150 5/18 21 @19': As above. 25 BORING TERMINATED AT 20 FEET BGS. 33



REMARKS

Boring drilled to 20 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 5.1 to 19.1 feet bgs. No groundwater was encountered. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING 0805-135.04 PROJECT NUMBER BORING NO. VW-7 PROJECT NAME Arco Station #6148 **PAGE** 1 OF 2 R.K.D. DATE 8/3/95 SURFACE ELEV. 107,96 ft. PID Sample Penetra-GROUND MATER LEVELS LITHO-DEPTH IN FT. WELL Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN (ppm) (in./in.) per 6") ASPHALT. FILL: SANDY GRAVEL (GP). SANDY SILT (ML), dark yellowish brown (10YR, 4/4); 60-70% low-plasticity fines; 30-40% fine-grained sand; stiff; damp; no hydrocarbon 0.0 17/18 5 odor. 13 SILTY SAND (SM), dark yellowish brown (10YR, 4/4); 30-35% low-plasticity fines; 65-70% fine-grained sand; medium dense; damp; no hydrocarbon odor. CLAYEY GRAVEL (GC), dark brown (10YR, 3/3); 0.0 16/18 13 15% medium-plasticity fines; 30% fine to 15 coarse-grained sand; 55% fine to coarse gravel (to 17 2" dia.); dense; damp; no hydrocarbon odor. @12.5': As above; mottled dark grayish brown and 21 16/18 6 light olive brown; 25% medium-plasticity fines; 10 35% fine to coarse-grained sand; 40% fine to 10 coarse gravel; medium dense; moist; hydrocarbon 15 11/18 7 odor. 19 15 11 37 11/18 11 16 21 125 13/18 6 @17.5': Wet in voids and fractures. 7 @18': No hydrocarbon odor. 13 8/3/95 又 CLAYEY SAND (SC), described on next page.



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.1 to 23.1 feet bgs. Groundwater was encountered at 19 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

VW-7

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

BY R.K.D.

DATE 8/3/95

SURFACE ELEV.

107.96 ft.

| D1 | K.K.D. | | DAI. | | 16 16 | <i></i> | SURFACE ELEV, | 107.961 | t. |
|-------------------------|---------------------------------|---------------------------------------|---------------------------|-----------------|---------|-----------------------------|---|---------|--|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WELL DETAIL |
| 0.0 | 17/18 | 5 11 7 5 9 | | 25- | | | CLAYEY SAND (SC), dark yellowish brown (10YR, 4/4); 30-40% low to medium-plasticity fines; 60-70% fine to medium-grained sand; trace coarse sand; trace fine gravel; iron oxide staining; medium dense; wet; no hydrocarbon odor. CLAYEY GRAVEL (GC), dark brown (10YR, 3/3); 15% medium-plasticity fines; 40% fine to coarse-grained sand; 45% fine to coarse gravel; | | ار والا و بنا او بنا او بنا و بنا و بنا او بنا و بنا الله و بنا ال إن ادبارة المراد المراد المراد المراد المراد المراد الله و الله و الله و الله و الله و الله و المراد المراد ال إن ارداد المراد الم |
| | | | | 35- | | | medium dense; wet; no hydrocarbon odor. BORING TERMINATED AT 25 FBG. SAMPLED TO A DEPTH OF 26,5 FEET BGS. | | 7 |



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.1 to 23.1 feet bgs. Groundwater was encountered at 19 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-8 PROJECT NAME Arco Station #6148 **PAGE** 1 OF 2 SURFACE ELEV. R.K.D. DATE 8/1/95 107,91 ft. PID Sample Penetra-LITHO-DEPTH IN FT. WELL Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN per 6") (ppm) (in./in.) ASPHALT. FILL: SANDY GRAVEL (GP), aggregate roadbase. CLAYEY SILT (ML), very dark grayish brown (10YR, 3/2); 85% low to medium-plasticity fines; 10% fine to coarse-grained sand; 5% fine gravel: 0.0 15/18 7 very stiff; damp; no hydrocarbon odor. 11 SILTY SAND (SM), dark yellowish brown (10YR, 18 3/4); 35% nonplastic fines; 65% fine-grained sand; medium dense; damp; no hydrocarbon odor. CLAYEY GRAVEL (GC), dark brown (10YR, 3/3): 0.0 16/18 20-30% medium-plasticity fines; 20% fine to 12 coarse-grained sand; 50-60% fine to coarse 17 gravel, subangular; occasionally well weathered; medium dense; moist; no hydrocarbon odor. CLAYEY SAND to CLAYEY GRAVEL (SC-GC), 33 15/18 13 mottled light olive brown (2.5Y, 5/4) and dark 8/1/95 17 olive gray (5Y, 3/2); 20-30% medium-plasticity 19 ∇ fines; 30-40% fine to coarse-grained sand; 30-40% fine to coarse gravel, subangular to angular; fractured; dense; wet; hydrocarbon odor. CLAYEY SAND (SC), described on next page.



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.8 to 23.8 feet bgs. Groundwater was encountered at 16.5 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

VW-8

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

BY R.K.D.

DATE 8/1/95

SURFACE ELEV.

107.91 ft.

| BY | R.K.D. | | DATI | 브 (| 3/1/ | 795 | SURFACE ELEV. 1 | 107.91 f | it. |
|-------------------------|--------------------|---------------------------------------|---------------------------|-----------------|---------|-----------------------------|--|----------|---|
| PID Reading (ppm) | Sample Recovery | Penetra- tion (Blows per 6") | GROUND WATER LEVELS | DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | | WELL DETAIL |
| | 14/18 | 7 6 7 | - | - | | | CLAYEY SAND (SC), light olive brown (2.5Y, 5/4); 20-25% medium-plasticity fines; 45-50% fine to coarse-grained sand; 25-30% fine to coarse gravel; medium dense; wet; no hydrocarbon odor. | | |
| | 11/18 | 7 7 7 | | 25- | | | CLAYEY GRAVEL (GC), light olive brown (2.5Y, 5/4); 20% medium-plasticity fines; 25-30% fine to coarse-grained sand; 50-55% fine to coarse gravel; medium dense; wet; no hydrocarbon odor. | | الم المواجعة المواجع |
| | | | - - - | _ | | | BORING TERMINATED AT 25 FBG. SAMPLED TO A DEPTH OF 26.5 FEET BGS. | | |
| | | | - - - | 30- | | | | | |
| | | | - - | _ | | | | | |
| | | | | 35- | | | | | |
| | | | - | 40- | | | | | |



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.8 to 23.8 feet bgs. Groundwater was encountered at 16.5 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-9 PROJECT NAME Arco Station #6148 PAGE 1 OF 2 1 R.K.D. DATE 8/1/95 SURFACE ELEV. 106.54 ft. Sample PID Penetra-GROUND WATER LEVELS SAMPLES LITHO-DEPTH IN FT. WELL Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN (ppm) (in./in.) per 6") ASPHALT. FILL: SANDY GRAVEL (GP), aggregate roadbase. SANDY CLAY (CL), dark yellowish brown (10YR, 4/4); 60% medium-plasticity fines; 30-35% fine to coarse-grained sand; 5-10% fine to coarse gravel (to 1.5" dia.); very stiff; damp; no hydrocarbon odor. 2.8 14/18 б 11 SAND (SP), dark yellowish brown (10YR, 4/4); 14 5-10% medium-plasticity fines; 90-95% fine to coarse-grained sand; trace fine gravel (to 1" dia.); medium dense; damp; no hydrocarbon odor. 10 CLAYEY SAND (SC), yellowish brown (10YR, 5/4); 2.6 16/18 9 15-25% medium-plasticity fines; 60% fine to 9 coarse-grained sand; 15-25% fine to coarse gravel (to 1" dia.); medium dense; moist; no hydrocarbon odor. CLAYEY GRAVEL to CLAYEY SAND (GC-SC), 301 12/18 10 dark olive gray (5Y, 3/2); 25% medium-plasticity 8/1/95 12 fines; 35-40% fine to coarse-grained sand; 14 ∇ 35-40% fine to coarse gravel; medium dense; very moist; hydrocarbon odor. CLAYEY SAND (SC), described on next page.



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.9 to 23.9 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

PROJECT NUMBER

0805-135.04

BORING NO.

VW-9

PROJECT NAME

Arco Station #6148

PAGE

2 OF 2

PKD

8/1/05

STIDEACE EL EV

| BY | R.K.D. | | DATI | 3 1 | 3/1/ | 95 | SURFACE ELEV. 106.54 | ft. |
|-------------------------|---------------------------------|---------------------------------------|---------------------------|-----------------|---------|-----------------------------|---|--|
| PID Reading (ppm) | Sample Recovery (in./in.) | Penetra- tion (Blows per 6") | GROUND MATER LEVELS | DEPTH IN FT. | SAMPLES | LITHO- GRAPHIC COLUMN | DESCRIPTION | WELL |
| 2.0 | 18/18 | 15 15 21 | - | _ | | | CLAYEY SAND (SC), yellowish brown (10YR, 5/4); 20-30% medium-plasticity fines; 60% fine to coarse-grained sand; 10-20% fine gravel; dense; wet; hydrocarbon odor. | |
| 2.1 | 18/18 | 14 18 23 | - - - | 25- | | | CLAYEY GRAVEL (GC), yellowish brown (10YR, 5/4); 20-30% medium-plasticity fines; 20-30% fine to coarse-grained sand; 50% fine to coarse gravel (to 1.5" dia.); dense; wet; no hydrocarbon odor. | ا ويار بريا ، وياه و يا بريا راي ايار في ايار في دار يا دار الم |
| | | | - - - - | _ | | | BORING TERMINATED AT 25 FBG. SAMPLED TO A DEPTH OF 26.5 FEET BGS. | |
| <u>.</u> : | | | - - - - | 30- | | | | |
| | | | - - - | - | | | | |
| | | | - - - | 35- | | | • | |
| | | | - | _ | | | | |
| | | | <u> </u> | 40- | _ | | | <u></u> |



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 9.9 to 23.9 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-10 PROJECT NAME Arco Station #6148 **PAGE** 1 OF 2 R.K.D. DATE |8/1/95 BY SURFACE ELEV. 107.18 ft. Sample PIO Penetra-GROUND WATER LEVELS LITHO-WELL DEPTH IN FT. Reading Recovery tion GRAPHIC DESCRIPTION DETAIL (Blows COLUMN (ppm) (in./in.) per 6") ASPHALT. FILL: SANDY GRAVEL (GP), aggregate roadbase. SANDY SILT (ML), dark yellowish brown (10YR, 0.0 10/18 7 4/4); 60-65% non to low-plasticity fines; 35-40% 7 fine-grained sand; stiff; damp; no hydrocarbon 11 odor. @10': yellowish brown (10YR, 5/4); hard; slightly 0.0 12/18 damp; no hydrocarbon odor. 10 21 @15': As above. 15-85 14/18 12 14 CLAYEY GRAVEL (GC), 15% low-plasticity fines; 8/1/95 18 30% fine to coarse-grained sand; 55% fine gravel; damp; no hydrocarbon odor. $\overline{\Delta}$ **SAND (SP)**, very dark gray (10YR, 3/1); 5-10% nonplastic fines; 90-95% fine to coarse-grained sand; dense; wet; hydrocarbon odor. CLAYEY GRAVEL (GC), described on next page.



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 10.2 to 24.2 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

LOG OF EXPLORATORY BORING PROJECT NUMBER 0805-135.04 BORING NO. VW-10 PROJECT NAME Arco Station #6148 PAGE 2 OF 2 BY R.K.D. DATE 8/1/95 SURFACE ELEV. 107.18 ft. PID Sample Penetra-GROUND WATER LEVELS SAMPLES LITHO-DEPTH IN FT. Reading Recovery tion WELL GRAPHIC DESCRIPTION DETAIL (Blows COLUMN per 6") (ppm) (in./in.) 0.0 14/18 6 CLAYEY GRAVEL (GC), 20-25% low-plasticity 9 fines; 20% fine to coarse-grained sand; 55-60% 11 fine to coarse gravel (to 2" dia.); medium dense; wet; no hydrocarbon odor. SANDY CLAY (CL). @25': As above. 14/18 8 10 BORING TERINATED AT 25 FBG. SAMPLED TO A DEPTH OF 26.5 FEET BGS.



REMARKS

Boring drilled to 25 feet below grade surface (bgs) by West Hazmat using 10" dia. hollow-stem augers. Samples collected using a 2" dia. modified-California split-spoon sampler. Boring completed as a 4" dia. PVC vapor extraction well screened from 10.2 to 24.2 feet bgs. Groundwater was encountered at 17 feet bgs. See explanation sheet for definition of symbols used in well detail and sample columns of this log.

APPENDIX E FIELD DATA SHEETS

EMCON - Groundwater Sampling and Analysis Request Form

PROJECT NAME: ARCO 6148

5131 Shattuck Ave., Oakland

EMCON Project #: 0805-135.0# (UOZ)

DATE REQUESTED: 07-Aug-95

Project Manager: John Young

| | Groundwater Monitoring Instructions | Treatment System Instructions |
|--|---|-----------------------------------|
| Develop w centrifugal settleable last three i Friday, Au | Request- Well Development and Sampling wells as usual using a surge block, bailer, and I pump if desired. Continue development until solids and turbidity are at a minimum and the readings are stable. Wells are to be sampled ugust 11th. You will need to bring the water trailer water transport. | No treatment system at this site. |
| | 's on the C-O-C and the sample bottles must include at which the sample was collected [i.e. MW-1 (30)] | Mark Adler Pager # (408) 932-6574 |

Site Contact: Balaji Angle Site Phone: (510) 654-3461 Well Locks: Dolphin

| Well ID or Source | Casing Diameter (inches) | Casing Length (feet) | Floating Product (feet) | Analyses Requested |
|----------------------|--------------------------------|----------------------------|-------------------------------|-------------------------|
| AS-2 | 2.0 | 22.0 | ND | |
| AS-3 | 2.0 | 22.5 | ND | Depth To Water |
| AS-4 | 2.0 | 28.5 | NÞ | Develop TPH-Gas/BTEX |
| AS-5 | 2.0 | 27.0 | ND | |
| | | | † ; | |
| | | | , | |
| | | | | |
| | | • | | |
| | | | | |
| | | | | |
| aboratory l | nstructions | | | |

Laboratory Instructions:

Provide lowest detection limits possible.

ND = None Detected IP = Intermitent Product

FIELD REPORT DEPTH TO WATER/FLOATING PRODUCT SURVEY

| | PROJECT # : 0805-135.04 (002)STATION ADDRESS : 5131 Shattuck Ave., Oakland | | | | | | | | | nd | DATE:_ | 8-11-95 |
|---------------|--|---------------------|-----------------------|--------|----------|------------------------|--------------------------------------|---------------------------------------|---|--|----------------------------------|----------|
| AF | CO STAT | ION#: | 6148 | | FI | | | 5 U | 1,111AN | 25 | DAY:_ | HI |
| DTW Order | WELL | Well Box Seal | Well Lid Secure | Gasket | Lock | Locking Well Cap | FIRST DEPTH TO WATER (feet) | SECOND DEPTH TO WATER (feet) | DEPTH TO FLOATING PRODUCT (feet) | FLOATING PRODUCT THICKNESS (feet) | WELL TOTAL DEPTH (feet) | COMMENTS |
| 1 | AS-2 | OK | YES | OC | D | 6K | 17.46 | 17.46 | W | NO | 22.2 | |
| 2 | AS-3 | OK | YES | 01 | 0 | DIC | 19.30 | 19.30 | OM | W | 22.3 | |
| 3 | | | 4ES | | | OK | 16.51 | 16.51 | WO | NO | 28.0 | |
| 4 | AS-5 | OK. | 453 | OK | 0 | OK | 16,52 | 1652 | ND | Nn | 26.8 | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | <u> </u> | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | ļ <u>.</u> | | | | | <u></u> | | | | | |
| | | <u> </u> | | | | | | | | | | |
| <u>.</u> | | <u> </u> | | | <u> </u> | | | | | | | |
| - | | | | | ļ | | | | | | | |
| | | <u> </u> | | | | | | | | | | |
| | | | <u> </u> | | <u></u> | <u> </u> | | | | | | |
| | SURVEY POINTS ARE TOP OF WELL CASINGS NORTH SIDE | | | | | | | | | | | |

| | | | | | | | FIELD DA | TA SHEET | | |
|-------------|-----------------|-------------|-------------------------|----------------|------------------------------|---------------------------------------|--|--|-------------|---------------|
| | | | Project Num | ber: <u>08</u> | 05-135. | 04/002 | Performe | d By: DE/M | 16 | |
| | | , | Client: | PISLU | 6148 md, cp | | | 8/7/95 | | |
| | Cas | | | | _ 3 inch _ | | | A5-Z | | |
| | | | | | _ 3 inch _ 17,47 | | 4.5 inch End/6 | | Other | |
| | | | | | 2.15 | | End $\frac{70}{22}$ | | | |
| | | | | | .76 | | | Purged (gal): | 14.0 | |
| | | | | , | | _ | | ruigeu (gai) | <u> </u> | |
| | | Centrifug | ısi Pump | - ✓ Ra | | | METHOD | | | |
| | | _ | ible Pump | | iler (Tetlon (iler (PVC) | | | • | | |
| | | _ | wie i anage | | iler (Fvo) | | Otner | | <u></u> | |
| | . | | | | FIELD | INSTRUI | MENTS | | | |
| 1 | 之, | pH, EC, T | emp. Meter | 之 NTI | J Meter _ | Limhof | Cone 🛨 C | olorimeter Otl | her | |
| | | | | | RCO Tombe | | | | 101 | |
| | w. 5 | 1 | Isposai wen | noa: | TUC TOWN | T | | | | |
| Da | ate | Time | Cumulative Discharge | Temp. | E.C. @ 25° C | рH | Turbidity Visual NTU | Color Visual Cobalt | Odor | Settleabl |
| | | | (gal) | (° F) | (μmho/cm) | (Stnd) | Heavy Scale = Moderate 0 - 200 or Light 0 - 1000 | Clear Scale = Cloudy 0 to 500 Yellow | | Solids (%) |
| <u>a</u> | 1/45 | 1326 | 2.0 | 7/5 | 737 | 100 | Trace // | Brown | | |
| 3 | //// | | | 1/5 | | 6.99 | /ten 7200 | Brown 7500 | None | 40% |
| <u>u</u> , | / | 1336 | 5.0 | 760 | 760 | 6.48 | 1 ′ | | | 10% |
| <u>3/</u> | 7 | 1348 | 10,0 | 748 | 482 | 6.46 | | | | 20% |
| 8/ | 7 | 1353 | 12.0 | 74.4 | 480 | 6.46 | | | | 20/ |
| 8/ | 1 | | 14,0 | 74.5 | 481 | | | | 4 | |
| <u>D1</u> | / | 100. | 1 46 | 17.~ | (01 | 6.51 | <u> </u> | Ψ | | 20/ |
| | | | · . | | | | | İ | | |
| | | } | 1 | - | | | | | | |
| | | | | | | | | | | |
| | | | | | | | <u> </u> | | | · <u> </u> |
| | | EGRITY: | | - 5 | | | | LOCK# | /phn | |
| ₹EM# | ARKS | : | Swabbell of | 01 10 | ww brin | to box | and | | | *··· |
| | | | | <u> </u> | - | · · · · · · · · · · · · · · · · · · · | | | | |
| | | | | | · | | | · · · · · · · · · · · · · · · · · · · | | |
| | | | | | | | | | | |
| IGN | ATUF | RE: | 15- | Sh | | REVIEV | VED BY: | Page | 1 _ | , 4 |

.

| l | | | WI | ELL DE | EVELOP | MENT | FIELD | DAT | A SI | HEET | | |
|-----|----------------|-----------------|----------------------|-----------------|------------------------------|---------------------------------------|--------------------------------|------------------------------|---------------------------|--|-------------|----------------------|
| | | ţ | Project Numb | oer: <u>080</u> | 5-/3 <i>5</i> - | 04 | P | | | M.G. | | · |
| | | , | Client: | RIOH (| 0148 | | Date: 8-7-85 Well ID: A S-3 | | | | | |
| - 1 | Cas | L MeiO Diama | ocation: <u>/_/</u> | inch | - CA | | W | /ell ID: | AS | <u>- 3</u> | | |
| | Der | oth to Wate | eter:2 er (feet): | Start Î | .sincn _ SIS | 4 inch | | 1.5 inch 21. | | î inch | Other | |
| | | | pth (feet): | | - | | | 27 | | | | |
| | | | olume at Sta | | | | | | | (gal): | 7,0 | |
| | | | | | スの(DEVELO | OPMENT | | | Ū | | | |
| | | Centrifug | al Pump | A Bail | ler (Teflon | | | | vok (Su | rah) | | |
| | | Submersi | ble Pump | | ler (PVC) | -, | | ther | | | | |
| | | | | | | | | | | | | |
| | / | =a = | | . 1 | FIELD | INSTRU | MENTS | | | | | |
| | | | emp. Meter | | | | f Cone | ≥∠ c | olorimet | er Oth | ner | |
| L | Purge | Water D | isposal Meth | od: <u>+</u> | railer | | | | | | | |
| | Date | Time | Cumulative | Temp. | EC | ni I | Tur | bidity | C | olor | 1 | T |
| | | | Discharge (gal) | (° F) | E.C. @ 25° C (μπho/cm) | pH | Visual Heavy Moderate | NTU Scale = 0 - 200 or | Visual Clear Cloudy | Cobatt Scale = 0 to 500 | Odor | Settleable Solids |
| | // | | (3) | , | (µmilo/cm) | (Stnd) | Light Trace | 0 - 1000 | Yellow Brown | 1 | | (%) |
| 1 | 7/55 | 1339 | 1.0 | 74.8 | /37/ | 6.98 | Heave | 7200 | BEN | 7500 | 00.26 | 90% |
| |) | 1344 | 210 | 743 | 1176 | 7,12 | 1/ | 41 | 1 | 1/ | 11 | 80% |
| 9/ | 8/55 | 1044 | 3.0 | 73.2 | 1028 | 6,97 | | | | | | 5% |
| | | 1120 | 4.0 | 70,7 | 954 | 4.79 | | | | : | | 3% |
| | | 1148 | 510 | 70.0 | 827 | 6,74 | 1/ | | | 1 | | 10/ |
| | | 1208 | 6.0 | 70,9 | 835 | 6.78 | 11 | 11 | \$271 | | | _ |
| | | | _ 1 | | | | 1 | 1, | | | | 1 /3 |
| | 71 | 1230 | 1.0 | 71,2 | 832 | 6,80 | | | 44- | (1) | <u>U/</u> | 1% |
| | | | | | | | | | | | | |
| | | EGRITY: | _600 | | | | | | LC | CK#: _ | MALPA | 6 in |
| REI | MARKS | i: | tll u | 197 | Suabbe | 1 2 | is pu | in_ | pri | <u>: </u> | 10 1 | 20:5:0 |
| | | | | | | · · · · · · · · · · · · · · · · · · · | | ····· | | | | |
| | | | | | | | | | | | | |
| | , - | | 10: | 11 11 | | | | | | | | - |
| SIG | NATU | RE:,7/ | V1/k | <u> </u> | | REVIEV | VED BY | 34 | | Page _ | Z_ 。 | ı 4_) |

| 1 | | | | | | | FIELD DAT | TA SHEET | | |
|---------------------------|-------------|-------------|--|-------------------------|--|-------------|--|------------------------------------|--|----------------------|
| - 1 | | | Project Numb | oer: <u>080</u> | 5-135.0 | 4(002) | Dorformo | d Ву: | 11.6 | |
| | | | Client: | | | <u> </u> | | 8/7/95 | <i>r</i> 1. 6-3 | |
| - 1 | | | ocation: O | | | | Date: Well ID: | 1. 1. | | |
| | Cas | | eter: X 2 | | | | | 7 | | |
| - 1 | Dep | oth to Wat | er (feet): | Start | 16.61 | 4 NICH | End | | Other | |
| | | | pth (feet): | | | | End2 | | | |
| | | | olume at Sta | | | | | Purged (gal): _e |).5 | |
| - | | - | | ··· (a-y | | | | Purgeu (gai): <u>"e</u> | <u>~</u> | |
| | ! | | | | | | METHOD | | | |
| | | Centritug | al Pump | Bai | ler (Teflon 0 | B) | ✓ Surge Bk | ock (Swab) | | |
| | | Submers | ible Pump | A Bai | ler (PVC) | | Other | | | |
| | | | | | | | | | | |
| 1 | X | 5U 50 T | ' *** -* | ٠ | HELD | INSTRUI | MENTS | | | |
| | | | | | _ | | f Cone <u>大</u> C | olorimeter Oth | ner | |
| | Purg | e Water D | isposal Meth | od: | ARCO | Tonk | | | | |
| $\int_{-\infty}^{\infty}$ | Date | Time | Cumulativa | 1 | | | Turbidity | Color | | |
| 1 | Jale | 1 11116 | Cumulative Discharge | | E.C. @ 25° C | pН | Visual NTU Heavy Scale = | Visual Cobalt | Odor | Settleable Solids |
| | 1 | | (gal) | (° F) | (μmho/cm) | (Stnd) | Moderate 0 - 200 or Light 0 - 1000 Trace | Cloudy 0 to 500 Yellow Brown | | (%) |
| 8 | 17/95 | 1233 | 2.5 | 76.2 | 607 | 6,61 | Hay 7200 | | None | 40% |
| 8/ | 7/45 | 1243 | 10,0 | 76.3 | 470 | 6.44 | Hlay 7200 | Boun 500 | None | 10% |
| 8/ | 7/95 | 1256 | 20,0 | 75.8 | 485 | 639 | | | | <5% |
| d)- | 7/95 | 1302 | 27.5 | 749 | 478 | ノって | | | | |
| 4 | 7 12 | <u> </u> | 7001 | <u> </u> | | ردد ري | | | 1 | 25% |
| 8/ | 7/45 | 1307 | 25,0 | 74.8 | 475 | 6.31 | V | V | 4 | Z50/ |
| • | ' | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | 1 | | | | |
| WE | l INIT | EGRITY : | | · | 1050 | L | | | O(1/2) | |
| | MARKS | 2. | Sumbbed | for 2: | <u>L'Oba</u> | - C + D | | LOCK#: <u>#</u> | JEIJOH. | <u>n</u> |
| | VIPACII (C | · | Control of the contro | -(27 + - ~ 3 | 2 min | War in h | 3/15 | | | |
| | - | | | | ************************************** | | | | | |
| | <u></u> | | ······································ | | | | · · · · · · · · · · · · · · · · · · · | | · . | |
| | | | | | | | | | | |
| SIG | NATU | RE: | 5- 560 | <u>ر</u> د | | REVIE | WED BY: 5 /1 | Page | 3 | 4 |

| | | | | | | | TA SHEET | | |
|--------------|---------------|----------------------------------|----------------|------------------------------|--------------|---|--|---------------|----------------------------|
| | (L | Client: .ocation; | ARCO Oaklar | nd, CA | | Date: Well ID: | A5-5 | Delm / | vy. 6- |
| Cas | sing Diame | eter: 🔷 2 | inch | _ 3 inch _ | 4 inch | 4.5 inch | 1 6 inch | Other_ | |
| Dep | oth to Wate | er (feet): | Start | 1.88 | | End | <u>, 83</u> | | |
| | | | | 26.90 | | End 26: | | 7 5 | • |
| Otte |) Casing v | olume at St | art (gal): | 1.47 | <u></u> | Total Volume | Purged (gal): | 110 | |
| | _ | | | _ | | METHOD | | | |
| 1 | Centrifug | • | | | | Surge Bl | lock (Swab) | | |
| - | Submersi | ible Pump | —∑Ba | iler (PVC) | | Other | | | |
| $ $ \times | ~U EC T | ' Motor | × | FIELD | INSTRU | MENTS | | | |
| | | | | | | ff Cone 💢 C | Colorimeter Ot | her | |
| Purg | ∍ Water D | isposal Meth | nod: | ALCO | Tank | | | | <u> </u> |
| Date | Time | Cumulative Discharge (gal) | Temp. | E.C. @ 25° C (μmho/cm) | pH (Stnd) | Turbidity Visual NTU Heavy Stale = Moderate 0 - 200 or Light 0 1 1000 Trace | Color Visual Cobalt Clear Scale = Cloudy 0 to 500 Yellow Brown | Odor | Settleabl Solids (%) |
| 8/1/95 | 1213 | 1,5 | 77,3 | 1037 | 7,28 | 1 | Brown 7500 | None | 40% |
| 8/7 | 1411 | 3.0 | 72.6 | 773 | 6.93 | 11/11 | 111 | | 40% |
| 8/8/95 | 1027 | 4.5 | 72.6 | 754 | 4,97 | | | | 1% |
| | 1110 | 4.0 | 719 | 733 | 7.01 | | | | 1 1/3 |
| V | 1/39 | | | 724 | | 7 1 | | 1 | 1% |
| | | | | - | | | | | |
| | | | | | | | | | |
| | | | | | | | | , | |
| MELL INT | EGRITY: | <u> 1</u> | | God | | | | | , |
| REMARKS | εαπιτ. ::ω | cl us | S. sable | is Great | 2.0 1 | pronto pu | LOCK#: _ | LO/pi | an |
| | | | | 11 700 | | pror in yo | ** | ······· | |
| | | | | | | | | | |
| | , | | | | | | | | |
| IGNATU | RE2/ | 0//0 | M | | REVIE | WED BY: 74 | Page _ | 4 . | . 4 |
| | | 7 7 | | | | 77 | raye _ | -/ | · — / |

| n | 2 2010 |
|------|---------|
| nev. | 3, 2/94 |

| EMCC |) ON ON | PF F |
|--------------------------|-------------------|---------|
| TYPE: CASING (| | |
| CASING | | VA. |
| | DEPT | |
| DATE SA | | |
| TIME (2400 Hr 1206 |) - | · |

WATER SAMPLE FIELD DATA

| | | | riatt FF LIC | | | |
|----------------------|---------------------|-------------------------------|------------------------|--|------------------|------------------------------|
| EMCON | PROJECT NO | : <u>080s-</u> | 135.04 | SAMPLE I |): <u>AS-</u> | <u>2 (22)</u> |
| ASSOCIATES | PURGED BY | JUIL | LIAMS | CLIENT NAME | BOCO | 11100 |
| | SAMPLED BY: | 3 W/L | LIAMC | LOCATION | : On Klau | 1 |
| TYPE: Grou | und Water | Surface V | Vater Trea | tment Effluent | Other | , |
| CASING DIAM | ETER (inches): | 2 | 3 4 | _ 4.5 | 6 0 | ther |
| CASING ELE | EVATION (feet/N | MSL): | in. | VOLUME IN CASI | NG (gal.) | •77 |
| II DEPIN | LIO MAIFH (I | eet):/ | 1.76 | ALCHIATED DI | PCE /coll | 9 22 |
| DEPT | 'H OF WELL (f | eet):2 | 2.2 A | CTUAL PURGE | VOL. (gal.) : | 7 |
| | | | | | | |
| I 1 | ED: <u>08-7</u> | | Start (2400 Hr) _ | 203 | End (2400 Hr) | 1212 |
| DATE SAMPL | .ED: <u>08-1</u> | 1-95- | Start (2400 Hr) _ | | End (2400 Hr) | |
| TIME | VOLUME | рН | E.C. | TEMPERATURI | | |
| (2400 Hr) 1206 | (gal.) / | (units) _6,63 | (µmhos/cm@ 25° C) | (°F) | (visual) | TURBIDITY (visual) |
| 1209 | 2 | 6.62 | <u>-511</u> _615 | 775 | Blown | HEALL |
| 1212 | 3 | 6,67 | <u> </u> | 74.3 | BROWN | HEMUY |
| | | <u> </u> | | 74.6 | Blown | HEAVY |
| | | | | | | |
| D. O. (ppm): | и / _ | 0000 | 6/0/11 | | · | |
| i i | | | Work | | | _ir |
| Field QC sample | es collected at the | is well: | Parameters field filte | ered at this well: | (COBALT 0 - 500) | (NTU 0 - 200 or 0 - 1000) |
| | PURGING EQ | | | | | |
| 2° Bladd | _ | → Bailer (Teflo | n(B) | | ING EQUIPMEN | _ |
| Centrifug | • | Bailer (PVC) | | 2" Bladder PumDDL Sampler | | ler (Teflon®) |
| Submers | ible Pump | - Bailer (Stain | - " | Dipper | | er (Stainless Steel) |
| Well Wiz | | Dedicated | | → Well Wizard™ | | mersible Pump licated |
| Other: | | | Other: | | | |
| WELL INTEGRITY | : _OK | | | | | |
| REMARKS | | , | | | _ LOCK#: <u></u> | lolphin_ |
| , LIMITING , | | | | | | |
| | | | | | | |
| | | | | | | |
| Meter Calibration: I | Date: 8-11-G | 5-111 | Meter Serial | | | , . |
| (EC 1000 /D19 / | INOO LOU | ≥ (ime; <u>//5</u> | Meter Serial | #: <u>7020</u> | Temperature | • °F: <u>73.'S</u> |
| Location of previous | calibration | /(pH/_ | 7.05/700) (F | H 10 <u>/U./)</u> Z/ <u>/(</u> | (pH 4 <u>4.0</u> | 121 |
| /) | 7 /// | | | i | | |
| Signature: | Volter | <u> </u> | Reviewed E | 3v: 2 4 | Page | of 4 |
| | | · | | , | ye | |

| Rev. | 3. | 2/94 |
|------|----|------|
| | ٠, | 207 |



| WATER SAMPLE FIELD DATA SHEET | | | | | | | |
|---|--|--|--|--|--|--|--|
| FMCON PROJECT NO: 0805-135-04 SAMPLE ID: 45-3 (22) | | | | | | | |
| ASSOCIATES PURGED BY: J WILLIAMS CLIENT NAME: ARCO 6148 | | | | | | | |
| SAMPLED BY: I WILLIAMC LOCATION: Oakland, Ca. | | | | | | | |
| TYPE: Ground Water Surface Water Treatment Effluent Other | | | | | | | |
| CASING DIAMETER (inches): 2 <u> </u> | | | | | | | |
| CASING ELEVATION (feet/MSL): WOLUME IN CASING (gal.): .49 | | | | | | | |
| DEPTH TO WATER (feet): 19.30 CALCULATED PURGE (gal.): 147 | | | | | | | |
| DEPTH OF WELL (feet): 22,3 ACTUAL PURGE VOL. (gal.): 1,5 | | | | | | | |
| DATE PURGED: 08-11-95" Start (2400 Hr) /233 End (2400 Hr) /233 | | | | | | | |
| DATE PURGED: 08-11-95 Start (2400 Hr) 1233 End (2400 Hr) 1246 DATE SAMPLED: 08-11-95 Start (2400 Hr) End (2400 Hr) 1250 | | | | | | | |
| TIME VOLUME | | | | | | | |
| (2400 Hr) (gal.) (units) (μmhos/cm@ 25° C) (°F) (visual) (visual) | | | | | | | |
| 12 (1) 100 837 73.7 BEOWN HEAVY | | | | | | | |
| 1241 6.97 889 71, Z BEOWN HEAVY 1246 15 6.90 833 706 BEOWN HEAVY | | | | | | | |
| 1246 1.5 6.40 833 70.6 BROWN HERUS | | | | | | | |
| | | | | | | | |
| D. O. (ppm): AR ODOR: STROWG | | | | | | | |
| Field QC samples collected at this well: Parameters field filtered at this well: (COBALT 0 - 500) (NTU 0 - 200 | | | | | | | |
| WR or 0 - 1000) | | | | | | | |
| PURGING EQUIPMENT SAMPLING EQUIPMENT | | | | | | | |
| 2° Bladder Pump Bailer (Teflon®) 2° Bladder Pump Bailer (Teflon®) | | | | | | | |
| Centrifugal Pump Bailer (PVC) — DDL Sampler — Bailer (Stainless Steel) — Dipper — Submersible Pump — Bailer (Stainless Steel) — Dipper — Submersible Pump | | | | | | | |
| —— Submersible Pump —— Bailer (Stainless Steel) —— Dipper —— Submersible Pump —— Well Wizard™ —— Dedicated —— Well Wizard™ —— Dedicated | | | | | | | |
| Other: Other: | | | | | | | |
| VELL INTEGRITY: _OK LOCK #: Defin | | | | | | | |
| REMARKS: | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Meter Calibration: Date: 8-1/90 Time: Meter Serial #: Temperature °F: | | | | | | | |
| EC 1000/) (DI) (pH 7/) (pH 10/) (pH 4/) | | | | | | | |
| Location of previous calibration: 45-2 | | | | | | | |
| gnature: Reviewed By: M Page 7 of 4 | | | | | | | |



| WATER SAMPLE FIELD DATA SHEET | | | | | |
|---|--|--|--|--|--|
| PROJECT NO: 0805-135-04 SAMPLE ID: 45-4 (28) | | | | | |
| EMCON ASSOCIATES PURGED BY: JWILLIAMS CLIENT NAME: ALGO 6148 | | | | | |
| SAMPLED BY: <u>SWILLIAMS</u> LOCATION: <u>Oakland</u> Ca | | | | | |
| TYPE: Ground Water Surface Water Treatment Effluent Other | | | | | |
| CASING DIAMETER (inches): 2 1/2 3 4 4.5 6 Other | | | | | |
| CASING ELEVATION (feet/MSL): NR VOLUME IN CASING (gal.): 1.87 | | | | | |
| DEPTH TO WATER (feet): 16.51 CALCULATED PURGE (gal.): 5.63 | | | | | |
| DEPTH OF WELL (feet): 28.0 ACTUAL PURGE VOL. (gal.): 6 | | | | | |
| MOTORE FORGE VOL. (gal.). | | | | | |
| DATE PURGED: 08-1/-95 Start (2400 Hr) 1309 End (2400 Hr) 1323 | | | | | |
| DATE SAMPLED: 08-11-96 Start (2400 Hr) End (2400 Hr) 1327 | | | | | |
| TIME WOULDER TO THE TOTAL | | | | | |
| (2400 Hr): (gal.) (units) (µmhos/cm@ 25° C) (°F) (visual) (visual) | | | | | |
| 1313 2 6.66 435 76.4 BLOWN HEAVY | | | | | |
| 1318 4 6.53 458 71.2 BOWN HEAVY | | | | | |
| 1323 6 6.55 459 70.2 BROWN HELENS | | | | | |
| | | | | | |
| | | | | | |
| D. O. (ppm): WE ODOR: UBUT W M | | | | | |
| Field OC samples collected at this well. Development of the state of | | | | | |
| or 0 - 1000) | | | | | |
| PURGING EQUIPMENT SAMPLING EQUIPMENT | | | | | |
| — 2° Bladder Pump — Bailer (Teflon®) — 2° Bladder Pump — Bailer (Teflon®) | | | | | |
| Centrifugal Pump Bailer (PVC) — DDL Sampter — Bailer (Stainless Stee | | | | | |
| Submersible Pump —— Bailer (Stainless Steel) —— Dipper —— Submersible Pump | | | | | |
| — Well Wizard™ — Dedicated — Well Wizard™ — Dedicated | | | | | |
| Other: Other: | | | | | |
| WELL INTEGRITY: OK LOCK #: Dolphin | | | | | |
| REMARKS: | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| Meter Calibration: Date: 8-11-95 Time: Meter Serial #: Temperature °F: | | | | | |
| (EC 1000 /) (DI) (pH 7 /) (pH 10 /) (pH 4 / | | | | | |
| Location of previous calibration: $AS-2$ | | | | | |
| | | | | | |
| ignature: Reviewed By: Page 3 of 4 | | | | | |



| WATER SAMPLE FIELD DATA SHEET |
|--|
| EMCON PROJECT NO: 0805-135-09 SAMPLE ID: AS-S |
| ASSOCIATES PURGED BY: J WILLIAMS CLIENT NAME: ALCO 6148 |
| SAMPLED BY: JWILLIAM C LOCATION: Oakland, Con |
| TYPE: Ground Water Surface Water Treatment Effluent Other |
| CASING DIAMETER (inches): 2 2 3 4 4.5 6 Other |
| CASING ELEVATION (feet/MSL): |
| DEPTH TO WATER (feet): |
| DEPTH OF WELL (feet): 16.8 ACTUAL PURGE VOL. (gal.): 25 |
| |
| DATE PURGED: <u>OB-11-95</u> Start (2400 Hr) <u>1407</u> End (2400 Hr) <u>1417</u> |
| DATE SAMPLED: 08-11-95 Start (2400 Hr) End (2400 Hr) |
| TIME VOLUME PH E.C. TEMPERATURE COLOR TURBIDITY |
| (yai.) (units) (μmhos/cm@ 25° C) (°F) (visual) (visual) |
| WELL DELETTO AFTER 2,5 GARLIONS |
| 1430 |
| 175 TOC 641 745 BLOWN HEAVY |
| |
| D. O. (ppm): We opon: nouve in |
| (COPALTO SOO) |
| Field QC samples collected at this well: Parameters field filtered at this well: OCEANT 0 - 500) (NTU 0 - 200 or 0 - 1000) |
| PURGING EQUIPMENT SAMPLING FOLLIPMENT |
| PORGING EQUIPMENT 2º Bladder Pump Bailer (Teflon®) 2º Bladder Pump Bailer (Teflon®) Bailer (Teflon®) |
| — Centrifugal Pump Bailer (PVC) — DDL Sampler — Bailer (Stainless Steel) |
| Submersible Pump —— Bailer (Stainless Steel) —— Dipper —— Submersible Pump |
| — Well Wizard ^M — Dedicated — Well Wizard ^M — Dedicated Other: |
| Other: |
| ELL INTEGRITY: OC LOCK #: Dolphian |
| MARKS: |
| |
| |
| |
| eter Calibration: Date: Time: Meter Serial #: Temperature °F: |
| EC 1000/) (DI) (pH 7/) (pH 10/) (pH 4/) |
| cation of previous calibration: |
| nature: Reviewed By: Page 4 of 4 |
| Reviewed By: Page 7 of 4 |

APPENDIX F CERTIFIED ANALYTICAL REPORTS AND CHAIN-OF-CUSTODY DOCUMENTATION



August 25, 1995

Service Request No: <u>S951001</u>

John Young EMCON 1921 Ringwood Avenue San Jose, CA 95131

Re: 0805-135.01 / TO# 17075.00 / 6148 Oakland

Dear Mr. Young:

The following pages contain analytical results for sample(s) received by the laboratory on August 11, 1995. Results of sample analyses are followed by Appendix A which contains sample custody documentation and quality assurance deliverables requested for this project. The work requested has been assigned Service Request No. S951001 - to help expedite our service please refer to this number when contacting the laboratory.

Analytical results were produced by procedures consistent with Columbia Analytical Services' (CAS) Quality Assurance Manual (with any deviations noted). Signature of this CAS Analytical Report below confirms that pages 2 through 7, following, have been thoroughly reviewed and approved for release in accord with CAS Standard Operating Procedure ADM-DatRev3.

Please feel welcome to contact me should you have questions or further needs.

Sincerely:

Steven L. Green

Project Chemist

Annelise J. Bazar

Regional QA Coordinator

Unnelise Jado Bayan

SLG/ajb

Acronyms

A2LA American Association for Laboratory Accreditation

ASTM American Society for Testing and Materials

BOD Biochemical Oxygen Demand

BTEX Benzene, Toluene, Ethylbenzene, Xylenes

CAM California Assessment Metals
CARB California Air Resources Board

CAS Number Chemical Abstract Service registry Number

CFC Chlorofluorocarbon
CFU Colony-Forming Unit
COD Chemical Oxygen Demand

DEC Department of Environmental Conservation
DEQ Department of Environmental Quality
DHS Department of Health Services
DLCS Duplicate Laboratory Control Sample

DMS Duplicate Matrix Spike
DOE Department of Ecology
DOH Department of Health

EPA U. S. Environmental Protection Agency

ELAP Environmental Laboratory Accreditation Program

GC Gas Chromatography

GC/MS Gas Chromatography/Mass Spectrometry

IC Ion Chromatography

ICB Initial Calibration Blank sample

ICP Inductively Coupled Plasma atomic emission spectrometry

ICV Initial Calibration Verification sample

J Estimated concentration. The value is less than the MRL, but greater than or equal to

the MDL. If the value is equal to the MRL, the result is actually <MRL before rounding.

LUFT Leaking Underground Fuel Tank

M Madified

MBAS Methylene Blue Active Substances

MCL Maximum Contaminant Level. The highest permissible concentration of a

substance allowed in drinking water as established by the U. S. EPA.

MDL Method Detection Limit
MPN Most Probable Number
MRL Method Reporting Limit

MS Matrix Spike

MTBE Methyl tert-Butyl Ether
NA Not Applicable
NAN Not Analyzed
NC Not Calculated

NCASI National Council of the paper industry for Air and Stream Improvement
ND Not Detected at or above the method reporting/detection limit (MRL/MDL)

NIOSH National Institute for Occupational Safety and Health

NTU Nephelometric Turbidity Units

ppb Parts Per Billion ppm Parts Per Million

PQL Practical Quantitation Limit

QA/QC Quality Assurance/Quality Control

RCRA Resource Conservation and Recovery Act

RPD Relative Percent Difference SIM Selected Ion Monitoring

SM Standard Methods for the Examination of Water and Wastewater, 18th Ed., 1992

STLC Solubility Threshold Limit Concentration

SW Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW-846,

3rd Ed., 1986 and as amended by Updates I, II, IIA, and IIB.

TCLP Toxicity Characteristic Leaching Procedure

TDS Total Dissolved Solids

TPH Total Petroleum Hydrocarbons

tr Trace level. The concentration of an analyte that is less than the PQL but greater than or equal

to the MDL. If the value is equal to the PQL, the result is actually <PQL before rounding.

TRPH Total Recoverable Petroleum Hydrocarbons

TSS Total Suspended Solids

TTLC Total Threshold Limit Concentration

VOA Volatile Organic Analyte(s) ACRONLST.DOC 7/14/95

Analytical Report

Client: ARCO Products Company

Project: 0805-135.01 / TO# 17075.00 / 6148 Oakland

Sample Matrix: Water

Date Collected: 8/11/95
Date Received: 8/11/95
Date Extracted: NA

Service Request: S951001

Date Analyzed: 8/22,23/95

BTEX and TPH as Gasoline EPA Methods 5030/8020/California DHS LUFT Method

| | Analyte: Units: Method Reporting Limit: | TPH as Gasoline ug/L (ppb) 50 | Benzene ug/L (ppb) 0.5 | Toluene ug/L (ppb) 0.5 | Ethyl- benzene ug/L (ppb) 0.5 | Xylenes, Total ug/L (ppb) 0.5 |
|--------------|---|--|------------------------------|------------------------------|--|--|
| Sample Name | Lab Code | | | | | |
| AS-2 (22) | S951001-001 | 310 | 15 | 2.6 | 5.9 | 44 |
| AS-3 (22) | S951001-002 | 10,000 | 1,700 | 380 | 490 | 1,600 |
| AS-4 (28) | S951001-003 | ND | ND | ND | ND | ND |
| AS-5 (26) | S951001-004 | ND | ND | ND | ND | ND |
| Method Blank | S950822-WB | ND | ND | ND | ND | ND |
| Method Blank | S950823-WB | ND | ND | ND | ND | ND |

APPENDIX A

QA/QC Report

Client:ARCO Products CompanyService Request:\$951001Project:0805-135.01 / TO# 17075.00 / 6148 OaklandDate Collected:8/11/95Sample Matrix:WaterDate Received:8/11/95Date Extracted:NA

Date Analyzed: 8/22,23/95

Surrogate Recovery Summary
BTEX and TPH as Gasoline
EPA Methods 5030/8020/California DHS LUFT Method

| Sample Name | Lab Code | Percent Recovery α, α, α -Trifluorotoluene |
|--------------|----------------|---|
| AS-2 (22) | S951001-001 | 101 |
| AS-3 (22) | S951001-002 | 92 |
| AS-4 (28) | S951001-003 | 90 |
| AS-5 (26) | S951001-004 | 92 |
| MS | S950994-003MS | 100 |
| DMS | S950994-003DMS | 100 |
| Method Blank | S950822-WB | 92 |
| Method Blank | S950823-WB | 95 |
| | | |

CAS Acceptance Limits: 69-116

QA/QC Report

Client: Project: **ARCO Products Company**

0805-135.01 / TO# 17075.00 / 6148 Oakiand

Service Request: S951001

Date Analyzed: 8/22/95

Initial Calibration Verification (ICV) Summary
BTEX and TPH as Gasoline
EPA Methods 5030/8020/California DHS LUFT Method
Units: ppb

| | | | CAS |
|-------|-----------------------|--|--|
| | | | Percent |
| | | | Recovery |
| True | | Percent | Acceptance |
| Value | Result | Recovery | Limits |
| 25 | 26.3 | 105 | 85-115 |
| 25 | 25.1 | 100 | 85-115 |
| 25 | 25.0 | 100 | 85-115 |
| 75 | 72.6 | 97 | 85-115 |
| 250 | 233 | 93 | 90-110 |
| | Value 25 25 25 25 75 | Value Result 25 26.3 25 25.1 25 25.0 75 72.6 | Value Result Recovery 25 26.3 105 25 25.1 100 25 25.0 100 75 72.6 97 |

QA/QC Report

Client: ARCO Products Company

Project: 0805-135.01 / TO# 17075.00 / 6148 Oakland

Sample Matrix: Water

Service Request: S951001

Date Collected: 8/11/95

Date Received: 8/11/95

Date Extracted: NA

Date Analyzed: 8/22,23/95

Matrix Spike/Duplicate Matrix Spike Summary

TPH as Gasoline

EPA Methods 5030/California DHS LUFT Method

Units: ug/L (ppb)

Sample Name:

Batch QC

Lab Code: \$950994-003

| | Percent Ro | | | | | | | ecovery | |
|----------|-------------|--------------|------------------|-------------|---------------|----|-----|-----------------------------|-----------------------------------|
| Analyte | Spike MS | Level DMS | Sample Result | Spike MS | Result DMS | MS | DMS | CAS Acceptance Limits | Relative Percent Difference |
| Gasoline | 250 | 250 | ND | 235 | 235 | 94 | 94 | 67-121 | <1 |

| AROU | LOC Division | of Atlanta | Certicold Controld Control | | | | | Task O | rder No. | 170 | 75. | 00 | • | | | | | | | • • | | Chain of Custody |
|------------------------------|-----------------|---------------|----------------------------|------------|-----------------|----------|--------------------|----------------------|---------------|--|---|---------------------------------|--------------------------------|-------------------------|------------------------------|--------------|--------------|-----------------------------------|-------------------|--|----------|--------------------------------------|
| ARCO Facili | ty no. | 148 | | Cit (Fa | y icility) (| Daki | land | ! | | Project (Consu | manag (tant) | ger \ | Oh | n Ve | フレハ | C | | | | | | Laboratory name |
| ARCO engir | | Vhel | | | | | Telepho: (ARCO) | ne no. | | Teleph (Consu | one no | (40) | Q)4 | 57. | .72/ | 7 Fa | X NO. | m [] | 1/12 | 1453 | -0457 | C/45 |
| Consultant r | ame | MC | ON_ | | | | 13 | Address (Consulta | unt) 1921 | Rii | 201 | 100 | di | ive | > 6 | XAN | 10 | 6 | CA | GS | 131 | Contract number |
| | | | | Matrix | | Prese | ervation | | | | | i | 1 | i | | | | T of | 10,7000 | | | Method of shipment |
| Sample I.D. | Lab no. | Container no. | Soil | Water | Other | lce | Acid | Sampling date | Sampling time | BTEX 602/EPA 8020 | BTEXTPH STEAM BOY | TPH Modified 8015 Gas Diesel | Oil and Grease 413.1 413.2 | TPH EPA 418.1/SM503E | EPA 601/8010 | EPA 624/8240 | EPA 625/8270 | TCLP Semi Metals □ VOA □ VOA [| CAM Metals EPA 69 | Lead Org./DHS Condition of 17420/7421 Condition of 174 | | Sampler will deliver |
| AS-2(. | 22) | 2 | | X | | X | HCL | 8-11-95 | 1216 | | X | | | | | | | | | | | Special detection Limit/reporting |
| 45-3(| 2) , | 2 | | × | | X | Ha | | 1250 | | X | | | | | | | | | | | Lowest Possible |
| 45-46 | 8) 3 | 2 | | X | | X | HCL | | 1327 | | \times | | | | | | | | | | | Possible |
| <u> 145-5(</u> | 26) 4 | 2 | | X | | X | HCL | | 1426 | | × | | | | | <u> </u> | _ | | | | | Special QA/QC |
| | | | | | | | | | | - | | <u> </u> | | | | | <u> </u> | | | | - | As Normal |
| | | | | | | | | | | | | | | | | | | | | | | Remarks |
| | | | | | | | | | | | | | | | | | | | | | | 2-40m1 HCL VOAs |
| | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | , | | | | | | | | | | | | | | # 0905 - 135,0 Lab number |
| | | | | | | | | | | - | | | | | | | _ | | | | _ | \$9.50/00 / Turnaround time |
| Condition | | | | | | | | | | | | | | | | | | | | | | Priority Rush 1 Business Day |
| Condition of Relinquishe | | | | | | | Date 8-11- | 95- | Time | <u> </u> | erature ved by | receive | ed: | | | | | | <u> </u> | | <u> </u> | Rush 2 Business Days |
| Relinquishe | d by | | | | | | Date | | Time | Recei | ved by | | | | _ | ., | | | | | | Expedited 5 Business Days |
| Refinquishe | d by | | | | | | Date | | Time | Time Received by laboratory Date 8-11-95 16 40 | | | | 40 | Standard 10 Business Days | | | | | | | |
| Distribution: APPC-3292 (| | py — Lai | ooratory; | Canary o | юру — А | RCO Envi | ronmental i | Engineering; F | Pink copy — | Consuit | ant | | | | | | | | | | | Due 8/25 |



: 1

August 18, 1995

Service Request No: <u>S950977</u>

John Young EMCON 1921 Ringwood Avenue San Jose, CA 95131

Re: 0805-135.04 / TO# 18334.00 / 6148 Oakland

Dear Mr. Young:

The following pages contain analytical results for sample(s) received by the laboratory on August 4, 1995. Results of sample analyses are followed by Appendix A which contains sample custody documentation and quality assurance deliverables requested for this project. The work requested has been assigned Service Request No. S950977 - to help expedite our service please refer to this number when contacting the laboratory.

Analytical results were produced by procedures consistent with Columbia Analytical Services' (CAS) Quality Assurance Manual (with any deviations noted). Signature of this CAS Analytical Report below confirms that pages 2 through 11, following, have been thoroughly reviewed and approved for release in accord with CAS Standard Operating Procedure ADM-DatRev3.

Please feel welcome to contact me should you have questions or further needs.

Sincerely:

Steven L. Green

Project Chemist

Annelise J. Bazar

Regional QA Coordinator

SLG/ajb

Acronyms

A2LA American Association for Laboratory Accreditation

ASTM American Society for Testing and Materials

BOD Biochemical Oxygen Demand

BTEX Benzene, Toluene, Ethylbenzene, Xylenes

CAM California Assessment Metals
CARB California Air Resources Board

CAS Number Chemical Abstract Service registry Number

CFC Chlorofluorocarbon
CFU Colony-Forming Unit
COD Chemical Oxygen Demand

DEC Department of Environmental Conservation
DEQ Department of Environmental Quality
DHS Department of Health Services
DLCS Duplicate Laboratory Control Sample

DMS Duplicate Matrix Spike
DOE Department of Ecology
DOH Department of Health

EPA U. S. Environmental Protection Agency

ELAP Environmental Laboratory Accreditation Program

GC Gas Chromatography

GC/MS Gas Chromatography/Mass Spectrometry

iC Ion Chromatography

ICB Initial Calibration Blank sample

ICP Inductively Coupled Plasma atomic emission spectrometry

ICV Initial Calibration Verification sample

J Estimated concentration. The value is less than the MRL, but greater than or equal to

the MDL. If the value is equal to the MRL, the result is actually <MRL before rounding.

LUFT Leaking Underground Fuel Tank

M Modified

MBAS Methylene Blue Active Substances

MCL Maximum Contaminant Level. The highest permissible concentration of a

substance allowed in drinking water as established by the U. S. EPA.

MDL Method Detection Limit
MPN Most Probable Number
MRL Method Reporting Limit

MS Matrix Spike

MTBE Methyl tert-Butyl Ether

NA Not Applicable
NAN Not Analyzed
NC Not Calculated

NCASI National Council of the paper industry for Air and Stream Improvement
ND Not Detected at or above the method reporting/detection limit (MRL/MDL)

NIOSH National Institute for Occupational Safety and Health

NTU Nephelometric Turbidity Units

ppb Parts Per Billion ppm Parts Per Million

PQL Practical Quantitation Limit
QA/QC Quality Assurance/Quality Control
RCRA Resource Conservation and Recovery Act

RPD Relative Percent Difference SIM Selected fon Monitoring

SM Standard Methods for the Examination of Water and Wastewater, 18th Ed., 1992

STLC Solubility Threshold Limit Concentration

SW Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW-846,

3rd Ed., 1986 and as amended by Updates I, II, IIA, and IIB.

TCLP Toxicity Characteristic Leaching Procedure

TDS Total Dissolved Solids

TPH Total Petroleum Hydrocarbons

tr Trace level The concentration of an analyte that is less than the PQL but greater than or equal

to the MDL. If the value is equal to the PQL, the result is actually <PQL before rounding.

TRPH Total Recoverable Petroleum Hydrocarbons

TSS Total Suspended Solids

TTLC Total Threshold Limit Concentration

VOA Volatile Organic Analyte(s) ACRONLST.DOC 7/14/95

Analytical Report

Client: ARCO Products Company

Project: 0805-135 04/TO#18334.00/6148 Oakland

Sample Matrix: Soil

Service Request: \$950977

Date Collected: 7/31-8/3/95

Date Received: 8/4/95

Date Extracted: NA

Date Analyzed: 8/10-11/95

BTEX and TPH as Gasoline EPA Methods 5030/8020/California DHS LUFT Method As Received Basis

| | Analyte: Units: Method Reporting Limit: | TPH as Gasoline mg/Kg (ppm) 1 | Benzene mg/Kg (ppm) 0.005 | Toluene mg/Kg (ppm) 0.005 | Ethyl- benzene mg/Kg (ppm) 0.005 | Xylenes, Total mg/Kg (ppm) 0.005 |
|--------------|---|-------------------------------|---------------------------------|---------------------------------|---|---|
| Sample Name | Lab Code | | | | | |
| AS-3, 16' | S950977-001 | ND | 0 34 | ND | ND | ND |
| AS-3, 26.5' | S950977-003 | ND | ND | ND | ND | 0.007 |
| AS-4, 14' | S950977-006 | ND | 0.009 | ND | ND | 0.045 |
| AS-4, 26.5' | S950977-007 | ND | ND | ND | ND | ND |
| AS-5, 28.5' | \$950977-008 | ND | ND | ND | ND | ND |
| VW-2, 16.5' | S950977-011 | ND | ND | ND | ND | ND |
| VW-4, 16' | S950977-015 | ND | ND | ND | ND | ND |
| VW-5, 21.5' | S950977-019 | ND | ND | ND | ND | ND |
| VW-8, 26' | S950977-029 | ND | ND | ND | ND | ND |
| VW-9, 16.5' | \$950977-032 | 6 | <0.025* | <0.025* | <0.025* | 0.026 |
| VW-9, 26' | S950977-033 | ND | ND | ND | ND | ND |
| VW-10, 16' | S950977-034 | ND | ND | ND | ND | ND |
| VW-10, 21' | S950977-035 | ND | ND | ND | ND | ND |
| Method Blank | S950810-SB1 | ND | ND | ND | ND | ND |
| Method Blank | S950811-SB1 | ND | ND | ND | ND | ND |

^{*} Raised MRL due to high analyte concentration requiring sample dilution.

Analytical Report

Client: AR
Project: 080

ARCO Products Company

0805-135.04/TO#18334.00/6148 Oakland

Sample Matrix:

Soil

Service Request: S950977

Date Collected: 7/31-8/3/95
Date Received: 8/4/95

Date Extracted: NA

Date Analyzed: 8/14-17/95

BTEX and TPH as Gasoline EPA Methods 5030/8020/California DHS LUFT Method As Received Basis

| | Analyte: Units: Method Reporting Limit: | TPH as Gasoline mg/Kg (ppm) 5 | Benzene mg/Kg (ppm) 0.05 | Toluene mg/Kg (ppm) 0.1 | Ethyl- benzene mg/Kg (ppm) 0.1 | Xylenes, Total mg/Kg (ppm) 0.1 |
|--------------|---|--|--------------------------------|-------------------------------|---|---|
| Sample Name | Lab Code | | | | | |
| VW-5. 16' | S950977-018 | 74 | 0.7 | <0.2* | 0.9 | 1.0 |
| VW-6, 6' | S950977-020 | 3,100 | <5* | 86 | 63 | 430 |
| VW-6, 8' | S950977-021 | 2,300 | <5* | 51 | 48 | 310 |
| VW-6, 11.5' | S950977-022 | 2,100 | <2* | 7.3 | 16 | 110 |
| VW-6 16' | S950977-023 | 1,700 | 5.9 | 94 | 44 | 240 |
| VW-7, 17' | S950977-025 | 30 | 0.3 | 0.5 | 0.6 | 2.8 |
| Method Blank | S950814-SB1 | ND | ND | ND | ND | ND |
| Method Blank | S950817-SB1 | ND | ND | ND | ND | ND |

^{*} Raised MRL due to high analyte concentration requiring sample dilution.

APPENDIX A

QA/QC Report

Client: ARCO Products Company

Project: 0805-135.04/TO#18334 00/6148 Oakland

Sample Matrix: Soil

Service Request: \$950977

Date Collected: 7/31-8/3/95

Date Received: 8/4/95

Date Extracted: NA
Date Analyzed: 8/10-11/95

Surrogate Recovery Summary BTEX and TPH as Gasoline

EPA Methods 5030/8020/California DHS LUFT Method

| Sample Name | Lab Code | Percent Recovery α, α, α -Trifluorotoluene | | |
|------------------------|----------------|---|--|--|
| AS-3, 16' | S950977-001 | 112 | | |
| AS-3, 26.5' | S950977-003 | 106 | | |
| AS-4, 14' | S950977-006 | 98 | | |
| AS-4, 26.5' | S950977-007 | 93 | | |
| AS-5, 28.5' | S950977-008 | 99 | | |
| VW-2, 16.5' | S950977-011 | 90 | | |
| VW-4, 16' | S950977-015 | 88 | | |
| VW-5, 21.5' | S950977-019 | 79 | | |
| VW-8, 26' | S950977-029 | 83 | | |
| VW-9, 16.5° | S950977-032 | 113 * | | |
| VW-9, 26' | S950977-033 | 92 | | |
| VW-10, 16' | S950977-034 | 91 | | |
| VW-10, 21 ¹ | S950977-035 | 77 | | |
| AS-3, 26.5' (MS) | S950977-003MS | 98 | | |
| AS-3, 26.5' (DMS) | S950977-003DMS | 102 | | |
| VW-8, 26' (MS) | S950977-029MS | 84 | | |
| VW-8, 26' (DMS) | S950977-029DMS | 92 | | |
| Method Blank | S950810-SB1 | 99 | | |
| Method Blank | S950811-SB1 | 99 | | |

CAS Acceptance Limits: 51-137

^{*} The surrogate used for this sample was 4-bromofluorobenzene.

QA/QC Report

Client: ARCO Products Company

Project: 0805-135.04/TO#18334.00/6148 Oakland

Sample Matrix: Soil

Service Request: \$950977

Date Collected: 7/31-8/3/95

Date Received: 8/4/95
Date Extracted: NA

Date Analyzed: 8/14-17/95

Surrogate Recovery Summary BTEX and TPH as Gasoline

EPA Methods 5030/8020/California DHS LUFT Method

| Sample Name | Lab Code | Percent Recovery α, α, α -Trifluorotoluene |
|--------------|--------------|---|
| VW-5, 16' | S950977-018 | 100 |
| VW-6, 6' | \$950977-020 | 93 |
| VW-6, 8' | S950977-021 | 88 |
| VW-6. 11.5' | S950977-022 | 93 |
| VW-6 16' | S950977-023 | 92 |
| VW-7, 17' | S950977-025 | 92 |
| Method Blank | S950814-SB1 | 92 |
| Method Blank | S950817-SB1 | 92 |

CAS Acceptance Limits: 59-115

QA/QC Report

 Client:
 ARCO Products Company
 Service Request:
 \$950977

 Project:
 0805-135.04/TO#18334.00/6148 Oakland
 Date Collected:
 7/31-8/3/95

Sample Matrix: Soil Date Received: 8/4/95

Date Extracted: NA
Date Analyzed: 8/10/95

Matrix Spike/Duplicate Matrix Spike Summary

BTE

EPA Methods 5030/8020 Units: mg/Kg (ppm) As Received Basis

Sample Name: AS-3, 26.5' Lab Code: S950977-003

Percent Recovery

| | Spike | Level | Sample | Spike | Result | | | CAS Acceptance | Relative Percent |
|--------------|-------|-------|--------|--------|--------|-----|-----|-------------------|---------------------|
| Analyte | MS | DMS | Result | MS | DMS | MS | DMS | Limits | Difference |
| Benzene | 0.050 | 0.050 | ND | 0.0559 | 0.0570 | 112 | 114 | 57 -15 4 | 2 |
| Toluene | 0.050 | 0.050 | ND | 0.0540 | 0.0565 | 108 | 113 | 60-142 | 5 |
| Ethylbenzene | 0.050 | 0.050 | ND | 0.0577 | 0.0617 | 115 | 123 | 46-150 | 7 |

QA/QC Report

Client: ARCO Products Company Service Request: \$950977

Project: 0805-135.04/TO#18334.00/6148 Oakland Date Collected: 7/31-8/3/95

Sample Matrix: Soil Date Received: 8/4/95

Date Extracted: NA
Date Analyzed: 8/10/95

Matrix Spike/Duplicate Matrix Spike Summary

BTE

EPA Methods 5030/8020 Units: mg/Kg (ppm) As Received Basis

Sample Name: VW-8, 26' Lab Code: S950977-029

| | | ecovery | ery | | | | | | |
|--------------|-------|---------|--------|--------|--------|-----|-----|------------|------------|
| | | | | | | | | CAS | Relative |
| | Spike | Level | Sample | Spike | Result | | | Acceptance | Percent |
| Analyte | MS | DMS | Result | MS | DMS | MS | DMS | Limits | Difference |
| Benzene | 0.050 | 0.050 | ND | 0.0625 | 0.0587 | 125 | 117 | 57-154 | 6 |
| Toluene | 0.050 | 0.050 | ND | 0.0583 | 0.0571 | 117 | 114 | 60-142 | 2 |
| Ethylbenzene | 0.050 | 0.050 | ND | 0.0614 | 0.0595 | 123 | 119 | 46-150 | 3 |

QA/QC Report

Client: Project: ARCO Products Company

0805-135.04/TO#18334.00/6148 Oakland

Service Request: \$950977

Date Analyzed: 8/10/95

Initial Calibration Verification (ICV) Summary
BTEX and TPH as Gasoline
EPA Methods 5030/8020/California DHS LUFT Method
Units: ppm

| | _ | | | Percent Recovery |
|----------------|---------------|--------|---------------------|----------------------|
| Analyte | True Value | Result | Percent Recovery | Acceptance Limits |
| n | 0.070 | | • | |
| Benzene | 0.050 | 0.0557 | 111 | 85-115 |
| Toluene | 0.050 | 0.0554 | 111 | 85-115 |
| Ethylbenzene | 0.050 | 0.0570 | 114 | 85-115 |
| Xylenes. Total | 0.15 | 0.159 | 106 | 85-115 |
| Gasoline | 1.0 | 0.953 | 95 | 90-110 |

QA/QC Report

Client:ARCO Products CompanyService Request:\$5950977Project:0805-135.04/TO#18334 00/6148 OaklandDate Analyzed:\$8/14/95

Initial Calibration Verification (ICV) Summary BTEX and TPH as Gasoline EPA Methods 5030/8020/California DHS LUFT Method Units: ppm

| | | | | CAS | | |
|----------------|-------|--------|----------|------------|--|--|
| | | | | Percent | | |
| | | | | Recovery | | |
| | True | | Percent | Acceptance | | |
| Analyte | Value | Result | Recovery | Limits | | |
| Benzene | 2.5 | 2.55 | 102 | 85-115 | | |
| Toluene | 2.5 | 2.45 | 98 | 85-115 | | |
| Ethylbenzene | 2.5 | 1.45 | 58 | 85-115 | | |
| Xylenes, Total | 7.5 | 7 13 | 95 | 85-115 | | |
| Gasoline | 25 | 23.7 | 95 | 90-110 | | |
| | | | | | | |

| | | | | Company | | | | Task C | rder No. | | | | | | | | • | | | | | Chain of Custody |
|--|----------|--|------|--------------|-----------------|-------|--------------------|--------------------|---------------|----------------------|-----------------|--|---------------------------------|-------------------------|--------------|--------------|--------------|------------------------|--------------------------------|--|------------------------------|--------------------------------------|
| ARCO Facility | | 148 | | Cit (Fa | y icility) (| Daklo | ind | | | Project (Consu | manag Itant) | \mathcal{J}^{ger} | ohn | Ϋ́ | u.ng | | | | | | | Laboratory name |
| ARCO engine | er M | Ke | Wh | e lav | | | Telephor (ARCO) | 10 no. 40\$)37 | 7-8697 | Telepho (Consu | one no. | (nS) 1 | <i>13</i> 7 - | 9520 | y 5 | Fax (Co | no. | 11) (4: | 274 | 53; | 305 | - CAS-SJ |
| Consultant na | | | ON | | | | | Address (Consul | | 21 | | | | | | | | | VI. 111 | | | Contract number |
| | | | | Matrix | | Pres | ervation | | _ | | B W | 101-1 | וח | ш | | | | emi VOA | 10/7/000 | | | Method of shipment |
| Ѕатріе І.D. | Lab no. | Container no. | Soil | Water | Other | Ice | Acid | Sampling date | Sampling time | BTEX 602/EPA 8020 | BTEX/TPH | TPH Modified 8015 Gas Diesel | Oil and Grease 413.1 U 413.2 | TPH EPA 418.1/SM503E | EPA 601/8010 | EPA 624/8240 | EPA 625/8270 | TCLP S Metals VOA | CAM Meials EPA 60 TTLC STLC | Lead Org./OHS C Lead EPA 7420/7421 | J704 | |
| A5.3.6 | / | 1 | | | | | | 8/2/95 | | | | | | | | | | | | | | Special detection Limit/reporting |
| iga | را نخ | | | | | | | 17 | | | | | | | | | | | | | 1 | |
| A5-3, K | 3 | | | | | | | | | | | | | | | | | | | | | |
| AS-4,65 | 4 | | | | | | | | | | | | | | | | | | | | | Special QA/QC |
| 1,11 | 5 | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | / | | | | | | | | | - | | |
| 14 / 14 / 14 / 15 / 15 / 15 / 15 / 15 / | | | | | | | | | <u> </u> | | P | | | | | | | | | | | |
| AS. 5. 185 | , 8 | | | | | | | 1 | | 1 | | | | | | | | | | | | Remarks |
| | . 9 | | | | | | | 7/21/95 | | | | | | | | | | | | | | #0805-155.04 |
| 1442,65 | | | | | | | | 1/21/95 | | 1 | | | | | | | | | <u> </u> | | | #0805-135.04 |
| 11.5.1 | 10 | - | | 1 | | | | | | + | | | | | | | | | <u> </u> | | | |
| 165 | 12 | \dashv | | | | | | | | ┪ | | | | | | | | | | | / | |
| 9 14 (51 | | | | | | | | | 1 | <u> </u> | | ļ <u>.</u> | | | | | | | | | | |
| VN4 6.51 | 13 | _ | | | | | | | | | | | | | : | | | | | | | Lab number |
| 1 11 | _j4 | | | - | | | | | | - | | - | | | | | | | | | | 995097// |
| 16 | 15 | | _1 | - | | 1/1 | | 4 | - | - | | ļ | | | | | | | | | | Turnaround time |
| | | | | | <u> </u> | | | <u> </u> | <u> </u> | _ | | | | | | | <u> </u> | | <u> </u> | | | Priority Rush 1 Business Day |
| Condition of sample: | | | | | | | | | | | | receive | ed: | | | | | | | | | Rush |
| Relinguished by sampler Date Time 8/4/95 16:35 | | | | | | | Recei | ved by | | | | | | | | | | | 2 Business Days | | | |
| Relinquished | | <u> </u> | - | - | | | Date | , - | Time | Recei | ved by | | | • | | | | | | · | | Expedited 5 Business Days |
| Relinquished by Date Time | | | | | | | | | | | laborate | | 056 | ·-·./_ | |)ate 5- 7 | 1 9: | <u>-</u> | Time | . A = | Standard 10 Business Days | |

Distribution: White copy — Laboratory; Canary copy — ARCO Environmental Engineering, Pink copy — Consultant APPC-3292 (2-91)

Due 5/15

| | Division | | | | | | | Task O | rder No. | | | 34. | $\mathcal{O}($ | > | | | | | | | | Chain of Custody |
|--|----------------------|---------------|--------|------------|---------------|-------|----------|---------------------|---------------|----------------------|--------------------------------|---------------------------------|-----------------------------------|-----------------------|--------------|--------------|----------------|------------------------|------------------|--|--------|---|
| ARCO Facil | ly no. | 148 | 3 | Cit (Fa | y icility) | Oakl | and | | | Project (Consul | manag tant) | jer - | Joh | 15 | Yer | unq | / | | | | | Laboratory name A 5 - 5 7 Contract number |
| ARCO engir | | | Wh | ielar | | | Telephor | ne no. 468)\$37~ | 86 97 | Telepho (Consul | one no. tant) | (408) | 453 | 3-7 | 300 | Fad. | no. nsultan | 0(40 | 8)4 | 53 4. | 37-952 | CAS-55 |
| Consultant r | ame Z | mcc | N | | | | | Address (Consult | | Rin | | ed f | Jue | • | | | | | | | | _ Contract number |
| | | | | Matrix | | Prese | rvation | • | | | 9015 | <u>1</u> 5 | | 3E | | | | Semi IVOA □ | 01077000 | | | Method of shipment |
| Sample I.D. | Lab no. | Container no. | Soil | Water | Other | Ice | Acid | Sampling date | Sampling time | BTEX 602/EPA 8020 | BTEX/TPH EPA M602/8020/8015 | TPH Modified 8015 Gas Diesel | Oil and Grease 413.1 🔲 413.2 🗆 | TPH EPA 418.1/SM50 | EPA 601/8010 | EPA 624/8240 | EPA 625/8270 | TCLP Metals □ VOA □ | CAM Metals EPA 6 | Lead Org /DHS C Lead EPA 7420/7421 C | かいり | |
| ¥ W -5,6.E | 1/6. | 1 | | | | 1 | | 8/1/95 | | | | | | | | | | | | | / | Special detection Limit/reporting |
| 11.5 | 17 | j | | | | | | 1 | | | | | | | | | | | | | ./ | |
| 16 | 18 | | | | | | | | | | | | _ | | | | | | | | |] |
| ر.از. ٧ | | \top | | | | | | 1 | | | | | | | | | | | | | | Special QA/QC |
| 14-6 6 | | | | | | | | 8/3/73 | | | | - | | | | | | | | | | -[|
| 1.8' | 21 | | | | | | | | | | | | | | | | | | | | | -1 |
| 11.5 | | | | | | | | | | | | | | | | | | | | | | Remarks |
| V .16 | 25 | | | | | | | | | | | | | | | | | | | | | , , , |
| VW-7, II | 24 | | | | | | | | | | | | | | | | | | | | | # 0805-135.04 |
| 111 | 25 | | | | | | | | <u> </u> | | | | | | | | | | | | | (20.2.2-13.571.1 |
| 1/21 | 26 | | | <u> </u> | | | | 1 | | | | | | | | | _ | | | | | |
| VN-8 C | 27 | | ! | | | | | 8/1/75 | | | | <u> </u> | | | | | | | | | | |
| 11.5 | 28 | | | | | | | | | ļ | | | | | ! | | | | | | | Lab number |
| 126 | 19 | > | V | | | V | | 4 | | | | | | | | | | | | ! | | 5950977 |
| ĺ | | | | | | | | | | | | | | | | | | | | | | Turnaround time |
| | | | | | | | | | | | | | | | | | | | | | 5 | Priority Rush 1 Business Day |
| Condition of | Condition of sample: | | | | | | | | | | erature | receive | ed: | - | | | | | | | | Rush |
| Relinquished by sampler Date Time 8/4/95 16:35 | | | | | | | | ved by | | | | | | _ | | | | | 2 Business Days | | | |
| Relinquishe | | (| J 644. | | | | Date | | Time | | ved by | | | | | | | | | | | Expedited 5 Business Days (.) |
| Relinquishe | ed by | | | | | | Date | | Time | | | laborat | | 3/20 | X |) [|) ate / | | ر | Time | 35 | Standard 10 Business Days |

Distribution: White copy — Laboratory; Canary copy — ARCO Environmental Engineering; Pink copy — Corfsulta APPC-3292 (2-91)

Due 8/18

| | | of Atlantic | Corm | Company | | | | Task O | rder No. | ĺZ | 35. | 2 lF. | · () | \bigcirc | | |] [| | | | | | hain of Custody |
|---|-----------------------|--------------------|------|---------|----------|----------|-------|---------------|--|--|-----------------------------|---------------------------------|-----------------------------------|-------------------------|--------------|--------------|--------------|----------|--------------------------------|--|-----------------|------------------------------|--------------------------------------|
| ARCO Facility no. 6148 City (Facility) ()akland | | | | | | | | | | Project manager (Consultant) Telephone no. (Consultant) (408) HEL 7100 Fax no. (Consultant) (408) HEL 7100 | | | | | | | | | | | | | Laboratory name |
| ARCO engine | | Mike Whelen (ARCO) | | | | | | | | Telephone no. (Consultant) (408) 453-7300 Fax no. (Consultant) (408) 457-7526 | | | | | | | | | | | | (AS-55 | |
| Consultant na | Consultant name ENGON | | | | | | 10000 | 144 | ant) [72] | Plin | | | | Contract number | | | | | | | | | |
| | Matrix Preservation | | | | | ervation | | | -6RE | 2 510 | 20 | |]] | 5a17 | | | Sem: | 000//010 | | | | Method of shipment | |
| Sample 1.D. | Lab no. | Container no. | Soil | Water | Other | íce | Acid | Sampling date | Sampling time | BTEX / 77/4 - | 3TEX/TPH :PA M602/8020/8 | TPH Modified 8015 Gas Diesef | Oil and Grease 413.1 U 413.2 U | TPH EPA 418.1/SM503E | EPA 601/8010 | EPA 624/8240 | EPA 625/8270 | CLP CLP | AM Metals EPA 6. TLC C STLC | Lead Org./DHS CLead EPA Lead EPA 7420/7421 | 50 | | |
| VN 51,6.5 | -3) | 1 | | | | 7 | | 8/1/75 | | | <u> </u> | | 04 | | 2 | ш_ | ш. | | OF. | 1126 | > | | Special detection Limit/reporting |
| 11/ | 31 | 1 | | | | | | | | | | | | | | | | | | | <u> </u> | | |
| j6.5 | 3.2 | | | | <u> </u> | | 1 | | | | 1 | | | | | | | | | 1 | | | |
| Y 76 | 33 | | | | | | | | | | | | | | | | | | | | | | Special QA/QC |
| Vu-10, 14, | 34 | ļ | | | | | 1 | | | | | | | | | | | | | | | | |
| 21 | 367 | | | | | | | | | / | | | | | | | | | | | | | |
| , , <u>,</u> | 136 | : | | | | | | | | | | | | | | | | | | | / | | |
| V | 3/1 | Ÿ | V | | | 1 | 1 | 4 | | | | | | | | | | | | | / | 1 | Remarks |
| <i>j</i> " | | * | | | | | | | | | | | | | | | | | | | | | Project # |
| | | | | | | | | | | | | | | | | | | | | | | | 0808-135-64 |
| | | _ | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | _ | | | | | | |] |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | Lab number |
| | | | | | | | 1 | <u> </u> | | | | | | | | | | | | | | | Turnaround time |
| | | | | | | | 1 | | | | | | | | | · · · · · · | | | | | | | Priority Rush 1 Business Day |
| Condition of sample: | | | | | | | | | Temp | erature | receive | ed. | · | · | | | · | | | <u> </u> | . | Rush | |
| Relinguished by sampler Date 8/4/95 Time | | | | | | | | Recei | ved by | | | | | | | | | | | | 2 Business Days | | |
| | | | | | | | | Time | Received by | | | | | | | | | | | Expedited 5 Business Days | | | |
| Relinquished by Date Time | | | | | | | | | Recei | yed by | laborat | ory E) | 31. | 438 | . [| Date | 1 3 | -> | Time | ş | 3 : 5 | Standard 10 Business Days | |

Distribution: White copy — Laboratory; Canary copy — ARCO Environmental Engineering; Pink copy — Consultant APPC-3292 (2-91)

Due 8/18