


HAZARDOUS WASTE GENERATOR INSPECTION REPORT

STID # 4240 FACILITY NAME: Former Diablo Cellulose PG. 1 OF 1

SUPPLEMENTAL FORM 106-110 Hwy Rd.

Air Forces: Guide to Air Sampling and Analysis
 (916) 985-1000 or (800) 985-5955

Present to witness S-V sampling through Summa canister
 BSK - M. Chue present



Decided to do another boring (B1) slightly closer to bld
 We assumed that shallow water would be a problem in this sampling area ∴ decided to take addnl samples @ 4' bop in some general area as prior proposed borings so as to have as many data points as possible.

PRINT NAME:

INSPECTED BY: BCHAN

SIGNATURE:

DATE: 10/26/98



10/26/98

0815304242-02 0555 3532

COPIES & ENLARGEMENTS CALL 800-421-1030

106-110 Nestle