

# BSK & ASSOCIATES GEOTECHNICAL CONSULTANTS, INC. BSK JOB NO. P92270.3

TENTH QUARTERLY GROUNDWATER MONITORING REPORT - JANUARY 1996 AMERICAN BRASS & IRON FOUNDRY 7825 SAN LEANDRO STREET OAKLAND, CALIFORNIA

February 12, 1996



Engineers, Geologists, Environmental Scientists



1181 Quarry Lane **Building 300** Pleasanton, CA 94566 (510) 462-4000 (510) 462-6283 FAX

February 12, 1996

**BSK JOB NO. P92270.3** 

American Brass and Iron Foundry 7825 San Leandro Street Oakland, California 94621

Attention: Mr. David Robinson

Environmental Engineering Manager

Subject: Tenth Quarterly Groundwater

> Monitoring Report - January 1996 American Brass and Iron Foundry

7825 San Leandro Street Oakland, California

As requested and authorized, BSK & Associates (BSK) has performed the tenth quarterly monitoring of three shallow groundwater Monitoring Wells MW-2 through MW-4 at American Brass & Iron Foundry, located at 7825 San Leandro Street, Oakland, California (Site). This report presents the project background, groundwater data obtained during this sampling event as well as previous data, conclusions based on this quarter's data, and recommendations for further action, as appropriate. The Site location is shown on the Vicinity Map, Figure 1.

BSK appreciates this opportunity to continue to be of service to American Brass & Iron. If there are questions or comments regarding this report, please contact the undersigned.

> Respectfully submitted, **BSK & Associates**

> Musch

Martin B. Cline, R.G.

Geologist

Alex Y. Eskandari, P.E.

Project Manager

C.E. #38101

AYE\MC:pc (ENV\AB&I\P92270-3 Q10)

Distribution:

American Brass & Iron Foundry (3 copies)

### TABLE OF CONTENTS

TEXT		<b>PAGE</b>
General Field Work	ARTERLY MONITORING ACTIVITIES - JANUARY 1996esting	2 2
Regional Hy	ATER DATA - JANUARY 1996  drology	7
<u>FINDINGS</u>	• • • • • • • • • • • • • • • • • • • •	8
RECOMME	NDATIONS	9
LIMITATIO	<u>NS</u>	9
DISTRIBUT	<u>ION</u>	9
TABLES		
Table 1	Analytical Results, Groundwater Samples Benzene, Toluene, Ethylbenzene and Xylenes	3
Table 2	Analytical Results, Groundwater Samples Total Petroleum Hydrocarbons (TPH) as Gasoline and Diesel Total and Hydrocarbons Oil and Grease Total Lead, and Volatile Halocarbons	4
Table 3	Summary of Groundwater Data	7
FIGURES		
Figure 1 Figure 2 Figures 3 - 5 Figure 6 Figure 7  APPENDICI Appendix "A	Groundwater Elevation Contour Map Summary of Groundwater Elevations  ES	
Figures A-1 t		



#### TENTH QUARTERLY GROUNDWATER MONITORING REPORT - JANUARY 1996 AMERICAN BRASS & IRON FOUNDRY 7825 SAN LEANDRO STREET OAKLAND, CALIFORNIA

#### Introduction

This quarterly monitoring report has been prepared to meet Alameda County Department of Environmental Health (ACDEH) requirements for status updates of groundwater at the Site following the removal of four Underground Storage Tanks (USTs) during 1991 and 1992, as initially presented in their letter of October 2, 1992, to David Robinson of American Brass & Iron Foundry (AB & I).

#### **Background**

AB & I has been operating at its present location for more than eighty years. AB & I's current activities include the manufacture of cast iron pipe and fittings. The facility accepts scrap iron and steel, which it stockpiles on-site, and utilizes in its processes.

AB & I maintained three USTs to store petroleum products and one UST to store solvent. AB & I removed the four USTs between August 1991 and June 1992. Removal and disposal of two of the USTs (the 8,000-gallon capacity gasoline tank and the 550-gallon capacity leaded gasoline tank) were described in two consultant's (Levine-Fricke) reports. Documentation of the removal and disposal of the two remaining USTs (the 8,000-gallon capacity 1,1,1-TCA UST and the 10,000-gallon capacity diesel UST) was reported by AB & I.

In general, analytical results for the soil and groundwater samples collected adjacent to the tanks during the tank removal projects showed detectable concentrations of Total Petroleum Hydrocarbons as gasoline (TPHg), Total Petroleum Hydrocarbons as diesel (TPHd), 1,1-DCA, Chloroethane, and 1,1,1-TCA. Affected soil at each former tank location was excavated until confirmation samples indicated the chemicals of concern were at relatively low concentrations, or to where an obstruction made further excavation impossible or hazardous.

BSK & Associates (BSK) installed four shallow groundwater monitoring wells at the Site in February 1993, one well per former tank location as shown on Figure 2, Site Plan. Soil and groundwater samples revealed soil contamination in the vicinities of the former 500-gallon gasoline tank and the TCA solvent tank, and contaminated groundwater at these two locations as well as the former diesel tank location. The well installation and sampling findings are presented in BSK Report No. P92270.3, dated April 30, 1993.

BSK

#### **TENTH QUARTERLY MONITORING ACTIVITIES - JANUARY 1996**

#### General

Tenth quarterly monitoring of groundwater Monitoring Wells MW-2, MW-3 and MW-4 was performed by BSK personnel on January 18 and 19, 1996, in accordance with the Groundwater Well Monitoring portion of our Proposal No. PR93204.3 of July 29, 1993. As directed by Mr. David Robinson (after meeting with Barney Chan of ACEHD on March 13, 1995), sampling of the groundwater Monitoring Well MW-1, was not performed this quarter. Field procedures and observations are provided in the following text and figures.

#### Field Work

Water samples from site wells were obtained after purging each well of approximately four casing volumes, and allowing eighty percent recovery. Observation of water level, and for immiscible product, was performed using an electric sounder and clear point-source bailer prior to purging. The water level was recorded to the nearest 1/100th of a foot. During purging, the water parameters: pH, temperature and electrical conductivity were monitored and recorded at regular intervals on Well Field Logs. The Well Field Logs are presented in Figures 3 through 5. Water samples for analytical testing were obtained in the order of most to least volatility. Samples were obtained via point-source bailer (Teflon<sup>R</sup> or polyethylene disposable), and transferred to the appropriate sample containers, with preservative as needed. The samples were labeled and placed into a cooler with water-ice or blue ice for delivery to our State-certified analytical laboratory.

Sampling, purging and decontamination waste water was contained on-site in a 55-gallon drum provided by AB & I. Each container was labeled according to the wastewater source, date of accumulation and owner.

#### **Analytical Testing**

Analytical testing of the water samples obtained from the site were performed by BSK State-certified Analytical Laboratories in Fresno, California.

The analyses performed for each contaminant type are those specified by the Tri-Regional Water Board Staff Recommendations of August 10, 1992 and ACDEH. The analyses are:

#### Well MW-2

Chlorinated Solvent by EPA Method 601 Oil and Grease by Methods 5520 C&F TPHgasoline by GCFID-5030 BTEX by EPA Method 602

Well MW-3

TPHgasoline by GCFID-5030 BTEX by Method 602

**BSK** 

BSK Job P92270.3 - 2 - February 12, 1996

#### Well MW-4

TPHgasoline by GCFID-5030 BTEX by Method 602

Samples were submitted to the analytical laboratory utilizing Chain-of-Custody documentation and procedure.

The results of the chemical analyses of groundwater for this quarter, and previous quarterly test results, are summarized in the following tables; water analyses results and related Action Levels are reported in Micrograms per liter (ug/l). The Chemical Test Data Sheets and project Chain-of-Custody documentation are presented in Appendix "A" of this report.

TABLE 1 - ANALYTICAL RESULTS, GROUNDWATER SAMPLES BENZENE, TOLUENE, ETHYLBENZENE, AND XYLENES (BTEX) Results in micrograms per liter (ug/l)

	CONSTI	TUENTS		
Sample Location (Action Level)	Benzene	Toluene	Ethylbenzene	Xylenes
(Action Level)	(1) <sub>1</sub>	(100) <sub>2</sub>	(680)	(1750)
SAMPLE DATE: 1/18/96 and 1/1	9/96 (Tenth Quart	er)		
MW-1				4-
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	0.8	ND	1.2	0.9
SAMPLE DATE: 9/6/95 (Ninth Qu	iarter)			
MW-I				
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	9.4	1.4	6.3	6.2
SAMPLE DATE: 6/23/95 (Eighth (	Quarter)			
MW-I				
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	ND	ND	0.9	1.7
SAMPLE DATE: 3/17/95 (Seventh	Quarter)			
MW-I				
MW-2	4.9	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	ND	ND	ND	ND
SAMPLE DATE: 12/16/94 (Sixth C	<u> </u>		<del></del>	
MW-1	0.6	ND	ND	ND
MW-2	ND	18	ND	ND
MW-3	NĐ	ND	ND	ND
MW-4	0.4	0.4	ND	1.2
SAMPLE DATE: 09/09/94 (Fifth Q	uarter)		<del></del>	
MW-I	ND	ND	ND	ND
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	0.4	ND	0.7	1.3

BSK Job P92270.3 - 3 - February 12, 1996



#### TABLE 1 (CONTINUED)

	CONST	TUENTS		
Sample Location (Action Level)	Benzene (1)	Toluene (100) <sub>2</sub>	Ethylbenzene (680)	Xylenes (1750),
SAMPLE DATE: 06/10/94 (Four	th Quarter)			
MW-I	ND	ND	ND	ND
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	4.3	ND	1.8	4.3
SAMPLE DATE: 03/04/94 (Third	l Quarter)	<u></u>	<u></u>	
MW-I	1.1	ND	ND	ND
MW-2	ND	ND	ND	3.6
MW-3	ND	ND	ND	ND
MW-4	ND	0.9	ND	1.1
SAMPLE DATE: 12/03/93 (Second	nd Quarter)		<del></del>	
MW-1	ND	ND	ND	ND
MW-2	ND	250	19	5.1
MW-3	ND	ND	ND	ND
MW-4	ND	ND	1.4	2.8
SAMPLE DATE: 08/20/93 (First	_ <del>-</del>		······································	<del> </del>
MW-I	2.2	3.7	4.5	17
MW-2	2.9	4.2	6.3	25
MW-3	7.2	9.3	8.6	31
MW-4	5.6	4.9	7.5	22
SAMPLE DATE: 03/10/93 (Initial	al Well Installation S	Sampling)		·
MW-I	0.6	ND	ND	ND
MW-2	ND	0.8	ND	ND
MW-3	ND	ND	ND	ND
MW-4	1.0	2.0	7.6	19

ND - None Detected

1 - California Department Of Health Services Drinking Water Standard, Revised 10/23/91

2 - California DOHS Action Level, 7/1/92

-- - Not Sampled

## TABLE 2 - ANALYTICAL RESULTS, GROUNDWATER SAMPLES TOTAL PETROLEUM HYDROCARBONS (TPH) AS GASOLINE AND DIESEL, TOTAL AND HYDROCARBON OIL AND GREASE TOTAL LEAD, AND VOLATILE HALOCARBONS

Results in micrograms per liter (ug/l)

3 %/>			CONST	ITUENTS	
Sample Location (Action Level)	Gasoline (NA)	Diesel (100) <sub>1</sub>	& Grease (NA)	Hydrocarbon Oil & Grease (NA)	Volatile Halocarbons (Determined by Compound)
SAMPLE DATE: 1/	18/96 and 1	/19/96 (T	enth Quart	er)	
MW-1					 
MW-2	120(4)		1	ND	 ND
MW-3	ND				 
MW-4	90(4)				 ~~

**BSK** 

BSK Job P92270.3

#### TABLE 2 (CONTINUED)

Sample	apound)
(Action Level)         (NA)         (100) <sub>1</sub> (NA)         (NA)         (50)         (Determined by Constant)           SAMPLE DATE: 9/6/95 (Ninth Quarter)         ————————————————————————————————————	apound)
SAMPLE DATE: 9/6/95 (Ninth Quarter)	
MW-1	(NA)
MW-2         110 <sub>(4)</sub> ND         ND          ND           MW-3         ND	(NA)
MW-3 ND SAMPLE DATE: 3/17/95 (Seventh Quarter)  MW-1 ND ND Chloroethane - 0.9  MW-4 180 <sub>(4)</sub>	(NA)
MW-3         ND  -	(NA)
SAMPLE DATE: 6/23/95 (Eighth Quarter)         MW-1  <	(NA)
MW-1	(NA)
MW-2 190 <sub>(4)</sub> ND ND Chloroethane - 0.9  MW-3 ND  MW-4 180 <sub>(4)</sub> SAMPLE DATE: 3/17/95 (Seventh Quarter)  MW-1	(NA)
MW-3 ND SAMPLE DATE: 3/17/95 (Seventh Quarter)	(NA)
MW-3 ND SAMPLE DATE: 3/17/95 (Seventh Quarter)	· · · · · /
SAMPLE DATE: 3/17/95 (Seventh Quarter)  MW-1	<u>`                                    </u>
SAMPLE DATE: 3/17/95 (Seventh Quarter)  MW-1	
[ <del> </del>	
MW-2 320 <sub>(4)</sub> 1 Chloroethane - 2.4	(NA)
MW-3 ND	<u>`</u>
MW-4 62 <sub>(4)</sub> ND	
SAMPLE DATE: 12/16/94 (Sixth Quarter)	
MW-1 180 <sub>(5)</sub>	····
MW-2 130 <sub>(4)</sub> ND ND ND	·
MW-3 ND	
MW-4 100 86	<del></del>
SAMPLE DATE: 09/09/94 (Fifth Quarter)	
MW-1 ND	
MW-2 830 <sub>(2)</sub> 2 2 Chloroethane - 1.4	
MW-3 ND 1,1-Dichloroethane	0.8(0.5)
MW-3 ND ND	
SAMPLE DATE: 06/10/94 (Fourth Quarter)	<del></del>
NOV I	
<del></del>	(NT 1 N
1,1-Dichloroethane - ( 1,1,1-Trichloroethane -	$0.6(0.5)_3$
MW-3 ND	<del></del>
MW-4 460 ND	
SAMPLE DATE: 03/04/94 (Third Quarter)	
MW-1 710	
MW-2 420 ND ND Chloroethane - 3.70	(NA)
MW-3 ND	
MW-4 50 ND	
SAMPLE DATE: 12/03/93 (Second Quarter)	
MW-1 3200 <sub>(3)</sub>	
MW-2 900 ND ND Chloroethane - 3.80	(NA)
MW-3 80	
MW-4 1100 ND	
SAMPLE DATE: 08/20/93 (First Quarter)	<del></del>
MW-1 2100 <sub>(t)</sub>	
MW-2 720 <sub>(2)</sub> ND ND Chloroethane - 4.7(	NA)

- 5 -

BSK

#### TABLE 2 (CONTINUED)

			CONST	ITUENTS		
Sample Location	TPH Gasoline	TPH Diesel	Total Oil		Total	Volatile
	(NA)	(100) <sub>1</sub>	(NA)	Oil & Grease (NA)	Lead (50)	Halocarbons (Determined by Compound)
MW-3	190					
MW-4	350				ND	
SAMPLE DATE: 03/	10/93 (Initi	al Well Ir	stallation S	ampling)		
MW-1		830				
MW-2	920		1.0	ND		Bromoform - 0.6(100) <sub>2</sub> Chloroethane - 5.0(NA) 1,1-Dichloroethane -1.7(0.5) <sub>3</sub> 1,1,1-Trichloroethane - 6.7(200) <sub>3</sub>
MW-3	ND					-
MW-4	1800				58.0	

ND - None Detected, NA - Not Applicable

- -- Not Tested
- 1 1980 EPA 10-Day Suggested No Adverse Response Level (SNARL)
- 2 EPA Drinking Water Standard, Revised 7/1/92
- 3 California Department of Health Services Drinking Water Standards, Revised 10/23/91

- (1) "Not Diesel-Like", as reported by analytical laboratory
  (2) "Not Gasoline-Like", as reported by analytical laboratory
  (3) "Appears to be heavier than diesel," as reported by analytical laboratory
- (4) Chromatography for this sample is described as inconsistent with the gasoline standard
- (5) Chromatography for this sample is described as inconsistent with the diesel standard



BSK Job P92270.3 February 12, 1996 - 6 -

#### **GROUNDWATER DATA - JANUARY 1996**

#### Regional Hydrogeology

The American Brass & Iron Foundry facility is located on the San Leandro alluvial cone of the East Bay Plain. The upper 400 feet of the San Leandro Cone comprises discontinuous beds of sand and gravel which extend westward under San Francisco Bay, and are capped by confining clay layers. Groundwater in this area is used mainly for industrial and irrigation purposes, but is suitable in quality for most uses. Shallow aquifers of limited extent located throughout the Bay Plain, are often perched and unconfined, and typically yield less than 35 gallons per minute from silty sands. These aquifers are often tapped by wells less than 50 feet in depth and used for local irrigation. These minor aquifers are most susceptible to groundwater pollution (Maslonowski, 1984).

#### **Site Groundwater Conditions**

Based upon the groundwater elevations in the three on-site groundwater monitoring wells (MW-2, MW-3 and MW-4) the direction of groundwater flow is generally in a northeast direction. The calculated hydraulic gradient is about 0.012 ft/ft. The groundwater elevation in each of the three measured on-site wells have increased by 0.61 to 0.77 feet since last reported. A summary of the groundwater data collected to date is listed below in Table 3 and graphically presented on Figure 8.

TABLE 3
SUMMARY OF GROUNDWATER DATA

Well Number	Date Measured	Groundwater Elevation (Feet)	Hydraulio Gradient (ft/ft)	Direction of Groundwater Flow
MW-2 MW-3 MW-4	1/19/96 1/18/96 1/18/96	3.56 2.46 2.37	0.012 (1)	Northeast (1)
MW-2 MW-3 MW-4	6/9/95	2.80 1.85 1.60	0.010 (1)	Northeast (1)
MW-2 MW-3 MW-4	6/23/95	3.05 2.31 2.04	0.008 (1)	Northeast (1)
MW-2 MW-3 MW-4	3/17/95	3.79 3.05 2.93	0.007 (1)	Northeast (1)
MW-1 MW-2 MW-3 MW-4	12/16/95	3.65 3.30 2.69 2.48	0.007 (1) 0.005 (2)	Northeast (1) Northeast (2)

**BSK** 

BSK Job P92270.3 - 7 - February 12, 1996

#### TABLE 3 (CONTINUED)

Well Number	Date Measured	Groundwater Elevation (Feet)	Hydraulic Gradient (ft/ft)	Direction of Groundwater Flow
MW-1 MW-2 MW-3 MW-4	9/9/94	2.14 2.38 1.74 1.43	0.008 (1) 0.003 (2)	Northeast (1) North-Northwest (2)
MW-1 MW-2 MW-3 MW-4	6/10/94	2.55 2.73 2.12 1.78	0.008 (1) 0.002 (2)	Northeast (1) North-Northwest (2)
MW-1 MW-2 MW-3 MW-4	3/4/94	1.29 3.14 2.54 2.25	0.007 (1) 0.005 (2)	Northeast (1) West (2)
MW-1 MW-2 MW-3 MW-4	12/3/93	2.04 2.39 1.72 1.47	0.008 (1) 0.003 (2)	Northeast (1) Northwest-West (2)
MW-1 MW-2 MW-3 MW-4	8/20/93	2.05 2.30 1.55 1.29	0.008 (1) 0.003 (2)	Northeast (1) Northwest (2)
MW-1 MW-2 MW-3 MW-4	3/10/93	2.29 3.41 2.53 3.45	0.004 (1) 0.003 (2)	North-Northwest (1) West (2)

- (1) Based upon a three point solution using wells MW-2, MW-3 and MW-4.
- (2) Based upon a three point solution using wells MW-1, MW-2 and MW-3.

#### **FINDINGS**

Petroleum hydrocarbons as gasoline (TPH-g) were detected at levels of 120 ug/l and 90 ug/l in groundwater samples collected from the groundwater Monitor Wells MW-2 and MW-4, respectively. Petroleum hydrocarbons as gasoline were reported as none detected in the groundwater samples collected from MW-3. Benzene, ethylbenzene, and total xylenes were detected at 0.8, 1.2, and 0.9 ug/l, respectively, in the groundwater sample collected from MW-4. Toluene and volatile halocarbons were reported as none detected in the groundwater samples collected from MW-2. Total oil and grease was detected at 1 mg/l in the groundwater sample collected from MW-2, however, hydrocarbon oil and grease was not detected in the same sample.

BSK

#### RECOMMENDATIONS

Since MW-1 will no longer be monitored, the well should be properly closed. Assessment of the lateral extent of shallow groundwater contamination should be considered in the vicinity of Wells MW-2 and MW-4.

Quarterly monitoring of the three wells installed should continue to be performed to assess contaminant concentration fluctuation with respect to groundwater level, gradient and flow direction. Groundwater samples collected from the quarterly monitoring of Well MW-4, should be analyzed for chlorinated hydrocarbons by EPA Method 601.

#### **LIMITATIONS**

This groundwater monitoring well report has been prepared for the exclusive use of American Brass & Iron Foundry Company. Unauthorized use of or reliance on the information contained in this report by others, unless given express written consent by BSK & Associates, is strictly prohibited.

The findings and conclusions presented in this report are based on field observations, and on data obtained from the sources listed in this report. This report has been prepared in accordance with generally accepted methodologies and standards of practice for the area. No other warranty, either expressed or implied, is made as to the findings or conclusions included in this report.

The findings of this report are valid as of the present. The passage of time, natural processes or human intervention on the property or adjacent properties, and changes in the regulations can cause changed conditions which can invalidate the findings and conclusions in this report.

This report is neither certification nor guarantee that the property is free of, or contains hazardous substance contamination, other than that mentioned in the report.


#### DISTRIBUTION

A copy of this report should be forwarded by the client to the Alameda County Department of Environmental Health for their review. An extra copy of this report has been forwarded to American Brass and Iron Foundry for this purpose.

Respectfully Submitted, BSK & Associates

**BSK** 

BSK Job P92270.3 - 9 - February 12, 1996






Figure: 3

#### WELL FIELD LOG

Well Observation: x Date: 1/19/96 Sample Collection: x Date: 1/19/96

Project Name: American Brass & Iron

Location: Oakland, CA
Personnel: RS/BS
Weather: Clear

#### WELL INFORMATION:

Measurement Technique	Solinst Electric Water Sounder		
Groundwater Elevation (feet)	+3.56	Purge Rate	2.5 GPM
Reference Elevation - feet(TOC)	+7.80	Purge End	9:58
Water Volume (gallons)	8.3	Purge Begin	9:50
Well Depth (feet)	17.0		
Depth to Water - feet(TOC)	4.24	Purge Method	Submersible Pump
Well Number	MW-2	Date Purged	1/19/96

#### **IMMISCIBLE LAYERS:**

**Top:** None Observed, No Odor

Bottom: Grey, Cloudy with fines, No Odor

**Detection Method:** Visual

Collection Method: Point-Source Bailer

#### WELL DEVELOPMENT/PURGE DATA:

TIME	VOLUME REMOVED (gallons)	ELECTRICAL CONDUCTIVITY (Micromhos)	рН	TEMP. (°F)	COLOR/COMMENTS
9:53	5.0	1134	7.80	64.0	Cloudy
9:55	10.0	1255	7,23	67.1	Cloudy
9:56	15.0	1272	7.06	67.9	Cloudy
9:58	20.0	1271	7.03	68.0	Clearing

#### SAMPLE COLLECTION DATA:

Sampling Equipment: Teflon Point-Source Bailer

TIME	ANALYSIS	AMOUNT/CONTAINER USED	SAMPLE INTERVAL
10:08	EPA 601	2-40 ml glass vials with HCl	±5'
п	TPH-G and BTEX	2-40 ml glass vials with HCl	и
11	Total and Hydrocarbon Oil & Grease	1-liter amber glass bottle with H <sub>2</sub> SO <sub>4</sub>	ч






Figure: 4

#### WELL FIELD LOG

Well Observation: x Date: 1/18/96 Sample Collection: x Date: 1/18/96

Project Name: American Brass & Iron

Location: Oakland, CA
Personnel: RS/BS

Weather: Cloudy, Windy

#### WELL INFORMATION:

Well Number	MW-3	Date Purged	1/18/96
Depth to Water - feet(TOC)	7.37	Purge Method	Submersible Pump
Well Depth (feet)	19.0		,
Water Volume (gallons)	2.0	Purge Begin	10:20
Reference Elevation - feet(TOC)	+9.83	Purge End	10:28
Groundwater Elevation (feet)	+2.46	Purge Rate	I.0 GPM
Measurement Technique		Solinst Electric Water	er Sounder

#### **IMMISCIBLE LAYERS:**

**Top:** None observed, no odor **Bottom:** None observed, no odor

**Detection Method:** Visual

Collection Method: Point-Source Bailer

#### WELL DEVELOPMENT/PURGE DATA:

TIME	VOLUME REMOVED (gallons)	ELECTRICAL CONDUCTIVITY (Micromhos)	рН	TEMP. (°F)	COLOR/COMMENTS
10:23	2.0	1780	6.80	60.9	Clear
10:24	4,0	1980	7.00	64.6	Clear
10:26	6.0	2170	7.07	66.3	Clear
10:28	8.0	2220	7.14	67.7	Clear

#### SAMPLE COLLECTION DATA:

Sampling Equipment: Teflon Point-Source Bailer

TIME	ANALYSIS	AMOUNT/CONTAINER USED	SAMPLE INTERVAL
10:35	ТРНg, ВТЕХ	2-40 ml glass vials with Hel	10'

Field Observations: None



#### WELL FIELD LOG

Well Observation: x Date: 1/18/96 Sample Collection: x Date: 1/18/96

Project Name: American Brass & Iron

Location: Oakland, CA.
Personnel: RS/BS

Weather: Cloudy, Windy

#### WELL INFORMATION:

Well Number	MW-4	Date Purged	1/18/96	
Depth to Water - feet(TOC)	7.15	Purge Method	Clear Point-Source	
Well Depth (feet)	24.5		Bailer	
Water Volume (gallons)	3.0	Purge Begin	10:55	
Reference Elevation - feet(TOC)	+9.52	Purge End	11:03	
Groundwater Elevation (feet)	+2.37	Purge Rate	1.5 GPM	
Measurement Technique	Solinst Electric Water Sounder			

#### **IMMISCIBLE LAYERS:**

**Top:** None Observed, Faint Hydrocarbon Odor

Bottom: Floating Particles Observed, Faint Hydrocarbon Odor

**Detection Method:** Visual

Collection Method: Clear Point-Source Bailer

#### WELL DEVELOPMENT/PURGE DATA:

TIME	VOLUME REMOVED (gallons)	ELECTRICAL CONDUCTIVITY (Micrombos)	pН	TEMP. (°F)	COLOR/COMMENTS
10:58	3.0	760	9.23	59.4	Grayish with Hydrocarbon Odor
11:00	6.0	530	8.30	63.9	Clearing with Hydrocarbon Odor
11:01	9.0	514	7.92	64.5	Clear with Hydrocarbon Odor
11:03	12.0	513	7.67	64.9	Clear with slight Odor


#### SAMPLE COLLECTION DATA:

Sampling Equipment: Teflon Point-Source Bailer


TIME	ANALYSIS	AMOUNT/CONTAINER USED	SAMPLE INTERVAL
11:05	трн-д & втех	2-40 ml glass vials with HCl	± 10'

Field Observations: None





### SUMMARY OF GROUNDWATER ELEVATIONS



BSK Job No. P92270.3 JANUARY 1996 FIGURE 7

**BSK** 

APPENDIX "A"





FIGURE: A-1

BSK-Pleasanton AB & I (Oakland)

Date Sampled : 01/19/96

Time Sampled : 1008

Date Received : 01/22/96
Date of Analysis : 01/25/96

Report Issue Date: 02/02/96

Case Number : Ch960272

Lab ID Number : 0272 Sample Type: LIQUID

Project Number : None Sample Description: MW-2

#### Analyses for BTEX by EPA Method 8020 and TPH(G) by EPA Method 8015 Prepared by Method 5030

Results Reported in Micrograms per Liter (ug/L)

Compound	Results	DLR
Benzene Toluene Ethylbenzene Total Xylene Isomers Total Petroleum Hydrocarbons (G)	ND ND ND ND	0.3 0.3 0.3 0.3
		I

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

#### NOTE:

Hydrocarbons in the gasoline boiling point range are reported, in accordance with the method, <u>as gasoline</u>.

Chromatography for this sample is described as inconsistent with the gasoline standard.

#### LEGEND:

DLR: Datection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences may result in higher detection limits.

ND: None Detected

## BSK ANALYTICAL LABORATORIES

BSK-Pleasanton AB & I (Oakland)

Date Sampled : 01/19/96

FIGURE: A-2

Time Sampled : 1008

Date Received : 01/22/96 Date of Analysis : 01/25/96 Report Issue Date: 02/02/96

Case Number : Ch960272

Lab ID Number : 0272

Project Number : None Sample Description: MW-2 Sample Type: LIQUID

## Analyses for Volatile Halocarbons by EPA Method 601 Prepared by EPA Method 5030

Results Reported in Micrograms per Liter (µq/L)

Compounds	Results	DLR	Compound	Results	DLR
Bromodichloromethane Bromoform Bromomethane Carbon tetrachloride Chlorobenzene Chloroethane Chloroform Chloromethane Dibromochloromethane 1,2-Dichlorobenzene 1,3-Dichlorobenzene	ND N	0.5 0.5 1.0 0.5 0.5 0.5 0.5 0.5	1,2-Dichloroethane 1,1-Dichloroethene cis-1,2-Dichloroethene trans-1,2-Dichloroethene 1,2-Dichloropropane cis-1,3-Dichloropropene trans-1,3-Dichloropropene trans-1,3-Dichloropropene trans-1,2-tetrachloroethane 1,1,2,2-tetrachloroethane 1,1,1-Trichloroethane	Results  ND	DLR 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5 0.5
1,4-Dichlorobenzene Dichlorodifluoromethane 1,1-Dichloroethane	ND ND	0.5 2.0 0.5	1,1,2-Trichloroethane Trichloroethene Trichlorofluoromethane Vinyl chloride	ND ND ND	0.5 0.5 0.5 1.0

ple DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

DLR: Detection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences
may result in higher detection limits.

ND: None Detected



FIGURE: A-3

BSK-Pleasanton AB & I (Oakland)

Date Sampled : 01/19/96 Time Sampled : 1008

Time Sampled : 1008
Date Received : 01/22/96 Date of Analysis: 01/26/96

Report Issue Date: 02/02/96

Case Number : Ch960272

Lab ID Number : 0272 Sample Type: LIQUID

Project Number : None Sample Description: MW-2

#### Analyses For Total and Hydrocarbon Oil & Grease By EPA Methods 413.2 & 418.1

Results Reported in Milligrams Per Liter (mg/L)

Analyte	Results	DLR
Total Oil and Grease Hydrocarbon Oil and Grease	1 ND	1 1

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

DLR: Detection Limit for the Purposes of Reporting. Exceptional sample conditions or matrix interferences may result in higher detection limits.

ND: None Detected

## BSK ANALYTICAL LABORATORIES

BSK-Pleasanton

American Brass & Iron

Date Sampled : 01/18/96

FIGURE: A-4

Time Sampled : 1035

Date Received : 01/22/96 Date of Analysis : 01/25/96

Report Issue Date: 02/01/96

Case Number : Ch960262 Lab ID Number : 0262-1

Project Number : P92270.3

Sample Description: MW-3

Sample Type: LIQUID

#### Analyses for BTEX by EPA Method 8020 and TPH(G) by EPA Method 8015 Prepared by Method 5030

Results Reported in Micrograms per Liter (ug/L)

Compound	Results	DLR
Benzene Toluene Ethylbenzene Total Xylene Isomers Total Petroleum Hydrocarbons (G)	ND ND ND ND	0.3 0.3 0.3 0.3

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

#### NOTE:

Hydrocarbons in the gasoline boiling point range are reported, in accordance with the method, as gasoline.

#### LEGEND:

DLR: Detection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences
may result in higher detection limits.

ND: None Detected



BSK-Pleasanton American Brass & Iron

Date Sampled : 01/18/96

FIGURE: A-5

Time Sampled : 1105

Date Received : 01/22/96 Date of Analysis : 01/25/96

Report Issue Date: 02/01/96

Case Number : Ch960262 Lab ID Number : 0262-2

Sample Type: LIQUID

Project Number : P92270.3

Sample Description: MW-4

#### Analyses for BTEX by EPA Method 8020 and TPH(G) by EPA Method 8015 Prepared by Method 5030

Results Reported in Micrograms per Liter (ug/L)

Compound	Results	DLR
Benzene Toluene Ethylbenzene Total Xylene Isomers Total Petroleum Hydrocarbons (G)	0.8 ND 1.2 0.9	0.3 0.3 0.3 0.3

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

#### NOTE:

Hydrocarbons in the gasoline boiling point range are reported, in accordance with the method, <u>as gasoline</u>.

Chromatography for this sample is described as inconsistent with the gasoline standard because late (heavy) boiling point range is missing or significantly reduced.

#### LEGEND:

DLR: Detection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences may result in higher detection limits.

ND: None Detected

1414 Stanislaus Street Fresno, CA 93706 (209) 485-8310 (800) 877-8310 (209) 485-6935 FAX

## Analyses Request / Chain of Custody

BSK Log Number: 0272

Analytical Due Date:

3696

FIGURE:

Shaded areas for LAB use only Requested Analyses

			Services							1		Ξ.	• .		٠,		. 1	
Clie	nt Name	AB	SI (C	BAKLAN	D	Report Attention. Rife	nat Sales	Phone #		BTEX	_	Hydrocarbun Grease						
Add	lress	40	BSK	& Asso	K.	Project , Quote or PO# PO	12270.3	FAX#		Bi	60	roc						
City	, State,	ζφ F	leasan	BAKLAN & Asso ton, Ca		Copy to.		System#		`	S	& Hys						
Samp	le Type	only	Date Sampled	Time Sampled	Sampled by: R	Sample Description/Loca	ation	Comment Station Co	,	PH-9	P P A	Total S						
1	t	5	V19/96	10:08	MW -			<u></u>		X	X	X				1		-
7	1 1 1														_			
	5.					·····							<del>-   -</del>			<del> </del>		-
<u> </u>	1 2 3 4							·					_   _			+-		
	-													1		-		_
1 1		//:																
																		_
. ;														1		<del> </del>		_
				<del> </del>	<u> </u>	<del></del>						_		-		-	-	_
	• • • •															<u> </u>		_
									-									
	1																	_
		-		<del> </del>					<del></del>					-		╂	<del>  </del>	_
ļ.:	-	7 1		<del> </del>				······································						-		╃		_
		i, .		<u> </u>														
	Matr			S - Solid G - Ga ociated with Samp	oles: E	Additional Ser tush Priority: []-2 Day mal Chain of Custody	y [ ] - 5 Day	Additional Se	rvices Authorized by	y:		Date:	ent Recei	<i>E</i>	Deliver mount: nitials		* : * *	
					{ 1-ro	mai Chain of Custody	1 1 - Ac mate backage	(Si	gnature)				ot #	<del>1</del>				ئہ
			Sign	ature (	0.0	Print	Name		Company				<del></del>	T	Date		Time	
Requ	uested /	Relinqui	shed by	Land	Date:	RIPMAT	SAUEM	BBK-f	2					1/2	2/9	48	OO	
Rece	eived / F	ehnquis	hed by:	$\bigcirc$			\											
Rece	ived / F	elinquis	hed by:															
200	irrad / D	alin autic	and her						· · · · · · · · · · · · · · · · · · ·							+		-

135E-Col

Gerald A. Pangilinan

Received for Laboratory by:

1414 Stanislaus Street Fresno, CA 93706 (209) 485-8310 (800) 877-8310

## Carlo

### Analyses Request / Chain of Custody

BSK Log Number: - C

Analytical Due Date:	1/	31	195
----------------------	----	----	-----

FIGURE:

(209) 485-6935 FAX Requested Analyses Shaded areas for LAB use only Environmental Services Chent Name RICAN BRASS & IRON

Address Clo BSK-P Phone # Project , Quote or PO # FAX# City, State, Zip System# LAB use only Sampled by: Date Time Comment or Sample Type Sampled Sampled Sample Description/Location Station Code 1035 MW-3 11:05 Matrix Type: L-Liquid S-Solid G-Gas Additional Services: Additional Services Authorized by: Payment Received with Delivery Type of Hazards Associated with Samples: Rush Priority: []-2 Day []-5 Day Amount: \$ [ ] - Formal Chain of Custody [ ] - QC Data package Check # \_\_ Initials Reciept # \_\_ (Signature) Print Name Company Requested / Relinquished by. Received / Relinquished by. Received / Relinquished by: Received / Relinquished by:

SARA K. DHILLOW