

April 17, 1997

Mr. Barney Chan Alameda County Health Care Services Agency 1131 Harbor Bay Parkway Room 250 Alameda, CA 94502 11th

Subject: Groundwater Monitoring Reports/Closure Request

Dear Mr. Chan:

Please find enclosed BSK & Associates Groundwater Monitoring Reports for our site located at 7825 San Leandro Street, Oakland. The report represents the Eleventh and Twelfth quarterly monitoring results of the groundwater at this site. As indicated by the results, it appears that contamination levels of suspected compounds are below State and Local requirements or at non detection levels.

As stated in our last correspondence, we are formally requesting that our case be reviewed for site closure. It is our understanding that additional information is required in order to complete your review. If convenient, I would like to meet in the next two week to discuss any issues pertaining to the Underground Storage Tanks.

Your response would be appreciated on this matter, please feel free in contacting me at (510) 632 - 3467, extension 211.

Sincerely;

Dave Robinson

Environmental Engineering Manager

cc: Eddy So, SRWQCB

BOHING TOUST 16

PROTECTION AND AND

Eleventh Quarterly Groundwater Monitoring Report - April 1996 AB&I Foundry 7825 San Leandro Street Oakland, California

BSK & ASSOCIATES

GEOTECHNICAL CONSULTANTS, INC.

BSK JOB NO. P92270.3

May 21, 1996





1181 Quarry Lane, Building 300 Pleasanton, CA 94566 (510) 462-4000 • FAX (510) 462-6283

May 21, 1996

BSK JOB NO. P92270.3

AB&I Foundry 7825 San Leandro Street Oakland, California 94621

Attention: Mr. David Robinson

Environmental Engineering Manager

Subject: Eleventh Quarterly Groundwater

Monitoring Report - April 1996

AB&I Foundry

7825 San Leandro Street Oakland, California

As requested and authorized, BSK & Associates (BSK) has performed the Eleventh quarterly monitoring of three shallow groundwater Monitoring Wells MW-2 through MW-4 at AB&I Foundry, located at 7825 San Leandro Street, Oakland, California (Site). This report presents the project background, groundwater data obtained during this sampling event as well as previous data, conclusions based on this quarter's data, and recommendations for further action, as appropriate. The Site location is shown on the Vicinity Map, Figure 1.

BSK appreciates this opportunity to continue to be of service to AB&I. If there are questions or comments regarding this report, please contact the undersigned.

Respectfully submitted, BSK & Associates

Mut Chi

Martin B. Cline, R.G.

Geologist

Alex Y. Eskandari, P.E.

Project Manager C.E. #38101

AYE\MC:pc (ENVAB&NP92270-3.011)

Distribution:

AB&I Foundry (3 copies)

TABLE OF CONTENTS

TEXT		<u>PAGE</u>
ELEVENTH	QUARTERLY MONITORING ACTIVITIES - APRIL 1996	2
General Field Work .	sting	2 2
Regional Hyd	ATER DATA - APRIL 1996	7
<u>FINDINGS</u> .		8
<u>RECOMMEN</u>	NDATIONS	9
<u>LIMITATION</u>	<u> </u>	9
DISTRIBUTI	<u>on</u>	9
TABLES		
Table 1	Analytical Results, Groundwater Samples Benzene, Toluene, Ethylbenzene and Xylenes	3
Table 2	Analytical Results, Groundwater Samples Total Petroleum Hydrocarbons (TPH) as Gasoline and Diesel Total and Hydrocarbons Oil and Grease Total Lead, and Volatile Halocarbons	4
Table 3	Summary of Groundwater Data	7
FIGURES		
Figure 1 Figure 2 Figures 3 - 5 Figure 6 Figure 7	Vicinity Map Site Plan Well Field Logs Groundwater Elevation Contour Map Summary of Groundwater Elevations	
APPENDICE Appendix "A'		
Figures A-1 t	-	



ELEVENTH QUARTERLY GROUNDWATER MONITORING REPORT - APRIL 1996 AB&I FOUNDRY 7825 SAN LEANDRO STREET OAKLAND, CALIFORNIA

Introduction

This quarterly monitoring report has been prepared to meet Alameda County Department of Environmental Health (ACDEH) requirements for status updates of groundwater at the Site following the removal of four Underground Storage Tanks (USTs) during 1991 and 1992, as initially presented in their letter of October 2, 1992, to David Robinson of AB&I Foundry.

Background

AB & I has been operating at its present location for more than eighty years. AB & I's current activities include the manufacture of cast iron pipe and fittings. The facility accepts scrap iron and steel, which it stockpiles on-site, and utilizes in its processes.

AB & I maintained three USTs to store petroleum products and one UST to store solvent. AB & I removed the four USTs between August 1991 and June 1992. Removal and disposal of two of the USTs (the 8,000-gallon capacity gasoline tank and the 550-gallon capacity leaded gasoline tank) were described in two consultant's (Levine-Fricke) reports. Documentation of the removal and disposal of the two remaining USTs (the 8,000-gallon capacity 1,1,1-TCA UST and the 10,000-gallon capacity diesel UST) was reported by AB & I.

In general, analytical results for the soil and groundwater samples collected adjacent to the tanks during the tank removal projects showed detectable concentrations of Total Petroleum Hydrocarbons as gasoline (TPHg), Total Petroleum Hydrocarbons as diesel (TPHd), 1,1-DCA, Chloroethane, and 1,1,1-TCA. Affected soil at each former tank location was excavated until confirmation samples indicated the chemicals of concern were at relatively low concentrations, or to where an obstruction made further excavation impossible or hazardous.

BSK & Associates (BSK) installed four shallow groundwater monitoring wells at the Site in February 1993, one well per former tank location as shown on Figure 2, Site Plan. Soil and groundwater samples revealed soil contamination in the vicinities of the former 500-gallon gasoline tank and the TCA solvent tank, and contaminated groundwater at these two locations as well as the former diesel tank location. The well installation and sampling findings are presented in BSK Report No. P92270.3, dated April 30, 1993.



BSK Job P92270.3 - 1 - May 21, 1996

ELEVENTH QUARTERLY MONITORING ACTIVITIES - APRIL 1996

General

Eleventh quarterly monitoring of groundwater Monitoring Wells MW-2, MW-3 and MW-4 was performed by BSK personnel on April 26, 1996, in accordance with the Groundwater Well Monitoring portion of our Proposal No. PR93204.3 of July 29, 1993. As directed by Mr. David Robinson (after meeting with Barney Chan of ACEHD on March 13, 1995), sampling of the groundwater Monitoring Well MW-1, was not performed this quarter. Field procedures and observations are provided in the following text and figures.

Field Work

Water samples from site wells were obtained after purging each well of approximately four casing volumes, and allowing eighty percent recovery. Observation of water level, and for immiscible product, was performed using an electric sounder and clear point-source bailer prior to purging. The water level was recorded to the nearest 1/100th of a foot. During purging, the water parameters: pH, temperature and electrical conductivity were monitored and recorded at regular intervals on Well Field Logs. The Well Field Logs are presented in Figures 3 through 5. Water samples for analytical testing were obtained in the order of most to least volatility. Samples were obtained via point-source bailer (Teflon^R or polyethylene disposable), and transferred to the appropriate sample containers, with preservative as needed. The samples were labeled and placed into a cooler with water-ice or blue ice for delivery to our State-certified analytical laboratory.

Sampling, purging and decontamination waste water was contained on-site in a 55-gallon drum provided by AB & I. Each container was labeled according to the wastewater source, date of accumulation and owner.

Analytical Testing

Analytical testing of the water samples obtained from the site were performed by BSK State-certified Analytical Laboratories in Fresno, California.

The analyses performed for each contaminant type are those specified by the Tri-Regional Water Board Staff Recommendations of August 10, 1992 and ACDEH. The analyses are:

Well MW-2

Chlorinated Solvent by EPA Method 601 Oil and Grease by EPA Methods 413.2 and 418.1 TPHgasoline by GCFID-5030 BTEX by EPA Method 602



Well MW-3 TPHgasoline by GCFID-5030 BTEX by Method 602

Well MW-4
TPHgasoline by GCFID-5030
BTEX by Method 602

Samples were submitted to the analytical laboratory utilizing Chain-of-Custody documentation and procedure.

The results of the chemical analyses of groundwater for this quarter, and previous quarterly test results, are summarized in the following tables; water analyses results and related Action Levels are reported in Micrograms per liter (ug/l). The Chemical Test Data Sheets and project Chain-of-Custody documentation are presented in Appendix "A" of this report.

TABLE 1 - ANALYTICAL RESULTS, GROUNDWATER SAMPLES
BENZENE, TOLUENE, ETHYLBENZENE, AND XYLENES (BTEX)
Results in micrograms per liter (ug/l)

	CONSTI	TUENTS		
Sample Location (Action Level)	Benzene (1) ₁	Toluene (100) ₂	Ethylbenzene (680) _i	Xylenes (1750) _i
SAMPLE DATE: 4/26/96				
MW-1				
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	ND	ND	ND	ND
SAMPLE DATE: 1/18/96 and 1/1	9/96 (Tenth Quarter)			
MW-1				
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	0.8	ND	1.2	0.9
SAMPLE DATE: 9/6/95 (Ninth C	(uarter)	<u> </u>		
MW-1				
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	9.4	1.4	6.3	6.2
SAMPLE DATE: 6/23/95 (Eighth	Quarter)			
MW-1				
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	ND	ND	0.9	1.7
SAMPLE DATE: 3/17/95 (Sevent	h Quarter)		· · · · · · · · · · · · · · · · · · ·	
MW-1				
MW-2	4.9	ND	ND	ND

BSK Job P92270.3 - 3 - May 21, 1996

	CONSTI	TUENTS		
Sample Location	Benzene	Toluene	Ethylbenzene	Xylenes
(Action Level)	(1) ₁	(100) ₂	(680)	(1750) ₁
MW-3	ND	ND	ND	ND
MW-4	ND	ND	ND	ND
SAMPLE DATE: 12/16/94 (Sixth Q	uarter)			
MW-1	0.6	ND	ND	ND
MW-2	ND	18	ND	ND
MW-3	ND	ND	ND	ND
MW-4	0.4	0.4	ND	1.2
SAMPLE DATE: 09/09/94 (Fifth Qu	uarter)			
MW-1	ND	ND	ND	ND
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	0.4	ND	0.7	1.3
SAMPLE DATE: 06/10/94 (Fourth	Quarter)			
MW-1	ND	ND	ND	ND
MW-2	ND	ND	ND	ND
MW-3	ND	ND	ND	ND
MW-4	4.3	ND	1.8	4.3
SAMPLE DATE: 03/04/94 (Third O	Quarter)			
MW-1	1.1	ND	ND	ND
MW-2	ND	ND	ND	3.6
MW-3	ND	ND	ND	ND
MW-4	ND	0.9	ND	1.1
SAMPLE DATE: 12/03/93 (Second	Quarter)			
MW-1	ND	ND	ND	ND
MW-2	ND	250	19	5.1
MW-3	ND	ND	ND	ND
MW-4	ND	ND	1.4	2.8
SAMPLE DATE: 08/20/93 (First Q				
MW-1	2.2	3.7	4.5	17
MW-2	2.9	4.2	6.3	25
MW-3	7.2	9.3	8.6	31
MW-4	5.6	4.9	7.5	22
SAMPLE DATE: 03/10/93 (Initial	Well Installation S	ampling)		,
MW-1	0.6	ND	ND	ND
MW-2	ND	0.8	ND	ND
MW-3	ND	ND	ND	ND
MW-4	1.0	2.0	7.6	19

ND None Detected

California Department Of Health Services Drinking Water Standard, Revised 10/23/91 California DOHS Action Level, 7/1/92

2

Not Sampled

BSK Job P92270.3 - 4 -May 21, 1996



TABLE 2 - ANALYTICAL RESULTS, GROUNDWATER SAMPLES TOTAL PETROLEUM HYDROCARBONS (TPH) AS GASOLINE AND DIESEL, TOTAL AND HYDROCARBON OIL AND GREASE TOTAL LEAD, AND VOLATILE HALOCARBONS

Results in micrograms per liter (ug/l)

***			CONST	TTUENTS		
Sample s	TPH	TPH	Total Oil	Hydrocarbon	Total	Volatile
Location T	Gasoline	Diesel	& Grease	Oil & Grease	Lead	Halocarbons
(Action Level)	52 (1950) 150m (1950a) 1 (1969a) 1960(1950)	(100)	(NA)	(NA)	(50)	(Determined by Compound)
SAMPLE DATE: 4/2	26/96					
MW-1				## W		<u></u>
MW-2	500(4)		ND	ND		ND
MW-3	ND					
MW-4	ND					
SAMPLE DATE: 1/1	8/96 and 1/	19/96 (Te	nth Quarter)		,	
MW-1						
MW-2	120(4)		1	ND		ND
MW-3	ND				1	·
MW-4	90(4)				1	
SAMPLE DATE: 9/6		Quarter)	<u></u>		l	
MW-1	T					Mu
MW-2	110(4)		ND	ND		ND
MW-3	ND					
MW-4	420					
SAMPLE DATE: 6/2		l 1 Ouarter)	<u> </u>			
MW-1			:] <u> </u>	
MW-2	190(4)		ND	ND		Chloroethane - 0.9(NA)
MW-3	ND					
MW-4	180(4)					****
SAMPLE DATE: 3/1		th Ouarte	r)	l		
MW-1					T 1	
MW-2	320(4)			1		Chloroethane - 2.4(NA)
MW-3	ND					
MW-4	62 ₍₄₎				ND	· · · · · · · · · · · · · · · · · · ·
SAMPLE DATE: 12/		l	1			
MW-1					1 ··· ··· r	
	120	180(5)		 NYI)		
MW-2	130 ₍₄₎		ND	ND		ND
MW-3	ND					
MW-4	100				86	
SAMPLE DATE: 09	/09/94 (Fift)	- ,	1			
MW-I		ND				*-
MW-2	830(2)		2	2		Chloroethane - 1.4(NA) 1,1-Dichloroethane - 0.8(0.5)
MW-3	ND					
MW-4	150(2)				ND	

BSK

TABLE 2 (CONTINUED)

			CONST	ITUENTS		
Sample	TPH	TPH	Total Oil	Hydrocarbon	Total	
Location (Action Level)	Gasoline	Diesel	& Grease	Oil & Grease	Lead	Halocarbons
(Action Level)	(NA)	(100) ₁	(NA)	(NA)	(50)	(Determined by Compound)
SAMPLE DATE: 06/	10/94 (Four	-	:)			
MW-1		490	1-			<u></u>
MW-2	920	11	2,000	2,000	-1	Chloroethane - 4.2(NA) 1,1-Dichloroethane - 0.6(0.5) ₃ 1,1,1-Trichloroethane - 0.8(200) ₃
MW-3	ND					
MW-4	460				ND	
SAMPLE DATE: 03/	04/94 (Thir	_)			
MW-I		710				
MW-2	420		ND	ND		Chloroethane - 3.7(NA)
MW-3	ND	- 1			1	<u></u>
MW-4	50				. ND	
SAMPLE DATE: 12	03/93 (Seco	_	er)			
MW-1		3200(3)	~-		1	
MW-2	900		ND	ND	13	Chloroethane - 3.8(NA)
MW-3	80		1		1	
MW-4	1100				ND	<u></u>
SAMPLE DATE: 08/	20/93 (Firs					
MW-1		2100 ₍₁₎				
MW-2	720(2)		ND	ND	-	Chloroethane - 4.7(NA)
MW-3	190				~-	
MW-4	350				ND	
SAMPLE DATE: 03/	10/93 (Initi		stallation S	ampling)		
MW-1		830	-~			
MW-2	920		1.0	ND		Bromoform - $0.6(100)_2$ Chloroethane - $5.0(NA)$ 1,1-Dichloroethane - $1.7(0.5)_3$ 1,1,1-Trichloroethane - $6.7(200)_3$
MW-3	ND					
MW-4	1800		-		58.0	

ND - None Detected, NA - Not Applicable

- -- Not Tested
- 1 1980 EPA 10-Day Suggested No Adverse Response Level (SNARL)
- 2 EPA Drinking Water Standard, Revised 7/1/92
- 3 California Department of Health Services Drinking Water Standards, Revised 10/23/91
- (1) "Not Diesel-Like", as reported by analytical laboratory
- (2) "Not Gasoline-Like", as reported by analytical laboratory
- (3) "Appears to be heavier than diesel," as reported by analytical laboratory
- (4) Chromatography for this sample is described as inconsistent with the gasoline standard
- (5) Chromatography for this sample is described as inconsistent with the diesel standard



BSK Job P92270.3 - 6 - May 21, 1996

GROUNDWATER DATA - APRIL 1996

Regional Hydrogeology

The AB&I Foundry facility is located on the San Leandro alluvial cone of the East Bay Plain. The upper 400 feet of the San Leandro Cone comprises discontinuous beds of sand and gravel which extend westward under San Francisco Bay, and are capped by confining clay layers. Groundwater in this area is used mainly for industrial and irrigation purposes, but is suitable in quality for most uses. Shallow aquifers of limited extent located throughout the Bay Plain, are often perched and unconfined, and typically yield less than 35 gallons per minute from silty sands. These aquifers are often tapped by wells less than 50 feet in depth and used for local irrigation. These minor aquifers are most susceptible to groundwater pollution (Maslonowski, 1984).

Site Groundwater Conditions

Based upon the groundwater elevations in the three on-site groundwater monitoring wells (MW-2, MW-3 and MW-4) the direction of groundwater flow is generally in a northeast direction. The calculated hydraulic gradient is about 0.0096 ft/ft. The groundwater elevation in each of the three measured on-site wells have decreased by 0.20 to 0.28 feet since last reported. A summary of the groundwater data collected to date is listed below in Table 3 and graphically presented on Figure 7.

TABLE 3
SUMMARY OF GROUNDWATER DATA

Well Number	Date Measured	Groundwater Elevation (Feet)	Hydraulic Gradient (ft/ft)	Direction of Groundwater Flow
MW-2 MW-3 MW-4	4/26/96	3.30 2.26 2.09	0.0096 (1)	Northeast (1)
MW-2 MW-3 MW-4	1/19/96 1/18/96 1/18/96	3.56 2.46 2.37	0.012 (1)	Northeast (1)
MW-2 MW-3 MW-4	6/9/95	2.80 1.85 1.60	0.010 (1)	Northeast (1)
MW-2 MW-3 MW-4	6/23/95	3.05 2.31 2.04	0.008 (1)	Northeast (1)
MW-2 MW-3 MW-4	3/17/95	3.79 3.05 2.93	0.007 (1)	Northeast (1)

BSK Job P92270.3 - 7 - May 21, 1996

TABLE 3 (CONTINUED)

Well Number	Date Measured	Groundwater Elevation (Feet)	Hydraulic Gradient (ft/ft)	Direction of Groundwater Flow
MW-1 MW-2 MW-3 MW-4	12/16/95	3.65 3.30 2.69 2.48	0.007 (1) 0.005 (2)	Northeast (1) Northeast (2)
MW-1 MW-2 MW-3 MW-4	9/9/94	2.14 2.38 1.74 1.43	0.008 (1) 0.003 (2)	Northeast (1) North-Northwest (2)
MW-1 MW-2 MW-3 MW-4	6/10/94	2.55 2.73 2.12 1.78	0.008 (1) 0.002 (2)	Northeast (1) North-Northwest (2)
MW-1 MW-2 MW-3 MW-4	3/4/94	1.29 3.14 2.54 2.25	0.007 (1) 0.005 (2)	Northeast (1) West (2)
MW-1 MW-2 MW-3 MW-4	12/3/93	2.04 2.39 1.72 1.47	0.008 (1) 0.003 (2)	Northeast (1) Northwest-West (2)
MW-1 MW-2 MW-3 MW-4	8/20/93	2.05 2.30 1.55 1.29	0.008 (1) 0.003 (2)	Northeast (1) Northwest (2)
MW-1 MW-2 MW-3 MW-4	3/10/93	2.29 3.41 2.53 3.45	0.004 (1) 0.003 (2)	North-Northwest (1) West (2)

⁽¹⁾ Based upon a three point solution using wells MW-2, MW-3 and MW-4.

FINDINGS

Petroleum hydrocarbons as gasoline (TPH-g) were detected at levels of 500 ug/l in the groundwater sample collected from the groundwater Monitor Well MW-2. Total and hydrocarbon oil and grease and volatile halocarbons were reported as none detected in the groundwater samples collected from MW-2. Petroleum hydrocarbons as gasoline and BTEX were reported as none detected in the groundwater samples collected from MW-3 and MW-4.



⁽²⁾ Based upon a three point solution using wells MW-1, MW-2 and MW-3.

RECOMMENDATIONS

Since MW-1 will no longer be monitored, the well should be properly closed. Assessment of the lateral extent of shallow groundwater contamination should be considered in the vicinity of Wells MW-2 and MW-4.

Quarterly monitoring of the three wells installed should continue to be performed to assess contaminant concentration fluctuation with respect to groundwater level, gradient and flow direction. Groundwater samples collected from the quarterly monitoring of Well MW-4, should be analyzed for chlorinated hydrocarbons by EPA Method 601.

LIMITATIONS

This groundwater monitoring well report has been prepared for the exclusive use of AB&I Foundry Company. Unauthorized use of or reliance on the information contained in this report by others, unless given express written consent by BSK & Associates, is strictly prohibited.

The findings and conclusions presented in this report are based on field observations, and on data obtained from the sources listed in this report. This report has been prepared in accordance with generally accepted methodologies and standards of practice for the area. No other warranty, either expressed or implied, is made as to the findings or conclusions included in this report.

The findings of this report are valid as of the present. The passage of time, natural processes or human intervention on the property or adjacent properties, and changes in the regulations can cause changed conditions which can invalidate the findings and conclusions in this report.


This report is neither certification nor guarantee that the property is free of, or contains hazardous substance contamination, other than that mentioned in the report.

DISTRIBUTION

A copy of this report should be forwarded by the client to the Alameda County Department of Environmental Health for their review. An extra copy of this report has been forwarded to American Brass and Iron Foundry for this purpose.

Respectfully Submitted, BSK & Associates






ELEVENTH QUARTERLY GROUNDWATER MONITORING AB&I FOUNDRY 7825 SAN LEANDRO STREET OAKLAND, CALIFORNIA

Job No. P92270.3 APRIL 1996 FIGURE: 1

BSK & ASSOCIATES



BSK Job No. P92270.3

April 1996 Figure: 3

WELL FIELD LOG

Well Observation: x Date: 4/26/96 Sample Collection: x Date: 4/26/96

Project Name: American Brass & Iron

Location: Oakland, CA

Personnel: MC

Weather: Clear, Warm

WELL INFORMATION:

Well Number	MW-2	Date Purged	4/26/96	
Depth to Water - feet(TOC)	4.50	Purge Method	Submersible Pump	
Well Depth (feet)	17.0			
Water Volume (gallons)	8.1	Purge Begin	11:55	
Reference Elevation - feet(TOC)	+7.80	Purge End	12:03	
Groundwater Elevation (feet)	+3.30	Purge Rate	3.0 GPM	
Measurement Technique	Solinst Electric Water Sounder			

IMMISCIBLE LAYERS:

Top: None Observed, No Odor

Bottom: Trace Olive Grey Colloids, No Odor

Detection Method: Visual

Collection Method: Point-Source Bailer

WELL DEVELOPMENT/PURGE DATA:

TIME	VOLUME REMOVED (gallons)	ELECTRICAL CONDUCTIVITY (Micromhos)	pН	TEMP. (°F)	COLOR/COMMENTS
11:58	8.0	901	6.51	76	
12:00	16.0	811	6.85	72	
12:03	24.0	789	6.94	71	

SAMPLE COLLECTION DATA:

Sampling Equipment: Teflon Point-Source Bailer

TIME	ANALYSIS	AMOUNT/CONTAINER USED	SAMPLE INTERVAL
12:10	EPA 601	2-40 ml glass vials with HCl	±5'
11	TPH-G and BTEX	2-40 ml glass vials with HCl	п
"	Total and Hydrocarbon Oil & Grease	1-liter amber glass bottle with H ₂ SO ₄	n

Field Observations: None

Figure: 4

WELL FIELD LOG

Well Observation: x Date: 4/26/96 Sample Collection: x Date: 4/26/96

Project Name: American Brass & Iron

Location: Oakland, CA

Personnel: MC

Weather: Clear, Warm

WELL INFORMATION:

Well Number	MW-3	Date Purged	4/26/96
Depth to Water - feet(TOC)	7.57	Purge Method	Submersible Pump
Well Depth (feet)	19.0		
Water Volume (galions)	2.0	Purge Begin	11:06
Reference Elevation - feet(TOC)	+9.83	Purge End	11:10
Groundwater Elevation (feet)	+2.26	Purge Rate	2.0 GPM
Measurement Technique	Solinst Electric Water Sounder		

IMMISCIBLE LAYERS:

Top: None observed, no odor Bottom: None observed, no odor

Detection Method: Visual

Collection Method: Point-Source Bailer

WELL DEVELOPMENT/PURGE DATA:

TIME	VOLUME REMOVED (gallons)	ELECTRICAL CONDUCTIVITY (Micromhos)	pН	TEMP. (°F)	COLOR/COMMENTS
11:07	2.0	1428	6.45	77	
11:08	4.0	1374	6.60	74	
11:09	6.0	1379	6.50	74	
11:10	8.0	1359	6.60	73	

SAMPLE COLLECTION DATA:

Sampling Equipment: Teflon Point-Source Bailer

TIME	ANALYSIS	AMOUNT/CONTAINER USED	SAMPLE INTERVAL
11:16	TPHg, BTEX	2-40 ml glass vials with Hel	10'

Field Observations: None

BSK Job No. P92270.3 April 1996

FIGURE: 5

WELL FIELD LOG

Well Observation: x Date: 4/26/96 Sample Collection: x Date: 4/26/96

Project Name: American Brass & Iron

Location: Oakland, CA.

Personnel: MC

Weather: Clear, Warm

WELL INFORMATION:

Well Number	MW-4	Date Purged	4/26/96			
Depth to Water - feet(TOC)	7.43	Purge Method	Clear Point-Source			
Well Depth (feet)	24.5		Bailer			
Water Volume (gallons)	2.9	Purge Begin	12:41			
Reference Elevation - feet(TOC)	+9.52	Purge End	12:46			
Groundwater Elevation (feet)	+2.09	Purge Rate	1.8 GPM			
Measurement Technique	Solinst Electric Water Sounder					

IMMISCIBLE LAYERS:

Top: None Observed, Faint Hydrocarbon Odor

Bottom: Orange Particles Observed, Faint Hydrocarbon Odor

Detection Method: Visual

Collection Method: Clear Point-Source Bailer

WELL DEVELOPMENT/PURGE DATA:


TIME	VOLUME REMOVED (gallons)	ELECTRICAL CONDUCTIVITY (Micromhos)	РĄ	TEMP. (°F)	COLOR/COMMENTS
12:58	3.0	3050	8.38	76	
12:00	6.0	2970	8.15	72	
12:01	9.0	2940	7.96	71	

SAMPLE COLLECTION DATA:


Sampling Equipment: Teflon Point-Source Bailer

TIME	ANALYSIS	AMOUNT/CONTAINER USED	SAMPLE INTERVAL
13:00	TPH-G & BTEX	2-40 ml glass vials with HCl	± 7.5'

Field Observations: None



SUMMARY OF GROUNDWATER ELEVATIONS



BSK Job No. P92270.3 APRIL1996 FIGURE 7

BSK

APPENDIX "A"



BSK ANALYTICAL LABORATORIES

ESK-Pleasanton
AB & I

Date Sampled : 04/26/96

Time Sampled : 1210

Date Received : 04/30/96
Date of Analysis : 05/03/96

Report Issue Date: 05/15/96

Case Number : Ch961643

Lab ID Number : 1643-2 Project Number : P92270 Sample Description: MW-2

Sample Type: LIQUID

Analyses for Volatile Halocarbons by EPA Method 601 Prepared by EPA Method 5030

Results Reported in Micrograms per Liter (μ g/L)

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

DLR: Detection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences
may result in higher detection limits.

ND: None Detected --: Not Analyzed

BSK LABORATORIES

BSK-Pleasanton AB & I

Date Sampled : 04/26/96 Time Sampled : 1210

Time Sampled : 1210
Date Received : 04/30/96

Date of Analysis: 05/06/96

Report Issue Date: 05/15/96

Case Number : Ch961643 Lab ID Number : 1643-2

Lab ID Number : 1643-2 Project Number : P92270 Sample Description: MW-2 Sample Type: LIQUID

Analyses For Total and Hydrocarbon Oil & Grease By EPA Methods 413.2 & 418.1

Results Reported in Milligrams Per Liter (mg/L)

Analyte	Results	DLR
Total Oil and Grease Hydrocarbon Oil and Grease	ND ND	1

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

DLR: Detection Limit for the Furposes of Reporting.

Exceptional sample conditions or matrix interferences may result in higher detection limits.

ND: None Detected

R941101 OGTHL41

BSK ANALYTICAL LABORATORIES

BSK-Pleasanton

AB & I

Date Sampled : 04/26/96

Time Sampled : 1210

Date Received : 04/30/96 Date of Analysis : 05/05/96

Report Issue Date: 05/15/96

Case Number

: Ch961643

Lab ID Number

: 1643-2

Project Number

: P92270

Sample Description: MW-2

Sample Type: LIQUID

Analyses for BTEX by EPA Method 8020 and TPH(G) by EPA Method 8015 Prepared by Method 5030

Results Reported in Micrograms per Liter (ug/L)

Compound	Results	DLR
Benzene Toluene Ethylbenzene Total Xylene Isomers Total Petroleum Hydrocarbons (G)	ND ND ND ND SOO	0.3 0.3 0.3 0.3
		l

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

NOTE:

Hydrocarbons in the gasoline boiling point range are reported, in accordance with the method, <u>as gasoline</u>.

Chromatography for this sample is described as inconsistent with the gasoline standard.

LEGEND:

DLR: Detection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences may result in higher detection limits.

ND: None Detected

LABORATORIES

BSK-Pleasanton

AB & I

Date Sampled : 04/26/96

Time Sampled : 1116

Sample Type: LIQUID

Date Received: 04/30/96 Date of Analysis: 05/05/96

Report Issue Date: 05/15/96

Case Number

: Ch961643

Lab ID Number

: 1643-1

Project Number

: P92270

Sample Description: MW-3

Analyses for BTEX by EPA Method 8020 and TPH(G) by EPA Method 8015 Prepared by Method 5030

Results Reported in Micrograms per Liter (ug/L)

Compound	Results	DLR
Benzene	ND	0.3
Toluene	ND	0.3
Ethylbenzene	ND	0.3
Total Xylene Isomers	ND	0.3
Total Petroleum Hydrocarbons (G)	ND	50
		l

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

NOTE:

Hydrocarbons in the gasoline boiling point range are reported, in accordance with the method, as qasoline.

LEGEND:

DLR: Detection Limit for the Purposes of Reporting. Exceptional sample conditions or matrix interferences may result in higher detection limits.

ND: None Detected

BSK ANALYTICAL LABORATORIES

BSK-Pleasanton

AB & I

Date Sampled : 04/26/96 Time Sampled : 1300 Date Received : 04/30/96 Date of Analysis : 05/05/96 Report Issue Date: 05/15/96

Case Number : Ch961643
Lab ID Number : 1643-3

Project Number : P92270 Sample Description: MW-4 Sample Type: LIQUID

Analyses for BTEX by EPA Method 8020 and TPH(G) by EPA Method 8015 Prepared by Method 5030

Results Reported in Micrograms per Liter (ug/L)

Compound	Results	DLR
Benzene Toluene Ethylbenzene Total Xylene Isomers Total Petroleum Hydrocarbons (G)	ND ND ND ND ND	0.3 0.3 0.3 0.3

Sample DLR = DLR x DLR Multiplier,

DLR Multiplier = 1

NOTE:

Hydrocarbons in the gasoline boiling point range are reported, in accordance with the method, as gasoline.

LEGEND:

DLR: Detection Limit for the Purposes of Reporting.

Exceptional sample conditions or matrix interferences
may result in higher detection limits.

ND: None Detected

A N A L Y T I C A L 1414 Stanislaus Street Fresno, CA 93706 (209) 485-8310 (800) 877-8310 L A B O R A T O R I E S (209) 485-6935 FAX

Analyses Request / Chain of Custody

BSK Log Number: 1643

Analytical Due Date: 5/9/96

L A	BOF	TAS	ORIES (20)	9) 485-6935 FAX												17	11	<u></u>
Envi			Services	BSK.	- D			Sh	naded areas for LAB use only	\times	ı	Re	ques	sted A	Analy	/ses		
Che	nt Name	A	B!I-	Oaklund P	/	Report Atte	ntion: Martin Clin	<u>e</u>	Phone #	$\exists \mathcal{A}$		dro	icas					
Add	ress /	c/0	B5K-	P		Project, Qu	muchin Clin per P92270		FAX#	W.	0	X	2					
City	State, 2	ip	<i></i>	,		Copy to:	, , , , , , ,	<u></u>	System#	(F)	9	mal	710					
	H 1150		_		Sampled by:	y. C.	/ .		_	J-H-	H	1/2	bon	1				
	іс Турю		Date Sampled	Time Sampled			Description/Location	1	Comment or Station Code	10,	E	Tota,	art				Ì	
I	乙	100	4/26/96	11:16	M	u-3				X								
2	7	5	172 3 1 2	17:10	MI	· .2		1		X	X	X			\top			
3	12	2	V	13:00	MU	- 4				ĺχ				\top				
	T-			1		•		+		1					+			
		ŀ				,			, <u>, , , , , , , , , , , , , , , , , , </u>				1		\top			
-	1.													\top	1			
								1							+			
														+	1			+
	1 -							1					1				1	
								†							+			
 	1												$\neg \dagger$	+	+			
-	-													-	-			
ستشت				S - Solid G - Ga ociated with Samp	oles:		Additional Services: y: []-2 Day []-5 Day	1	Additional Services Authorized	by:		Date:			with De	unt: \$	<u> </u>	<u> </u>
					[] - Fo	rmal Chain	of Custody [] - QC Data package		(Signature)							Is	 	
Γ			Sign	ature			Print Name		Compan	y					Dat	te	T	Time
Req	Requested / Rehnquished by Mutt Chi		Mar	tin Cline		BSK-P							4/29/96		5.00			
		elinquis	hed by:			ļ								\perp				
Roc	ived / R	elinquis	hed by:				4-144							\perp				
Rec	ived / R	elinquisl	hed by:		0 11										·/	,		
- Rec	ived for	r Laborai	tory by:	2 - 12/1	rillor	k S	ARA K-DHIL	LON	BSK-	P				(1,130	196	12	200