



2315 Dunn Rd., Hayward

03216271255-8

3/11/93

The pit was excavated down to g.w.  
& the groundwater was pumped & allowed  
to recharge before sampling. Juliet Sluij

03216211255-8

3/11/93

The tank pit was backfilled when I  
went out to site. Juliet Sluij  
2315 Dunn Rd., Hayward