

A RESNA Company



"File Name: FRANSMT.PRJ

TRANSMITTAL

3315 Almaden Expressway, Suite 34 San Jose, CA 95118

Phone: (408) 264-7723 Fax: (408) 264-2435

TO: MR. LAR	RY SETO	 	DATE:			
	COUNTY HEALT				ER 69036. 0	
		Z MAT DIVISION	ALBANY,		STATION 20)35 AT
	WAY, ROOM 20 , CALIFORNIA		ALDANI,	CALIFOR	MIA	
	JOEL COFFMAN					
	PROJECT GEOLO	GIST				
WE ARE SENDIN	ig you [XXX	Attached [] Uno	der separat <mark>e</mark> co	over via	the fo	ollowing items:
[] Shop d	rawings []	Prints [] Re	ports []S	pecificatio	ns	
🙀 Letters	[]	Change Orders	[]	·		<u> </u>
COPIES D	DATED	NO.		DESCRI	IPTION	
= = : :=	4/91	COVI	CR LETTER E	OR CORR	RCTED PACE	<u> 16.</u>
1 9/1	1/91	CORI	RECTED PAGE	16 OF	UNDERGROUN	ND GASOLINE-
i .		STO	RAGE TANK F	REMOVAL	AND REPLAC	CEMENT REPORT.
		<u> </u>				
THESE ARE TRA	NSMITTED as c	hecked below:				
[] For review	and comment []	Approved as submit	ted I	Resubmit _	copies for	approval
[] As requeste	d []	Approved as noted	[] \$	Submit	copies for dis	tribution
[For approva	л []	Return for correction	ns [] E	Return	corrected pri	nts
kk For your tile	es []				·	
REMARKS:	THESE DO	CUMENTS HAVE BI	ZEN FORWARI	DED TO Y	OU AT THE	
		OF MR. CHUCK CA				
			<u> </u>			
·					<u> </u>	
Copies: 1 to AGS p	roject file no. 6	9036.03		SAN JO	SE READER	'S FILE
					Revision Da	ite: 10/15/90



A RESNA Company



3315 Almaden Expressway, Suite 34

San Jose, CA 95118 Phone: (408) 264-7723 Fax: (408) 264-2435

September 24, 1991

Mr. Larry Seto Alameda County Health Care Services Agency Hazardous Materials Division 80 Swan Way, Room 200 Oakland, California 94621

Subject:

Corrected Page 16 of Underground Gasoline-Storage Tank Removal and

Replacement Report (RESNA/AGS September 11, 1991) at ARCO Station

2035, Albany California.

Dear Mr. Seto:

Enclosed is a corrected copy of page 16 of the above-referenced report. Please substitute this page in place of the one originally sent.

> Sincerely, **RESNA**

Joel Coffman Project Geologist fran

Corrected Page 16 Enc:

Chuck Carmel, ARCO cc:



A RESNA Company



No. C 044600 Exp. 3-31-94

3315 Almaden Expressway, Suite 34 San Jose, CA 95118 Phone: (408) 264-7723 Fax: (408) 264-2435

UNDERGROUND GASOLINE-STORAGE TANK REMOVAL AND REPLACEMENT

at ARCO Station 2035 1001 San Pablo Avenue Albany, California

69036.03

Report prepared for

ARCO Products Company P.O. Box 5811 San Mateo, California

by RESNA/Applied GeoSystems

Steve Strausz

Assistant Project Geologist

Joan E. Tiernan, Ph.D., P.E. Engineering Manager

September 11, 1991

TABLE OF CONTENTS

1.0 INTROE	DUCTION 1
	ESCRIPTION AND BACKGROUND
	te Description
	ocal and Regional Hydrogeology
2.3 Pr	revious Work
3.0 FIELD V	
	ew Tank Pit Soil Borings
	1.1 Soil Sampling in Borings
3 2 R	emoval of Underground Tanks 6
	2.1 Soil Sampling in Former Tank Pits
	ew Tank Pit Excavation and Backfilling Former Tank Pits 8
	3.1 Soil Sampling in New Tank Pit
	oduct Line Removal 9
	old Aeration
	ATORY METHODS
	nalytical Methods and Sample Summary
	GIC AND LABORATORY RESULTS
5.1 U	eologic Results
	USIONS
7.0 DISTRIE	
8.0 LIMITA	
	ΓΙΟΝS
7.0 KEFEKI	INCES CITED 18
	TABLES
TABLE 1:	LABORATORY ANALYSIS OF NEW TANK PIT SOIL SAMPLES
TABLE 2:	LABORATORY ANALYSIS OF FORMER GASOLINE TANK PIT
	SOIL SAMPLES
TABLE 3:	LABORATORY ANALYSIS OF PRODUCT LINE AND PRODUCT
	DISPENSER SOIL SAMPLES
TABLE 4:	LABORATORY ANALYSIS OF COMPOSITE SOIL SAMPLES
TIBLE I.	OF STOCKPILED SOIL FOR DISPOSAL
TABLE 5:	LABORATORY ANALYSIS OF WATER "GRAB" SAMPLE FROM
TABLE 5.	TANK T4 TANK PIT
	IZMINE IT IZMINE III
	PLATES
PLATE 1:	SITE VICINITY MAP
PLATE 2:	GENERALIZED SITE PLAN
PLATE 3:	SOIL SAMPLING
PLATE 4:	GEOLOGIC CROSS SECTION A-A'
THE THE	GLOLOGIO ORODO DLOTTOR A A



TABLE OF CONTENTS (Continued)

PLATE 5: AERATION SOIL STOCKPILE

APPENDIX A

FIELD PROTOCOL (3)

APPENDIX B

LOGS OF BORINGS Soil Borings B-6 and B-7

APPENDIX C

CHAIN OF CUSTODY RECORDS ANALYSIS REPORTS

APPENDIX D

MANIFESTS FOR TANKS INVOICE FOR SOIL DISPOSAL







3315 Almaden Expressway, Suite 34 San Jose, CA 95118

Phone: (408) 264-7723 Fax: (408) 264-2435

REPORT UNDERGROUND GASOLINE-STORAGE TANK REMOVAL AND REPLACEMENT

at ARCO Station 2035 1001 San Pablo Avenue Albany, California

For ARCO Products Company

1.0 INTRODUCTION

At the request of ARCO Products Company (ARCO), RESNA/Applied GeoSystems (RESNA) conducted an environmental investigation related to the removal and replacement of four underground gasoline-storage tanks and soil aeration at the site of an operating ARCO AM/PM store and service station at 1001 San Pablo Avenue in Albany, California. This investigation was initiated as part of ARCO's planned tank replacement program.

This investigation included the following:

- drilling of two soil borings and collecting soil samples for laboratory analysis 0 in the proposed new tank pit location;
- observing excavation and removal of four underground gasoline-storage tanks, 0 and associated product lines;
- sampling and analysis of the soil from the former tank pits and product-line o trenches;

- o obtaining one "grab" sample of water collected in one of the former tank pits;
- o monitoring aeration of the soil from the former tank pits and former productline trenches in compliance with Regulation 8, Rule 40;
- o observing excavation of a new tank pit;
- o sampling and analysis of soil from the new tank pit and stockpiled soil as required by Mr. Larry Seto of the Hazardous Materials Division of the Alameda County Health Care Services Department (ACHCSD);
- o observing disposal of aerated, stockpiled soil after analytical results showed that petroleum hydrocarbon concentrations had been reduced to acceptable levels.

This report presents the results of this work, together with a description of the field methods employed, the laboratory analyses, and other information related to gasoline-tank removal and replacement.

2.0 SITE DESCRIPTION AND BACKGROUND

2.1 Site Description

ARCO Station 2035 is an operating service station and AM/PM mini-market on the southeast corner of the intersection of San Pablo and Marin Avenues at 1001 San Pablo Avenue, Albany, California. The location of the site is shown on Plate 1, Site Vicinity Map. The site is a relatively flat, asphalt- and concrete-covered lot at an elevation of approximately 47 feet above mean sea level.

RESNA understands from information provided by ARCO that the former tanks at the site consisted of one steel 6,000-gallon underground supreme gasoline-storage tank (T1), two



steel 4,000-gallon underground regular gasoline-storage tanks (T2 and T3), and one fiberglass 10,000-gallon underground unleaded gasoline-storage tank (T4). The new tanks at the site consist of four fiberglass 10,000-gallon underground gasoline-storage tanks installed in a new location. Based on data supplied by ARCO, one 550-gallon waste-oil tank was removed from the site in 1977 during ARCO's conversion of the station to a minimarket. The approximate locations of the former gasoline-storage tanks, new gasoline storage tanks, former waste-oil tank, and other features at the site are shown on Plate 2, Generalized Site Plan.

2.2 Local and Regional Hydrogeology

ARCO Station 2035 is located within the East Bay Plain in the north-central portion of the Berkeley Alluvial Plain (Hickenbottom and Muir, 1988). The active Hayward Fault is approximately 2 miles east of the site. Helley et al. (1979) mapped the earth materials underlying the site area as older Quaternary alluvium deposits composed of a heterogeneous mixture of poorly consolidated to unconsolidated clay, silt, sand and gravel. The site is less than 1,200 feet north of the Codornices Creek and approximately 1 mile east of Fleming Point on the eastern shoreline of the San Francisco Bay. The direction of ground-water flow in the vicinity of the site is inferred to be to the west-southwest, based on regional and local topography and drainage patterns.

2.3 Previous Work

On August 9, 1989, RESNA performed a limited environmental site assessment to evaluate possible gasoline hydrocarbons in the soil in the vicinity of the four underground gasoline-storage tanks (1990). Five soil borings (B-1 through B-5) were drilled as shown on Plate 2.



Soils encountered in the borings consisted primarily of interbedded layers of silty to gravelly clay and silty to sandy gravel. Ground water was encountered in the borings at depths between 17 and 18 feet below ground surface, except in boring B-5 where ground water was not encountered to a the total depth of 20-1/2 feet below ground surface. A hydrocarbon sheen was noted on the surface of water samples obtained from borings B-1 and B-4. Laboratory analyses of selected soil samples from borings B-1 through B-5 reported concentrations of TPHg ranging from nondetectable (less than 1 parts per million [ppm]) to 2,400 ppm. AGS concluded that shallow soils near the four underground gasoline-storage tanks had been impacted by gasoline hydrocarbons, and shallow ground water beneath the site appeared to have been impacted by gasoline hydrocarbons.

On behalf of ARCO, RESNA submitted the Work Plan for Subsurface Investigations and Remediation, and Addendum One to Work Plan, dated April 29, 1991, to the Alameda County Health Care Services Agency (ACHCSA) and the California Regional Water Quality Control Board (RWQCB). The Work Plan summarizes previous work at the site and describes RESNA's approach, field methods, and project tasks recommended to perform subsurface investigations and remediation at the site. The addendum to work plan describes proposed work for performing a subsurface investigation at the site including: performing well research for nearby water wells and monitoring wells; records research; and installing four ground-water monitoring wells. The purpose of this work is to evaluate further the extent of gasoline hydrocarbons in the soil and investigate the possible impact of gasoline and waste-oil hydrocarbons in the ground water at the site.



3.0 FIELD WORK

Field work conducted on behalf of ARCO during this investigation included drilling two soil borings; collecting soil samples from the borings for analysis; removal of four gasoline underground storage tanks (USTs) and associated product lines; excavation of a new UST pit; aeration of the stockpiled soil; and collecting soil samples from the former and new tank pits, product-line excavations, and stockpiled soil for laboratory analysis. The field work was conducted according to the procedures described in Appendix A, Field Procedures, and in conformance with the RESNA Site Safety Plan (RESNA, June 24, 1991).

3.1 New Tank Pit Soil Borings

On June 27, 1991, RESNA personnel supervised the drilling of two borings (B-6 and B-7) to depths of 18 and 19-½ feet in the area of the proposed new tank pit as shown on Plate 3, Soil Samples. Ground water was first encountered at 17-½ feet in B-6 and 19-½ feet in B-7.

3.1.1 Soil Sampling in Borings

A RESNA geologist observed the drilling, and classified the soils according to the Unified Soil Classification System. Nine soil samples from borings B-6 and B-7 were submitted for laboratory analysis for TPHg and the gasoline constituents BTEX. The borings were backfilled to grade with a bentonite and neat cement grout upon completion of the work.



3.2 Removal of Underground Tanks

On July 1 through 3, 1991, a field geologist from RESNA was onsite to observe the excavation and removal of four underground gasoline-storage tanks T1 through T4, as shown on Plate 2, inspect their outer surfaces, collect soil samples from native soil beneath the ends of tanks T1 through T4, obtain a sample of water perched at the bottom of tank T4 tank pit, and observe the excavation of field-detected gasoline-impacted backfill soil from the tank excavations. Tank and product-line removal was performed by W. F. Lewis Construction, Inc., of Sacramento, California. The Albany Fire Department (AFD), ACHCSD, and the Bay Area Air Quality Management District (BAAQMD) were notified prior to tank removal. Mr. Larry Seto of the ACHCSD, and Mr. Frank Westphal of the AFD were present on July 3, 1991 to observe the removal of the tanks. Furthermore, Mr. Larry Seto was present to observe soil and water sampling in the former tank pits.

The RESNA field geologist noted that product-line plumbing above tanks T1, T2, and T3 consisted primarily of single-walled steel pipes and fittings. The product line plumbing and the former vapor vent lines above tank T4 consisted primarily of single-walled fiberglass pipes and fittings.

On July 3, 1991, three single-walled steel underground storage tanks T1, T2, and T3 measuring approximately 8 feet in diameter by 16 feet in length, and one single-walled fiberglass underground storage tank T4 measuring approximately 8 feet in diameter by 30 feet in length were uncovered and prepared for removal. Hydrocarbon vapors and oxygen were purged from the tanks by the addition of solid carbon dioxide (dry ice) into the tanks. Tanks T1 through T4 were then excavated and removed from the tank pit.



Examination of the three steel tanks after their removal indicated that tank T1 was slightly pitted and rusty, but had no visible through-going holes. Tank T2 was rusty and pitted along the bottom half of the tank, had a 2 inch long split along the seam at the eastern end of the tank, and had a 1 inch by 1-½ inch hole under the fill opening at the western end of the tank. Tank T3 was pitted and rusty throughout, and had holes up to ½-inch diameter throughout the lower half of the tank and especially in the southwest side and bottom. Examination of the fiberglass tank T4 indicated the tank was in good condition with no visible through-going holes. Tanks T1 through T4 were transported by Erickson, Inc., a licensed waste hauler, to a their licensed disposal facility in Richmond, California. Manifests documenting the disposal of tanks are included in Appendix D.

The backfill soil excavated from the tank pit above and around the steel tanks T1, T2, and T3 was predominately fine- to medium-grained imported sand. The backfill soil excavated from the tank pit above and around the fiberglass tank T4 was predominantly fine gravel (pea-gravel). Excavated soil was monitored with an organic vapor meter (OVM), field calibrated to a 100 ppm sample of isobutylene, as it was removed from the excavation. OVM readings during this monitoring indicated levels of hydrocarbons up to approximately 1,000 ppm equivalent units in the soil. Ground water was not encountered in the tank pits which were excavated to depths of approximately 12 feet; however, a small pool of possibly perched surface water was collected in a portion of the T4 tank pit.

3.2.1 Soil Sampling in Former Tank Pits

On July 3, 1991, soil samples were collected from native soil beneath the ends of each of tanks T1 through T4 at depths of 12 or 13 feet to evaluate the impact of gasoline hydrocarbons on the native soil beneath the former gasoline-storage tanks. The native soils



at the sample depths included clayey silt, clayey sand, gravelly clay and clayey gravel. On July 3, 1991 a "grab" sample of the water pooled in the T4 tank pit was obtained.

Approximately 350 cubic yards of backfill soil removed from the tank pit excavations was stockpiled onsite for subsequent aeration or disposal. The stockpiled soil was placed on and covered by plastic sheeting.

3.3 New Tank Pit Excavation and Backfilling Old Tank Pits

The new tank pit for four 10,000 gallon gasoline-storage tanks was excavated by W. F. Lewis Construction Inc. on July 8 through 10, 1991. A RESNA geologist was onsite on July 8 and July 10, 1991 to observe removal of approximately 450 cubic yards of soil from the excavation for transportation and disposal to West Contra Costa County Sanitary Landfill in Richmond, California, and to obtain soil samples from the sidewalls of the new tank pit excavation. A RESNA geologist was onsite with a Sequoia Analytical mobile laboratory on July 9, 1991, to obtain and analyze samples from approximately 350 cubic yards of soil removed from the new tank pit excavation for use in backfilling the former gasoline-storage tank pits, and to supervise backfilling of the former tank pits.

3.3.1 Soil Sampling in New Tank Pit

Soil sampling of sidewalls and of material to be used for backfilling the former tank pits was performed according to the instructions of Mr. Larry Seto of ACHCSD as told to Mr. Steve Strausz of RESNA on July 3, 1991. These instructions for obtaining soil samples from the new tank pit as recorded by Mr. Steve Strausz on July 3, 1991, included: (1) a single sample must be obtained and laboratory analyzed for TPHg and BTEX for every 20 cubic yards of



soil to be used in backfilling the former tank pits, and laboratory reported levels of TPHg must be nondetectable for soil to be used in backfilling; (2) a single soil sample must be obtained and laboratory analyzed for TPHg and BTEX for every 200 square feet of area of new tank pit sidewalls, for characterization of soils in the vicinity of the new tank pit. The locations and depths of soil samples obtained from the new gasoline-storage tank pit excavation are shown on Plate 3, Soil Sampling.

3.4 Product-Line Removal

The former product lines were excavated and removed on July 19, 1991. The ACHCSD, the AFD, and the BAAQMD were notified prior to performing this work. A RESNA geologist was onsite to observe removal of the product lines, supervise excavation of field-detected impacted soils from the area of the southwestern product dispenser and product lines, and obtain soil samples from the native soil beneath the former product dispensers and product lines. Mr. Larry Seto of ACHCSD was onsite to observe soil sampling of native soil beneath former product dispensers and product lines.

The RESNA geologist onsite noted that the soils near the surface in the area of the site nearest the former gasoline-storage tanks appeared to be uniformly impacted by gasoline hydrocarbons, based on OVM measurements of soil in that area of up to 500 ppm-equivalent units. The product dispensers and product lines did not appear to be the primary source of gasoline impacting these soils. No excavation was performed in this area beyond that required for removal of product and vapor/vent lines.

The RESNA geologist onsite noted that the shallow soil in the area of the product dispensers nearest the new tank pit appeared to be uniformly non-impacted by gasoline



hydrocarbons, with the exception of localized impacted soils in the area of the southernmost product dispensers. Based on these field observations, the RESNA geologist in consultation with Mr. Larry Seto of the ACHCSD directed the excavation of gasoline-hydrocarbon impacted soils from the vicinity of the southernmost product dispensers as shown on Plate 7, Product Line/Dispenser Sampling.

The former product lines consisted of single-walled fiberglass pipes and fittings, and appeared to be in good condition with no visible holes or loose fittings. The former product lines were originally installed from approximately \frac{1}{2}-foot to 1 foot depth below the ground surface. Soil samples were obtained from the native soil beneath the product dispensers and the product lines as shown on Plate 3, Soil Sampling, and submitted for laboratory analysis of TPHg and BTEX.

A RESNA geologist returned to the site on August 9, 1991 to determine the extent of gasoline impacted soil in the vicinity of the product line soil sample S-1-PL4. Measurements of organic vapors obtained with an OVM, in the vicinity of the former product lines and product dispensers near the location of soil sample S-0719-PL4, indicated ppm-equivalent units below 50. A second confirmation sample S-1½-PL4 was obtained from a depth of 1½ feet, just below the location of S-1-PL4.

Soil excavated during product line removal was stockpiled with soils removed from the former tank pit for subsequent aeration or disposal.

3.5 Soil Aeration

On July 9, 1991, a composite sample was obtained from the stockpiled backfill soil removed from the former tank pits, from a portion of the most highly gasoline-impacted soils as based on field measured OVM readings. Laboratory analysis of this sample reported a level of TPHg of 200 ppm. On July 15, 1991, RESNA notified the BAAQMD, the AFD, and the ACHCSD that passive aeration of approximately 350 cubic yards of soil in compliance with Regulation 8, Rule 4 of the BAAQMD (1986) would begin on July 17, 1991, at the site.

On July 17, 1991 the backfill soil stockpile was moved from the northwestern corner of the site to the area on the eastern side of the site, with approximately one third of the stockpile left uncovered to allow passive aeration. Laboratory analysis of seven confirmation composite samples obtained on July 22, 23, and 25, 1991, from approximately 50 cubic yard sections of the stockpiled soil reported TPHg from 31 to 81 ppm. Laboratory analysis results of composite soil samples from the aerated soil are included in Table 4. The entire stockpiled soils were covered with plastic sheeting on July 29, 1991. On August 1 and 2, 1991, the stockpiled soil was transported by Dillard Trucking, a licensed waste hauler from Byron, California, to Redwood Landfill Inc., a Class III Landfill in Novato, California. An invoice for hauling of soils is included in Appendix D.

4.0 LABORATORY METHODS

4.1 Analytical Methods and Sample Summary

Soil and ground-water "grab" samples were analyzed in Sequoia Analytical's Mobile Laboratory (State Hazardous Waste Testing Laboratory Certification No. 1229) onsite or



at Sequoia Analytical in Redwood City, California (State Hazardous Waste Testing Laboratory Certification No. 1210). The Chain of Custody Records and the laboratory Analysis Reports are attached in Appendix C.

Eight soil samples obtained from beneath the former USTs (T1 through T4) were analyzed for TPHg by modified EPA Method 5030/8015 and for the gasoline constituents BTEX by EPA Method 8020. One soil sample collected from beneath the southern end of tank T4 was also analyzed for total oil and grease (TOG) by EPA Standard Method 5520 E&F, and volatile organic compounds (VOCs) by EPA Method 8240. Two samples collected from beneath tank T3 were analyzed for organic lead by the California State LUFT (Leaking Underground Fuel Tank) Manual Method (December 1987).

One "grab" sample of water collected in the T4 tank pit was analyzed for TPHg and BTEX using EPA Methods 8015/602.

Thirty seven soil samples obtained from borings B-6 and B-7, and the excavation for the new tank pit were analyzed for TPHg by modified EPA Method 5030/8015 and for the gasoline constituents BTEX by EPA Method 8020.

Nineteen soil samples obtained from beneath the former product lines and product dispensers were analyzed for TPHg by modified EPA Method 5030/8015 and for the gasoline constituents BTEX by EPA Method 8020.

Nine composite soil samples from backfill soil removed from the former tank pits were analyzed for TPHg by modified EPA Method 5030/8015 and for the gasoline constituents BTEX by EPA Method 8020.



One composite sample obtained from the stockpiled soil removed from the former tank pits was analyzed for organic lead by the California State LUFT (Leaking Underground Fuel Tank) Manual Method (December 1987).

5.0 GEOLOGIC AND LABORATORY RESULTS

5.1 Geologic Results

A geologist observed the drilling of borings B-6 and B-7, and classified the soils according to the Unified Soil Classification System, which is briefly summarized on Plate B-1 in Appendix B, Logs of Borings. The boring logs are also presented in Appendix B in Plates B-2 and B-3. Earth materials encountered in borings B-6 and B-7 ranged from sandy clay to clayey gravel as shown on the Logs of Borings, Plates B1 and B2 in Appendix B. Organic vapor meter readings are shown on the boring logs in the column labeled PID (photoionization detector). Geologic cross section A-A' (Plate 4) shows the subsurface stratigraphy at the site. The location of the geologic cross section A-A' is shown on Plate 2. Ground water was encountered at a depth of about 18 feet.

5.2 Laboratory Results

The results of laboratory analyses of soil samples obtained from soil borings B-6 and B-7, and from soil samples obtained from the excavation for the new tank pit are summarized in Table 1, Laboratory Analyses of New Tank Pit Soil Samples; and TPHg results and sample locations in the excavation for the new tank pit are shown on Plate 3, Soil Sampling. In borings B-6 and B-7 in the new tank pit, TPHg and BTEX levels were reported nondetectable in all 9 samples (S-5½-B6 through S-18½-B-7). In the remaining 28 soil



samples (S-15-EWC through S-0709-NP18{11'}), TPHg was reported nondetectable, and BTEX was reported ranging from nondetectable to 0.056 ppm.

The results of laboratory analyses of soil samples obtained from the former tank excavation are reported in Table 2, Laboratory Analyses of Former Tank Pit Soil Samples; and the sample locations and results are shown on Plate 3. In these 8 soil samples, TPHg ranged from nondetectable to 65 ppm. BTEX ranged from nondetectable to 2.4 ppm. Organic Lead and TOG were nondetectable in the soil sample (S-13-T4S) obtained nearest the former waste-oil tank location.

The results of laboratory analyses of the 19 soil samples collected beneath the former product lines and dispensers are summarized on Table 3, Laboratory Analyses of Product Line/Dispenser Soil Samples; and sample locations and results are shown on Plate 3. Laboratory reported levels of TPHg ranged from nondetectable to 4,200 ppm (in sample S-1-PL4). Laboratory reported levels of TPHg for three samples exceeded 1,000 ppm. Laboratory reported TPHg levels for nine samples were nondetectable. Laboratory levels of BTEX ranged from nondetectable to 640 ppm (in S-1-PL4).

Results of laboratory analysis of composite soil samples collected from the stockpiles soil at the site are shown on Table 4, Laboratory Analyses of Stockpiled Soils. TPHg in these samples ranged from nondetectable to 200 ppm, and BTEX ranged from nondetectable to 7.8 ppm.

The results of laboratory analysis of the single "grab" sample are summarized in Table 5, Laboratory Analysis of Water "Grab" Sample. The results of laboratory analyses of soil



samples and the water "grab" sample are also shown on Plate 3. TPHg was reported at 190,000 parts per billion (ppb), and BTEX ranged from 4,100 ppb to 27,000 ppb.

6.0 CONCLUSIONS

Based on the results of this investigation, RESNA concludes:

- o the soils in the vicinity of the new gasoline-storage tank pit have not been significantly impacted by gasoline hydrocarbons, as suggested by nondetectable concentrations of TPHg reported in nine samples collected from borings B-6 and B-7 and in twenty-eight samples collected from the new tank pit (although low levels of BTEX were detected);
- o gasoline hydrocarbons over 100 ppm have not impacted the shallow soils (12 to 13 feet below grade) in the vicinity of the former gasoline-storage tanks, as indicated by results of laboratory analysis of soil samples collected from the bottom of the former tank pit; however through-going holes noted in tanks T2 and T3 suggest that leakage occurred from these tanks and has likely impacted soils at the site;
- o gasoline hydrocarbons over 1,000 ppm have impacted the shallow soils (one foot below grade) in the vicinity of the product dispensers adjacent to the former steel gasoline-storage tanks T1, T2, and T3, as indicated by laboratory results of samples collected from the service island area closest to Marin Avenue. The former product dispensers, and the former product lines in these areas are likely sources of gasoline hydrocarbons impacting shallow soils;
- the product dispensers and product lines along San Pablo Avenue apparently have not significantly impacted the shallow soils at the site, as suggested by nondetectable concentrations of TPHg, with the exception of one sample collected at a depth of one foot from the northern portion of the service island (4,200 ppm). A soil sample collected from beneath this area at a depth of 1½ feet indicated the presence of 4.1 ppm TPHg; and



o ground water may be impacted at the site as suggested by laboratory results of a "grab" water sample from one of the former tank pits of 190,000 ppb TPHg.

7.0 DISTRIBUTION

RESNA recommends that copies of this report be forwarded to:

Mr. Lester Feldman
California Regional Water Quality Control Board
San Francisco Region
2101 Webster Street, Suite 500
Oakland, California 94612

Mr. Larry Seto
Alameda County Health Services Department
Hazardous Materials Division
80 Swan Way, Room 200
Oakland, California 94621

8.0 LIMITATIONS

This report was prepared in accordance with generally accepted standards of environmental geological practice in California at the time this investigation was performed. This investigation was conducted solely for the purpose of evaluating environmental conditions of the soil with respect to gasoline contamination related to the underground gasoline storage tanks and dispenser lines at the subject site. No soil engineering or geotechnical implications are stated or should be inferred. Evaluation of the geologic conditions at the site for the purpose of this investigation is made from a limited number of observation points. Subsurface conditions may vary away from the data points available. Additional



o ground water may be impacted at the site as suggested by laboratory results of a "grab" water sample from one of the former tank pits of 190 pp TPHg.

190,000 796

7.0 DISTRIBUTION

RESNA recommends that copies of this report be forwarded to:

Mr. Lester Feldman
California Regional Water Quality Control Board
San Francisco Region
2101 Webster Street, Suite 500
Oakland, California 94612

Mr. Larry Seto
Alameda County Health Services Department
Hazardous Materials Division
80 Swan Way, Room 200
Oakland, California 94621

8.0 LIMITATIONS

This report was prepared in accordance with generally accepted standards of environmental geological practice in California at the time this investigation was performed. This investigation was conducted solely for the purpose of evaluating environmental conditions of the soil with respect to gasoline contamination related to the underground gasoline storage tanks and dispenser lines at the subject site. No soil engineering or geotechnical implications are stated or should be inferred. Evaluation of the geologic conditions at the site for the purpose of this investigation is made from a limited number of observation points. Subsurface conditions may vary away from the data points available. Additional




September 11, 1991 AGS 69036.03


work, including further subsurface investigation, can reduce the inherent uncertainties associated with this type of investigation.


9.0 REFERENCES CITED

- Applied GeoSystems. January 24, 1990. <u>Limited Environmental Site Assessment at ARCO Station 2035</u>. AGS 96036-1.
- Bay Area Air Quality Management District. July 16, 1986. "Regulation 8, Rule 40. Aeration of Contaminated Soil and Removal of Underground Storage Tanks."
- Helley, E.S., K.R. Lajoie, W.E. Spangle, and M.L. Blair. 1979. <u>Flatland Deposits</u> of the San Francisco Bay Region, California. U.S. Geological Survey Professional Paper 943.
- Hickenbottom, K. and K. Muir. 1988. <u>Geohydrology and Groundwater-Quality Overview</u>, <u>East Bay Plain Area</u>, <u>Alameda County</u>, <u>California</u>. Alameda County Flood Control and Water Conservation District 205(J) Report.
- RESNA/Applied GeoSystems. June 24, 1991. <u>Site Safety Plan for the ARCO Service Station</u>
 No.2035, 1001 San Pablo Avenue, Albany, California. AGS 69036.03S.
- RESNA/Applied GeoSystems. April 29, 1991. Work Plan for Subsurface Investigations and Remediation at ARCO Station 2035, 1001 San Pablo Avenue, Albany, California. AGS 69036.02.
- RESNA/Applied GeoSystems. April 29, 1991. <u>Addendum One to Work Plan at ARCO Station 2035, 1001 San Pablo Avenue, Albany, California</u>. AGS 69036.02











EXPLANATION




PLATE

4

GEOLOGIC CROSS SECTION A-A'
ARCO Station 2035
1001 San Pablo Avenue
Albany, California








TABLE 1 LABORATORY ANALYSIS OF NEW TANK PIT SOIL SAMPLES ARCO Station 2035 Albany, California (Page 1 of 2)

Sample ID	В	Т	E	X	TPHg
June 25, 1991					
S-51/2-B6	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-101/-B6	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-15%-B6	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-17-B6	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-51/ - B7	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-101/-B7	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-151/-B7	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-17-B7	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-181/r-B7	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
July 8, 1991					
S-15-EWC	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-15-SE	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-16-SW1	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-15-SW	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-15-NWC	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-15-WWC	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-15-NWF	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-9-NWW	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-8-NW	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-15-NW	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
July 9, 1991			•		
S-0709-NP1(10')	0.025	0.027	0.0060	0.024	< 1.0
S-0709-NP2(14')	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-0709-NP3(10')	< 0.0050	0.0050	< 0.0050	0.018	<1.0
S-0709-NP4(15)	0.0050	0.0050	< 0.0050	< 0.0050	<1.0
S-070 9 -NP5(5')	0.012	0.013	< 0.0050	0.0080	<1.0
S-0709-NP6(15')	0.017	0.021	0.014	0.056	<1.0
S-0709-NP7(3')	0.0060	0.0060	< 0.0050	< 0.0050	< 1.0
S-0709-NP8(14')	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-0709-NP9(9')	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-0709-NP10(10')	0.0090	0.0060	< 0.0050	< 0.0050	< 1.0

See notes on page 2 of 2.



TABLE 1 LABORATORY ANALYSIS OF NEW TANK PIT SOIL SAMPLES

ARCO Station 2035 Albany, California (Page 2 of 2)

Sample ID	В	T	E	X	TPHg
S-0709-NP11(8')	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-0709-NP12(14')	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0
S-0709-NP13(2')	< 0.0050	< 0.0050	< 0.0050	< 0.0050	<1.0
S-0709-NP14(6')	< 0.0050	< 0.0050	0.0050	0.0080	< 1.0
S-0709-NP15(5')	< 0.0060	< 0.0050	< 0.0050	0.0060	< 1.0
S-0709-NP16(16')	< 0.0050	< 0.0050	0.0050	0.0080	<1.0
S-0709-NP17(10')	< 0.0050	< 0.0050	0.0050	0.0080	<1.0
S-0709-NP18(11')	< 0.0050	< 0.0050	0.0050	0.0080	<1.0

Results in parts per million (ppm).

<: Less than the indicated laboratory detection limit.

B: benzene, T: toluene, E: ethylbenzene, X: total xylenes

TPHg: Total petroleum hydrocarbons as gasoline

TPHg with BTEX distinction measured by EPA Methods 5030/8015/8020)

Sample Identification:

Soil Borings:

Excavation Samples:

Sidewall and Floor Samples:






TABLE 2 LABORATORY ANALYSIS OF FORMER GASOLINE TANK PIT SOIL SAMPLES ARCO Station 2035 Albany, California

Sample ID	В	Т	E	х	ТРН	TOG	voc	Pb
July 3, 1991								
S-12-T1W	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0	NA	NA	NA
S-12-T1E	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 1.0	NA	NA	NA
S-12-T2W	0.031	< 0.0050	0.0080	< 0.0050	< 1.0	NA	NA	NA
S-12-T2E	0.019	< 0.0050	< 0.0050	< 0.0050	< 1.0	NA	NA.	NA
S-12-T3W	1.2	2.4	1.0	3.8	48	NA	NA	< 0.03
S-12-T3E	0.2	0.51	0.97	3.9	65	NA	NA	< 0.02
S-13-T4N	0.45	0.039	0.18	0.33	6.2	NA	NA	NA
S-13-T4S	0.061	0.034	0.0080	0.15	< 1.0	< 30	ND	NA
	(0.160)			(0.430)				

Results in parts per million (ppm). NA: Not analyzed.

<: Less than the indicated laboratory detection limit

ND: Less than laboratory limit for each compound, except benzene and total xylenes

(): Indicates results measured by EPA Method 8240

B: benzene, T: toluene, E: ethylbenzene, X: total xylenes

TPHg: Total petroleum hydrocarbons as gasoline

(TPHg with BTEX distinction measured by EPA Methods 5030/8015/8020)

TOG: Total oil and grease (measured by Standard Method 5520 E and F)
VOC: Volatile organic compounds (measured by EPA Method 8240)

Pb: Organic lead (measured by California LUFT Manual Method, 12/87)

Sample Identification:

S-12-T1W

Tank number and locator

Depth of sample Soil sample



TABLE 3 LABORATORY ANALYSIS OF PRODUCT-LINE AND PRODUCT-DISPENSER SOIL SAMPLES ARCO Station 2035 Albany, California

Sample ID	В	T	E	X	TPHg
July 19, 1991			· ·		
S-2½-PL1	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
S-21/2-PL2	< 0.005	< 0.005	< 0.005	< 0.005	< 1.0
S-1-PL3	0.005	0.02	0.016	0.12	1.7
S-1-PL4	36	320	100	640	4,200
S-1-PL5	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
S-1-PL6	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
S-1-PL7	0.10	0.37	0.16	1.2	11
S-1-PL8	3.6	28	29	200	1,900
S-1-PL9	0.2	0.78	0.36	3.1	110
S-1-PL10	0.09	0.43	0.72	2.8	84
S-21/-PD1	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
S-21/2-PD2	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
S-1-PD3	< 0.005	< 0.005	< 0.005	< 0.005	< 1.0
S-1-PD4	< 0.005	< 0.005	< 0.005	12	330
S-1-PD5	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
S-1-PD6	0.13	0.28	0.48	3.8	87
S-1-PD7	0.35	2.1	1.1	47	1,000
S-1-PD8	< 0.005	< 0.005	< 0.005	< 0.005	<1.0
August 9, 1991					
S-1%-PL4	0.21	0.040	0.15	0.12	4.1

Results in parts per million (ppm).

<: Less than the laboratory detection limit.

B: benzene, T: toluene, E: ethylbenzene, X: total xylenes

BTEX: Measured by EPA Method

Total petroleum hydrocarbons as gasoline (measured by EPA Method TPHg: S-1%-PL1

Sample Identification:

-Depth of sample -Soil sample



TABLE 4
LABORATORY ANALYSIS OF COMPOSITE SOIL SAMPLES
ARCO Station 2035
Albany, California

Sample ID	В	Т	E	X	TPHg	Pb
July 7, 1991					· · · · · ·	
S-0709-SP(A-D)	0.16	0.76	0.051	7.8	200	NA
July 22, 1991						
S-0722-1(a-d)	< 0.0050	< 0.0050	< 0.0050	< 0.0050	78	NA
S-0722-2(a-d)	0.05	0.1	0.05	0.34	81	NA
July 23, 1991						
S-0723-3(a-d)	0.032	0.035	0.045	0.17	130	NA
S-0723-4(a-d)	< 0.0050	< 0.0050	< 0.0050	0.054	31	< 0.0
July 25, 1991						
S-0725-3(a-d)	0.0080	0.0080	0.011	0.049	31	NA
S-0725-5(a-d)	< 0.0050	0.0070	< 0.0050	0.010	47	NA
S-0725-6(a-d)	0.0080	0.018	0.029	0.10	49	NA
S-0725-7(a-d)	0.013	0.018	0.032	0.22	65	NA

Results in parts per million (ppm). NA: Not analyzed. B: benzene, T: toluene, E: ethylbenzene, X: total xylenes

BTEX: Measured by EPA Method

TPHg: Total petroleum hydrocarbons as gasoline (measured by EPA Method).

Pb: Organic lead (measured by California LUFT Manual, 12/87).

Sample Identification:



TABLE 5 LABORATORY ANALYSIS OF WATER "GRAB' SAMPLE FROM T4 TANK PIT ARCO Station 2035 Albany, California

Sample ID	В	Т	E	x	ТРНg
"Grab"	27,000	41,000	4,100	28,000	190,000

Results in parts per billion (ppb).

<: Less than the laboratory detection limit.

B: benzene, T: toluene, E: ethylbenzene, X: total xylenes TPHg: Total petroleum hydrocarbons as gasoline

(TPHg with BTEX distinction measured by EPA Methods 5030/8015/8020)

APPENDIX A

Field Protocol

FIELD PROTOCOL

The following presents Applied GeoSystems' protocol for a typical site investigation involving gasoline hydrocarbon-impacted soil and/or ground water.

Site Safety Plan

The Site Safety Plan (Applied GeoSystems 60009-1S, March 22, 1990) describes the safety requirements for the evaluation of gasoline hydrocarbons in soil, ground-water, and the vadose-zone at the site. The site Safety Plan is applicable to personnel of Applied GeoSystems and its subcontractors. Applied GeoSystems personnel and subcontractors of Applied GeoSystems scheduled to perform the work at the site are briefed on the contents of the Site Safety Plan before work begins. A copy of the Site Safety Plan is available for reference by appropriate parties during the work. A site Safety Officer is assigned to the project.

Soil Borings

The borings are drilled by a truck-mounted drill rig equipped with 8- or 10-inch-diameter, hollow-stem augers. The augers are steam-cleaned prior to drilling each boring to minimize the possibility of cross-contamination. After drilling the borings, monitoring wells are constructed in the borings, or neat-cement grout with bentonite is used to backfill the borings to the ground surface.

Drill Cuttings

Drill cuttings subjectively evaluated as containing hydrocarbons at levels greater than 100 parts per million (ppm) are separated from those subjectively evaluated as containing hydrocarbons at levels less than 100 ppm. Evaluation is based either on subjective evidence of soil discoloration, or on measurements made using a field calibrated OVM. Readings are taken by placing a soil sample into a ziplock-type plastic bag and allowing volatilization to occur. The intake probe of the OVM is then inserted into the headspace created in the plastic bag immediately after opening it. The drill cuttings from the borings are placed in labeled 55-gallon drums approved by the Department of Transportation, or on plastic at the site, and covered with plastic. The cuttings remain the responsibility of the client.



Soil Sampling in Borings

Soil samples are collected at no greater than 5-foot intervals from the ground surface to the total depth of the borings. The soil samples are collected by advancing the boring to a point immediately above the sampling depth, and then driving a California-modified, split-spoon sampler containing brass sleeves through the hollow center of the auger into the soil. The sampler and brass sleeves are laboratory-cleaned, steam-cleaned, or washed thoroughly with Alconox® and water, prior to each use. The sampler is driven with a standard 140-pound hammer repeatedly dropped 30 inches. The number of blows to drive the sampler each successive six inches are counted and recorded to evaluate the relative consistency of the soil.

The samples selected for laboratory analysis are removed from the sampler and quickly sealed in their brass sleeves with aluminum foil, plastic caps, and aluminized duct tape. The samples are then labeled, promptly placed in iced storage, and delivered to a laboratory certified by the State of California to perform the analyses requested.

One of the samples in brass sleeves not selected for laboratory analysis at each sampling interval is tested in the field using an OVM that is field calibrated at the beginning of each day it is used. This testing is performed by inserting the intake probe of the OVM into the headspace in the plastic bag containing the soil sample as described in the Drill Cuttings section above. The OVM readings are presented in Logs of Borings included in the project report.

Logging of Borings

A geologist is present to log the soil cuttings and samples using the Unified Soil Classification System. Samples not selected for chemical analysis, and the soil in the sampler shoe, are extruded in the field for inspection. Logs include texture, color, moisture, plasticity, consistency, blow counts, and any other characteristics noted. Logs also include subjective evidence for the presence of hydrocarbons, such as soil staining, noticeable or obvious product odor, and OVM readings.

Soil Excavation

Permits are acquired prior to the commencement of work at the site. Excavated soil is evaluated using a field calibrated (using isobutylene) Thermo-Environmental Instruments Model 580 Organic Vapor Meter (OVM). This evaluation is done upon arrival of the soil at the ground surface in the excavator bucket by removing the top portion of soil from the



bucket, and then placing the intake probe of the OVM against the surface of the soil in the bucket. Field instruments such as the OVM are useful for measuring relative concentrations of vapor content, but cannot be used to measure levels of hydrocarbons with the accuracy of laboratory analysis. Samples are taken from the soil in the bucket by driving laboratory-cleaned brass sleeves into the soil. The samples are sealed in the sleeves using aluminum foil, plastic caps, and aluminized duct tape; labeled; and promptly placed in iced storage. If field subjective analyses suggest the presence of hydrocarbons in the soil, additional excavation and soil sampling is performed, using similar methods. If ground water is encountered in the excavation, ground water samples are collected from the excavation using a clean Teflon® bailer. The excavation is backfilled or fenced prior to departure from the site.

Sampling of Stockpiled Soil

One composite soil sample is collected for each 50 cubic yards of stockpiled soil, and for each individual stockpile composed of less than 50 cubic yards. Composite soil samples are obtained by first evaluating relatively high, average, and low areas of hydrocarbon concentration by digging approximately one to two feet into the stockpile and placing the intake probe of a field calibrated OVM against the surface of the soil; and then collecting one sample from the "high" reading area, and three samples from the "average" areas. Samples are collected by removing the top one to two feet of soil, then driving laboratory-cleaned brass sleeves into the soil. The samples are sealed in the sleeves using aluminum foil, plastic caps, and aluminized duct tape; labeled; and promptly placed in iced storage for transport to the laboratory, where compositing is performed.

APPENDIX B

LOGS OF BORINGS

Soil Borings B-6 and B-7


UNIFIED SOIL CLASSIFICATION SYSTEM

MAJOR (DIVISION	LTR	DESCRIPTION	MAJOR I	DIVISION	LTR	DESCRIPTION
		GW	Well-graded Gravels or Gravel-Sand mixtures, little or no fines.			ML	Inorganic Silts and very fine sands, rock flour, Silty or Clayey fine Sands,
ļ	GRAVEL	GP	Poorly—graded Gravels or Gravel—Sand mixtures,		SILTS		or Clayey Silts with slight plasticity.
[AND GRAVELLY		little or no fines.]	AND CLAYS	CL	Inorganic Clays of low to medium plasticity, Gravelly
	SOILS	GM	Silty Gravels, Gravel—Sand— Silt mixtures.		LL<50		Clays, Sandy Clays, Silty Clays, Lean Clays.
COARSE-		GC	Clayey Gravel, Gravel—Sand —Clay mixtures.	FINE-		OL	Organic Silts and Organic Silt—Clays of low plasticity.
GRAINED SOILS	SAND	sw	Well—graded Sand or Gravelly Sands, little or no fines.	GRAINED SOILS	SILTS	мн	Inorganic Silts, micaceous or diatomaceous fine Sandy or Silty Soils, Elastic Silts.
	AND SANDY SOILS	SP	Poorty—graded Sands or Gravelly Sands, little or no fines.		AND CLAYS LL>50	СН	Inorganic Clays of high plasticity, fat Clays.
		SM	Silty Sands, Sand-Silt mixtures.			ОН	Organic Clays of medium to high plasticity, organic Silts.
		SC	Clayey Sands, Sand-Clay mixtures.	HIGHLY ORGA	ANIC SOILS	PT	Peat and other highly Organic Soils.

T	Depth through which sampler is driven		Sand pack
Ī	Relatively undisturbed sample		Bentonite
T	'	A A	Neat cement
黨	No sample recovered		Caved native soil
<u></u>	Static water level observed in well/baring		Blank PVC
$\frac{\bar{\Box}}{\Box}$	Initial water level observed in boring		Machine-slotted PVC
S-10	Sample number	P.I.D.	Photoionization detector

BLOWS REPRESENT THE NUMBER OF BLOWS OF A 140-POUND HAMMER FALLING 30 INCHES TO DRIVE THE SAMPLER THROUGH EACH 6 INCHES OF AN 18-INCH PENETRATION.

DASHED LINES SEPARATING UNITS ON THE LOG REPRESENT APPROXIMATE BOUNDARIES ONLY, ACTUAL BOUNDARIES MAY BE GRADUAL LOGS REPRESENT SUBSURFACE CONDITIONS AT THE BORING LOCATION AT THE TIME OF DRILLING ONLY.



UNIFIED SOIL CLASSIFICATION SYSTEM PLATE AND SYMBOL KEY ARCO Station 2035 1001 San Pablo Avenue Albany, California

B1

Depth of boring:	18 feet Diameter of	boring: 8 inc	hes Date drilled: 6-25-91
Well depth:	NA Material type:	NA	Casing diameter:NA
Screen interval: _	NA NA	_ Slot size:	NA .
Drilling Company <u>:</u>	Exceltech	Driller:	Gene & Richard
Method Used:	Hollow-Stem Auger		Field Geologist: Joel Coffman
Signo	ture of Registered Profes	ssional:	<u> </u>
	Registration No.:	State:	

Depth	Samp No.	le	Blows	P.I.D.	USCS Code	Description	Well Const.
- 0 -						Asphalt.	-V V V V
					SM	Sîlty sand, brown, dry, loose: fill.	
2 -					CL	Sandy clay, green—brown, dry to damp, medium plasticity, soft.	.
- 4 -							0 0 0 0
- 6 -	S-5.5		14 23 30	0		Brown, low plasticity, stiff.	2 2 2 2 2 2 2 2 2 2 2 2
- 8 -							
10							A A A A A A A A A A A A A A A A A A A
	5-10.5		11 12 22	0		Color change to green-brown.	\$ \$ \$ \$ \$
- 12 -							
14 -							
- 16 ~	S-15.5		12 15 33	0			$ \begin{array}{cccccccccccccccccccccccccccccccccccc$
	S-17		30 48 50	0	sc <u>▼</u>		\[\sigma
- 18 -					-	Total Depth = 18 feet.	
- 20 -							



LOG OF BORING B-6

ARCO Station 2035
1001 San Pablo Avenue
Albany, California

PLATE

В2

Depth of boring: 1	9-1/2 feet	_ Diameter of	boring: 8 in	ches Date drilled: 6-25-91
Well depth:	NA	Material type:	NA	Casing diameter:NA
Screen interval:	NA		Slot size: _	NA
Drilling Company <u>:</u>	Exceltect	<u> </u>	Driller:	Gene & Richard
Method Used:	Hollow-	-Stem Auger		Field Geologist: Joel Coffman
Signat	ture of Re	gistered Profes	ssional:	
	Registrat	ion No.:	State:_	

Depti	Samp No.	Blows	P.I.D.	USCS Code	Description	Well Const.
- 0 -	_				Asphalt.	
				SM	Silty sand, brown, dry, loose: fill.	A A A A A A A A A A A A
2 -	1			CL	Sandy clay, dark brown, dry, medium plasticity, medium plasticity, soft.	
4 -					Old cancrete slab, possible part of old foundation.	
- 6 -	S-5,5	30 40 30	0	CL	Sandy clay, brown, dry to damp, low plasticity, very stiff.	
- 8 -				GC	Clayey gravel, brown—gray, damp, dense.	A A A A A A A A A A A A A A A A A A A
- 10 - - 12 -	S-10.5	22 22 30	6.8	SC	Clayey sand, brown, damp, dense.	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
- 14 -		11		CL	Sandy clay, brown-olive, damp, low to medium plasticity, stiff.	V V V V
- 16 -	15.5	11 18	0			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
- 18 -	S-17	24	1.7	!		$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
	6 - 18.5	25 40 50	0	sc <u></u> ✓	Clayey sand, brown, damp, dense.	<u> </u>
20 -				-	Total Depth = 18 feet.	, , ,

Applied	GeoSystems
PROJECT:	69036.03

LOG OF BORING B-7

ARCO Station 2035
1001 San Pablo Avenue
Albany, California

В3

PLATE

APPENDIX C

Chain of Custody Records

Laboratory Data Sheets

ARCO	Produ Division	JCts of Atlantic	Comp	oany					Task O	der No.	a	0	3 5	5 -	C	· / -		/		<u></u>			C	hain of Custody
ARCO Facili	ty no.	203	<	Cit	y 	AI	Kar		Cc	<u>uc: 110.</u>	Project	manag	er _ (∧Æ:		<u></u>		. as		II'Y	الأستطا	ا سنا ص	ı w	Laboratory name
ARCO engin				(Cr	o [111	J	elephon	ار کری	2069	Telepho	one no	ַעוניאַ באוריאַ	1 2	_ 	<u>327</u>	Fax	no.	ilre	121	ر قراسة عا	٤٠١٤	<:	Laboratory name Sequo i a Dentract number (as 9 0 3 6 - 0 3) Method of shipment
Consultant n		esn		<u> </u>	المحرار	7	<u>۱۱</u>	400) <u>(</u>	Address	<u>ر ا مارت</u> ۲ ۶	(Consul	A.	<u> </u>	12	<u>4</u>) [(Gar	nsuitant)\	<u> </u>	<u> </u>	12 U.L	7 7 4 17 8 4	<u> </u>	Chritiact number
-		<u>esn</u>	~ / /	142 L	. tur		<u>47</u>		(Consulta	nt) 32		/1 (4	Ma	ري يليد		7/	7,	77		2 A	SAN .	OSE I	I SYSI BRAL	Method of shipment
į				Matrix	,	P	'reserva	tion				₹ 8015	5=		3€				Metals VOA VOA	CAM Metals EPA 6010/7000 TTLC STLC C	٦			Seguora Courser
<u>a</u>		er no							g dat	g tim	020	180200	fied BO Diesel	ease 413.2	/SM50	010	1240	270	NOA	SFLC	第 口			
Sample I.D	Lab no.	Container no	Soil	Water	Other	l lc	e	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	ВТЕХЛРН <i>Ga_S</i> EPA M602/8020/8015	TPH Modified 8015 Gas Diesel	Oil and Grease 413.1 🗀 413.2 🗀	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	r' #8 □		Lead Org./DHS L. Lead EPA 7420/7421			
		రి	ļ		<u> </u>	ļ			Sa	Sa	8TE 602	BT8	TP	Oil 413	EP.	£b/	EP/	a i	<u>Ş</u> <u>₹</u>	<u>5</u> E	a 25			Special detection
55/zB6	\checkmark		X	<u></u>					6.25.91			X	- ,			10		}	7					Limit/reporting
S10/2B6												入				IC		Y6	5		j			
S15/2Be												χ				IC	المرسيل	4.5	6					
S17 B6			1/-			11					1	Ý) 	Y (2/	ח					Special QA/QC
55/287	/											(<u>)</u>					7	/ T						
	,		+	 		+-}					 	7				_/C	7	× 1	$\frac{2}{2}$					
S10/287	1		-								-	X		 .		/(201	7					
S15/287	\mathcal{L}_{j}			ļ 	ļ		 					X				10	X0	<u>}_</u> \	\supset					Remarks
S17 B7	_/_											X				/(X 2	363	1					TAHa
518/287	/		X			17	と		6-25-91	ļ.		X				/	\mathcal{X}_{a}	363	\exists					TAHG and BTEX
) <u></u>																								RIEX
							-																	
											. 								_					
				-							ļ		<u> </u>											Lab number
			ļ <u>.</u>	ļ <u></u>		ļ <u>.</u>					<u> </u>													
				<u> </u>	<u> </u>																			Turnaround time
																			}				(Priority Rush 1 Business Day
Condition of	sample:	<u> </u>	•	. *			<u>-</u>		•		Temp	erature	receive	ed: /		*····	<u>* </u>		1.			•		
Relinquished			2 10	····			D	ate	5.91	Time	Recei	ed by	- \	10.	. \$	1.	1^	pole	_		,			Rush 2 Business Days
Retinguishe		O7	TVV	lan-				ر کر عر ate) - [[T-ph~	Recei	Ved by	<u> </u>	<i>I</i> W	<u>~</u> (<u>Lan</u>	W161	100K						Expedited
Ит	. , ,	\sim	<u>Xen</u>	Man	sol_	 			4E91	520 pm		·····												5 Business Days
Relinquishe	d by				.—•			ate		Time	Recei	ved by	laborat	ory 0	7	\sim		Date	<		Time	=		Standard 10 Business Days
											1 1	<u>1 . </u>	<u>ا</u>	$-\infty$	$\sim \pm$	<u> </u>						<u> </u>		<u> </u>



RECEIVED

JUL 8 1991

APPLIED GEOSYSTEMS SAN JOSE BRANCH

Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Joel Coffman

Project: ARCO #2035, Albany

Enclosed are the results from 9 soil samples received at Sequoia Analytical on June 25,1991. The requested analyses are listed below:

SAMPLE #	PLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1063624	Soil, S-5½ 25	6/25/91	EPA 5030/8015/9020
1063625	Soil, S-10½ B6	6/25/91	EPA 5030/8015/8020
1063626	Soil, S-15½ B6	6/25/91	EPA 5030/8015/8020
1063627	Soil, S-17 B6	6/25/91	EPA 5030/8015/8020
1063628	Soil, S-51/2 B7	6/25/91	EPA 5030/8015/8020
1063629	Soil, S-10½ B7	6/25/91	EPA 5030/8015/8020
1063630	Soil, S-15½ B7	6/25/91	EPA 5030/8015/8020
1063631	Soil, S-17 B7	6/25/91	EPA 5030/8015/8020
1063632	Soil, S-18½ B7	6/25/91	EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

Client Project ID: Matrix Descript: ARCO #2035, Albany

Soil

Analysis Method: First Sample #:

EPA 5030/8015/8020

106-3624

Sampled: Received: Jun 25, 1991 Jun 25, 1991

Analyzed: Reported:

6/ 25-26 /91 Jun 27, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
106-3624	S-5½ B6	N.D.	N.D.	N.D.	N.D.	N.D.
106-3625	S-10½ B6	N.D.	N.D.	N.D.	N.D.	N.D.
106-3626	S-15½ B6	N.D.	N.D.	N.D.	N.D.	N.D.
106-3627	S-17 B6	N.D.	N.D.	N.D.	N.D.	N.D.
106-3628	S-5½ B7	N.D.	N.D.	N.D.	N.D.	N.D.
106-3629	S-10½ B7	N.D.	N.D.	N.D.	N.D.	N.D.
106-3630	S-15½ B7	N.D.	N.D.	N.D.	N.D.	N.D.
106-3631	S-17 B7	N.D.	N.D.	N.D.	N.D.	N.D.
106-3632	S-18½ B7	N.D.	N.D.	N.D.	N.D.	N.D.

Detection Limits:	1.0	0.0050	0.0050	0.0050	0.0050
<u></u>					

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Project Manager

1063624.APG < 1>



Client Project ID: ARCO #2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Dave Higgins

QC Sample Group: 1063624-3627, 3630-3632

Reported: Jun 27, 1991

QUALITY CONTROL DATA REPORT

ANALYTE		· · · · · · · · · · · · · · · · · · ·	Ethyl	
	Benzene	Toluene	Benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	C. Donohue	C. Donohue	C. Donohue	C. Donohue
Reporting Units:	ng	ng	ng	ng
Date Analyzed: QC Sample #:	Jun 25, 1991	Jun 25, 1991	Jun 25, 1991	
QC Sample #.	GBLK 062591	GBLK 062591	GBLK 062591	GBLK 062591
Sample Conc.:	N.D.	N.D.	N.D.	ND
Sample Conc.	N.D.	N.D.	IV.D.	N.D.
0 - 11 - 0				
Spike Conc. Added:	100	100	400	000
Added:	100	100	100	300
Conc. Matrix	04	20	0.4	
Spike:	91	90	91	270
Matrix Spike	••			
% Recovery:	91	90	91	90
Conc. Matrix				
Spike Dup.:	94	93	92	270
Matrix Spike				
Duplicate				
% Recovery:	94	93	92	90
Relative				
% Difference:	3.2	3.3	1.1	0.0

SEQUOIA ANALYTICAL

#lizabeth W. Hackl Project Manager % Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1063624.APG <2>



Client Project ID: ARCO #2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Dave Higgins

QC Sample Group: 1063628-3629

Reported: Jun 27, 1991

QUALITY CONTROL DATA REPORT

ANALYTE	-	<u></u>	Ethyl	
	Benzene	Toluene	Benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	ng	пg	ng	ng
Date Analyzed:	Jun 26, 1991	Jun 26, 1991		Jun 26, 1991
QC Sample #:	GBLK 062591	GBLK 062591	GBLK 062591	GBLK 062591
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
Conc. Matrix Spike:	00	20		.=.
Spike.	89	89	89	270
Matrix Calles				
Matrix Spike % Recovery:	89	89	89	90
75 Hebbyery.	00	09	09	90
Conc. Matrix				
Spike Dup.:	88	87	87	250
Matrix Spike Duplicate				
% Recovery:	88	87	87	83
			O,	00
Relative				
% Difference:	1.1	2.3	2.3	7.7

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager % Recovery:

Conc. of M.S. - Conc. of Sample x 100

Spike Conc. Added

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D. x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1063624.APG <3>

ARCOT	Division	of Allantic	Comp chichlield(Dany	₹			Task O	der No.	26.	_3-	97-	-1		•								Custody
RCO Facility	^{/ no.} 2	035	-	City (Fa	y cility) <i>i</i>	Alba	nV			Project (Consul	manag Itant)	jer Jo	el (Cof	Emo	λn	•				2435	Laborator	y name
RCO engine	eCh	nck	Car	mel			Telephor (ARCO)	e no.		Telepho (Consul	one no ltant) 1	US.	264.	77	23	Fax (Co	no. nsultan	458	326	4-3	2435	Contract	number
onsultant na	$^{\text{ame}} \bigwedge_{a}$	police	Ce	งรีษร	tem	5	• • • • • • • • • • • • • • • • • • • •	Address (Consulta	int) 3315	Alm	ade	LE)	c. #	34	Sar	Jo	s€ (ĆA		5118		6707	73
				Matrix			rvation		*		,,								8010/7000 []	П		Method of	shipment
Sample I.D.	Lab no.	Container no.	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/801	TPH Modified 8015 Gas Dieset	Oil and Grease 413.1 ☐ 413.2 ☐	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Semi	CAM Metals EPA 6010/7000	Lead Org./DHS ☐ Lead EPA 7420/7421 ☐			atory on
10709 NPJ			X			×		7-9-91	800		×											Special d Limit/repo	
-0709			X			×			0845		×												
6709 NP3			X			X			0910		×												
-0709 1184			X			X			0950		X											Special C	A/QC
NC3			1			4			1015		X												
0709- NP6 -0709- NP7			X	ļ		X			1030	<u> </u>	X												
NP7			*			メ			1050	<u> </u>	X	<u> </u>						ļ	ļ			- Hemarks	
0709 - NP8			メ	ļ		7			1120	ļ	X											_	
0709 NP9			X_			X			1150	<u> </u>	X							<u> </u>					
NP10 -0109			X			X			1305		X				!			<u> </u>	ļ			_	
NPII -0709		 	X	-		X			1340	†	X	ļ		ļ									
N1912			*			X	1		1400	1	X	<u> </u>					-					_	
NP12 NP13 NP14 NP14			X			X			1430	+	X								-			Lab num	ber
10709			7			*			1500	1	X								<u> </u>				
NP15 -0709			X			<u> </u>			ļ		X	-				<u> </u>		ļ	ļ			Turnarou Priority	8 62
ondition of	sample:]	<u> </u>		<u> </u>	Κ			1620	+	X erature	receiv	ed: -A	400 1	1	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	1 Busin	ess Day
lelinquished			1				Date		Time	ļ	ved by		1	ומיווי	rend		•			<u> </u>		Aush 2 Busine	ess Days R
Relinquished	1/1-1 by		tave	<u> </u>	رر		7/9/9 Date		Time	Recei	ved by	Col	<u> </u>	N	1	Js.						Expedite 5 Busine	ed ess Days
Relinquished	by				•		Dale		Time	Recei	ived by	labora		Ri	1/2	- 1	Date 7	9-9	7 /	Time	.00	Standar	·

ARCO Pi Jucts Company \$\ \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Task Order	· No.	20	- 35-	91 -	- /									Chain of Custody
ARCO Facility no. 1035 City All	any, CA		Project (Consul	manag lant)	ger Ja	oel	Cof	fmo	14				. 24.		Laboratory name
ARCO engineer Chuck Carnel	Telephone no. (ARCO)		Telepho (Consul	ne no.	08-3	264.	フフ	23	Fax (Co	no. ⁴ nsultar	108	264	. 24.	35	Contract number
ARCO engineer Chack Carnel Consultant name Applications Consultant name Applications	Address (Consultant)	73/5	-A1	mad	le. E	χŤ	34	50	inde	50	CA	95	118		07073
Matrix Pres	ervation						l			•	emi /OA□	0002/01			Method of shipment
Soil Water Other Ice	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8019 Gas ☐ Diesel ☐	Oil and Grease 413.1 □ 413.2 □	TPH EPA 418.1/SM503	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP S Metals VOA V	CAM Metals EPA 60	Lead Org./DHS ☐ Lead EPA 7420/7421 ☐		Mobile laboratory on site
50709 SPa X X	7-9-91 15	45													Special detection Limit/reporting
\$ 0109 \$ 5 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	737 15	545													
S 0709	14	545	7	X											
K-0709 8 X	1/53 15	545													Special QA/QC
															_
				<u> </u>											_
															- Remarks
										·					_
										/					Lab number
										:					Turnaround time
															Priority Rush 1 Business Day
Condition of sample:	[Date	Time			receive	H :bs	Mpi	en	<u>t</u>	1					Rush &
Relinquistied by samples	7/9/9 1 16	Time	Receiv	ина Dy —	Co	de		h	\mathcal{J}_{r}	,					2 Business Day
Relinquished by	Date	Time	Receiv	ed by			<u> </u>	1							Expedited 5 Business Days
Relinquished by Z Distribution: White copy — Laboratory; Canary copy — ARCO Env	Date	Time		Yc.	labora	ory.			-)ale 7 - 9	-91	,	Time /8	60	Standard 10 Business Days

APPC-3292 (2-91)

Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118

Attention: Joel Coffman

Project: ARCO Station 2035, Albany

Enclosed are the results from 17 soil samples received at the Sequoia Analytical Mobile Lab on July 9,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1079697	Soil, S-0709-NP1	7/9/91	EPA 5030/8015/8020
1079698	Soil, S-0709-NP2	7/9/91	EPA 5030/8015/8020
1079699	Soil, S-0709-NP3	7/9/91	EPA 5030/8015/8020
1079700	Soil, S-0709-NP4	7/9/91	EPA 5030/8015/8020
1079701	Soil, S-0709-NP5	7/9/91	EPA 5030/8015/8020
1079702	Soil, S-0709-NP6	7/9/91	EPA 5030/8015/8020
1079703	Soil, S-0709-NP7	7/9/91	EPA 5030/8015/8020
1079704	Soil, S-0709-NP8	7/9/91	EPA 5030/8015/8020
1079705	Soil, S-0709-NP9	7/9/91	EPA 5030/8015/8020
1079706	Soil, S-0709-NP10	7/9/91	EPA 5030/8015/8020
1079707	Soil, S-0709-NP11	7/9/91	EPA 5030/8015/8020
1079708	Soil, S-0709-NP12	7/9/91	EPA 5030/8015/8020
1079709	Soil, S-0709-NP13	7/9/91	EPA 5030/8015/8020
1079710	Soil, S-0709-NP14	7/9/91	EPA 5030/8015/8020
1079711	Soil, S-0709-SP (A-D)	7/9/91	EPA 5030/8015/8020
1079712	Soil, S-0709-NP15	7/9/91	EPA 5030/8015/8020
1079713	Soil, S-0709-NP16	7/9/91	EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager 1079697.APG <1>

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

Client Project ID:

ARCO Station 2035, Albany

Soil

Matrix Descript: Analysis Method: First Sample #:

EPA 5030/8015/8020

107-9697

Sampled: Received: Jul 9, 1991 Jul 9, 1991

Analyzed: Reported: Jul 9, 1991 Jul 10, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
107-9697	S-0709-NP1	N.D.	0.025	0.027	0.0060	0.024	
107-9698	S-0709-NP2	N.D.	N.D.	N.D.	N.D.	N.D.	
107-9699	S-0709-NP3	N.D.	N.D.	0.0050	N.D.	0.018	
107-9700	S-0709-NP4	N.D.	0.0050	0.0050	N.D.	N.D.	
107-9701	S-0709-NP5	N.D.	0.012	0.013	N.D.	0.0080	
107-9702	S-0709-NP6	N.D.	0.017	0.021	0.014	0.056	
107-9703	S-0709-NP7	N.D.	0.0060	0.0060	N.D.	N.D.	
107-9704	S-0709-NP8	N.D.	N.D.	N.D.	N.D.	N.D.	
107-9705	S-0709-NP9	N.D.	N.D.	N.D.	N.D.	N.D.	
107-9706	S-0709-NP10	N.D.	0.0090	0.0060	N.D.	N.D.	
Detection Limits	§:	1.0	0.0050	0.0050	0.0050	0.0050	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Prøject Manager

Applied GeoSystems 3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Joel Coffman Client Project ID: Matrix Descript: Analysis Method: ARCO Station 2035, Albany

Soil EPA 5030/8015/8020

First Sample #: 107-9707

Sampled:

Jul 9, 1991 Jul 9, 1991

Received: Analyzed:

Reported:

Jul 9, 1991 Jul 10, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-9707	S-0709-NP11	N.D.	N.D.	N.D.	N.D.	N.D.
107-9708	S-0709-NP12	N.D.	N.D.	N.D.	N.D.	N.D.
107-9709	S-0709-NP13	N.D.	N.D.	N.D.	N.D.	N.D.
107-9710	S-0709-NP14	N.D.	N.D.	N.D.	0.0050	0.0080
107-9711	S-0709-SP (A-D)	200	0.16	0.76	0.051	7.8
107-9712	S-0709-NP15	N.D.	N.D.	N.D.	N.D.	0.0060
107-9713	S-0709-NP16	N.D.	N.D.	N.D.	N.D.	N.D.

Detection Limits:	1.0	0.0050	0.0050	0.0050	0.0050

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Froject Manager

1079697.APG <2>



Client Project ID: ARCO Station 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1079697-1079713

Reported: Jul 10, 1991

QUALITY CONTROL DATA REPORT

ANALYTE		· · · · · · · · · · · · · · · · · · ·	Ethyl	
	Benzene	Toluene	Benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Chieffo	S. Chieffo	S. Chieffo	S. Chieffo
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 9, 1991	Jul 9, 1991	Jul 9, 1991	Jul 9, 1991
QC Sample #:	BLK 070991	BLK 070991	BLK 070991	BLK 070991
Sample Conc.:	28	33	6.1	32
Spike Conc.				
Added:	100	100	100	300
Conc. Matrix				
Spike:	110	110	100	310
Matrix Spike				
% Recovery:	82	77	94	93
-				
Conc. Matrix				
Spike Dup.:	100	100	98	300
			00	000
Matrix Spike				
Duplicate %	70	27	•	
% Recovery:	72	67	92	89
Relative	0.5			
% Difference:	9.5	9.5	2.0	3.3

Quality Assurance Statement: All standard operating procedures and quality control requirements have been met.

SEQUOIA ANALYTICAL

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

Elizabeth W. Hackl /Project Manager

(Conc. of M.S. + Conc. of M.S.D.) / 2

ARCO I	Produ Division	of Atlantic	Comp Richfield	Dany Company				Task O	der No.	20	335	9	1-	/							Chain of Custody
ARCO Facilit ARCO engine Consultant na	y no. 2 eer Clame	nuck	Ca d Ge	Cit (Fi	y acility) Sdr M	Alba	(ARCO)	Address (Consulta	nt) 3 3/5	Project (Consu Telepho (Consu	manaciltant) one not ltant)	108 408	rel 264	Co 1-11 34	ff 23 Sa	Ma Fax (Co	no. (4	108/ 1) 2	1	2435-	Laboratory name EQUDIA Contract number 07-07-3
-				Matrix		Prese	rvation		e e		/8015	TPH Modified 8015 Gas ☐ Diesel ☐	•	щ				TCLP Semi Metals □ VOA □ VOA □	S EPA 6010/7000 STLC [Lead Org./DHS ☐ Lead EPA 7420/7421 ☐	Method of shipment MOBILE LAR (SCOTT)
O: 0209	Гар по.	Container no	Soil	Water	Other	Ice	Acid	Sampling date		BTEX 602/EPA 8020		TPH Modi	Oil and G	TPH EPA 418.	EPA 601/6	EPA 624/8240			CAM Metal	Lead Org Lead EPA 7420/7421	(Scorr) Special detection
5-0709 NP17 S-0709 NP18			×			×		7-9-91 7-9-91	1700		× ×					-	122				Limit/reporting
																					Special QA/QC
																					Remarks
											·										
						:															Lab number Turnaround time
Condition of s	sample:	0	×900	2_						Tempe	erature	receive	d:	Co	· O(2					Priority Rush 1 Business Day
Relinquished	Loci	oler	Than		ر		Date 7/9/9 Date	`\	Time 1760	Receiv	red by	S	est	1		2-	ff	1			Rush 2 Business Days Expedited
Relinquished	by	w _ lah	oratos	Concre	000		Date	Ingineering; P	Time	Receiv	ed by	Alforato	H	Ri	Ph	!	ate 7 -	7-9		Time (P; Q	5 Business Days

APPC-3292 (2-91)

Re(10 2 / Deta Statupen 2020 7/9/9/



- R 1991

APPLIED GEOSYSTEMS SAN JOSE BRANCH

Applied GeoSystems 3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

Client Project ID: Matrix Descript:

Analysis Method: First Sample #:

Soil EPA 5030/8015/8020

ARCO 2035, Albany, 69036.03

107-1229

Sampled: Received:

Jul 9, 1991 Jul 9, 1991

Analyzed: Jul 10, 1991 Reported:

Jul 11, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-1229	S-0709, NP17	N.D.	N.D.	N.D.	N.D.	N.D.
107-1230	S-0709, NP18	N.D.	N.D.	N.D.	N.D.	N.D.

Detection Limits: 1.0 0.0050 0.0050 0.0050 0.0050

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

Please Note:

Amended report on 8/7/91

1071229.APG <1>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 107-1229

Reported: Jul 11, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl	
<u></u>	Benzene	Toluene	Benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 10, 1991	Jul 10, 1991	Jul 10, 1991	Jul 10, 1991
QC Sample #:	GBLK 070991	GBLK 070991	GBLK 070991	GBLK 070991
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Cuiles Cons				
Spike Conc. Added:	100	100	100	300
Conc. Matrix				
Spike:	96	97	97	280
Matrix Spike				
% Recovery:	96	97	97	93
Conc. Matrix	0.4	•		 -
Spike Dup.:	94	94	94	280
Matrix Spike				
Duplicate % Recovery:	94	94	94	93
,	O T	57	07	<i>3</i> 0
Relative				
% Difference:	2.1	3.1	3.1	0.0

Quality Assurance Statement: All standard operating procedures and quality control requirements have been met.

SEQUOIA ANALYTICAL

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

1 . 1 col (1 1 1/16) 2 / 1 / 1

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

Elizabeth W. Hackl Project Manager

(Canc. of M.S. + Canc. of M.S.D.) / 2

1071229.APG <2>

ARCO	Produ Division	ucts (Comp	Dany (\$			Task O	rder No.	20	 D3≤	5-9	1/-	/								Chain of C	Custody
ARCO Facili	ty no.	203.	5	City (Fa		Alba	inv. (^A		Project (Consul	manag itant)	jer	Ja e	Ca	ff	Ma	м					Laboratory nam	e
ARCO engir	eer (hucl	c C	armo			Telephon (ARCO)	ie no.		Telepho (Consul	one no.	M18 -	2/.4	-77	27	Fax	ri CNO. Insultar	(408	3)26	4-2	435	Control	
Consultant r		می ارد	1				10	Address (Consulta	int) 33/3	Alv	nast	h E	xou	43	- 3 4 5	- No.	11:5	"'' آم مآ	$^{\circ}\mathcal{A}$	95	112	Contract number	
	(3	<u> </u>	Matrix		Presei	rvation						١.						2000			Method of ships	
		۵۰.		l			1	Tate	e E	_	20/801	8015 el 🗀	3.2	1503E	_		_	Pag []	A 6010/				
Sample I.D.	ē.	Container no	Soil	Water	Other	Ice	Acid	Sampling date	Sampling time	7A 802(TPH 1602/80	odified Dies	Greas	18.1/SN	01/8010	24/8240	25/8270	TCLP Semi	etals EF	5.9.2 £ ∏			
Saml	Lab no	Cont						Samp	Samp	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8015 Gas Diesel	Oil and Grease 413.1 🗀 413.2 🗆	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP	CAMIN	Lead Org./DHS Lead EPA 7420/7421			= =
>15-EW	_	,	X			*		7-8-91	1720	1 -	X					21.						Special detection Limit/reporting	ЭП
SUSSE			X	,		X		7-8-91	1710		\rightarrow				{		27						
S-16-Sh		/	7			*		7-8-91			X				~		28						
2-15-51		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Κ			~		7-10-91	0930		7				7	غ	११					Special QA/QC	
8-15-N			1			X			1000		X					·	30						•
5-1:-1		أسرا	Χ.			×			1330		×					,	B1						
3-15-1			Κ			X		1	1400		x					3	3 2.						
5-9-11	l .	أمسم	Χ			X			1600		X					-	₹3					Remarks	
2-8-N			X			X			1620		Y				\rightarrow	ي .	8 4 1						
5-15-		/	X			X			1645		X				\$	3	35						
<u> </u>																							
																						Lab number	
																						Turnaround tim	e
														^4		,						Priority Rush 1 Business Da	ay 🗆
Condition of	1		1	<u> 900</u>	<u> </u>	ı ı	Data		*:			receive		13	<u> 26</u>	1/						Rush	
Relinquished	1 1/2	pler	Mr	auen		į	Date 7-12-	91	Time /600	Hecen	ved by	7	7	7	//	4	39	7				2 Business Da	ays 🗆
Relinquished		4	//	#3	R.		Date	<u> </u>	Time	Recei	ved by	~		U,	y		<u> </u>	*				Expedited 5 Business Da	ays 🗆
Relinquishei	<u> </u>	<i>∵</i>					Date	Engineering; f	Time	<u> </u>	4.(iaborati	•	لت.	2	1	Date	[S]	91	Time	sp	Standard 10 Business C	ays 🗡

71000



Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Joel Coffman

Project: ARCO 2035, Albany

Enclosed are the results from 10 soil samples received at Sequoia Analytical on July 12,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1072126	Soil, S-15-EWC	7/8/91	EPA 5030/8015/8020
1072127	Soil, S-15-SE	7/8/91	EPA 5030/8015/8020
1072128	Soil, S-16-SW1	7/8/91	EPA 5030/8015/8020
1072129	Soil, S-15-SW	7/8/91	EPA 5030/8015/8020
1072130	Soil, S-15-NWC	7/8/91	EPA 5030/8015/8020
1072131	Soil, S-15-WWC	7/8/91	EPA 5030/8015/8020
1072132	Soil, S-15-NWF	7/8/91	EPA 5030/8015/8020
1072133	Soil, S-9-NWW	7/8/91	EPA 5030/8015/8020
1072134	Soil, S-8-NW	7/8/91	EPA 5030/8015/8020
1072135	Soil, S-15-NW	7/8/91	EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Joel Coffman

Client Project ID: Matrix Descript:

Analysis Method:

First Sample #:

ARCO 2035, Albany

Soil

EPA 5030/8015/8020

Sampled: Received:

Jul 8, 1991 Jul 12, 1991

Analyzed: Reported:

Jul 16, 1991 Jul 24, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

107-2126

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
107-2126	S-15-EWC	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2127	S-15-SE	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2128	\$-16-\$W1	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2129	S-15-SW	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2130	S-15-NWC	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2131	S-15-WWC	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2132	S-15-NWF	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2133	\$-9-NWW	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2134	S-8-NW	N.D.	N.D.	N.D.	N.D.	N.D.	
107-2135	S-15-NW	N.D.	N.D.	N.D.	N.D.	N.D.	
Detection Limits:		1.0	0.0050	0.0050	0.0050	0.0050	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1072126.APG <1>



Applied GeoSystems 3315 Almaden Expressway, Ste 34 Client Project ID: ARCO 2035, Albany

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1072126-35

Reported:

Jul 24, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 16, 1991	Jul 16, 1991	Jul 16, 1991	Jul 16, 1991
QC Sample #:	GBLK071691	GBLK071691	GBLK071691	GBLK071691
	MS/MSD	MS/MSD	MS/MSD	MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Saika Cana				
Spike Conc. Added:	100	100	100	300
Added.	100	100	100	300
Conc. Matrix				
Spike:	92	92	93	270
Matrix Spike				
% Recovery:	92	92	93	90
Conc. Matrix				
Spike Dup.:	92	91	92	270
•	-	<u> </u>	- -	•
Matrix Spike				
Duplicate				
% Recovery:	92	91	92	90
Relative				
% Difference:	0.0	1.1	1.1	0.0

SEQUOIA ANALYTICAL

Rroject Manager

Elizabeth W. Hacki

Relative % Difference:

% Recovery: Conc. of M.S. - Conc. of Sample

x 100

ative % Difference: Conc. of

Conc. of M.S. - Conc. of M.S.D.

Spike Conc. Added

x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1072126.APG <2>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1072126-35

Reported:

Jul 24, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	ng	ng	ng	ng
Date Analyzed: QC Sample #:	Jul 16, 1991 GBLK071691	Jul 16, 1991 GBLK071691	Jul 16, 1991	Jul 16, 1991
QC Sample #.	MS/MSD	MS/MSD	GBLK071691 MS/MSD	GBLK071691 MS/MSD
	Wey web	WO WOD	1410/14105	1410/141013
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
0 84-4-5-				
Coпс. Matrix Spike:	96	94	95	280
Spike.	90	94	95	280
Matrix Spike				
% Recovery:	96	94	95	93
Conc. Matrix				
Spike Dup.:	93	92	92	270
•				
Matrix Spike				
Duplicate % Recovery:	02	92	00	00
% Recovery:	93	92	92	90
Relative				
% Difference:	3.2	2.2	3.2	3.6

SEQUOIA ANALYTICAL

_ / /

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

% Recovery:

Conc. of M.S. - Conc. of M.S.D.

x 100

Elizabeth W. Hackl Project Manager (Conc. of M.S. + Conc. of M.S.D.) / 2

1072126.APG <3>

ARCC	Prod	ucts	Com	pany Company	*			Task	Order No.	(203	35 -	91	- J								Chain of Custoo	iy
ARCO Fa	cility no.	1.62	4	Cit	y acility) /	$\Delta \mu_{ba}$	tsi <i>i</i>			Project	manag	jer										Laboratory name	
ARCO en	gineer		<u> </u>	<u>- 144.5</u> 	icility) /		Telephor	ne no.	11.5/1.6	Telepho (Consu	one no.	Dog	7 (44 -	112	7	Fax	по		204	- 14		Contract number	
Consultan	I name	IKCH	<u> </u>	11. c 1	. A	110	_(<u>, 1</u> .	475 - 57 Addr	71-2469 ess sultant) 33/5	A. i	nant) 7	<u> </u>	7	<u>, (</u>	- ,	_ الم	nsultar 4	() (),-1	/\$2		· · ·		
ļ	 	10v2	717	aus.	E, MIC	hid bec	1. 7/2/Gi	15" (Con	sultant) <u>メダイカ</u>	/*\]\\^ 	ددلادتر ا آ	ا برای	57,	Sich	. 36)	₹ . (.	<u> </u>	/) /.	8	1		Method of shipment	
				Matrix		Presei	vation		40		3015	ভাশ	元島	 				Semi	1 55 C	nón !		İ	
Sample I.D.	Гар по.	Container no.	Sail	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8015 Gas Diesel E	Oil and Grease 5 413.1 ☐ 413.2/	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Metals □ VOA □	CAM Metals EPA 6 TTLC STLC	Lead Org./DHS_DS- Lead EPA 7420/7421		Special detection	
2 13-11	V		X			7		7-3	91 1230		X					10-	108	96	1			Limit/reporting	
5/2-1	آءً ا		X			X		\$.	1240		X						(90	 	4			
S 12-13	لاد		X			ス			1250		X						1	100	<u> </u>	× 16			
. > 12 1 21	Ę		X			\times			1305	-	X							0,		35		Special QA/QC	
2.4243	n.		X			X			1245	-	X							02	1	Ž.			
× 12-T3			X			X			1300		X							03	}				
S-13 T			X			×			1330		X					-	(0	4				
13-74	i i	1	×			X			1340		X	×	1			ン	5	0	 			Hemarks	1
· · · ·											关	<u> </u>					1					scal surger with	
4-141	17			×		×	×	1	\$ 1430		X	n	215	Ca	ntic	N. 634	Scile	, c 2/	ech	chyc	वहार-	histor Tilly to	ı
19:00						1																Please analyce south south highest tilly he original lead	
		1			<u> </u>					 		-	 	ļ									
				-							1											-	
		ļ								 		-	 		<u> </u>							Lab number	
	_	-	<u> </u>								1											Turnaround time	
																						Priority Rush 1 Business Day	
<u> </u>	of sample						T		mget t			receiv	ed:	Coo	(_
Relinquis	hed by sa	mpler	17	all in	- .		Date 1/5/9	7/	Time 15 <i>0</i> -5	Hece	ived by	tt.	Dat.	, ₂ ,	داليه	e 🧐	355	-				2 Business Days	
Relinquis				1			Date		Time	Rece	ived by		V									Expedited 5 Business Days	
Relinquis	shed by						Date		Time	Rece	ived by	labora	tory				Date	/3		Time	SD	Standard 10 Business Days	A



Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Steve Strausz

Project: ARCO 2035, Albany

Enclosed are the results from 8 soil samples, 1 water samples, 0 other samples received at Sequoia Analytical on July 3,1991. The requested analyses are listed below:

1070898	Soil, S-12-T1W	7/3/91	EPA 5030/8015/8020
1070899	Soil, S-12-T1E	7/3/91	EPA 5030/8015/8020
1070900	Soil, S-12-T2W	7/3/91	EPA 5030/8015/8020
1070901	Soil, S-12-T2E	7/3/91	EPA 5030/8015/8020
1070902	Soil, S-12-T3W	7/3/91	EPA 5030/8015/8020
1070903	Soil, S-12-T3E	7/3/91	EPA 5030/8015/8020
1070904	Soil, S-13-T4N	7/3/91	EPA 5030/8015/8020
1070905	Soil, S-13-T4S	7/3/91	EPA 5030/8015/8020 EPA 8240 SM 5520 E&F (Gravimetric)
1070906	Water	7/3/91	EPA 5030/ 8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



Applied GeoSystems 3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Steve Strausz Client Project ID: Matrix Descript: Analysis Method:

First Sample #:

ARCO 2035, Albany Soil

EPA 5030/8015/8020 107-0898 Sampled: Ji Received: Ji Analyzed: Ji

Reported:

Jul 3, 1991 Jul 3, 1991 Jul 8, 1991

Jul 9, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-0898	S-12-T1W	N.D.	N.D.	N.D.	N.D.	N.D.
107-0899	S-12-T1E	N.D.	N.D.	N.D.	N.D.	N.D.
107-0900	S-12-T2W	N.D.	0.031	N.D.	0.0080	N.D.
107-0901	S-12-T2E	N.D.	0.019	N.D.	N.D.	N.D.
107-0902	S-12-T3W	48	1.2	2.4	1.0	3.8
107-0903	S-12-T3E	65	0.20	0.51	0.97	3.9
107-0904	S-13-T4N	6.2	0.45	0.039	0.18	0.33
107-0905	S-13-T4S	N.D.	0.061	0.034	0.0080	0.15

Detection Limits:	1.0	0.0050	0.0050	0.0050	0.0050	
		0.000	0.000	0.0000	0.0000	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1070898.APG <1>



Sampled: Applied GeoSystems Client Project ID: ARCO 2035, Albany Jul 3, 1991 3315 Almaden Expressway, Ste 34 Sample Descript.: Water Received: Jul 3, 1991 San Jose, CA 95118 Analysis Method: EPA 5030 / 8015 / 8020 Analyzed: Jul 8, 1991 Attention: Steve Strausz Lab Number: 107-0906 Reported: Jul 9, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS WITH BTEX DISTINCTION (EPA 8015/8020)

Analyte Detection Limit Sample Results $\mu g/L$ (ppb) $\mu g/L$ (ppb)

Low to Medium Boiling F Benzene	oint Hydrocarbo	ons	30	*****************	190,000
Senzene		4	0.30	• • • • • • • • • • • • • • • • • • • •	27,000
thyl Benzene	**********	************	0.30	*********	41,000
(vienes	******************	*************	0.30 0.30	****************	4,100 28,000

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Steve Strausz

QC Sample Group: 1070898-0905

Reported: Jul 9, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl	
	Benzene	Toluene	Benzene	Xylenes
** 41 1	EPA	EPA	EPA	EPA
Method:	8015 / 8020	8015 / 8020	8015 / 8020	8015 / 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 8, 1991	Jul 8, 1991	Jul 8, 1991	Jul 8, 1991
QC Sample #:	GBLK 070891	GBLK 070891	GBLK 070891	GBLK 070891
Instrument I.D.:	GCHP-6	GCHP-6	GCHP-6	GCHP-6
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Saika Cana				
Spike Conc. Added:	100	100	400	000
Added:	100	100	100	300
Conc. Matrix				
Spike:	94	92	93	270
Matrix Spike				
% Recovery:	94	92	93	90
.				
Conc. Matrix				
Spike Dup.:	89	87	88	260
opine Dup	03	O7	00	200
Matrix Spike				
Duplicate				
% Recovery:	89	87	88	87
•				•
Relative				
% Difference:	5.5	5.6	5.5	3.8
/a Dillerence.	J.J	5.0	0.0	ა.ნ

Quality Assurance Statement: All standard operating procedures and quality control requirements have been met.

SEQUOIA ANALYTICAL

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

/Prøject Manager

(Conc. at M.S. + Canc. at M.S.D.) / 2

1070898.APG <3>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Steve Strausz

QC Sample Group: 1070898-0905

Reported: Jul 9, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			F-11	
ANALTIE	Benzene	Toluene	Ethyl Benzene	Xylenes
<u> </u>	Delizette	ioldelle	Delizeite	VAICTICS
	EPA	EPA	EPA	EPA
Method:	8015 / 8020	8015 / 8020	8015 / 8020	8015 / 8020
Analyst:	G. Meyer	G. Meyer	G. Meyer	G. Meyer
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 8, 1991	Jul 8, 1991	Jul 8, 1991	Jui 8, 1991
QC Sample #:	GBLK 070891	GBLK 070891	GBLK 070891	GBLK 070891
Instrument I.D.:	GCPE-2	GCPE-2	GCPE-2	GCPE-2
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
				545
Conc. Matrix				
Spike:	90	89	89	270
Matrix Spike				
% Recovery:	90	89	89	90
,-		30	55	
Conc. Matrix				
Spike Dup.:	87	86	85	250
2 h 2 2 les.	. .	5 5		
Matrix Spike				
Duplicate				
% Recovery:	87	86	85	83
Relative				
% Difference:	3.4	3.4	4.6	7.7

Quality Assurance Statement: All standard operating procedures and quality control requirements have been met.

SEQUOIA ANALYTICAL

Elizabeth W. Hacki

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

Project Manager

(Conc. of M.S. + Conc. of M.S.D.) / 2

1070898.APG <4>



ms Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Steve Strausz

QC Sample Group: 107-0906

Reported: Jul 9, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl	
	Benzene	Toluene	Benzene	Xylenes
	EPA	EPA	EPA	EPA
Method:	8015 / 8020	8015 / 8020	8015 / 8020	8015 / 8020
Analyst:	L. Laikhtman	L. Laikhtman	L. Laikhtman	L. Laikhtman
Reporting Units:	ng	ng		ng
Date Analyzed:	Jul 8, 1991	*	ng Jul 8, 1991	•
		Jul 8, 1991		Jul 8, 1991
QC Sample #:	GBLK 070891	GBLK 070891	GBLK 070891	GBLK 070891
Instrument I.D.:	GCHP-2	GCHP-2	GCHP-2	GCHP-2
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
Conc. Matrix				
Spike:	98	98	96	290
Spike.	30	90	90	290
Matrix Spike				
% Recovery:	98	98	96	97
•				
0 14 ()				
Conc. Matrix				
Spike Dup.:	98	97	96	290
Matrix Spike				
Duplicate	0.0	07	00	07
% Recovery:	98	97	96	97
Relative				
% Difference:	0.0	1.0	0.0	0.0
				

Quality Assurance Statement: All standard operating procedures and quality control requirements have been met.

SEQUOIA ANALYTICAL

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

Elizabeth W. Hackl Project Manager (Conc. of M.S. + Conc. of M.S.D.) / 2

1070898.APG <5>



Applied GeoSystems 3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Steve Strausz

Client Project ID: Matrix Descript:

Analysis Method:

First Sample #:

ARCO 2035, Albany

Soil

SM 5520 E&F (Gravimetric) 107-0905

Sampled:

Jul 3, 1991

Received: Extracted:

Jul 3, 1991 Jul 8, 1991

Analyzed: Reported: Jul 8, 1991 Jul 9, 1991

TOTAL RECOVERABLE PETROLEUM OIL

Sample Number	Sample Description	Oil & Grease mg/kg (ppm)
107-0905	S-13-T4S	N.D.

Detection Limits:

30

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager Project Manager

1070898.APG < 6 >



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Steve Strausz

QC Sample Group: 107-0905

Reported: Jul 9, 1991

QUALITY CONTROL DATA REPORT

ANALYTE	Total
	Oil & Grease
Method:	SM 5520 E:F
Analyst:	V. Nunzir
Reporting Units:	mg
Date Analyzed:	Jul 8, 1991
QC Sample #:	BLK 070891
Sample Conc.:	N.D.
oumpic conon	14.0.
Spike Conc.	
Added:	100
Conc. Matrix	
Spike:	84
·	
Matrix Spike	84
% Recovery:	04
Conc. Matrix	
Spike Dup.:	83
Matrix Saika	
Matrix Spike Duplicate	
% Recovery:	83
Relative % Difference:	1.2
% Dinerence:	1.2

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

% Recovery:

Conc. of M.S. - Conc. of Sample

x 100

Spike Cond. Added

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1070898.APG <7>



Applied GeoSystems 3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Steve Strausz

Client Project ID: Sample Descript: Analysis Method:

Lab Number:

ARCO 2035, Albany Soil, S-13-T4S **EPA 8240** 107-0905

Sampled: Received: Analyzed: Reported:

Jul 3, 1991 Jul 3, 1991 Jul 8, 1991 Jul 9, 1991

VOLATILE ORGANICS by GC/MS (EPA 8240)

Analyte	Detection Limit µg/kg		Sample Results µg/kg
Acetone	500		N.D.
Benzene	100	.,	160
Bromodichloromethane	100		N.D.
Bromoform	100		N.D.
Bromomethane	100		N.D.
2-Butanone	500		N.D.
Carbon disulfide	100	***************************************	N.D.
Carbon tetrachloride	100	***************************************	N.D.
Chlorobenzene	100		N.D.
Chloroethane	100	*******************************	N.D.
2-Chloroethyl vinyl ether	500		N.D.
Chloroform	100	***************************************	N.D.
Chloromethane	100	(14,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,1,	N.D.
Dibromochloromethane	100		N.D.
1,1-Dichloroethane	100		N.D.
1,2-Dichloroethane	100		N.D.
1,1-Dichloroethene	100	*******************************	N.D.
cis-1,2-Dichloroethene	100		N.D.
trans-1,2-Dichloroethene	100		N.D.
1,2-Dichloropropane	100	***************************************	N.D.
cis-1,3-Dichloropropene	100	***************************************	N.D.
trans-1,3-Dichloropropene	100		N.D.
Ethylbenzene	100		N.D.
2-Hexanone	500		N.D.
Methylene chloride	100		N.D.
4-Methyl-2-pentanone	500		N.D.
Styrene	100		N.D.
1,1,2,2-Tetrachioroethane	100	144144144444444444444444444444444444444	N.D.
Tetrachloroethene	100		N.D.
Toluene	100		N.D.
1,1,1-Trichloroethane	100		N.D.
1,1,2-Trichloroethane	100	***************************************	N.D.
Trichloroethene	100		N.D.
Trichlorofluoromethane	100		N.D.
Vinyl acetate	100	***************************************	N.D.
Vinyl chloride	100	***************************************	N.D.
Total Xylenes			

Analytes reported as N.D. were not present above the stated limit of detection.

Elizabeth W. Hackl Project Manager /Prøject Manager

1070898.APG <8>



Attention: Steve Strausz

Client Project ID:

ARCO 2035, Albany

3315 Almaden Expressway, Ste 34 Method (units): San Jose, CA 95118

Analyst(s):

EPA 8240 (μg/L purged)

L. Saunders QC Sample #: BLK 070891

Q.C. Sample Dates

Analyzed: Jul 8, 1991 Reported: Jul 9, 1991

QUALITY CONTROL DATA REPORT

Anaiyte	Sample Conc.	Spike Conc. Added	Conc. Matrix Spike	Matrix Spike % Recovery	Conc. Matrix Spike Duplicate	Matrix Spike Duplicate % Recovery	Relative % Difference
1,1-Dichloro- ethene	N.D.	50	43	86	44	88	2.3
Trichloroethene	N.D.	50	43	86	47	94	8.9
Benzene	N.D.	50	46	92	47	94	2.2
Toluene	N.D.	50	45	90	45	90	0.0
Chlorobenzene	N.D.	50	44	88	48	96	8.7

SEQUOIA ANALYTICAL

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added

x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

Ælizabeth W. Hackl Project Manager

(Conc. of M.S. + Conc. of M.S.D.) / 2

1070898.APG <9>

ARCO	Prodi Division	ucts i	Comp	oany :	\$			Task O	rder No.	(203	35-	91	'-/		•						C	hain of Custody	
ARCO Facili	y no.	107		Cit	y sciliba) /	Allva		THOR O	der No.	Project	manag												Laboratory name	
ARCO engin	eer ()	inch	Carr	ne)	ioniyy ,	.1.1517	Telephor (ARCO) 4	Task O	246 T	(Consu Teleph (Consu	one no.	108 - 3	264-	172	<u> </u>	Fa)	k no	708	264	1 - 2.4	135		Sequena Contract number	
Consultant r	S-ema	leve	514	4u5	Z, A30	Ired Geo	Systen	Address (Consulta	ant) 33/5	Alm	ecles 1	آمې⊼	34	San	زيمل	ح , د	Á	95-1	18				Comiaci number	
				Matrix		Preser												_ Ę₫	07000			ı	Method of shipment	
Sample 1.D.	Lab no.	Container no.	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/80	TPH Modified 8015 Gas Diesel X	Oil and Grease 5 5 4 13.1 ☐ 413.2 ☐	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Se	CAM Metals EPA 601	Lead Org./DHS/S Lead EPA 7420/7421 □			Lab Courier	
3-12-TILY		ļ	X			\geq		7-3-91	1230		X						108						Special detection Limit/reporting	
5-12-TIE			X			X		٥ /	1240	<u> </u>	X						(99		4				
5-12-72h			X			く			1250		X						1	100		3				
51272E			X			X			1305		X							0,		remirks			Special QA/QC	
5-12-T3W			X			X	•		1245		X							01	1	جُ				
8 12·T3 €		ļ	X			X			1300		X						(03						
5-13 74N			X			×			1330	<u></u>	X						\	0	4					
5-13-145			X			X			1540		X	×	1			X	5	0					Remarks Please unalted I	
			ļ. <u></u>								大												soil samper with	
W-14 [P	_			×		×	X	13	1430		X	n	te:	ca	Aic	. . ga	soli	وعام	ech	ch5i	nple	•	Please unaljee 2 soil samper with highest TPHs Lev organic lead	
			ļ					-	<u> </u>	ļ			ļ <u></u>	ļ									organic lead	
										ļ		<u> </u>	ļ										•	
										ļ.,, <u>.</u>													Lab number	
																							Turnaround time	
																							Priority Rush	_
Condition of			1,							Temp	erature	receive	•d:	· · · · · · · · · · · · · · · · · · ·			1		l		lI			
Relinquished	// ***	pler ကို (၁)	Alia	2/12			Date 7/3/9	,	Time 1505	Recei	ved by	-01	1			. ব	55						Rush 2 Business Days	
Relinquished				1			Date C		Time	Recei	ved by	_	(Lx		· vvv	<u>د</u>					·		Expedited 5 Business Days	
Relinquished	by		·				Date		Time	Recei	ved by	laborat	ery/			C	Date //	<u>/_</u> 3		Time			Standard 10 Business Days	X



69036.03



Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Steve Strausz

Project: ARCO 2035, Albany

Enclosed are the results from 2 soil samples received at Sequoia Analytical on July 3,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1070902	Soil, S-12-T3W	7/3/91	California LUFT Manual, 12/87
1070903	Soil, S-12-T3E	7/3/91	California LUFT Manual, 12/87

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Ælizabeth W. Hackf Prøject Manager



3315 Almaden Expressway, Ste 34 Sample Descript:

San Jose, CA 95118

Attention: Steve Strausz

Client Project ID:

ARCO 2035, Albany

Soil

California LUFT Manual, 12/87

Analysis Method: First Sample #:

107-0902

Sampled:

Jul 3, 1991

Received:

Jul 3, 1991

Analyzed: Reported: Jul 9, 1991 Jul 16, 1991

ORGANIC LEAD

Sample Number	Sample Description	Sample Results mg/kg (ppm)
107-0902	\$-12-T3W	N.D.
107-0903	S-12-T3E	N.D.

Detection Limits:

0.050

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1070902.APG <1>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Steve Strausz

Q.C. Sample Group: 107-0902

Reported: Jul 16, 1991

QUALITY CONTROL DATA REPORT

ANALYTE	· · · · · · · · · · · · · · · · · · ·		
	Organic Lead		
Method:	LUFT		
Analyst:	V. Patel		
Reporting Units:	mg/kg		
Date Analyzed:	Jul 9, 1991		
QC Sample #:	107-0902		
Sample Conc :	ND		

Sample Conc.:

Spike Conc.

Added: 0.50

Conc. Matrix

Spike: 0.48

Matrix Spike

% Recovery: 96

Conc. Matrix

Spike Dup.: 0.47

Matrix Spike Duplicate

% Recovery: 94

Relative

% Difference: 2.1

SEQUOIA ANALYTICAL

Elizabeth W. Hacki Project Manager % Recovery: Conc. of M.S. - Conc. of Sample x 100
Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D. x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1070902.APG <2>

ARCO F	Division	of Atlantic	:Richfield(Company					Order No.			35-										C	Chain of Custody
RCO Facility	у по. <u>/</u> зег (203	35	City (Fa	y cility)	Alba	Telephon (ARCO)	CA le no.		Project (Consul Telepho	manaç lanı) one no.	ger) o e	10	201	() ()/1 Fax	<u> ()()</u>	4605					SEQUOLA
onsultant na	ame 4	hhei	$\frac{1}{1}$	arme	<u>, </u>		(ÁRĊO)														243		Contract number
onsultant na		pplie	d Ce	<u>60775</u>	stem	1		(Cons	ss ultant) 33パ	TA.	mac	les [Ξ <u>λ</u> ,	74	<u> 34</u>	San	<u> 105</u>	e/(Α_	95	118		07-073
				Matrix		Prese	rvation				50							□	00270				Method of shipment
_		E		T			I .	ate	e E	_	20/80	250 in	#25 23.	1503E	_		_	85	\ § ∏	S			SAL
Sample I.D.	Lab no.	Container	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8015 Gas Dieset	Oil and Grease 413.1 🔲 413.2 🗆	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Metals VOA VOA	CAM Metals EF	Lead Org./DHS C Lead EPA 7420/7421			SAL COURIER
-21/2-FLI	/		*			×		7-19-9	1 1410		1			73		1							Special detection Limit/reporting
-2½- PLス			Х			ベ		53 	1415		X		I	73									
-1-PL3	•		×			х			0940		Х			73		1							
-1-P14	<i>-</i>		×			Χ			1005		X		10	73	95	3		ļ <u>.</u>					Special QA/QC
-1-PL5	·		X			Χ			1010		X		10	73	25	4	<u> </u>						
-1-P26	~		X			X			1020		X		/0	73	95	5							
-1-PL7	<u> </u>		*			\prec			1030		X		<i>1</i> c	7	39	56							Remarks
-1-PL8	•		Χ.			×			1100	ļ	X		10	73	95	7		,,					
-1-PL9	_	,	×			X			1110?		K		/0) 7]	39	58				ļ			j
-1-PL10	~		*			X			1116		X		10	7 3	95	9				-			_
-21/2- PDI			x			×			1400		X	<u> </u>	10	73	396	C)				<u> </u>	ı		
24	~		Κ			<			1405	1	×			7	1			<u> </u>					1
-1-P03	,		×			X			0935	-	X		i i	7						1			Lab number
E1-R24	~		X			ζ			1000		K		, — ·			63							Turnaround time
205			٨			~		55	1025		×		10	73	9	64							Priority Aush 1 Business Day
	sample:		exc	200	-					Temp	erature	receive	ed:	ಬ	هو	ب							,
	M San	npler	ra.				Date/ 7/23	171	10:55 A		ved by	Cu	((5		lu)ور	~					- Rush 2 Business Days
				1,0	~		Date 7/23	171	100 Pm	Pacci	ved by)			·	,						Expedited 5 Business Days
		,					Date	1 **	Time		vee by	laboral	1.4	- Cm		-	Dail)/2	— 3		Time			Standard 10 Business Days
			1	Canary o	сору — А	RCO Envir	onmental (Engineerin	g; Pink copy —	Consul	lant	*	·/	1			1			-			

· ·	DIVISION	of Allantic	RichfieldC	ompany		4 ()		Task Or	der No.	Denimat	733	-4	/ * /		<u> </u>	١						 hain of Custody
OFACIII	y 110.	2035	<u> </u>	(Fa	cility)	Hba	Telephor (ARCO)	CA		Project (Consul Telepho (Consul	manag tant)	e1 \	00	C	off	ma	h	11000				 Laboratory name
O engine	er C	huck	Car	mel			(ARCO)	19 NO.		(Consul	пе по. tant)	408	264	-77	23	(Co	no. <	70% t}				Contract number
sultant n	ame A	hnck pplie	I G	eoSv	stem	j		Address (Consulta	nt) 33/3	-/	t/m	cdec	EX	, 7 ² 1	34	Sai	10	se. C	1			
	1 - 7	1		/ Matrix		Prese	rvation	.	ф		8015	5 □		3E				Semi JVOA	0010/7000			Method of shipment
Sample I.D.	Lab по.	Container no.	Soil	Water	Other	lce	Acid	Sampling date	Nampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/	TPH Modified 80 Gas Diesel	Oil and Grease 413.1 413.2	TPH EPA 418.1/SM50	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Metals VOA	CAM Metals EPA 6 TTLC STLC	Lead Org./DHS ☐ Lead EPA 7420/7421 ☐		
-PDE	/		×			×		7-19-91	1040		X			10	730	76:	10					Special detection Limit/reporting
-P07	_		X			X		7-199			\times					96	1					
- PI28			$\underline{\hspace{0.1cm}}^{\hspace{0.1cm}0.1cm$			X		7-19-91	1110		X			10	23	90	67					
		<u> </u>										<u>.</u>										Special QA/QC
																						Remarks Lab number
						ļ				<u> </u>					-					ļ	ļ	Turnaround time
	<u> </u>		a																			Priority Rush 1 Business Day
i (a	ample:	npler A	tou				Date / Z	3/9/	Time 10:55A	Recei	VE TO	le de la composition della com	ed:	Se		lu	tu					Rush 2 Business Days Expedited 5 Business Days
		A CA	<u> </u>	X	llu	Du	Date	ا ۱۱ إد.	COP		ved by	laborat	99	Je.	- eAr	Ī	Date /	/ 23		Time	00	 Standard 10 Business Days



AUG - 1991

APPLIED GEOSYSTEMS SAN JOSE BRANCH

Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Joel Coffman

Project: ARCO 2035, Albany

Enclosed are the results from 18 soil samples received at Sequoia Analytical on July 23,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1073950	Soil, S-2½-PL1	7/19/91	EPA 5030/8015/8020
1073951	Soil, S-21/2-PL2	7/19/91	EPA 5030/8015/8020
1073952	Soil, S-1-PL3	7/19/91	EPA 5030/8015/8020
1073953	Soil, S-1-PL4	7/19/91	EPA 5030/8015/8020
1073954	Soil, S-1-PL5	7/19/91	EPA 5030/8015/8020
1073955	Soil, S-1-PL6	7/19/91	EPA 5030/8015/8020
1073956	Soil, S-1-PL7	7/19/91	EPA 5030/8015/8020
1073957	Soil, S-1-PL8	7/19/91	EPA 5030/8015/8020
1073958	Soil, S-1-PL9	7/19/91	EPA 5030/8015/8020
1073959	Soil, S-1-PL10	7/19/91	EPA 5030/8015/8020
1073960	Soil, S-2½-PD1	7/19/91	EPA 5030/8015/8020
1073961	Soil, S-2½-PD2	7/19/91	EPA 5030/8015/8020
1073962	Soil, S-1-PD3	7/19/91	EPA 5030/8015/8020
1073963	Soil, S-1-PD4	7/19/91	EPA 5030/8015/8020
1073964	Soil, S-1-PD5	7/19/91	EPA 5030/8015/8020
1073965	Soil, S-1-PD6	7/19/91	EPA 5030/8015/8020
1073966	Soil, S-1-PD7	7/19/91	EPA 5030/8015/8020



SAMPLE #

SAMPLE DESCRIPTION

DATE OF COLLECTION

TEST METHOD

1073967

Soil, S-1-PD8

7/19/91

EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

Client Project ID:

ARCO 2035, Albany

Matrix Descript: Soil

Analysis Method: First Sample #:

EPA 5030/8015/8020

107-3950

Sampled:

Jul 19, 1991 Jul 23, 1991

Received: Analyzed: Reported:

7/31 - 8/1/91 Aug 2, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)	
107-3950	S-2½-PL1	N.D.	N.D.	N.D.	N.D.	N.D.	
107-3951	S-2½-PL2	N.D.	N.D.	N.D.	N.D.	N.D.	
107-3952	S-1-PL3	1.7	0.0050	0.020	0.016	0.12	
107-3953	S-1-PL4	4,200	36	320	100	640	
107-3954	S-1-PL5	N.D.	N.D.	N.D.	N.D.	N.D.	
107-3955	S-1-PL6	N.D.	N.D.	N.D.	N.D.	N.D.	
107-3956	S-1-PL7	11	0.10	0.37	0.16	1.2	
107-3957	S-1-PL8	1,900	3.6	28	29	200	
107-3958	S-1-PL9	110	0.20	0.78	0.36	3.1	
107-3959	S-1-PL10	84	0.090	0.43	0.72	2.8	
Detection Limits:		1.0	0.0050	0.0050	0.0050	0.0050	

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1073950.APG <1>



3315 Almaden Expressway, Ste 34 Matrix Descript:

San Jose, CA 95118

Attention: Joel Coffman

Client Project ID:

First Sample #:

Analysis Method:

ARCO 2035, Albany Soil

EPA 5030/8015/8020

107-3960

Sampled:

Jul 19, 1991 Jul 23, 1991

Received: Analyzed:

7/31 - 8/2/91

Reported: Aug 2, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-3960	S-2½-PD1	N.D.	N.D.	N.D.	N.D.	N.D.
107-3961	S-2½-PD2	N.D.	N.D.	N.D.	N.D.	N.D.
107-3962	S-1-PD3	N.D.	N.D.	N.D.	N.D.	N.D.
107-3964	S-1-PD5	N.D.	N.D.	N.D.	N.D.	N.D.
107-3965	S-1-PD6	87	0.13	0.28	0.48	3.8
107-3966	S-1-PD7	1,000	0.35	2.1	1.1	47
107-3967	S-1-PD8	N.D.	N.D.	N.D.	N.D.	N.D.

Detection Limits:	1.0	0.0050	0.0050	0.0050	0.0050

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1073950.APG <2>



3315 Almaden Expressway, Ste 34 Matrix Descript:

San Jose, CA 95118 Attention: Joel Coffman Client Project ID:

First Sample #:

ARCO 2035, Albany Soil

Analysis Method:

EPA 5030/8015/8020

107-3963

Sampled: Received:

Reported:

Jul 19, 1991 Jul 23, 1991

Heceived: Jul 23, 1991 Analyzed: 7/31 - 8/2/91

Áug 2, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-3963	S-1-PD4	330	N.D.	N.D.	N.D.	12

Detection Limits: 100 0.50 0.50 0.50 0.50

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard.

Analytes reported as N.D. were not present above the stated limit of detection. Because matrix effects and/or other factors required additional sample dilution, detection limits for this sample have been raised.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1073950.APG <3>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1073950-52, 54

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
<u> </u>	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	mg/kg	mg/kg	mg/kg	mg/kg
Date Analyzed:	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991
QC Sample #:	GBLK073191	GBLK073191	GBLK073191	GBLK073191
	MS/MSD	M\$/MSD	MS/MSD	MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	200	200	200	600
Added.	200	200	200	000
Conc. Matrix				
Spike:	210	210	200	620
Spike.	210	210	200	020
Matais Cailea				
Matrix Spike	440	440	400	400
% Recovery:	110	110	100	100
Como Matrix				
Conc. Matrix	200	200	100	580
Spike Dup.:	200	∠00	190	280
Matrix Spike				
Duplicate				
% Recovery:	100	100	95	97
•				
Relative				
	4.9	4.9	5.1	6.7
% Difference:	4.9	7.5	O. I	Q- 1

SEQUOIA ANALYTICAL

% Recovery:

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Land / / / Dal /

Conc. of M.S. - Conc. of M.S.D.

x 100

Relative % Difference:

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073950.APG <4>

Elizabeth W. Hackf Project Manager



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Joel Coffman

offman QC Sample Group: 107-3953

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method: Analyst: Reporting Units:	EPA 8020 C. Donohue μg/kg	EPA 8020 C. Donohue μg/kg	EPA 8020 C. Donohue µg/kg	EPA 8020 C. Donohue μg/kg
Date Analyzed: QC Sample #:	Aug 1, 1991 GBLK073191 MS/MSD	Aug 1, 1991 GBLK073191 MS/MSD	Aug 1, 1991 GBLK073191 MS/MSD	Aug 1, 1991 GBLK073191 MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc. Added:	200	200	200	600
Conc. Matrix Spike:	180	180	180	550
Matrix Spike % Recovery:	90	90	90	92
Conc. Matrix Spike Dup.:	190	190	190	560
Matrix Spike Duplicate % Recovery:	95	95	95	93
Relative % Difference:	5.4	5.4	5.4	1.8

SEQUOIA ANALYTICAL

Relative % Difference:

% Recovery:

Spike Conc. Added

Conc. of M.S. - Conc. of Sample

x 100

Elizabeth W. Hackl

Conc. of M.S. - Conc. of M.S.D. (Conc. of M.S. + Conc. of M.S.D.) / 2 x 100

Project Manager

1073950.APG <5>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1073955-57

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	G. Meyer	G. Meyer	G. Meyer	G. Meyer
Reporting Units:	μg/kg	μg/kg	μg/kg	μg/kg
Date Analyzed:	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991
QC Sample #:	GBLK073191	GBLK073191	GBLK073191	GBLK073191
	MS/MSD	MS/MSD	MS/MSD	MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	200	200	200	600
Conc. Matrix				
Spike:	180	180	190	550
opc.	100	100	130	330
Madelin On the				
Matrix Spike	00	00	^=	60
% Recovery:	90	90	95	92
Conc. Matrix				
Spike Dup.:	190	190	200	590
Matrix Spike				
Duplicate				
% Recovery:	95	95	100	98
Relative				
% Difference:	5.4	5.4	5.1	7.0
/8 Dillerence.	J. 4	5.4	5.1	7.0

SEQUOIA ANALYTICAL

Elizabeth W. Hack Project Manager % Recovery: Conc. of M.S. - Conc. of Sample x 100
Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D.

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073950 APG <6>

x 100



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 107-3958

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	C. Donohue	C. Donohue	C. Donohue	C. Donohue
Reporting Units:	μg/kg	μ g/kg	μg/kg	μg/kg
Date Analyzed:	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991
QC Sample #:	GBLK073191	GBLK073191	GBLK073191	GBLK073191
·	MS/MSD	MS/MSD	MS/MSD	MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	200	200	200	600
Conc. Matrix				
Spike:	200	200	200	590
- •-				
Matrix Caika				
Matrix Spike % Recovery:	100	100	100	98
% necovery.	100	100	100	90
Conc. Matrix	400	100	400	
Spike Dup.:	190	190	180	550
Matrix Spike				
Duplicate				
% Recovery:	95	95	90	93
Relative				
% Difference:	5.1	5.1	11	7.0
,, 5,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	···	0.1		, .0

SEQUOIA ANALYTICAL

Jakoble Strakt

Elizabeth W. Hackl Project Manager % Recovery: Conc. of M.S. - Conc. of Sample x 100
Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D.

(Conc. of M.S. + Conc. of M.S.D.) / 2

x 100

1073950.APG <7>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34 San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1073959-61, 64

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Aug 1, 1991	Aug 1, 1991	Aug 1, 1991	Aug 1, 1991
QC Sample #:	GBLK073191	GBLK073191	GBLK073191	GBLK073191
	MS/MSD	MS/MSD	MS/MSD	MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	200	200	200	600
Conc. Matrix				
Spike:	190	190	190	570
-	, , ,	100	.00	0.0
Matrix Spike	95	05	O.E.	OF
% Recovery:	95	95	95	95
Conc. Matrix				
Spike Dup.:	190	180	170	540
Matrix Spike				
Duplicate				
% Recovery:	95	90	85	90
Relative	0.0	E 4	4.4	E 4
% Difference:	0.0	5.4	11	5.4

SEQUOIA ANALYTICAL

Elizabeth W. Hacki

Project Manager

% Recovery:

Conc. of M.S. - Conc. of Sample

x 100

Spike Conc. Added

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073950.APG <8>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1073962-63, 65-66

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-		
	Benzene	Toluene	benzene	Xylenes	
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020	
Analyst:	S. Gill	S. Gill	S. Gill	S. Gill	
Reporting Units:	ng	ng	ng	ng	
Date Analyzed:	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991	Jul 31, 1991	
QC Sample #:	GBLK073091	GBLK073091	GBLK073091	GBLK073091	
	MS/MSD	MS/MSD	MS/MSD	MS/MSD	
Sample Conc.:	N.D.	N.D.	N.D.	N.D.	
Spike Conc. Added:	200	200	200	600	
		200	200	555	
Conc. Matrix					
Spike:	180	180	180	550	
opo.	100	.00	.00	000	
Matrix Spike					
% Recovery:	90	90	90	92	
78 necovery.	30	90	90	92	
Conc. Matrix	100	400	100	540	
Spike Dup.:	180	180	180	540	
Matrix Spike					
Duplicate					
% Recovery:	90	90	90	90	
Relative					
% Difference:	0.0	0.0	0.0	1.8	

SEQUOIA ANALYTICAL

Elizabeth W. Hacki Alle

Project Manager

% Recovery: Conc. of M.S. - Conc. of Sample x 100
Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D. x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073950.APG <9>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 107-3967

Reported:

Aug 2, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method: Analyst: Reporting Units: Date Analyzed: QC Sample #:	EPA 8020 L. Gonzalez μg/kg Aug 2, 1991 GBLK073191 MS/MSD			
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc. Added:	200	200	200	600
Conc. Matrix Spike:	180	180	180	540
Matrix Spike % Recovery:	90	90	90	90
Conc. Matrix Spike Dup.:	190	190	190	570
Matrix Spike Duplicate % Recovery:	95	95	95	95
Relative % Difference:	5.4	5.4	5.4	5.4

SEQUOIA ANALYTICAL

Elizabeth W. Hackt/ Project Manager

% Recovery: Conc. of M.S. - Conc. of Sample x 100 Spike Conc. Added x 100

Relative % Difference: Conc. of M.S. - Conc. of M.S.D.

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073950.APG <10>

ARCO I	Produ	icts (Comp	ompany	*			Task Or	der No.	20	35	-91	-/	·								С	hain of Custody	$\overline{/}$
						Albai	ny , C	A e no.	(Project Consul	manag lani)	er J	oe	Col	Ffn	nah							Laboratory name	
ARCO Facilit	er (hho	x Co	irme			(ARCO)	e no.	(Felepho Consul	ne no. tant)	405	1-7	72:		Fax (Co	no. nsultar	408 11)	264	1-20	435		Contract number	\dashv
Consultant na	ame R	ESN	<i>A</i>		•			Address (Consulta	nt) 3315	KI	made	el E	* PV	# 34	1,5	ah	bse	CA	9	51/	2			
				Matrix		Preser	rvation				3015	5 ELL	7	3E				Semi VOA	0010/7000				Method of shipment	
Sample I.D.	Lab no.	Container no.	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/	TPH Modified 80 Gas Diesel	Oil and Grease 413.1 413.2	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Semi	CAM Metals EPA 6	Lead Org./DHS C			Special detection	
5-11/2-PLA	ł		X			X		8-9-91	1300	4	X						36						Limit/reporting	
											•													ļ
·	25.13 (9 0.700)																						Special QA/QC	
				11 1.11																				İ
	•																							
		İ																						
				1	<u> </u>															-			Remarks	
								 .		<u> </u>							<u> </u>			 				
		<u> </u>								<u> </u>	 						 		<u> </u>					
		ļ																						
													<u>. </u>											
						<u> </u>				ļ						ļ <u>.</u>								
				-								-									+		Lab number	
				<u> </u>								<u> </u>				 		-	_		+ +		Turnground time	
			-			1	ļ						-				-	-			1		Turnaround time	
		<u> </u>													<u></u>			<u> </u>					Priority Rush 1 Business Day	
Condition of Relinquished	7	IPIO	joed	 -			Date	,	Time	Recei	ive)plby	receive		cont	- - 9	1 -	100						Rush 2 Business Days	Æ
Relinquished	y by	Ivo	le				8-9-9) Date	<u>'</u>	1430 Time	+ +	yww. ived by		1	0-	٦_	1.	1 30						Expedited 5 Business Days	
Relinquished	d by		· · · · · · · · · · · · · · · · · · ·				Date		Time	Rece	ived by	laborat	ory				Date			Time			Standard 10 Business Days	

ARCOT	rodi Division	icts (Comp	any a	\}			Task Or	der No.	20	35	-91	-/										hain of Custody
ARCO Facility	y no.	203	5	City (Fa	/ cility)	Albai	14,0	Task Or A no: 466		Project (Consul	manag Itant)	jer J	oe	Col	f f n	h G h			- .		v ⊑ i 199k		Laboratory name
ARCO engine	er (huc	1 Ca	irme	1		Telephone (ARCO)	no. 🕶 6		Telepho (Consul	one по. Itant)	4/67	1-7	72:	?	Fax (Co	no. ' nsultan	40 M	184	12	199 k		Contract number
Consultant na	ame R	ESM	A					Address (Consulta	nt) 3315	11	made	-1 E	× PV	#1 34	1,50	ahi	bse	· AR	LIE	SEPA	YETEM	s [.]	67073 .
	•			Matrix		Prese	rvation	_					1					Semi ⊐voA □	0007000				Method of shipment Consultant Delinery
Sample I.D.	Lab no.	Container no	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8015 Gas Diesel	Oil and Grease 413.1 T 413.2	TPH EPA 418.1/SM503E	EPA 501/8010	EPA 624/8240	EPA 625/8270	TCLP Metals [] VOA [CAM Metals EPA	Lead Org./DHS ☐ 67 Lead EPA 7420/7421 ☐ □			Special detection
5-11/2-PLA	<i>F</i>		X			×		8-9-91	1300	46	X						360						Limit/reporting
													:										-
										ļ													Special QA/QC
							,			<u> </u>							\ \ \						
																			-				_
																	1						Remarks
· - <u> </u>							ļ			<u> </u>		-							<u> </u>	1			ſ
	_									-										-			
-																					,		Lab number
														1			-	ļ <u>-</u>		-			
			ļ	1						-	ļ		-		ļ		-		-		-		Turnaround time
		<u> </u>								ļ	<u> </u>	<u> </u>	<u> </u>	Cor	<u> </u>			1	<u> </u>				Priority Rush 1 Business Day
Relinquished by sample: Date Time Received by								- Rush 2 Business Days															
Relinguisher	d by	110	1.6				6-9 - 9 Date	/	1430 Time	Rec	gvul eived by	Jon	-	С.	9	1,	190						Expedited 5 Business Days
Relinquishe	ti by	<u>.</u> <u>-</u>		,			Date		Tirne		wed by						Date &	; - q		Time	130		Standard 10 Business Days
Distribution: APPC-3292		opy — La	aboratory	; Canary	сору —	ARCO Env	ironmental :	Engineering;	Ріпк сору —		0- 1 1		1				• •				•	•	





RESNA 3315 Almaden Expwy., Suite 34 San Jose, CA 95112 Attention: Joel Coffman

Project: ARCO 2035, Albany

Enclosed are the results from 1 soil samples received at Sequoia Analytical on August 9,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1081369	Soil, S-11/2-PL4	8/9/91	EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



RESNA

3315 Almaden Expwy., Suite 34

San Jose, CA 95112 Attention: Joel Coffman Client Project ID: ARCO 2035, Albany

Matrix Descript: Soil

Analysis Method: EPA 5030/8015/8020 First Sample #: 108-1369 Sampled: Received: Aug 9, 1991 Aug 9, 1991

Analyzed:

Aug 9, 1991

Reported: Aug 13, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
108-1369	S-11/2-PL4	4.1	0.21	0.040	0.15	0.12

Detection Limits: 1.0 0.0050 0.0050 0.0050 0.0050

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1081369.RRR <1>



RESNA

Client Project ID: ARCO 2035, Albany

3315 Almaden Expwy., Suite 34

San Jose, CA 95112

Attention: Joel Coffman

QC Sample Group: 108-1369

Reported:

Aug 13, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
ANALITE	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	B. Cox	B. Cox	B. Cox	B. Cox
Reporting Units:	mg/kg	mg/kg	mg/kg	mg/kg
Date Analyzed:	Aug 9, 1991	Aug 9, 1991	Aug 9, 1991	Aug 9, 1991
QC Sample #:	GBLK080991	GBLK080991	GBLK080991	GBLK080991
QO Campic ».	MS/MSD	MS/MSD	MS/MSD	MS/MSD
	Mo, mos			
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
, and the second				
0-4-0				
Spike Conc.	000	000	000	000
Added:	200	200	200	600
Conc. Matrix				
Spike:	180	170	170	510
ор				
Matrix Spike				
% Recovery:	90	85	85	85
O M.13				
Conc. Matrix	400	470	470	coo
Spike Dup.:	180	170	170	520
Matrix Spike				
Duplicate				
% Recovery:	90	85	85	87
, o 11000 tol. y .	00		33	-
Relative				
% Difference:	0.0	0.0	0.0	1.9

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager % Recovery: Conc. of M.S. - Conc. of Sample x 100
Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D. (Conc. of M.S. + Conc. of M.S.D.) / 2

1081369.RRR <2>

x 100

ARCO	Produ	ucts (Comp Richfield	Dany :	*			Task Or	der No.	20	33	-91	- /									Chain of Custody
ARCO Facili	y no.	20:	35	Cit (Fa	y icility) A	Ilbani	, CA			Project (Consul	manag Itant)	ger	oel	Co	Etn	nar					1435	Laboratory name
ARCO engin	eer (hall	t C	arma	e [Telephor	ne no.	i	Telepho (Consul	one no.	408	26	+ 77	127	Fax	no.	408	21	4-7	435	
Consultant n	ame A	pplic	& G	205v	stem		T(NHCO)	Address (Consulta	nt) 3315	A	me	dei	15x	- // - //	34	Sai		50 (A	93"	118	Contract number
	···· •) ()		/ Matrix			rvation											Gĕ	00270			Method of shipment
Sample I.D.	Lab no.	Container no.	Soil	Water	Other	Ice	Acid	Sampling date	Sampting time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8035 Gas Diesel	Oil and Grease 413.1 🔲 413.2 🗀	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Serri Metals □ VOA □ VOA □	CAM Metals EPA 601	Lead Org./DHS C Lead EPA 7420/7421		Seguoia Courier
5 722	ki)	_P_		-																		Special detection Limit/reporting
3-0722 1h 3-07-2	7	ansoqua	×	1		×		7-22-91	1500		×											
- 77																						Special QA/QC
5-0722- 29 5-0722 2h	-	<u>¥</u>	×			×		7-22-91	1515		X											
2h 5 0722- 2c 5 0122 20	}	composite						, 20 (,,,,													Remarks
																						Lab number
																						Turnaround time
																						Priority Rush 1 Business Day
Condition of Relinquished	1 ,	pler	than	un.			Date /2:	3/31	10:53Av	ļ	erature red by	receive	ed: (<u> </u>	e ul)L)c	<u> </u>				Rush 2 Business Days
Relinquished	Бу	مسر لما			10		Date /Z	i -	Time	Recei	Ved by								7			Expedited 5 Business Days
Relinquistie	by	** **					Date	<i>V</i> · · ·	Tíme	Recei	yes ox	laborat	ory_	l.		- 1) (2)	3/4	; ,	Time	00	Standard 10 Business Days
Distribution: 1 APPC-3292 (Vhite co 2-91)	py — Lat	ooratory;	Canary o	ору — А	RCO Envir	onmental	Engineering; F	Pink copy —	Consult	laint	•				·· •	1	1	, ,	· /		

Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Joel Coffman

Project: ARCO 2035, Albany

Enclosed are the results from 2 soil samples received at Sequoia Analytical on July 23,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1073608	Soil, composite, S-0722-1 (a-d)	7/22/91	EPA 5030/8015/8020
1073609	Soil, composite, S-0722-2 (a-d)	7/22/91	EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



3315 Almaden Expressway, Ste 34 Matrix Descript:

San Jose, CA 95118 Attention: Joel Coffman Client Project ID: Matrix Descript: Analysis Method:

First Sample #:

ARCO 2035, Albany Soil, composite

EPA 5030/8015/8020 107-3608 Sampled: Received: Jul 22, 1991 Jul 23, 1991

Analyzed: Reported:

Jul 23, 1991 Jul 24, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-3608	\$-0722-1 (a-d)	78	N.D.	N.D.	N.D.	N.D.
107-3609	S-0722-2 (a-d)	81	0.050	0.10	0.050	0.34

Detection Limits: 10 0.050 0.050 0.050 0.050

Low to Medium Bolling Point Hydrocarbons are quantitated against a gasoline standard.

Analytes reported as N.D. were not present above the stated limit of detection. Because matrix effects and/or other factors required additional sample dilution, detection limits for this sample have been raised.

SEQUOIA ANALYTICAL

-Elizabeth W. Hackl Project Manager

1073608.APG <1>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1073608-09

Reported:

Jul 24, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	L. Laikhtman	L. Laikhtman	L. Laikhtman	L. Laikhtman
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 23, 1991	Jul 23, 1991	Jul 23, 1991	Jul 23, 1991
QC Sample #:	GBLK072391	GBLK072391	GBLK072391	GBLK072391
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
Conc. Matrix				
Spike:	100	99	98	300
Matrix Spike				
% Recovery:	100	99	98	100
Conc. Matrix			_	
Spike Dup.:	100	100	99	300
Matrix Spike				
Duplicate				
% Recovery:	100	100	99	100
Relative				
% Difference:	0.0	1.0	1.0	0.0

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager % Recovery: Co

Conc. of M.S. - Conc. of Sample Spike Conc. Added x 100

Relative % Difference:

Conc. of M.S. - Conc. of M.S.D.

x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073608.APG <2>

RCQ Facili	eer C	huck	Car	mel	y acility) A	Alban	Telephor (ARCO)	A	1	Project (Consul Telepho (Consul	tanti		Joe1	123	off	tma	h			- 2 3	03	Laboratory name SE QUOIA Contract number	
onsultant n	ame RE	SNA	/APA	lica	Geo	Skete			nı) 3 315	- A1	mad	er 1	ج ج ک	£34	1.50	neb	se i	CA	95	1/8		07-07	3
				Matrix	· · -	'	rvation							,			==,1	semi VOA □	0007/086			Method of shipment	
Sample I.D.	Lab по.	Container no.	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8015 Gas Diesel	Oil and Grease	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Metals □ VOA □ VOA □	CAM Metals EPA 6010/7000 TTLC D STLC D	Lead Org./DHS C Lead EPA 7420/7421	:	A.G.	~
0725 G	$\overline{)}$												<u> </u>					F 46.	<u> </u>	77.		Special detection Limit/reporting	
7725- 36 0125 3C	to day	,	×			X		7-25-91	1105		×				107L	110	4						
0725 30																						Special QA/QC	
0725	7-7-															<u>-</u> -1	42	<u>~</u>					
0725 0725 0725 50 50	COMO		×			X		7-25-91	1138		×				> \) [ተ^					Remarks	
0725 oq	/ ገ												•				-						
0725 6525 0725	7. P. G. G. I.))	X			×		7-25-91	1145		X					07	42	 				_	
5c 1725.	3																					Lab number	
				<u> </u>			ļ <u>-</u>															Turnaround time	
ondition of	sample:			good .						Tempe	erature	receive	d:	اا		· ·						Priority Rush 1 Business Day	7
linquistleg				<u>0 '</u>			Date 7/26	k,	Time 1376	Recei												Rush 2 Business Days	
linquished	l by	y V -1					Date	<u>ч</u>	Time	Receiv	red by									·	 	Expedited 5 Business Days	
. Sandalan	i by						Date	Engineering; F	Time	ا ا	go by	laborate	ory			C	ate	2J		Time しろ	76	Standard 10 Business Days	



RECEIVED

JUL 25 1991

APPLIED GEOSYSTEMS SAN JOSE BRANCH

Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Joel Coffman

Project: ARCO 2035, Albany

Enclosed are the results from 2 soil samples received at Sequoia Analytical on July 24,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1073898	Soil, composite, S-0723-3 (a-d)	7/23/91	EPA 5030/8015/8020
1073899	Soil, composite, S-0723-4 (a-d)	7/23/91	California LUFT Manual, 12/87 EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

Client Project ID: Matrix Descript: Analysis Method:

First Sample #:

ARCO 2035, Albany Soil, composite EPA 5030/8015/8020

107-4199 A-D

Sampled: Received:

Jul 25, 1991 Jul 25, 1991

Analyzed: Jul 25, 1991 Reported:

Jul 26, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-4199	S-0725-91/3	31	0.0080	0.0080	0.011	0.049
107-4200	S-0725-91/5	47	N.D.	0.0070	N.D.	0.010
107-4201	S-0725-91/6	49	0.0080	0.018	0.029	0.10
107-4202	S-0725-91/7	65	0.013	0.018	0.032	0.22

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Project Manager



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1074199-202

Reported:

Jul 26, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	D. Dreblow	D. Dreblow	D. Dreblow	D. Dreblow
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 25, 1991	Jul 25, 1991	Jul 25, 1991	Jul 25, 1991
QC Sample #:	GBLK072591	GBLK072591	GBLK072591	GBLK072591
•	MS/MSD	MS/MSD	MS/MSD	MS/MSD
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
Conc. Matrix				
Spike:	100	100	91	300
·				
Matrix Spike				
% Recovery:	100	100	91	100
	- 		- '	
Conc. Matrix				
Spike Dup.:	90	90	89	270
•			-	0
Matrix Spike				
Duplicate 8/ December 1	00	00	00	00
% Recovery:	90	90	89	90
Relative	4.4	4.4	0.0	4.4
% Difference:	11	11	2.2	11

SEQUOIA ANALYTICAL

Elizabeth W. Hacki Project Manager % Recovery:

Conc. of M.S. - Conc. of Sample x 100

Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D.

(Conc. of M.S. + Conc. of M.S.D.) / 2

1074199.APG <2>

x 100

RCO F	rodu Division	of Atlantic	Comp RichfieldC	any (()			Task Or	der No.	21	73	5-7	71-	1								Chain of Custod	y
RCO Facility	по.	103	5_	City (Fa	cility) A	llban	(1) , (CA		Consul	tant)	<u></u>	<u>00e</u> 1	<u>l La</u>	2+1-	Fax	no.	408		1-24		-	
RCO engine	er C	huci	k C	arn	nel		Telephon (ARCO)	e no.		Consul	tant)	700	264	-77	723	(Cor	nsultan	t)	269	1-24	<i>3</i> 3	Contract number	
onsultant na	me RE	SNA	(An	Med	Geos	System	m5	(Consulta	nı) 3315	Alv	nade	on F	5x. 7	#34	<u> </u>	inU	<u>950</u>	, (/-	\ 9	5//2	· -	Method of shipment	
				Matrix		Prese	vation				015	ייטר		щ				Semi J VOA [001070			Montos of Stripmon	ļ
Sample I.D.	Lab no.	Container no.	Soil	Water	Other	lce	Acid	Sampling date	Sampling time	BTEX 602/EPA 8020	BTEX/TPH EPA M602/8020/8015	TPH Modified 8015 Gas Diesel	Oil and Grease 413.1 🔲 413.2 🗀	TPH EPA 418.1/SM503E	EPA 601/8010	EPA 624/8240	EPA 625/8270	TCLP Metals ☐ VOA ☐ VOA ☐	CAM Metals EPA (Lead Org./DHS X Lead EPA 7420/7421		Special detection	
-0723-				<u> </u>		<u> </u>		7-23-91	1410		X											Limit/reporting	
-0123- 39 -0723- 3b	/ +		×		-	×		1073	290	<u> </u>	<u> </u>												
3b -0723 3C	('S'O		-					1070	0 10													_	
3c -0723- 3d	\-\\\\-\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			i													 					Special QA/QC	
3d	/ _	-		<u> </u>						<u> </u>													
-0713-			 	<u> </u>				1073	899		<u> </u>	· · · · · ·			_	i							
49	-/=				-	X	-	7-23-91				ļ		<u> </u>						X			
5-0723- 4b 5-0723 4C 5-0723- 4d	(7)		X	<u> </u>	 	-	-	1-23-91	1.500			 				 	 			<u> </u>		Remarks	
40	1 8				-	 	-						-		 		1		 				
4d	_		<u> </u>	<u> </u>			<u> </u>			 	 	-			 			<u> </u>	 				
					-	ļ	 			<u> </u>	 	-	 	-			1		-				
		-	-	 		<u> </u>	-			-	-	 	 		-				 	† †			
						ļ.—				}_	 -	 	-	1	 -		+		lacktriangledown				
		-		-		 	-		-		+	-			-		-	†		+		Lab number	
	ļ	<u> </u>	-	_	 	 	 			-		-		-			+	ļ. 	-			Turnaround time	
					ļ	ļ.,	 					-				-	+-	-	+	-		Priority Rush	ι.
		<u>L</u> _	1		<u></u>		1		<u> </u>	-		e recei	mod.			.1		_1	<u> </u>		!_	1 Business Day	<u> </u>
Condition o	1 .		#				Date		Time	Rec	peratur eived b		√6 <	سرجاد	ek	Zs.							
Relinquishe	Selv	4	Ma	wy	1.		7-24 Date		2:35PM	Rec	eived b	P		/						<u></u> -		Expedited 5 Business Days	
Pelinquish	_>	pe'	معلر	Led			7-24- Date	9)	3;50P/1 Time) Rec	eived t	y lapor	atory	teč			Date	51/		Time	G Z .	Standard 10 Business Days	
•							1	l Engineering	0.4		<u>/</u>	//-	/W	V	<u> </u>		1 //	J. J		1.2	· 0		



RECEIVED

JUL 2 9 1991

Applied GeoSystems 3315 Almaden Expressway, Ste 34 San Jose, CA 95118 Attention: Joel Coffman

APPLIED GEOSYSTEMS SAN JOSE BRANCH

Project: ARCO 2035, Albany

Enclosed are the results from 4 soil samples received at Sequoia Analytical on July 25,1991. The requested analyses are listed below:

SAMPLE #	SAMPLE DESCRIPTION	DATE OF COLLECTION	TEST METHOD
1074199	Soil, composite, S-0725-91/3	7/25/91	EPA 5030/8015/8020
1074200	Soil, composite, S-0725-91/5	7/25/91	EPA 5030/8015/8020
1074201	Soil, composite, S-0725-91/6	7/25/91	EPA 5030/8015/8020
1074202	Soil, composite, S-0725-91/7	7/25/91	EPA 5030/8015/8020

Please contact me if you have any questions. In the meantime, thank you for the opportunity to work with you on this project.

Very truly yours,

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager



3315 Almaden Expressway, Ste 34 Sample Descript:

San Jose, CA 95118 Attention: Joel Coffman Client Project ID:

ARCO 2035, Albany Soil, composite

California LUFT Manual, 12/87

Analysis Method: California First Sample #: 107-3899 Sampled:

Jul 23, 1991

Received: Jul

Jul 24, 1991

Analyzed: Reported: Jul 25, 1991 Jul 26, 1991

ORGANIC LEAD

Sample Number	Sample Description	Sample Results mg/kg (ppm)
107-3899	S-0723-4 (a-d)	N.D.

Detection Limits: 0.050

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl Project Manager

1073899.APG <1>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 107-3899

Reported:

Jul 26, 1991

QUALITY CONTROL DATA REPORT

ANALYTE Organic Lead

Method:

LUFT

Analyst:

K. Anderson

Reporting Units:

mg/kg

Date Analyzed: QC Sample #: Jul 25, 1991 107-3899

Sample Conc.:

N.D.

Spike Conc.

Added:

0.50

Conc. Matrix

Spike:

0.32

Matrix Spike

% Recovery:

64

Conc. Matrix

Spike Dup.:

0.33

Matrix Spike Duplicate

% Recovery:

66

Relative

% Difference:

3.1

SEQUOIA ANALYTICAL

Elizabeth W. Hack Project Manager

% Recovery: Conc. of M.S. - Conc. of Sample x 100

Spike Conc. Added

Relative % Difference: Conc. of M.S. - Conc. of M.S.D.

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073899.APG <2>

x 100



Applied GeoSystems 3315 Almaden Expressway, Ste 34

San Jose, CA 95118 Attention: Joel Coffman

Client Project ID: Matrix Descript:

Analysis Method: First Sample #:

ARCO 2035, Albany Soil, composite EPA 5030/8015/8020 107-3898 A-D

Sampled: Received: Analyzed:

Reported:

Jul 23, 1991 Jul 24, 1991 Jul 24, 1991 Jul 26, 1991

TOTAL PETROLEUM FUEL HYDROCARBONS with BTEX DISTINCTION (EPA 8015/8020)

Sample Number	Sample Description	Low/Medium B.P. Hydrocarbons mg/kg (ppm)	Benzene mg/kg (ppm)	Toluene mg/kg (ppm)	Ethyl Benzene mg/kg (ppm)	Xylenes mg/kg (ppm)
107-3898	S-0723-3 (a-d)	130	0.032	0.035	0.045	0.17
107-3899	S-0723-4 (a-d)	31	N.D.	N.D.	N.D.	0.054

Detection Limits: 1.0 0.0050 0.0050 0.0050 0.0050

Low to Medium Boiling Point Hydrocarbons are quantitated against a gasoline standard. Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL

Elizabeth W. Hackl **Project Manager**

1073899.APG <3>



Client Project ID: ARCO 2035, Albany

3315 Almaden Expressway, Ste 34

San Jose, CA 95118

Attention: Joel Coffman

QC Sample Group: 1073898-99

Reported:

Jul 26, 1991

QUALITY CONTROL DATA REPORT

ANALYTE			Ethyl-	
	Benzene	Toluene	benzene	Xylenes
Method:	EPA 8020	EPA 8020	EPA 8020	EPA 8020
Analyst:	L. Gonzales	L. Gonzales	L. Gonzales	L. Gonzales
Reporting Units:	ng	ng	ng	ng
Date Analyzed:	Jul 24, 1991	Jul 24, 1991	Jul 24, 1991	Jul 24, 1991
QC Sample #:	GBLK072491	GBLK072491	GBLK072491	GBLK072491
Sample Conc.:	N.D.	N.D.	N.D.	N.D.
Spike Conc.				
Added:	100	100	100	300
Conc. Matrix				
Spike:	93	93	90	270
Matrix Spike				
% Recovery:	93	93	90	90
Conc. Matrix	0.4		. .	0.45
Spike Dup.:	84	84	81	240
Matrix Spike				
Duplicate				
% Recovery:	84	84	81	80
Relative				
% Difference:	10	10	11	12

SEQUOIA ANALYTICAL

Project Manager

% Recovery: Conc. of M.S. - Conc. of Sample x 100 Spike Conc. Added Relative % Difference: Conc. of M.S. - Conc. of M.S.D. x 100

(Conc. of M.S. + Conc. of M.S.D.) / 2

1073899.APG <4>

APPENDIX D MANIFESTS FOR TANKS INVOICE FOR SOIL DISPOSAL

3 Harden Hart author votes / VECC	0038636 9	218122				by Federal law.
50 307 2811 311 1001	SAN PAGLO			e Generator's ID	90:	73885
4. Generator a Priorie (BANY CA			CITI		
5. Transporter 1 Company Name C C I CKSON PUCKINA	E POPICIAL 6			e Transporter's II aporter's Phone,	_ % \.	3/6/
7. Transporter 2 Company Name	8. US EPA ID Numbe			Transporter's f	<u>' </u>	<u> </u>
O Decimal Association			A	sporter's Phone		
9. Designated Facility Name and Site Address Erickson, Inc. 255 Parr 81vd.	10. US EPA ID Number		C		146	6392
Richmond, Ca. 94801	C A D O O 9 4 6	6 3 9 2	n. Faci	ity's Phone (41.	5) 2:	5-1393
11. US DOT Description (Including Proper Shipping Name, Hazai	rd Class, and ID Number)	12. Conta	iners Type	13. Total Quantity	14. Unit	Weste No
a. Waste Empty Storage Tank	• <u>;</u> .	140.	CM	- · · ·	Wt/Vo	State 312
NON-RCRA Hazardous Waste Solid.		a		80.00	P	EPA/Othes NON
b.		1 445	94	RD 0 D	-	State
				* .		EPA/Other
C.					ļ	
, c.						State
			ı	1111		EPA/Other
d.						State
		1 1	1			- A.
J. Additional Descriptions for Materials Listed Above QtyEmpty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gai. Capacity.	# <u>(550,655)</u> n inerted with 15	DB		diing Codes for W	d.	EPA/Other
J. Additional Geocrations for Materials Listed Above QtyEmpty Storage Tank (s)Tank (s) have been Dry Ice per 1000 Gai. Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitions.	on. Always wear	hardhat	C.	n working	d.	Isted Above
J. Additional Geometricons for Materials Listed Above Qty. Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gai. Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name		hardhat	C.	n working	d.	Isted Above
J. Additional Descriptions for Materials Listed Above Qty. Empty Storage Tank (a) Tank (b) have been Dry Ice per 1000 Gal. Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name 18. GENEPATOR'S CEPTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are innational government regulations. If I am a large quantity generator. I certify that I have a proof to be economically practicable and that I have selected the present and future threat to human health and the environment.	e contents of this consignment at all respects in proper condition tram in place to reduce the volum practicable method of treatment ent: OR, if I am a small quantity	hardhat: & Phone re fully and according transport became and toxicity, storage, or dependently, i ha	B whee	lescribed above it according to	d. 275	end and resident a
J. Additional Generations for Materials Listed Above Qty. Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gai. Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition of the second of the	e contents of this consignment at all respects in proper condition tram in place to reduce the volum practicable method of treatment ent: OR, if I am a small quantity	hardhat: & Phone re fully and according transport became and toxicity, storage, or dependently, i ha	B whee	lescribed above it according to	d. 275	end and resident a
J. Additional Generations for Materials Listed Above Qty. Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gai. Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition of the second of the	on. Always wear contents of this consignment at all respects in proper condition ram in place to reduce the volum practicable method of treatment ent; OR, if I am a small quantity what is available to me and that I	hardhat: & Phone re fully and according transport became and toxicity, storage, or dependently, i ha	B whee	lescribed above it according to	d. 275	r shipping name international and thave determined the minimizes the mize my waste
J. Additional Descriptions for Materials Listed Above Oty. Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gai. Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name 16. GEMEPATOR'S CEPTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are innational government regulations. If I am a large quantity generator, I certify that I have a program to be economically practicable and that I have selected the present and future threat to human health and the environme generation and select the best waste management method to Printed/Types.	e contents of this consignment at all respects in proper condition tram in place to reduce the volum practicable method of treatment ent: OR, if I am a small quantity that is available to me and that I signature.	hardhat: & Phone The fully and according to transport be the and toxicity, and the control of t	B whee	lescribed above it according to	d. 275	r shipping name international and thave determined minimizes the mize my waste
J. Additional Descriptions for Materials Listed Above Oty. Empty Storage Tank (s) Tank (s) have been to be a capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition to be an are classified, packed, marked, and labeled, and are innational government regulations. If I am a large quantity generator. I certify that I have a progress of the economically practicable and that I have selected the present and future threat to human health and the environment generation and select the best waste management method to be recommended. Printed/Type For Tank Comment of Receipt of Materials Printed/Typed Name The Comment of Receipt of Materials Commended Typed Name The Comment of Receipt of Materials Commended Typed Name	on. Always wear contents of this consignment at all respects in proper condition ram in place to reduce the volum practicable method of treatment ent; OR, if I am a small quantity what is available to me and that I	hardhat: & Phone The fully and according to transport be the and toxicity, and the control of t	surrately of highway of waate isposal over made	en working	d. 275	r shipping name international and thave determined minimizes the mize my waste
J. Additional Descriptions for Materials Listed Above Qty. Empty Storage Tank (s) Tank (s) have been provided to be a capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitive U.S.T.'s 24 Hr. Contact Name 1.5. GEMEPATOR'S CEPTIFICATION: I hereby declare that the and are classified, packed, merked, and labeled, and are invational government regulations. If I am a large quantity generator. I certify that I have a proof to be economically practicable and that I have selected the present and future threat to human health and the environment generation and select the best waste management method to Printed/Type for Instance of Printed/Type for Instance of Printed/Typed Name 15 August 18. Transporter 2 Acknowledgement of Receipt of Materials	e contents of this consignment at all respects in proper condition ram in place to reduce the volum practicable method of treatment ent: OR, if I am a small quantity that is available to me and that I signature.	hardhat: & Phone The fully and according transport by the and toxicity, storage, or digenerator, I had can afford.	surrately of highway of waate isposal over made	en working	d. 275	r shipping name international and have determined minimizes the mize my waste. Month Day 0.7.03
J. Additional Descriptions for Materials Listed Above Oty. Empty Storage Tank (s) Tank (s) have been to be a capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition to be an are classified, packed, marked, and labeled, and are innational government regulations. If I am a large quantity generator. I certify that I have a progress of the economically practicable and that I have selected the present and future threat to human health and the environment generation and select the best waste management method to be recommended. Printed/Type For Tank Comment of Receipt of Materials Printed/Typed Name The Comment of Receipt of Materials Commended Typed Name The Comment of Receipt of Materials Commended Typed Name	e contents of this consignment at all respects in proper condition tram in place to reduce the volum practicable method of treatment ent: OR, if I am a small quantity that is available to me and that I signature.	hardhat: & Phone The fully and according transport by the and toxicity, storage, or digenerator, I had can afford.	surrately of highway of waate isposal over made	en working	d. 275	r shipping name international and have determined minimizes the mize my waste. Month Day 0.7.03
J. Additional Descriptions for Materials Listed Above Qty. Empty Storage Tank (s) Tank (s) have been provided to be a capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitive U.S.T.'s 24 Hr. Contact Name 1.5. GEMEPATOR'S CEPTIFICATION: I hereby declare that the and are classified, packed, merked, and labeled, and are invational government regulations. If I am a large quantity generator. I certify that I have a proof to be economically practicable and that I have selected the present and future threat to human health and the environment generation and select the best waste management method to Printed/Type for Instance of Printed/Type for Instance of Printed/Typed Name 15 August 18. Transporter 2 Acknowledgement of Receipt of Materials	e contents of this consignment at all respects in proper condition ram in place to reduce the volum practicable method of treatment ent: OR, if I am a small quantity that is available to me and that I signature.	hardhat: & Phone The fully and according transport by the and toxicity, storage, or digenerator, I had can afford.	surrately of highway of waate isposal over made	en working	d. 275	r shipping name international and have determined the minimizes the international and and a second of the second o

3. Generator's Name and Mailing Address A	0038676 E	1900	A. Sta	of is no te Manifest Doc		by Federal la
ARCO Fredrets Company	2035 San Pablo Ly, CA			ite Generator's i	90	57391
6. Transporter 1 Company Name	6. US EPA ID Number		C. Str	ite Transporter's	10 - 11	4-1
Exickson Trucking Inc. 1	CHUDO9461	6392		saporter's Phon	415	235.1
7. Transporter 2 Company Name	8. US EPA*ID Number			ite Transporter's naporter's Phone		
9. Designated Facility Name and Site Address	10. US EPA ID Number		- ·	ta Facility's ID		
Erickson, Inc. 255 Parr Blvd.				A DOO	112.5	
Richmond, Ca. 94801	<u> </u>	3 9 2 1 12. Conta	iners	13. Total	14.	5-1393
11. US DOT Description (Including Proper Shipping Name, Hazar	rd Class, and ID Number)	No.	Тура	Quantity	Unit Wt/Vo	Was
Waste Empty Storage Tank	·					State 51:
		ma	ct e4	ଧ <u>୍</u> ୟ ବର	7	EPA/Other
NON-RCRA Hazardous Waste Solid.			o ka	<u> </u>	, Z	State
						EPA/Other
c.					+	State
						EPA/Other
d.			_1_			
°.						State
		t l				EPA/Other
J. Additional Descriptions for Materials Listed Above	W-518/54/9		K. Ha	ndling Codes for	Wastes L	isted Above
Qty. 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity:	#65 18.65/9 inerted with 15	lbs:	K. Ha	ndking Codes for		isted Above
Qty: 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitio U.S.T.'s 24 Hr. Contact Name GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are in a national government regulations. If I am a large quantity generator, I certify that I have a progress to be economically practicable and that I have selected the	contents of this consignment are all respects in proper condition for	fully and according transport by	whe	deacribed above	d. d. e by properapplicable	er shipping na international
Qty: 2 Empty Storage Tank (s) Tank (s) have been Tank (s) have been Dry Ice per 1000 Gals Capacitys 15. Special Handling Instructions and Additional Information Keep away from sources of ignitio U.S.T.'s 24 Hr. Contact Name 16. GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are in national government regulations.	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ant; OR, if I am a small quantity gr	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	er shipping na international I I have determined which minimize minize my was
Qty. 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitio U.S.T.'s 24 Hr. Contact Name K 16. GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are in national government regulations. If I am a large quantity generator, I certify that I have a progressent and future threat to human health and the environme generation and select the best waste management method to	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ant; OR, if I am a small quantity great is available to me and that I content to the practical content to the	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	und or shipping na international at have deterwhich minimize my was
Qty: 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitio U.S.T.'s 24 Hr. Contact Name GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are in national government regulations. If I am a large quantity generator, I certify that I have a progr to be economically practicable and that I have selected the present and future threat to human health and the environme generation and select the best waste management method to Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ant; OR, if I am a small quantity ghat is available to me and that I consider the second	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	und or shipping na international at have deterwhich minimize my was
Qty: 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitio U.S.T.'s 24 Hr. Contact Name K 18. GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are in national government regulations. If I am a large quantity generator, I certify that I have a progressent and future threat to human health and the environme generation and select the best waste management method to Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Priptery Typed Name R. T. T. Transporter 1 Acknowledgement of Receipt of Materials	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ant; OR, if I am a small quantity great is available to me and that I content to the practical content to the	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	er shipping na international la have determined him minimize my was month.
Qty. 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T. I hereby declare that the and are classified, packed, marked, and labeled, and are in Instituted I have selected the present and future threat to human health and the environme generation and select the best waste management method to Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials 18. Transporter 2 Acknowledgement of Receipt of Materials	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ent; OR, if I am a small quantity gents is available to me and that I consider the state of the state	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	er shipping na international at have deterwhich minimize my was month. D. Mo
Qty: 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignitio U.S.T.'s 24 Hr. Contact Name K 18. GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are in national government regulations. If I am a large quantity generator, I certify that I have a progressent and future threat to human health and the environme generation and select the best waste management method to Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Priptery Typed Name R. T. T. Transporter 1 Acknowledgement of Receipt of Materials	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ant; OR, if I am a small quantity ghat is available to me and that I consider the second	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	er shipping na international state have deter which minimizatimize my was month D 10 17 D Month D 10 17 D
Qty: 2 Empty Storage Tank (s) Tank (s) have been Dry Ice per 1000 Gals Capacity. 15. Special Handling Instructions and Additional Information Keep away from sources of ignition U.S.T.'s 24 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25 Hr. Contact Name Keep away from sources of ignition U.S.T.'s 25	contents of this consignment are all respects in proper condition for ram in place to reduce the volume practicable method of treatment, ent; OR, if I am a small quantity gents is available to me and that I consider the state of the state	fully and according transport by and toxicity storage, or dienerator, I have	whe	deacribed above ay according to the generated to the currently available a good faith ei	d. d. a by proper applicable to me vertex to min	er shipping na international at have deterwhich minimize my was month. D. Mo

RECD AUG 1 6 1991

PAGE: 01

DILLARD TRUCKING, INC. P.O. BOX 218

3YRON

CA 94514

(415) 634-6850

DATE: 08/07/91

INVOICE NO: 01169

ACCOUNT NO: 00001

ARCO PRODUCTS

P.O. 80X 5811

SAN MATEO

CA 94402

JOB#: 0001/74 07-045/2035-91-18MM

FROM: ARCO #2035/ALBANY

TO: REDWOOD LANDFILL/NOV

COMOTY: 85-BULK SOIL

y t 	FREIGHT	BILL	WEIGHT TAG	TRK	MANIFEST #		DESCRIPTION	INU	TS	RATE	AMOUNT
	15572		8091					5.000	Hrs	64.1600	320.80 🗸
	15572B		ADL CHG			8RIDGE	TOLL				7.25
	16380		8065					7.500	Hrs	64.1600	481.20
	16380B		ADL CHG			BRIDGE	TOLL				15.50
	16640		8058					6.250	Hrs	64.1600	401.00
	166408		ADL CHG			8RIDGE	TOLL				14.50
		-00	8086					5.250	Hrs	64.1600	336.84 V
	17022B		ADL CHG			BRIDGE	TOLL				7.25 🗸
01/91		-00	8102	35				7.500	Hrs	64.1600	481.20
	184318		ADL CHG			BRIDGE	TOLL				7.25 🗸
	18646		8101	82				8.000	Hrs	64.1600	513.28
01/91		00	8085					4.750	Hrs	64.1600	304.76
	18714B -		ADL CHG			BRIDGE	TOLL				7.25
01/91		00	8082					6.000	Hrs	64.1600	384.96
01/91		00	8113					8,500	Hrs	64.1600	545.36 V
01/91			8062								
	20455B -		ADL CHG			8RIDGE	TOLL				14.50
1/91			8111					8.500	Hrs	64.1600	545.36
	205298 -		ADL CHG			BRIDGE	TOLL				16.50
01/91 7 Nazon e			8097	21				6.750	Hrs	64.1600	433.08 🗸
	20601B -		ADL CHG			BRIDGE	TOLL				7.25 🗸
2/91 1			9207/8240/60					7.750	Hrs	64.1600	497.24 🗸
UZ/91) B	163818 -	UŲ	ADL CHG			BRIDGE	TOLL				16.50 V
	SUB	TOTL	TRANSPORT					81.750	Hre		E DAE AO
•	SUB	TOTL						15.000			5,245.08 5,358.83

ACCT COST CENTER FAC. # TYPE CAPITALLES FOR SOLL DISPOSAL DURING TANK JOB AT #2035 ##

Verified to Contract Terms

Initials