

FAX

1/30/97

Number of pages including cover sheet: 3

To: Barney Chan

ACHCSA

Phone: _____

Fax phone: 337-9335

CC: _____

From: Jeriann Alexander

Phone: (510) 299-7960

Fax phone: (510) 299-7970

REMARKS: Urgent For your review Reply ASAP Please comment

For your use Original in mail As requested

R. MORRISON & ASSOCIATES, INC.

Environmental Consulting

January 14, 1997

Ms. Jerri Ann Alexander
Subsurface Consultants, Inc.
3736 Mt. Diablo Blvd., Suite 200
Lafayette, California 94549

Dear Ms. Alexander:

Enclosed is map showing the locations of our borings and the data from the EPA test methods for our samples.

If you have any questions please call me at (619) 480-1178.

Sincerely,



Justin Schimnowski
Geologist


Enclosure

JAN172\LETTERS\SCI_JA.01

201 East Grand Avenue, Suite 2B • Escondido, California 92025
(619) 480-1178 • (800) 725-7799 • Fax (619) 480-1179
e-mail: RMandAssoc@aol.com

DRAFT

- RMA Soil Boring Locations
- ▭ Study Area
- - - Approximate Lease Boundaries
- ▭ Current Building Location
- - - Former Building Location
- Sewer System
 - ▭ Sanitary Sewer
 - ▭ Storm Drain
- ▭ Railroad
- ▭ Fuel Line
- ▭ Fence
- Tank Locations
 - ▭ Existing Tank
 - - - Former Tank
- ▭ Drain Grate
- ▭ Bulkhead



**RMA Boring Location Map
January 14, 1997**

Source: Subsurface Consultants, Inc., August 8, 1996

P. 3/3

JAN 30 '97 02:36PM 51029979705CI