

Contact Log (Alameda Lock & Glass)

- 8/12/96 Spoke to Ron Brown about getting copies of Forms A & B
- 9/6/96 Left message for Ron Brown requesting copies of Forms A & B
- 9/16/96 Spoke to Ron Brown & requested copies of Forms A & B. He said he would have someone submit them soon.
- 10/3/96 Spoke to Sam Argila, RWQB, who agreed that further characterization is warranted at the site for lead contaminated g.w.
- 10/8/96 Left message for Harry Sato. Told him that Mark Wozniak called yesterday & wanted to know why they are still being asked to permit the OSTs that they already closed in place. Have already told Kevin Turley 3 times that OSTs were already closed in place.
- 10/8/96 Spoke to Mark Wozniak. Told him to disregard permit requirements. Discussed lead issues & submitted of Form B.
- 11/2/96 Left message for Jim Owens re the status of the work plan submittal
- 11/2/96 Spoke to Jim Owens. He stated he could not find copy of Oct 3 '96 letter. I told him I would fax a copy and set down a new deadline for Feb 27th/97
- 1/7/97 Ron Brown called & asked that I fax him a copy of Oct 3 '96 letter.

Contact Log

- 7/18/96 Spoke to Mark Wouat → I called him to find out status of tank closure in place. When I spoke to Ron Brown on May 23, '96, I specifically requested that he submit a site figure w/ the sample locations, sample results, & to resubmit the sample w/ lead levels for analysis after filtering. Have not heard back from him since then.
- 7/18/96 Left messages for Ron Brown and Jim Owens re status of tank closure.
- 7/18/96 Ron Brown called & left message so I returned his call & he said he would have to call me back today.
- 7/18/96 Jim Owens called back & said he would comply w/ whatever work is necessary.
- 7/23/96 Ron Brown left me a message
- 7/23/96 Left Mr. Brown a message (452-5500) regarding that he fax me the sample analysis results for soil & g.w. samples, site figure showing sample locations, filtered lead results, & schedule for tank closure in place.
- 7/25/96 Spoke to RMC contractor re slurry mixture.
- 7/25/96 Met w/ Ron Brown & Mark Wouat. They will go out to site tomorrow to collect another "grab" g.w. sample, filter it w/ a 0.45 micron filter, & have it analyzed for lead. The results should be in by Monday. They will schedule a time next week to remove the tanks, fill w/ slurry, & close USTs in place. The USTs ports should be fitted w/ concrete/armor.
- 7/29/96 Ron Brown called to say that they will fill USTs w/ concrete on Thurs. 8/1/96. They will fax sample results.

Contact Log

- 4/8/96 Mark Womack, Architectural Edge, 510-522-7038
Discussed Sect 2672(c)(d) Article 7 Title 23CCR
regulations for tank closure in place and explained
that they need to submit an addendum to ~~the work~~^{the} plan addressing the work.
- 4/8/96 Ron Brown, MicroSearch Environmental, Inc., 510-452-5500
Discussed the necessary addendum to closure plan
addressing requirements as outlined in Article 7.
Boeing SB001 was drilled down to 4' bgs until they hit
what they believe to be UST. Depths of USTs are
not known. Mr. Brown stated that shallow
groundwater exists at the site.
- 4/9/96 Ron Brown → called him to request the following:
- Contractor's State license (w/ exp. date)
- Hazardous Substance Removal Certy.
- Proof of H+S training
- 4/22/96 Ron Brown → I informed them we will collect additional
soil samples beneath the USTs to help them decide
whether they want to risk removing the USTs or
leave them in place. I reminded them that if they
wish to close in place, they will be required to install
a well. Soil samples should be analyzed for
lead & edc & edb, in addition to gas & VOCs.
Will bring info to site (certifications).
- 7/3/96 Spoke to Mark Womack. He said he would have
Ron Brown get back to me on status of tank closure.