

## erSchy Environmental, Inc.

## **RECEIVED**

2:54 pm, Nov 29, 2007

Alameda County

Environmental Health

November 21, 2007

Ms. Donna Drogos Alameda County Health Care Services Agency Environmental Health Services 1131 Harbor Bay Parkway, Ste. 250 Alameda, California 94502-6577

RE: Site Update

Alaska Gas 6211 San Pablo Avenue Oakland, California

Dear Ms. Drogos:

HerSchy Environmental, Inc. (HerSchy) presents this site update letter for the above-referenced site to inform you of our intent to remove the propane tank, and at least temporarily, cease soil vapor extraction operations. This is a result of relatively low concentrations entering the oxidizer, making operating costs high, as well as a recent issue with permitting for the 500-gallon propane tank used in delivery of supplemental fuel for the oxidizer.

HerSchy has taken this action in light of diminishing effectiveness of the oxidizer, to continue to develop our alternative remediation plan of excavation and a "trench and gate" system for this site to capture floating product, as well as to allow the new oversight personnel to review and comment on this project to provide comment and directives on this project.

In the August 29, 2007 "Site Update" report, HerSchy proposed modified and/or additional borings locations to more accurately assess the contaminant plume. These modifications and additions were a result of the limited data collected from the recently installed off-site soil borings indicating the need for additional assessment, and the difficulties in being granted access by property owners or physical access issues. Additionally, HerSchy had requested a meeting with your office to discuss remediation options in response to the diminishing effectiveness of soil vapor extraction, and to discuss approval potential for alternative remediation options.

As of the date of this letter, HerSchy is not aware that a full-regulator for this site has been assigned. HerSchy continues to request a meeting with Alameda County, whether with Mr. Chan's replacement, or with you, to discuss further remediation options.

Upon approval of the modified soil boring installation plan, HerSchy will schedule the work. This work will assist HerSchy in evaluating the lateral spread of contaminants, and as a result, aid in determining appropriate alternative remediation.

If you have any questions, please contact Reijo Ratilainen by phone at (559) 760-0037.

With best regards,

Scott Jackson

Senior Project Geologist

cc: Mr. Pritpaul Sappal

P.O. Box 229 ◆ Bass Lake, CA 93604-0229 ◆ Phone: 559 • 641-7320 ◆ Fax: 559 • 641-7340