Environmental Management Company 6001 Bollinger Canyon Rd, L4050 P.O. Box 6012 San Ramon, CA 94583-2324 Tel 925-842-1589 Fax 925-842-8370 Karen Streich Project Manager

R0138 /

October 12 ,2004

ChevronTexaco

Alameda County Health Care Services 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Re:

Chevron Service Station # 9-0517

Address: 3900 Piedmont Ave., Oakland, California

I have reviewed the attached routine groundwater monitoring report dated September 21, 2004.

I agree with the conclusions and recommendations presented in the referenced report. The information in this report is accurate to the best of my knowledge and all local Agency/Regional Board guidelines have been followed. This report was prepared by Gettler-Ryan, Inc., upon whose assistance and advice I have relied.

This letter is submitted pursuant to the requirements of California Water Code Section 13267(b)(1) and the regulating implementation entitled Appendix A pertaining thereto.

I declare under penalty of perjury that the foregoing is true and correct.

Sincerely.

Karen Streich Project Manager

Karen Shex

Enclosure: Report

September 21, 2004 G-R #386420

TO:

Mr. Bruce H. Eppler

Cambria Environmental Technology, Inc.

4111 Citrus Avenue, Suite 12 Rocklin, California 95677

FROM:

Deanna L. Harding

Project Coordinator Gettler-Ryan Inc.

6747 Sierra Court, Suite J Dublin, California 94568 **RE:** Former Chevron Service Station

#9-0517

3900 Piedmont Avenue Oakland, California MTI: 61D-1995

WE HAVE ENCLOSED THE FOLLOWING:

| COPIES | DATED | DESCRIPTION |
|--------|--------------------|---|
| 2 | September 20, 2004 | Groundwater Monitoring and Sampling Report Second Semi-Annual - Event of August 23, 2004 |

COMMENTS:

Pursuant to your request, we are providing you with copies of the above referenced report for **your use** and distribution to the following:

Ms. Karen Streich, ChevronTexaco Company, P.O. Box 6012, Room K2256, San Ramon, CA 94583

Please provide any comments/changes and propose any groundwater monitoring modifications for the next event prior to *October 11*, 2004, at which time the final report will be distributed to the following:

cc: Mr. Barney Chan, Alameda County Health Care Services, Dept. of Environmental Health, 1153 Harbor Bay
 Parkway, Suite 250, Alameda, CA 94502-6577
 Neil B. Goodhue and Mrs. Diane C. Goodhue, 300 Hillside Avenue, Piedmont, CA 94611

Enclosures



September 20, 2004 G-R Job #386420

Ms. Karen Streich ChevronTexaco Company P.O. Box 6012, Room K2256 San Ramon, CA 94583

RE: Second Semi-Annual Event of August 23, 2004

Groundwater Monitoring & Sampling Report Former Chevron Service Station #9-0517 3900 Piedmont Avenue

3900 Piedmont Avenue Oakland, California

Dear Ms. Streich:

This report documents the most recent groundwater monitoring and sampling event performed by Gettler-Ryan Inc. (G-R) at the referenced site. All field work was conducted in accordance with G-R Standard Operating Procedure - Groundwater Sampling (attached).

Static groundwater levels were measured and the wells were checked for the presence of separate-phase hydrocarbons. Static water level data, groundwater elevations, and separate-phase hydrocarbon thickness (if any) are presented in the attached Table 1. A Potentiometric Map is included as Figure 1.

Groundwater samples were collected from the monitoring wells and submitted to a state certified laboratory for analyses. The field data sheets for this event are attached. Analytical results are presented in the table(s) listed below. The chain of custody document and laboratory analytical report are also attached.

Please call if you have any questions or comments regarding this report. Thank you.

Sincerely,

Deanna L. Harding Project Coordinator

-FOR-

Hagop Kevork P.E. No. C55734

Figure 1: Potentiometric Map

Table 1: Groundwater Monitoring Data and Analytical Results
Attachments: Standard Operating Procedure - Groundwater Sampling

Field Data Sheets

Chain of Custody Document and Laboratory Analytical Reports

Planter MW-1 PIEDMONT AVENUE 77.77 **Apartment** House MW-2 77.86 Planter ≳lanter

EXPLANATION


Groundwater monitoring well

99.99

Groundwater elevation in feet referenced to Mean Sea Level

Groundwater elevation contour, dashed where inferred

Approximate groundwater flow direction at a gradient of 0.01 Ft./Ft.



MONTELL STREET

Source: Figure modified from drawing provided by RRM engineering contracting firm.



POTENTIOMETRIC MAP

Former Chevron Service Station #9-0517 3900 Piedmont Avenue Oakland, California

REVISED DATE

PROJECT NUMBER 386420

REVIEWED BY August 23, 2004

FILE NAME: P:\Enviro\Chevron\9-0517\Q04-9-0517.DWG | Layout Tob: Pot3

FIGURE

Table 1
Groundwater Monitoring Data and Analytical Results
Former Chevron Service Station #9-0517

mer Chevron Service Station #9-05 3900 Piedmont Avenue Oakland, California

| | | | | Oakiano, C | Zamonna | | | | |
|-----------------------|-------|---------------|-------|------------|---------|---------|----------|---------|-------|
| WELLID/ | TOC* | GWE | DTW | TPH-G | B | 1 | . | X | MTBE |
| DATE | (fi.) | (msl) | (fi.) | (ppb) | (ppb) | (ppb) | (ррь) | (ppb) | (ppb) |
| MW-1 | | | | | | | | | |
| 08/03/98 | 87.89 | 75.46 | 12.43 | <50 | <0.5 | <0.5 | <0.5 | < 0.5 | <2.5 |
| 11/23/98 | 87.89 | 78.84 | 9.05 | <50 | <0.5 | <0.5 | < 0.5 | < 0.5 | <2.0 |
| 02/08/99 | 87.89 | 81.39 | 6.50 | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | <2.5 |
| 05/07/99 | 87.89 | 80.76 | 7.13 | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | <5.0 |
| 08/23/99 | 87.89 | 78.74 | 9.15 | <50 | < 0.5 | <0.5 | <0.5 | < 0.5 | <2.5 |
| 11/03/99 | 87.89 | 78.35 | 9.54 | < 50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | <2.5 |
| 02/15/00 | 87.89 | 81.99 | 5.90 | <50 | < 0.5 | < 0.5 | < 0.5 | <0.5 | <5.0 |
| 05/12/00 ³ | 87.89 | 80.84 | 7.05 | <50 | < 0.50 | <0.50 | < 0.50 | < 0.50 | <2.5 |
| 07/31/00 | 87,89 | 79.49 | 8.40 | <50 | <0.50 | < 0.50 | < 0.50 | < 0.50 | <2.5 |
| 10/30/00 | 87.89 | 79.24 | 8.65 | <50.0 | < 0.500 | < 0.500 | < 0.500 | <1.50 | <2.50 |
| 02/27/01 | 87.89 | 82.06 | 5.83 | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 |
| 05/15/01 | 87.89 | 80.18 | 7.71 | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 |
| 08/23/01 | 87.89 | DRY | | | | | | | •• |
| 02/25/02 | 87.89 | 81.18 | 6.71 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| 08/05/02 | 87.89 | 79.00 | 8.89 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| 02/11/03 | 87.89 | 80.53 | 7.36 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| 08/09/03 ⁵ | 87.89 | 78.42 | 9.47 | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 0.5 |
| 02/25/045 | 87.89 | 81.59 | 6.30 | <50 | <0.5 | <0.5 | < 0.5 | <0.5 | < 0.5 |
| 08/23/04 ⁵ | 87.89 | 77.77 | 10.12 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <0.5 |
| MW-2 | | | | | | | _ | | |
| 08/03/98 | 86.09 | 74.75 | 11.34 | <50 | <0.5 | < 0.5 | < 0.5 | < 0.5 | 3.4 |
| 11/23/98 | 86.09 | 79.19 | 6.90 | <50 | <0.5 | <0.5 | <0.5 | < 0.5 | <2.0 |
| 02/08/99 | 86.09 | 80.86 | 5.23 | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | <2.5 |
| 05/07/99 | 86.09 | 7 9.97 | 6.12 | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | <5.0 |
| 08/23/99 | 86.09 | 79.68 | 6.41 | <50 | < 0.5 | <0.5 | < 0.5 | < 0.5 | <2.5 |
| 11/03/99 | 86.09 | 78.80 | 7.29 | <50 | < 0.5 | <0.5 | <0.5 | < 0.5 | <2.5 |
| 02/15/00 | 86.09 | 81.60 | 4.49 | <50 | <0.5 | <0.5 | <0.5 | < 0.5 | <5.0 |
| 05/12/00 | 86.09 | 80.19 | 5.90 | $4,000^3$ | 240 | 26 | 100 | 76 | <100 |
| 07/31/00 | 86.09 | 79.51 | 6.58 | <50 | < 0.50 | < 0.50 | < 0.50 | < 0.50 | <2.5 |
| 10/30/00 | 86.09 | 79,86 | 6.23 | <50.0 | < 0.500 | 2.92 | < 0.500 | 1.88 | 4.89 |
| 02/27/01 | 86.09 | 81.49 | 4.60 | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 |

Table 1
Groundwater Monitoring Data and Analytical Results
Former Chevron Service Station #9-0517

Former Chevron Service Station #9-3900 Piedmont Avenue Oakland, California

| WELL ID/ | TOC* | GWE | DTW | TPH-G | В | T | E | X | MTBE |
|-----------------------|-------|-------|-------|---------------------|--------|---------|----------|--------|-------|
| DATE | (fi.) | (msl) | (1.) | (pph) | (pph) | (ppb) | (ppb) | (pph) | (ppb) |
| | | | | | | | | · | 4 |
| MW-2 (cont) | | | | | | | | -0.500 | ~2.5A |
| 05/15/01 | 86.09 | 79.79 | 6.30 | <50.0 | <0.500 | < 0.500 | < 0.500 | <0.500 | <2.50 |
| 08/23/01 | 86.09 | 78.81 | 7.28 | <50 | < 0.50 | < 0.50 | < 0.50 | <0.50 | <2.5 |
| 02/25/02 | 86.09 | 80.48 | 5.61 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| 08/05/02 | 86.09 | 78.99 | 7.10 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| 02/11/03 | 86.09 | 78.64 | 7.45 | <50 | < 0.50 | < 0.50 | <0.50 | <1.5 | <2.5 |
| 08/09/03 ⁵ | 86.09 | 78.44 | 7.65 | < 50 | < 0.5 | < 0.5 | < 0.5 | <0.5 | <0.5 |
| 02/25/045 | 86.09 | 81.24 | 4.85 | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 0.5 |
| 08/23/04 ⁵ | 86.09 | 77.86 | 8.23 | <50 | <0.5 | <0.5 | <0.5 | < 0.5 | <0.5 |
| | out, | | | | | | | | |
| | | | | | | | | | |
| MW-3 | | | | | | -e 0 | <5.0 | 73 | 180 |
| 08/03/98 | 86.28 | 74.20 | 12.08 | 4000 | 160 | <5.0 | | 24.5 | 41.2 |
| 11/23/98 | 86.28 | 78.59 | 7.69 | 4000 | 67.7 | 7.56 | 17.1 | | <2.5 |
| 02/08/99 | 86.28 | 80.01 | 6.27 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | |
| 05/07/99 | 86.28 | 79.32 | 6.96 | 1800 | 53.6 | 8.96 | 33 | 18.6 | 21.4 |
| 08/23/99 | 86.28 | 78.36 | 7.92 | 3970 | 155 | 24 | 88.8 | 39.8 | 185 |
| 11/03/99 | 86.28 | 78.36 | 7.92 | 3320 | 108 | 19.9 | 98.4 | 44.8 | <25 |
| 02/15/00 | 86.28 | 80.54 | 5.74 | 779 | 26.7 | 3.82 | 15.4 | 4.24 | <12.5 |
| 05/12/00 | 86.28 | 79.52 | 6.76 | 12,000 ³ | 3,100 | 120 | 980 | 1,400 | 820 |
| 07/31/00 | 86.28 | 78.98 | 7.30 | 1,200 ³ | 32 | <5.0 | 11 | 7.3 | - 39 |
| 10/30/00 | 86.28 | 79.26 | 7.02 | $3,300^4$ | 119 | <5.00 | 40.0 | <15.0 | <25.0 |
| 02/27/01 | 86.28 | 80.39 | 5.89 | 432 ³ | 15.5 | 1.53 | 14.9 | 1.06 | 15.7 |
| 05/15/01 | 86.28 | 79.21 | 7.07 | $3,220^3$ | 96.4 | 12.6 | 11.5 | 11.6 | 128 |
| 08/23/01 | 86.28 | 78.23 | 8.05 | 2,300 | 48 | <10 | <10 - | <10 | 100 |
| 02/25/02 | 86.28 | 79.55 | 6.73 | 3,100 | 27 | 2.1 | 4.8 | 6.6 | <2.5 |
| 08/05/02 | 86,28 | 78.33 | 7.95 | 4,100 | 87 | 21 | 90 | 47 | 21 |
| 02/11/03 | 86.28 | 79.23 | 7.05 | 3,700 | 21 | 2.3 | 4.4 | 9.0 | <20 |
| 08/09/03 ⁵ | 86.28 | 78.05 | 8.23 | 1,600 | 12 | 1 | 2 | 4 | 0.7 |
| 02/25/045 | 86.28 | 80.43 | 5.85 | <50 | < 0.5 | < 0.5 | <0.5 | <0.5 | < 0.5 |
| 08/23/04 ⁵ | 86.28 | 77.23 | 9.05 | 3,000 | 21 | 3 | 3 | 9 | < 0.5 |

Table 1
Groundwater Monitoring Data and Analytical Results
Former Chevron Service Station #9-0517

Former Chevron Service Station
3900 Piedmont Avenue
Oakland, California

| | | | | | | | and the second | | MTBE |
|-----------------------|-------|-------------|-------|--------------------|----------|---------|----------------|------------|------------------------|
| WELL ID/ | TOC* | GWE | DTW | TPH-G | B | T | E | X (ppb) | (ppb) |
| DATE | (ft.) | (msl) | (fi.) | (ppb) | (ppb) | (ррв) | (p ph) | (рро) | PP97 |
| MW-4 | | | | | | • | | | |
| 08/03/98 | 87.22 | 74.30 | 12.92 | 1900 | 110 | 12 | < 0.5 | 55 | 130 |
| 1/23/98 | 87.22 | 77.82 | 9.40 | 4080 | 136 | 17.8 | 37.2 | 30.1 | 51.8 |
| 2/08/99 ¹ | 87.22 | 79.40 | 7.82 | 2900 | 150 | 16 | <5.0 | 15 | 230/30.7 ² |
| 5/07/99 | 87.22 | 79.80 | 7.42 | 6050 | 161 | <25 | 39.8 | 36.9 | <250/30.2 ² |
| 8/23/99 | 87.22 | 77.83 | 9,39 | 3930 | 203 | 37.6 | 58.6 | 42,2 | 255 |
| 1/03/99 | 87.22 | 77.41 | 9.81 | 5350 | 324 | 44.7 | 91.5 | 56.1 | <50 |
| 2/15/00 | 87,22 | 79.50 | 7.72 | 4080 | 161 | 27.7 | 31.1 | 39.1 | 73.9 |
| 5/12/00 | 87.22 | 79.31 | 7.91 | $3,600^3$ | 170 | 27 | 49 | 64 | 170 |
| 7/31/00 | 87.22 | 78.57 | 8.65 | $2,900^3$ | 160 | 20 | 15 | 56 | 170 |
| 0/30/00 | 87.22 | 78.14 | 9.08 | 5,630 ⁴ | 301 | 17.8 | 11.8 | 51.5 | <25.0 |
| 2/27/01 | 87.22 | 79.92 | 7.30 | $2,140^3$ | 95.1 | 12.8 | 53.4 | 43.0 | 235 |
| 5/15/01 | 87.22 | 79.07 | 8.15 | 4,580 ³ | 200 | 44.1 | 46.3 | 51.7 | 172 |
| 8/23/01 | 87.22 | 77.89 | 9.33 | 2,700 | 250 | 44 | 21 | 72 | 130 |
| 2/25/02 | 87.22 | 79.42 | 7.80 | 4,100 | 100 | 18 | 27 | 39 | <10 |
| 8/05/02 | 87.22 | 80.12 | 7.10 | 4,100 | 130 | 18 | 50 | 20 | <10 |
| 2/11/03 | 87.22 | 79.10 | 8.12 | 4,100 | 100 | 23 | 20 | 51 | <50 |
| 8/09/03 ⁵ | 87.22 | 77.67 | 9.55 | 3,700 | 110 | 24 | 10 | 45 | 8 |
| 12/25/04 ⁵ | 87.22 | 79.16 | 8.06 | 5,400 | 94 | 28 | 34 | 49 | 5 |
| 18/23/04 ⁵ | 87.22 | 77.03 | 10.19 | 5,100 | 100 | 26 | 7 | 43 | 5 |
| | | | | | | | | | |
| TRIP BLANK | | | | | | | | | |
| 8/03/98 | ** | | | <50 | <0.5 | <0.5 | < 0.5 | <0.5 | <2.5 |
| 1/23/98 | | | | <50 | < 0.5 | < 0.5 | < 0.5 | <0.5 | <2.0 |
| 2/08/99 | | | | <50 | <0.5 | <0.5 | < 0.5 | <0.5 | <2.5 |
| 5/07/99 | | | | <50 | <0.5 | <0.5 | < 0.5 | < 0.5 | <5.0 |
| 8/23/99 | | | | <50 | <0.5 | <0.5 | < 0.5 | <0.5 | <2.5 |
| 1/03/99 | | | | <50 | <0.5 | <0.5 | < 0.5 | < 0.5 | <2.5 |
| 2/15/00 | | | | <50 | < 0.5 | < 0.5 | < 0.5 | < 0.5 | <5.0 |
| 05/12/00 | | | | <50 | <0.50 | < 0.50 | < 0.50 | <0.50 | <2.5 |
| 7/31/00 | •- | | | <50 | < 0.50 | < 0.50 | < 0.50 | < 0.50 | <2.5 |
| 10/30/00 - | - | | | <50.0 | < 0.500 | < 0.500 | <0.500 | <1.50 | <2.50 |

Table 1 Groundwater Monitoring Data and Analytical Results Former Chevron Service Station #9-0517

er Chevron Service Station # 3900 Piedmont Avenue Oakland, California

| | | | | | 100000000000000000000000000000000000000 | San and B. S. | (ppb) | (ppb) |
|-------|--------|----------------|-------|---|---|---------------|---------|---------------------------------------|
| (fi.) | (mzsl) | (fi.) | (ppb) | (ppb) | (ppb) | (ppb) | (рро) | y y y y y y y y y y y y y y y y y y y |
| | | • | | | | | | |
| | | · | <50.0 | < 0.500 | < 0.500 | < 0.500 | | <2.50 |
| | | - - | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | <2.50 |
| | | | <50 | < 0.50 | <0.50 | <0.50 | <0.50 | <2.5 |
| | | | | | | | | <i>(</i>) <i>(</i> |
| | •• | | <50 | < 0.50 | - <0.50 | <0.50 | | <2.5 |
| | | | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| | | •• | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| | | | | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 0.5 |
| | | | | < 0.5 | < 0.5 | < 0.5 | < 0.5 | < 0.5 |
| | | | | <0.5 | <0.5 | < 0.5 | <0.5 | <0.5 |
| | | | | <50.0 <50.0 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 <50 | < | | <- | |

Table 1

Groundwater Monitoring Data and Analytical Results

Former Chevron Service Station #9-0517 3900 Piedmont Avenue Oakland, California

EXPLANATIONS:

Groundwater monitoring data and laboratory analytical results prior to May 12, 2000, were compiled from reports prepared by Blaine Tech Services, Inc.

TOC = Top of Casing

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary butyl ether

(ft.) = Feet

B = Benzene

(ppb) = Parts per billion

GWE = Groundwater Elevation

T = Toluene

-- = Not Measured/Not Analyzed

(msl) = Mean sea level

E = Ethylbenzene

QA = Quality Assurance/Trip Blank

DTW = Depth to Water

X = Xylenes

- * TOC elevations are referenced to msl.
- Chromatogram pattern indicates gas and an unidentified hydrocarbon.
- Confirmation run.
- Laboratory report indicates gasoline C6-C12.
- Laboratory report indicates hydrocarbon pattern present in the requested fuel quantitation range but does not resemble the pattern of the requested fuel.
- 5 BTEX and MTBE by EPA Method 8260.

STANDARD OPERATING PROCEDURE - GROUNDWATER SAMPLING

Gettler-Ryan Inc. field personnel adhere to the following procedures for the collection and handling of groundwater samples prior to analysis by the analytical laboratory. Prior to sample collection, the type of analysis to be performed is determined. Loss prevention of volatile compounds is controlled and sample preservation for subsequent analysis is maintained.

Prior to sampling, the presence or absence of free-phase hydrocarbons is determined using an interface probe. Product thickness, if present, is measured to the nearest 0.01 foot and is noted in the field notes. In addition, all depth to water level measurements are collected with a static water level indicator and are also recorded in the field notes, prior to purging and sampling any wells.

After water levels are collected and prior to sampling, if purging is to occur, each well is purged a minimum of three well casing volumes of water using pre-cleaned pumps (stack, suction, Grundfos), or disposable bailers. Temperature, pH and electrical conductivity are measured a minimum of three times during the purging. Purging continues until these parameters stabilize.

Groundwater samples are collected using disposable bailers. The water samples are transferred from the bailer into appropriate containers. Pre-preserved containers, supplied by analytical laboratories, are used when possible. When pre-preserved containers are not available, the laboratory is instructed to preserve the sample as appropriate. Duplicate samples are collected for the laboratory to use in maintaining quality assurance/quality control standards. The samples are labeled to include the job number, sample identification, collection date and time, analysis, preservation (if any), and the sample collector's initials. The water samples are placed in a cooler, maintained at 4°C for transport to the laboratory. Once collected in the field, all samples are maintained under chain of custody until delivered to the laboratory.

The chain of custody document includes the job number, type of preservation, if any, analysis requested, sample identification, date and time collected, and the sample collector's name. The chain of custody is signed and dated (including time of transfer) by each person who receives or surrenders the samples, beginning with the field personnel and ending with the laboratory personnel.

A laboratory supplied trip blank accompanies each sampling set. For sampling sets greater than 20 samples, 5% trip blanks are included. The trip blank is analyzed for some or all of the same compounds as the groundwater samples.

As requested by ChevronTexaco Company, the purge water and decontamination water generated during sampling activities is transported by IWM to McKittrick Waste Management located in McKittrick, California.



GETTLER-RYAN INC.

WELL MONITORING/SAMPLING FIELD DATA SHEET

| Client/Facility #: C | hevronTexaco | y9-0517 | 7 J | ob Number: | 386420 | |
|--|---------------------------------------|---------|---|------------------------|--|------------|
| | 900 Piedmont | | | vent Date: | 8 23104 | (inclusive |
| _ | akland, CA | | | ampler: | A. Saith | |
| City: | akiailu, OA | | | | | |
| Well ID | MW- \ | Date | Monitored: 8 | 123/64 | Well Condition: | <u> </u> |
| Well Diameter | 2 in. | | | | 1"= 0.04 2"= 0.17 3"= 0.3 | |
| Total Depth | 1/2. 17 ft. | a | Volume Factor (VF) | 3/4"= 0.02 4"= 0.66 | 1"= 0.04 2"= 0.17 3"= 0.3 5"= 1.02 6"= 1.50 12"= 5. | · [|
| Depth to Water | 10 12 4 | | <u> </u> | | | |
| | 6:05 xV | F 0.17 | = 1.63 x | 3 case volume= | Estimated Purge Volume: 3.00 | gai. |
| _ | | · | | | Time Started: | (2400 hrs) |
| Purge Equipment: | ~ | Sam | pling Equipment: | ···· | Time Completed: | (2400 hrs) |
| Disposable Bailer | | Disp | osable Bailer | | Depth to Product: Depth to Water: | π ft |
| Stainless Steel Bailer | | Pres | sure Bailer | | Hydrocarbon Thickness: | ft. |
| Stack Pump | | | rete Bailer | | Visual Confirmation/Description | 1. |
| Suction Pump | | Othe | :r | - | Skimmer / Absorbant Sock (circ | cle one) |
| Grundfos | | | | | Skimmer / Absorbant Sock (circ Amt Removed from Skimmer:_ | |
| Other: | | | | | Amt Removed from Well: | gal |
| | | | | | Water Removed: | |
| | | | | | Product Transferred to: | <u> </u> |
| Sample Time/Date Purging Flow Rate Did well de-water? Time (2400 hr.) 1154 1159 1203 | : <u>14 gpm.</u> | | Water Color: ent Description: e: Conductivity (u mhos/cm) 33 | | Odor: Odor: | |
| | | LAI | BORATORY INFO | | | |
| SAMPLE ID | (#) CONTAINER | REFRIG. | PRESERV. TYPE | LABORATO | - A CARACHOTEVA MITOE/DC | 260) |
| MW- / | 6 x voa vial | YES | HCL | LANCASTE | K IFH-G(0013)/BTEX-INT BE(02 | |
| | | | | | | |
| | · · · · · · · · · · · · · · · · · · · | | | | | |
| | | | | | | |
| | | | | <u> </u> | | |
| COMMENTS: | | | | | | |
| Add/Replac | ed Lock: | | | .dd/Replaced | Plug:Size: | |



GETTLER-RYAN INC.

WELL MONITORING/SAMPLING **FIELD DATA SHEET**

| Client/Facility #: C | hevronTexac | o #9-051 | 7 | Job Number: | 386420 | |
|--|---------------|-------------|-------------------------|----------------------------|--|--------------------|
| | 900 Piedmont | Avenue | | Event Date: | 8/23/04 | (inclusive |
| City: | akland, CA | | · · · | Sampler: | A. Smith | |
| Well ID | MW-⊃ | Date | Monitored: | 8/23/04 | Well Condition: OK | |
| Well Diameter | 2 in. | | Volume | 3/4"= 0.02 | 1"= 0.04 2"= 0.17 3*= 0.36 | 8 |
| otal Depth | 16.53 ft. | | Factor (VF | | 5"= 1.02 6"= 1.50 12"= 5.8 | 80 |
| Depth to Water _ | 8.23 ft. | 1F 6, 17 | - 1.41 | v2 sass valumes F | Estimated Purge Volume: 4, 2 | .3 _{oal.} |
| · - | 8.30 × | /r <u> </u> | #: <u>!•_</u> :(| x3 case volume= t | Time Started: | (2400 hrs) |
| Purge Equipment: | • | Sam | pling Equipment | : _ | Time Completed: | |
| Disposable Bailer | | Disp | osable Bailer | | Depth to Product: | ft ft |
| Stainless Steel Bailer | | Pres | sure Bailer | | Depth to Water: | n ft |
| Stack Pump | | Disc | rete Bailer | | Hydrocarbon Thickness: Visual Confirmation/Description | |
| Suction Pump | | Oth | er | | <u> </u> | |
| Grundfos | | | | | Skimmer / Absorbant Sock (circ | de one) |
| Other: | | | | | Amt Removed from Skimmer: Amt Removed from Well: | |
| | | ÷ | | | Water Removed: | 931 |
| | | | | | Product Transferred to: | |
| 4 · 4 | | | | | <u> </u> | |
| Sample Time/Date Purging Flow Rate Did well de-water Time (2400 hr.) /056 | e: <u>√</u> | | Conductivity (umhos/cm) | Volume: Temperature (C/F) | Ø gal. D.O. OR (mg/L) (mV | |
| 1106 | 4 | 8.01 | 371 | | | |
| | | | | | | |
| SAMPLE ID | (#) CONTAINER | REFRIG. | BORATORY IN | | Y ANALYSES | |
| MW- Z | x voa vial | | HCL | LANCASTER | TOUR OVERALL VOTEY MATRIC/99 | 60) |
| ······ | X 700 110. | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| COMMENTS: | | | | | | |
| Add/Replac | ad Look: | | × . | Add/Replaced F | Plua: Size: | |



GETTLER-RYAN INC.

WELL MONITORING/SAMPLING FIELD DATA SHEET

| | nevronTexaco ‡ 00 Piedmont A | | Job Number: Event Date: | 8/23/64 | (inclusive |
|--|---|--|--|---|-----------------------|
| City: | akland, CA | | Sampler: | A. Smith | |
| Well ID Well Diameter Total Depth Depth to Water | MW-3 2 in. 17.58 ft. 9.05 ft. 8.53 xVF. | Fa | olume 3/4"= 0.02 actor (VF) 4"= 0.66 | 1"= 0.04 2"= 0.17 3"= 0.5"= 1.02 6"= 1.50 12"= 5 | 38 5.80 35 gal. |
| Purge Equipment: Disposable Bailer Stainless Steel Bailer Stack Pump Suction Pump Grundfos Other: | | Sampling Equ Disposable Ba Pressure Baile Discrete Bailer Other: | iler | Time Started: Time Completed: Depth to Product: Depth to Water: Hydrocarbon Thickness: Visual Confirmation/Description Skimmer / Absorbant Sock (of Amt Removed from Skimmer: Amt Removed from Well: Water Removed: Product Transferred to: | ftftft on: ircle one) |
| Start Time (purge): Sample Time/Date Purging Flow Rate Did well de-water? Time (2400 hr.) 1 0 2 3 1 6 2 9 1 0 3 7 | : να gpm. | Weather Conduction Weather Conduction Water Sediment Description Conduction (umhos) 164 49 162 45 150 40 | r Color: Light or cription: No New Yolume: | e D.O. C | ORP mV) |
| | · <u>, </u> | | ORY INFORMATION | ORY ANALYSES | |
| SAMPLE ID | (#) CONTAINER x voa vial | | CL LANCAST | CONTRACTOR MATRICE | |
| COMMENTS: | | | Add/Replace | ed Plua: Size: | |

WELL MONITORING/SAMPLING FIELD DATA SHEET

| Client/Facility #: C | ChevronTexac | o #9-051 | 7 | Job Number: | 386420 | |
|-------------------------------|--|----------------------------|----------------------------------|----------------------------|---|------------------|
| · - | 900 Piedmon | t Avenue | <u> </u> | Event Date: | 8/23/04 | (inclusiv |
| _ | Dakland, CA | | | Sampler: | A. Smith | |
| Well ID | MW- 4 | Date | Monitored: | 8123/04 | Well Condition: | ck_ |
| Well Diameter _ | 2 in. | | Volume | 3/4"= 0.02 | 1"= 0.04 2"= 0.17 | 3"= 0.38 |
| Total Depth _ | 16.27 ft. | | Factor (VI | | 5"= 1.02 6"= 1.50 1 | 2"= 5.80 |
| Depth to Water _ | 10-19 ft. 6.08 × | vF 0.17 | = 1.03 | x3 case volume= E | Estimated Purge Volume: | .69 gal. |
| | 0.00 | | | / | Time Started: | (2400 hrs) |
| Purge Equipment: | / | | npling Equipment | t: / | Time Completed: | (2400 hrs) ft |
| Disposable Bailer | | • | osable Bailer | | Depth to Product: Depth to Water: | n |
| Stainless Steel Bailer | | - | ssure Bailer crete Bailer | | Hydrocarbon Thickness: | |
| Stack Pump Suction Pump | | | er: | | Visual Confirmation/Desc | |
| Grundfos | | | | | Skimmer / Absorbant Soc | ck (circle one) |
| Other: | | | | | Amt Removed from Skim | mer: gal |
| | | | | | Amt Removed from Well: | gal |
| | | | | | Water Removed: Product Transferred to: | |
| ₹ | | | | | | |
| Time (2400 hr.) 10 09 16 13 | Volume (gal.) | pH 8,34 8,26 7,74 | Conductivity (u mhos/cm) 436 463 | Temperature (OF) 20.9 21.1 | D.O. (mg/L) | ORP (mV) |
| | | | BORATORY INI | FORMATION | | |
| SAMPLE ID | (#) CONTAINER | REFRIG. | PRESERV. TYPI | | Y ANALYS | ES |
| MW- 4 | x voa vial | | HCL | LANCASTER | TPH-G(8015)/BTEX+MT | BE(8260) |
| | 0 | | | | | |
| | | : | - | | | |
| | | | | <u> </u> | | |
| | | | | - | | |
| COMMENTS: | | | | | | |
| | | | | | | |
| Add/Replac | ad Lock: | | | Add/Replaced F | Plua: Size: | |

Chevron California Region Analysis Request/Chain of Custody

| 413 | Lancaster | Laboratories |
|-----|--------------------|--------------|
| Ų. | Where quality is a | science. |

082604-13

Acci. #: 10404

For Lancaster Laboratories use onl

A 09743

| Fecility #: SS#9-0517 G-R#386420 Global ID#T0800102248 Matrix Preservation Codes H - HCl T = Thiosulfate N - HCl T = Thiosu | • • where quality is a science. | | 40 U T | | | r | | _ | - | | | Anal | y888 | Rea | uest | ed | | | 1 | | | |
|--|---|--------------------|--------------|--------------|------|------------|-------------|----------|-------------|---------|--|----------|----------|----------|-----------|--------------|----------|--------|----------------------|-----------|-----------------|---|
| Site Address 900 PIEDMONT AVENUE, CAKLAND, CA Chevron PIMTI Lead Consultant CAMBRIA Consultant Pri, Mg: Mg: Deannat L. Harding (deanna@grinc.com) Consultant Pri, Mg: Deannat L. Harding (deanna@grinc.com) Consultant Pri, Mg: Mg: Deannat L. Harding (deanna@grinc.com) Service Order #: | | <u>_</u> _ | | 320 | 1 | | | + | | | | | | | | | | | Pression | Hue Cod | | 7 |
| Size Address 900 PIELMONT AVENUE, CARCAND, CA Chevron PM-MT Lead Consultant PM-Cas Barbor (deanna @grinc.com) Consultant PM-pit Mg/-Deanna L. Harding (deanna @grinc.com) Sample: | Facility #: 55#9-0317 G-R#380420 G | ODBIT IDET VOUCT | UZZ48 | | [| META | ١ | 7 | Į Į | F | | T | | | | Ť | | \top | | | | J |
| Consultant Phone #925-551-7859 Sample: | | | | | 1 | 2 | | ľ | | \top | | | | \neg | | | 1 | | N = HNO ₃ | B = NaO | Н | 1 |
| Consultant Phone #925-551-7859 Sample: | Chevron PM.MT! Lea | id Consultant. AM | IBRIA | | | 7. 44. | П, | , | | 18 | | | 1 1 | | | | 1 | i | | | | 4 |
| Consultant Phone #925-551-7859 Sample: | Consultant/Office G-R, Inc., 6747 Sierra Ci | ourt, Suite J, Du | blin, Ca. 94 | 5 6 8 | | DES | j | | | 90 | | ļ | | | | | | | № 3 | | | |
| Consultant Phone #925-551-7859 Sample: | Consultant Prj. Mgr.: Deanna L. Harding (o | leanna@grinc.c | om) | | | D Z | į S | | | 漫 | | 1 | | | | | 1 | | | | | ļ |
| Sample Identification Collected Col | | | | | |) | ورا | 5 | ်မှု | | | | | | | 1 | | | 8021 MTBE Con | firmation | | l |
| Sample Identification Collected Col | Sampler: Andrew Smith | | | ø | 1 | | | W | 8 | 8 | Ļ | 를 | ~ | | | | | | | - | 26 0 | I |
| Comments / Remarks S/23/ey 215 X S | Service Order #: | Non SAR: | | Dos. | | · | ₹ 2 | | 15 M | 15 14 | S | 8 | 8 | - 1 | | | | | _ | • | st hit | I |
| Comments / Remarks S/23/ey 215 X S | Sample Identification | | Time | | Š | Nate | 등 | ב ב | F E | Æ | 360 f | | Pes | | | | | | | _ | | 1 |
| Relinquished by: Date Time Received by: Date Time Date Time Received by: Date Time Date Date Time Date D | | | | _ | - | X | | Σij | ₹ | オ▔ | | | | _ | + | + | 十 | 1 | Comments / R | lemarks | | 1 |
| Termstround Time Requested (TAT) (please circle) STD. TAT 24 hour 4 day 5 day Relinquished by: R | MW-1 | 8/23/04 | 1215 X | <u> </u> | | X | 6 | | ĺΧ | | | | | | | | | 45. |] | | | I |
| Termstround Time Requested (TAT) (please circle) STD. TAT 24 hour 4 day 5 day Relinquished by: Relinquished by: Relinquished by: Date Time Received by: Date Time Relinquished by: Date Time Relinquished by: Date Time Received by: Dat | Mw-Z | 8/23/0Y | 1115 | ۷. | | X | - 6 | 3 3 | <u>{</u> } | 4 | | | | | | | | 1 |] | | | I |
| Ternstround Time Requested (TAT) (please circle) STD. TAT 24 hour 4 day 5 day Date Relinquished by: Relinquished by: Relinquished by: Date Time Received by: Date Date Date Date Date Date Date Dat | | | | <u></u> | | X | 6 | | _ | 1 | L | | | | | I. | \perp | |] | | | |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Received by: | <u> </u> | 8/23/4 | 1015 7 | <u> </u> | | X | 6 |) | (12 | 1 | | ļ | | _ | _ | 4 | | 1. | . | | | 1 |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Received by: | | | | - | | *** | | \dashv | + | ┼ | ╂ | | \vdash | | \dashv | + | + | - | · \ | | | l |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Received by: | | - - | | + | | | ┝╌ | + | + | ╁╌ | - | | H | + | + | ╁ | + | + | - G. | | | 1 |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Pate Time Received by: Date Time Received by: | | | | + | 1 | | | | + | †- | | _ | Н | + | \dashv | + | +- | +- | ` | Ţ. | | Ì |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Pate Time Received by: Date Time Received by: | | | | | | | | | • | 1 | | | | 寸 | 7 | \top | - | + | | | | l |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Pate Time Received by: Date Time Received by: | | | | | | | | | ٠. | \prod | | | | | | | I | | | | | l |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Pate Time Received by: Date Time Received by: | | | | + | | | 1 | _ | ļ. <u>.</u> | ╀ | <u> </u> | ļ., | | _ | _ | | _ | | 1 | | | ļ |
| STD. TAT 72 hour 48 hour 4 day 5 day Relinquished by: Relinquished by: Relinquished by: Pate Time Received by: Date Time | | | Relinquish | مرابع المام | برا | | | | | ╀ | Doto | <u> </u> | Time | |) acob | _ <u></u> | | | | l per- | T : | 4 |
| Data Package Options (please circle if required) QC Summary Type 1 — Full Type VI (Raw Data) | V \(\) | • | | | | | mu | 7 | | | | | | | localy | ou by | • | , | | Cere | Ime | l |
| Data Package Options (please circle if required) QC Summary Type 1 — Full Type VI (Raw Data) | 14 | | Relinquish | ed by: | - | <u> </u> | | | | | ·L | 1 | | | tecelv | ed by | : {// | | 7) | | Time | 1 |
| QC Summary Type 1—Full Type VI (Raw Data) | <u> </u> | | Pallbodiet | in Mar | | _ | ¥ <i>/Q</i> | ĽΔ¢ | 8 | -~ | | _ | | -4- | بما | سيد | <u> </u> | 00 | amoye | | | † |
| Type VI (Raw Data) Coelt Deliverable not neede EDF/EDD Relinquished by Commercial Carrier: Repelved by: Date Time UPS FedEx Other | 00.0 | | 1// | | | 11 | / ^~~ / | ~ | 0 | | | | | " اد | (ecelv | ed by | D | 41 | | | Time | ١ |
| Disk | CO Contracts VDA FIRE | | | _ | | | | | | | <u> </u> | <u> </u> | _ | deelv | ed by | <u></u> : | ' | | | Time | + | |
| Disk | WIF (RWQCB) | בייבטר/בטט | UPS | Fed | ΙEx | (| Othe | <u>y</u> | | | | | c | <u> </u> | ۱// | _ | | | Mau - | | | K |
| Action Action Action 1 (183) NO 1 | Disk | | Temperatu | re Upo | n Re | ceipt _ | <u>3-(</u> | ف | C° | | | | | 0 | · | | | | Yes No | كريحان | 1 ~O 1 | t |



2425 New Holland Pike, PO Box 12425, Lencaster, PA 17605-2425 • 717-656-2300 Fex: 717-656-2681 • www.lancasterlabs.com

ANALYTICAL RESULTS

Prepared for:

ChevronTexaco c/o Cambria Camb

Prepared by:

Lancaster Laboratories 2425 New Holland Pike Lancaster, PA 17605-2425

SAMPLE GROUP

The sample group for this submittal is 909743. Samples arrived at the laboratory on Friday, August 27, 2004. The PO# for this group is 99011184 and the release number is MTl.

| Client Description | | | <u>Lancaster Labs Number</u> |
|--------------------|------|-------|------------------------------|
| QA-T-040823 | NA V | Vater | 4340463 |
| MW-1-W-040823 | Grab | Water | 4340464 |
| MW-2-W-040823 | Grab | Water | 4340465 |
| MW-3-W-040823 | Grab | Water | 4340466 |
| MW-4-W-040823 | Grab | Water | 4340467 |

I COPY TO ELECTRONIC COPY TO Cambria C/O Gettler- Ryan

Gettler-Ryan

Attn: Deanna L. Harding Attn: Cheryl Hansen



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-856-2300 Fax: 717-656-2661 • Www.lancasterlabs.com

Questions? Contact your Client Services Representative Megan A Moeller at (717) 656-2300.

Respectfully Submitted,

Victoria M. Martell

Chemist



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW

QA-T-040823 Facility# 90517 Job# 386420 MIT# 61D-1995 3900 Piedmont Ave Oakland T0600102248 QA

GRD

Collected: 08/23/2004

Account Number: 10904

Submitted: 08/27/2004 08:40 Reported: 09/01/2004 at 16:43

ChevronTexaco c/o Cambria

Suite 9

Discard: 10/02/2004

4111 Citrus Avenue Rocklin CA 95677

48-TB

| CAT No. | Analysis Name | CAS Number | As Received Result | As Received Method Detection Limit | Units | Dilution Factor |
|------------|---|-----------------------------------|-------------------------------------|---|-------|--------------------|
| 01728 | TPH-GRO - Waters | n.a. | N.D. | 50. | ug/l | 1 |
| | The reported concentration of TI gasoline constituents eluting prestart time. | PH-GRO does not rior to the C6 | include MTBE or (n-hexane) TPH-G | other RO range | | |
| 06054 | BTEX+MTBE by 8260B | | | | | |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | N.D. | 0.5 | ug/l | 1 |
| 05401 | Benzene | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| 05407 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 05415 | Ethylbenzene | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 06310 | Xylene (Total) | 1330-20-7 | N.D. | 0.5 | ug/l | 1 |

| CAT | Laboratory Chronicle Analysis | | | | | | |
|-------|-------------------------------|-------------------------------|--------|------------------|---------------|--------|--|
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor | |
| 01728 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 08/28/2004 03:28 | Brian C Veety | 1 | |
| 06054 | BTEX+MTBE by 8260B | SW-846 8260B | 1 · | 08/31/2004 14:37 | Anita M Dale | 1 | |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 08/28/2004 03:28 | Brian C Veety | n.a. | |
| 01163 | GC/MS VOA Water Prep | SW-846 5030B | 1 | 08/31/2004 14:37 | Anita M Dale | n.a. | |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW 4340464

MW-1-W-040823 Grab Water
Facility# 90517 Job# 386420 MIT# 61D-1995 GRD

3900 Piedmont Ave Oakland T0600102248 MW-1 Collected: 08/23/2004 12:15 by AS

Submitted: 08/27/2004 08:40 Reported: 09/01/2004 at 16:43

Discard: 10/02/2004

Account Number: 10904

ChevronTexaco c/o Cambria

Suite 9

4111 Citrus Avenue Rocklin CA 95677

48--1

| | | | | As Received | | Dilution |
|-------|---|-----------------------------------|--------------------------------------|--------------------|-------|----------|
| CAT | • | | As Received | Method | | |
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01728 | TPH-GRO - Waters | n.a. | N.D. | 50. | ug/l | 1 |
| | The reported concentration of T gasoline constituents eluting p start time. | PH-GRO does not rior to the C6 | include MTBE or (n-hexane) TPH-GH | other RO range | | |
| 06054 | BTEX+MTBE by 8260B | | | | | ı |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | N.D. | 0.5 | ug/l | 1 |
| 05401 | Benzene | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| 05407 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 05415 | · Ethylbenzene | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 06310 | Xylene (Total) | 1330-20-7 | N.D. | 0.5 | ug/l | 1 |

| | | Laboratory | Chro | | | 5 43-44-5 |
|-------------------------|---|--|-------------|--|---|-------------------------|
| CAT No. 01728 | Analysis Name TPH-GRO - Waters | Method N. CA LUFT Gasoline | Trial# | Analysis Date and Time 08/28/2004 03:57 | Analyst Brian C Veety | Dilution Factor 1 |
| 06054 01146 01163 | BTEX+MTBE by 8260B GC VOA Water Prep GC/MS VOA Water Prep | Method SW-846 8260B SW-846 5030B SW-846 5030B | 1 1 1 | 08/31/2004 15:03 08/28/2004 03:57 08/31/2004 15:03 | Anita M Dale Brian C Veety Anita M Dale | 1 п.а. п.а. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

4340465 Lancaster Laboratories Sample No.

MW-2-W-040823 Grab Facility# 90517 Job# 386420 MIT# 61D-1995

3900 Piedmont Ave Oakland T0600102248 MW-2

Collected: 08/23/2004 11:15

Submitted: 08/27/2004 08:40 Reported: 09/01/2004 at 16:43

Discard: 10/02/2004

Account Number: 10904

ChevronTexaco c/o Cambria

Suite 9

4111 Citrus Avenue Rocklin CA 95677

48--2

| | | | | As Received | | |
|-------|--|-------------------------------------|-------------------------------------|----------------------|-------|----------|
| CAT | | | As Received | Method | | Dilution |
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01728 | TPH-GRO - Waters | n.a. | N.D. | 50. | ug/l | 1 |
| | The reported concentration of I gasoline constituents eluting patent time. | PPH-GRO does not prior to the C6 | : include MTBE o (n-hexane) TPH- | r other GRO range | | |
| 06054 | BTEX+MTBE by 8260B | | | | | |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | N.D. | 0.5 | ug/l | 1 |
| 05401 | Benzene | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| 05407 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 05415 | Ethylbenzene | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 06310 | Xylene (Total) | 1330-20-7 | N.D. | 0.5 | ug/l | 1 |

GRD

| | | Laboratory | Chro | nicle | | Dilution | |
|-------|----------------------|-------------------------------|----------|------------------|---------------|----------|--|
| CAT | | - | Analysis | Analysis | | | |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor | |
| 01728 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 08/28/2004 04:26 | Brian C Veety | 1 | |
| 06054 | BTEX+MTBE by 8260B | SW-846 8260B | 1 | 08/31/2004 15:29 | Anita M Dale | 1 | |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 08/28/2004 04:26 | Brian C Veety | n.a. | |
| 01163 | GC/MS VOA Water Prep | SW-846 5030B | 1 | 08/31/2004 15:29 | Anita M Dale | n.a. | |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-655-2300 Fax: 717-656-2681 • www.tancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW 4340466

MW-3-W-040823 Grab Facility# 90517 Job# 386420 MIT# 61D-1995

3900 Piedmont Ave Oakland T0600102248 MW-3

Collected:08/23/2004 10:40

Submitted: 08/27/2004 08:40 Reported: 09/01/2004 at 16:43 Discard: 10/02/2004

Account Number: 10904

ChevronTexaco c/o Cambria

Suite 9

4111 Citrus Avenue Rocklin CA 95677

48--3

| CAT No. 01728 | Analysis Name TPH-GRO - Waters The reported concentration of TR | CAS Number n.a. PH-GRO does not | As Received Result 3,000. include MTBE or | As Received Method Detection Limit 250. other | Units ug/l | Dilution Factor |
|---|---|---|--|--|--------------------------------------|--------------------|
| 06054 | gasoline constituents eluting present time. BTEX+MTBE by 8260B | rior to the C6 | (n-hexane) TPH-GF | RO range | | |
| 02010 05401 05407 05415 06310 | Methyl Tertiary Butyl Bther Benzene Toluene Bthylbenzene Xylene (Total) | 1634-04-4 71-43-2 108-88-3 100-41-4 1330-20-7 | N.D. 21. 3. 3. | 0.5 0.5 0.5 0.5 | ug/1 ug/1 ug/1 ug/1 ug/1 | 1 1 1 1 |

GRD

| | | Laboratory | tory Chronicle Analysis | | | | |
|-------------------------|--|--|-------------------------|--|---|--------------------|--|
| CAT No. 01728 | Analysis Name TPH-GRO - Waters | Method N. CA LUFT Gasoline | Trial# 1 | Date and Time 08/28/2004 04:55 | Analys t Brian C Veety | Factor 5 | |
| 06054 01146 01163 | BTEX+MTBE by \$260B GC VOA Water Prep GC/MS VOA Water Prep | Method SW-846 8260B SW-846 5030B SW-846 5030B | 1 1 1 | 08/31/2004 15:55 08/28/2004 04:55 08/31/2004 15:55 | Anita M Dale Brian C Veety Anita M Dale | n.a. n.a. | |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW 4340467

MW-4-W-040823 Grab Water Facility# 90517 Job# 386420 MIT# 61D-1995 GRD

3900 Piedmont Ave Oakland T0600102248 MW-4 Collected:08/23/2004 10:15 by AS

Submitted: 08/27/2004 08:40 Reported: 09/01/2004 at 16:43

Discard: 10/02/2004

Account Number: 10904

ChevronTexaco c/o Cambria

Suite 9

4111 Citrus Avenue Rocklin CA 95677

48--4

| | | | | As Received | | |
|-------|--|-------------------------------------|-----------------------------------|----------------------|-------|----------|
| CAT | | | As Received | Method | | Dilution |
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01728 | TPH-GRO - Waters | n.a. | 5,100. | 500. | ug/l | 10 |
| | The reported concentration of question constituents eluting part time. | PPH-GRO does not orior to the C6 | include MTBE o (n-hexane) TPH- | r other GRO range | | |
| 06054 | BTEX+MTBE by 8260B | | | | | |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | 5. | 1. | ug/l | 2 |
| 05401 | Benzene | 71-43-2 | 100. | 1. | ug/l | 2 |
| 05407 | Toluene | 108-88-3 | 26. | 1. | ug/l | 2 |
| 05415 | Ethylbenzene | 100-41-4 | 7. | 1. | ug/l | 2 |
| 06310 | Xylene (Total) | 1330-20-7 | 43. | 1. | ug/l | 2 |

| | | Laboratory | Chro | nicle | | |
|-------|----------------------|-------------------------------|----------|------------------|---------------|--------|
| CAT | | | Dilution | | | |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor |
| 01728 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 08/28/2004 05:24 | Brian C Veety | 10 |
| 06054 | BTEX+MTBE by 8260B | SW-846 8260B | 1 | 08/31/2004 16:21 | Anita M Dale | 2 |
| 01146 | GC VOA Water Prep | SW-846 5030B | ı | 08/28/2004 05:24 | Brian C Veety | n.a. |
| 01163 | GC/MS VOA Water Pren | SW-846 5030B | 1 | 08/31/2004 16:21 | Anita M Dale | n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 2

Quality Control Summary

Client Name: ChevronTexaco c/o Cambria

Reported: 09/01/04 at 04:43 PM

Group Number: 909743

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Laboratory Compliance Quality Control

| Analysis Name | Blank <u>Result</u> | Blank MDL | Report <u>Units</u> | LCS <u>%REC</u> | LCSD *REC | Limits | RPD | RPD Max | |
|--|--|---|--|-------------------------------------|--------------|--|-----|---------|--|
| Batch number: 04240A08C TPH-GRO - Waters | Sample n | number(s): 50. | 4340463-43 ug/l | 40467 86 | 85 | 70-130 | 1 | 30 | |
| Batch number: Z04244ZAA Methyl Tertiary Butyl Ether Benzene Toluene Ethylbenzene Xvlene (Total) | Sample r N.D. N.D. N.D. N.D. | number(s): 0.5 0.5 0.5 0.5 0.5 | 4340463-43 ug/l ug/l ug/l ug/l ug/l | 40467 92 92 93 93 92 | | 77-127 85-117 85-115 82-119 83-113 | | | |

Sample Matrix Quality Control

| Analysis Name | ms <u>%rbc</u> | MSD %REC | MS/MSD <u>Limits</u> | RPD | RPD <u>MAX</u> | BKG Conc | DUP <u>Conc</u> | DUP <u>RPD</u> | Dup RPD Max |
|--|--------------------------------------|--------------------------------------|---|----------------------------------|----------------------------------|-------------|--------------------|-------------------|----------------|
| Batch number: 04240A08C TPH-GRO - Waters | Sample 97 | number | (s): 434046 63-154 | 3-43404 | 67 | | | | |
| Batch number: Z042442AA Methyl Tertiary Butyl Ether Benzene Toluene Ethylbenzene Xylene (Total) | Sample 92 93 96 97 94 | number 91 91 90 91 90 | (s): 434046 69-134 83-128 83-127 82-129 82-130 | 3-43404 1 3 6 6 5 | 67 30 30 30 30 30 | | | | |

Surrogate Quality Control

Analysis Name: TPH-GRO - Waters Batch number: 04240A08C

Trifluorotoluene-F

| 4340463 | 99 |
|---------|-----|
| 4340464 | 99 |
| 4340465 | 97 |
| 4340466 | 108 |
| 4340467 | 106 |
| Blank | 98 |
| LCS | 99 |
| LCSD | 100 |
| | |

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 2 of 2

Quality Control Summary

Client Name: ChevronTexaco c/o Cambria

Group Number: 909743

Reported: 09/01/04 at 04:43 PM

Surrogate Quality Control

| MS | 100 | Surroyate Quartey concret | | • |
|---------|--|---------------------------|------------|----------------------|
| Limits: | 57-146 | | | <u> </u> |
| | Name: BTEX+MTBE by 8260B DET: Z042442AA Dibromofluoromethane | 1,2-Dichloroethane-d4 | Toluene-d8 | 4-Bromofluorobenzene |
| 4340463 | 102 | 106 | 98 | 94 |
| 4340464 | 104 | 109 | 97 | 93 |
| 4340465 | 103 | 106 | 98 | 95 |
| 4340466 | 101 | 106 | 99 | 100 |
| 4340467 | 102 | 106 | 102 | 100 |
| Blank | 103 | 105 | 98 | 96 |
| LCS | 102 | . 105 | 98 | 97 |
| MS | 101 | 104 | 98 | 99 |
| MSD | 101 | 104 | 98 | 100 |
| Limits: | 81-120 | 82-112 | 85-112 | 83-113 |

*- Outside of specification

(1) The result for one or both determinations was less than five times the LOQ.

(2) The background result was more than four times the spike added.



Explanation of Symbols and Abbreviations

Inorganic Qualifiers

The following defines common symbols and abbreviations used in reporting technical data:

| N.D. TNTC IU umhos/cm C meq g ug ml m3 | none detected Too Numerous To Count International Units micromhos/cm degrees Celsius milliequivalents gram(s) microgram(s) milliliter(s) cubic meter(s) | BMQL Below Minimum Quantitation Level MPN Most Probable Number CP Units cobalt-chloroplatinate units nephelometric turbidity units degrees Fahrenheit lb. pound(s) kg kilogram(s) mg milligram(s) liter(s) ul microliter(s) | |
|--|---|--|--|
|--|---|--|--|

- less than The number following the sign is the <u>limit of quantitation</u>, the smallest amount of analyte which can be reliably determined using this specific test.
- > greater than
- J estimated value The result is ≥ the Method Detection Limit (MDL) and < the Limit of Quantitation (LOQ).</p>
- ppm parts per million One ppm is equivalent to one milligram per kilogram (mg/kg), or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter of gas per liter of gas.
- ppb parts per billion
- Dry weight basis

 Results printed under this heading have been adjusted for moisture content. This increases the analyte weight concentration to approximate the value present in a similar sample without moisture. All other results are reported on an as-received basis.

U.S. EPA CLP Data Qualifiers:

X,Y,Z

Organic Qualifiers

| A TIC is a possible aldol-condensation product B Analyte was also detected in the blank C Pesticide result confirmed by GC/MS D Compound quantitated on a diluted sample E Concentration exceeds the calibration range of the instrument N Presumptive evidence of a compound (TICs only) P Concentration difference between primary and confirmation columns >25% U Compound was not detected Defined in case narrative | B Value is <crdl, (msa)="" <0.995<="" additions="" analysis="" but="" calculation="" coefficient="" compound="" control="" correlation="" detected="" digestion="" due="" duplicate="" e="" estimated="" for="" injection="" interference="" limits="" m="" met="" method="" msa="" n="" not="" of="" out="" post="" precision="" sample="" spike="" standard="" th="" to="" u="" used="" w="" was="" within="" ≥idl=""></crdl,> |
|--|--|
|--|--|

Analytical test results for methods listed on the laboratories' accreditation scope meet all requirements of NELAC unless otherwise noted under the individual analysis.

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff. This report shall not be reproduced except in full, without the written approval of the laboratory.

WARRANTY AND LIMITS OF LIABILITY - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL LANCASTER LABORATORIES BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF LANCASTER LABORATORIES AND (B) WHETHER LANCASTER LABORATORIES HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Lancaster Laboratories which includes any conditions that vary from the Standard Terms and Conditions of Lancaster Laboratories and we hereby object to any conflicting terms contained in any acceptance or order submitted by client.