



2/7/96
SUMP AREA 575
Pasco Grande
San Lorenzo
A



2/7/96
AREA C 575 Pasco Grande
San Lorenzo



2/7/96
AREA B 575 Pasco Grande
San Lorenzo



2/7/96
AREA D 575 Pasco Grande
San Lorenzo



View of former pump island/pipe trench OE area.
Looking Northwest. 12/14/95



View of add'l pump discovered during OE activities looking east. 12/14/95



Looking South. Add'l pump discovered during OE activities. May believe it may lead to a w/o VST. 12/14/95
View of OE area of former pump

575 Paseo Grande
San Lorenzo CA


6/5/95



Foreground Abandoned JST Pit
Background Pipe Trench to dispenser

575 Paseo Grande
San Lorenzo CA

6/5/95



Grease Sump Pit

575 Paseo Grande
San Lorenzo CA

6/5/95



Grease Pit

575 Paseo Grande

575 Paseo Grande
San Lorenzo CA

6/5/95



Grease Sump Pit

575 Paseo Grande
San Lorenzo CA

6/5/95



UST Pit

575 Paseo Grande
San Lorenzo CA

6/5/95



UST pit filled in w/ backfill
material

6/5/95



4" Cast iron pipe discovered in
pipe trench

575 Paseo Grande
San Lorenzo CA