ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY



ALEX BRISCOE, Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

April 29, 2014

Ms. Jan Shipley (Sent via E-mail to: JShipley@lvjusd.k12.ca.us)
Livermore Unified School District
685 E. Jack London Blvd.
Livermore, CA 94550

Subject: Case Closure for Fuel Leak Case No. RO0000188 and GeoTracker Global ID T0600100844, Laidlaw Transit (Maintenance Yard), 2900 Ladd Avenue, Livermore, CA 94550

Dear Ms. Shipley:

This letter transmits the enclosed underground storage tank (UST) case closure letter in accordance with Chapter 6.75 (Article 4, Section 25296.10[g]). The State Water Resources Control Board adopted this letter on February 20, 1997. As of March 1, 1997, the Alameda County Environmental Health (ACEH) is required to use this case closure letter for all UST leak sites. We are also transmitting to you the enclosed case closure summary. These documents confirm the completion of the investigation and cleanup of the reported release at the subject site. The subject fuel leak case is closed. This case closure letter and the case closure summary can also be viewed on the State Water Resources Control Board's Geotracker website (http://geotracker.swrcb.ca.gov) and the Alameda County Environmental Health website (http://www.acgov.org/aceh/index.htm).

If you have any questions, please call Jerry Wickham at (510) 567-6791. Thank you.

Sincerely,

Dilan Roe, P.E.

LOP and SCP Program Manager

Enclosures:

1. Remedial Action Completion Certification

Case Closure Summary

Cc w/enc.:

Danielle Stefani, Livermore Pleasanton Fire Department, 3560 Nevada St, Pleasanton, CA 94566 (Sent via E-mail to: dstefani@lpfire.org)

Colleen Winey (QIC 8021), Zone 7 Water Agency, 100 North Canyons Pkwy, Livermore, CA 94551 (Sent via E-mail to: cwiney@zone7water.com)

City of Livermore Planning Division, 1052 South Livermore Avenue, Livermore, CA 94550 (Sent via E-mail to: planning@cityof livermore.net)

Ms. Jan Shipley RO0000188 April 29, 2014 Page 2

Julia Siudyla, ACC Environmental Consultants, 7977 Capwell Drive, Oakland, CA 94621 (Sent via E-mail to: jsiudyla@accenv.com)

Jerry Wickham, ACEH (Sent via E-mail to: jerry.wickham@acgov.org)

GeoTracker, eFile

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

ALEX BRISCOE, Agency Director



DEPARTMENT OF ENVIRONMENTAL HEALTH
OFFICE OF THE DIRECTOR
1131 HARBOR BAY PARKWAY
ALAMEDA, CA 94502
(510) 567-6777
FAX (510) 337-9135

REMEDIAL ACTION COMPLETION CERTIFICATION

April 29, 2014

Ms. Jan Shipley (Sent via E-mail to: <u>JShipley@lvjusd.k12.ca.us</u>)
Livermore Unified School District
685 E. Jack London Blvd.
Livermore, CA 94550

Subject: Case Closure for Fuel Leak Case No. RO0000188 and GeoTracker Global ID T0600100844, Laidlaw Transit (Maintenance Yard), 2900 Ladd Avenue, Livermore, CA 94550

Dear Ms. Shipley:

This letter confirms the completion of a site investigation and remedial action for the underground storage tanks formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this agency was accurate and representative of site conditions, this agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25296.10 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.3 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

Please be aware that claims for reimbursement of corrective action costs submitted to the Underground Storage Tank Cleanup Fund more than 365 days after the date of this letter or issuance or activation of the Fund's Letter of Commitment, whichever occurs later, will not be reimbursed unless one of the following exceptions applies:

- · Claims are submitted pursuant to Section 25299.57, subdivision (k) (reopened UST case); or
- Submission within the timeframe was beyond the claimant's reasonable control, ongoing work is
 required for closure that will result in the submission of claims beyond that time period, or that under the
 circumstances of the case, it would be unreasonable or inequitable to impose the 365-day time period.

This notice is issued pursuant to subdivision (g) of Section 25296.10 of the Health and Safety Code. Please contact our office if you have any questions regarding this matter.

Sincerely.

Ariu Levi Director

CASE CLOSURE SUMMARY LEAKING UNDERGROUND FUEL STORAGE TANK - LOCAL OVERSIGHT PROGRAM

I. AGENCY INFORMATION

Date: September 30, 2013

Agency Name: Alameda County Environmental Health	Address: 1131 Harbor Bay Parkway				
City/State/Zip: Alameda, CA 94502-6577	Phone: (510) 567-6791				
Responsible Staff Person: Jerry Wickham	Title: Senior Hazardous Materials Specialist				

II. CASE INFORMATION

Site Facility Name: Laidlaw Transi	t	*******			
Site Facility Address: 2900 Ladd A	venue, Livermore, CA 94550				
RB Case No.: 01-0919	Local Case No.: StID 3095	LOP Cas	P Case No.: RO0000188		
URF Filing Date: 9/6/1990	Geotracker ID: T0600100844	APN: 098-0264-001-17			
Responsible Parties	Addresses		Phone Numbers		
Jan Shipley Livermore Valley Unified School District	685 East Jack London Blvd. Livermore, CA 94551-1855		(925) 606-3390		

Tank I.D. No	ank I.D. No Size in Gallons Contents		Closed In Place/Removed?	Date		
1	6,000	Unleaded gasoline	Removed	8/6/1992		
2	6,000	6,000 Low leaded gasoline		8/6/1992		
3	10,000 Diesel		3 10,000 Diese		Removed	8/6/1992
	Piping		Removed	8/4/1992		

III. RELEASE AND SITE CHARACTERIZATION INFORMATION

Cause and Type of Release: Unknown. Three holes were observed in the 6,000-gallon leaded gasoline tank; however, two of the holes appeared to be punctures caused by a drilling operation to collect soil and groundwater samples. The fuel had been removed prior to the drilling. The third hole in the tank was caused by backfilling of soil. Soil staining was evident around the fill pipe of the diesel tank and directly beneath the diesel and unleaded gasoline dispensers.

Site characterization complete? Yes	Date Approved By Oversigh	Date Approved By Oversight Agency:				
Monitoring wells installed? Yes	Number: 6	Proper screened interval?				
Highest GW Depth: 12 fbgs	Lowest GW Depth: 57 fbgs	Flow Direction: West northwest to northwest				
Most Sensitive Current Use: Drinking water	er					

Summary of Production Wells in Vicinity: Two active municipal water supply wells are within ½ mile of site. The nearest municipal water supply well (California Water Service Well 12-01) is located approximately 1,400 feet south of the site. Based on the upgradient location and distance from the site, the well is not expected to be a receptor for the site. A second municipal water supply well is located approximately 2,500 feet west northwest of the site. Based on the distance from the site, the second municipal water supply well is also not expected to be a receptor for the site. Cal Water Service well CWS-17 was a municipal supply well located approximately 500 feet southeast of the site. Well CWS-17 was reported decommissioned in February 2013 and therefore, is not a receptor for the site.

Are drinking water wells affected? No	Aquifer Name: Mocho II Subbasin of Livermore-Amador Valley Groundwater Basin
Is surface water affected? No	Nearest SW Name: Arroyo Mocho Creek is approximately 6,200 feet south of the site.
Off-Site Beneficial Use Impacts (Addresses/I	_ocations): None identified.
Reports on file? Yes	Where are reports filed? Alameda County Environmental Health and Livermore-Pleasanton Fire Department

Material	Amount (Include Units)	Action (Treatment or Disposal w/Destination)	Date	
	6,000 gallon leaded gasoline			
Tanks	10,000 gallon diesel	Transported to H & H Ship Service Company at 220 China Basin Street, San Francisco, CA 94107	8/6/1992	
6,000 gallon unleaded gasoline				
Piping	Approximately 60 feet	Disposal destination not reported	8/5/1992	
Soil	40 yd ³	Disposal destination not reported. Soil is from excavation activities that took place on August 5 and 27, 1992.	8/5 and 8/27/1992	
Groundwater				

MAXIMUM DOCUMENTED CONTAMINANT CONCENTRATIONS BEFORE AND AFTER CLEANUP (Please see Attachments 3 - 5 for additional information on contaminant locations and concentrations)

Contaminant	Soil	(ppm)	Water (ppb)		
Containinant	Before	After	Before	After	
TPH (Gas)	2,700	300	92,000 ¹	25,000 ¹	
TPH (Diesel)	120	120	<50	<50	
TPH (Oil and Grease)	All hel has som		# to to		
Benzene	9.8	2.3	12,000 ²	3,100 ²	
Toluene	79	12	16,000 ²	480 ²	
Ethylbenzene	38	4.8	1,700 ²	2,400 ²	
Xylenes	220	31	11,000 ²	4,800 ²	
Heavy Metals (Cd, Cr, Pb, Ni, Zn)	12 ³	12 ³			
MTBE	<0.023 4	<0.023 4	20 ⁵	20 ⁵	
Other (8240/8270)					
			L	I	

- (1) The maximum concentration before cleanup is from a groundwater sample from well MW-5 on 09/21/2000; the maximum concentration after cleanup is from a groundwater sample collected from well MW-5 during the most recent groundwater monitoring event on 06/13/2013.
- (2) The maximum concentration before cleanup is from a grab groundwater sample collected from boring "A" on 06/30/1994; the maximum concentration after cleanup is from a groundwater sample collected from well MW-5 during the most recent groundwater monitoring event on 06/13/2013.
- (3) Total lead = 12 ppm; no other metals analyzed.
- (4) MTBE <0.023 ppm; EDB and EDC <0.005 pm; TBA, DIPE, TAME, ETBE, and ethanol not analyzed.
- (5) MTBE = 20 ppb; EDB, EDC, TBA, DIPE, TAME, ETBE, and ethanol not analyzed.

Site History and Description of Corrective Actions:

The site is currently part of the maintenance yard for the Livermore Valley Joint and Unified School District. Three former underground storage tanks (USTs) and dispensers that were removed in August 1992, were used in conjunction with the Maintenance Building. The former USTs and dispensers are bordered by a parking lot, sports fields, the Maintenance Building, and a hockey rink. Surrounding properties include residential and school properties. The Ladd School building is located approximately 235 feet southwest of the former USTs and dispensers. The Junction Avenue K-8 School buildings are located approximately 500 feet west of the former USTs and dispensers.

Depths to groundwater vary seasonally and have historically been measured between 12 and 57 fbgs. A seasonal perched zone has been encountered typically at a depth of roughly 20 fbgs in the area surrounding B-5/MW-2 and MW-5. Groundwater flows towards the west northwest to northwest.

In mid-1990, a leaded gasoline tank at the property failed a precision test. On July 25, 1990, an exploratory boring was angled beneath the tank to a depth of 17 vertical feet below ground surface (fbgs). Soil samples collected from the boring contained 2,300 parts per million (ppm) total petroleum hydrocarbons as gasoline (TPHg) at 14 fbgs and 1,500 ppm TPHg at 17 fbgs. Xylenes were also detected at 220 ppm and 140 ppm in the 14 and 17 fbgs samples, respectively. Groundwater was not encountered during the drilling event.

Three exploratory borings (B-1, B-2, and MW-1) were advanced on December 13, 1990, with one boring converted into a groundwater monitoring well. A total of nine soil samples and one groundwater sample were collected during this event. The south end of the empty 6,000 gallon leaded gasoline tank was punctured during drilling due to incorrect plotting of the UST. Three to four cubic yards of pea gravel backfill emptied into the punctured tank. Groundwater was first encountered at 57 fbgs and rose approximately 10 feet after drilling. MW-1 was installed December 14, 1990 to the northwest of the USTs. Soil samples collected from the monitoring well boring contained 2,700 ppm TPHg, 8.1 ppm benzene, and 52 ppm xylenes at depths between 16 and 36 fbgs. The groundwater sample contained 1,400 parts per billion (ppb) TPHg, 63 ppb benzene, 8.0 ppb ethylbenzene, 52 ppb toluene, and 590 ppb xylenes.

Three tanks were removed from 2900 Ladd Avenue on August 6, 1992. Upon removal, three holes were visible in the 6,000 gallon leaded gas tank. The holes were caused by previous boring and excavation activities when the tank was empty. Petroleum odor and elevated OVM readings were noted in native soil at the northern ends of the diesel and leaded gasoline tank. Soil staining was also noted around the fill pipe of the diesel tank. Soil samples were collected from native soil beneath the tanks, piping, and dispenser pumps. No groundwater was encountered during the excavation.

Six exploratory soil borings (B-3 through B-8) were advanced on April 9, 1993. Soil samples were collected at approximate five-foot intervals through the vadose zone. Soil boring B-5 was converted into monitoring well MW-2. The borings indicated that soil and groundwater northwest of the former USTs is impacted by petroleum hydrocarbons with the highest concentrations occurring from 18 to 35 fbgs. Soil samples collected from B-4 at a depth of 26 fbgs contained 2,300 ppm TPHg, 7.7 ppm benzene, 88 ppm toluene, 35 ppm ethylbenzene, and 210 ppm total xylenes. TPHd was detected at a concentration of 120 ppm in soil sample B6-2, collected to the west of the former diesel UST. The groundwater sample collected from the newly installed MW-2 contained 4,500 ppb TPHg, 340 ppb benzene, 110 ppb toluene, 8.0 ppb ethylbenzene, and 630 ppb total xylenes. TPHd was not detected in the groundwater sample. Groundwater elevations during the 1993 investigation were reported to be 15 feet higher (approximately 35 fbgs) than during the 1992 site investigation. Soil lithology was observed to be sandy gravel interstratified with clayey to sandy silt. Significant contamination was encountered in the sandy gravel layer found between 20 and 32 fbgs.

Site History and Description of Corrective Actions (continued):

In July 1994, additional site investigation including the installation of two additional monitoring wells (MW-3 and MW-4) was conducted. Grab groundwater samples from boring B10 and pilot test hole "A" contained TPHg and benzene at concentrations up to 70,000 ppb and 12,000 ppb, respectively. A perched groundwater zone was encountered at approximately 20 fbgs in borings B-9, B-10, and MW-4. The highest concentrations of petroleum hydrocarbons in soil were detected in a soil sample collected at a depth of 20 feet from boring B-4.

One additional monitoring well (MW-5) was installed between June 28 and August 1, 2000. A groundwater sample collected from MW-5 contained 92,000 ppb TPHG, 9,900 ppb benzene, 15,000 ppb toluene, 540 ppb ethylbenzene, and 17,000 ppb total xylenes. MTBE was analyzed but not detected at concentrations above the reporting limit.

Between September 12 and 16, 2011, eight soil borings (ACC-1 through ACC-8) were advanced to a maximum depth of 65 fbgs. Soil samples were collected for laboratory analysis at 5 to 10 foot intervals with additional samples collected at first encountered groundwater, lithologic changes, and zones exhibiting impact from petroleum hydrocarbons. Grab groundwater samples were collected from the first encountered groundwater in each boring. Petroleum hydrocarbons were detected in groundwater samples from ACC-3, ACC-4, and ACC-5. The grab groundwater sample from ACC-4 contained 14,000 ppb TPHg, 1,500 ppb benzene, 1,900 ppb toluene, 500 ppb ethylbenzene, and 4.5 ppb MTBE. In order to further define the vertical extent of contamination three cone penetrometer borings were completed adjacent to borings ACC-2, ACC4, and ACC-5. A membrane interface probe was used in the three CPT borings to collect continuous information on the vertical distribution of petroleum hydrocarbons.

Monitoring wells MW-2, MW-3, and MW-4 were decommissioned on April 9 and 10, 2013. On April 9, 2013, well MW-6A was installed approximately 20 feet southeast of the former USTs and product lines for use as a remediation well. A dual-phase extraction (DPE) pilot test was conducted from April 15 through April 17, 2013. Based on vapor readings from wells MW-5 and MW-6, approximately 11 gallons of hydrocarbons were removed during the 48-hour DPE pilot test.

Groundwater monitoring events have been conducted on 14 separate occasions since 1991. The concentrations of petroleum hydrocarbons in groundwater have decreased over time.

IV. CLOSURE

Does completed corrective action protect existing beneficial uses per the Regional Board Basin Plan? Yes

Does completed corrective action protect potential beneficial uses per the Regional Board Basin Plan? Yes

Does corrective action protect public health for current land use? Alameda County Environmental Health staff does not make specific determinations concerning public health risk. However, based upon the information available in our files to date, closure of this site appears to be consistent with the policies established by the State Water Resources Control Board Low-Threat Underground Storage Tank Closure Policy which became effective on August 17, 2012.

Site Management Requirements: This fuel leak case has been evaluated for closure consistent with the State Water Resources Control Board Low-Threat Underground Storage Tank Closure Policy (LTCP). Based on this evaluation, no site management requirements appear to be necessary.

Should corrective action be reviewed if land u	se changes? No	
Was a deed restriction or deed notification file	ed? No	Date Recorded:
Monitoring Wells Decommissioned: No	Number Retained: 2	
List Enforcement Actions Taken: None		
List Enforcement Actions Rescinded:		

V. ADDITIONAL COMMENTS, DATA, ETC.

Considerations and/or Variances:

The site meets the general criteria for case closure under the LTCP.

The site appears to meet scenario 1 of the groundwater media-specific criteria for closure under the LTCP based on the following:

- 1. The plume is stable or decreasing in size.
- 2. The plume is less than 100 feet in length.
- 3. There is no free product.
- 4. No water supply wells or surface water bodies are within 250 feet of the plume boundary.

The site does not appear to meet any of the scenarios of the numerical media-specific criteria in the LTCP for petroleum vapor intrusion to indoor air for the following reasons:

- 1. No soil vapor sampling has been completed.
- 2. The concentration of benzene in groundwater exceeds 1,000 ppb.

Although the site does not meet scenarios 1 through 4 of the numerical media-specific criteria in the LTCP for petroleum vapor intrusion to indoor air, ACEH believes the site-specific conditions do not pose a significant risk of vapor intrusion to indoor air for the following reasons:

- 1. The residual contamination appears to be limited to depths below 13 fbgs. There is a continuous zone with TPH concentrations below 100 ppm that provides a separation of more than 10 feet vertically between the residual contamination and the foundation of existing buildings and likely future buildings. Therefore, the site is considered to have a bioattenuation zone.
- 2. The depth to groundwater is typically greater than 20 fbgs.
- 3. The age of the release is greater than 20 years.
- 4. Detections of benzene in groundwater at concentrations exceeding 1,000 ppb are limited to monitoring well MW-5.

The site appears to meet the media-specific criteria for direct contact and outdoor air exposure under the LTCP. The maximum concentrations of benzene and ethylbenzene detected in soil samples collected to date within the upper 10 feet are less than the media-specific criteria in Table 1 of the LTCP for direct contact and outdoor air exposure. Since the release at the site consisted primarily of gasoline, napthalene concentrations are not likely to exceed the media-specific criteria in Table 1 of the LTCP.

Conclusion:

Alameda County Environmental Health staff believe that the site meets the conditions for case closure under the State Water Resources Control Board Low-Threat Underground Storage Tank Closure Policy. Based upon the information available in our files to date, no further investigation or cleanup for the fuel leak case is necessary at this time.

VI. LOCAL AGENCY REPRESENTATIVE DATA

Prepared by: Jerry Wickham, P.G.	Title: Senior Hazardous Materials Specialist
Signature: Surn Wishelm	Date: 10/09/13
Approved by: Donna Drogos, P.E.	Title: Division Chief
Signature:	Date: 10/9/13
	/

This closure approval is based upon the available information and with the provision that the information provided to this agency was accurate and representative of site conditions.

VII. REGIONAL BOARD NOTIFICATION

Regional Board Staff Name:	Cherie McCaulou	Title: Engineering Geologist
Notification Date:	107/13	

VIII. MONITORING WELL DECOMMISSIONING

Date Requested by ACEH: 01/08/14	Date of Well Decommissioning Rep	port: 04/18/14
All Monitoring Wells Decommissioned: $\frac{1}{2}$	Number Decommissioned: 2	Number Retained:
Reason Wells Retained: N		
Additional requirements for submittal of groundwa	ter data from retained wells: No	ne
ACEH Concurrence - Signature:	Wichlam	Date: 04/29/14

Attachments:

- 1. Site Maps (2 pp)
- 2. Site Plans (3 pp)
- 3. Chemical Concentration Maps and Cross Sections (6 pp)
- 4. Soil Analytical Data (3 pp)
- 5. Groundwater Analytical Data (4 pp)
- 6. Boring Logs (62 pp)

This document and the related CASE CLOSURE LETTER & REMEDIAL ACTION COMPLETION CERTIFICATE shall be retained by the lead agency as part of the official site file.



Source: Google Earth, 2011

Title Site Location Map 2900 Ladd Avenue Livermore, California

An Employee Owned Company


Figure Number: 1 Scale: None

Project Number: 3054-103.01 Drawn By: JS

Date: 4/7/11

N
ENVIRONMENTAL
CONSULTANTS

ENVIRONMENTAL



Title Site Plan 2900 Ladd Avenue Livermore, California

Figure Number: 2

Drawn By: JS

Project Number: 3054-103.01


Date:4/6/11





W SE


0' 37.5' 75'


Scale


























TABLE 1 Soil Analytical Summary Table 2900 Ladd Avenue Livermore, California ACC Project Number: 3054-103.01

		Constituents & Concent								entrations mg/kg			
	Sampling Depth / Interval - Feet Below Ground Surface (bgs)	Sampling Date	Matrix	ТРИВ	PH4T	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Lead		
6A-5'	5	4.11.13	soil	ND<1.0	ND<10	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.05			
6A-10'	10	4.11.13	soil	ND<1.0	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.05	-		
6A-15'	15	4.11.13	soil	ND<1.0	ND<1.0	ND<0.005	ND<0.005	ND<0.005	ND<0.005	ND<0.05	_		
6A-20'	20	4.11.13	soil	ND<1.0	ND<2.5	0.018	0.0053	0.014	0.013	ND<0.05	-		
6A-25'	25	4.11.13	soil	ND<1.0	ND<1.0	0.10	0.020	0.020	0.029	ND<0.05	_		
ACC1 (13.5-15')	13.5-15	12-Sep-11	Soll (mg/kg)	<0.240	NT	<0.0049	<0.0049	<0.0049	<0.0098	<0.0049	NT		
ACC1 (33.5-35')	33.5-35	12-Sep-11	Soll (mg/kg)	<0.130	NT	<0.0027	<0.0027	<0.0027	<0.0053	<0.0027	N ¹		
ACC2 (18.5-20')	18.5-20	13-Sep-11	Soil (mg/kg)	<0.120	NT	<0.0024	<0.0024	<0.0024	<0.0048	<0.0024	ΝΊ		
ACC2 (38.5-40')	38.5-40	13-Sep-11	Soil (mg/kg)	<0.120	NT	<0.0024	<0.0024	<0.0024	<0.0048	<0.0024	NT		
ACC3 (8.5-10')	8.5-10	14-Sep-11	Soil (mg/kg)	<0.120	NT	<0.0023	<0.0023	<0.0023	<0.0046	<0.0023	N ⁻		
ACC3 (18.5-20')	18.5-20	14-Sep-11	Soll (mg/kg)	0.52	NT	0.046	0.0047	0.027	0.097	<0.0021	N		
ACC3 (23.5-25')	23.5-25	14-Sep-11	Soil (mg/kg)	270	NT	<2	2.7	<2	31	<2	N ¹		
ACC3 (33.5-35')	33.5-35	14-Sep-11	Soll (mg/kg)	<0.110	NT	<0.0023	0.0024	<0.0023	0.0074	<0.0023	N1		
ACC4 (8.5-10')	8.5-10	14-Sep-11	Soll (mg/kg)	<0.110	NT	<0.0022	<0.0022	<0.0022	<0.0045	<0.0022	N7		
ACC4 (23.5-25')	23.5-25	14-Sep-11	Soil (mg/kg)	240	NT	2.3	12	2.8	24	<2.3	N.		
ACC4 (43.5-45')	43.5-45	14-Sep-11	Soil (mg/kg)	0.58	NT	0.02	0.051	0.001	0.058	<0.0047	N ¹		
ACC5 (18.5-20')	18.5-20	15-Sep-11	Soil (mg/kg)	300	NT	1.2	8.7	4.8	30	<1.1	N		
ACC5 (38.5-40')	38.5-40	15-Sep-11	Soil (mg/kg)	<0.098	NT	<0.002	<0.002	<0.002	<0.0039	<0.002	N1		
ACC6 (33.5-35')	33.5-35	15-Sep-11	Soll (mg/kg)	<0.094	NT	<0.0019	<0.0019	<0.0019	<0.0038	<0.0019	N ¹		
ACC7 (13.5-15')	13.5-15	16-Sep-11	Soil (mg/kg)	<0.110	NT	<0.0023	<0.0023	<0.0023	<0.0045	<0.0023	N1		
ACC7 (38.5-40')	38.5-40	16-Sep-11	Soll (mg/kg)	<0.120	NT	<0.0024	<0.0024	<0.0024	<0.0048	<0.0024	N		
ACC8 (5-6.5')	5-6.5	16-Sep-11	Soil (mg/kg)	<0.110	NT	<0.0022	<0.0022	<0.0022	<0.0044	<0.0022	N1		
ACC8 (43.5-45')	43.5-45	16-Sep-11	Soil (mg/kg)	<0.120	NT	<0.0023	<0.0023	<0.0023	<0.0047	<0.0023	N1		
B1-2	16	13-Dec-90	Soll (mg/kg)	1.1	NT	0.18	0.036	0.0053	0.032	NT	N1		
B1-3	21	13-Dec-90	Soil (mg/kg)	1.5	NT	0.16	0.071	0.0081	0.051	NT	NI		
B1-5	31	13-Dec-90	Soil (mg/kg)	ND	NT	0.013	ND	ND	ND	NT	N1		
B1-11	44	13-Dec-90	Soil (mg/kg)	ND	NT	0.004	ND ND	ND	ND	NT	NT		
B2-2	16	13-Dec-90	Soil (mg/kg)	ND	NT	0.016	0.0026	ND	ND	NT	NI		
MW1-2	16	13-Dec-90	Soil (mg/kg)	970	NT	8.1	27	13	27	NT	רא		
MW1-4	26	13-Dec-90	Soil (mg/kg)	1,000	NT	ND	27	10	53	NT -	NT		
MW1-6	36	13-Dec-90	Soil (mg/kg)	2,700	NT	ND	27	10	53	NT	III		
MW1-8	46	13-Dec-90	Soll (mg/kg)	ND	NT	0.001	0.004	ND	0.0099	NT	NI		
EB-1, No. 2	14	25-Jul-90	Soll (mg/kg)	2,300	NT	9.8	79	38	220	NT	N		
EB-1, No. 3	17	25-Jul-90	Soll (mg/kg)	1,500	NT	7.3	54	22	140	NT	IN		
T2-1N	11.5	6-Aug-92	Soil (mg/kg)	ND	37	ND ND	ND ND	ND	ND.	NT	N1		
T2-1S	12	6-Aug-92	Soil (mg/kg)	NT	ND	ND	ND	ND	ND ND	NT	10,000		
T3-1N	11.5	6-Aug-92	Soil (mg/kg)	ND	Nt	ND	ND	ND ND	ND ND	NT NT	N1 N1		
T3-1S	12	6-Aug-92	Soil (mg/kg)	ND	NT	ND	ND	ND	ND ND	NT NT	NI NI		
T4-1N	11.5	6-Aug-92	Soil (mg/kg)	1,200	NT	2.1	4.2	2.4	160	NT NT	12		
T4-1S	12	6-Aug-92	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT NT			
PL-1	4	6-Aug-92	Soll (mg/kg)	ND	ND	ND	ND	ND ND	ND	NT NT	8.2 NT		
PL-2	4	6-Aug-92	Soil (mg/kg)	ND	ND	ND	ND	ND	ND ND				
DP-1	3.75	6-Aug-92	Soil (mg/kg)	NT	46	ND	ND ND	ND	ND ND	NT NT	NT NT		
RULP-1	3.5	6-Aug-92	Soil (mg/kg)	3	NT	ND	ND	0.0074	0.013	NT NT	12		
RLP-1	3.75	6-Aug-92	Soil (mg/kg)	ND	NT	ND	ND	0.0074 ND	0.013 ND				
	5.70	Shallow Soil	Land Land		2-1-1		7.0000	Twee College	100000	NT	NT		
SLs - Groundwater is a	Residential Land Use -	(≤3 m) Deep Soil	Soil (mg/kg) Soil (mg/kg)	83	83 83	0.044	2.9	3.27	2.26	0.023	750		
rent source of drinking water		(>3 m) Shallow Soil		0.00		NAMES AND		710000 11	3.7332	10///2/20			
	Commercial / Industrial Land Use	(< 3 m) Deep Soil	Soil (mg/kg)	83	83	0.044	2.9	3.27	2.26	0.023	75		
		(>3 m)											
PRG's		Residential	Soil (mg/kg)	NA	NA	1.1	5,000	5.4	630	43	400		
and the second		Commercial	Soil (mg/kg)	NA	NA	5.4	46,000	27	2,700	220	800		
alifornia Human Health		Residential	Soil (mg/kg)	NA	NA	NA	NA	NA	NA	NA	80		

TABLE 1 Soil Analytical Summary Table 2900 Ladd Avenue Livermore, California ACC Project Number: 3054-103.01

				Constituents & Concentrations mg/kg							
Boring / Sample ID	Sampling Depth / Interval - Feet Below Ground Surface (bgs)	Sampling Date	Matrix	тРН9	ТРН	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	Lead
B4-2	21	9-Apr-93	Soil (mg/kg)	800	9.1	1.9	22	8.1	56	NT /	NT
B4-3	26	9-Apr-93	Soil (mg/kg)	2,300	ND	7.7	88	35	210	NT	NT
B4-4	30.5	9-Apr-93	Soil (mg/kg)	31	ND	0.051	0.64	3.5	2.4	NT	NT
B5-2	20.5	9-Apr-93	Soil (mg/kg)	790	ND	2.8	21	6.7	4,1	NT	NT
B5-3	25.5	9-Apr-93	Soil (mg/kg)	24	ND	0.052	0.62	3,3	2.2	NT	NT
B5-4	36	9-Apr-93	Soll (mg/kg)	1.1	ND	0.23	0.0083	ND	0.13	NT	NT
B5-5	41	9-Apr-93	Soil (mg/kg)	ND	ND	ND	ND	, ND	ND	NT	NT
B6-1	15.5	9-Apr-93	Soil (mg/kg)	860	46	ND	13	83	55	NT	NT
B6-2	21	9-Apr-93	Soil (mg/kg)	530	120	1.9	17	73	44	NT	NT
B6-3	26	9-Apr-93	Soil (mg/kg)	1,200	ND	4.1	39	150	100	NT	NT
B6-4	31	9-Apr-93	Soll (mg/kg)	410	ND	ND	4.5	35	22	NT	NT
B7-1	16	9-Apr-93	Soll (mg/kg)	670	ND	1.2	16	97	58	NT	NT
B7-2	21	9-Apr-93	Soil (mg/kg)	46	ND	0.19	1.3	6	3.6	NT	NT
B7-3	26	9-Apr-93	Soll (mg/kg)	480	ND	ND	6.7	40	25	NT	NT
B7-4	31	9-Apr-93	Soll (mg/kg)	65	ND	8.4	1.3	7.5	4.8	NT	NT
B8-2	21	9-Apr-93	Soil (mg/kg)	18	ND	1.6	3.1	3,3	2.2	NT	NT
B8-3	26	9-Apr-93	Soil (mg/kg)	ND	ND	0.08	0.77	0.11	0.73	NT	NT
B8-4	30.5	9-Apr-93	Soll (mg/kg)	ND	ND	0.05	0.20	0.005	0.37	NT	NT
MW3-1	10	1-Jul-94	Soll (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW3-2	15	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW3-3	20	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW3-4	25	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW3-5	30	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW3-6	35	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW3-7	40	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW4-1	10	1-Jul-94		ND	NT	ND					ļ
MW4-2	15	1-Jul-94	Soll (mg/kg)	26	NT	0.21	ND 0.75	ND 0.04	ND	NT	NT
MW4-3	20	1-Jul-94	Soll (mg/kg)	44	NT	0.21	0.75	0.21	1.4	NT	NT
MW4-4	25		Soil (mg/kg)				0.70	0.28	2.3	NT NT	NT
MW4-5	30	1-Jul-94	Soll (mg/kg)	ND	NT	ND	ND	ND	ND	NT NT	NT
		1-Jul-94	Soll (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW4-6	35	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
MW4-7	40	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT NT	NT
MW4-8 B9-1	45	1-Jul-94	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	NT	NT
B9-2	15 20	1-Jul-94 1-Jul-94	Soil (mg/kg) Soil (mg/kg)	ND 640	NT NT	0.074	0.008	0.011	0.059	NT	NT
B9-3	25	1-Jul-94			NT	4.2	23	10 ND	70	NT	NT
B10-1	14	1-Jul-94	Soil (mg/kg)	ND	NT	0.12	0.013	ND 0.11	0.02	NT	NT
B10-2	18	1-Jul-94	Soil (mg/kg) Soil (mg/kg)	3 ND	NT	0.5 ND	ND	0.11 ND	0.62 ND	NT NT	NT NT
MW5-4	22	28-Jun-00	Soil (mg/kg)	ND	NT	ND	ND	ND	ND	ND	NT
	Residential Land Use	Shallow Soil (<3 m)	Soil (mg/kg)	83	83	0.044	2.9	2.30	2.26	0.023	200
*ESLs - Groundwater is a current source of drinking water		Deep Soil (>3 m) Shallow Soil	Soil (mg/kg)	83	83	0.044	2.9	3.27	2.26	0.023	750
wa(t)	Commercial / Industrial Land Use	(< 3 m) Deep Soil	Soil (mg/kg) Soil (mg/kg)	83 83	83	0.044	2.9	3.27	2.26	0.023	750
LUCKER TO THE		(>3 m) Residential	Soil (mg/kg)	NA	NA	1.1	5,000	5.4	630	43	400
PRG's		Commercial	Soil (mg/kg)	NA NA	NA NA	5.4	46,000	27	2,700	220	800
California Human Hartt		Residential	Soil (mg/kg)	NA NA	NA NA	NA	46,000 NA	NA NA	2,700 NA	NA NA	80
California Human Health creening Levels (CHHSLS)		anochaennel	Soil (mg/kg)	1050			The second	1000	100	IVA	60

NT: Not Tested; NM: Not Measured; NS: Not Sampled

*- No Data
Shadeded/Bolded Values Exceed Their Respective Criteria

^{***}ESLS = Bay Area Regional Water Quality Control Board Environmental Screening Levels (Interim Final May 2008), where Groundwater IS a Current Source of Drinking Water PRGs=EPA Region 9 Preliminary Remediation Goal (April 2009)

CHHSLS = California Human Health Screening Levels for Soil, Cal EPA (January 2005) (Lead Revision September 2009)

CHROMALAB, INC.

Environmental Laboratory (1094)

5 DAYS TURNAROUND

August 11, 1992

ChromaLab File No.: 0892044

ENGEO, INC.

Attn: Eric Harrell

RE: Five soil samples for Total Lead analysis

Project Name: LVJUSD UST REMOVAL

Project Number: N2-3174-FA

Date Sampled: Aug. 6, 1992 Date Extracted: Aug. 11, 1992

Date Submitted: Aug. 6, 1992 Date Analyzed: Aug. 11, 1992

RESULTS:

Sample I.D.	Lead (mg/Kg)
RLP-1	12
T1-1E	8.0
T1-1W	7.6
T4-1N	12
T4-1S	8.2

BLANK N.D.
SPIKE RECOVERY 90%
DUPLICATE SPIKE RECOVERY 89%
DETECTION LIMIT 2.5
METHOD OF ANALYSIS 3050/7420

ChromaLab, Inc.

Jack Kelly

Analytical Chemist

Eric Tam

Laboratory Director

Groundwater Analytical Summary Table 2900 Ladd Ave Livermore, CA

ACC Project Number: 3054-103.01

				Constituents and Concentrations (μg/L)						
Boring / Well ID	Sampling Date	Matrix	DTW (in feet)	ТЕРН-9	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE	
ACC-1	12-Sep-11	Water	39.5	<50	<0.50	<0.50	<0.50	<1.0	<0.50	
ACC-2	13-Sep-11	Water	48.5	<50	<0.50	<0.50	<0.50	<1.0	<0.50	
ACC-3	14-Sep-11	Water	39	4,100	170	260	100	1,000	20	
ACC-4	14-Sep-11	Water	41.15	14,000	1,500	1,900	500	2,500	4.5	
ACC-5	15-Sep-11	Water	43.5	100	1.7	8.9	4.4	19	<0.50	
ACC-6	15-Sep-11	Water	43.5	<50	<0.50	<0.50	<0.50	<1.0	<0.50	
ACC-7	16-Sep-11	Water	42.6	<50	<0.50	<0.50	<0.50	<1.0	<0.50	
ACC-8	16-Sep-11	Water	46.8	<50	<0.50	<0.50	<0.50	<1.0	<0.50	
MW-2	20-Apr-93	Water	30.81	4,500	340	110	. 8	630	NT	
10100-2	12-May-94	Water	31.12	7,000	520	220	35	410	NT	
	8-Feb-95	Water	28.04	170	8.9	4.5	2.1	17	NT	
	23-May-95	Water	17.77	<50	<0,5	<0.5	<0.5	<0.5	NT	
*	20-Sep-95	Water	25.55	8,400	2,500	1,200	180	940	NT	
	29-Dec-95	Water	20.91	640	0.7	<0.5	1.9	4.7	NT	
	1-Nov-96	Water	22,63	1,600	390	140	25	120	NT	
	29-Apr-97	Water	20.39	4,900	640	240	83	200	<250	
	5-Aug-99	Water	26.18	3,000	1,100	370	97	240	<25	
	1-Aug-00	Water	23.96	2,200	850	240	74	240	<50	
	18-Jan-02	Water	30.85	350	62	0.85	0.82	2.5	<5	
	2-Jul-02	Water	33,45			-				
	4-Dec-02	Water	36.21			 				
	31-Mar-11	Water	- <u>-</u>	<50	<0.5	<0.5	<0.5	<1	<0.5	
MW-3	12-Jul-94	Water	38.76	<50	<0.5	<0.5	<0.5	<0.5	NT	
WW-3	8-Feb-95	Water	27.08	<50	<0.5	<0.5	<0.5	<0.5	NT	
	23-May-95	Water	17.28	<50	<0.5	<0.5	<0.5	<0.5	NT	
	20-Sep-95	Water	25.06	<50	1.4	<0.5	<0.5	<0.5	NT	
	29-Dec-95	Water	20.25	50	1.8	<0.5	<0.5	<0,5	NT	
	1-Nov-96	Water	22.22	<50	<0.5	<0.5	<0.5	<0.5	NT	
	29-Apr-97	Water	20.05	<50	1.7	<0.5	<0.5	<0.5	<5	
	5-Aug-99	Water	26.07	<50	<0.5	<0.5	<0.5	<0.5	<5	
	20-Jul-00	Water	23.35	<50	1.4	3.6	<0.5	3.9	<5	
U	18-Jan-02	Water	30.5	<50	<.5	<0.5	<0.5	<0,5	<5	
	2-Jul-02	Water	33.53			-			l -	
**ESLs	Groundwater is a Current or Potential Source of Drinking Water	Water		100	1	40	30	20	5	
PRG's	MCLs	Water		NA	5	1,000	7,000	10,000	NA	

ACC Environmental Consultants, Inc. • 7977 Capwell Drive, Suite 100, Oakland, CA 94621 • (510) 638-8400 • Fax (510) 638-8404
Page 1 of 2

TABLE 2 Groundwater Analytical Summary Table 2900 Ladd Ave Livermore, CA ACC Project Number: 3054-103.01

				Col	nstituen	ts and Co	oncentra	ations (µ	g/L)
Boring / Well ID	Sampling Date	Matrix	DTW (in feet)	TEPH-9	Benzene	Toluene	Ethylbenzene	Total Xylenes	MTBE
MW-3	4-Dec-02	Water	36.35			-			
	31-Mar-11	Water		<50	<0.5	<0.5	<0.5	<1	<0.5
MW-4	12-Jul-94	Water	39.5	<50	<0.5	<0.5	<0.5	<0.5	NT
	8-Feb-95	Water	27.66	<50	<0.5	<0.5	<0.5	<0.5	NT
- 1	23-May-95	Water	17.68	60	<0.5	<0.5	<0.5	<0.5	NT
	20-Sep-95	Water	25.81	<50	<0.5	<0.5	<0.5	<0.5	NT
_	29-Dec-95	Water	20.9	<50	<0.5	<0.5	<0.5	<0.5	NT
	1-Nov-96	Water	22.84	<50	2.7	<0.5	<0.5	<0.5	NT
	29-Apr-97	Water	20.57	<50	2.6	<0.5	<0.5	<0.5	9.2
ĺ	5-Aug-99	Water	26.64	120	59.0	<0.5	<0.5	<0.5	19.0
İ	20-Jul-00	Water	23.91	97	21.0	6.8	0.66	4.6	11.0
	18-Jan-02	Water	NM	NS	NS	NS	NS	NS	NS
	2-Jul-02	Water				-			-
MW-5	21-Jul-00	Water	20.19	92,000	9,900	15,000	540	17,000	<1,300
	18-Jan-02	Water	23.61	63,000	5,900	10,000	1,900	15,000	<1,300
	2-Jul-02	Water	24.29	86,000	10,000	14,000	2,100	15,000	<1,300
	4-Dec-02	Water	24.35	72,000	8,500	11,000	1,600	10,000	<1,300
	31-Mar-11	Water		65,000	8,700	8,700	2,800	16,000	<500
	6.13.13	water	23.31	25,000	3,100	480	2,400	4,800	ND<50
MW-6A	4.12.13	water	23.28	1,800	230	66	81	140	ND<30
	6.13.13	water	26.35	PURGED	DRY (APPE	ROX 200 ml)	NO RECH	ARGE AFTE	R 24 HR
**ESLs	Groundwater is a Current or Potential Source of Drinking Water	Water		100	1	40	30	20	5
PRG's	MCLs	Water		NA	5	1,000	7,000	10,000	NA

Notes

**ESLs = Bay Area Regional Water Quality Control Board Environmental Screening Levels (Interim Final May 2008)

where Groundwater IS a Current or Potential Source of Drinking Water

PRGs=EPA Region 9 Preliminary Remediation Goal November 2009)

¹Metals analysis for these samples was run on unfiltered groundwater.

DTW: ;Depth to water (ft.) measured from top of casing (TOC).

NT: Not Tested; NM: Not Measured; NS: Not Sampled

*-- No Data

Shaded/Bolded Values Exceed Their Respective Criteria

Ground-water samples were collected for laboratory testing using a Voss Technologies dedicated polyethylene bailer. The samples were decanted with zero head space into 40-milliliter volatile organic analysis vials (VOA). Following collection, the samples were cooled in an ice chest until delivery under documented chain-of-custody to NET Pacific, in Santa Rosa, California. Sample collection, preservation, chain-of-custody procedures and equipment decontamination were performed in accordance with ENGEO's standard quality assurance/quality control procedures.

Chain-of-custody documents and the ground water sampling information form are included as an attachment to this report.

Laboratory Analysis

Laboratory analysis was performed in accordance with the test methods specified in the Tri-Regional Board Staff Recommendations for Preliminary Evaluation and Investigation of Underground Tank Sites (August 1990). The sample was analyzed for total volatile petroleum hydrocarbons as gasoline (EPA 8015/5030) and benzene, toluene, xylene and ethylbenzene (EPA 602).

Table I shows the results of the most recent sampling event, along with results from the December 1990 ground-water sampling event.

	TABLE I		
MW-1 Ground Water S	Sample Laboratory	Analyses	Summary

(Concentrations reported in parts per billion)

SAMPLING DATE	TVPH	BENZ	TOLN	EBENZ	XYLN
12/19/90	1,400	63	52	8.0	590
9/5/91	ND	ND	ND	ND	ND

ND: Non-Detectable



D. Laboratory Testing

The soil and ground-water samples selected for laboratory testing will be analyzed for Total Petroleum Hydrocarbons (TPH) as gasoline (EPA Test Methods 8015/5030 and 8020) and for benzene, toluene, xylene and ethyl benzene (BTEX) (EPA 602). The laboratory testing was performed in accordance with test methods specified in the Tri-Regional Board Staff Recommendations for Preliminary Evaluation and Investigation of Underground Tank Sites (August, 1990). Copies of the laboratory test results are included in the Appendix. Table I provides a summary of the laboratory test results.

TABLE I - water simples
Laboratory Analysis Summary
(Concentrations reported in parts per billion)

	NUMBER	DATE	TPHg	В	T	Е	X
	MW3	7/12/94	<50	< 0.5	< 0.5	< 0.5	< 0.5
	MW4	7/12/94	<50	< 0.5	< 0.5	< 0.5	< 0.5
·	B10 25	7/01/94	56,000	5,700	13,000	ND	13,000
?	"A" 44'	6/30/94	70,000	12,000	16,000	1,700	11,000

HP HP DATE:

07/25/90

LOG DESIGNATION _

LOGGED BY:

MC .

ELEVATION: None encountered WATER LEVEL:

Mobile Drill B-53, 8" Hollow Stem Auger

JOB: P90150

DEPTH, FEET	NOMINAL (1) DIAMETER, IN.	BLOWS /FOOT (2)	MOISTURE %	DRY DENSITY, PCF	SAMPLES	U.S.C.S.	SOIL OR ROOK DESCRIPTION	NOTES	/k
						PMT	3" Asphaltic Concrete over 8" Aggregate Base		
						CL	SILTY CLAY: Redish medium brown, very moist, slightly gravelly, no odor	OVM* = 0	•
5 -						GC	CLAYEY GRAVEL: Medium brown, damp, medium to coarse-grained	OVM = 0	
-							¥ *	e e	
								el :-	-
10 –		ж						OVM = 37	-
-		æ							
-	2.0	_	-	-	1		CLAYEY SANDY GRAVEL: Light brown, very moist, slight hydrocarbon odor	OVM = 37	
15									-
-	2.0	_		-	2		Strong gasoline odor, sample wet with product	OVM = 512	
4							e	a	٠
20_	2.0		_	_	3		as above	OVM = 738	•
								Boring Terminated At 20'	
							OVM: Denotes Organic Vapor Meter		•
-							,		

THE LOGS SHOW SUBSURFACE CONDITIONS AT THE DATES AND LOCATIONS INDICATED, AND IT IS NOT WARRANTED THAT THEY ARE REPRESENTATIVE OF SUBSURFACE CONDITIONS AT OTHER LOCATIONS AND TIMES.

() SAMPLER INSIDE DIAM.

12 1 140 M HAMMER - 30 INCH DROP.

IP) HYDRAULICALLY PUSHED



	æ	[<u>8</u>	DATE OF BORING: July 1, 1994	N S.P.T.	OVM	IN PI	ACE
рертн (беет)	SAMPLE NUMBER	OG, LOCATION AN	SURFACE ELEVATION: Approx. feet msl	BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTI	SAMPLE	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-0		22200	Dry GRAVEL, base rock.				
			Reddish brown, damp, sandy SILT.				
-			Changes to silty GRAVEL, little sand.	,			
			Brown, silty SAND with some fine to medium gravel, damp/dry.				
-5			Light brown, damp, silty SAND (fine to coarse) with some gravel.				
			Increase in gravel (gravel layer).				
- 10							
			Brown, damp, silty, fine to coarse SAND and fine to medium GRAVEL.		20		
			Increase in clay content. Brown, moist, clayey, fine to coarse SAND with some fine to medium gravel.				***************************************
-15	9-1		Brown, wet, fine to coarse SAND with fine to medium GRAVEL, little clay, little silt, slight odor.		19		
			Brown, wet, clayey SAND with fine to medium gravel.		50		
-20	9-2				66		
			Brown, wet, fine to coarse SAND with fine to medium GRAVEL, slight odor.		23		
			Increase in clay content. Clayey fine to coarse SAND, some fine to medium gravel.				
-25	9-3		Brown, slightly clayey fine to coarse SAND with fine to medium GRAVEL.		12		
			Bottom of boring at approximately 26.5 feet.				
-30			·				
EN	IGE	O	2900 LADD AVENUE	BORING NO.			FIGURE NO.
	RPORAT		LIVERMORE, CALIFORNIA	DATE: Marc			4
			, , , , , , , , , , , , , , , , , , , ,	JOB NO.: 31	/4-F7	L	


	es,	ND E	DATE OF BORING: July 1, 1994	N S.P.T.	OVM	IN P	LACE
ОЕРТН (FEET)	SAMPLE NUMBER	NG, LOCATION AN TYPE OF SAMPLE	SURFACE ELEVATION; Approx. feet msl	BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPT	SAMPLE	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-0 -		* 00	Light reddish brown, damp, fine to medium sandy				
-		0 0 0	SILT with fine to medium gravel. Increase in gravel.				
- 5		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Light brown, sandy SILT with fine to medium gravel.				
-			Fine to coarse SAND and fine to medium GRAVEL,				
- 10 -			Increase in moisture. Brown, slightly clayey, damp, fine to coarse SAND and fine to medium GRAVEL.				
-			Brown, moist, clayey fine to coarse SAND with fine to medium GRAVEL, moist to wet.				
-15	10-1		Mottled yellow-brown/gray-brown, moist, fine sandy SILT to silty fine SAND, moist (odor).		104		
			Fine sandy SILT, little fine gravel.				
-20	10-2		Brown moist to wet, fine interbeds of wet fine to coarse SAND with silt (moist).		22		
20			Bottom of boring at approximately 20 feet.				
-25 -							
-			·				
-30							
	NGE	O	2900 LADD AVENUE	BORING NO.			FIGURE NO.
EI	ORPORATI	ED	LIVERMORE, CALIFORNIA	JOB NO.: 31			5

	~	e	DATE OF BORING: July 1, 1994	N	OVM	IN PI	ACE
DEPTH (FEET)	SAMPLE NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	SURFACE ELEVATION: Approx. feet msl DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	READING P.I.D. (10.0eV) (parts per million)	DRY UNIT WEIGHT (PCF)	MOIST. CONTEN % DRY WEIGHT
,		Tun	Brown, silty LOAM	OFWIT DER		(FOL)	WEXOR
5		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Light brown, dry, sandy GRAVEL.				
10		4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			3		
15			Brown, clayey GRAVEL, moist/wet.				
20					14		
25		# & & & & & & & & & & & & & & & & & & &	Brown clayey GRAVEL, some fine to coarse sand, wet, slight hydrocarbon odor. Decrease in gravel.				
30			Wet, clayey, fine to medium GRAVEL with sand, hydrocarbon odor.		24		
EN	VGE/	0	2900 LADD AVENUE	BORING NO.			FIGURE NO.
	NGEO PROPORATED 2900 LADD AVENUE LIVERMORE, CALIFORNIA			DATE: March 1995			6


	~~··	<u>6</u> "	DATE OF BORING: July 1, 1994	N S.P.T.	OVM	IN P	LACE
рертн (рест)	SAMPLE NUMBER	OG, LOCATION AN	SURFACE ELEVATION: Approx. feet msl	BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTE	SAMPLE	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-30			Decrease in gravel clayey				
			Wet, odorous, clayey GRAVEL, gravelly CLAY.		58		
-35			Stiffer, sandy CLAY, wet, brown, odor.				
-40					37		
-			Brown, stiff, wet silty CLAY, little fine to medium gravel. Hydropunch samples collected from 44'-45'.		9		
-45			Bottom of boring at approximately 45 feet.		9		
-					E-		
-50							
-55							
1						}	
-60	,			Donnes	DITA		FIGURE
E INC	NGE	O	2900 LADD AVENUE	BORING NO			NO.
INC	ORPORAT		LIVERMORE, CALIFORNIA	JOB NO.: 31			6

-


Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	OPEI LOGO LOCA WOR	IPMENT: Hollow Stem Auger RATED BY: Gregg Drilling & Testing GED BY: Julia Siudyla & Gwen Santos ATION: 2900 Ladd Avenue, Livermore RK DATE: 9/12/2011 ING: ACC-1
10 YR 4/3 - Brown	0			— 0 — — 2 — — 4 —		GC - Clayey gravel with fine/medium grained sand. Dry, no odors, no staining.
10 YR 3/4 - Dark, Yellowish Brown	0	ACC-1 (5-6.5')		- 6 - - 8 - - 10 -		GC - Clayey gravel with fine/medium grained sand. Dry, no odors, no staining. BC: 16-18-22
10 YR 3/4 - Dark, Yellowish Brown	0	ACC-1 (13.5-15')		14 16 18 20 22		GC - Clayey gravel with fine grained sand. Moist, no odors, no staining. BC: 9-20-25
10 YR 3/2 - Very Dark Grayish Brown	0	ACC-1 (23.5-25')		24 26 28		CL - Clay with medium to large grained sand and gravel. Moist to wet, no odors, no staining.
ACC Environmental Consultants, Inc. 7977 Capwell Drive, Suite 100 Oakland, California 94621 (510)638-8400 FAX: (510)638-8404			Project Number 3054-103.01 Date: 9/12/2011			EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis



Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/12/2011 - 9/13/2011 BORING: ACC-2 (near MW-3)
10 YR 3/3 - Dark Brown	0			— 2 — — 4 —	SC- Fine to medium grained sands and gravels with clay, dark brown, moist, no odor, no staining
10 YR 3/4 (8') - Dark, Yellowish Brown	0	ACC-2 (5-6.5')		- 6 - - 8 - - 10 -	GC - Clayey gravels with fine/medium grained sand. Moist, no odors, no staining.
10 YR 3/4 - Dark, Yellowish Brown	0	No Recovery No Sample		— 14 — — 16 — — 18 —	SC- Fine to medium grained sands and gravels with clay, dark brown, moist, no odor, no staining
10 YR 3/4 - Dark, Yellowish Brown	0	ACC-2 (18.5-20')		— 20 - — 22 - — 24 - — 26 -	CL - Clay with sand and gravel, fine/larger. No odor, no staining. BC: 3-8-12
10 YR 3/4 - Dark Yellowish Brown	0	ACC-2 (28.5-30')		— 28 -	SC- Fine to medium grained sands and gravels with clay, dark brown,moist, no odor, no staining. BC: 18-23-27
ACC Environmental Consultants, Inc. 7977 Capwell Drive, Suite 100 Oakland, California 94621 (510)638-8400 FAX: (510)638-8404				roject Nui 3054-103 Date: /12-9/13/2	Static Groundwater Groundwater Encountered During Drilling.



Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/13/2011 BORING: ACC-3 (near Batting Cage)
10 YR 3/2 - Very dark, greyish brown	0			— 2 — — 4 <i>—</i>	CL - Clay with fine sand and gravels Fine/medium sand and gravels. Moist, no odors, no staining.
	0	ACC-3 (8.5-10')	1 1 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	- 6 8 10 12 14 16 18 -	SC - Clay with fine sands and gravels but more sand and gravel than clays. Large gravel. BC:34-31-19
10 YR 4/2 - Dark, greyish brown	331 731 PPB	ACC-3 (18.5-20')		20 22	SC - Fine to medium grained sand and gravel with clay. Slight gas odor. BC: 14-12-15
10 YR 4/2 - Dark, greyish brown	28 PPM 458 PPB	ACC-3 (23.5-25')		- 24 - - 26 -	SC - Fine to medium grained sand and gravel with clay. Gasoilne odor. Moist/Wet odor. BC: 6-15-21
10 YR 3/3 - Dark	16 100M	ACC-3 (28.5-30')		<u> </u>	SW - Sand with trace clay, fine/medium.
brown PPM (28.5-30') ACC Environmental Consultants, Inc. 7977 Capwell Drive, Suite 100 Oakland, California 94621 (510)638-8400 FAX: (510)638-8404			Р	1 roject Nu 3054-103 Date: 9/13/201	Static Groundwater Groundwater Encountered During Drilling.



Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	OPE LOG LOC WOF	IPMENT: Hollow Stem Auger RATED BY: Gregg Drilling & Testing GED BY: Julia Siudyla & Gwen Santos ATION: 2900 Ladd Avenue, Livermore RK DATE: 9/14/2011 ING: ACC-4 (near MW-2/MW-5)
] 				Asphalt
10 YR 3/2 - Very dark, greyish brown	0			_ 2 _ _ 4 _		SC/GC - Clayey sand to clayey gravel. Dry, no odors, no staining. BC:5/50", 50/5", 50/5" Sampler full of gravel, no soil recovery.
No sample tubes, full of rocks, no soil recovery.	0	ACC-4 (5-6.5')		— 6 —		
	i	1 000 4		<u> </u>		
10 YR 4/4 - Dark, Yellowish Brown	0	ACC-4 (8.5-10')		10 -		SC/GC - Clayey sand, fine to med grained, to clayey gravel. Moist, no odor, no staining. BC: 19-21-25
	<u> </u>			_ 12 -		
	 	 	227			
10 YR 4/4 - Dark, Yellowish Brown with grey staining	800 PPM 1281 PPM 927	ACC-4 (13.5-15') 		- 14 - - 16 -		SC/GC - Clayey sand, fine to med grained to clayey gravel. Moist, strong gasoline odor. High PID. BC: 11-12-19
·	PPM			 - 18 -		
10 YR 5/2 - Greyish brown	33-42 PPM	ACC-4 (18.5-20')		20 -		SC/GC - Clayey sand, fine to med grained to clayey gravel. Slight gas odor,grey staining. BC: 12-14-18
		 		_ 22 -		staining. BO: 12-14-10
10 YR 5/3 - Brown	1	 ACC-4 (23.5-25')		- 24 -		CL - Clay with fine/medium sands and gravel. Moist/wet, gas odor. BC: 9-21-22
	to 15 PPM			- 26 - - 28 -		
10 YR 5/3 - Brown	-54 DDM	ACC-4 !(28.5-30')				CL - Clay, brown with fine sands and gravel. Moist/wet, gas odor. BC: 17-18-39
ACC Environmental Co 7977 Capwell Drive Oakland, Californ (510)638-8400 FAX: (5	onsultar , Suite ia 9462	nts, Inc. 100 21	Р	roject Nu 3054-103 Date: 9/14/20	mber 3.01	EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis

Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	OPEI LOGO LOCA WOR	PMENT: Hollow Stem Auger RATED BY: Gregg Drilling & Testing GED BY: Julia Siudyla & Gwen Santos ATION: 2900 Ladd Avenue, Livermore IK DATE: 9/14/2011 NG: ACC-4 (near MW-2/MW-5)
				- 32 -		CL - Clay with sand and gravel, fine-coarse. Moist, no odor, slight PID, no staining. BC: 5-8-12
10 YR 4/6 - Dark, yellowish brown	1926 to 2433 PPB	ACC-4 (33.5-35')		- 34 - - 36 - - 38 -		SC/GC - Clayey sand, fine to med grained to clayey gravel. Moist, no odor, slight PID, no staining. BC: 5-8-12
10 YR 4/6 - Dark, yellowish brown	635 to 1143 PPB	ACC-4 (38.5-40')		-40 - -42 -		CL - Clay with silty sand and gravel, brown, wet no odor, no staining. CL grading to SC/GC - sand and gravel increases
	592 PPB	ACC-4 (43.5-45')		- 44 - - 46 - - 48 - - 50 -		Groundwater equilibrated at 41.15' Groundwater at 43.5' ACC-4 Water Sample SC/GC - Clayey sand, fine to med grained, to clayey gravel. Moist, no odor, slight PID, no staining.
10 YR 5/3 - Brown	130 PPB 1916 PPB	ACC-4 (53.5-55')		- 54 - - 56 - - 58 -		CL - Clay with silty sand and gravel. Wet, no odor, no staining. BC: 9-20-20
ACC Environmental Co 7977 Capwell Drive Oakland, Californ (510)638-8400 FAX: (100 21	Project Number 3054-103.01 Date: 9/14/2011			EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis	


Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	OPER LOGO LOCA WOR	PMENT: Hollow Stem Auger RATED BY: Gregg Drilling & Testing GED BY: Julia Siudyla & Gwen Santos ATION: 2900 Ladd Avenue, Livermore K DATE: 9/14/2011 NG: ACC-4 (near MW-2/MW-5)
·	566	ACC-4		- 62 - - 64 -		GC - Coarse Gravel - Grey/Brown with
	PPB	(63.5-65')		- 66 -		silty clay. BC: 8-14-24 EOB
	! ! ! ! ! !			- 68 - - 70 -		
	 			72 74 -		·
	i i i i i			- 76 -		
				78 80 -		
				82 84		
	 			86 88		
ACC Environmental Co				roject Nu		EOB: End of Boring BC: Blow Counts
7977 Capwell Drive Oakland, Californ (510)638-8400 FAX: (ia 946	321		3054-103 Date: 9/14/201		Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis


Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/15/2011 BORING: ACC-5			
10 YR 4/2 - Dark Greyish Brown	0			— 2 — — 4 —	SC - Clayey sand (fine to medium grained) with gravels. Dry, no odors, no PID no staining. BC: 50/5"			
10 YR 4/3 - Brown	0	ACC-5 (5-6.5')		- 6 - - 8 -	SC - Clayey sand (fine to medium grained) with gravels. Dry, no odors, no PID no staining.			
10 YR 4/2 - Dark Greyish Brown	0	ACC-5 (8.5-10')		— 10 — — 12 —	SC - Clayey sand (fine to medium grained) with gravels. Moist, no odor, no PID, no staining. BC:17-21-23			
10 YR 5/3 - Brown	499		:	14 16 18	CL - Clay with sand and gravel, fine to			
	29 PPM 3 PPM	(18.5-20') ACC-5 (23.5-25')		- 20 - - 22 - - 24 - - 26 -	coarse. Moist, gas odor, greyish staining. SC - Clayey sand (fine to medium grained) with gravels. Moist, no odor, no staining. BC: 4-12-22			
10 YR 5/4 - Yellowish Brown	48 PPM 1 1 PPM	ACC-5 (28.5-30')		- 28 -	CL - Clay with fine sand and coarse gravel. Moist, slight gas odor, no staining.			
ACC Environmental Co 7977 Capwell Drive Oakland, Californ (510)638-8400 FAX: (, Suite ia 946	100 21	11	roject Nui 3054-103 Date: 9/15/20	Static Groundwater Groundwater Encountered During Drilling.			

Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	OPEI LOG(LOC/ WOR	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/15/2011 BORING: ACC-5		
				- 32 -				
10 YR 4/6 - Dark, yellowish brown	PPM to 46 PPB	ACC-5 (33.5-35')		- 34 - - 36 - - 38 -		CL - Clay with silty sand, fines. Moist, slight gas odor, no staining. BC: 3-5-7		
10 YR 4/3 Brown	0.3 to 3 PPM	ACC-5 (38.5-40')		- 40 - - 42 -		SC/GC - Clayey sand (fine to medium grained) to clayey medium to coarse gravels. Moist to wet,no odor, no PID, no staining. BC: 14-17-19 Groundwater at 43.5' bgs		
10 YR 4/3 Brown	0	ACC-5 (43.5-45')		- 44 - - 46 -		SC/GC - Clayey sand (fine to medium grained) to clayey medium to coarse gravels. Wet, no odor, no PID, no staining.		
10 YR 4/3 Brown	 0 	ACC-5 (48.5-50')		- 48 - - 50 - - 52 -		CL - Clay with sand and gravel. Wet. BC: 15-23-31		
10 YR - 5/4 Yellowish Brown	0	ACC-5 (53.5-55')		– 54 – – 56 –				
				- 58 -		No sample at 60' bgs.		
ACC Environmental Consultants, Inc. 7977 Capwell Drive, Suite 100 Oakland, California 94621 (510)638-8400 FAX: (510)638-8404				roject Nu 3054-103 Date: 9/15/20	3.01	EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis		

Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/15/2011 BORING: ACC-5
		ACC-5 (63.5-65')		- 62 - - 64 -	SC/GC - Clayey sand (fine to medium grained) with medium to coarse gravels. Wet, no odor, no PID, no staining. No recovery, no sample.
	† † 		,,,,	- 66 - - 68 -	65' bgs EOB
				70 72	
	 			74 76	
				-78 - -80 -	
				82 84	
		 		86 88	
ACC Environmental Co 7977 Capwell Drive Oakland, Californ (510)638-8400 FAX: (5	, Suite ia 9462	100 21		roject Nui 3054-103 Date: 9/15/20	Static Groundwater Groundwater Encountered During Drilling.


Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft)	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/16/2011 BORING: ACC-6		
				— 2 — — 4 —		SM - Very fine silty sands, likely fill materials with trace coarse gravels. Very dry.	
10 YR 3/4 - Very dark, greyish brown	0	ACC-6 (5-6.5')		- 6 - - 8 -		GC - Clay gravel with sands fine to coarse. Dry. BC: 50/5"	
		[- 10 - - 12 -			
10 YR 4/3 - Brown	0	ACC-6 (13.5-15')		- 14 - - 16 -		GC - Clay gravel with sands fine to coarse. Moist, no odor, no staining.	
				- 18 - - 20 -			
10 YR 4/4 - Dark		ACC-6		- 22 - - 24 -		GC - Clay gravel with sands fine to	
yellowish brown	0	(23.5-25')		- 26 - - 28 -		coarse No odor, no staining. BC: 17-32-33	
ACC Emiliana and a Co		A. I	Dr	oject Nun	nher	EOR: Fod of Positive DOUBLE O	
ACC Environmental Co 7977 Capwell Drive Oakland, Californi (510)638-8400 FAX: (5	, Suite a 9462	100 21	Project Number 3054-103.01 Date: 9/16/2011			EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis	





Additional Observations	PID (ppm)	SAMPLE ID	SAMPLE INTERVAL	depth below ground surface (ft) 30	LOC LOC WOI	EQUIPMENT: Hollow Stem Auger OPERATED BY: Gregg Drilling & Testing LOGGED BY: Julia Siudyla & Gwen Santos LOCATION: 2900 Ladd Avenue, Livermore WORK DATE: 9/16/2011 BORING: ACC-7		
	0			- 32 - - 34 -				
 10 YR 5/3 - Brown	0.87	ACC-7		- 36 - - 38 -		CL - Clay with silty fine to medium		
TO TIX 0/0 - DIOWII	PPM to 2 PPM	(38.5-40') 		- 40 - - 42 -		grained sands. Moist, plastic, no odor, no staining. BC: 6-8-13		
				- 44 - - 46 -	X	Groundwater at 45' bgs, equilibrated at 42.6' bgs.		
10 YR 5/3 - Brown	0	ACC-7 (48.5-50')		- 48 - - 50 - 52 -		CC - Clay with sand and gravel. BC: 14-18-23 EOB		
·				- 54 - - 56 -				
				- 58 -				
ACC Environmental Consultants, Inc. 7977 Capwell Drive, Suite 100 Oakland, California 94621 (510)638-8400 FAX: (510)638-8404				oject Nur 3054-103 Date: 9/16/201	.01	EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis		

			 ·		
Additional Observations	PID (ppm)	SAMPLE ID	depth below ground surface (ft)	LOC WOF	IIPMENT: Hollow Stem Auger RATED BY: Gregg Drilling & Testing GED BY: Julia Siudyla & Gwen Santos ATION: 2900 Ladd Avenue, Livermore RK DATE: 9/15/2011 ING: ACC-8
10 YR 3/2 - Very Dark Greyish Brown	0		2 4		Asphalt CL - Clay, brown, trace fine sand, small amounts of gravel. Moist, no odor, no staining.
10 YR 3/2 - Very Dark Greyish Brown	0	ACC-8 (5-6.5')	- 6 - - 8 - - 10 - - 12 -		CL - Clay, brown, trace fine sand and gravel. No odor, no staining. BC: 2-8-12
10 YR 4/3 - Brown	0	ACC-8 (13.5-15')	- 14 - - 16 - - 18 - - 20 -		CL - Clay with fine to coarse sands and gravels. Moist, no odors, no staining. BC: 42, 50/4"
10 YR 4/3 - Brown	0	ACC-8 (23.5-25')	- 24 - - 26 - - 28 -		GC - Clayey gravel with fine to coarse sands. Moist-wet. BC: 18-13
ACC Environmental Co 7977 Capwell Drive Oakland, Californ (510)638-8400 FAX: (5	, Suite ia 946	100 21	roject Nur 3054-103 Date: 9/15/201	.01	EOB: End of Boring BC: Blow Counts Static Groundwater Groundwater Encountered During Drilling. Sample not submitted for analysis



	Œ	ON H	DATE OF BORING: December 13, 1990	N S.P.T.	qu	IN	PLACE
H (FEET)	E NUMBER	LOCATION AN E OF SAMPLE	SURFACE ELEVATION: Approx. 490.0 feet	BLOWS/FT	UNCON. COMP. STRENGTH (TSF)	DRY UNIT WEIGHT	MOIST. CONTENT
DEPTH	SAMPLE	LOG, LC TYPE	DESCRIPTION	FOR 3" O.D. SAMPLER	*FIELD PENET. APPROX.	(PCF)	% DRY WEIGHT
-e			ASPHALT				
			PEA GRAVEL.			٠	
			Reddish-brown silty CLAY, some				
٠			gravels. (CL)		0		
-5			Brown clayey GRAVEL, medium to coarse. (GC)		О		
			Coarser gravel.			·	
.					0		
-10			Brown sandy clayey GRAVEL,				
	1-1		moist, very dense, slight odor. (GC)	50/5*	30		
,							
-15			Strong petroleum odor at 14 feet.		410		
	1-2			22*	500		
-20			Medium dense, strong petroleum hydrocarbon odor.		532		
.	1-3			30*	180		
-25					102		
50	1-4		Light brown sandy gravelly CLAY, moist, very stiff, odor. (CL)	28*	75		
	·				50		
-30		1 200		BORING NO].: 1		FIGURE
E	NGI	E0	Livermore Valley Unified School District	DATE: Sep		991	NO.
INC	ORPORAT	red	Livermore, California				
				JOB NO: N	11-3174-F	1	

	æ.	S mi	DATE OF BORING: December 13, 1990	N	đn	EN	PLACE
(FEET)	NUMBER	LOCATION AND	SURFACE ELEVATION: Approx. 490.0 feet	S.P.T, BLOWS/FT	UNCON. COMP. STRENGTH (TSF)	DRY UNIT WEIGHT	MOIST.
DEPTH	SAMPLE	LOG, LOC TYPE D	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	*FIELD PENET. APPROX.	(PCF)	% DRY WEIGHT
-30 - -	1-5		Moist, harder, slight odor. (CL)	33*	50		
-35			Reddish-brown sandy silty CLAY, with gravels, moist, stiff.		57		
-	1-6		СП	9*	30		
	1-7		Lense of red clay at 38.5 feet.	9*			
-40	1-8		Brown sandy silty CLAY with some gravels, very moist, hard,	36*	2		
	1-9		odor. (CL)	50/5"	30		
	1-10		Brown sandy gravelly CLAY, very moist, hard, odor. (CL)	50/5"	18		
-45	1-11			46*	20		
- 59	1-12		Mottled brown sandy gravelly CLAY, very moist, hard. (CL)	63*	5		
-55					0		
69	1-13		Brown silty CLAY with some gravel, very moist, hard. (CL) Approximate water level at time of drilling	50/6"*	o		
F	NGE	=_	Livermore Valley Unified School District	BORING NO			FIGURE NO.
	ORPORAT		Livermore, California	JOB NO: N	tember 19	91	

ł

į

	Œ	A M	DATE OF BORING: December 13, 1990	N S.P.T.	dn	IN	PLACE
(FEET)	NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	SURFACE ELEVATION: Approx. 490.0 feet	BLOWS/FT	UNCON. COMP. STRENGTH	DRY UNIT	MOIST.
1 1		OCAT OF		*MODIFIED	(TSF)	WEIGHT	
DEPTH	SAMPLE	3, L YPE	DESCRIPTION	FOR 3" O.D.	*FIELD PENET.		% DRY
	•	٦٢		SAMPLER	APPROX.	(PCF)	WEIGHT
- 68	1-14		Brown gravelly silty CLAY, saturated, hard. (CL)	57	0		
-	4 4		Bottom of boring at approximately 61.5 feet.	3,		:	
-65							
-							
-							
-							
78							
	,						
-							
}							
-75							
-							
-							
-							
80							
}							
85							
-90		<u> </u>	Livermore Valley Unified School District	BORING NO).; <u>1</u>		FIGURE
1	NG		Livermore, California	DATE: Sej			NO.
			waver mus my Vesal WI I las	100 BOL	N1-3174-F	1	

	OΣ		DATE OF BORING: December 13, 1990	N S.P.T.	qu	IN	PLACE
(FEET)	NUMBER	SAMP	SURFACE ELEVATION: Approx. 490.0 feet	BLOWS/FT	UNCON. COMP. STRENGTH	DRY UNIT	MOIST.
ОЕРТН	SAMPLE	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(TSF) *FIELD PENET. APPROX.	WEIGHT (PCF)	% DRY WEIGHT
-0			ASPHALT				
			PEA GRAVEL.		0		
-5			Brown clayey GRAVEL, coarse, moist, dense. (GC)			·	
-10					0		
و جورون المسلم	2-1			48*	0		summer such the foundation of the summer such that the such such that the such such such such such such such such
-15			Brown silty CLAY with gravel, brown moist, hard, very slight odor. (CL)				
	2-2			51*			
20					7		
	2-3		Brown sandy silty CLAY with minor gravels, moist, hard. (CL)	34*	1		
-25					1		
-	2-4		Brown silty CLAY (CL), with some gravels, moist, hard. (CL)	50*	1		
-38			·		_		
		=	Livermore Valley Unified School District	BORING NO).: 2		FIGURE
	MI = 1	_,	· ·		stember 1		NO.

	Œ	S m	DATE OF BORING: December 13, 1990	N S.P.T.	qu	IN	PLACE
(FEET)		TION AND SAMPLE	SURFACE ELEVATION: Approx. 490.0 feet	BLOWS/FT	UNCON. COMP. STRENGTH	DRY UNIT	MOIST.
DEPTH (SAMPLE NUMBER	LOG, LOCATION TYPE OF SAMP	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(TSF) *FIELD PENET. APPROX.	WEIGHT	% DRY Weight
-36	2-5			48*	0		
-35			Brown silty gravelly CLAY, moist, very stiff. (CL)			·	
-40	2-6		Brown silty CLAY with minor gravels, moist, very stiff. (CL) Light brown silty sandy CLAY, moist, very stiff. (CL)	22*	0		
45					o		
59							
55			Brown silty sandy CLAY, some gravel, moist, very stiff. (CL)			·	
	2-7		∇	22*	o		
50			Water encountered at approximately 57 feet. Bottom of boring at approximately 57 feet.				
	NGI		Livermore Valley Unified School District	BORING NO			FIGURE NO.
	ORPORAT		Livermore, California	DATE: Sep	tember 1	991	, var 9

	ſΥ	2 4	DATE OF BORING: December 13, 1990	N	đn	IN	PLACE
DEPTH (FEET)	SAMPLE NUMBER	LOG, LOCATION AN TYPE OF SAMPLE	SURFACE ELEVATION: Approx. 490.0 feet DESCRIPTION	S.P.T. BLOHS/FT *MODIFIED FOR 3* O.D. SAMPLER	UNCON. COMP. STRENGTH (TSF) *FIELD PENET. APPROX.	DRY UNIT WEIGHT (PCF)	MOIST. CONTENT * DRY WEIGHT
-0			ASPHALT				
-			PEA GRAVEL.		0		
-5			Brown clayey GRAVEL, coarse, moist, dense. (GC)				
-10					0		
_	2-1			48*	o		
-15			Brown silty CLAY with gravel, brown moist, hard, very light clor. (CL)				
690	16 pens			51*	4		
-28	\ -'				7		
	2-3		Brown sandy silty CLAY with minor gravels, moist, hard. (CL)	34*	1		
-25					1		
-39	2-4		Brown silty CLAY (CL), with some gravels, moist, hard. (CL)	50*	1		
	kio-		Livermore Valley Unified School District	BODENO M		· ·)	FIGURE
	NGE		Livermore, California	DATE: Sep			NO.
				JOB NO: N	1-3174-F1	_	

· |

	Œ.	2 4	DATE OF BORING: December 13, 1990	N	qu	IN	PLACE
(FEET)	NUMBER	. 	SURFACE ELEVATION: Approx, 490.0 feet	S.P.T. BLOWS/FT	UNCON. COMP. STRENGTH	DRY UNIT	MOIST.
DEPTH (SAMPLE N	LOG, LOCATION TYPE OF SAMP	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(TSF) *FIELD PENET. APPROX.	WEIGHT	% DRY WEIGHT
-3 9 -	2-5			48*	0	· ·	
- -35		TINE STATES	Brown silty gravelly CLAY, moist, very stiff. (CL)				
-40			Brown silty CLAY with minor gravels, moist, very stiff. (CL) Light brown silty sandy CLAY, moist, very stiff. (CL)				
-45	2-6			22*	0		
-50					0		
-			Brown silty sandy CLAY, some gravel, moist, very stiff. (CL)				
- 69	2-7		Water encountered at approximately 57 feet. Bottom of boring at approximately 57 feet.	22*	0		
	NGE		Livermore Valley Unified School District Livermore, California	BORING NO DATE: Sept JOB NO: N	tember 19	91	FIGURE NO.

	- α	2 4	DATE OF BORING: April 9, 1993	N S.P.T.	OVM	IN	PLACE
(FEET)	NUMBER	SAMP	SURFACE ELEVATION: Approx. feet msl	BLOW/FT	READING P.1.D. (10.0eV)	DRY UNIT WEIGHT	MOIST. CONTENT
DEPTH	SAMPLE	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-6			ASPHALT/BASE ROCK				
			10YR 4/4 Dark yellowish-brown gravelly CLAY, moist. (CL)				
-5			10YR 4/4 Dark yellowish brown clayey GRAVEL. (GC)		2.3		
-10			10YR 5/4 Yellowish brown clayey sandy GRAVEL. Gravel to 4 inches.		3.0		
	3-1		·	<u>}</u>	3.0		
-15	3-2		10YR 5/4 Yellowish brown silty SAND with some clay, slightly to medium plasticity. (SM/SC) Increasing gravel.		20.5		
						•	:
-20	3-3		10YR 6/5 Pale brown clayey sandy GRAVEL, very moist. (GC)		3.8		
26							
	3-4				4.6	,	
-30							
	NGE		Livermore Valley Joint Unified School District Livermore, California	BORING NO	lu 1993		FIGURE NO.
				JOB NO.:	3174-F6		

•

	nz nz	D H	DATE OF BORING: April 9, 1993	N N	MVO	IN	PLACE
(FEET)	SAMPLE NUMBER	TION	SURFACE ELEVATION: Approx. feet msi	S.P.T. BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTH	SAMPLE	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	X DRY WEIGHT
-30							
	3-5		10YR 5/4 Yellowish brown silty CLAY, moist, medium plasticity. (CL)		2.7		
-35	3-6		Water level 4/13/93. Mottled 10YR 5/8 yellowish brown and 10YR 5/3 brown clayey SAND, wet, moisture on grains. (CL)		3.8		
-40			10YR 5/4 Yellowish brown clayey SILT, wet, trace rounded gravel, moisture on grains.				
-	3-7		Water level three = hours after drilling.		4.0		
-46	3-8		<pre></pre>		1.1		
			Bottom of boring at approximately 46.5 feet.				
-50							
-66							
-60							
F	NGI	=_	Livermore Velley Joint	BORING N		3	FIGURE NO.
	ORPORAT		Unified School District Livermore, California	JOB NO.:	, , , , , , , , , , , , , , , , , , , ,		3
				1 000 110	07 I#-LD		

	œ	ON H	DATE OF BORING: April 9, 1994	N	OVM	IN F	PLACE
H (FEET)	E NUMBER	LOCATION AND E OF SAMPLE	SURFACE ELEVATION: Approx. feet msl	S.P.T. BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
ОЕРТН	SAMPLE	LOG, LC TYPE	DESCRIPTION	*MODIFIED FOR 3" C.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
			ASPHALT/BASE ROCK				
			10YR 4/4 Dark yellowish brown gravelly CLAY with some sand moist. (CL)				
5			Increasing gravel.		10.8		
			10Y 5/4 Yellowish brown sandy GRAVEL with some clay, slightly moist. (GC)	:			
					5.6		
10			Increasing moisture				
-				· ·			
15							
	4-1				478		
			Very moist.		· .		
20							
	4-2				478		
25							
	4-3		Harder drilling.		401		
30			10YR 5/4 Yellowish brown sandy GRAVEL, damp. (GW)				
			Livermore Valley Joint	BORING NO),: 3 5-2	V	FIGURE
	NG		Unified School District	DATE: Ju.	ly 1993		NO.
INC	DRPORAT	ED	Livermore, California	J08 NO.:	~454		4

_	2 u	DATE OF BORING: April 9, 1994	N	OVM	1N	PLACE
DEPTH (FEET)	LOCATION AND E OF SAMPLE	SURFACE ELEVATION: Approx. feet msl	S.P.T. BLOW/FT	P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST. CONTENT
SAMPLE	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-30	4	Easier drilling.		579		
-35		Mottled 10YR 5/8 Yellowish brown and 10YR 6/3 pale brown clayey SILT, trace fine sand, very moist, slight plasticity. (SM) Water level on 4/12/93.				
4-	5	Increasing sand.	<u> </u> - !	181		
4-	6	10YR 5/6 Yellowish brown clayey silty SAND with rounded gravels, very moist. SC)		40	·	
- 4- -45	7			23		
-50	en e					
- -55	Appropriate to the state of the					
-60						
EN(3EC	Livermore Valley Joint Unified School District Livermore, California	DATE: JL		4	FIGURE NO.

	1,	Q ⊌	DATE OF BORING: April 9, 1993	N	OVM	IN F	LACE
(FEET)	TORING WEL STRUCTION DETAIL	TION	SURFACE ELEVATION: Approx. feet MSL	S.P.T. BLOWS/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTH	MONITORING CONSTRUCT DETAIL	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" 0.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-0			ASPHALT/BASE ROCK.				
			10YR 4/6 Dark yellowish brown silty CLAY with some gravel, moist, medium plasticity. (CL) Increasing gravel.				
-5			10YR 3/3 Dark brown clayey GRAVEL with gravels to 4 inches, moist. (GC) Very coarse gravel.		1.5		
					2.7		
-18	0				2.7		
- - -			water level at time of drilling. 10YR 6/4 Light yellowish brown sandy GRAVEL with trace fines,				
-1 5			**************************************		584		
- -20 - -			10YR 5/4 Dark yellowish brown clayey sandy GRAVEL, wat. (CG) 5-2		693		
- 25			10YR 5/4 Dark yellowish brown gravelly SAND with little silt and clay, very moist. (SC) 5-3	- - -	659		
- -30			Increasing clay. No sample recovery.				
	NGE	=	Livermore Valley Joint	WELL NO.			FIGURE NO.
	CORPORATI		Livermore, California	JOB NO.:			5

I

	4_	S ii	DATE OF BORING: April 9, 1993	N	QVM	IN I	PLACE
(FEET)	TORING WEL STRUCTION DETAIL	LOCATION AN E OF SAMPLE	SURFACE ELEVATION: Approx. feet MSL	S.P.T. BLOWS/FT	READING P.I.D. (18.0eV)	DRY UNIT WEIGHT	MOIST. CONTENT
DEPTH	MONITORING CONSTRUCT DETAIL	LOG, LO TYPE C	DESCRIPTION	*MODIFIED FOR 3" 0.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
36			Mottled 10YR 5/8 yellowish brown and 10YR 6/3 pale brown silty CLAY, moist. (CL) Increasing silt. Water level on 4/12/93 5-4 Mottled 10YR 5/8 yellowish brown and 10YR 6/3 pale brown clayey SILT. (SM) Increasing sand; trace gravel. 2.5Y 5/4 Light olive-brown		119		
.			clayey sandy GRAVEL, moist. (GC) 5-5		125		
45			10YR 5/4 Yellowish brown clayey sandy GRAVEL, wet. 5-6			·	
-50			5-7		11		
-65			5-8				
60			Bottom of boring at approximately 57 feet.				
	NGE	<u></u>	Livermore Valley Joint	WELL NO.:	·····		FIGURE NO.
	CORPORATI		Livermore, California	DATE: Jul			5
L				JOB NO.:	31 (4-F6	l.	

	α	N N	DATE OF BORING: April 9, 1993	N	OVM	NI	PLACE
(FEET)	NUMBER	FION AN	SURFACE ELEVATION: Approx. feet mst	S.P.T. BLOW/FT	READING P.1.D. (10.0eV)	DRY	MOIST.
оертн (SAMPLE	LOG, LOCATION TYPE OF SAMP	DESCRIPTION	*MODIFIED FOR 34 O.D. SAMPLER	(parts per million)	WEIGHT (PCF)	% DRY WEIGHT
-8			ASPHALT/BASE ROCK				
		1111	PEA GRAVEL. (FILL)				
		1 1 1					
-5		1111					
-							
-							
-10		1111					
		0.	CONCRETE.	-			
			10YR 4/6 Dark yellowish brown		·		
-15			clayey GRAVEL, moist. (GC)		<u> </u>		
	6-1				603		
-	•			:			
-20							
-	6-2		10YR 5/4 Yellowish-brown clayey GRAVEL, wet. (GC)		598		
-25							
-	6-3		10YR yellowish brown silty CLAY, very moist, medium plasticity. (CL)	de de la composition della com	478		
-30		1	10YR 5/6 Yellowish brown silty SAND and GRAVEL, moist. (GM)				
E	NGE	ΞΩ	Livermore Valley Joint Unified School District	BORING N		3	FIGURE NO.
	ORPORAT		Livermore, California	JOB NO.:			6

	Œ	S W	DATE OF BORING: April 9, 1993	N	OVM	IN	PLACE
(FEET)	SAMPLE NUMBER	LOCATION AND E OF SAMPLE	SURFACE ELEVATION: Approx. feet msi	S.P.T. Blow/ft	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST. CONTENT
DEPTH	SAMPL	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-30 -	6-4				522		
-35	6-5		Mottled 10YR 5/8 yellowish brown and 10YR 6/3 pale brown clayey SILT with fine sand, very moist. (SM) Bottom of boring at approximately 36.5 feet.		151		
-46	·					•	
-45							
-50							
-56							
		Transverse ring of the first consequence of th					
	NGE		Livermore Valley Joint Unified School District Livermore, California	BORING NO DATE: Jul JOB NO.:	ly 1993	3	FIGURE NO.

	œ	A A	DATE OF BORING: April 9, 1993	N	OVM	IN	PLACE
(FEET)	= NUMBER	LOCATION AN	SURFACE ELEVATION: Approx. feet msl	S.P.T. BLOW/FT	REĂDING P.I.O. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTH	SAMPLE	LOG, LOG TYPE O	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-0			ASPHALT/BASE ROCK	d .			
			10YR 4/2 Very dark grayish-brown sandy gravelly CLAY, slightly moist, medium plasticity. (CL)	,	5.4		
-5			10YR 4/3 Brown clayey SAND, damp. (CL)				
-10			10YR 4/4 Dark yellowish brown sandy clayey GRAVEL, moist. (CG)		2.3		
- -					2.3		
-15	7-1		10YR 5/3 Brown silty SAND with gravel, trace clay, wet. (SM)		733		
- -20 -	7-2		Mottled 10YR 5/4 yellowish brown and 10YR 6/3 pale brown clayey SILT, very moist, wet. (SM)		742		
-25	7-3		10YR 5/6 Yellowish brown clayey sandy GRAVEL, very moist. (CG)		623		
-30							
	NGI	=_	Livermore Valley Joint	BORING N	o.: 🍇 🎏 -	7	FIGURE
	ORPORAT		Unified School District Livermore, California	DATE: Ju.	ly 1993		NO.
			Livermore, California	JOB NO.:	3174-F6		

n,	S m	DATE OF BORING: April 9, 1993	N	OVM	IN F	PLACE
DEPTH (FEET)	LOCATION AND E OF SAMPLE	SURFACE ELEVATION: Approx. feet msl	S.P.T. BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTH	LOG, LOC TYPE O	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-30	4			707		
-35 -7-	-5	Mottled 10YR 5/8 yellowish brown silty CLAY/clayey SILT, very moist, medium plasticity. (CL) Bottom of boring at		280		
-40		approximately 36.5 feet.				
-45					·	
- -59 -						
-55						
-50 FN1	GEC	Livermore Valley Joint	BORING N		7	FIGURE
INCORPO		Unified School District Livermore, California	JOB NO.:	1y 1993 3174-F6		7

DESCRIPTION ASPHALT/BASE ROCK 10YR 4/4 Dark yellowish brown clayey GRAVEL, slightly moist. (GC) Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 8-2 Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey GRAVEL, wast. (GC) 10YR 5/4 Yellowish brown clayey GRAVEL, wast. (GC) 8-2 Livermore Veiley Joint BORN REDURN BBY RECORD (10.00) 10.0 10.0 10.0 10.0 10.0 10.0 10.0 10.0 10.0 5.4 14.1 14.1		y Q	шi	DATE OF BORING: April 9, 1993	N	MVO	EN I	PLACE
ASPHALT/BASE ROCK 10YR 4/4 Dark yellowish-brown gravelly CLAY, moist. (CL) 10YR 5/4 Dark yellowish brown clayey GRAVEL, slightly moist. (GC) 7.0 Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 8-2 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 7.0 10.0 1	(FEET)	PATION		SURFACE ELEVATION: Approx. feet msl	S.P.T. BLOW/FT		UNIT	MOIST. CONTENT
ASPHALT/BASE ROCK 10YR 4/4 Dark yellowish-brown gravelly CLAY, moist. (CL) 10YR 5/4 Dark yellowish brown clayey GRAVEL, slightly moist. (GC) 7.0 Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: E-8 FIGURE	SAMPL	Log, Log	~ :	DESCRIPTION	FOR 3" 0.D.	(parts per million)	(PCF)	% DRY WEIGHT
gravelly CLAY, moist. (CL) 10YR 5/4 Dark yellowish brown clayey GRAVEL, slightly moist. (GC) 7.0 Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Velley Joint BORING ND.: E-8 FIGURE 0	-0			ASPHALT/BASE ROCK				
Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 137 Livermore Velley Joint BORING NO.: E-8 FIGURE O								
Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 137 ENCEO Livermore Valley Joint BORING NO.: B-8 FIGURE	-5			clayey GRAVEL, slightly moist.		10.0		
Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 137				(GC)		7.0		
Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: B-8 FIGURE	-10							
Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: E-8 FIGURA NO.: E-8 NO.						5.4		
Mottled 10YR 6/6 brownish yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: E-8 FIGURA NO.: E-8 NO.				Met.				
yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: 8-8 FIGURE NO.	10 0	1				14.1		
yellow and 10YR 6/3 pale brown clayey SILT, moist, low plasticity. (ML) 10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: 8-8 FIGURE NO.								
10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC) 8-3 Livermore Velley Joint BORING NO.: 8-8 FIGURE	-29 8-	-2		yellow and 10YR 6/3 pale brown clayey SILT, moist, low		534		
clayey GRAVEL, wet. (GC) 8-3 Livermore Valley Joint BORING NO.: 5-8 FIGURE NO.								
ENCEO Livermore Valley Joint BORING NO.: 5-8 FIGU	-25			10YR 5/4 Yellowish brown clayey GRAVEL, wet. (GC)				
Livermore Valley Joint BORING NO.: 8-8 FIGU	8-	-3				137		
ElCEO Livermore Valley Joint No.	-30							
	FNI		\cap				8	FIGURE NO.
			_	Unified School District Livermore, California				8

	α	를 파	DATE OF BORING: April 9, 1993	N	OVM	1 N	PLACE
(FEET)	NUMBER	LOCATION AND E OF SAMPLE	SURFACE ELEVATION: Approx. feet msl	S.P.T. BLOW/FT	READING P.I.D. (10.0eV)	DRY UNIT WEIGHT	MOIST.
DEPTH	SAMPLE	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" O.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-30 -	8-4				20		
-36	8 - 5		Mottled 10YR 5/8 yellowish brown and 10YR 6/3 pale brown silty CLAY, moist. (CL) Bottom of boring at approximately 35.5 feet.				
-49							
-45							
-59							
55							
-60			·				
	NG		Livermore Vailey Joint Unified School District Livermore, California	DATE: Jul JOB NO.:	ly 1993	3	FIGURE NO.

DATE OF BORING: December 14, 1998 S.P.T. SURFACE ELEVATION: Approx. 496.8 feet SLOWS/FT READI P.I. (10.00 *MODIFIED FOR 3" 0.D. SAMPLER MILL PEA GRAVEL. PEA GRAVEL.	DRY UNIT WEIGHT	MOIST CONTEN % DRY WEIGH
ASPHALT COVER. Brown silty CLAY, dry. (CL) PEA GRAVEL. PEA GRAVEL.	on) (PCF)	
ASPHALT cover. Brown silty CLAY, dry. (CL) PEA GRAVEL.	0	
PEA GRAVEL.	0	
PEA GRAVEL.		
4' ' -		
MW1-1 Brown clayey GRAVEL, medium to coarse, moist, medium dense, odor. (GC)	0	
MW1-2 Very dense, strong odor. 50/5" 54	12	
29 MW1-3 34* 54	10	
MW1-4 Brown gravelly sandy CLAY, moist, hard, strong petroleum hydrocarbon odor. (CL)	00	
Brown silty sandy CLAY, moist, hard, strong odor. (CL)	, <u>ļ</u>	
ENGED Livermore Valley Unified School District DOTE: Sentenber		FIGURE NO.
INCORPORATED Livermore, California DATE: September	r 1991	:

_	1, Z	DATE OF BORING: December 14, 1990	N S.P.T.	OUM	IN F	LACE
(FEET)	TORING WELL ASTRUCTION DETAIL LOCATION AN	SURFACE ELEVATION: Approx. 490.0 feet	BLOWS/FT	READING P.I.D. (10.0mV)	DRY UNIT WEIGHT	MOIST.
DEPTH	MONITORING WELL CONSTRUCTION DETAIL LOG, LOCATION AN TYPE OF SAMPLE	DESCRIPTION	*MODIFIED FOR 3" 0.0. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-3 0	Δ	MW1-5 Brown gravelly sandy CLAY, moist, hard, odor. (CL)	44*	250		
35		MW1-6 Mottled brown silty CLAY some sand and gravels, moist,	27*	100 153		
		very stiff, odor. (CL) Brown sandy silty CLAY, moist,	2/*	153		
40		very stiff, odor. (CL)	30*	300 413	·	
45		Brown silty CLAY, minor sand and gravel, moist, very stiff, odor. (CL)		100	·	
•••		MW1-8 Brown gravelly CLAY, moist, hard, odor. (CL)	42*	38		
50						
		Brown silty CLAY, minor gravel, moist, hard, odor. (CL)		6		
·55		MW1-9 Brown sandy gravelly CLAY, moist, hard, slight	50*	2		
60			WELL NO.:	Mwil	7	FIGURE
E	NGEO		DATE: Sep	tember 1	991	NO.
	CORPORATED	Livermore, California				

	٦,	ON THE	DATE OF BORING: December 14, 1990	_ N _	OUM	IN F	LACE
(FEET)	ONITORING WELL CONSTRUCTION DETAIL	LOCATION AND E OF SAMPLE	SURFACE ELEVATION: Approx. 498.0 feet	S.P.T. BLOWS/FT	READING P.I.D. (10.0=V)	DRY UNIT WEIGHT	MOIST.
DEPTH	MONITORING CONSTRUCT DETAIL	LOG, LOCA TYPE OF	DESCRIPTION	*MODIFIED FOR 3" 0.D. SAMPLER	(parts per million)	(PCF)	% DRY WEIGHT
-69					0		
-65			Yellow-brown clayey gravelly SAND, saturated. (SP) Running sands at approximately 63.5 feet.		0		
70			Bottom of boring at approximately 67 feet. NOTE: After removal of augers from hole, water measured at approximately 46 feet.				
-75						·	
- 80							
-85							
90				WELL NO.:	MW1	T	FIGURE
1	CORPORATE		Livermore Valley Unified School District Livermore, California	DATE: Sep	tember 1	991	NO.

MONITORING WELL DETAIL

		MOMITON	IACA A	<u> </u>	DEIAN			
PROJECT	NUMBER	N90-3174-F1		DATE OF	INSTALLATIO	N Decembe	r 14, 1	<u>.9</u> 90
PROJECT	NAME Liv	ermore Vlly Sch.	Dist.	TOP OF	CASING ELEV.	±489.5		
COUNTY_	Ala	meda		GROUND	SURFACE ELE	ev. ±490		
WELL PER	RMIT NO	90702	., .,	DATUM	MSL_		····	
888	H A			EXPL	orator	y Borin	<u>G</u>	
	Δ.	Δ. Δ. Δ.	A. TOTAL	DEPTH			67	FT.
	Δ. Δ		B. DIAMET	ER			6	IN.
	Δ. ₂	Δ Δ Ε Δ Δ Ι	DRIL	ING METH	HOD HOLLOW	stem aug	ers	
	Δ ·	Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ		well	_ const	RUCTION	<u>0</u>	
		F	C. CASING	LENGTH			67	FT.
			MATER	IAL	Sch 40	PVC		
l A	C C		DIAME	TER			2	IN.
			D. SLOTTE	ED INTERV	AL LENGTH		25	FT.
			SLOTT	ED INTERV	/AL FROM	42 TO	67	FT.
·			SLOT	SIZE			.020	IN.
			E. GROUT	INTERVAL	0	OTO	38	FT.
	D .		GROUT	MATERIAL	neat c	ement		
			F. FILTER	PACK SEA	AL <u>38</u>	то	40	FT.
			SEAL 1	MATERIAL_	Benton	ite		
			G. FILTER	PACK INT	TERVAL 40	TO	67	FT.
			FILTE	R MATERIA	L #2 san	đ		
			H. Chr	isty bo	x (flush	with surf	ace) ·	




and locking well cap.

MONITORING	WELL DETAIL
PROJECT NUMBER 3174-F6	DATE OF INSTALLATION April 13, 1993
PROJECT NAME L.V.J.U.S.D. Maintenance	TOP OF CASING ELEV.
	GROUND SURFACE ELEV.
WELL PERMIT NO. #93167	DATUM
H Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ Δ	
	NG LENGTH 57' FT
A C DIA	METER 2.0 IN
	TED INTERVAL LENGTH 25 FT
sto	TTED INTERVAL FROM 32 TO 57 F

SLOT SIZE

D

- B -





0.020 IN

ОЕРТН (РЕЕТ)	SAMPLE NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	DATE OF BORING: July 1, 1994 SURFACE ELEVATION: Approx. feet MSL DESCRIPTION	MONITORING WELL, CONSTRUCTION DETAIL	PID READING (10.0eV)	N S.P.T. BLOWS/FT "MODIFIED FOR 3" O.D. SAMPLER
-5			Loose layer of GRAVEL, light brown (fill)? Brown, sandy SILT with some gravel, damp. Increase in gravel at 3 feet. Fine to coarse GRAVEL with little sand and silt. Some fine to coarse GRAVEL, angular to subrounded, little fine to coarse sand, damp, trace of clay.	Type I/II Portland Cement		
10	MW3-1	0	Increase in clay, fine gravel, increase in moisture. Brown/reddish brown, moist wat, fine to coarse SAND and fine to coarse GRAVEL. Increase in moisture.			
-15	MW3-2		Red brown/brown, moist, clayey SILT to silty CLAY, stiff. More gravelly at 19 to 20 feet.			
-25	MW3-4		Brown, moist, fine to coarse SAND with lenses of silty clay, trace 10 to 15% gravel, no obvious odor. Brown, weatine to coarse SAND with fine to medium GRAVEL, little clay. Clay content varies.	Bentonite scal 0.01 in, slotted 2 in. PVC pipe with #3 Monterey sand		
M)	ENGE CORPORAT		2900 LADD AVENUE LIVERMORE, CALIFORNIA	WELL NO.: MW3 DATE: March 1995 JOB NO.: 3174-F7		FIGURE NO.

.


:

	es	(A)	DATE OF BORING: July 1, 1994			N
EET))MBE	ON A	SURFACE ELEVATION: Approx. feet MSL	MONITORING WELL CONSTRUCTION	PID READING	S.P.T. BLOWS/F
DEPTH (FEET)	SAMPLE NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	DETAIL	(10.0eV)	"MODIFIED FOR 3" O.D. SAMPLER
30	MW3-5		Brown/reddish brown, fine to coarse SAND with fine to medium GRAVEL, lenses of fine to medium sand, wet, grace little clay.			
35			¥ Water level at time of drilling.			
33	MW3-6		Increase in fines, brown fine to coarse SAND with silt, little clay trace of gravel, interbedded with lenses of fine to coarse sand.			
40			Brown, stiff, silty CLAY with fine to coarse sand, little gravel, moist. Wet, clayey sand.			
40	MW3-7		Yellow-brown, stiff, sandy SILT, little fine to medium gravel, lenses of stiff silt with fine to medium sand. Becomes more CLAYEY. No odors			
45			Increase in gravel at 43 to 44 feet. Brown, wet, silty CLAY with little fine to coarse sand, trace of fine gravel.			
50		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Brown, wet, fine to coarse SAND with fine to medium GRAVEL. Wet.			
		0 0 0	Wet, fine to coarse SAND and fine to medium GRAVEL. Bottom of boring at approximately 53 feet.			
55						
~ 0						
60		 ^	2900 LADD AVENUE	WELL NO,: MW3		FIGURE
	NGE			DATE: March 1995		NO.
IN	CORPORAT	ED	LIVERMORE, CALIFORNIA	JOB NO.: 3174-F7		2

MONITORING WELL DETAIL

PROJECT NUMBER 3174-F7	DATE OF INSTALLATION July 1, 1994
PROJECT NAME 2900 Ladd Avenue	TOP OF CASING ELEV.
COUNTYAlameda	GROUND SURFACE ELEV.
WELL PERMIT NO. 94371	DATUM

B. DIAMETER



EXPLORATORY BORING

- A. TOTAL DEPTH _____7.25 IN.
- DRILLING METHOD Hollow Stem Auger

WELL CONSTRUCTION

- <u>53</u> FT. C. CASING LENGTH MATERIAL Schedule 40 PVC
- DIAMETER
- ____25 FT. D. SLOTTED INTERVAL LENGTH SLOTTED INTERVAL FROM 28 TO 53 FT.
 - 0.020 IN. SLOT SIZE
- E. FILTER PACK INTERVAL 26 TO 53 FT.
 - FILTER MATERIAL No. 3 Monterey Sand
- F. FILTER PACK SEAL 24 TO 26 FT.
 - SEAL MATERIAL Bentonite Pellets
- G. GROUT INTERVAL 0 TO 24 FT.
- GROUT MATERIAL Type I/II Portland Cement
- H Flush Mount Cristie Box

	~	8 2	DATE OF BORING: June 30, 1994			N
(LEEL)	лмве	ON A	SURFACE ELEVATION: Approx. feet MSL	MONITORING WELL CONSTRUCTION	PID READING	S.P.T.
DEPTH (FEET)	SAMPLE NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	DETAIL	(10.0eV)	*MODIFTE FOR 3" O.D. SAMPLEF
0			Dark brown, moist, clayey LOAM.	Type VII Portland		
			Increase in gravel.	Cement		
5			Brown/dark brown, moist, silty CLAY with gravel, some sand.	\\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
			Clayey SAND with fine to medium gravel, brown, moist.			
			Moist clayey SAND and GRAVEL, brown.		i i	
10	MW4-1		Brown, wet SAND and GRAVEL, trace of clay, angular gravels.			
			Brown, wet, SAND and GRAVEL, little silt and clay.			
15	MW4-2				310	
			Brown, wet, SAND and GRAVEL, trace of clay.			
20	MW4-3		Brown, wet, fine to coarse SAND and fine to coarse GRAVEL, little clay, slight odor.		268	
			Increase in clay content, wet.	Bentonite seal		
-25	MW4-4		Brown/yellow brown, clayey fine to coarse SAND, moist.	0.01 in slotted 2 in. PVC pipe with #3	90	
-30			Brown, moist/wet, fine to coarse SAND with some clay, little fine to medium gravel.	Monterey sand		
			2900 LADD AVENUE	WELL NO.: MW4		FIGURE
	NGE		LIVERMORE, CALIFORNIA	DATE: March 1995 JOB NO.: 3174-F7		NO. 3


"

			TARTE OF BODYNG I GO 4004			
_	麗	AND	DATE OF BORING: June 30, 1994	- LONGODING VIEW	DYD	N
	TOME	TON	SURFACE ELEVATION: Approx. feet MSL	MONITORING WELL CONSTRUCTION	PID READING	S.P.T. BLOWS/FT
DEPTH (FEET)	SAMPLE NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	DETAIL	(10.0eV) (ppm)	*MODIFIED FOR 3" O.D. SAMPLER
<u> </u>		<u> </u>		1	- Tr7	
-30	MW4-5	0.0	Brown SAND and GRAVEL (large angular gravel fragments in liner).		116	
			Yellow-brown, moist sandy CLAY, fine to coarse sand, trace of gravel. Clay increase with fine to coarse sand and a trace of fine gravel.			
-35	MW4-6		Yellow-brown/brown, moist clayey SILT, no odor.		34	
			Increase in gravel.			
-40 -	MW4-7		Moist, brown, hard, fine to coarse SAND and GRAVEL, trace of clay and silt.		14	
-			Brown, moist, fine to coarse sandy CLAY with fine to medium gravel.			
-45 -	MW4-8		Brown, moist, fine to coarse SAND and fine to coarse GRAVEL. Water at time of drilling.			
a		6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Brown, wet, fine to coarse SAND with little fine to medium gravel.			
-50		2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Clayey fine to coarse SAND with GRAVEL, wet.			
-			Bottom of boring at approximately 53 feet.	<u> 2781—1978 </u>		
-55	The state of the s					7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
-60						
	```````	$\sim$	2900 LADD AVENUE	WELL NO.: MW4		FIGURE
	NGE (		LIVERMORE, CALIFORNIA	DATE: March 1995		NO.
IN	OMII	-1.7	LIVERMORE, CALIFORNIA	JOB NO.: 3174-F7		<u> </u>

:

## MONITORING WELL DETAIL

PROJECT NUMBER 3174-F7	DATE OF INSTALLATION June 30, 1994
PROJECT NAME 2900 Ladd Avenue	TOP OF CASING ELEV.
COUNTY Alameda	GROUND SURFACE ELEV.
WELL PERMIT NO. 94371	DATUM



### EXPLORATORY BORING

- A. TOTAL DEPTH <u>53</u> FT.

  B. DIAMETER <u>7.25</u> IN.
  - DRILLING METHOD Hollow Stem Auger

### WELL CONSTRUCTION

- C. CASING LENGTH _____53 ___FT.

  MATERIAL Schedule 40 PVC
  - DIAMETER 2 IN.
- D. SLOTTED INTERVAL LENGTH 25 FT.
  - SLOTTED INTERVAL FROM 28 TO 53 FT.
  - SLOT SIZE 0.020 IN.
- E. FILTER PACK INTERVAL 26 TO 53 FT.
  - FILTER MATERIAL No. 3 Monterey Sand
- F. FILTER PACK SEAL 24 TO 26 FT.
  - SEAL MATERIAL Bentonite Pellets
- G. GROUT INTERVAL 0 TO 24 FT.
- GROUT MATERIAL Type I/II Portland Cement
- H. Flush Mount Cristie Box

**ENGEO**INCORPORATED

			Q	DATE OF BORING: June 28, 2000		OVM	IN PI	ACE
ET)	SYRI	MBER	ON AN	SURFACE ELEVATION: Approx. 490 feet (149 meters)	BLOWS/FT	READING P.I.D.	DRY	MOIST.
DEPTH (FEET)	DEPTH (METEKS)	SAMPLE NUMBER	LOG, LOCATION AND TYPE OF SAMPLE	DESCRIPTION	,	(10.0eV) (Parts Per million)	UNIT WEIGHT  (PCF)	% DRY
0 -			900	2 inches Asphalt over 4 inches of Aggregate Baserock.				
-1	1			CLAYEY GRAVEL (GC), dark brown, moist, gravels to 2/3 inches maximum diameter, subangular.		1.5		
5 -2	2	<b>5-</b> l		CLAYEY GRAVEL (GC), gravels to 1 1/4 inch maximum diameter, subangular to subrounded, very moist, very dense.	75	1.2		
10 -3	3			subangular to subrounded, very moist, very dense.		100		
-4	+	5-2		CLAYEY GRAVEL (GC), dark gray, moderate petroleum odor.	75	1124		
15	5	5-3		SANDY lean CLAY (CL), mottled dark yellowish brown/gray, moist, fine-grained sand, moderate petroleum odor, stiff.	19	394		
20	6							
-7	7	5-4		SILTY, CLAYEY fine SAND (SC-SM), dark gray with dark yellow brown mottling, wet, very dense.  CLAYEY GRAVEL (GC), dark gray with dark yellowish brown mottling, very moist, with sand, dense.	85	190.4		
25		5-5		✓ Water level at 24.4 feet, at 11:30.	55	28.5		
-8	8			Bottom of boring at approximately 25 feet. Ground water encountered at 24.4 feet during drilling.				
30	9						1	
$\mathbf{E}$	N	GE	O	LVJUSD MAINTENANCE YARD	BORING DATE: Aug		V-5	FIGURE NO.
		PORA'	-	LIVERMORE, CALIFORNIA		3174.3.050.02	CHECKED BY	

BORING/WELL NO. MW-5


## MONITORING WELL DETAIL


PROJECT NUMBER 3174.3.050.02 DATE OF INSTALLATION 5/28/2000 PROJECT NAME LVJUSD MAINTENENCE YARD TOP OF CASING ELEV. GROUND SURFACE ELEV. 482 FT. (APPROX) COUNTY ALAMEDA WELL PERMIT NO. 20102 DATUM EXPLORATORY BORING 25 FT. A. TOTAL DEPTH B. DIAMETER _____**8**____1N. DRILLING METHOD CONTINUOUS FLIGHT HOLLOW STEM AUGER WELL CONSTRUCTION 24.5 FT. C. CASING LENGTH MATERIAL SCH 40 PVC _____2 IN. DIAMETER ____10___FT. D. SLOTTED INTERVAL LENGTH SLOTTED INTERVAL FROM 15 TO 25 FT. 0.010 IN SLOT SIZE E. FILTER PACK INTERVAL 14 TO 25 FT. FILTER MATERIAL MONTEREY #2/16 SAND D F. FILTER PACK SEAL 13 TO 14 FT. SEAL MATERIAL BENTONITE CHIPS G. GROUT INTERVAL 0.5 TO 13 FT. GROUT MATERIAL NEET CEMENT



H 12" DIAMETER FLUSH MOUNT MONUMENT


- B ---








	Client: ACC Environmental Consultants	Date: 11/22/2011
į	Project ID: Livermore MIP	Location:






Client: ACC Environmental Consultants	Date: 11/22/2011
Project ID: Livermore MIP	Location:






Client: ACC Environmental Consultants	Date: 11/22/2011
Project ID: Livermore MIP	Location:






	COLUMN TO THE PROPERTY OF THE
Client: ACC Environmental Consultants	Date: 11/22/2011
Project ID: Livermore MIP	Location:





	1 1/0/ 1/00 1/1/1/
Client: ACC Environmental Consultants	Date: 11/22/2011
Project ID: Livermore MIP	Location:





		THE PROCESSIN
	Client: ACC Environmental Consultants	Date: 11/22/2011
1	Project ID: Livermore MIP	Location: