

12/21/92
12:100 PM

566 Heggenburger Rd
Oakland

Site visit
Area fenced

Free water
pumped out H₂O/product 12/18/92
FP observed. appears to be all

over the site - TOG, TPH₂, TPH₃
BTXE 182 TO



12/21/92 D3216211255-8
566 Heggenburger Rd Anco.
FP - tank pit



12/21/92 D3216211255-8
566 Heggenburger Rd Anco
sewer line



12/21/92 03216211255-8
566 Heggenberger Rd Area
Scour line at back of property



12/21/92 03216211255-8
566 Heggenberger Rd. Area
valley sidewalk next to
bldg.



12/21/92 03216211255-8
566 Heggenberger Rd Area
valley
Scour line - FP.



12/17/92
Sheen on water



Middle Street tanks, some wrap
566 Heg 12/17/92 deteriorated



North pit wall 12/17/92



3-10K tanks in pit @ 566
Heg Rd. 12/17/92



12-17-92 Black liquid in pit
566 Hwy Rd Area



Pit #1, over excavated to Grid
12/18/92, H₂O coming from under former Pipeline
Area



(P) From Hwy Rd looking towards
Station. Large storm drain (re) &
Sanitary sewer left slightly exposed



The S east corner of pit w/ only
natural opening in 12/18/92

12/18/92

566 Hwy Rd

94621



Dead Heads in rear
South pit area - 1/17/79 ✓