



VIP Station  
3889 C.V.



VIP Station  
3889 C.V. Blvd

10-14-93



Station  
C.V. Blvd

10-14-93

4/28/93



VIP  
3089 Castro Valley Bl  
Castro Valley

FP on EW in gasoline UST pit

4/28/93

VIP  
3089 C.V. Blvd  
Castro Valley

~ sampling in piping / dispenser  
trenches





4/26/93

VIP  
3889 C.V. Blvd  
Castro Valley

note FP on GW in gasoline pit



4/28/93

VIP  
3889 C.V. Blvd  
Castro Valley



4-26-93



VIP Station  
3889 Castro Valley Blvd  
Castro Valley

Arrow points to fuel leak into SE corner  
of UST pit from product line.

4-26-93

VIP Station  
3889 Castro Valley Blvd  
Castro Valley

View into the west end of pit.  
Station building in back ground.





4-26-93



VIP Station  
3889 Castro Valley Blvd  
Castro Valley

4-26-93

VIP Station  
3889 Castro Valley Blvd  
Castro Valley



Note "cascade" of fuel leaking from product piping into NE portion of UST pit.

4/26/93

VIP  
3889 C.v. Blvd  
Castro Valley



Corrosion pits in gasoline  
UST

4/26/93

VIP  
3889 C.V. Blvd  
Castro Valley



holes in  
waste oil  
UST



4/26/93

VIP  
3589 Castro Valley Blvd



holes in  
waste oil  
LST



4/26/93

VIP  
3089 C.V. Blvd  
Castro Valley

- note GW and discolored soil in