

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT

EMERGENCY <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE DISTRIBUTION SHOWN ON THE INSTRUCTION SHEET ON THE BACK PAGE OF THIS FORM.	
REPORT DATE 05/03/93		CASE #		SIGNED: <i>[Signature]</i> DATE: 5/17/93	
REPORTED BY	NAME OF INDIVIDUAL FILING REPORT LALJI PATEL / PAWAN GUPTA		PHONE: 510-828-0768 SIGNATURE: <i>[Signature]</i>		
	REPRESENTING: <input checked="" type="checkbox"/> OWNER/OPERATOR <input type="checkbox"/> REGIONAL BOARD <input type="checkbox"/> LOCAL AGENCY <input type="checkbox"/> OTHER		COMPANY OR AGENCY NAME VIP SERVICE STATION		
ADDRESS: 385 CENTURY CIRCLE, DANVILLE, CA 94526					
RESPONSIBLE PARTY	NAME VIP SERVICE STATION <input type="checkbox"/> UNKNOWN		CONTACT PERSON: PAWAN GUPTA / LALJI B. PATEL		PHONE: 510-226-0136 / (510) 838-0768
	ADDRESS: 385 CENTURY CIRCLE, DANVILLE, CA 94526				
SITE LOCATION	FACILITY NAME (IF APPLICABLE) VIP SERVICE STATION		OPERATOR PAWAN GUPTA / LALJI PATEL		PHONE: SAME AS ABOVE / 510-582-0201
	ADDRESS: 3889 CASTRO VALLEY BLVD, CASTRO VALLEY, ALAMEDA 94546 CROSS STREET: ASPEN AVENUE				
IMPLEMENTING AGENCIES	LOCAL AGENCY: ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY		CONTACT PERSON: SCOTT SEERY		PHONE: (510) 271-4530
	REGIONAL BOARD: S.F. BAY REGION WQCB				
SUBSTANCES INVOLVED	(1) NAME: GASOLINE		QUANTITY LOST (GALLONS): <input checked="" type="checkbox"/> UNKNOWN		
	(2) NAME: WASTE OIL		QUANTITY LOST (GALLONS): <input checked="" type="checkbox"/> UNKNOWN		
DISCOVERY/ABATEMENT	DATE DISCOVERED: 04/26/93		HOW DISCOVERED: <input type="checkbox"/> INVENTORY CONTROL <input type="checkbox"/> SUBSURFACE MONITORING <input type="checkbox"/> NUISANCE CONDITIONS <input type="checkbox"/> TANK TEST <input checked="" type="checkbox"/> TANK REMOVAL <input type="checkbox"/> OTHER		
	DATE DISCHARGE BEGAN: <input checked="" type="checkbox"/> UNKNOWN		METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY): <input checked="" type="checkbox"/> REMOVE CONTENTS <input checked="" type="checkbox"/> CLOSE TANK & REMOVE <input type="checkbox"/> REPAIR PIPING <input type="checkbox"/> REPAIR TANK <input type="checkbox"/> CLOSE TANK & FILL IN PLACE <input type="checkbox"/> CHANGE PROCEDURE <input type="checkbox"/> REPLACE TANK <input type="checkbox"/> OTHER		
	HAS DISCHARGE BEEN STOPPED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, DATE: 04/26/93				
SOURCE/CAUSE	SOURCE OF DISCHARGE: <input type="checkbox"/> TANK LEAK <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> PIPING LEAK <input type="checkbox"/> OTHER		CAUSE(S): <input type="checkbox"/> OVERFILL <input type="checkbox"/> RUPTURE/FAILURE <input type="checkbox"/> SPILL <input type="checkbox"/> CORROSION <input checked="" type="checkbox"/> UNKNOWN <input type="checkbox"/> OTHER		
	CASE TYPE: CHECK ONE ONLY <input type="checkbox"/> UNDETERMINED <input type="checkbox"/> SOIL ONLY <input checked="" type="checkbox"/> GROUNDWATER <input type="checkbox"/> DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)				
CURRENT STATUS	CHECK ONE ONLY <input type="checkbox"/> NO ACTION TAKEN <input type="checkbox"/> PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED <input type="checkbox"/> POLLUTION CHARACTERIZATION <input checked="" type="checkbox"/> LEAK BEING CONFIRMED <input type="checkbox"/> PRELIMINARY SITE ASSESSMENT UNDERWAY <input type="checkbox"/> POST CLEANUP MONITORING IN PROGRESS <input type="checkbox"/> REMEDIATION PLAN <input type="checkbox"/> CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY) <input type="checkbox"/> CLEANUP UNDERWAY				
	REMEDIAL ACTION: CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS) <input type="checkbox"/> CAP SITE (CD) <input type="checkbox"/> EXCAVATE & DISPOSE (ED) <input type="checkbox"/> REMOVE FREE PRODUCT (FP) <input type="checkbox"/> ENHANCED BIO DEGRADATION (IT) <input type="checkbox"/> CONTAINMENT BARRIER (CB) <input type="checkbox"/> EXCAVATE & TREAT (ET) <input type="checkbox"/> PUMP & TREAT GROUNDWATER (GT) <input type="checkbox"/> REPLACE SUPPLY (RS) <input type="checkbox"/> VACUUM EXTRACT (VE) <input type="checkbox"/> NO ACTION REQUIRED (NA) <input type="checkbox"/> TREATMENT AT HOOKUP (HU) <input type="checkbox"/> VENT SOIL (VS) <input checked="" type="checkbox"/> OTHER (OT) WAITING FOR SAMPLING RESULTS				
COMMENTS	• WASTE OIL TANK, 500 GALLON SIZE, SHOWED SIGNS OF CORROSION.				
	• GASOLINE TANKS, 3-10,000 GALS, APPEARED IN GOOD SHAPE (NO SIGN OF LEAK) HOWEVER, UST pit (gasoline) showed signs of releases.				