## RECEIVED

1:10 pm, Apr 30, 2009

Alameda County
Environmental Health

## QUARTERLY SUMMARY REPORT 3rd QTR - 1998

(Jul. - Sep.)

BACKGROUND: The site contains an operating 76 service station. Soil samples were collected from the product pipe trenches in October 1991. Six monitoring wells MW-1 through MW-6 were installed in 1992. The waste oil tank was removed from the site in September of 1994. Wells MW-9 and MW-10 were installed and wells MW-4 and MW-5 were destroyed in January 1995. Replacement of the underground fuel tanks and product piping was conducted (beginning) in March of 1995. Extensive excavation of hydrocarbon-impacted soil was conducted during tank replacement activities. Approximately 5730 cubic yards of soil were removed and

TOSCO 76 BRANDED FACILITY #5043 449 Hegenberger Road Oakland, CA

Oakland

Alameda

CITY/COUNTY ID #:

**COUNTY:** 

\5043qsr.q3

transported to approved landfills. Approximately 125,000 gallons of groundwater were removed and disposed of during excavation activities. Monitoring wells MW-1, MW-2 were properly destroyed in April of 1995 during continuing over-excavation activities. Wells MW-7 and MW-8 were installed in April 1997. Installed passive skimmer in MW-6 in 1996. Free product skimmed in MW-6 is emptied on a monthly basis.  RECENT QUARTER ACTIVITIES: Monitored and sampled groundwater monitoring wells. Emptied skimmer and bailed free product from MW-6 monthly.  NEXT QUARTER ACTIVITIES: Monitor and sample groundwater monitoring wells. Continue free product removal from MW-6.			
		CHARACTERIZATION/REMEDIAL STATUS:	
		Soil contamination delineated?	yes
Dissolved ground water delineated?	yes		
Free product delineated?	yes		
Amount of groundwater contaminant recovered			
this quarter (free product)?	<u>0.1 (gal)</u>		
Historically? (total volume of free product extracted)	16.2 (gal)		
Soil remediation in progress?	no		
- anticipated start?	N/A		
- anticipated completion?	July 1995		
Dissolved/free product remediation			
in progress?	no		
- anticipated start?	<u>unknown</u>		
- anticipated completion?	unknown		
CONSULTANT/CONTRACTOR:	Gettler-Ryan Inc.		
50H3	$\checkmark$		
140081.01			