TO: Ms. Karen Streich

Chevron Products Company

P.O. Box 6004

San Ramon, CA 94568

PROJ. #:

DG90338H.4C01

SUBJECT: Report, Chevron SS# 9-0338

5500 Telegraph Avenue Oakland, California

#### FROM:

Geoffrey D. Risse **Project Geologist** Gettler-Ryan Inc. 3140 Gold Camp Drive, Suite 170 Rancho Cordova, California 95670

WE	ARE	<b>SENDING</b>	YOU:

COPIES	DATED	D	DESCRIPTION						
1	· · · · · <u>- · · · · · · · · · · · · · ·</u>	Soil Bori	ng Sampling Report, Chevron SS# 9-0338						
THESE ARE T	RANSMITTED as	checked below:							
[] For review	ew and comment	[] Approved as submitted	[] Resubmitcopies for approval						
[] As reque	ested	[] Approved as noted	[] Submit _ copies for distribution						
[ ] For app	roval	[] Return for corrections	[] Return corrected prints						
[X] For you	r files								

#### COMMENTS:

Delta Environmental Consultants Inc. network associate Gettler-Ryan Inc. will also be submitting a copy of the above referenced report to the following:

Mr. Barney Chan, Alameda County Health Care Services Agency-Environmental Health Department, 1131 Harbor Bay Parkway, Ste. 250, Alameda, California, 94502

Mr. James Brownell, Delta Environmental Consultants Inc., 3164 Gold Camp Dr., Ste. 200, Rancho Cordova, California 95670

If you have any questions, please contact our Sacramento office at (916) 631-1300.



# Alameda County SEP 2 6 2002 Environmental Healthour SOIL BORING SAMPLING REPORT

3164 Gold Camp Drive Suite 200 Rancho Cordova, CA 95670-6021 U.S.A. 916/638-2085 FAX: 916/638-8385

at Chevron Service Station No. 9-0338 5500 Telegraph Avenue Oakland, California

Report No. DG90338H.4C01 Delta Project No. DG90-338-H

#### Prepared for:

Ms. Karen Streich Chevron Products Company P.O. Box 6012 San Ramon, California 94583-2324

#### Prepared by:


Delta Environmental Consultants Inc. Network Associate Gettler-Ryan Inc. 3140 Gold Camp Drive, Suite 170 Rancho Cordova, California 95670

> Geoffrey D. Risse Staff Geologist

David W. Herzog Senior Geologist R.G. #7211

September 20, 2002

### TABLE OF CONTENTS



INTRODUC	CTION	1 Health 1
SITE DESC	CRIPTION	
		I
<b>PREVIOUS</b>	SENVIRONMENTAL ACTIVITIES	2
Discussion	1	3
FIELD ACT	rivities	3
RESULTS O	OF THE SUBSURFACE INVESTIGATION	4
CHEMICA	L ANALYTICAL RESULTS	4
Chemical A	nalytical Procedures	4
0-21 41-42	and Danasida	
Son Analyti	cal Results	4
Groundwate	er Analytical Results	4
Preducero	ON	4
DISCUSSIC	JN	4
	TABLES	
Table 1.	Historical Soil Chemical Analytical Results	
Table 2.	Soil Chemical Analytical Results	
Table 3.	Groundwater Chemical Analytical Results	
	<b>,</b>	
	FIGURES	
Figure 1.	Vicinity Map	
Figure 2.	Extended Site Plan	
_	APPENDICES	
Appendix A.	Field Methods and Procedures	
Appendix B.		

Appendix C Boring Logs

Appendix D Chemical Analytical Report and Chain-of-Custody Form

at

Chervon Service Station No. 9-0338 5500 Telegraph Avenue Oakland, California

Report No. DG90338H.4C01 Delta Project No. DG90-338-H

#### INTRODUCTION

This report presents the results of additional site assessment performed by Delta Environmental Consultants Inc. network associate Gettler-Ryan Inc. (GR) at the above referenced site. The purpose of this work was to determine whether the utility trenches adjacent to the site are acting as preferential pathways, and to further delineate the petroleum hydrocarbon plume downgradient of the site. The scope of work performed included: updating the site safety plan; obtaining a drilling permit from the Alameda County Public Works Agency (ACPWA) and excavation permits from the City of Oakland; advancing four hand auger off-site soil borings; collecting soil and grab groundwater samples from the soil borings; analyzing selected soil and groundwater samples; and preparing a report documenting the work performed. The scope of work performed during this investigation was originally proposed in report #DG90338G.3C01, Addendum to Plume Delineation Workplan, dated December 3, 2001, and was subsequently approved by the Alameda County Health Care Services Agency-Environmental Health Department (ACHCSA-EHD) in a letter dated December 6, 2001.

#### SITE DESCRIPTION

The subject site is a Chevron service station located at the northeastern corner of Telegraph Avenue and 55<sup>th</sup> Street in Oakland, California (Figure 1). Site facilities consist of a station building, a car wash, six dispenser islands, and two gasoline underground storage tanks (USTs) that share a common pit near the northern site boundary. Pertinent site features are shown on Figure 2. The site vicinity is used for transportation, commercial, and residential purposes. The subject site is bordered to the north by State Route 24, to the east by residential housing, to the west by Telegraph Avenue, to the south by 55<sup>th</sup> Street. Beyond 55<sup>th</sup> Street to the south and southwest lie commercial buildings. West of Telegraph Avenue lies State Route 24.

The subject site is located on the East Bay Plain, approximately 2.5 miles east of San Francisco Bay and 2 miles north of Lake Merritt. The local topography is relatively flat at an elevation of approximately 125 feet above mean sea level.

Chevron Service Station No.9-0338 5500 Telegraph Avenue Oakland, California Page 2

As mapped by E.J. Helley and others (1979, Flatland Deposits of the San Francisco Bay Region, California: U.S. Geological Survey Professional Paper 943), soil in the site vicinity consists of Holoceneage Bay Mud containing unconsolidated saturated dark plastic carbonaceous clay and silty clay. These materials are underlain by late Pleistocene-age alluvium consisting of weakly consolidated slightly weathered, poorly sorted and irregularly interbedded clay, silt, sand, and gravel.

The nearest surface water body is Glen Echo Creek located approximately 1 mile south of the site. Based on groundwater monitoring data, the groundwater flow direction in the vicinity of the site has fluctuated between the southwest and the southeast.

#### PREVIOUS ENVIRONMENTAL ACTIVITIES

- 1988: October Chevron removed one 1,000-gallon waste oil UST. A soil sample was collected from the beneath the waste oil UST at a depth of 8 feet below ground surface (bgs) (Blaine Tech Services, *Soil Sampling Report*, dated January 13, 1989).
- 1989: July Chevron replaced the product lines associated with the gasoline USTs. During the removal and replacement of the product lines, contaminated soil was discovered in the westernmost product line trench (closest to Telegraph Avenue). Ten compliance soil samples were collected from the westernmost product trench at depths between 4.0 and 6.75 feet bgs (Geotest Report No. 90686-01 dated July 1989).

  November GR installed groundwater monitoring wells C-1, C-2, and C-3. Petroleum hydrocarbons were not detected in the soil samples collected from the well borings. Initial groundwater samples from the wells did not contain dissolved petroleum hydrocarbons (GR report no. 7263-2, Well Installation Report, dated February 14, 1990).
- 1998: July GR removed three 10,000-gallon gasoline USTs, one 1,000-gallon waste oil UST, product lines and dispenser islands, three hydraulic hoists, and an oil/water separator. Soil samples were collected from beneath the USTs, the product lines, the dispenser islands, the hydraulic hoists and the oil/water separator (GR report no. 1288.02, Sampling During Tank and Product Line Replacement at Chevron Station #9-0338, 5500 Telegraph Ave., Oakland, California, dated November 11, 1998).

  October GR supervised the destruction of monitoring well C-3. Following the destruction of well C-3, a grab groundwater sample was collected from a UST backfill well. Methyl tert-butyl ether was detected in the grab groundwater sample at a concentration of 15,000 parts per billion (ppb) (GR report no. 346456.01-2, Well Destruction Letter Report, dated October 5, 1998).
- 1999: May GR supervised the installation of two groundwater monitoring wells (C-4 and C-5) and the replacement of two existing groundwater monitoring wells (C-1A and C-2A) (GR report no. 346456.02-2, Monitoring Well Replacement and Installation Report, dated July 1, 1999).
- 2001: September GR prepared and submitted a Site Conceptual Model (SCM). The SCM presented summaries of fieldwork to date, description of hydrogeological conditions, contaminant distributions over time and space, current and potential receptors, and recommendations for future

Chevron Service Station No.9-0338 5500 Telegraph Avenue Oakland, California Page 3

work (Report no. DG90338B.4C01, Site Conceptual Model Report, dated September 26, 2001).

#### **Discussion**

Residual petroleum hydrocarbon impacted soil beneath the site is centered in the vicinity of the former USTs. Historical soil analytical data are presented in Table 1.

Boring logs from previous environmental investigations indicate that native soil beneath the site consists of sandy clays and silts underlain by clayey gravels and silty sands. Groundwater is first encountered at a depth of approximately 6 feet bgs.

Groundwater monitoring and sampling has been conducted quarterly since November 1989. During the latest monitoring and sampling event on June 25, 2002, MtBE was reported in wells C-1A, C-2A, C-4, and C-5 at concentrations of 7.5, 29, 21 and 180 ppb, respectively. Total Petroleum Hydrocarbons as gasoline (TPHg) were reported in wells C-1A, C-2A and C-5 at concentrations of 1,800, 1,100, and 79 ppb, respectively. Benzene was reported in wells C-2A and C-5 at concentrations of 17 and 7.7 ppb, respectively. Concentrations of dissolved petroleum hydrocarbons in the site wells appear to be stabilizing. Depth to water during this monitoring event ranged from 8.02 to 11.76 feet below top of casing, and groundwater flow was to the south at a gradient of approximately 0.02, which is consistent with historical data.

#### FIELD ACTIVITIES

To determine whether the utility trenches adjacent to the site are acting as preferential pathways, and to further delineate the petroleum hydrocarbon plume downgradient of the site, GR advanced four soil borings (HA-1 through HA-4) at the locations shown on Figure 2. Field work was performed in accordance with GR's Site Safety Plan dated August 6, 2002. GR Field Methods and Procedures are included in Appendix A. Underground Service Alert was notified prior to beginning site activities. The soil borings were advanced by GR (C57 #220793) under ACPWA permit no. 02-802 and City of Oakland excavation permit nos. X0200636 through X0200638 (Appendix B).

On August 12 and 13, 2002, four soil borings were advanced (HA-1 through HA-4) adjacent to the utility trenches in Telegraph Avenue and 55<sup>th</sup> Street. Borings HA-2 and HA-3 were advanced to a depth of 13.5 feet bgs. Boring HA-1 was advanced to a depth of 18.0 feet bgs. Boring HA-4 was advanced to a depth of 11.5 feet bgs. The borings were advanced using a 3.5-inch diameter hand auger. Soil samples were collected using a slide hammer. A GR geologist performed the field activities. Soil samples were collected from the borings for description and preparation of a log, and for possible chemical analysis. Grab groundwater samples were also collected from the borings. Boring logs are included in Appendix C. Borings were backfilled with pea gravel, compacted, then completed to ground surface per request of the City of Oakland Public Works Agency.

Chevron Service Station No.9-0338 5500 Telegraph Avenue Oakland, California Page 5

#### RESULTS OF THE SUBSURFACE INVESTIGATION

Soil encountered during this investigation consisted of interbedded clay, clay with sand, and clay with gravel to the total depth explored. Groundwater was encountered in boring HA-1 at approximately 16 feet bgs, in boring HA-2 and HA-3 at 13 feet bgs, and in boring HA-4 at 11 feet bgs. Detailed descriptions of the soil encountered in the borings are presented on the boring logs in Appendix C.

#### CHEMICAL ANALYTICAL RESULTS

A total of four soil samples and four grab groundwater samples collected from the soil borings were submitted under chain-of-custody for chemical analysis. Analyses were performed by Lancaster Laboratories (ELAP #2116) of Lancaster, Pennsylvania. Copies of the laboratory reports and chain-of-custody form are included in Appendix D. Soil and groundwater chemical analytical data are summarized in Tables 2 and 3, respectively.

#### **Chemical Analytical Procedures**

The soil and groundwater samples were analyzed for TPHg by EPA Method 8015 Modified, and for benzene, toluene, ethylbenzene, and total xylenes (BTEX) and MtBE by EPA Method 8021B. Groundwater samples were additionally analyzed for MtBE, ethyl tert-butyl ether (ETBE), tert-amyl methyl ether (TAME), di-isopropyl ether (DIPE), and tert-butyl alcohol (TBA) by EPA Method 8260B.

#### Soil Analytical Results

Soil samples collected from borings HA-1 through HA-4 were non-detect for TPHg, BTEX, and MtBE.

#### **Groundwater Analytical Results**

The grab groundwater samples collected from borings HA-1 through HA-4 were non-detect for TPHg, BTEX, ETBE, DIPE, TAME, and TBA. MtBE was reported in grab groundwater samples from borings HA-3 and HA-2 at concentrations of 4.0 and 37 ppb, respectively, by EPA Method 8260B.

#### DISCUSSION

TPHg, BTEX or MtBE were not detected in soil during this investigation. Low levels of MtBE were

reported in the grab groundwater samples from borings HA-2 (37 ppb) and HA-3 (4.0 ppb). Based on the depth to water encountered in the borings (11 to 16 feet bgs), the burial depth of sanitary sewer and storm drain lines in Telegraph Avenue and 55<sup>th</sup> Street (8.5 to 12 feet bgs), and that boring HA-4, which is located in the downslope direction for the sanitary sewer and storm drain lines, was non-detect for petroleum hydrocarbons, it appears that the utility trenches are mostly above the groundwater table and do not appear to be acting as preferential pathways for plume migration. Based on the results of this and previous investigations, no further subsurface assessment is warranted at this time. GR recommends that

the monitoring and hydrocarbon trends.	sampling	of the	site	wells	be c	continue	ed in	order	to fu	rther	evaluate	the o	dissolved

Table 1
Historical Soil Chemical Analytical Results
Chevron Service Station No. 9-0338
5500 Telegraph Avenue
Oakland, California

Sample ID	Sample Depth (feet)	Sample Date	TPHg (ppm)	TPHd (ppm)	B (ppm)	T (ppm)	E (ppm)	X (ppm)	MtBE (ppm)	Lead (ppm)	TOG (ppm)	Chromium (ppm)	Cadmium (ppm)	Zinc (ppm)	Nickel (ppm)	TPHho (ppm)
WOOP	8	10/5/88	NA	ND	NA	NA	NA	NA	NA	NA	ND	NA	NA	NA	NA	NA
1		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
2		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
3		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
4		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
5		7/7/89	340	NA	0.24	0.09	0.74	4.0	NA	NA	NA	NA	NA	NA	NA	NA
5B		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
6		7/7/89	800	NA ·	3.5	11	12	59	NA	NA	NA	NA	NA	NA	NA	NA
6C		7/7/89	49	NA	0.37	ND	0.72	3.0	NA	NA	NA	NA	NA	NA	NA	NA
7		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
8		7/7/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
Southwest	6.75	7/11/89	130	NA	ND	ND	2.2	3.0	NA	NA	NA	NA	NA	NA	NA	NA
Southwest	4.5	7/14/89	73	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
Northwest	6.25	7/11/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
Northwest	4.0	7/14/89	1.5	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
Southeast	6.75	7/11/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
Southeast	5.0	7/14/89	ND	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
Northeast	6.25	7/11/89	480	NA	0.31	ND	10	28	NA	NA	NA	NA	NA	NA	NA	NA
Northeast	4.5	7/14/89	9.7	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
South	4.5	7/14/89	3	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA
North	5.0	7/14/89	1.8	NA	ND	ND	ND	ND	NA	NA	NA	NA	NA	NA	NA	NA

Table 1
Historical Soil Chemical Analytical Results
Chevron Service Station No. 9-0338
5500 Telegraph Avenue
Oakland, California

Sample ID	Sample Depth (feet)	Sample Date	TPHg (ppm)	TPHd (ppm)	B (ppm)	T (ppm)	E (ppm)	X (ppm)	MtBE (ppm)	Lead (ppm)	TOG (ppm)	Chromium (ppm)	Cadmium (ppm)	Zinc (ppm)	Nickel (ppm)	TPHho (ppm)
Sample 1D	(TCCE)		\PP***/	(PP)	(P.F)	(FF7	<u> </u>	CFF /	(11)	N. 1 . 2				····		
C-1	10.5	11/13/89	<1	NA	< 0.05	< 0.05	< 0.05	< 0.05	NA	NA	NA	NA	NA	NA	NA	NA
C-1	15.5	11/13/89	<1	NA	< 0.05	< 0.05	< 0.05	< 0.05	NA	NA	NA	NA	NA	NA	NA	NA
C-1	25.5	11/13/89	<1	NA	< 0.05	< 0.05	< 0.05	< 0.05	NA	NA	NA	NA	NA	NA	NA	NA
C-2	10.5	11/13/89	<1	NA	< 0.05	< 0.05	< 0.05	< 0.05	NA	NA	NA	NA	NA	NA	NA	NA
C-2	15.5	11/13/89	<1	NA	< 0.05	< 0.05	< 0.05	< 0.05	NA	NA	NA	NA	NA	NA	NA	NA
C-2	25.5	11/13/89	<1	NA	< 0.05	< 0.05	< 0.05	< 0.05	NA	NA	NA	NA	NA	NA	NA	NA
C-3	10.5	11/13/89	<1	<10	< 0.05	< 0.05	< 0.05	< 0.05	NA	<10	<20	16	1.0	39	NA	NA
C-3	15.5	11/13/89	<1	<10	< 0.05	< 0.05	< 0.05	< 0.05	NA	<10	<20	12	0.6	60	NA	NA
C-3	25.5	11/13/89	<1	<10	< 0.05	< 0.05	< 0.05	< 0.05	NA	10	<20	27	1.4	74	NA	NA
CX-1-9	9.0	7/22/98	<1.0	NA	0.013	0.0058	0.044	0.067	0.46	5.1	NA	NA	NA	NA	NA	NA
CX-2-9	9.0	7/22/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	0.28	6.8	NA	NA	NA	NA	NA	NA
CX-3-9	9.0	7/22/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	0.21	5.1	NA	NA	NA	NA	NA	NA
CX-4-9	9.0	7/22/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	0.74	3.3	NA	NA	NA	NA	NA	NA
CX-5-9	9.0	7/22/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.050	6.4	NA	NA	NA	NA	NA	NA
CX-6-9	9.0	7/22/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	0.31	6.2	NA	NA	NA	NA	NA	NA
CT-1-3.5	3.5	7/27/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	0.012	< 0.050	<1.0	NA	NA	NA	NA	NA	NA
CT-2-3.5	3.5	7/27/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	0.0057	< 0.050	2.8	NA	NA	NA	NA	NA	NA
CT-3-4	4.0	7/27/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	0.0057	< 0.050	1.0	NA	NA	NA	NA	NA	NA
CT-4-4	4.0	7/27/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	0.0057	< 0.050	<1.0	NA	NA	NA	NA	NA	NA
CT-5-4	4.0	7/27/98	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	0.0057	< 0.050	<1.0	NA	NA	NA	NA	NA	NA
CT-1-9	9.0	7/27/98	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<10
CT-2-9	9.0	7/27/98	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	<10

Table 1
Historical Soil Chemical Analytical Results
Chevron Service Station No. 9-0338
5500 Telegraph Avenue
Oakland, California

Sample ID	Sample Depth (feet)	Sample Date	TPHg (ppm)	TPHd (ppm)	B (ppm)	T (ppm)	E (ppm)	X (ppm)	MtBE (ppm)	Lead (ppm)	TOG (ppm)	Chromium (ppm)	Cadmium (ppm)	Zinc (ppm)	Nickel (ppm)	TPHho (ppm)
							0.0050	0.0050	.0.050	-1.0	2 600	24	<0.50	47	23	2,800
CT-3-9	9.0	7/27/98	1.6	2,000	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.050	<1.0	2,600					-
CW-1-9	9.0	7/22/98	<1.0	<1.0	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.050	<1.0	130	29.1	< 0.50	35.2	18.9	NA
_			<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.050	NA	NA	NA	NA	NA	NA	NA
C4-6	6.0	5/12/99							< 0.050	NA	NA	NA	NA	NA	NA	NA
C4-11	11.0	5/12/99	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050						NA	NA	NA
C5-6	6.0	5/12/99	<1.0	NA	< 0.0050	< 0.0050	< 0.0050	< 0.0050	< 0.050	NA	NA	NA	NA			
C5-11	11.0	5/12/99	1.3	NA	0.017	< 0.0050	< 0.0050	0.012	0.1	NA	NA	NA	NA	NA	NA	NA

#### **EXPLANATIONS**

NA = Not Analyzed

ppm = parts per million

TPHg = Total Petroleum Hydrocarbons as gasoline

TPHd = Total Petroleum Hydrocarbons as diesel

TOG = Total Oil and Grease

B = Benzene

T = Toluene

E = Ethylbenzene

X = Xylenes

MtBE = Methyl tert-butyl ether

TPHho = Total Petroleum Hydrocarbons as hydraulic oil

Table 2
Soil Chemical Analytical Results
Chevron Service Station No. 9-0338
5500 Telegraph Avenue
Oakland, California

Sample ID	Sample Depth (feet)	Sample Date	TPHg (ppm)	B (ppm)	T (ppm)	E (ppm)	X (ppm)	MtBE (ppm)
HA1-11.5	11.5	8/12/02	<1.0	<0.0050	<0.0050	<0.0050	< 0.015	<0.050
HA2-12.0	12.0	8/12/02	<1.0	<0.0050	<0.0050	<0.0050	< 0.015	< 0.050
HA3-11.0	11.0	8/13/02	<1.0	<0.0050	<0.0050	<0.0050	< 0.015	<0.050
HA4-11.0	11.0	8/13/02	<1.0	< 0.0050	<0.0050	<0.0050	<0.015	< 0.050

**Analytical Laboratory** 

Lancaster Laboratories (ELAP# 2116)

#### **Explanation**

ppm = parts per million

MtBE = Methyl-tert Butyl Ether

B = Benzene

T = Toluene

E = Ethylbenzene

X = Xylenes

TPHg = Total Petroleum Hydrocarbons as gasoline

### **Analytical Methods**

TPHg by LUFT Methods BTEX/MtBE by EPA 8021B

Table 3
Groundwater Chemical Analytical Results
Chevron Service Station No. 9-0338
5500 Telegraph Avenue
Oakland, California

Sample ID	Sample Date	TPHg (ppb)	B (ppb)	T (ppb)	E (ppb)	X (ppb)	MtBE (ppb)	ETBE (ppb)	DIPE (ppb)	TAME (ppb)	TBA (ppb)
HA1-W	8/13/02	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<0.5	<0.5	<0.5	<0.5	<5.0
HA2-W	8/12/02	<50	<0.50	<0.50	<0.50	<1.5	40/37	<0.5	<0.5	<0.5	<5.0
HA3-W	8/13/02	<50	<0.50	<0.50	<0.50	<1.5	3.9/4.0	<0.5	<0.5	<0.5	<5.0
HA4-W	8/13/02	<50	<0.50	<0.50	<0.50	<1.5	<2.5/<0.5	<0.5	<0.5	<0.5	<5.0

#### Explanation

ppb = parts per billion

TPHg = Total Petroleum Hydrocarbons as gasoline

B = Benzene

T = Toluene

E = Ethylbenzene

X = Xylenes

MtBE = Methyl-tert butyl ether

ETBE = Ethyl tert-butyl ether

DIPE = Di-isopropyl ether

TAME = Tert-amyl methyl ether

TBA = Tert-butyl alcohol

#### **Analytical Laboratory**

Lancaster Laboratories (ELAP# 2116)


#### **Analytical Methods**

TPHg by DHS LUFT Methods

BTEX by EPA Method 8021B

ETBE/DIPE/TAME/TBA by EPA Method 8260B

MtBE by EPA Method 8021B/MtBE by EPA Method 8260B






Chevron Service Station No. 9-0338 5500 Telegraph Avenue Oakland, California

DATE 7/01 REVISED DATE

PROJECT NUMBER

DG90338B.3C01
FILE NAME: P:\ENVIRO\CHEVRON\9-0338\VIC-9-0338.DWG | Layout Tab: CA-North

REVIEWED BY



-0338Ġ Š

EXTENDED SITE PLAN Chevron Service Station N 5500 Telegraph Avenue Oakland, California PATE 8/02

(925) 551-7555

RYAN

GETTLER - 6747 Serra CL, Suite J

#### **GETTLER-RYAN INC.**

## FIELD METHODS AND PROCEDURES HAND-AUGERED BORINGS

#### Site Safety Plan

Field work performed by Gettler-Ryan Inc. (GR) is conducted in accordance with GR's Health and Safety Plan and the Site Safety Plan. GR personnel and subcontractors who perform work at the site are briefed on the contents of these plans prior to initiating site work. The GR geologist or engineer at the site when the work is performed acts as the Site Safety Officer. GR utilizes a photoionization detector (PID) to monitor ambient conditions as part of the Health and Safety Plan.

#### Collection of Soil Samples

Hand-augered soil borings are drilled by a California-licensed well driller. A GR geologist is present to observe the drilling, collect soil samples for description and chemical analysis, and prepare a log the exploratory soil boring. Soil samples are collected from the boring with a hand-driven sampling device fitted with a 2-inch diameter, clean brass tube or stainless steel liner. After removal from the sampling device, soil samples are covered on both ends with Teflon sheeting, capped, labeled, and place in a cooler with blue ice for preservation. A chain-of-custody form is initiated in the field and accompanies the selected soil samples to the analytical laboratory.

#### Field Screening of Soil Samples

A PID is used to perform head-space analysis in the field for the presence of organic vapors from the soil sample. This test procedure involves placing a small amount of the soil to be screened in a sealed plastic bag. The bag is warmed in the sun to allow organic compounds in the soil sample to volatilize. The PID probe is inserted through the wall of the bag and into the headspace inside, and the meter reading is recorded in the field notes. Head-space screening is performed and results recorded as reconnaissance data only. GR does not consider field screening techniques to be verification of the presence or absence of hydrocarbons.

#### **Grab Groundwater Sampling**

Grab samples of groundwater are collected from the boring using a bailer. The groundwater sample is decanted into laboratory-supplied containers appropriate for the anticipated analyses. Sample bottles are then labeled and placed in chilled storage for transport to the analytical laboratory. A chain-of-custody form is initiated in the field and accompanies the groundwater samples to the analytical laboratory.

#### Storing and Sampling of Soil Stockpiles

Excavated material is stockpiled on and covered with plastic sheeting. Stockpile samples are collected and analyzed for disposal classification on the basis of one composite sample per 100 cubic yards of soil. Stockpile samples are composed of four discrete soil samples, each collected from an arbitrary location on the stockpile. The four discrete samples are then composited in the laboratory prior to analysis.

Each discrete stockpile sample is collected by removing the upper 12 to 18 inches of soil, and then driving the stainless steel or brass sample tube into the stockpiled material with a mallet or drive sampler. The sample tubes are then covered on both ends with Teflon sheeting, capped, labeled, and placed in a cooler with blue ice for preservation. A chain-of-custody form is initiated in the field and accompanies the selected soil samples to the analytical laboratory. Stockpiled soils are covered with plastic sheeting after completion of sampling.

Aug-09-02 11:15am From-Gettler-Ryan Inc
UU1-28-U1 IIU1 UD:40 111 tillitulli

+9186311317

T-555 P.002/003 F-349



## ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION
399 ELMHURST ST. HAYWARD CA. 94544-1395
PHONE (510) 670-5554
FAX (510)782-1939

DRILLING PERMI	T APPLICATION
FOR APPLICANT TO COMPLETE LOCATION OF PROJECT 5500 TELEGISTIPH AVE,	FOR OFFICE USE  PERMIT NUMBER WELL NUMBER  APN
the vron service station 9-0338)	PERMIT CONDITIONS Circled Permit Requirements Apply
CLIENT Chevron Products Company Name Chevron Products Company Address P.O. Box 6004 Phone (925) 842-1584 City Sun Ramon zip 94583	A. GENERAL  I. A permit application should be submitted so as to arrive at the ACPWA office five days prior to proposed starting date.
APPLICANT Name GeHler-Ry AN INC  Address 3140 Gold (ump or, stel 70 Phone 1916) 631-1317  City Lawano Condera Zip 46 6 70	2. Submit to ACPWA within 60 days after completion of permitted original Department of Water Resources-Well Completion Report.  3. Permit is void if project not begun within 90 days of approval date  B. WATER SUPPLY WELLS
TYPE OF PROJECT  Well Construction Geotechnical Investigation  Cathodic Protection II General II  Water Supply II Contamination M  Monitoring II Well Destruction II	I. Minimum surface seal thickness is two inches of coment grout placed by tremic.  2. Minimum seal depth is 50 feet for municipal and Industrial wells or 20 feet for domestic and irrigation wells unless a lesser depth is specially approved.  C. GROUNDWATER MONITORING WELLS  INCLUDING PIEZOMETERS
PROPOSED WATER SUPPLY WELL USE  New Domostic () Replacement Domostic ()  Municipal () Irrigation ()  Industrial () Other ()	1. Minimum surface seal thickness is two inches of coment grout placed by tremis. 2. Minimum seal depth for monitoring walls is the maximum depth practicable or 20 feet.  CHOTROMNICAL
DRILLING METHOD:  Mud Rolary II Air Rotary II Auger II  Cable II Other IV Hand Anger	Backfill bore hole by tremie with coment grout or comen grout/sand mixture. Upper two-three feet replaced in kin or with compacted cultings.  E. CATHODIC
DRILLER'S NAME <u>Gettler-Ryan</u> INC DRILLER'S LICENSE NO. <u>(-57</u> 2) 0 793	Fill hole anode zone with concrete placed by treme.  F. WELL DESTRUCTION  Send a map of work site. A separate permit is required for wells deeper than 45 feet.
WELL PROJECTS  Drill Hole Diameter in. Maximum  Casing Diameter in. Depth ft.  Surface Seal Depth ft. Owner's Well Number	SPECIAL CONDITIONS  NOTE: One application must be submitted for each well or well destruction. Multiple borings on one application are associable for geotechnical and contamination investigations.
CEOTECHNICAL PROJECTS  Number of Borings	see if excavation permit is rega
ESTIMATED STARTING DATE 8/12/02 ESTIMATED COMPLETION DATE 8/13/02	APPROVED MOWED CONSTRUCTION DATE 702
I hereby agree to comply with all requirements of this permit and Alameda County  APPLICANT'S SIGNATURE SAME DATE	7/24/02 Drovide clearer

CITY OF OAKLAND • Community and Economic Development Agency

250 Frank H. Ogawa Plaza, 2nd Floor, Oakland, CA 94612 • Phone (510) 238-3443 • FAX (510) 238-2263

Job Site 5500 TELEGRAPH AV

Parcel#

Appl# X0200636

Descr BORING FOR SOIL & WATER SAMPLING ADJACENT TO ABOVE ADDRESS Permit Issued 06/21/02

(SEE ATTACHED PLAN FOR LOCATIONS)

Work Type EXCAVATION-PRIVATE P

USA #

Util Co. Job #

Acctg#:

Util Fund #:

Applcnt

Phone#

Lic# --License Classes--

Owner

Contractor GETTLER RYAN INC

X (510)551-7555 220793 B C61 A C57 C10

Arch/Engr

Agent Applic Addr 6747 SIERRA CT, DUBLIN CA, 94568

\$250.00 TOTAL FEES PAID AT ISSUANCE

\$45.00 Applic

\$205.00 Permit

\$.00 Process

\$.00 Rec Mgmt

\$.00 Gen Plan

\$.00 Invstg

\$.00 Other



## **EXCAVATION PERMIT**

**CIVIL ENGINEERING** 

TO EXCAVATE IN STREETS OR OTHER SPECIFIED WORK

PAGE 2 of 2		. KA	BLTH 9-55 M ST.				
PERMIT NUMBER X 0	20 <u>0636</u>	SITE ADDRESS/LOCATION - 1016	graph Ave				
APPROX. START DATE	APPROX.END DATE	24-HOUR EMERGENCY PHONE NUMBER (Permit not valid without 24-Hour number)	916/631-1300				
CONTRACTOR'S LICENSE # ANI	OCLASS 793	CITY BUSINESS TAX #					
2- 48 hours pric	dentification number issued by USA. The U Or to starting work, you MUS	Service Alert (USA) two working days before excavating SA telephone number is 1-800-642-2444. Underground ST CALL (510) 238-3651 to schedule certificate is required (waived for a	e an inspection. $+331036$				
I hereby affirm that I am exempt from the Contractor's License Law for the following reason (Sec. 7031.5 Business and Professions Code: Any city or county which requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he is licensed pursuant to the provisions of the Contractor's License law Chapter 9 (commencing with Sec. 7000) of Division 3 of the Business and Professions Code, or that he is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more than \$500):  I, as an owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business Professions Code: The Contractor's License Law does not apply to an owner of property who builds or improves thereon, and who does such work himself or through his own employees, provided that such improvements are not intended or offered for sale. If however, the building or improves thereon, and who does such work himself or through his own employees, provided that such improvements are not intended or offered for sale. If however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he did not build or improve for the purpose of sale).  I, as owner of the property, am exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be performed prior to sale, (3) I have residence for the 12 months prior to completion of the work, and (4) I have not claimed exemption on this subdivision on more than two structures more than once during any three-year period. (Sec. 7044 Business and Professions Code).  I, as owner of the property, am exclusively contracting with licensed contractors to co							
WORKER'S COMPENSATION  I hereby affirm that I have a certif	icate of consent to self-insure, or a certific	cate of Worker's Compensation Insurance, or a certi	fied copy thereof (Sec. 3700, Labor Code).				
Policy #	Company Name						
I certify that in the performance of California (not required for work v	f the work for which this permit is issued, alued at one hundred dollars (\$100) or les	, I shall not employ any person in any manner so as as as).	to become subject to the Worker's Compensation Laws				
comply with such provisions or this p granted upon the express condition the perform the obligations with respect to and employees, from and against any sustained or arising in the construction	ermit shall be deemed revoked. This perm at the permittee shall be responsible for all be street maintenance. The permittee shall, and all suits, claims, or actions brought by a of the work performed under the permit	nit is issued pursuant to all provisions of Title 12 Ch claims and liabilities arising out of work performed and by acceptance of the permit agrees to defend, in y any person for or on account of any bodily injuries	under the permit or arising out of permittee's failure to ademnify, save and hold harmless the City, its officers a disease or illness or damage to persons and/or property the obligations with respect to street maintenance. This				
I hereby affirm that I am licensed und this permit and agree to its requirement Signature of Permittee	er provisions of Chapter 9 of Division 3 of the state of the short information is true.  Agent for © Contractor □ Owner	of the Business and Professions Code and my license and correct under penalty of law.	is in full force and effect (if contractor), that I have read				
DATE STREET LAST	SPECIAL PAVING DETAIL	HOLIDAY RESTRICTION?	LIMITED OPERATION AREA?				
RESURFACED	REQUIRED? PYES (NO)	(NOV 1 - JAN 1) YES Q NO	(7AM-9AM & 4PM-6PM) YES O NO				
ISSUED BY		DATE ISSUED					

CITY OF OAKLAND • Community and Economic Development Agency 250 Frank H. Ogawa Plaza, 2nd Floor, Oakland, CA 94612 • Phone (510) 238-3443 • FAX (510) 238-2263

Job Site 5500 TELEGRAPH AV

Parcel#

Descr BORING FOR SOIL & WATER SAMPLING ADJACENT TO ABOVE ADDRESS Permit Issued 06/21/02 (SEE ATTACHED PLAN FOR LOCATIONS)

Work Type EXCAVATION-PRIVATE P

USA #

Util Co. Job #

Acctg#:

Util Fund #:

Applent

Phone#

Lic# --License Classes--

Owner

Contractor GETTLER RYAN INC

Х

(510)551-7555 220793 B C61 A C57 C10

Appl# X0200637

Arch/Engr

Agent

Applic Addr 6747 SIERRA CT, DUBLIN CA, 94568

\$250.00 TOTAL FEES PAID AT ISSUANCE

\$45.00 Applic \$205.00 Permit

\$.00 Process

\$.00 Rec Mgmt

\$.00 Gen Plan \$.00 Invstg

\$.00 Other



## **EXCAVATION PERMIT**

CIVIL ENGINEERING

TO EXCAVATE IN STREETS OR OTHER SPECIFIED WORK

PAGE 2 of 2	South of 55'
PERMIT NUMBER X 0 2 0 0 2 7	SITE ADDRESS/LOCATION 5500 Teleyraph Ave
APPROX. START DATE  APPROX. END DATE  7/31/0	24-HOUR EMERGENCY PHONE NUMBER (Permit not valid without 24-Hour number)  (916)631-1300
CONTRACTOR'S LICENSE # AND CLASS	CITY BUSINESS TAX #
secured an inquiry identification number issued by USA. The U  2- 48 hours prior to starting work, you MUS	Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has ISA telephone number is 1-800-642-2444. Underground Service Alert (USA) # 3 3 2 01 4 ST CALL (510) 238-3651 to schedule an inspection.  In certificate is required (waived for approved slurry backfill).
construct, alter, improve, demolish, or repair any structure, prior to its issuance provisions of the Contractor's License law Chapter 9 (commencing with Sec. 7 alleged exemption. Any violation of Section 7031.5 by any applicant for a pen   I, as an owner of the property, or my employees with wages as their sole or  Professions Code: The Contractor's License Law does not apply to an owner  provided that such improvements are not intended or offered for sale. If howe  burden of proving that he did not build or improve for the purpose of sale).  I, as owner of the property, am exempt from the sale requirements of the al  be performed prior to sale, (3) I have resided in the residence for the 12 month  structures more than once during any three-year period. (Sec. 7044 Business at  I, as owner of the property, am exclusively contracting with licensed contra	ompensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business of property who builds or improves thereon, and who does such work himself or through his own employees, wer, the building or improvement is sold within one year of completion, the owner-builder will have the bove due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will us prior to completion of the work, and (4) I have not claimed exemption on this subdivision on more than two nd Professions Code).  actors to construct the project, (Sec. 7044, Business and Professions Code: The Contractor's License Law to contracts for such projects with a contractor(s) licensed pursuant to the Contractor's License law).
Policy # Company Name	icate of Worker's Compensation Insurance, or a certified copy thereof (Sec. 3700, Labor Code).  i. I shall not employ any person in any manner so as to become subject to the Worker's Compensation Laws as).
comply with such provisions or this permit shall be deemed revoked. This per granted upon the express condition that the permittee shall be responsible for all perform the obligations with respect to street maintenance. The permittee shall and employees, from and against any and all suits, claims, or actions brought be	su should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwith mit is issued pursuant to all provisions of Title 12 Chapter 12.12 of the Oakland Municipal Code. It is Il claims and liabilities arising out of work performed under the permit or arising out of permittee's failure to I, and by acceptance of the permit agrees to defend, indemnify, save and hold harmless the City, its officers by any person for or on account of any bodily injuries, disease or illness or damage to persons and/or property to rin consequence of permittee's failure to perform the obligations with respect to street maintenance. This by the Director of the Office of Planning and Building.
Signature of Permittee  Agent for Contractor 22 Owner	6/71/02 Date
DATE STREET LAST  RESURFACED  ISSUED BY  SPECIAL PAVING DETAIL  REQUIRED? YES NO.	HOLIDAY RESTRICTION?  (NOV 1 - JAN 1)  DATE ISSUED  (NOV 1 - JAN 2)  (NOV 1 - JAN 3)  (NOV

CITY OF OAKLAND . Community and Economic Development Agency 250 Frank H. Ogawa Plaza, 2nd Floor, Oakland, CA 94612 • Phone (510) 238-3443 • FAX (510) 238-2263

Job Site 5500 TELEGRAPH AV

Parcel#

Appl# X0200638

Descr BORING FOR SOIL & WATER SAMPLING ADJACENT TO ABOVE ADDRESS Permit Issued 06/21/02 (SEE ATTACHED PLAN FOR LOCATIONS)

Work Type EXCAVATION-PRIVATE P

USA #

Util Co. Job #

Acctg#:

Util Fund #:

Applent

Phone#

Lic# --License Classes--

Owner

Contractor GETTLER RYAN INC

X (510)551-7555 220793 B C61 A C57 C10

Arch/Engr

Agent

Applic Addr 6747 SIERRA CT, DUBLIN CA, 94568

\$250.00 TOTAL FEES PAID AT ISSUANCE

\$45.00 Applic

\$205.00 Permit

\$.00 Process

\$.00 Rec Mgmt

\$.00 Gen Plan

\$.00 Invstg

\$.00 Other



## **EXCAVATION PERMIT**

CIVIL **ENGINEERING** 

LIMITED OPERATION AREA?

(7AM-9AM & 4PM-6PM)

TO EXCAVATE IN STREETS OR OTHER SPECIFIED WORK PAGE 2 of 2 PERMIT NUMBER SITE ADDRESS/LOCATION X O 2 O D6 3 5500 Te legraph Ave 24-HOUR EMERGENCY PHONE NUMBER (Permit not valid without 24-Hour number) (916) 631 — 1300 CITY BUSINESS TAX # ATTENTION: State law requires that the contractor/owner call Underground Service Alert (USA) two working days before excavating. This permit is not valid unless applicant has secured an inquiry identification number issued by USA. The USA telephone number is 1-800-642-2444. Underground Service Alert (USA) # 332 / / 3 48 hours prior to starting work, you MUST CALL (510) 238-3651 to schedule an inspection. 48 hours prior to re-paving, a compaction certificate is required (waived for approved slurry backfill). OWNER/BIJILDER I hereby affirm that I am exempt from the Contractor's License Law for the following reason (Sec. 7031.5 Business and Professions Code: Any city or county which requires a permit to construct, after, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for such permit to file a signed statement that he is licensed pursuant to the provisions of the Contractor's License law Chapter 9 (commencing with Sec. 7000) of Division 3 of the Business and Professions Code, or that he is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more than \$500): I, as an owner of the property, or my employees with wages as their sole compensation, will do the work, and the structure is not intended or offered for sale (Sec. 7044, Business Professions Code: The Contractor's License Law does not apply to an owner of property who builds or improves thereon, and who does such work himself or through his own employees, provided that such improvements are not intended or offered for sale. If however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he did not build or improve for the purpose of sale). I, as owner of the property, am exempt from the sale requirements of the above due to: (1) I am improving my principal place of residence or appurtenances thereto, (2) the work will be performed prior to sale, (3) I have resided in the residence for the 12 months prior to completion of the work, and (4) I have not claimed exemption on this subdivision on more than two structures more than once during any three-year period. (Sec. 7044 Business and Professions Code). 1, as owner of the property, am exclusively contracting with licensed contractors to construct the project, (Sec. 7044, Business and Professions Code: The Contractor's License Law does not apply to an owner of property who builds or improves thereon, and who contracts for such projects with a contractor(s) licensed pursuant to the Contractor's License law). \_\_\_, B&PC for this reason I am exempt under Sec. \_\_\_\_ WORKER'S COMPENSATION I hereby affirm that I have a certificate of consent to self-insure, or a certificate of Worker's Compensation Insurance, or a certified copy thereof (Sec. 3700, Labor Code). Policy # \_\_\_\_\_ Company Name \_ I certify that in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the Worker's Compensation Laws of California (not required for work valued at one hundred dollars (\$100) or less). NOTICE TO APPLICANT: If, after making this Certificate of Exemption, you should become subject to the Worker's Compensation provisions of the Labor Code, you must forthwith comply with such provisions or this permit shall be deemed revoked. This permit is issued pursuant to all provisions of Title 12 Chapter 12.12 of the Oakland Municipal Code. It is granted upon the express condition that the permittee shall be responsible for all claims and liabilities arising out of work performed under the permit or arising out of permittee's failure to perform the obligations with respect to street maintenance. The permittee shall, and by acceptance of the permit agrees to defend, indemnify, save and hold harmless the City, its officers and employees, from and against any and all suits, claims, or actions brought by any person for or on account of any bodily injuries, disease or illness or damage to persons and/or property sustained or arising in the construction of the work performed under the permit or in consequence of permittee's failure to perform the obligations with respect to street maintenance. This permit is void 90 days from the date of issuance unless an extension is granted by the Director of the Office of Planning and Building. I hereby affirm that I am licensed under provisions of Chapter 9 of Division 3 of the Business and Professions Code and my license is in full force and effect (if contractor), that I have read this permit and agree to its requirements, and that the above information is true and correct under penalty of law. Signature of Permitted Agent for Contractor Owner DATE STREET LAST SPECIAL PAVING DETAIL HOLIDAY RESTRICTION?

(NOV 1 - JAN 1)

DATE ISSUED

REQUIRED?

O YES

RESURFACED

ISSUED BY

	MAJOR DIV	ISIONS	:		TYPICAL NAMES	
		CLEAN GRAVELS	(	GW	Well graded gravels with or without sand, little or no fines	
SIEVE	GRAVELS MORE THAN HALF	WITH LITTLE OR NO FINES		GP	Poorly graded gravels with or without sand, little or no fines	
SOILS NO. 200 S	COARSE FRACTION IS LARGER THAN NO. 4 SIEVE SIZE	GRAVELS WITH		GM	Silty gravels, silty gravels with sand	
_ 1		OVER 15% FINES	PAR (	GC	Clayey gravels, clayey gravels with sand	
E-GRAINED IS COARSER THAN		CLEAN SANDS		SW	Well graded sands with or without gravel, little or no fines	
COARSE—GRAINED THAN HALF IS COARSER THAN	SANDS	WITH LITTLE OR NO FINES		SP	Poorly graded sands with or without gravel, little or no fines	
C MORE THA	MORE THAN HALF COARSE FRACTION IS SMALLER THAN NO. 4 SIEVE SIZE	SANDS WITH		SM	Silty sands with or without gravel	
	100 1 012 012	OVER 15% FINES		SC	Clayey sands with or without gravel	
SIEVE	SILTS AND CLAYS			ML	Inorganic silts and very fine sands, rock flour, silts with sands and gravels	
SOILS No. 200				CL	Inorganic clays of low to medium plasticity, clays with sands and gravels, lean clays	
z				OL	Organic silts or clays of low plasticity	
ΩS	01.70 41	D CLAYS		мн	Inorganic silts, micaceous or diatomaceous, fine sandy or silty soils, elastic silts	
		LIQUID LIMIT GREATER THAN 50%		СН	Inorganic clays of high plasticity, fat clays	
MORE THA				ОН	Organic silts or clays of medium to high plasticity	
ŀ	IIGHLY ORGANI	C SOILS		PT	Peat and other highly organic soils	
		e vapors in ppm			Observed contact	
		ground surface	M18	ı	———— Inferred contact	
(2.		olor according to olor Charts (199			No soil sample recovered "Undisturbed" sample	
BL	140 p Blows	e drive hammer ounds falling 30 required to drive t are indicated o	inches. e sample	er	<ul> <li></li></ul>	
	TA GETTLE	R - RYAN	Inc.		UNIFIED SOIL CLASSIFICATION ASTM D 2488-85	



UNIFIED SOIL CLASSIFICATION
ASTM D 2488-85
AND
KEY TO SAMPLING DATA

	Geti	tleı	r-Ry	an,	Inc.	Log of Boring HA	
10	CT: "	urc-	Spring	2 Sto4	tion No. 9-0338	LOCATION: 5500 Telegraph Avenue, Oakla	and, California
						SURFACE ELEVATION:	
	CT NO.:						07:52
	STARTED					WL (ft. bgs): DATE: TIME:	
	FINISHED				nd Auger	TOTAL DEPTH: 18 feet	
	ING METH					GEOLOGIST: Geoffrey Risse	
(1LL	ING COMP	ANY.	. Gett	e1 -K,	,		
(feet)	SAMPLE NUMBER	SAMPLE INT.	GRAPHIC LOG	SOIL CLASS	GE	OLOGIC DESCRIPTION	REMARKS
=	<u></u>	Ŝ	(D)	n	Asphalt - 6 inches thick.		Boring backfilled
-					Base rock - 1.5 feet thick.		with pea gravel to 6 inch below ground surface, then finish to
3-			7// (	CL	CLAY (CL) - black (GLEY : 10% fine sand.	2.5/N), moist, low plasticity; 80% clay, 10% silt,	surface grade with concrete.
9-	HA1-11.5				CLAY WITH GRAVEL (CL) - fine gravel, 5% fine sand.	light brown (7.5YR 6/4), dry, low plasticity;  - light brown (7.5YR 6/4), dry; 80% clay, 15%  (7.5YR 6/4), moist; 80% clay, 10% silt, 10% fine	
15-	-	-			Ţ		
18	3- HA1-W				Bottom of boring at 18 fe	eet bgs.	Grab groundwate sample HA1-W, taken at 18 feet bgs.
21	11- DB NUMBE	P	Deces	384	4001		Page 1

Gettler-Ryan,	Inc.	Log of Boring HA	
Carrier Carrier Char	tion No. 9-0338	LOCATION: 5500 Telegraph Avenue, Oak	kland, California
ROJECT: Chevron Service State		SURFACE ELEVATION:	
ROJECT NO.: DG90338H.4C01		WL (ft. bgs): 13.0 DATE: 08/12/02 TIME	E: 14:20
ATE STARTED: 08/12/02		WL (ft. bgs): DATE: TIME	E:
ATE FINISHED: 08/12/02	and Auger	TOTAL DEPTH: 13.5 feet	
RILLING METHOD: 3 1/2 in. Ha	YVAD	GEOLOGIST: Geoffrey Risse	
RILLING COMPANY: Gettler-R	ı y alı		
(feet) SAMPLE NUMBER SAMPLE INT. GRAPHIC LOG SOIL CLASS		GEOLOGIC DESCRIPTION	REMARKS
3 0 0 0 0 0	Asphalt - 6 inches this	ick.	Boring backfilled
	Base rock - 2.5 feet	thick.	with pea gravel to 6 inch below ground surface, then finish to surface grade with concrete.
		(GLEY 2.5/N), moist; 90% clay, 5% silt, 5% fine sand.	
3- CL	CLAY (CL) - black (i	LOLE 1 STOLING MICHOL, GOW CHUY, CAS, CALL CAS THIS COLLEGE	
9-	silt, 10% tine sand.	tht brown (7.5YR 6/4), becomes dry; 80% clay, 10% (CL) - greenish gray (5G 6/1), moist; 80% clay, 15% gravel.	
12— HA2-12.0	20% fine grave.	L (CL) – dark brown (7.5YR 3/4), moist; 80% clay,	Grab groundwate
HA2-W 15-	Bottom of boring a	at 13.5 feet bgs.	sample HA2-W, taken at 13.5 fee bgs.
18-			

Gettler-Ryan, Inc.	Log of Boring HA-3
Coming Station No. 0-	0338 LOCATION: 5500 Telegraph Avenue, Oakland, California
ROJECT: Chevron Service Station No. 9-	SURFACE ELEVATION:
ROJECT NO.: DG90338H.4C01	WL (ft. bgs): 13.0 DATE: 08/13/02 TIME: 10:42
ATE STARTED: 08/12/02	WL (ft. bgs): DATE: TIME:
ATE FINISHED: 08/13/02	TOTAL DEPTH: 13.5 feet
RILLING METHOD: 3 1/2 in. Hand Auger	GEOLOGIST: Geoffrey Risse
RILLING COMPANY: Gettler-Ryan	
SAMPLE NUMBER SAMPLE INT. GRAPHIC LOG SOIL CLASS	GEOLOGIC DESCRIPTION REMARKS
Asphalt	- 6 inches thick.  Boring backfilled
Base ro	with pea gravel to 6 inch below ground surface, then finish to surface grade with concrete.
3- CL CLAY (sand.	CL) - black (GLEY 2.5/N), moist, low plasticity; 95% clay, 5% fine
9-	wITH SAND (CL) - greenish gray (5G 6/1), moist, low plasticity; le to medium sand, 5% silt.  (CL) - dark brown (7.5YR 3/4), moist; 80% clay, 10% fine gravel,
CLAY 10% fil	ne sand.
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Grab groundwate
HA3-W Botto	om of boring at 13.5 feet bgs. sample HA3-W, taken at 13.5 fee bgs.
15-	
1   1	
18-	
	1
21-	Page i

	Gett	ler-	Rya	n, Inc.	Log of Boring HA	
DO IE	CT: Chei	ron Se	rvice S	tation No. 9-0338	LOCATION: 5500 Telegraph Avenue, Oaki	and, California
PROJECT: Chevron Service Station No. 9-0338  PROJECT NO.: D690338H.4C01  DATE STARTED: 08/13/02					SURFACE ELEVATION:	
					WL (ft. bgs): 11.0 DATE: 08/13/02 TIME:	12:00
	FINISHED				WL (ft. bgs): DATE: TIME:	
				Hand Auger	TOTAL DEPTH: 11.5 feet	
	ING COMP			<u> </u>	GEOLOGIST: Geoffrey Risse	
JKILL.		AIVI.	T I	11) 4		
(feet)	SAMPLE NUMBER	SAMPLE INT. GRAPHIC LOG	SOIL CLASS		EOLOGIC DESCRIPTION	REMARKS
		0, 0		Asphalt - 6 inches thick.		Boring backfilled
- - - -				Base rock - 2 feet thick.	·	with pea gravel to 6 inch below ground surface, then finish to surface grade with concrete.
3-6-			CL	silt.	(5PB 2.5/1), moist, low plasticity; 95% clay, 5% greenish gray (5G 6/1), moist; 80% clay, 15%	
9-	HA4-11			coarse gravel, 10% fine to		Grab groundwater
12- - - 15-	HA4-W			Bottom of boring at 11.5	feet bgs.	sample HA4-W, taken at II.5 feet bgs.
18-	  -  -  -  -  -					
21	NUMBE	<u> </u>	200338	H 4C01		Page 1

#### CASE NARRATIVE

Prepared For:

Karew Streich
Bob Cochran
ChevronTexaco
6001 Bollinger Canyon Road L4310
San Ramon, CA 94583-0904

Prepared By:

Lancaster Laboratories 2425 New Holland Pike Lancaster, PA 17605-2425

#### SAMPLE GROUP

The sample group for this submittal is 819126. Samples arrived at the laboratory on Thursday, August 15, 2002.

#### **METHODOLOGY**

The specific methodologies used in obtaining the enclosed analytical results are indicated on the laboratory chronicles.

#### **COMMENTS**

The HA2 vials from Facility 90338 submitted for the Oxygenates analysis did not have a pH < 2 at the time of analysis. Due to the volatile nature of the analytes, it is not appropriate for the laboratory to adjust the pH at the time of sample receipt.



#### ANALYTICAL RESULTS

Prepared for:

ChevronTexaco 6001 Bollinger Canyon Rd L4310 San Ramon CA 94583

925-842-8582

Prepared by:

Lancaster Laboratories 2425 New Holland Pike Lancaster, PA 17605-2425

#### **SAMPLE GROUP**

The sample group for this submittal is 819126. Samples arrived at the laboratory on Thursday, August 15, 2002. The PO# for this group is 99011184 and the release number is STREICH.

Client Description			<u>Lancaster Labs Nu</u>
HA1-S-11.5-020812	Grab	Soil	3879949
HA2-W-020812	Grab	Water	3879950
HA1-W-020813	Grab	Water	3879951
HA2-S-12.0-020812	Grab	Soil	3879952
HA3-S-11.0-020813	Grab	Soil	3879953
HA3-W-020813	Grab	Water	3879954
HA4-S-11.0-020813	Grab	Soil	3879955
HA4-W-020813	Grab	Water	3879956
TA4- W-U2U013	Grau	yy alci	3019730

1 COPY TO

Gettler-Ryan Inc.

Attn: Geoffrey D. Risse

Questions? Contact your Client Services Representative Teresa M Lis at (717) 656-2300.

Respectfully Submitted,

Robert E. Mellinger Sr. Chemist/Coordinator



Lancaster Laboratories Sample No. SW 3879949

Collected: 08/12/2002 10:10 by GDR Account Number: 10992

Submitted: 08/15/2002 09:15 ChevronTexaco

Reported: 08/22/2002 at 20:18 6001 Bollinger Canyon Rd L4310

Discard: 08/30/2002 San Ramon CA 94583

HA1-S-11.5-020812 Grab Soil

Facility# 90338 GRRC

5500 Telegraph Av-Oakland T0600100307 HA-1

				As Received				
CAT			As Received	Method		Dilution		
No.	Analysis Name	CAS Number	Result	Detection Limit	Units	Factor		
01726	TPH-GRO - Soils							
01727	TPH-GRO - Soils	n.a.	N.D.	1.0	mg/kg	25		
02160	The reported concentration of T gasoline constituents eluting p start time. The analysis for volatiles was in methanol. The reporting lim BTEX/MTBE	rior to the C6 performed on a	(n-hexane) TPH-C	RO range preserved				
02174	Benzene	71-43-2	N.D.	0.0050	mg/kg	25		
02177	Toluene	108-88-3	N.D.	0.0050	mg/kg	25		
02178	Ethylbenzene	100-41-4	N.D.	0.0050	mg/kg	25		
02182	Total Xylenes	1330-20-7	N.D.	0.015	mg/kg	25		
02199	MTBE	1634-04-4	N.D.	0.050	mg/kg	25		
	The analysis for volatiles was performed on a sample which was preserved in methanol. The reporting limits were adjusted appropriately.							

State of California Lab Certification No. 2116

	7		-
Laboratory	('hror	דו	$\alpha \mid \Delta$

CAT		-		Analysis		Dilution
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	Factor
01726	TPH-GRO - Soils	N. CA LUFT Gasoline Method	1	08/16/2002 20:55	Steven A Skiles	25
02160	BTEX/MTBE	SW-846 8021B	1	08/16/2002 20:55	Steven A Skiles	25
01150	GC VOA Soil Prep	SW-846 5035	1	08/16/2002 09:16	Steven A Skiles	n.a.





3879950 Lancaster Laboratories Sample No. WW

Account Number: 10992 by GDR Collected:08/12/2002 14:23

Submitted: 08/15/2002 09:15

ChevronTexaco 6001 Bollinger Canyon Rd L4310 Reported: 08/22/2002 at 20:18

San Ramon CA 94583 Discard: 08/30/2002

Water Grab HA2-W-020812 GRRC

Facility# 90338 5500 Telegraph Av-Oakland T0600100307 HA-2

HA2 - -

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
01729	TPH-GRO - Waters					
01730	TPH-GRO - Waters The reported concentration of TP gasoline constituents eluting pr start time. A site-specific MSD sample was n was performed to demonstrate pre	ior to the C6 ot submitted f	(n-hexane) TPH-GR or the project. A	O range . LCS/LCSD	ug/l	1
02159	BTEX, MTBE					
02161 02164	Benzene Toluene	71-43-2 108-88-3	N.D. N.D.	0.50 0.50	ug/l ug/l	1
02166	Ethylbenzene	100-41-4	N.D.	0.50	ug/l	1
02171	Total Xylenes	1330-20-7	N.D.	1.5	ug/l	1
02172	Methyl tert-Butyl Ether	1634-04-4	40.	2.5	ug/l	1
	A site-specific MSD sample was n was performed to demonstrate pre					
01595	Oxygenates by 8260B					
02010	Methyl t-butyl ether	1634-04-4	37.	0.5	ug/l	1
02011	di-Isopropyl ether	108-20-3	N.D.	0.5	ug/l	1
02013	Ethyl t-butyl ether	637-92-3	N.D.	0.5	ug/l	1
02014	t-Amyl methyl ether	994-05-8	N.D.	0.5	ug/l	1
02015	t-Butyl alcohol	75-65-0	N.D.	5.	ug/l	1
	The vial submitted for volatile of analysis. Due to the volatil					

State of California Lab Certification No. 2116

receipt. The pH of this sample was pH = 4.

appropriate for the laboratory to adjust the pH at the time of sample

Laboratory Chronicle



Lancaster Laboratories, Inc. 2425 New Holland Pike PO Box 12425 Lancaster, PA 17605-2425 717-656-2300 Fax: 717-656-2681



Page 2 of 2

Lancaster Laboratories Sample No. WW 3879950

Collected:08/12/2002 14:23

by GDR

Account Number: 10992

San Ramon CA 94583

6001 Bollinger Canyon Rd L4310

ChevronTexaco

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:18

Discard: 08/30/2002

b Water

HA2-W-020812

GRRC

Facility# 90338 5500 Telegraph Av-Oakland T0600100307 HA-2

HA2 CAT				Analysis		Dilution
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	Factor
01729	TPH-GRO - Waters	N. CA LUFT Gasoline Method	1	08/17/2002 00:22	Melissa D Mann	1
02159	BTEX, MTBE	SW-846 8021B	1	08/17/2002 00:22	Melissa D Mann	1
01595	Oxygenates by 8260B	SW-846 8260B	1	08/20/2002 05:55	Kenneth L Boley Jr	1
01146	GC VOA Water Prep	SW-846 5030B	1	08/17/2002 00:22	Melissa D Mann	n.a.
01163	GC/MS VOA Water Prep	SW-846 5030B	1	08/20/2002 05:55	Kenneth L Boley Jr	n.a.



Lancaster Laboratories Sample No. WW 3879951

Collected:08/13/2002 07:52

by GDR

Account Number: 10992

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:18

ChevronTexaco

6001 Bollinger Canyon Rd L4310

San Ramon CA 94583

Discard: 08/30/2002

HA1-W-020813 Facility# 90338 Grab Water

GRRC

5500 Telegraph Av-Oakland T0600100307 HA-1

HA1--

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
01729	TPH-GRO - Waters					
01730	TPH-GRO - Waters The reported concentration of T gasoline constituents eluting p start time. A site-specific MSD sample was p was performed to demonstrate pro-	rior to the C6 not submitted :	(n-hexane) TPH-G for the project.	RO range A LCS/LCSD	ug/l	1
02159	BTEX, MTBE					
02161 02164 02166 02171 02172	Benzene Toluene Ethylbenzene Total Xylenes Methyl tert-Butyl Ether A site-specific MSD sample was was performed to demonstrate pr				ug/1 ug/1 ug/1 ug/1 ug/1	1 1 1 1
01595	Oxygenates by 8260B					
02010 02011 02013 02014 02015	Methyl t-butyl ether di-Isopropyl ether Ethyl t-butyl ether t-Amyl methyl ether t-Butyl alcohol	1634-04-4 108-20-3 637-92-3 994-05-8 75-65-0	N.D. N.D. N.D. N.D.	0.5 0.5 0.5 0.5	ug/l ug/l ug/l ug/l ug/l	1 1 1 1

State of California Lab Certification No. 2116

Laboratory Chronicle

		Dascrace.	OLLE O.				
CAT	Analysis						
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	<b>Factor</b>	
01729	TPH-GRO - Waters	N. CA LUFT Gasoline Method	1	08/17/2002 00:58	Melissa D Mann	1	
02159	BTEX, MTBE	SW-846 8021B	1	08/17/2002 00:58	Melissa D Mann	1	
01595	Oxygenates by 8260B	SW-846 8260B	1	08/20/2002 06:21	Kenneth L Boley Jr	1	





Page 2 of 2

Lancaster Laboratories Sample No. WW 3879951

Collected: 08/13/2002 07:52

by GDR

Account Number: 10992

San Ramon CA 94583

6001 Bollinger Canyon Rd L4310

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:18

Discard: 08/30/2002

HA1-W-020813

Grab

Water

GRRC

Facility# 90338 5500 Telegraph Av-Oakland T0600100307 HA-1

HA1--01163

01146 GC VOA Water Prep GC/MS VOA Water Prep

SW-846 5030B SW-846 5030B

08/17/2002 00:58 1

ChevronTexaco

Melissa D Mann 08/20/2002 06:21 Kenneth L Boley Jr n.a. n.a.

MEMBER



Lancaster Laboratories Sample No. SW 3879952

Collected: 08/12/2002 13:21 by GDR Account Number: 10992

Submitted: 08/15/2002 09:15 ChevronTexaco

Reported: 08/22/2002 at 20:19 6001 Bollinger Canyon Rd L4310

Discard: 08/30/2002 San Ramon CA 94583

HA2-S-12.0-020812 Grab Soil Facility# 90338 GRRC

5500 Telegraph Av-Oakland T0600100307 HA-2

				As Received			
CAT			As Received	Method		Dilution	
No.	Analysis Name	CAS Number	Result	Detection Limit	Units	Factor	
01726	TPH-GRO - Soils						
01727	TPH-GRO - Soils	n.a.	N.D.	1.0	mg/kg	25	
003.50	The reported concentration of TPH-GRO does not include MTBE or other gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time.  The analysis for volatiles was performed on a sample which was preserved in methanol. The reporting limits were adjusted appropriately.						
02160	BTEX/MTBE						
02174	Benzene	71-43-2	N.D.	0.0050	mg/kg	25	
02177	Toluene	108-88-3	N.D.	0.0050	mg/kg	25	
02178	Ethylbenzene	100-41-4	N.D.	0.0050	mg/kg	25	
02182	Total Xylenes	1330-20-7	N.D.	0.015	mg/kg	25	
02199	MTBE	1634-04-4	N.D.	0.050	mg/kg	25	
	The analysis for volatiles was in methanol. The reporting lim	performed on a its were adjus	sample which was ted appropriately	preserved			

State of California Lab Certification No. 2116

		Laboratory	Chro	nicle			
CAT	Analysis						
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	Factor	
01726	TPH-GRO - Soils	N. CA LUFT Gasoline Method	1	08/16/2002 21:32	Steven A Skiles	25	
02160	BTEX/MTBE	SW-846 8021B	1	08/16/2002 21:32	Steven A Skiles	25	
01150	GC VOA Soil Prep	SW-846 5035	1	08/16/2002 09:17	Steven A Skiles	n.a.	





3879953 Lancaster Laboratories Sample No. SW

Collected: 08/13/2002 09:57

by GDR

Account Number: 10992

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:19

Discard: 08/30/2002

Grab

ChevronTexaco

6001 Bollinger Canyon Rd L4310

San Ramon CA 94583

HA3-S-11.0-020813 Facility# 90338

Soil

5500 Telegraph Av-Oakland T0600100307 HA-3

CAT			As Received	As Received Method		Dilution
No.	Analysis Name	CAS Number	Result	Detection Limit	Units	Factor
01726	TPH-GRO - Soils					
01727	TPH-GRO - Soils	n.a.	N.D.	1.0	mg/kg	25
02160	The reported concentration of The gasoline constituents eluting pastart time.  The analysis for volatiles was pain methanol. The reporting limits between the statement of the s	rior to the C6 performed on a	(n-hexane) TPH-G sample which was	RO range preserved		
02100	DIBN/ WIBE					
02174	Benzene	71-43-2	N.D.	0.0050	mg/kg	25
02177	Toluene	108-88-3	N.D.	0.0050	mg/kg	25
02178	Ethylbenzene	100-41-4	N.D.	0.0050	mg/kg	25
02182	Total Xylenes	1330-20-7	N.D.	0.015	mg/kg	25
02199	MTBE	1634-04-4	N.D.	0.050	mg/kg	25
	The analysis for volatiles was not methanol. The reporting limit	performed on a its were adjus	sample which was ted appropriately	preserved		

GRRC

State of California Lab Certification No. 2116

		<b>-</b>				
CAT				Analysis		I
No.	Analysis Name	Method		Date and Time	Analyst	
01726	TPH-GRO - Soils	N. CA LUFT Gasoline	1	08/16/2002 22:10	Steven A Skiles	

Laboratory Chronicle

Method 08/16/2002 22:10 Steven A Skiles SW-846 8021B BTEX/MTBE 02160 08/16/2002 09:18 Steven A Skiles 01150 GC VOA Soil Prep SW-846 5035

Dilution Factor 25

25

n.a.



Lancaster Laboratories Sample No. WW 3879954

Collected:08/13/2002 10:42

by GDR

Account Number: 10992

San Ramon CA 94583

6001 Bollinger Canyon Rd L4310

ChevronTexaco

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:19

Discard: 08/30/2002

Grab

Water

GRRC

HA3-W-020813 Facility# 90338

5500 Telegraph Av-Oakland T0600100307 HA-3

HA3--

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
01729	TPH-GRO - Waters					
01730	TPH-GRO - Waters The reported concentration of TR gasoline constituents eluting pr start time. A site-specific MSD sample was r was performed to demonstrate pre	ior to the C6 ot submitted f	(n-hexane) TPH-GF for the project. A	RO range A LCS/LCSD	ug/l	1
02159	BTEX, MTBE					
02161 02164 02166 02171 02172	Benzene Toluene Ethylbenzene Total Xylenes Methyl tert-Butyl Ether A site-specific MSD sample was r was performed to demonstrate pre	71-43-2 108-88-3 100-41-4 1330-20-7 1634-04-4 not submitted to ecision and according	N.D. N.D. N.D. S.9 For the project. Accuracy at a batch	0.50 0.50 0.50 1.5 2.5 A LCS/LCSD level.	ug/l ug/l ug/l ug/l ug/l	1 1 1 1
01595	Oxygenates by 8260B					
02010 02011 02013 02014 02015	Methyl t-butyl ether di-Isopropyl ether Ethyl t-butyl ether t-Amyl methyl ether t-Butyl alcohol	1634-04-4 108-20-3 637-92-3 994-05-8 75-65-0	4. N.D. N.D. N.D. N.D.	0.5 0.5 0.5 0.5	ug/l ug/l ug/l ug/l ug/l	1 1 1 1

State of California Lab Certification No. 2116

		Laboratory	Chro:	nicle		Dilution		
CAT	Analysis							
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	<b>Factor</b>		
01729	TPH-GRO - Waters	N. CA LUFT Gasoline Method	1	08/17/2002 01:33	Melissa D Mann	1		
02159	BTEX, MTBE	SW-846 8021B	1	08/17/2002 01:33	Melissa D Mann	1		
01595	Oxygenates by 8260B	SW-846 8260B	1	08/20/2002 06:47	Kenneth L Boley Jr	1		





Page 2 of 2

Lancaster Laboratories Sample No. 3879954

Collected:08/13/2002 10:42

by GDR

Account Number: 10992

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:19

Discard: 08/30/2002

Grab

ChevronTexaco

6001 Bollinger Canyon Rd L4310

San Ramon CA 94583

HA3-W-020813 Facility# 90338 Water

GRRC

5500 Telegraph Av-Oakland T0600100307 HA-3

HA3--

01146 GC VOA Water Prep 01163 GC/MS VOA Water Prep

SW-846 5030B SW-846 5030B

08/17/2002 01:33 1 08/20/2002 06:47

Melissa D na.... Kenneth L Boley Jr Melissa D Mann

n.a. n.a.



Lancaster Laboratories Sample No. SW 3879955

Collected: 08/13/2002 11:45

by GDR

Account Number: 10992

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:19

ChevronTexaco

6001 Bollinger Canyon Rd L4310

San Ramon CA 94583

Discard: 08/30/2002

HA4-S-11.0-020813

Soil Grab

Facility# 90338

GRRC

5500 Telegraph Av-Oakland T0600100307 HA-4

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor		
01726	TPH-GRO - Soils							
01727	TPH-GRO - Soils The reported concentration of T	n.a. PH-GRO does no	N.D. t include MTBE or	1.0 other	mg/kg	25		
	gasoline constituents eluting prior to the C6 (n-hexane) TPH-GRO range start time. The analysis for volatiles was performed on a sample which was preserved in methanol. The reporting limits were adjusted appropriately.							
02160	BTEX/MTBE							
02174	Benzene	71-43-2	N.D.	0.0050	mg/kg	25		
02177	Toluene	108-88-3	N.D.	0.0050	mg/kg	25		
02178	Ethylbenzene	100-41-4	N.D.	0.0050	mg/kg	25		
02182	Total Xylenes	1330-20-7	N.D.	0.015	mg/kg	25		
02199	MTBE	1634-04-4	N.D.	0.050	mg/kg	25		
	The analysis for volatiles was in methanol. The reporting lim	performed on a its were adjus	sample which was ted appropriately	preserved				

State of California Lab Certification No. 2116

		Laboratory	Chro	nicle					
CAT		Analysis							
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	<b>Factor</b>			
01726	TPH-GRO - Soils	N. CA LUFT Gasoline Method	1	08/16/2002 22:48	Steven A Skiles	25			
02160	BTEX/MTBE	SW-846 8021B	1	08/16/2002 22:48	Steven A Skiles	25			
01150	GC VOA Soil Prep	SW-846 5035	1	08/16/2002 09:19	Steven A Skiles	n.a.			



3879956 Lancaster Laboratories Sample No.

Collected:08/13/2002 12:07

by GDR

Account Number: 10992

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:19

ChevronTexaco

6001 Bollinger Canyon Rd L4310

San Ramon CA 94583

Discard: 08/30/2002

HA4-W-020813

Grab Water

Facility# 90338

GRRC

5500 Telegraph Av-Oakland T0600100307 HA-4

HA4 - -

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit	Units	Dilution Factor
01729	TPH-GRO - Waters					
01730	TPH-GRO - Waters The reported concentration of TP gasoline constituents eluting pr start time. A site-specific MSD sample was n was performed to demonstrate pre	ior to the C6 ot submitted f	(n-hexane) TPH-GF for the project. A	O range LCS/LCSD	ug/l	1
02159	BTEX, MTBE					
02161 02164 02166 02171 02172	Benzene Toluene Ethylbenzene Total Xylenes Methyl tert-Butyl Ether A site-specific MSD sample was n	71-43-2 108-88-3 100-41-4 1330-20-7 1634-04-4 not submitted f	N.D. N.D. N.D. N.D. Sor the project.	0.50 0.50 0.50 1.5 2.5 LCS/LCSD	ug/l ug/l ug/l ug/l ug/l	1 1 1 1
	was performed to demonstrate pre					
01595	Oxygenates by 8260B					
02010 02011 02013 02014 02015	Methyl t-butyl ether di-Isopropyl ether Ethyl t-butyl ether t-Amyl methyl ether t-Butyl alcohol	1634-04-4 108-20-3 637-92-3 994-05-8 75-65-0	0.7 N.D. N.D. N.D. N.D.	0.5 0.5 0.5 0.5	ug/1 ug/1 ug/1 ug/1 ug/1	1 1 1 1

State of California Lab Certification No. 2116

		Laboratory	Chro	nicle		
CAT		_		Analysis		Dilution
No.	Analysis Name	Method	Trial#	Date and Time	Analyst	Factor
01729	TPH-GRO - Waters	N. CA LUFT Gasoline Method	1	08/17/2002 02:09	Melissa D Mann	1.
02159	BTEX, MTBE	SW-846 8021B	1	08/17/2002 02:09	Melissa D Mann	1
01595	Oxygenates by 8260B	SW-846 8260B	1	08/20/2002 07:13	Kenneth L Boley Jr	1



Lancaster Laboratories, Inc. 2425 New Holland Pike PO Box 12425 Lancaster, PA 17605-2425 717-656-2300 Fax: 717-656-2681



Page 2 of 2

Lancaster Laboratories Sample No. 3879956

Collected: 08/13/2002 12:07

by GDR

Account Number: 10992

ChevronTexaco

Submitted: 08/15/2002 09:15

Reported: 08/22/2002 at 20:19

Discard: 08/30/2002

Grab

6001 Bollinger Canyon Rd L4310 San Ramon CA 94583

Water HA4-W-020813 Facility# 90338

5500 Telegraph Av-Oakland T0600100307 HA-4

HA4--

01146 GC VOA Water Prep 01163

SW-846 5030B GC/MS VOA Water Prep

SW-846 5030B 08/17/2002 02:09 1 08/20/2002 07:13

GRRC

Melissa D Mann Kenneth L Boley Jr

n.a. n.a.





Page 1 of 2

Client Name: ChevronTexaco

Reported: 08/22/02 at 08:19 PM

#### Group Number: 819126

#### Laboratory Compliance Quality Control

Analysis Name	Blank Result	Blank <u>MDL</u>	Report <u>Units</u>	LCS %REC	LCSD %REC	LCS/LCSD <u>Limits</u>	RPD	RPD Max
Batch number: 02228A34A	Sample nu	mber(s): 3	879949,38	79952-387	9953,3879	955		
TPH-GRO - Soils	N.D.	1.	mg/kg	89		69-112		
Benzene	N.D.	.005	mg/kg	102		93-123		
Toluene	N.D.	.005	mg/kg	104		93-122		
Ethylbenzene	N.D.	.005	mg/kg	104		87~127		
Total Xylenes	N.D.	.015	mg/kg	103		88-120		
MTBE	N.D.	.05	mg/kg	101		80-132		
Batch number: 02228A56A Sample number(s): 3879950-3879951,3879954,3879956								
TPH-GRO - Waters	N.D.	50.	ug/l	90	90	74-116	0	30
Benzene	N.D.	. 5	ug/l	99	95	80-118	4	30
Toluene	N.D.	. 5 . 5	ug/l	107	103	82-119	4	30
Ethylbenzene	N.D.	. 5	ug/l	106	102	81-119	4	30
Total Xylenes	N.D.	1.5	ug/l	108	104	82-120	4	30
Methyl tert-Butyl Ether	N.D.	2.5	ug/l	103	99	79-127	4	30
Batch number: N022282AB	Sample nu	mber(s): 3	879950-38	79951,387	9954,3879	956		
Methyl t-butyl ether	N.D.	.5	ug/l	101		77-127		
di-Isopropyl ether	N.D.	.5	ug/l	104		74-125		
Ethyl t-butyl ether	N.D.	.5	ug/l	95		74-120		
t-Amyl methyl ether	N.D.	.5	ug/l	95		71-114		
t-Butyl alcohol	N.D.	5.	ug/l	95		59-139		

#### Sample Matrix Quality Control

	MS	MSD	MS/MSD		RPD	BKG	DUP	DUP	Dup RPD				
Analysis Name	%REC	%REC	<u>Limits</u>	RPD	<u>MAX</u>	Conc	Conc	RPD	Max				
Batch number: 02228A34A	Sample number(s): 3879949,3879952-3879953,3879955												
TPH-GRO - Soils	85	89	42-105	4	30								
Benzene	94	95	62-153	2	30								
Toluene	91	92	66-111	1	30								
Ethylbenzene	102	105	66-131	3	30								
Total Xylenes	95	98	62-120	3	30								
MTBE	102	102	43-186	0	30								
Batch number: 02228A56A TPH-GRO - Waters Benzene Toluene Ethylbenzene Total Xylenes Methyl tert-Butyl Ether	Sample 99 103 106 111 112 109	e number	74-132 83-130 87-129 86-133 86-132 66-140	50-38799	951,387	9954,38799	56						
Batch number: N022282AB	Sample	number	(s): 38799	50-38799	951,387	9954,38799	56						
Methyl t-butyl ether	103	103	69-134	0	30								
di-Isopropyl ether	107	105	68-133	2	30								
Ethyl t-butyl ether	94	96	73-123	2	30								
t-Amyl methyl ether	95	95	69-118	0	30								
t-Butyl alcohol	97	96	51-148	1	30								

#### Surrogate Quality Control

- \*- Outside of specification
- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.



Lancaster Laboratories, Inc. 2425 New Holland Pike PO Box 12425 Lancaster, PA 17605-2425 717-656-2300 Fax: 717-656-2681



Page 2 of 2

#### Quality Control Summary

Client Name: ChevronTexaco

Group Number: 819126

Reported: 08/22/02 at 08:19 PM

Surrogate Quality Control

Analysis Name: TPH-GRO - Soils Batch number: 02228A34A

Trifluorotoluene-F Trifluorotoluene-P 3879949 96 3879952 84 98 3879953 88

102 101 3879955 88 103 96 Blank 99 LCS 108 105 109 MS 102 MSD 106

58-118 68-122 Limits:

Analysis Name: TPH-GRO - Waters

Batch number: 02228A56A

Trifluorotoluene-P Trifluorotoluene-F 3879950 84 95 3879951 95 3879954 83 94 3879956 84 95 Blank 86 94 LCS 94 94 LCSD 94 MS 94 97

71-130 Limits: 57-146

Analysis Name: Oxygenates by 8260B

Batch number: N022282AB

Batch number: N022282AB Dibromofluoromethane		1,2-Dichloroethane-d4	Toluene-d8	4-Bromofluorobenzene				
3879950	102	96	97	93				
3879951	104	96	97	94				
3879954	104	95	98	94				
3879956	103	95	98	93				
Blank	102	94	98	95				
LCS	97	96	101	99				
MS	101	95	98	101				
MSD	100	98	98	102				
Limits:	86-118	80-120	88-110	86-115				

\*- Outside of specification

(1) The result for one or both determinations was less than five times the LOQ.

(2) The background result was more than four times the spike added.



## Chevron California Region Analysis Request/Chain of Custody

Lancaster Laboratories Where quality is a science.	\$19126	Acct	.#: <u></u> [(	<sub>)</sub> ዓዓ′	$\mathcal{V}$ Sa		Lancaste			ies us 5 -	se only	, scf	R#:			
Facility#: 9-0338 (G) Site Address: 5500 Teley r Chevron PM: KareW Streich Lea Consultant/Office: Gettler-Ry Consultant Prj. Mgr.: Geoffrey D Consultant Phone #: [9]6)631-1300 Sampler: Geoffrey D, Service Order #: [5]  Sample Identification  HAI-II,5 HAI-W	A ph Ave de Consultant:  (N JN),  Risse  Fax #: (916)6  Risse  Non SAR:  Date  Collected C  8/12/12    8/13/12    8/13/12    8/13/12    8/13/12    11/	21-1317	□ Potable □ NPDES	Oil ☐ Air ☐ Total Number of Containers	BTEX+MTBE 8260   8021 EJ	TPH 8015 MOD DRO Silica Gel Cleanup		servatio					H = HC N = HN S = H <sub>2</sub> I  J valu  Must possii 8021 M  Confi	CI NO3 SO4  Le report meet lov ble for 8: TBE Cor irm highe irm all hitoxyoxy	tive Code T = Thiose B = NaOh O = Other ing needed west detectic 260 compountifirmation est hit by 820 ts by 8260 y s on higher y s on all hits Remarks	ulfate I on limits unds 60 st hit
Turnaround Time Requested (TAT) (please STD. TAT) 72 hour 48 hour 4 day 5 day  Data Package Options (please circle if require	our y	Relinquished by:  Relinquished by:		Koe		_8	Date Date	Time 0 900 Time	Rec	eived	by:			·····	Date Date	Time

Other

Relinquished by Commercial Carrier:

FedEx

Temperature Upon Receipt

UPS

QC Summary

Disk

Type VI (Raw Data)

WIP (RWQCB)

Type ! - Full

Coelt Deliverable not needed

Date

Received by

Custody Seals Intact?

Time