

of the

JUN 2 4 2005

Environmental Health

2005 ANNUAL GROUNDWATER MONITORING REPORT

FORMER HEGENBERGER MAINTENANCE STATION 555 HEGENBERGER ROAD OAKLAND, CALIFORNIA

PREPARED FOR:

CALIFORNIA DEPARTMENT OF TRANSPORTATION
DISTRICT 4
OFFICE OF ENVIRONMENTAL ENGINEERING
111 GRAND AVENUE
OAKLAND, CALIFORNIA

PREPARED BY:

GEOCON CONSULTANTS, INC. 2356 RESEARCH DRIVE LIVERMORE, CALIFORNIA

CALTRANS CONTRACT NO. 04A1862 TASK ORDER NO. 17

GEOCON PROJECT NO. E8220-06-17

June 2005



MATERIALS



ENVIRONMENTAL E GEOTECHNICAL E MATERIAL



Project No. E8220-06-17 June 20, 2005

Mr. Bahram Sazegar California Department of Transportation District 4 111 Grand Avenue, 14th Floor Post Office Box 23660 Oakland, California 94623-0660

Subject:

2005 ANNUAL GROUNDWATER MONITORING REPORT FORMER HEGENBERGER MAINTENANCE STATION 555 HEGENBERGER ROAD, OAKLAND, CALIFORNIA CONTRACT NO. 04A1862, TASK ORDER NO. 17

Dear Mr. Sazegar:

In accordance with California Department of Transportation (Caltrans) Contract No. 04A1862 and Task Order No. 17, Geocon has performed environmental engineering services at the project site. The project site consists of the Former Hegenberger Maintenance Station located at 555 Hegenberger Road in Oakland, California.

The accompanying report summarizes the services performed consisting of the collection of groundwater samples and laboratory analyses.

The contents of this report reflect the views of Geocon, who is responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the State of California or the Federal Highway Administration. This report does not constitute a standard, specification, or regulation.

If there are any questions concerning the contents of this report, or if Geocon may be of further service, please contact the undersigned at your convenience.

Sincerely,

GEOCON CONSULTANTS, INC.

John Love, PG

Sr. Project Geologist

Richard Day, CEG, CHG Regional Manager

JL:RWD:rjk

Exerca 1)-30-06

(4) Addressee

TABLE OF CONTENTS

		<u>P</u>	age?
1.0	INTRO 1.1 1.2	DDUCTION	1
2.0	SCOP	E OF SERVICES	3
3.0	INVES 3.1 3.2	STIGATIVE METHODS Groundwater Sampling Laboratory Analyses	4
4.0	FIELD 4.1 4.2	OBSERVATIONS AND INVESTIGATIVE RESULTS Depth to Groundwater Measurements Analytical Results	5
5.0	CONC	CLUSIONS AND RECOMMENDATIONS	6
6.0	REPO	RT LIMITATIONS	7
FIG 1 2	URES Vicinity Site Plan	·	
TAI	BLES Histor	rical Depth to Groundwater and Sample Results	
API	PENDICES	5	
A.		oring Well Sampling Data Sheets	
В.	Labor	atory Report and Chain-of-Custody Documentation	

2005 ANNUAL GROUNDWATER MONITORING REPORT

1.0 INTRODUCTION

This Groundwater Monitoring Report for the former Hegenberger California Department of Transportation (Caltrans) Maintenance Station was prepared under Caltrans Contract No. 04A1862 and Task Order (TO) No. 17.

1.1 Site Description

The subject site is located at 555 Hegenberger Road in Oakland, California. The site was formerly used by Caltrans to store and service maintenance vehicles and equipment. Currently, the site is developed as an automobile dealership.

The approximate location of the site is depicted on the attached Vicinity Map presented as Figure 1. The approximate site boundaries and former structures are depicted on the Site Plan presented as Figure 2.

1.2 Background

In September 1994, four underground storage tanks (USTs) and the associated product piping and pump island were removed. The USTs consisted of two 2,000-gallon diesel and two 6,500-gallon gasoline tanks. During the tank removals, the UST areas were over-excavated and the soil was disposed. Soil samples collected from the tank excavation exhibited concentrations of total petroleum hydrocarbons as gasoline (TPHg), as diesel (TPHd), as oil and grease (O&G), and benzene, toluene, ethylbenzene, and xylenes (BTEX).

To evaluate the potential impacts to groundwater and soil beneath the site, a soil and groundwater investigation was conducted by Geocon in September and October 1995. The investigation included the installation of five monitoring wells (MW1 through MW5) at the locations depicted on the Site Plan, Figure 2. The investigation indicated that groundwater and soil beneath the site was impacted by petroleum hydrocarbons.

Based on the findings of the investigation, the Alameda County Department of Environmental Health Services (ACDEHS) requested quarterly groundwater monitoring. The five monitoring wells were monitored quarterly from October 1995 through November 1996. The wells were also sampled in February 1998.

Total petroleum hydrocarbons as motor oil (TPHmo) and O&G were not detected in groundwater samples and analysis of these compounds was discontinued. TPHg, TPHd, BTEX and MTBE have

historically been detected in groundwater. Since the constituent concentrations have not attenuated over time, the ACDEHS has requested annual monitoring of groundwater beneath the site. The requested annual monitoring began in February 2003 and laboratory analysis indicated that MTBE was no longer present in groundwater at the site. Subsequently, ACDEHS stated that MTBE was no longer a contaminant of concern.

Groundwater monitoring has continued at the site on an annual basis since February 2003. Contaminant concentrations have remained relatively stable over that time period with the highest contaminant concentrations consistently reported in monitoring well MW3.

June 20, 2005

2.0 SCOPE OF SERVICES

The following scope of services was performed:

- Collected depth to groundwater measurements and groundwater samples from five monitoring well locations;
- Submitted groundwater samples for laboratory analysis; and
- Prepared Groundwater Monitoring Report.

3.0 INVESTIGATIVE METHODS

3.1 Groundwater Sampling

Groundwater monitoring was performed on May 12, 2005. Prior to purging each monitoring well, depths to groundwater were determined using an electronic water level indicator (accurate to 0.01ft). Groundwater was purged from each well using a using a centrifugal pump fitted with 3/8-inch diameter disposable polyethylene tubing. At least three well-casing-volumes of groundwater were purged from each well prior to sample collection. Field parameters such as temperature, conductivity and pH were monitored after each casing volume had been removed to insure groundwater from the surrounding formation had entered the well casing prior to sample collection. The water level in each well was allowed to recover approximately 80% prior to sampling. Groundwater samples were collected using disposable polyethylene bailers. A new bailer was used to collect samples from each well. Monitoring well sampling data sheets are included as Appendix A.

Groundwater samples were collected in laboratory-provided containers, labeled and placed in a chilled container and transported to Sparger Technology, Inc. using chain-of-custody protocol. The purged groundwater from the sampling event was containerized and transported back to Geocon's warehouse for temporary storage pending disposal arrangements.

3.2 Laboratory Analyses

Geocon instructed the analytical laboratory to conduct the following laboratory analyses:

- TPHg following EPA Test Method 8015B Modified; and
- BTEX following EPA Test Method 8260B.

A copy of the laboratory report and chain of custody documentation is presented as Appendix B.

4.0 FIELD OBSERVATIONS AND INVESTIGATIVE RESULTS

4.1 Depth to Groundwater Measurements

On May 12, 2005, depth to groundwater ranged from 4.55 feet to 6.18 feet below the top of casing (TOC).

Historic depth to groundwater data are presented in Table 1. The groundwater flow direction was not calculated in January 2004, and could not be calculated in May 2005 because the groundwater elevation data do not support a specific flow direction. However, historic flow direction and groundwater sample results data indicates the groundwater flow direction is towards the west-northwest.

4.2 Analytical Results

TPHg was reported in all five monitoring wells at concentrations ranging from 0.33 mg/l in MW-2 to 6.2 mg/l in MW-3. Benzene was reported at concentrations of 20 ug/l, 1,000 ug/l, and 14 ug/l in monitoring wells MW-1, MW-3, and MW-4, respectively.

Toluene, ethylbenzene, and xylenes were reported at concentrations ranging from 5.7 to 30 ug/l in monitoring wells MW-1, MW-3, and MW-4.

5.0 CONCLUSIONS AND RECOMMENDATIONS

Historical groundwater sample results indicate a significant portion of the petroleum hydrocarbon plume has migrated northwest from the former UST excavation towards MW-3. During the recent sample event, TPHg and benzene were reported in MW-3 at concentrations of 6.2 mg/l and 1,000 ug/l, respectively. The next highest TPHg and benzene concentrations were reported in MW-1, located approximately 20 feet west of the former UST excavation. TPHg and benzene were reported in MW-1 at concentrations of 1.2 mg/l and 20 ug/l.


Benzene has been detected in groundwater samples collected from several monitoring wells at concentrations that exceed the maximum contaminant level (MCL) of 1 ug/l. Although groundwater samples collected from several onsite monitoring wells exceed the MCL established for drinking water, shallow groundwater in the vicinity of the site is not used for this purpose. The highest concentration of benzene (3,070 ug/l in 1998) ever reported at the site is below the Tier 1 Environmental Screening Levels (ESLs) established by the Regional Water Quality Control Board – San Francisco Bay Region (RWQCB) for volatilization of compounds from shallow groundwater to indoor air, the only viable exposure pathway at the site, should the plume have migrated northwest beneath the existing building.

Based on the results of this and previous groundwater monitoring events, it appears the lateral extent of petroleum hydrocarbon impacts to shallow groundwater have not been defined to the north and west of the former UST excavation. Therefore, Geocon recommends advancing up to eight soil borings west of MW-4, northwest of MW-3, and north of the former UST excavation to characterize the lateral extent of the petroleum hydrocarbon plume. Once completed, additional monitoring wells may be constructed (if necessary) to monitor the down gradient extent, as well as stability of the plume. Should future groundwater monitoring confirm that the plume is stable, then the Alameda County Department of Environmental Health Services may consider the site for case closure as a low risk groundwater site.

6.0 REPORT LIMITATIONS

This report has been prepared exclusively for Caltrans. The information contained herein is only valid as of the date of the report, and will require an update to reflect additional information obtained.

This report is not a comprehensive site characterization and should not be construed as such. The findings as presented in this report are predicated on the results of the limited sampling and laboratory testing performed. In addition, the information obtained is not intended to address potential impacts related to sources other than those specified herein. Therefore, the report should be deemed conclusive with respect to only the information obtained. We make no warranty, express or implied, with respect to the content of this report or any subsequent reports, correspondence or consultation. Geocon strived to perform the services summarized herein in accordance with the local standard of care in the geographic region at the time the services were rendered.






Table 1 Historical Depth to Groundwater and Sample Results Former Hegenberger Maintenance Station

Well	Date	TOC Elevation (feet)	Depth to Water (feet)	Groundwater Elevation (feet amsl)	TPHg (mg/l)	TPHd (mg/l)	Benzene (ug/l)	Toluene (ug/l)	Ethylbenzene (ug/l)	Xylenes (ug/l)	MTBE (ug/l)
NAME 1	10/11/1005	00.70		02.19	0.73	< 0.05	660	13	4.7	2.8	
MW-1	10/11/1995	99.73	6.55	93.18	0.72	< 0.05	660			2. s 17	
	1/17/1996	99.73	5.64	94.09	4.4	< 0.05	1,000	30	21		
	4/16/1996	99.73	5.46	94.27	6.05	7.45	914	34.7	34.4	15.8	
	8/26/1996	99.73	5.91	93.82	3.8	0.43	780	23	21	20	
	11/14/1996	99.73	6.16	93.57	2.6	0.27	500	18	14	8.9	
	2/18/1998	99.73	3.82	95.91	3.1	0.90	240	18	7.8	11	20
	3/30/2001	99.73	6.19	93.54	3.6	0.48	150	13	0.69	10.8	ND
	9/30/2002	10.26	5.79	4.47	0.59	< 0.05	12	2.7	< 0.5	1.6	< 0.5
	2/20/2003	10.26	4.49	5.77	2.65	**	36.9	10.6	7	18.1	<5
	1/12/2004	10.26	4.41	5.85	1.61		5.6	1.8	1.6	1.4	
	5/12/2005	10.26	4.45	5.81	1.2		20	<5.0	<5.0	<5.0	
MW-2	10/11/1995	99.68	6.88	92.8	< 0.05	< 0.05	< 0.3	<0.3	< 0.3	<0.5	
	1/17/1996	99.68	5.32	94.36	4.9	< 0.05	2,100	<15	<15	<15	
	4/16/1996	99.68	5.81	93.87	< 0.05	< 0.05	1.02	< 0.5	< 0.5	< 0.5	
	8/26/1996	99.68	5.98	93.70	< 0.05	< 0.05	< 0.5	< 0.5	< 0.5	< 0.5	
	11/14/1996	99.68	6.72	92.96	< 0.05	0.056	< 0.5	< 0.5	< 0.5	< 0.5	
	2/18/1998	99.68	5.01	94.67	< 0.05	0.260	< 0.5	<0.5	< 0.5	< 0.5	< 0.5
	3/30/2001	99.68	6.54	93.14	< 0.20	0.37	2.7	0.82	< 0.5	0.84	ND
	9/30/2002	10.22	6.48	3.74	< 0.05	< 0.05	< 0.5	< 0.5	< 0.5	<1.5	< 0.5
	2/20/2003	10.22	5.98	4.24	0.11		6.6	< 0.5	< 0.5	<1.0	< 0.5
	1/12/2004	10.22	5.69	4.53	0.067		< 0.5	< 0.5	<0.5	<1.0	
	5/12/2005	10.22	5.55	4.67	0.33		<1.0	<1.0	<1.0	<1.0	

Table 1
Historical Depth to Groundwater and Sample Results
Former Hegenberger Maintenance Station

Well	Date	TOC Elevation (feet)	Depth to Water (feet)	Groundwater Elevation (feet amsl)	TPHg (mg/l)	TPHd (mg/l)	Benzene (ug/l)	Toluene (ug/l)	Ethylbenzene (ug/l)	Xylenes (ug/l)	MTBE (ug/l)
MW-3	10/11/1995	98.92	6.43	92.5	1.3	< 0.05	1.0	<0.3	<0.3	<0.3	
IVI W -3			6.42	92.3 93.1	0.171	< 0.05	64	<0.3	1.0	<0.3	
	1/17/1996	98.92	5.82		6.74	0.565	2,770	31	13.9	21.9	
	4/16/1996	98.92	5.85	93.07	,		•			4.6	
	8/26/1996	98.92	5.72	93.2	0.7	0.70	180	4.2	1.0		
	11/14/1996	98.92	6.28	92.64	0.3	0.12	6.2	1.2	0.7	1.4	
	2/18/1998	98.92	4.65	94.27	11	2.5	3,070	50	54	19	25
	3/30/2001	98.92	5.62	93.30	9.9	0.49	2,000	48	39	39	ND
	9/30/2002	9.46	5.84	3.62	2.02	0.57	775	17.2	1.0	9.4	< 0.5
	2/20/2003	9.46	5.55	3.91	4.01		1,120	<50	<50	<100	<50
	1/12/2004	9.46	4.77	4.69	3.32		632	26.9	<25	< 50	
	5/12/2005	9.46	4.63	4.83	6.2		1,000	30.0	20.0	10.0	
MW-4	10/11/1995	99.46	6.63	92.83	0.5	< 0.05	17	1.1	<0.3	0.48	
	1/17/1996	99.46	5.77	93.69	0.46	< 0.05	72	4.1	< 0.3	1.7	***
	4/16/1996	99.46	5.89	93.57	2.20	< 0.05	851	7.67	1.41	5.72	
	8/26/1996	99.46	6.14	93.32	0.30	0.11	55	4.9	1.2	< 0.5	
	11/14/1996	99.46	6.72	92.74	0.20	0.20	3.4	< 0.5	<0.5	< 0.5	
	2/18/1998	99.46	5.02	94.44	1.60	0.28	320	9.1	1.0	0.59	1.7
	3/30/2001	99.46	6.21	93.25	2.7	0.35	320	16	5.3	13.6	ND
	9/30/2002	10.00	6.40	3.6	0.067	< 0.05	< 0.5	<0.5	<0.5	<1.5	<0.5
	2/20/2003	10.00	5.83	4.17	0.57		107	<10	<10	<20	<10
					0.70		122	13.5	0.6	8.8	
	1/12/2004	10.00	5.41	4.59						<5.0	
	5/12/2005	10.00	5.59	4.41	0.76		14.0	5.70	<5.0	<3.0	

Table 1
Historical Depth to Groundwater and Sample Results
Former Hegenberger Maintenance Station

Well	Date	TOC Elevation (feet)	Depth to Water (feet)	Groundwater Elevation (feet amsl)	TPHg (mg/l)	TPHd (mg/l)	Benzene (ug/l)	Toluene (ug/l)	Ethylbenzene (ug/l)	Xylenes (ug/l)	MTBE (ug/l)
**		·									
MW-5	10/11/1995	99.91	6.68	93.23	1.0	< 0.05	45	15	1.9	6.1	
	1/17/1996	99.91	5.74	94.17	< 0.05	< 0.05	2	< 0.3	< 0.3	< 0.3	
	4/16/1996	99.91	5.85	94.06	1.74	0.855	157	20.1	3.92	22.4	
	8/26/1996	99.91	5.99	93.92	0.90	0.27	55	6.4	0.9	3.7	
	11/14/1996	99.91	6.70	93.21	0.70	0.32	31	5.7	0.7	3.6	
	2/18/1998	99.91	5.74	94.17	1.20	0.58	14	5.2	0.76	5.5	9.5
	3/30/2001	99.91	6.73	93.18	1.5	0.48	7.2	6.5	< 0.50	10.7	ND
	9/30/2002	10.34	6.18	4.16	0.56	0.43	1.8	5.2	< 0.5	6.5	< 0.5
	2/20/2003	10.34	5.80	4.54	1.04		<2.5	8.6	<2.5	11.3	<2.5
	1/12/2004	10.34	5.60	4.74	1.82		4.2	8.0	0.6	12.8	647
	5/12/2005	10.34	6.18	4.16	1.3		<5.0	<5.0	<5.0	<5.0	

Notes:

TOC = Top of well casing

feet amsl - Feet above mean sea level

mg/l - Milligrams per liter

ug/l - Micrograms per liter

Project Name: Former Hegenberger Station	Project Number: E8220-06-17
Address: 555 Hogenburger RD. OAKland CA	Date: 5·12·05 Well Lock Number:
Well Number: Mw-i	Well Integrity: 6000
Development/Purge/Sampler(s): PArroyo	Ambient Conditions: Cloudy
131111111111111111111111111111111111111	Tanasan Goridianis.
Pre-Purge DO (mg/L) NA	
WELL VOLUME CALCULA	TION
Well Casing Total Well Depth to Linear Feet	Gallons Per
Diameter (in.) Depth (ft.) Goundwater (GW) of GW	<u>Linear Foot</u> 1 Well Volume (gal.) X 0.17 =
	X 0.38 =
19.50 - 4.45 = 15.05	x 0.66 = 9.93
6 - =	X 0.83 = X 1.5 =
GROUNDWATER SURFACE IN: Floating Product (ft.) (in.): GROUNDWATER PURGING Submersible Pump; Air Diaphrae	cence: NoNE Odor: YES
• • • • • • • • • • • • • • • • • • • •	girl dilip Outer
Stagnant Volume Volumes Purged Conductivit	
Volumes Purged Conductivit Purged (gal.) Time pH (µs/umhos)	
tare by (hardings)	(°C) (other)
0 0 0914 219 520	19.9 CLEAR
1 600 0917 7.12 557	19.6 Recovery
2 200 0920 210 629	79.7 Rate:
3 30.0 0924 7.13 684	
4	Fast Medium
5	Slów
6	
7	
8	·
10	
Depth to GW (ft.) (I) Initially 4.45 Sample C Depth to GW (ft.) 1 liter (L).	ment: <u>Disposable Bailer</u> containers No. Preservation Method/pH amber glass
(P) After Purging 19.00 40 ml VO	
	lypropylene
(S) Before Sampling 7.36 Trip Blank (P-S) / (P-I) X 100 = 90 % Total Recovery	
	(NTU): <u>N/A</u>
Calibrate Date 5 12-35	
PURGED WATER O	CONTAINMENT
Total drums at site: Water 💋 Soil 💆 Wate	er pump through treatment system
Remarks:	

Project Nam	ne: Former	<u>Hegenbe</u>	rger Stat	tion		iber: <u>E8220-06-</u>	<u> </u>
າບປະເວລີ. 	555 He Jano CA	devestioned	er KD		Date:5 Well Lock N		
Well Numbe		MW-2			Well Integrit	***************************************	
	nt/Purge/Sa		SAMOJO		Ambient Co	nditions: Sum	
Pre-Purg	e DO (mg/L	NA					
ļ.				JME CALCULA	TION	•	
Well Cas Diameter		l Well h (f <u>t.) Go</u>	Depth to undwater (GW	Linear Feet Of GW	Gallons Linear F		olume (gal.)
2	That Dept	-		= 51.611	X 0.17	7 =	olume (gal.)
1	19.15	. 5	:55	= = 13.60	X 0.38 X 0.66		
4.5	, , , <u>.</u>			= 13.60	X 0.83	= 7,41 3 =	
6		-		=	X 1.5	<u> </u>	
		. GROI	INDIA/ATEE	SURFACE INS	PECTION		\$****
Floatino Pro	oduct (ft.) (in			Sheen/Iridesc	ence: M	೨ <i>NÉ</i> Odor: _ :	JEC
ioaing i io	, , , , , , , , , , , , , , , , , , ,		<u> </u>	_ 0//00////////////////////////////////	- 70 C	<u> </u>	703
			GROUND	WATER PURGI	NG PURGE N	/ETHOD	
	•	Subme	rsible Pump	: Air Diaphrac	am Pump: (F	Honda Pump; Othe	er
				,			
Stagnant	Volume					, :	
Volumes	Purged			Conductivity	y Temp.	Color/Turbidity	•
Purged	(gal.)	Time	pН	(µs/umhos)	(°C)	(other)	•
٠,							
0	0 -	1009	6.96	1042	<u> 22.7</u>	CLEAR	Recovery
1	9.0	1011	6.92	996	22.3	4	1
2	18.0	1014	<u>6.92</u>	1023	22.2		Rate:
3	220	1017	6.97	1014	23.3		Fast
4						-	(Mèdium
5			_				Slow
6							İ
7		_					
8							
9							
10							
00010			•		~		
	IDWATER S	SAMPLING	S	ampling Equip	ment: <u>Dis</u> ç	<u>ocsable Bailer</u>	
AAgrei FeAF	Recovery	epth to GW	/# \	Sample C	ontainers	Na Dannaria	14-4521-11
(I) Initially		5.55	(IL)	1 litae (+)	conher alega	No. Preservati	on Method/pH
(P) After P		7.00		40 ml VQ	amber glass	11 1741	
P - 0.8 (P-I			% Recovery	A CONTRACTOR OF THE CONTRACTOR	lypropylene	4 HCL	· · · · · · · · · · · · · · · · · · ·
(S) Before (5. 55		Trip Blank			
(P-S) / (P-I)	X 100 = _	100 %T	otal Recove				· · · · · · · · · · · · · · · · · · ·
Sample Da	te/Time:	5-12-05	1055	Turbidity	(NTU): NA	:	
Calibrate D	nto:	530.05		•			
Canniare D	at s	2.12.02	bile	RGED WATER (CALTAINIAGE		
			rur	COLD WATER (N I	
Total drums	at site: Wa	eter 🛮 🖄	Soil _	Ø Wate	er pump throug	gh treatment system	Comm
•	•	-			•	<u> </u>	
Remarks: _		·		· · · · · · · · · · · · · · · · · · ·	······		
•							

Project Nar	ne: Former	· Hegenber	cser_Stat	ievo.		mber: <u>E8220</u>	-06-17	
Address: _	555 Ho Kland, CA	denpert i	RD_			5.12.05		
: UA	Kland, CA	<u> </u>			Well Lock I			-
Well Numb		1W-3	. A		Well Integr	ity: <u>Goesa</u>	В	
Developme	ent/Purge/Sa	mbiei(s): 🛨	: Huteric		Ambient Co	onditions: _S	·	
Pre-Purg	ge DO (mg/L) NA			· ·		,	
Well Ca	sing Tota	l Well.	WELL VOLU	JME CALCULAT	ION Gallon			
Diameter			ndwster (GW		Lînear	Foot 1	Well Volume (gal.)	
3~				=	X 0.: X 0.:	17 = 38 =		
	16.20	- 4.	63	= 14.87	X 0.6	· · · · · · · · · · · · · · · · · · ·	81	
4.5		•		=	X 0.8		•	:
	,,,		······································	:	X 1.5	<u> </u>		
Cleatine De				SURFACE INS			1155	
Floating Pr	oduct (ft.) (in	-): <u>Nov</u>		Sheen/Iridesce	nce: N	Odo	ir. <u>YES</u>	
	•		GROUND\	NATER PURGI	NG PURGE	METHOD		
		Submer	sible Pump;	Air Diaphrag	m Pump; (Honda Pump;	Other	
Stagnant	Volume					÷	•	,
Volumes	Purged			Conductivity	Temp.	Color/Turbid	litv	
Purged	(gal.)	Time	Hq	(µs/umhos)	(°C)	(other)	•	•
0	0	0954	7-17	1213	22.9	CLEAR		
1	10.0	0956	7.01	1212	<u>.</u>			overy
-	20.0	0958	6.97		23.4		R	ate:
2		1000		1361			Fast	
3	<u> 36.0</u>		6.97	1300	22.3			
4			 ,			· · · · · · · · · · · · · · · · · · ·	Medium	
5					-		(Slow)	
6								
7								. ,
8		-				•		
9								
10								
	NDWATER S	AMPLING	S	ampling Equipn Sample Co	nent: <u>Dis</u>	posable Be	iler	
		epth to GW (ft. \	Cample Co	manier 3	No. Pres	ervation Method/pl	н
(i) Initially		4.63	,	1 liter (τ.)	amber glass	****	er varion i vieti i odi pi	
(P) After P	_	9.00		40 ml VOA	-			
P - 0.8 (P-	~ ~		Recovery	500 ml poly		HCI	<u> </u>	·
(S) Before		1.50	110001019	Trip Blank	hiopylene			
(P-S) / (P-I)			otal Recover	у		<u> </u>		-
Sample Da	ite/Time:	5-12-05/	1045	Turbidity ((עדא: <u>א</u>	4		
Calibrate D	oatea	5-12-05				•	,	
	_	-	PUR	GED WATER C	ONTAINME	NT		
Total drums	s at site: Wa	iter <u>Ø</u>	Soil	Ø Water	r pump throu	ugh treatment sy	stem	
Remarks:	· · · · · · · · · · · · · · · · · · ·							<u> </u>
							•	

Project Nam	ie: <u>Former</u>	<u> Hegenbei</u>	<u>rger Stat</u>	iov			(7
Address:	555_He	genbergi	Z RD.				
UAK	<u>land (A</u>	· · · · · · · · · · · · · · · · · · ·					
) A				
Develobiliei	wruigeroa	inhici(s). 🛨	: Huteric		Ambient Co	iluliions. <u>Idano</u>	
Pre-Purg	e DO (mg/L) NA				· · · · · · · · · · · · · · · · · · ·	
			WELL VOLU	ME CALCULAT	ION		
			Depth to	Linear Feet			
Diameter 2	(in.) Dept	n (π.)Gos	undwater (GW)	of GW	Linear i		olume (gal.)
3~	3, . .	`سر -		=	X 0.3	8 =	
	16.62	- 5.	7.4	= 11.06	X 0.66	-	
6		_		=			
Floating Pro	duct (ft.) (in					NE Odor:	YES
			CPOUNDY	ATED DUDGIN	IG BLIDGE N	METUOD	
							•
		Submer	sible Pump;	Air Diaphragi	m Pump; 🔱	Honda Pump; Other	er
Staanant	Volumo				•		
				Conductivity	Temp	Color/Turbidity	
	_	Time	ъН		•	•	
	(5)		F	(pora)	()	(outer)	,
U ,	n	0933	6.84	1991-	22.3	CLEAR	
Well Number: MW-Y Well Integrity: Well Conditions: Closed Pre-Purge DO (mg/L) N A							
							Rate:
							Fast
		01700	7.07	200			Medium
				<u> </u>			
							(0.0.1)
							
							
			· ,				
							
, 10							
		SAMPLING	Sa	mpling Equipn	ient: <u>Dis</u> g	ocsable Bailer	
Water Leve			-				•
713 Initially			ft.)			No. Preservati	on Method/pH
							
			& Pacayon			HCL_	
			o Necovery		bioblieue		
			otal Recover				
, , , ,	_				4		
Sample Dat	te/Time:	5-12-05/	1040	Turbidity (NTU): <u>N/A</u>	<u> </u>	
Coliberto D	ata (ייי אי מיני					
Calibrate Di	are -	3.12.07	DIIO	CED WATER C	ONTAINIBE	NT	
			FUR	OFF MATER C	ONTAIMME	IA 1	
Total drums	at site: Wa	iter <u>Ø</u>	Sail	Ø Water	r pump throu	oh treatment system	-
						J.:	
Remarks: _		· · · · · · · · · · · · · · · · · · ·					<u> </u>
				•		•	

	ne: Former			ion	Project Nur	nber: E8	220-06-1	1
Address: _	555 Heg	genberge	KD.			<u>5-12-05</u>	<u> </u>	·
Well Numb	Kland (A.	1-2	 		Well Lock N			
	er: <u>Pro</u> ent/Purge/Sar		A.m.		Well Integri Ambient Co		(Maria)	
Developine	in ruigeroai	inpier(s). 🚓	Huodo -		Vilipietif or	muldons	Clouby	
Pre-Purg	ge DO (mg/L) NA	·····					
-		1	WELL VOLU	ME CALCULAT	ION			
Well Car		Well	Depth to	Linear Feet	Gallon	- •	4 141-11 1 5-1	
Diameter 2	r (în.) Dept	n (TL) GOL	indwater (GW)	of GW =	Linear X 0.1			ume (gal.)
	19.35	- In	18	= (3.17)	X 0.3		8.69	
4.5	141.23	- 6		= = (2·()	X 0.6		8.69	
6	· · · · · · · · · · · · · · · · · · ·	, -	<u> </u>	=	X 1.5			
		GROU	NDWATER	SURFACE INS	PECTION			
Floating Pr	oduct (ft.) (in			Sheen/Iridesce		VE	Odor: Y	ES
•	ř.		CDCUNDU	VATER RUDOR	IC DUDGE	METHOD	,	
				VATER PURGI				
		Submer	sible Pump;	Air Diaphrag	m Pump; (Honda Pun	np; Other	
Stagnant	Volume							
Volumes	Purged		•	Conductivity	Temp.	Color/Tu	urbidity	
Purged	(gal.)	Time	pН	(µs/umhos)	(°C)	(other	•	
	•	<u>.</u>		S. C.				· ·
0	0	0848	6.97	749	19.3	<u> </u>	AR	Recovery
1	9.0	0852	6.97	797	19.8			i
2	18.0	0857	6.92	817	20.0			Rate:
3	27.0	0859	6.94	840	20.2	Dry (D)	124 GAL	Fast
4								Medium
5								(Slow)
6								
7								
8					,		<u> </u>	1
9							-	
10								
GROUN	NDWATER S	A MIDLINIC	0.	malina Cautan	name Tim	and a laic	Qalica	
	el Recovery	MINIFERING	30	mpling Equipm Sample Co		POSHIDIO	<u> Derib</u>	· .
		epth to GW (ft.)	<u>campic oc</u>	<u> </u>	No.	Preservation	n Method/pH
(I) initially		6.18	,	1 liter (L), a	amber glass			
(P) After F	Purging	9.35 (Dry)		40 ml VOA	_		HCL	
P - 0.8 (P-		8.81 80%	Recovery	500 ml pol	ypropylene			
(S) Before		8.81		Trip Blank				
(P-S) / (P-I) X 100 = _	<u>50</u> % To	otal Recover	у			·-··	
Sample Da	ate/Time:	5-12-05/	1023	Turbidity	(NTU): <u>И</u>	4		
Calibrate D	Date _8	5-12-05						
			PUR	GED WATER C	ONTAINME	NT		
Total drum	s at site: Wa	ter Ø	Soil	Wate	r pump throu	ugh treatme	nt system _	
Remarks:		· · · · · · · · · · · · · · · · · · ·						
4		•				··· ···	-	



Environmental Laboratories

John Love Geocon Consultants, Inc. 2356 Research Dr Livermore, CA 94550

Client

Geocon Consultants, Inc.

Workorder

16879

Former Hegenberger Maint Stat.

Received

05/13/05

The samples were received in EPA specified containers. The samples were transported and received under documented chain of custody and stored at four (4) degrees C until analysis was performed.

Sparger Technology, Inc. ID Suffix Keys - These descriptors will follow the Sparger Technology, Inc. ID numbers and help identify the specific sample and clarify the report.

DUP - Matrix Duplicate

MS - Matrix Spike

MSD - Matrix Spike Duplicate

LCS - Lab Control Sample

LCSD - Lab Control Sample Duplicate

RPD - Relative Percent Difference

QC - Additional Quality Control

DIL - Results from a diluted sample

ND - None Detected

RL - Reporting Limit

Note: In an effort to conserve paper, the results are printed on both sides of the paper.

Ray James

Laboratory Director



Environmental Laboratories

Test Certificate of Analysis

Client ID

Geocon Consultants, Inc.

Workorder # Laboratory ID 16879 16879001

Sample ID Matrix MW-1 Water Workorder ID Former Hegenberger Maint Stat.

Sampled

05/12/05 05/13/05

Received Reported

05/25/05

8260B Oxygenates - 8260B

Parameter		Prep Date	Analyzed	Result	RL Units	Dilutior
Benzene		05/24/05	05/24/05	20.0	5.00 ug/L	1:5
Toluene		05/24/05	05/24/05	ND	5.00 ug/L	1:5
Ethylbenzene		05/24/05	05/24/05	ND	5.00 ug/L	1:5.
Xylene (Total)		05/24/05	05/24/05	ND .	5.00 ug/L	1:5
Surrogates	Docult	Danas	rom I imita			l

Surrogates Result Recovery Limits
1,2-Dichloroethane-d4 44 ug/L 88 % (65 - 135)



Environmental Laboratories

Test Certificate of Analysis

Client ID

Geocon Consultants, Inc.

Workorder # Laboratory ID 16879 16879002

Sample ID Matrix MW-2 Water Workorder ID Former Hegenberger Maint Stat.

Sampled Received

05/12/05

Reported

05/13/05 05/25/05

8260B Oxygenates - 8260B

Parameter	P	rep Date	Analyzed	Result	RL U	Units	Dilution
Benzene	0	5/24/05	05/24/05	ND	1.00 u	ıq/L	1:1
Toluene	0	5/24/05	05/24/05	ND	1.00 t	ıq/L	1:1
Ethylbenzene	0	5/24/05	05/24/05	ND	1.00 t	-	1:1
Xylene (Total)	0	5/24/05	05/24/05	ND	1.00	-	1:1
Surrogates	Result	Recoy	•	s _ 135\			



Environmental Laboratories

Test Certificate of Analysis

Client ID

Geocon Consultants, Inc.

Workorder # Laboratory ID

16879

Sample ID

16879003 MW-3

Matrix

Water

Workorder ID Former Hegenberger Maint Stat.

Sampled

05/12/05

Received

05/13/05

Reported

05/25/05

8260B Oxygenates - 8260B

Parameter	Prep Date	Analyzed	Result	RL Units	Dilutio:
Benzene	05/24/05	05/24/05	1000	10.0 ug/L	1:10
Toluene		05/24/05	30.0	10.0 ug/L	1:10
Ethylbenzene		05/24/05	20.0	10.0 ug/L	1:10
Xylene (Total)	05/24/05	05/24/05	10.0	10.0 ug/L	1:10

Surrogates Result Recovery Limits 1,2-Dichloroethane-d4 45 ug/L 90 % (65 - 135)



Environmental Laboratories

Test Certificate of Analysis

Client ID

Geocon Consultants, Inc.

Workorder # Laboratory ID 16879 16879004

Sample ID Matrix 1687900 MW-4 Water Workorder ID Former Hegenberger Maint Stat.

Sampled

05/12/05

Received Reported 05/13/05 05/25/05

8260B Oxygenates - 8260B

Parameter		Prep Date	Analyzed	Result	RL Units	Dilutior
Benzene		05/24/05	05/24/05	14.0	5.00 ug/L	1:5
Toluene		05/24/05	05/24/05	5.70	5.00 ug/L	1:5
Ethylbenzene		05/24/05	05/24/05	ND	5.00 ug/L /	1:5
Xylene (Total)		05/24/05	05/24/05	ND	5.00 ug/L	1:5
Surrogates	Result	Recov	•			
■ 1 2-Dichloroethane-d4	46 ua/L	Q 2 9	165	_ 135\ .		



Environmental Laboratories

Test Certificate of Analysis

Client ID

Geocon Consultants, Inc.

Workorder # Laboratory ID 16879 16879005

Sample ID Matrix MW-5

Water

Workorder ID Former Hegenberger Maint Stat.

Sampled

05/12/05

Received

05/13/05

Reported

05/25/05

8260B Oxygenates - 8260B

Parameter	Prep Date Analyzed	Result	RL Units	Dilution
Benzene	05/24/05 05/24/05	ND	5.00 ug/L	1:5
Toluene	05/24/05 05/24/05	ND	5.00 ug/L	1:5
Ethylbenzene	05/24/05 05/24/05	ND	5.00 ug/L	1;5
Xylene (Total)	05/24/05 05/24/05	ND	$5.00~{ m ug/L}$	1:5

Surrogates	Result	Recovery	Limits
1,2-Dichloroethane-d4	45 ug/L	90 %	(65 - 135)



Environmental Laboratories

Test Certificate of Analysis

Client ID Workorder# Geocon Consultants, Inc.

16879

Workorder ID Former Hegenberger Maint Stat.

Parameter Method	TPHgas 8015M DHS				N.			
Lab ID	Sample ID	Result	RL	Units	Collected	Analyzed	Matrix	Dilution
16879001	MW-1	1200	50	ug/L	05/12/05	05/23/05	Water	1:1
16879002	MW-2	330	50	ug/L	05/12/05	05/23/05	Water	1:1
16879003	MW-3	6200	50	ug/L	05/12/05	05/23/05	Water	1:1
16879004	MW – 4	760	50	ug/L	05/12/05	05/23/05	Water	1:1
16879005	MW-5	1300	50	ug/L	05/12/05	05/23/05	Water	1:1



Environmental Laboratories

Method Blank Report

Client ID

Geocon Consultants, Inc.

Workorder ID

Former Hegenberger Maint Stat.

Laboratory ID

68904

Sample ID

MB for HBN 266350 [VGXV/2696]

Matrix

Parameter	Method	Prep Date	Analyzed	Result	RL Units	Dilution
TPHgas	8015M DHS	05/23/05	05/23/05	ND	50 ug/L	1:1



Environmental Laboratories

Lab Control Sample Report

Client ID

Geocon Consultants, Inc.

Workorder ID

Former Hegenberger Maint Stat.

Laboratory ID 68905 Sample 1D

LCS for HBN 266350 [VGXV/2696]

Matrix

Parameter	Method	Prep Date Analyzed	Result	RL Units	Dilution
TPHgas	8015M DHS	05/23/05 05/23/05	1010	50 ug/L	1:1



Environmental Laboratories

Lab Control Sample Duplicate Report

Client ID

Geocon Consultants, Inc.

Workorder ID

Former Hegenberger Maint Stat.

Laboratory ID

6890

Sample ID

LCSD for HBN 266350 [VGXV/2696

Matrix

Parameter	Method	Prep Date Analyzed	Result	RL Units	Dilution
TPHgas	8015M DHS	05/23/05 05/23/05	1080	50 ug/L	1:1



Environmental Laboratories

Matrix Spike Report

Client ID Workorder ID Geocon Consultants, Inc.

Former Hegenberger Maint Stat.

68907

Laboratory ID Sample ID

MS for HBN 266350 [VGXV/2696]

Matrix Water

Parameter	Method	Prep Date	Analyzed	Result	RL Units	Dilution
TPHgas	8015M DHS	05/23/05	05/23/05	900	50 ug/L	1:1



Environmental Laboratories

Matrix Spike Duplicate Report

Client ID

Geocon Consultants, Inc.

Workorder ID

Former Hegenberger Maint Stat.

Laboratory ID

68908

Sample ID MSI

MSD for HBN 266350 [VGXV/2696]

Matrix

Parameter	Method	Prep Date Analyzed	Result	RL Units	Dilution
TPHgas	8015M DHS	05/23/05 05/23/05	1020	50 ug/L	1:1



Environmental Laboratories

QC SUMMARY

Client ID Workorder ID QC Batch Geocon Consultants, Inc.

Former Hegenberger Maint Stat.

VGX 2809

Matrix Water

Original

16888001

Samples Matrix Spike [68907]

Matrix Spike Duplicate [68908]

Parameter	Spike %Recovery	• •	Recovery Limits	RPD	RPD Limits
TPHgas	90	102	(65-135)	13	(20 MAX)



Environmental Laboratories

QC SUMMARY

Client ID Workorder ID Geocon Consultants, Inc.

Workorder II

Former Hegenberger Maint Stat.

QC Batch VGX 2809

Matrix Water

Samples

Lab Control Sample [68905]

Lab Control Sample Duplicate [68906]

Parameter	Check %Recovery	Check Dup %Recovery	Recovery Limits	RPD	RPD Limits
TPHgas	101	108	(65-135)	6.7	(20 MAX)

yticai Labo		۶h	one: (916)	362-	8947								13	42	უ			_		. I.e		- A I	المسدار		1									
le Circle, #112 Si	-		27						-AX: (Pa	de -	į		i	_ــــ				LYS		-			ce N	uma	Jer.v				1
any: Gaoden						Ph	on a :	(12)	13	1 (-)	5 (° t	<u>ا</u> ك							,,,,, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	··-··			AMA	LYS	15 H		UES) [<u> </u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
Menager: Tob	n Lize é	2				F	AX:	(12:3	13	71-	511]PE	MA	AKS) :		٠									Sampler's Name:						
Menager: John Address:	<u> </u>	·	Billin			Addr	ess:																						1	A	(1, 15	40			
ic RESCHIC	H. Dr	الرابية ا	a no	Qr^đ	. , C	A	q	533	5			:																	1			ij			
																,							1	/		ne		onie			· 				_
Name:			.,		Proj	ect/Jo	ob#:	286	:2C	(1)	. (1	_]_						-	°C	<u> C</u>)K_	<u>C</u>)K_		OK_	- V	<u>/ET(</u>	STL	<u>C)</u>	-		
a Helsopeal	er HH	চল্ল ি ট্ৰাই	di 3	es.								1					Ten				-		<u> </u>	-	├-				 	TC	CLP		1		
Location:						R	O.#:					ļ			ļ		e Co	noit	ion		├			 · .	 		ļ		+		/ E-I		·		
ikiano, ca	-T		7					 							pH					 	TC	LP	<u> </u>					- Andrewson	+	Tr	otal	<u> </u>	1		1
	_			_					serva	1			- A7		-		Ţ	T	1	T -	T	<u> </u>	<u> </u>	Γ	<u> </u>	Ţ	T	T	-	<u> </u>			1	TAT	
	Sar	npling	-	Co	on tal	Iner	Т	-	Usec			Pys:	atrix	<u> </u>	 	-	3	 	 	1		-	-			-		-	1			-	-		- ;
SAMPLEID HW-i MW-2	Date Sit2(c)	Time 1032 1055		Brass Sleeve	1 Lamber bottle	250 mL Plastic	Other	X X	None	Other:	X X Water	Soil	Air	Other:		X X BTEX/(FHgas) 602/8020/(6015)	TPHdlese\TPHmotor oil/kerosena(3015)	EPA 601/8010/502.2/504	EPA 602/8020	EPA 608/8080 (Pesticides)/505/508	EPA 608/8080 (PCB/S)	EPA 624/8240/524.2	EPA 625/8270/525	Total Oil & Grease (5520)	Non-Polar O & G/TRPH (418.1)	Organic Lead	Acı		CAM-17 Metals	CAM-5 Metals (Cd, Cr, Pb, Ni, Zn)	pag		Standard	Rush Services (72hr./ 48hr / 24hr / 12hr)	
MW-3		1045	+ Williams					X			X	:		<u> </u> 	×	X				<u> </u>								 			-				 K
itw.4		1040				ļ		X			\succeq		} 	<u> </u>	×	X		<u> </u>	ļ																_
MW-5	11/	1003	X.				ļ	X			X	_			×	×				<u> </u>													<u> </u>		
	<u> </u>	<u> </u>	<u> </u>			ļ						-!			_																				
		ļ	ļ		ļ																										\dashv				
		<u></u>		<u> </u>								ِ											-						 						
		ļ	<u> </u>									-								-		-				[\vdash					_	
ished by:		<u> </u> 			Reg	give	TY.	rile	201	<u>_</u> _ 					Reli	ngui	shed	Z			1			_]	Rec	eived	i by:	 		l			1		_
5/11/05	Time:	ℓ'			Dat	- گ :e	7/3	108	_Y	Time	a: /	2,	20		Date	∌ :		171				6. Z	: Z	ا ن	Date):						Time	a:		
	1 1:11(3-1			i			PIF	ASF	RE	AD	₹ĒV	ERS	ES	IDE	FOR	TE	AMS	AN	D C	OND	ITIO	NS							-						