8 March 1995 Ref: 726104.05000

Alameda County Health Care Services Agency Department of Environmental Health Hazardous Materials Division 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502

Attention: Ms. Madhulla Logan

Subject: Ouarterly Progress Report 2 (January - March 1995)

Redwood Regional Park Service Yard, Oakland, California

Dear Ms. Logan:

#### INTRODUCTION


This report presents the results of the February 1995 groundwater monitoring event conducted by Parsons Engineering Science, Inc. (Parsons ES) (formerly Engineering-Science, Inc. [ES]) at the East Bay Regional Park District (EBRPD) Redwood Regional Park Service Yard in Oakland, California. This report presents the results of the second consecutive groundwater monitoring event in the site quarterly monitoring program which is designed to evaluate the extent and magnitude of groundwater contamination associated with two former leaking underground fuel storage tanks (UFSTs). A summary of previous site characterization and remedial activities associated with the former UFSTs is presented in the first quarterly progress report (Parsons ES 1994). An annual summary assessment report will be presented following the fourth quarterly monitoring event of 1994 (scheduled for August 1995). That summary report will summarize the year of quarterly groundwater monitoring activities, analyze hydrochemical trends, and evaluate regulatory agency criteria governing detected groundwater contaminants.

## Site Description

The project site is located at **7867 Redwood Road** in Oakland, Alameda County, California. Figure 1 shows the location of the project site. The project site is a service yard for Redwood Regional Park, and utilized two UFSTs (one 2,000-gallon diesel fuel and one 5,000-gallon unleaded gasoline) from the mid-1960's until their removal in 1993. Figure 2 is a site plan which shows the limits of the former UFST remedial excavation and the groundwater monitoring wells which were installed in October 1994 to monitor groundwater impacts associated with the former UFSTs.

# Site Stratigraphy and Hydrogeology

Shallow soil stratigraphy beneath the project site consists of a surficial 3 to 10 foot thick clayer silt unit underlain by a 5 to 15 foot thick silty clay unit. In all monitoring



Alameda County Health Care Services Agency 8 March 1995 Page 2

well borings, a 5- to 10-foot thick clayey coarse-grained sand and clayey gravel unit was encountered that laterally grades to a clay or silty clay. This unit overlies a weathered siltstone at the base of the observed soil profile. Soils in the vicinity of MW-1 are inferred to be landslide debris.

Groundwater at the site occurs under unconfined or possibly partially confined conditions, as evidenced by the equilibration of static water levels relative to the first occurrence of groundwater encountered during drilling for the 1993 site characterization and November 1994 well installation program. The February 1995 data indicate that the direction of local groundwater flow beneath the project site is approximately from northeast to southwest. This groundwater flow direction is consistent with previously recorded measurements made in site wells in November 1994 (Parsons ES 1994).

#### PROCEDURES AND CURRENT ACTIVITIES

The current groundwater monitoring program is in accordance with the Workplan for Groundwater Characterization Program (ES 1994).

#### **Laboratory Analyses**

All laboratory analyses were conducted by a laboratory certified by the California Environmental Protection Agency (CalEPA) Environmental Laboratory Accreditation Program (ELAP) for each required analytical method. All groundwater samples were analyzed for the following constituents:

- Total petroleum hydrocarbons gasoline, diesel and kerosene ranges (TPH-G, -D, and -K) by the State of California Department of Toxic Substances Control (DTSC) Leaking Underground Fuel Tank (LUFT) Manual Method (equivalent to modified EPA Method 8015)
- Aromatic hydrocarbons (including benzene, toluene, ethylbenzene, and total xylenes [BTEX]) by EPA Method 8020

# **Groundwater Monitoring and Sampling**

Parsons ES personnel measured static water levels (Table 1 and Attachment A) in all six site wells on 9 February 1995. Water level measurements were made using an electric water level indicator. Initial water level measurements were collected immediately upon removal of the well casing caps. Water levels were then remeasured after a period no less than one-half hour to allow dissipation of potential air pressure and equilibration of static water levels. No differences in static water levels were noted.

Groundwater sampling was conducted on 9 February 1995 in accordance with California Water Resources Control Board (WRCB 1989) guidelines for sampling dissolved product in groundwater associated with leaking USTs. Prior to collection of groundwater samples, a pre-cleaned Teflon<sup>TM</sup> bailer or submersible pump was used to purge a minimum of three casing volumes from each well. Electrical conductivity, pH, and temperature of purge water were measured during well purging, to document the

Alameda County Health Care Services Agency 8 March 1995 Page 3

presence of stabilized formation-water in the wells. Attachment A includes water level data and groundwater monitoring field notes from the groundwater monitoring event.

Sample containers were filled with sample water from the pre-cleaned bailer. To prevent cross-contamination, groundwater sampling equipment was decontaminated prior to use and between each monitoring well with an Alconox<sup>TM</sup> wash followed by three deionized water rinses. Following sample collection, sample containers were labeled, placed in a cooler packed with "blue ice," and transported under chain-of-custody the same day to a CalEPA ELAP certified laboratory. Chain-of-custody records for the groundwater samples are included in Attachment B.

A total of approximately 215 gallons of wastewater (including monitoring well purge water and equipment decontamination rinsate) from the sampling event was containerized on site in a plastic storage tank.

## **Creek Surface Water Sampling**

Surface water samples were not collected from Redwood Creek during the February 1995 monitoring event because there was no water present in the creek at the time of the event.

## **Analytical Results**

Analytical results of the February 1995 monitoring event are presented in Table 2. Fuel hydrocarbons were detected in MW-2, MW-4 and MW-5 during both the present and previous quarterly sampling events. Detected concentrations reported for the present quarter are greater by as much as one order of magnitude compared to concentrations reported for the previous quarter. This may be a result of water table fluctuation; measured water levels in all site wells except MW-3 were higher this quarter with an increase of 0.5 to 5.6 feet compared to the previous quarter. Future quarterly monitoring will assess trends in concentrations and water level elevations.

Two types of field quality control (QC) samples were used to assess whether field or laboratory procedures affected analytical results of the current groundwater sampling event. One equipment rinsate blank (MW-0B) was collected following sampling and decontamination activities at well MW-4 to monitor potential cross-contamination in the field due to inadequate decontamination of sampling equipment and/or sample contamination during transport. That sample was analyzed for TPH-G and BTEX; none of these constituents were detected, verifying the integrity of field decontamination procedures and sample containers.

One field duplicate sample (MW-0A) was collected from well MW-4 and analyzed for TPH-G and BTEX to assess whether field procedures produced reproducible results. The field duplicate sample contained 9,400 gHz TPH-G (compared to 11,000 gHz in the field sample), which is a variance of approximately 16 percent from the mean (aka relative percent difference [RPD]). Values of RPD for BTEX constituents were 7, 6, 7 and 9 percent, respectively.

ug/l

Alameda County Health Care Services Agency 8 March 1995 Page 4

Laboratory QC samples (e.g., method blanks, matrix spikes, surrogate spikes, etc.) were analyzed by the laboratory in accordance with the requirements of each analytical method. All laboratory QC sample results and sample holding times were within the acceptance limits of the methods (Attachment B).

We trust that this submittal meets the needs of your agency. Please call us at our Alameda office (510-769-0100) if you have any questions or require clarification.

Very truly yours,

PARSONS ENGINEERING SCIENCE, INC.

Brue M. Rully.


Bruce M. Rucker Project Manager

Frederick T. Stanin, C.E.G.

**Technical Director** 

#### REFERENCES

- Engineering-Science, Inc. (ES) 1994, Workplan for Groundwater Characterization Program at Redwood Regional Park Service Yard, Oakland, California. 17 August
- Parsons Engineering Science 1994, Quarterly Progress Report 1 (October December 1994), Redwood Regional Park Service Yard, Oakland, California. 28 December
- Water Resources Control Board (WRCB) 1989, Leaking Underground Fuel Tank Field Manual: Guidelines for Site Assessment, Cleanup, and Underground Storage Tank Closure: State of California Leaking Underground Fuel Tank Task Force. October






TABLE 1
WELL ELEVATIONS AND WATER LEVEL MEASUREMENTS
February 1995

Well	,	Well Elevation(TOC)	Water Levels	
MW-1	Depth		1.64	
	Elevation	565.9	564.3	
MW-2	Depth		18.87	
	Elevation	566.5	547.6	
MW-3	Depth		18.27	
	Elevation	560.9	542.6	
MW-4	Depth		12.31	
	Elevation	548.1	535.8	
MW-5	Depth		14.40	
	Elevation	547.5	533.1	
MW-6	Depth		12.68	
	Elevation	545.6	532.9	

#### Remarks:

- 1) All water level depths are feet below top of well casing (TOC)
- 2) All elevations are feet above USGS mean sea level (MSL). Elevations were surveyed by EBRPD relative to USGS Survey Benchmark No. JHF-49.

TABLE 2

GROUNDWATER SAMPLE ANALYTICAL RESULTS
9 February 1995

Redwood Regional Park Service Yard, Oakland, California

	Concentration (g/L) · ug/L									
Compound: Reporting Limit:	TPH-G 50	TPH-D/K 50	Benzene 0.5	Toluene 0.5	Ethylbenzene 0.5	Total Xylenes 0.5				
Sample Location										
MW-1	ND	ND	ND	ND	ND	ND				
MW-2	89	ND	18	2.4	1.7	7.5				
MW-3	ND	ND	0.8	ND	ND	ND				
MW-4	11,000	330	420	17	440	460				
MW-4*	9,400	NA	390	16	410	420				
MW-5	70	ND	0.6	ND	ND	ND				
MW-6	ND	ND	ND	ND	ND	ND				

#### Notes:

TPH-D/K = Total petroleum hydrocarbons - diesel/kerosene ranges

NA - Not Analyzed ND = Not Detected

g/L = Micrograms per liter, equivalent to parts per billion (ppb)

<sup>\* =</sup> Quality control field duplicate sample designated MW-0A on the chain-of-custody and analytical laboratory report TPH-G = Total petroleum hydrocarbons - gasoline range

# ATTACHMENT A WATER LEVEL DATA AND GROUNDWATER MONITORING NOTES

# WATER LEVEL DATA

### PARSONS ENGINEERING SCIENCE

DATE:

9 February 1995

PROJECT/LOCATION:

Redwood Regional Park Service Yard,

Oakland, California

PROJECT No.: 726104

PERSONNEL:

Alan C. Peel

	Water Level	Well Depth	Depth	Water Level	Well Casing	Gallons/	T.O.C. Elev.	Water Level
Well No	from T.O.C.	From T.O.C	to T.O.C	from G.S.	Dia.	Casing Vol.	USGS	USGS
MW-1	1.64	18.0	-2.3	-0.7	4	10.6	565.9	564.3
MW-2	18.87	36.5	-2.4	16.5	4	11.5	566.5	547.6
MW-3	18.27	45.0	-2.8	15.5	4	17.4	560.9	542.6
MW-4	12.31	26.0	-2.1	10.2	4	8.9	548.1	535.8
MW-5	14.40	26.0	-2.3	12.1	4	7.5	547.5	533.1
MW-6	12.68	27.0	-2.3	10.4	4	9.3	545.6	532.9

#### NOTES:

T.O.C. = Top of Casing

Gallons/casing volume for 4" inner diameter casing = 0.65 gallons per linear foot

Negative value for "Depth to T.O.C." indicates that T.O.C. is above ground surface

G.S. - Ground Surface

USGS = U.S. Geological Survey mean sea level (MSL)

C:\ebrpd\Feb95WL.wk1

All elevations surveyed by East Bay Regional Parks District relative to USGS Survey Benchmark No. JHF-49

# **GROUNDWATER SAMPLING FIELD NOTES**

#### PARSONS ENGINEERING SCIENCE

PROJECT/LOCATION: REDWOOD REGIONAL PARK SERVICE YARD, OAKLAND, CA

PERSONNEL: Alan Peel

PROJECT	NUMBER:	726104									DATE:		9 February 1995	
Well ID	Sampler Date Time	Water Level Before, Well Diameter and Depth*	Water Level After *	Gallons per Casing Volume	Well Purging Method	Pump On	Pump Off	Temp. (o C)	Specific Cond (umbos/ cm)	pН	Water	Sample Coll. Method	Analysis & Number/type of Containers	Comments
	ACP	1.64						14.0	85	7.03	0			
							1	14.2	650	7.65	11		İ	Turbid sample
MW-1	2/09/95	4"	1.64	10.6	G	1000	1010	14.2	650	7.75	22	В	(a) (b) & (c)	
								14.5	650	7.75	33		ļ	
	1025	18									ļ			
	ACP	18.87						14.6	700	NR	0			
		1				ĺ	İ	16.0	700	8.27	12	_		m 1111 11.11
MW-2	2/09/95	4"	32.88	11.5	G	1040	1130	16.0	700	7.83	24	B	(a) (b) & (c)	Turbid, bailed dry
						j	!	16.0	700	7.98	33			@ 33 gallons;
	1145	36.5						<u> </u>						fuel odor
	ACP	18.27		Ì				15.1	500	NR	0			
								14.7	470	8.4	18	_		Classesmale
MW-3	2/09/95	4"	21.07	15.4	G	1220	1256	14.7	470	7.95	36	В	(a) (b) & (c)	Clear sample
							İ	14.6	480	8.08	54		ĺ	
	1310	45			1	ļ		ļ			<u> </u>	<del> </del>		<u></u>
	ACP	12.31						13.5	575	8.30	0		<u> </u>	
								13.5	600	7.90	9	1 _	, , , , , ,	e:
MW-4	2/09/95	4"	17.84	8.9	G	1544	1606	13.7	600	7.64	18	В	(a) (b) & (c)	Semi-turbid; fuel odo
							1	14.1	600	7.65	27			
	1610	26				<u> </u>			<u> </u>			<u> </u>	L	

#### NOTES

- Measured from top of casing in feet
- WW -- Well Wizard; G -- Grundfos Pump; B Bailer
- Not Applicable NA

NR Not Recorded

- Total Petroleum Hydrocarbons as diesel (TPH-D), unpreserved {1: 1L amber bottles}. (a)
- BTEX, EPA Method 8020, HCl preserved (2: 40ml VOAs). (b)
- Total Petroleum Hydrocarbons as gasoline (TPH-G), HCl preserved (2: 40ml VOAs). (c)

# **GROUNDWATER SAMPLING FIELD NOTES**

#### PARSONS ENGINEERING SCIENCE

PROJECT/LOCATION: REDWOOD REGIONAL PARK SERVICE YARD, OAKLAND, CA

PERSONNEL: Alan Peel

Well	NUMBER: Sampler	Water Level	Water	Gallons	Well	Pamp	Pump	Temp.	Specific	pH	Total	Sample	Analysis &	Comments
ID.	Date	Before, Well	Level	per	Purging	On	ori	(0 C)	Cond	•	Water	Coll.	Number/type	
	Time	Diameter and	After *	Casing	Method				(umbos/ cm)		Purged (gais)		of Containers	
		Depth*		Volume	##									
	ACP	14.40						14.7	465	NR	0			
								14.5	460	NR	8			
MW-5	2/09/95	4"	15.75	7.5	G	1325	1348	14.4	460	8.96	16	В	(a) (b) & (c)	Turbid;
								14.4	460	8.56	24			fuel odor
	1400	26						14.3	460	8.31	32			
	ACP	12.68												
							1	13.0	440	NR	0			
MW-6	2/09/95	4*	23.18	9.3	В	NA	NA	12.2	430	9.3	10	В	(a) (b) & (c)	Very turbid
							ļ	12.1	435	8.75	20			
	1530	27			_		]	12.1	400	8.56	30	<u> </u>		
	ACP													
									ļ i					Field duplicate
MW-0A	2/09/95	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	В	(b) & (c)	collected at MW-4
												İ		
	1625									ļ				
	ACP													
					1									Equipment rinsate
MW-0B	2/09/95	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	(b) & (c)	blank, collected
		1							1					after decon. at
	1635						l	1				<u> </u>	<u> </u>	Well MW-4

#### NOTES

- Measured from top of casing in feet
- WW -- Well Wizard; G -- Grundfos Pump; B Baller
- NA Not Applicable
- NR Not Recorded

- Total Petroleum Hydrocarbons as diesel (TPH-D), unpreserved (1: 1L amber bottles). (a)
- BTEX, EPA Method 5020, HCl preserved {2: 40ml VOAs}. (b)
- Total Petroleum Hydrocarbons as gasoline (TPH-G), HCl preserved (2: 40ml VOAs). (c)

# ATTACHMENT B CHAIN-OF-CUSTODY RECORDS AND ANALYTICAL LABORATORY REPORT



# Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 9471O, Phone (510) 486-0900

# ANALYTICAL REPORT


Prepared for:

Parsons Engineering Science, Inc. 1301 Marina Village Parkway Suite 200 Alameda, CA 94501

Date: 17-FEB-95

Lab Job Number: 119871 Project ID: 726104

Location: EBRPD Redwood Regional



Reviewed by: Just K

Reviewed by:

This package may be reproduced only in its entirety.

Curtis & Tompkins, Ltd.

LABORATORY NUMBER: 119871

CLIENT: PARSONS ENGINEERING SCIENCE, INC.

PROJECT ID: 726104

LOCATION: EBRPD REDWOOD REGIONAL

DATE SAMPLED: 02/09/95
DATE RECEIVED: 02/10/95
DATE EXTRACTED: 02/14/95
DATE ANALYZED: 02/15/95
DATE REPORTED: 02/17/95

BATCH NO: 19056

# Extractable Petroleum Hydrocarbons in Aqueous Solutions California DOHS Method LUFT Manual October 1989

LAB ID	CLIENT ID	KEROSENE RANGE (ug/L)	DIESEL RANGE (ug/L)	REPORTING LIMIT (ug/L)
119871-001	MW-1	ND	ND	50
119871-002	MW-2	ND	ND	50
119871-003	MW-3	ND	ND	50
119871-004	MW-5	ND	ND	50
119871-005	MW-6	ND	ND	50
119871-006	MW-4	**	330*	50
METHOD BLANK	N/A	ND	ND	50

- ND = Not detected at or above reporting limit. Reporting limit applies to all analytes.
- \* Sample chromatogram does not resemble hydrocarbon standard.
- \*\* Kerosene range not reported due to overlap of hydrocarbon ranges.

QA/QC SUMMARY: BS/E	SD
	======================================
RPD, %	4
RECOVERY, %	116



LABORATORY NUMBER: 119871

CLIENT: PARSONS ENGINEERING SCIENCE, INC.

PROJECT ID: 726104

LOCATION: EBRPD REDWOOD REGIONAL

DATE SAMPLED: 02/09/95
DATE RECEIVED: 02/10/95
DATE ANALYZED: 02/10,11/95

DATE REPORTED: 02/17/95

BATCH NO.: 18977

Total Volatile Hydrocarbons with BTXE in Aqueous Solutions TVH by California DOHS Method/LUFT Manual October 1989 BTXE by EPA 5030/8020

LAB ID	SAMPLE ID	TVH AS GASOLINE (ug/L)	BENZENE (ug/L)	TOLUENE (ug/L)	ETHYL BENZENE (ug/L)	TOTAL XYLENES (ug/L)
119871-001	MW-1	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
119871-002	MW-2	. 89	18	2.4	1.7	7.5
119871-003	MW-3	ND(50)	0.8	ND(0.5)	ND(0.5)	ND(0.5)
119871-004	MW-5	70	0.6	ND(0.5)	ND(0.5)	ND(0.5)
119871-005	MW-6	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
119871-006	MW-4	11000	420	17	440	460
119871-007	AO-WM	9400	390	16	410	420
119871-008	MW-OB	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)
METHOD BLAN	K N/A	ND(50)	ND(0.5)	ND(0.5)	ND(0.5)	ND(0.5)

ND = Not detected at or above reporting limit; Reporting limit indicated in parentheses.

QA/QC SUMMARY: BS/BSD

	**
RPD, %	~ 5
RECOVERY, %	98

Enginee 1301 M Alamed Phone:

Engineering-Science, Inc.
1301 Marina Village Parkway, Suite 200
Alameda, California 94501
Phone: (510) 769-0100 Fax: (510) 769-9244

# **CHAIN OF CUSTODY RECORD**

PAGE / OF /

F		,					Ţ <u> </u>										<u> </u>
LABORATO				MANAGEI Ruck					- 	/ 	ANA	LYSI	S REC	7	7	_///	
PROJECT N				· · · · · · · · · · · · · · · · · · ·		٠,			1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1/2	r/1					/ 🕏 / /	
				2 1		ER.			T.	11/	/	/	/ /	/ /	/		
Kedwo	ou ru	egron	<i>y</i> /	ar u					$\overline{}$	-/	_/	$\overline{}$	$\overline{}$	-/	-/		
Redwood Regional Park  SAMPLER(S): (SIGNATURE)  AC Peel  M.				, ا	ૢ૽ૺ/ૢ	ر آهـ / او	3/ 3	7					3/ § /				
AC P	ed	//	u		<u> </u>	NO. OF CONTAINERS	MET			\ \?\ \ \?\	7 /	/ /	/ /	/ /	/ §	/ <del>₹</del> /	
SAMPLE ID	DATE	ТІМЕ	MATRIA	SAM	PLE LOCATION	NO	70.			T.			/			REMARKS	S
MW-1	02/09/95		H20	T .	#1	3	-	1	1						5 d	ang	
MW-Z		1140			2	3	V	~	1						1		
MW-3	19	1310			3	7	V	1	/								
MW-5		1400			5	3	V	/	V	_							
mw-6		1530			6	3	V	/	1							Note: VERY TO	UROD
MW-4		1610			4	3	V	1	1								
MW-BA		1625			ØA	2	V	1									
MW-ØB	V	1635	V		& B	Z	/	V							V		
1			<u></u>														
				,									-				· · · · · · · · · · · · · · · · · · ·
												-	,		<u> </u>	,	
				.e													
RELINQUISHE ////			2/0/	95	RECEIVED BY: (SIGNAL)	lees		LINQUI	SHED	BY(SI	GNATU	JRE)	DA	ITE	TIN	E RECEIVED BY: (SIGNA	TURE)
RELINQUISHE	D BY: (SIG	NATURE	) DAI	E TIME	RÉCEIVED FOR LABO (SIGNATURE)	RATQR	Y BY:	DAT	E 7	ПМЕ	REN	MARK	S:				