

PHONE LOG (U.S. Coast Guard)

2/9/94 Mark Casterson, PSI, (510) 284-3070, + Juliet Stein
Mr. Casterson inquired as to what needs to be done next after their 4th qtr sampling. I stated that gaily must continue & that plume delineation at both sites may be required of them depending on the 4th qtr monitoring results. Mr. Casterson stated that all the monitoring wells are screened from 5' to 15' by

12/9/94 Joe Dirhake, PSI, (510) 284-3070
Mr. Dirhake stated that they just completed a gaily report & submitted to the US Coast Guard in Nov 94. They have a contract w/ US Coast Guard to continue ground water monitoring.

12/9/94 Louis Rivero, Contact at US Coast Guard, 535-7275
Mr. Rivero stated that he would mail the latest quarterly report w/in the next wk.

12/20/94 Dave Stalters, 535-7275
Requested that future gaily reports use Sepp's detection limit for gas analysis per RWOCB guidelines.

12/20/94 Glenn Shurt, lab - Mr. Shurt stated that they have the equipment to go down to Sepp's detect l.

P. in Conversation

3/3/93

Christopher Lutton, U.S. Coast Guard
& Juliet Shier ¹⁵³⁵⁻⁷²⁶⁷

RE: U.S. Coast Guard

Mr. Lutton called in response to a Coe County letter requiring further investigations associated w/ the former 2,000-gallon diesel tank on the southeastern corner of the site. He did not think there was a problem w/ that tank. I stated that the reason I felt further investigations were required was because diesel was discovered in the stockpiled soil & apparently diesel was not stored in the two 2,000-gallon "gasoline" USTs, located on the western portion.

Pione Conversations 2/25/93

Mr. Casterson, consultant
& Juliet Shui

RE: U.S. Coast Guard, Alameda

Sample #7 in Hunter's Report
represents a composite sample of
tank rinsewater. Mr. Casterson
stated that he would FAX a copy
of a letter from Hunter Environmental
to John Spores, dated Jan 24 '89,
stating the source of Sample #7.
He will also FAX a copy of
Brygg & Assoc. Chain-of-custody.

P'nce Message (1/20/93

From Ltn. & Chrisutton, Coast Guard
To Juliet Shin 535-7267

RE: U.S. Coast Guard Support Center,
STID 2911

They have retained Professional Services Industries, Inc. to prepare work plan for two VST locations at the site and to implement work plan. These² work plans should be in to the County by the end of the month (January).

To: Mark Casterson, consultant 2/25/93
From: Juliet Shin

The reference to "two new VSTs" in the Feb. '93 work plan refers to the fact that the 70 former 5,000-gallon VSTs were replaced by two VSTs. I discussed the fact that the implementation details may not be

means if no soil contamination
is observed in the easternmost
proposed well locations for the
former 8,000-gall. UST area.

Phone Conversation

12/11/92

(510) 284-3070

From: Mark Gusterson, consultant
to: Juliet Stein

RE: STID 2911, U.S. Coast Guard

Mr. Gusterson called to confirm proper procedures for the preparation and submittal of a work plan. I told him that the County, specifically ~~me~~, need to receive a copy of the work plan to approve it before it is implemented. I also added that copies of all correspondence and reports need to be submitted to Rich Platt, RWACB.

DATE 5/6/92

CONTACT LOG

FROM: Juliet Shin AFFILIATION: Alameda County
TITLE: Env. Mat. Specialist PHONE: (510) 271-4320
TO: Chris Lutton AFFILIATION: U.S. Coast Guard
TITLE: Lieutenant PHONE: 535-7267

RE: STID 2911 - U.S. Coast Guard, Support Center, Alameda

Mr. Lutton stated that he had a diagram showing where the soil samples were collected from the tank pits in 1988. He also stated that the excavated soils were removed from the site. He will send the manifests along w/ the diagram of sampling locations.

5/20/92

Mr. Lutton stated that he's having problems locating copies of the hazardous waste manifests. He is working on it though. He stated that if he can't find the manifests w/in a week of this date, then he won't be able to work on it for the following three weeks because he's going on vacation.

10/5/92

Mr. Lutton stated that he still could not locate manifests for stockpiled soil that was hauled off site. Ms. Shin stated that she would check w/ the state water board for a copy. Ms. Shin asked if there was a Tank Closure Plan. Mr. Lutton stated that he had a copy right in front of him & would make a copy & send it to Ms. Shin w/ any other available files on the

U.T.

FILE OR] ENVELOPE
 PER NO.] No. of

OWNER **US Coast Guard**
 Address **Support Center**
Alameda Phone

Contractor **SEMCO**
 Address **431 W. Hatch Rd.**
Modesto Phone

OTHER (Specify)
 Address
 Phone **209/524-9653**

PLAN REVIEW

\$ **600.00** Rec'd.

No. Plans Rec'd.

Plans Approved

Layout Made

Rejected

Applicant Notified

Plans Returned

Permit Issued

CONSTRUCTION PROGRESS ACCEPTANCE

FOOD
 Pre-Plaster/drywall
 Pre-Final
 Final

By Date

POOL
 Pre-Concrete/Gunite
 Pre-Plaster
 Final

EXCAVATION
 Septic Tank
 Absorption Field
 Absorption Bed
 House Sewer

FINAL
 Septic Tank
 Absorption Field
 Absorption Bed

OTHER

U.G. TANKS
 Pre-Covering
 Final

LOP
2911a

CLOSED

CONTACT FOR INVESTIGATION **Terry Hamilton**

XR

REMARKS

LOCATION

Date By

Date By

Vicinity Map

REMARKS

Date By

11/29 DB Plan Reviewed, Approved

12/30 DB Tanks Removed