



FACSIMILE COVER SHEET

CHEVRON U.S.A. PRODUCTS COMPANY
MARKETING - NORTHWEST REGION



Mailing Address : Chevron U.S.A. Products Company
P.O. Box 5004
San Ramon, CA 94583-0804
(Street - 2410 Camino Ramon)

Date : 8-27-92 Fax Number : 510 589-4757

To : Susan Hogg - Alameda Co. Environmental Health

From: Kenneth Kan Site Assessment & Remediation Group	Phone Number	Room / Building
	(510) 842-8752	A-02 / 2410

Subject : Chevron Station: 9-1740 in Montclair

Remarks : ATTACHED IS A SITE PLAN SHOWING AND IDENTIFYING SAMPLING LOCATIONS. ALSO ATTACHED IS A TABLE OF RESULTS.

Number of Pages Including Cover Sheet 3-4

To Reply By Facsimile - Dial (510) 842-9591

COUNTY ADMINISTERED CITIES
HAZARDOUS MATERIALS
INCIDENT INVESTIGATION
GUIDANCE DOCUMENT



FACSIMILE COVER SHEET


To: Kenneth Ken Date: 8-24-92

Fax # 842 8252 No. of pages 2


From: Jeff Mohrre Phone (707) 538-8818

Comments: Site Plan of SS #9-1740
w/ sample locations. West
has already typed results to
you:
WX-1 -> WX-2 @ 5' below grade
WX-3 & WX-4 @ 5' " "
WO-1 & WO-2 @ 8'-9' below grade
WX-4 was 3000 ppm TOC next
to Monitoring Well C-1

8-20-92



SIERRA



EXPLANATION	
⊕ C-4	Existing monitoring well
591.47	Ground water elevation
588.43'	Ground water elevation corrected for presence of fire product
- 591.00	Ground water elevation contour, dashed where inferred, queried where uncertain

Base map after Pacific Environmental Group, Inc.

Figure 2. Monitoring Well Locations and Ground Water Elevation Contour Map - June 28, 1992 - Chevron Service Station #9-1740, 8550 Moraga Avenue, Oakland, California