

2680 Bishop Drive · Suite 203 · San Ramon, CA 94583 TEL (925) 244-6600 • FAX (925) 244-6601

August 5, 2003

Mr. Amir Gholami Alameda County Department of Environmental Health Services 1131 Harbor Bay Parkway, Suite 250 Alameda, California 94502-6577

Subject: StID#3337

E.14th

Site Address: 3609 International Blvd., Oakland, California

Dear Mr. Gholami:

Enclosed for your review is a copy of SOMA's "Third Quarter 2003 Groundwater Monitoring and Remediation System Operation Report" for the subject property.

Thank you for your time in reviewing our report. If you have any questions or comments, please call me at (925) 244-6600.

Sincerely,

Mansour Sépehr Ph.D..PE Principal Hydrogeologist

Enclosure

cc: Mr. Abolghassem Razi w/enclosure Tony's Express Auto Service

> Mr. Vince Tong w/enclosure Traction International

Certification

This report has been prepared by SOMA Environmental Engineering, Inc. on behalf of Mr. Abolghassem Razi, the property owner of 3609 International Boulevard, Oakland, California, to comply with the Alameda County Department of Environmental Health Service's requirements for the Third Quarter 2003 groundwater monitoring event.

Alameda County

AUG 0 7 2003

Environmental Health

Mansour Sepehr, Ph.D., P.E.

Principal Hydrogeologist

Table of Contents

CER	TIFICATION	II
ТАВ	LE OF CONTENTS	111
LIST	OF TABLES	IV
LIST	OF FIGURES	IV
LIST	OF APPENDICES	V
1.0	INTRODUCTION	1
1.1	Background	2
1.2	Site Hydrogeology	3
2.0	FIELD ACTIVITIES	4
3.0	LABORATORY ANALYSIS	7
4.0	RESULTS	8
4.1	Field Measurements	8
4.2	Laboratory Analysis	12
5.0	GROUNDWATER TREATMENT SYSTEM OPERATION	. 14
6.0	VAPOR EXTRACTION SYSTEM OPERATION	. 16
7.0	CONCLUSIONS AND RECOMMENDATIONS	. 18
8.0	REPORT LIMITATIONS	. 21
9.0	REFERENCES	. 22

List of Tables

Table 1: Groundwater Elevation Data, July 24, 2003

Table 2: Historical Groundwater Elevation Data

Table 3: Field Measurements of Physical and Chemical Properties of

Groundwater at Time of Sampling, July 24, 2003

Table 4: Groundwater Biodegradation Parameters

Table 5: Groundwater Analytical Data, July 24, 2003

Table 6: Historical Groundwater Analytical Data

Table 7: Total Volume of Water Treated, Historical Operational Data, and

Effluent and GAC-1 Analytical Results

Table 8: Total Mass of Petroleum Hydrocarbons Removed by Vapor

Extraction System

List of Figures

Figure 1: Site vicinity map.

Figure 2: Site map showing the locations of groundwater monitoring wells, French

drain, SVE system, and GAC system.

Figure 3: Groundwater elevation contour map in feet. July 24, 2003.

Figure 4: Contour map of dissolved oxygen concentrations in the groundwater.

July 24, 2003.

Figure 5: Contour map of Ferrous Iron concentrations in the groundwater.

July 24, 2003.

Figure 6: Map of Nitrate concentrations in the groundwater.

July 24, 2003.

Figure 7: Contour map of Sulfate concentrations in the groundwater.

July 24, 2003.

Figure 8: Contour map of TPH-g concentrations in the groundwater.

July 24, 2003.

Figure 9: Contour map of Benzene concentrations in the groundwater.

July 24, 2003.

Figure 10: Contour map of MtBE (EPA Method 8260B) concentrations in the groundwater. July 24, 2003.

Figure 11: Schematic Diagram of the Groundwater Remediation System.

Figure 12: Cumulative mass of TPH-g and MtBE removed from groundwater since the installation of the treatment system.

List of Appendices

Appendix A: Field Measurements of Physical, Chemical, and Biodegradation
Parameters of Groundwater Samples

Appendix B: Chain of Custody Form and Laboratory Report of Third Quarter 2003 Monitoring Event

Appendix C: Laboratory Reports and Chain of Custody Forms for Groundwater

Extraction Treatment System

1.0 Introduction

This report has been prepared by SOMA Environmental Engineering, Inc. (SOMA) on behalf of Mr. Abolghassem Razi, the owner of Tony's Express Auto Service, which is located at 3609 International Boulevard at the intersection of 36th Avenue in Oakland, California (the "Site"), as shown in Figure 1.

The Site is located in an area where the surrounding properties are primarily commercial businesses and residential housing. The Site currently houses a gasoline service station and convenience store. During the Third Quarter 2002, the station was remodeled and several hydraulic hoists were removed. The station no longer has an auto repair facility. Figure 2 shows the location of the main service station, dispenser islands, underground storage tanks (USTs), the on-site and off-site groundwater monitoring wells, and neighboring properties.

This report summarizes the results of the Third Quarter 2003 groundwater monitoring event conducted on July 24, 2003 at the Site. Included in this report are the bioattenuation parameters measured in the field for each groundwater sample. Also, included in this report are the results of the laboratory analysis of the groundwater samples, which were analyzed for:

- Total petroleum hydrocarbons as gasoline (TPH-g)
- Benzene, toluene, ethylbenzene, total xylenes (collectively referred to as BTEX)
- Methyl tertiary Butyl Ether (MtBE)

These activities were performed in accordance with the general guidelines of the Regional Water Quality Control Board (RWQCB) and the Alameda County Environmental Health Services (ACEHS).

This report also describes the operation of the groundwater extraction system

installed by SOMA in December 1999, as well as the operation of the vapor extraction system, which was installed by SOMA in July 2000. The locations of the groundwater extraction system and the vapor extraction system are displayed in Figure 2.

1.1 Background

The environmental investigation at the subject property began in 1992, when Mr. Razi, the property owner, retained Soil Tech Engineering, Inc. (STE) of San Jose to conduct a limited subsurface investigation. The purpose of STE's investigation was to determine whether or not the soil near the product lines and USTs had been impacted with petroleum hydrocarbons.

In July 1993, STE removed one single-walled 10,000-gallon gasoline tank and one single-walled 6,000-gallon gasoline tank along with a 550-gallon waste oil tank from the Site. Three double-walled USTs replaced these tanks. Currently, there is one 10,000-gallon double-walled gasoline tank and two 6,000-gallon double-walled gasoline tanks beneath the Site. The locations of the USTs are shown in Figure 2.

In December 1997, Mr. Razi retained Western Geo-Engineers (WEGE) to conduct additional investigations and perform groundwater monitoring on a quarterly basis. The results of the WEGE groundwater monitoring events indicated elevated levels of petroleum hydrocarbons and MtBE in the groundwater.

In April 1999, Mr. Razi retained SOMA to conduct groundwater monitoring, risk-based corrective action (RBCA), a corrective action plan (CAP), as well as soil and groundwater remediation at the Site. The results of the RBCA study indicated that the Site is a high-risk groundwater site; therefore, the soil and groundwater in on and off-site areas warranted remedial actions. The source of

the petroleum hydrocarbons in the groundwater was believed to have been the former USTs, which were used to store gasoline at the Site. The results of the CAP study indicated that the installation of a French drain combined with a vapor extraction system would be the most cost effective alternative for the Site's remediation.

In late August 1999, SOMA installed a French drain and groundwater treatment system to prevent further migration of the chemically impacted groundwater. This treatment system has been in operation since early December 1999.

In July 2000, following approval from the ACEHS, SOMA installed a vapor extraction system as recommended in our CAP document, dated July 1, 1999.

In January 2002, Environmental Fabric removed old product dispensers and installed new ones in the fuel islands.

On July 25, 2003, an additional on-site extraction pump was installed by SOMA, in the western French drain riser. The extraction pump was installed to create a capture zone in the region around the USTs and to contain off-site migration in the southwestern corner of the Site.

1.2 Site Hydrogeology

Previous investigations have shown that groundwater is encountered at depths of approximately 10 to 11 feet beneath the Site. Figure 2 shows the location of the on-site and off-site groundwater monitoring wells. Prior to the operation of the French drain, groundwater was found to flow from the north to the south with an average gradient of 0.014 feet/feet. When the groundwater extraction system is in operation, the groundwater flows towards the French drain. The capture zone of the drain has extended down-gradient past well MW-10.

Based on the results of a pumping test conducted by SOMA, the hydraulic conductivity of the saturated sediments ranges from 1.5 to 18.3 feet per day. Assuming that the effective porosity of the saturated sediments is 0.35, the groundwater flow velocity ranges from 22 to 267 feet per year.

2.0 Field Activities

On July 24, 2003, SOMA's field crew conducted a groundwater monitoring event in accordance with the procedures and guidelines of the RWQCB, San Francisco Bay Region. During this groundwater monitoring event, a total of eight on-site monitoring wells (MW-1 to MW-8), three off-site monitoring wells (MW-10 and MW-12), and three on-site French drain risers were measured for depth to groundwater.

The depth to groundwater at each monitoring well and riser was measured from the top of the casing to the nearest 0.01 foot using an electric sounder. The top of the casing elevation data and the depth to groundwater at each monitoring well and riser were used to calculate the groundwater elevation. Kier Wright Civil Engineers Surveyors, Inc. surveyed the wells and risers on August 9, 2002. At the time of the survey, monitoring well MW-11 could not be accessed due to obstacles preventing the proper use of surveying equipment, therefore, this well was not surveyed. The top of casing elevations were based on the survey data measured at this time. The elevation data was based on an assumed datum of 14.20 NAVD88. The top of casing elevations data are shown in Table 1.

Prior to the collection of samples, each well was purged using a battery operated 2-inch diameter pump (Model ES-60 DC). During the purging activities, in order to obtain accurate measurements of groundwater parameters and especially to avoid the intrusion of oxygen from ambient air into the groundwater samples, field measurements were conducted in-situ (i.e., down-hole inside each monitoring well). The pH, temperature, electric conductivity (EC), dissolved


oxygen (DO), turbidity, and Oxygen Reduction Potential (ORP) were measured in-situ using a Horiba, Model U-22 multi-parameter instrument. The Horiba, Model U-22 was calibrated at the Site using standard solutions and procedures provided by the manufacturer. Detailed field measurements are shown in Appendix A.

The Horiba U-22 portable microprocessor-based turbidity probe provides labgrade accuracy, even in the field. The unit of measurement adopted by the ISO Standard is the Formazine Turbidity Unit (FTU), which is identical to the Nephelometric Turbidity Unit (NTU). It has been found that there is a strong correlation between the turbidity level and the biological oxygen demand of natural water bodies. Turbidity is an indicator and, as such, does not reveal the presence or quantity of specific pollutants in the groundwater. It does, however, provide general information on the extent of the suspended solids in the groundwater.

The Horiba U-22's ORP electrode was used to measure the ORP of the groundwater samples. Oxidation is a process in which a molecule or ion loses one or several electrons. Reduction is a process by which a molecule or ion gains one or several electrons. The ORP, or Eh, is a measure of the potential for these processes to occur. The unit of Eh, which is commonly referred to as the redox potential, is the Volt or m-Volt. The most important redox reaction in petroleum contaminated groundwater is the oxidation of petroleum hydrocarbons in the presence of bacteria and free molecular oxygen. Because the solubility of O₂ in water is low (9 mg/L at 25 °C and 11 mg/L at 5 °C), and because the rate of O₂ replenishment in subsurface environments is limited, oxidation of only a small amount of petroleum hydrocarbons can result in the consumption of all the DO.

When DO in groundwater is consumed, oxidation of petroleum hydrocarbons can still occur, but the oxidizing agents (i.e., the constituents that undergo reduction) are then Fe (OH)₃, NO₃, SO₄²⁻, MnO₂, and others (Freeze and Cherry, 1979). As

these oxidizing agents are consumed, the groundwater environment becomes more and more reduced. If the process proceeds far enough, the environment may become so strongly reduced that the petroleum hydrocarbons may undergo anaerobic degradation, resulting in the production of methane and carbon dioxide. The concept of oxidation and reduction in terms of changes in oxidation states is illustrated below:



The purging continued until the parameters for pH, temperature, EC, DO, turbidity, and redox stabilized, or three casing volumes were purged. The groundwater samples were also tested on-site for ferrous iron (Fe⁺²), and nitrate (NO₃), and sulfate (SO₄⁻²) concentrations once stabilization occurred.

Ferrous iron, nitrate, and sulfate were measured colorimetrically using the Hach Colorimeter Model 890. The Hach Model 890 Colorimeter is a microprocessor-controlled photometer suitable for colorimetric testing in the laboratory or the field. The required reagents for each specific test are provided in AccuVac ampuls.

Ferrous iron was measured colorimetrically using Method 8146 (1,10-phenanthroline Method). The 1,10-phenathroline indicator in Ferrous Iron Reagent reacts with Fe⁺² in the sample to form an orange color. The intensity of the orange color is proportional to the iron concentration.

Nitrate was measured colorimetrically using Method 8039: the Cadmium Reduction Method. Cadmium metal in the Nitra Ver 5 Nitrate Reagent reduces nitrates present in the sample to nitrite; the nitrite ion reacts in an acidic medium with sulfanilic acid to form an intermediate diazonium salt, which couples with getistic acid to form an amber-colored product. The intensity of the color is proportional to nitrate-N concentration in the sample.

Sulfate was measured colorimetrically using Method 8051 of Sulfa Ver 4 Method. Sulfate ions in the sample react with barium in the Sulfa Ver 4 Sulfate Reagent to form insoluble barium sulfate. The amount of turbidity formed is proportional to the sulfate concentration. The Sulfa Ver 4 also contains a stabilizing agent to hold the barium sulfate in suspension.

For sampling purposes, after purging, a disposable polyethylene bailer was used to collect sufficient samples from each monitoring well for laboratory analyses. The groundwater sample was transferred into three 40-mL VOA vials and preserved with hydrochloric acid. The vials were then sealed to prevent development of air bubbles within the headspace. After the groundwater samples were collected, they were placed on ice and maintained at 4°C in a cooler. A chain of custody (COC) form was written and placed along with the samples in the cooler. SOMA's field crew delivered the groundwater samples to Curtis & Tompkins, Ltd. Laboratory in Berkeley, California on July 24, 2003.

3.0 Laboratory Analysis

Curtis & Tompkins, Ltd., a state certified laboratory, analyzed the groundwater samples for TPH-g, BTEX and MtBE. TPH-g was prepared using EPA Method 5030B and measured using EPA Method 8015B. EPA Method 8021B was used to measure BTEX and MtBE concentrations. Detections of MtBE were confirmed using EPA Method 8260B.

4.0 Results

The following sections provide the results of field measurements and laboratory analyses for the July 24, 2003 groundwater monitoring event.

4.1 Field Measurements

Table 1 presents the calculated groundwater elevations at each groundwater monitoring well and riser. The calculated groundwater elevation data was used to evaluate the impact of the French drain and determine the extent of the groundwater extraction capture zone. The groundwater elevation data presented in Table 1 is based on the survey data measured by Kier Wright Civil Engineers Surveyors, Inc. on August 9, 2002. Due to obstacles around monitoring well MW-11, the surveying equipment could not be set-up; therefore, no survey was conducted for this well. The new survey was conducted to comply with an Electronically Deliverable Format (EDF) request made by the State Water Resources Control Board (SWRCB) Database.

As shown in Table 1, depths to groundwater in the monitoring wells ranged from 10.76 feet in monitoring well MW-10 to 12.98 feet in monitoring well MW-6. The corresponding groundwater elevations ranged from 25.40 feet in monitoring well MW-12 to 28.71 feet in monitoring well MW-5. Depths to groundwater in the center, east and west risers were 16.45 feet, 13.10 feet and 12.12 feet, respectively. In the French drain risers the corresponding elevations for the center, east and west risers were 22.90 feet, 26.96 feet and 27.04 feet, respectively.

Table 2 shows the historical groundwater elevations at different groundwater monitoring wells and the French drain risers, as well as, annual and quarterly deviations in groundwater elevations. In general, groundwater elevations in all of the monitoring wells decreased since the previous quarter. The range in

deviation of the quarterly groundwater elevation decrease was between 2.20 feet to 4.03 feet. Variations in groundwater elevations are typically due to seasonal fluctuations. The decrease in elevations noted during this event is most likely caused by the onset of a drier season.

Figure 3 displays the groundwater elevation contour map, depicted in feet, as measured on July 24, 2003. Groundwater flows towards the French drain, throughout the Site, at an approximate gradient of 0.050 feet/feet. The lowest groundwater elevation was measured in the center French drain riser. The calculated groundwater elevation data was also used to evaluate the impact of the French drain operation. Based on the groundwater elevation contour map shown in Figure 3, it appears that the French drain is providing excellent hydraulic control to prevent the off-site migration of contaminants.

Table 3 summarizes the field measurements of physical and chemical properties of groundwater samples collected from the groundwater monitoring wells at the time of sampling. The pH measurements ranged from 7.08 in monitoring well MW-6 to 7.57 in monitoring well MW-7. In general, groundwater pH stayed fairly consistent throughout the Site. Temperature measurements of groundwater ranged from 18.80 °C in monitoring well MW-11 to 21.60 °C in monitoring well MW-7. EC ranged from 443 μ S/cm in monitoring well MW-7 to 924 μ S/cm in monitoring well MW-3.

The groundwater biodegradation parameters for this monitoring event, as well as the previous monitoring events, are shown in Table 4.

As shown in Table 4, DO concentrations were below the minimum allowable equipment (Horiba U-22) tolerance range in monitoring wells MW-2 to MW-5, MW-8 to MW-12. The concentration contour map for DO during the Third Quarter 2003 is displayed in Figure 4. As displayed in Figure 4, the highest DO concentration was detected in monitoring well MW-7 at a level of 2.83 mg/L. In

general, DO was consumed in the majority of the wells with the exception of very low concentrations in MW-1, south of the USTs, in MW-6, near the SVE system, and in MW-7, west of the USTs.

DO concentrations detected during this monitoring event were well below the solubility standard of O₂ in water at 18°C to 22°C, which is approximately 8.7 mg/L to 9.4 mg/L. The Site groundwater temperature at the time of sampling was approximately 18.80°C to 21.60°C. Therefore, oxidation of petroleum hydrocarbons could still have occurred in these monitoring wells at these DO readings.

As shown in Table 4, turbidity of groundwater samples ranged from 19 NTU in monitoring well MW-12 to 610 NTU in monitoring well MW-8. The oxidation-reduction potential in groundwater samples ranged from -129 mV in monitoring well MW-8 to +128 mV in monitoring well MW-4. All monitoring wells showed strongly reduced conditions, with the exception of MW-2, MW-4, and MW-10. Oxygen-depleted environments with strongly reduced conditions depict anaerobic processes utilizing alternate electron acceptors, such as nitrate, iron (III) and sulfate, for oxidation of petroleum hydrocarbons (Lovley *et. al.*, 1994). Under strongly reduced conditions and a lack of other terminal electron acceptors, the occurrence of methanogenesis may be possible.

Ferrous iron concentrations were below the allowable equipment (Hach Colorimeter Model 890) tolerance range in the groundwater samples collected from MW-2, MW-4, MW-10, and MW-11. The maximum ferrous iron concentrations were detected in MW-1, MW-3, and MW-6. The presence of ferrous iron in groundwater indicates the occurrence of biological activities beneath the Site.

Figure 5 shows a contour map of ferrous iron concentrations in the groundwater

as measured during the Third Quarter 2003. As shown in Figure 5, the highest ferrous iron concentrations were detected in the vicinity of the USTs in monitoring wells MW-1 and MW-3, and the eastern section of the Site in MW-6. Ferrous iron concentrations were not detected in wells MW-2, MW-4, MW-10 and MW-11, and at a low concentration of .61 mg/L in MW-7.

During this monitoring event, nitrate was below the allowable equipment (Hach Colorimeter Model 890) tolerance range in all monitoring wells. Non-existent levels of nitrate suggest that microorganisms have consumed nitrate and that biodegradation is occurring in the subsurface. A map of the nitrate concentrations in the groundwater is displayed in Figure 6. The non-detectable values displayed in Figure 6 further illustrate that nitrate concentrations have been consumed throughout the Site.

Sulfate concentrations were below the allowable equipment (Hach Colorimeter Model 890) tolerance range in the groundwater samples collected from MW-1, MW-3, MW-6, MW-8, and MW-12. The highest sulfate concentration was detected in monitoring well MW-5 at 30 mg/L. Sulfate-depleted subsurface contaminated environments may reveal a strong demand by microorganisms for a source of terminal electron acceptors for oxidizing contaminant hydrocarbons (Lovley *et. al.*, 1994).

The contour map of sulfate concentrations in the groundwater as measured during the Third Quarter 2003 monitoring event is presented in Figure 7. As shown in Figure 7, sulfate concentrations were below the measurable specifications of the equipment in monitoring wells MW-1, MW-3, and MW-8, which are in the vicinity of the USTs and French drain. Sulfate concentrations were also not observed in MW-6, or off-site monitoring well MW-12. The highest sulfate concentration was observed in the northwest corner of the Site in MW-5.

The field notes for the physical, chemical and biodegradation parameters are shown in Appendix A.

4.2 Laboratory Analysis

Table 5 presents the results of the laboratory analyses on the groundwater samples collected during the Third Quarter 2003 monitoring event. The most impacted monitoring wells, based on the analytical results, for this quarter were MW-1 and MW-3, which are in the vicinity of the USTs.

As shown in Table 5, TPH-g was detected in all of the groundwater samples, with the exception of MW-4. Detectable TPH-g levels ranged from 220 μ g/L in monitoring well MW-2 to 36,000 μ g/L in monitoring well MW-1. High TPH-g concentrations were also detected in MW-3 and MW-6 at 31,000 μ g/L and 29,000 μ g/L, respectively.

Figure 8 shows a contour map of TPH-g concentrations at the Site as analyzed during the Third Quarter 2003. As shown in Figure 8, the highest TPH-g concentrations were detected in the vicinity of the USTs in wells MW-1 and MW-3. Based on the analytical results TPH-g has migrated to all off-site wells.

As shown in Table 5, all BTEX analytes, with the exception of benzene, were below the laboratory reporting limit in monitoring well MW-4. Both benzene and total xylenes were below the laboratory reporting limit in MW-5. Toluene and ethylbenzene were at low levels in MW-5. Benzene and ethylbenzene were below the laboratory reporting limit in MW-7. Toluene and total xylenes were at low levels in MW-7. Low levels of BTEX analytes were detected in all off-site wells, with the exception of ethylbenzene in MW-12, which was below the laboratory reporting limit.

As shown in Table 5, the maximum BTEX concentrations, with the exception of ethylbenzene in MW-6 at 1,500 μ g/L, were detected in MW-1. Benzene, toluene, and total xylenes were detected in MW-1 at 4,800 μ g/L, 1,800 μ g/L, and 5,600 μ g/L, respectively. Benzene was also detected at a high concentration in MW-3 of 4,700 μ g/L. Toluene and ethylbenzene were detected in MW-3 at high concentrations of 990 μ g/L and 1,400 μ g/L, respectively. Total xylenes were detected in high concentrations in MW-3 and MW-6 of 5,200 μ g/L and 4,400 μ g/L, respectively.

Figure 9 displays the contour map of benzene concentrations in the groundwater collected during the Third Quarter 2003. As shown in Figure 9, the highest benzene concentrations were found in MW-1 and MW-3, in the vicinity of the USTs. Benzene has migrated to all off-site monitoring wells. The highest off-site concentration of benzene was detected in monitoring well MW-10 at 160 μ g/L.

EPA Method 8260B is a more accurate analytical method than EPA Method 8021B. Therefore, to properly determine the MtBE plume and on-site concentrations, the MtBE iso-concentration figure is contoured using EPA Method 8260B. However, as shown in Table 5, MtBE is presented using both EPA methods 8021B and 8260B.

MtBE, using EPA Method 8260B, was below the laboratory reporting limit in monitoring wells MW-2, MW-4, MW-5, MW-6, and MW-11. The highest MtBE concentration was detected in monitoring well MW-1 at 25,000 μ g/L. A high MtBE concentration was also detected in MW-3 at 16,000 μ g/L.

Figure 10 displays the contour map of MtBE concentrations in the groundwater during the Third Quarter 2003, as analyzed using EPA Method 8260B. The elevated level of MtBE found in MW-1 may be attributed to the proximity and down-gradient location of MW-1 to the USTs. In general, with the exception of

wells MW-1, MW-3, and MW-8, MtBE was either at low concentrations or below the laboratory reporting limit in the remaining site wells.

The laboratory report and COC form for the Third Quarter 2003 monitoring event are included in Appendix B.

Table 6 shows the historical groundwater analytical data. The following concentration trends were observed since the previous monitoring event.

- TPH-g increased slightly in MW-5 and MW-11. TPH-g decreased in the remaining wells, with the exception of MW-12, which remained constant.
 TPH-g decreased significantly in MW-1, MW-3, MW-6.
- The only BTEX analyte to increase in MW-1 and MW-6 was benzene. All BTEX analytes decreased in MW-2, MW-3, MW-4, MW-10. Only toluene increased in MW-5. Total xylenes decreased significantly in MW-6. Both toluene and total xylenes increased slightly in MW-7. Both benzene and total encreased slightly in MW-8 and MW-11. Both ethylbenzene and total xylenes decreased in MW-8 and MW-11. Both benzene and ethylbenzene decreased slightly in MW-12. Both toluene and total xylenes increased in MW-12.
- MtBE, using EPA Method 8260B, increased in MW-1, MW-3, MW-8. MtBE decreased in MW-5, MW-7, MW-10, and MW-12. MtBE has remained below the laboratory reporting limit in MW-2, MW-4, MW-6, and MW-11.

5.0 Groundwater Treatment System Operation

The treatment system began operation on December 9, 1999. Since that time, 1,995,240 gallons of groundwater has been treated and discharged into the East Bay Municipal Utility District (EBMUD) sewer system under the existing discharge permit (as of July 21, 2003).

As required by the discharge permit and the ACEHS, sampling of the groundwater treatment system has been performed on a routine basis. The effluent sampling and maintenance of the system were performed on a weekly basis from the start of the system's operation to the end of July 2000. In August 2000, maintenance of the system continued weekly, but sampling was performed on a monthly basis. The results from the first effluent testing were used to acquire a discharge permit from EBMUD.

A total of 112,800 gallons of chemically impacted groundwater has been treated since the Second Quarter 2003 monitoring event, (as of July 21, 2003, which was the last sampling date at the time of this Third Quarter 2003 monitoring event). The effluent passing both Granulated Active Carbon (GAC) units is regularly sampled for chemical analysis. The schedule for refurbishing the GAC units is based on the analytical results of the samples. The first GAC unit was refurbished as soon as traces of chemicals broke through the unit. The second GAC unit is serving as a polishing unit and is always kept highly active. This procedure ensures that the effluent discharging into the EBMUD sewer are in compliance with our permit discharge requirements. A schematic diagram of the groundwater remediation system is displayed in Figure 11.

Table 7 presents the total volume and chemical composition of GAC-1 and effluent treated at the Site. Table 7 shows that all the effluent samples have maintained in compliance with the permit, with the exception of the October 2002 sampling event. The analytical data for the October 2002 sampling period was erroneous. The high non-detectable concentration levels are due to a high dilution factor caused by the presence of 2-Butanone. During the laboratory testing 2-Butanone was detected at a high concentration of 200,000 μ g/L in only the effluent sample. The influent sample concentration for 2-Butanone was only 20 μ g/L. Based on the fact that 2-Butanone has never been detected since December 1999 in any of the effluent samples and had a very low influent

concentration, the sample results shown are erroneous and are only used to depict that sampling was conducted in October 2002. The high TPH-g concentration for this sample may not be representative due to the sample exhibiting unknown peaks, and the sample also exhibiting a fuel pattern, which did not resemble the standard. The laboratory designated these items by "Y" and "Z" flags. However, the system was turned off upon detection of these concentrations and a carbon change-out was performed. During this carbon change-out both the carbon in the 2,000-pound carbon vessel and the carbon in the 55-gallon vessel (GAC-2) were removed and replaced. In future carbon change-out cycles, both GAC-1 and GAC-2 will be replaced with fresh carbon. The laboratory reports for the treatment system are included as Appendix C of this report.

The cumulative weight of TPH-g and MtBE extracted from the groundwater since the installation of the treatment system is displayed in Figure 12. As Figure 12 shows, an approximate total of 133.5 pounds of TPH-g and 74.5 pounds of MtBE have been removed during the operation of the treatment system, from start-up to July 21, 2003.

6.0 Vapor Extraction System Operation

The Vapor Extraction System (VES) consists of 6 vapor extraction wells, a demoisturizing unit, a blower and four drums of GAC filters. The VES began operation on July 24, 2000. Since then, during its working days, the system has extracted and treated more than 3,000,000 liters per day of soil gas. When the system first began to operate, the influent had a concentration of 394 parts per million on volumetric basis (ppmv) of petroleum hydrocarbons. However, it gradually decreased to 68 ppmv after 31 days of operation. On January 4, 2001, due to extremely low influent concentrations (i.e., less than 10 ppm of hydrocarbons), the soil vapor extraction (SVE) system was turned off.

The following services were performed on the SVE system during 2001. On October 23, 2001, the system was inspected for operation and it was determined that all four GACs were not in good enough condition to re-start the system. On October 25, 2001, one of the four GACs was replaced with a new one, and on October 29, 2001 the three remaining GAC units were replaced. The system was then under continuous operation and extracted over 80 cubic feet per minute (CFM) of contaminated air from the vadose zone. On November 21, 2001 due to the low concentration of contaminants in the influent (i.e., less than 10 ppmv of hydrocarbons) the system was turned off.

The following services were performed on the SVE system during 2002. In February 2002, the system was inspected for operation and it was determined that the blower was not functioning. The blower was repaired and installed on February 15, 2002. On the same day, the four old GACs were replaced with four new ones and the system was turned on. The system was shut down on March 7, 2002, due to low influent readings caused by the saturated soil conditions on-site. The system was turned back on June 12, 2002 and has been operational, with the exception of the time period from August 15 to August 23, 2002 due to low influent readings.

On November 6, 2002, SOMA met a representative of the Bay Area Air Quality Management District (BAAQMD) on-site. During this time the 2002 yearly maintenance record was shown to BAAQMD representative. The SVE system was determined to be in compliance with the BAAQMD operating permit. At the request of BAAQMD, an air sample was collected from the influent and effluent of the system on November 7, 2002 and sent to Curtis & Tompkins, Ltd. Laboratory in Berkeley, California for analysis. The sample results are in the Fourth Quarter 2002 monitoring report. The system was turned off November 22, 2002, due to the onset a wetter season. The system became operational again on May 9, 2003.

The total mass of petroleum hydrocarbons removed by the SVE system is shown in Table 8. As of July 28, 2003, the SVE system had removed 410.22 pounds of petroleum hydrocarbons from the vadose zone beneath the Site. The operation of the SVE will help reduce the increasing hydrocarbon concentrations found in the vicinity of MW-6.

7.0 Conclusions and Recommendations

The findings of the Third Quarter 2003 groundwater monitoring event can be summarized as follows:

- 1. The groundwater remediation system is providing excellent hydraulic control to prevent further migration of contaminants. The lowest groundwater elevation was measured in the center French drain riser at 22.90 feet. The groundwater gradient is approximately 0.050 feet/feet towards the center riser.
- 2. Biodegradation parameters were collected during the Third Quarter 2003 monitoring event. In general, DO was consumed in the majority of the wells, with the exception of very low concentrations observed in MW-1, south of the USTs, and in MW-6, near the SVE system. The highest DO concentrations were observed in MW-7, west of the USTs at 2.83 mg/L.
- 3. The presence of ferrous iron in the groundwater is indicative of biological activities beneath the Site. The highest ferrous iron concentrations were detected in the vicinity of the USTs in monitoring wells MW-1 and MW-3, and the eastern section of the Site in MW-6. Ferrous iron concentrations were not detected in wells MW-10 and MW-11, and at a low concentration of 1.13 mg/L in MW-12.

- 4. The presence of high ferrous iron concentrations in combination with low concentrations of other electron receptors, such as DO and nitrate is indicative of anaerobic biodegradation beneath the Site.
- 5. During this monitoring event, nitrate was below the allowable equipment (Hach Model 890 Colorimeter) tolerance level in all monitoring wells.
- 6. Sulfate depletion occurred in MW-1 and MW-3, which are located in the vicinity of the USTs. Sulfate was also not detected in MW-6, which is located near the SVE system, and MW-8, which is located near the French drain. Sulfate was below the allowable equipment tolerance level in off-site well MW-12. The presence of ferrous iron in combination with low sulfate levels in the subsurface strongly suggests that biodegradation is occurring beneath the Site.
- 7. The highest TPH-g, benzene, and MtBE concentrations were detected in the vicinity of the USTs in MW-1 at 36,000 μg/L, 4,800 μg/L, and 25,000 μg/L, respectively. High TPH-g concentrations were also detected in MW-3 and MW-6 at 31,000 μg/L, and 29,000 μg/L, respectively. Benzene was detected at a high concentration of 4,700 μg/L in MW-3. MtBE was detected at a high concentration of 16,000 μg/L in MW-3.
- 8. Since the previous monitoring event, TPH-g significantly decreased in monitoring wells MW-1, MW-3, and MW-6. Benzene was the only BTEX analyte to increase in MW-1 and MW-6. All BTEX analytes decreased in MW-3. MtBE increased in wells MW-1 and MW-3. However, the MtBE concentration detected in MW-1 and MW-3, during this monitoring event, is well below the historical high MtBE concentration.

- The treatment system began operation on December 9, 1999. Since that time approximately 1,995,240 gallons of groundwater has been treated and discharged into the East Bay Municipal Utility District (EBMUD) sewer system under the existing discharge permit (as of July 21, 2003).
- 10. All effluent samples of the groundwater treatment system have maintained in compliance with the permit, with all contaminant concentrations remaining below the allowable discharge requirements, with the exception of the October 2002, sampling event. However, the laboratory results for TPH-g were misrepresentative due to the "Y" and "Z" flags, see the lab report for these designations.
- 11. From December 9, 1999 to July 21, 2003, approximately 133.5 pounds of TPH-g and 74.5 pounds of MtBE have been removed during the operation of the treatment system.
- 12. To more effectively remediate the area in the vicinity of MW-1, on July 25, 2003 SOMA installed an additional on-site extraction pump in the western French drain riser on July 25, 2003. Further monitoring events should determine the effectiveness of this additional on-site extraction pump.
- 13. As of July 28, the SVE system has removed 410.22 pounds of petroleum hydrocarbons from the vadose zone beneath the Site. The operation of the SVE system is based on seasonal fluctuations occurring at the Site. The system is turned off during wetter periods of the year and operational during drier periods. The system was temporary off-line from November 22, 2002 to May 9, 2003.

8.0 Report Limitations

This report is the summary of work done by SOMA including observations and descriptions of the Site's conditions. It includes the analytical results produced by Curtis & Tompkins Laboratories as well as the summaries of data produced by previous environmental consultants. The number and location of the wells were selected to provide the required information, but may not be completely representative of the entire site's conditions. All conclusions and recommendations are based on the results of the laboratory analysis. Conclusions beyond those specifically stated in this document should not be inferred from this report.

SOMA warrants that the services provided were done in accordance with the generally accepted practices in the environmental engineering and consulting field at the time of this sampling.

9.0 References

Freeze R.A. and Cherry J.A. 1979. Groundwater. Prentice-Hall, Inc., Englewood Cliffs, N.J. PP.114-127.

Lovley, D.R.; Chapell, F.H.; Woodward, J.C. 1994. Use of Dissolved H₂ Concentration to Determine Distribution of Microbially Catalyzed Redox Reactions in Anoxic Groundwater. Environmental Science & Technology. Vol, 28, No. 7:1205-1210.

Soil Tech Engineering, Quarterly Groundwater Monitoring Reports, from 1995 to July 1997.

SOMA Environmental Engineering, Inc., June 9, 2000. "Semi-Annual Technical Report: Treatment System Discharge to EBMUD Sewer from November 15, 1999 to May 14, 2000".

SOMA Environmental Engineering, Inc., December 4, 2000. "Semi-Annual Technical Report: Treatment System Discharge to EBMUD Sewer from May 15, 2000 to November 14, 2000".

SOMA Environmental Engineering, Inc., March 7, 2001. "Semi-Annual Technical Report: Treatment System Discharge to EBMUD Sewer from November 15, 2000 to February 14, 2001".

SOMA Environmental Engineering, Inc., June 30, 1999. "Second Quarter 1999 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., September 14, 1999. "Third Quarter 1999 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., November 30, 1999. "Fourth Quarter 1999 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., March 10, 2000. "First Quarter 2000 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., July 26, 2000. "Second Quarter 2000 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., August 24, 2000. "Installation of Soil

Vapor Extraction and Air Sparging System and Initial Results Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., August 29, 2000. "Third Quarter 2000 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., December 4, 2000. "Fourth Quarter 2000 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., April 23, 2001. "First Quarter 2001 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., July 17, 2001. "Second Quarter 2001 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., September 20, 2001. "Third Quarter 2001 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., January 8, 2002. "Fourth Quarter 2001 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

Taras, M.J.; Greenberg, A.E.; Hoak, R.D.; and Rand, A.E. 1975. Standard Methods for the Examination of Water and Wastewater. American Public Health Association, Washington, D.C.

Western Geo-Engineers, Quarterly Groundwater Monitoring and Sampling Reports from Fourth Quarter 1997 to First Quarter 1999.

SOMA Environmental Engineering, Inc., April 8, 2002. "First Quarter 2002 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., June 18, 2002. "Second Quarter 2002 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., September 11, 2002. "Third Quarter 2002 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., January 13, 2003. "Fourth Quarter 2002 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., February 12, 2003. "First Quarter 2003 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

SOMA Environmental Engineering, Inc., May 20, 2003. "Second Quarter 2003 Groundwater Monitoring Report Tony's Express Auto Service Oakland, California".

TABLES

Table 1
Groundwater Elevation Data
July 24, 2003
3609 International Boulevard, Oakland, California

Monitoring Well	Top of Casing Elevation ¹ (feet)	Depth of Well (feet)	Depth to Groundwater (feet)	Groundwater Elevation (feet)
MW-1	40.11	30.00	12.44	27.67
MW-2	40.71	31.00	12.23	28.48
MW-3	40.91	31.50	12.94	27.97
MW-4	40.01	26.00	12.44	27.57
MW-5	41.16	26.50	12.45	28.71
MW-6	40.92	25.00	12.98	27.94
MW-7	39.94	26.00	11.72	28.22
MW-8	39.38	27.00	11.92	27.46
MW-10	36.71	23.40	10.76	25.95
MW-11	NS	25.40	12.30	NC NC
MW-12	36.84	30.00	11.44	25.40
		Erench Brain Als	ejes	
F.D. Center	39.35		16.45	22.90
F.D. East	40.06		13.10	. 26.96
F.D. West	39.16		12.12	27.04

Notes:

NC: Not calculated because top of casing elevation data was not available.

NS: Not surveyed. MW-11 was not surveyed due to obstacles in vicinity of the well.

F.D. Center: French drain center riser.F.D. East: French drain east riser.F.D. West: French drain west riser.

1 Top of casing elevations were re-surveyed to comply with the EDF requirements for electronic reporting of data to the State Water Resources Control Board Database on

Table 2
Historical Groundwater Elevation Data
3609 International Boulevard, Oakland, California

	Mor					nitoring V	nitoring Wells					French Drain		
Date	MW-1	MW-2	MW-3	MW-4	MW-5	MW-6	MW-7	8-WM	MW-10	MW-11	MW-12	FDC	FDE	FDW
Jul-03	27.67	28.48	27.97	27.57	28.71	27.94	28.22	27.46	25.95	NC	25.40	22.90	26.96	27.04
May-03	30.40	31.54	30.90	30.23	31.92	31.00	32.25	29.90	28.41	NC	27.60	23.15	28.27	28.32
Jan-03	30.38	32.05	31.12	30.22	32.43	31.14	31.49	29.90	28.48	NC	27.61	24.17	26.93	27.03
Oct-02	24.61	26.48	25.93	25.67	26.65	25.99	26.20	25.58	24.17	NM	23.71	25.61	25.53	25.66
Jul-02 ¹	27.31	28.01	27.66	27.39	28.22	27.64	27.79	27.59	25.78	NM	25.91	27.42	27.25	27.37
May-02	87.13	87.99	86.50	87.04	88.35	87.44	87.70	86.93	85.05	84.95	84.58	86.74	86.72	86.76
Feb-02	87.88	89.59	87.77	87.88	90.00	88.85	88.92	87.37	86.26	86.25	86.06	80.36	84.72	84.12
Nov-01	83.98	85.15	83.46	84.17	85.32	NM	85.00	84.06	82.48	82.46	82.08	79.28	83.98	82.59
Aug-01	84.48	85.05	83.68	84.05	85.25	NM	84.81	84.28	82.90	82.90	82.60	83.80	84.21	83.82
May-01	86.49	87.58	85.97	86.35	87.92	. 86.95	87.23	86.10	84,74	84.79	84.32	81.25	84.85	83.40
Маг-01	89.03	90.03	88.35	88.61	90.37	89.28	89.79	88.50	86.47	86.33	85.80	87.71	88.76	86.78
Nov-00	84.79	85.98	84.38	84.80	85.49	85.37	85.88	84.70	83.19	83.39	82.79	80.25	85.15	81.40
Aug-00	84.63	85.55	84.05	84.5	85.82	84.99	85.2	84.38	83.02	81.07	82.77	81.40	NM	NM
May-00	86.50	87.70	86.10	86.39	88.01	87.07	87.31	86.10	85.09	82.14	84.36	84.69	84.68	84.70
Feb-00	86.79	88.73	86.83	86.60	89.19	87.82	88.33	86.40	85.29	82.34	84.64	81.70	NM	NM
Nov-99	83.54	84.48	83.08	83.75	84.74	84.02	84.58	83.60	82.04	82.09	81.64	NA	ΝA	NA
Aug.99	84.64	85.08	83.93	84.65	85.49	84.87	85.03	84.50	82.94	83.19	NA	NA	NA	NA
Jun.99	86.89	87.34	85.98	86.55	87.54	86.87	87.13	86.45	84,59	84.44	NA	NA	NA	NA
Mar.99	88.08	90.98	89.34	89.39	91.31	90.37	90.83	89.67	87.24	87.13	NA	NA	NA	NA
Dec.98	86.89	87.64	86.23	86.72	87.84	87.17	87.31	86.50	84.35	84.36	NA	NA	, NA	NA
Sep.98	84.41	85.00	83.10	84.21	85.22	84.67	84.74	84.23	82.61	82.70	NA .	NA	NA	NA
Dec.97	88.69	89.54	NM	88.42	89.89	89.47	89.18	88.30	85.76	85.54	NA	NA	NA	NA
Apr.97	86.85	87.18	86.05	86.62	87.69	87.01	84.88	84.30	84.47	84.47	NA	NA	NA	NA
Dec.96	86.32	86.91	85.76	86.27	87.56	86.73	86.86	86.12	84.10	83.95	NA	NA	NA	NA
Apr.96	89.70	90.45	89.02	89.50	90.80	90.01	90.08	89.27	NA	NA	NA	NA	NA	NA
Jan.96	87.92	88.65	87.23	87.74	89.01	88.22	88.26	87.46	NA	NA	NA	NA	NA	NA
Oct.95	84.70	85.16	84.87	NA	85.47	84.83	84.88	84.39	NA	NA	NA	NA	NA	NA
Jun.95	88.46	88.99	87.53	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA I
Маг.95.	89.92	90.90	89.09	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Dec.94	88.67	89.98	87.99	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Oct.94	82.60	83.22	81.99	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA NA
Change in C	M clayatio													
Change in G Annual	-2.71	-3.57	-3.15	-2.65	-3.72	-3.20	-3.27	-2.44	-2.53		-2.21	-1.27	0.03	0.01
Quarter	-2.73	-3.06	-2.93	-2.66	-3.21	-3.06	-4.03	-2.44	-2.46		-2.21	-0.25	-1.31	-1.28
		2.23												

Notes

FDC: French drain center riser. FDE: French drain east riser. FDW: French drain west riser.

¹Top of casing elevations were re-surveyed to comply with the EDF requirements for electronic reporting of data to the State Water Resources Control Board NA: Not Applicable, Well/Drain did not exist at time of sampling

NC: Not calculated. No top of casing elevation was available for MW-11.

NM: Not Measured

Table 3
Field Measurements of Physical and Chemical Properties
of Groundwater at Time of Sampling
July 24, 2003

3609 International Blvd., Oakland, CA

Monitoring Well	рH	Temp (°C)	EC (uS/cm)
MW-1	7.16	20.30	791
MW-2	7.24	20.20	615
MW-3	7.09	20.20	924
MW-4	7.24	19.20	569
. MW-5	7.26	20.70	700
MW-6	7.08	19.70	703
MW-7	7.57	21.60	443
MW-8	7.20	19.80	675
MW-10	7.35	19.80	658
MW-11	7.42	18.80	621
MW-12	7.29	19.70	659

Table 4
Groundwater Biodegradation Parameters
3609 International Boulevard, Oakland, California

		Dissolved Oxygen	Turbidity	Redox Potential	Ferrous Iron	Nitrate	Sulfate
Well	Date	(mg/L)	(NTU)	(mV)	(mg/L)	(mg/L)	(mg/L)
MW-1	July 24, 2003	0.43	217.0	-107	3.30	0.0	0
	May 1, 2003	0.42	257.0	-78	2.26	0.0	1 0
	January 16, 2003	7.64	87.5	-76	3,30	3.2	0
1	October 30, 2002	0.00	87.2	-97	3.30	0.9	0
l	July 30, 2002	2.37	24.8	-102	2.13	0.0	0
i	May 7, 2002	0.00	287	-81	3.09	0.0	ŏ
	February 21, 2002	0.00	153	-16	3.06	0.0	ŏ
	November 19, 2001	0.36	17.2	-54	1.89	. 0.6	41
Į.	August 8, 2001	1.71	200	-54 -35	2.18	0.0	23
1	May 22, 2001	1.36	40.9	32.5	0.34	0.0	23
]	March 13, 2001	0.53	40.9	-4.7	0.50	4.4	80
i	November 2, 2000	0.56	18	-39.4	1.14	0.0	33
	August 9, 2000	0.32	219	-40	1.70	0.0	0
	May 31, 2000	0.30	30	-37	0.57	2.8	ŏ
	February 7, 2000	0.77	NM	-74	3.30	0.0	1 1
	November 9, 1999	0.20	NM	NM	5.10	0.0	26
	August 23, 1999	1.40	NM	NM	2.67	0.0	8
	Јиле 10, 1999	0.14	NM .	NM	3.17	0	1 .
	December 30, 1997	0.50	NM	NM	3.04	<0.1	<1
			ACCES SERVICES	erigi Destala aus	San San Balance	THE RESERVE	Market of the
MW-2	July 24, 2003	0.00	56.2	122	0.00	0.0	23.0
	May 1, 2003	0.67	83.3	117	0.15	2.1	32.0
	January 16, 2003	3.39	76.1	174	0.56	0.0	39.0
	October 30, 2002	0.87	15.9	85	0.80	10.6	31.0
	July 30, 2002	0.37	111.0	57	0.43	0.0	50.0
	May 7, 2002	0.00	65.1	-46	0.64	0.6	35.0
i	February 21, 2002	1.46	41	131	0.36	0.8	45.0
<u> </u>	November 19, 2001	0.78	105	13	1.18	0.0	33.0
	August 8, 2001	2.03	0	160	0.09	7.4	51.0
1	May 22, 2001	0.80	160	274	0.71	0.0	25.0
	March 13, 2001	0.89	24.15	117.9	0.10	- 6.8	80.0
	November 2, 2000	1.35	ND 1 DOD	111	0.69	0.0	7.9
	August 9, 2000 May 31, 2000	0.76 0.80	1,000 30.9	-74 55	0.72 0.18	5.4	0.0
	February 7, 2000	0.80 1.12	30.9 NM	-55 -20	0.18	2.5 6.2	54.0 55.0
	November 9, 1999	0.80	NM	-20 NM	1,00	0.9	55.0
	August 23, 1999	0.50	NM	NM	0,62	1.0	60.0
[June 10, 1999	0.70	NM:	NM NM	0.55	0.7	40.0
	June 30, 1998	3.20	NM	NM	0.50	<0.1	14.0
	December 30, 1997	<0.1	NM	NM	3.35	<0.1	<1

Table 4
Groundwater Biodegradation Parameters
3609 International Boulevard, Oakland, California

Well Date Date Chrygen Turbidity Potential (mg/L)		,	Dissolved		Redox	Ferrous Iron	Nitrate	Sulfate
MW-3 July 24, 2003	Well	Date		_		(ma/L)	(ma/L)	(ma/L)
MW-3	24.4							
May 1, 2003	MW-3							
October 30, 2002			0.38	40.0	-108	3.30	1.7	0
July 30, 2002		January 16, 2003	3.56	82.9	-129	3.30		
May 7, 2002		· ·				1		
February 21, 2002		-				li e		· ·
November 19, 2001 NA							-	_
August 8, 2001 1.17 28 5-54 7.00 0.7 111 May 22, 2001 0.08 98 -32 6.72 0.2 16 March 13, 2001 0.62 26.91 -60 2.66 0.0 0 November 2, 2000 0.63 4.816 -94 4.10 0.0 28 August 9, 2000 0.40 123 -72 6.10 0.0 0 May 31, 2000 0.40 123 -72 6.10 0.0 0 May 31, 2000 0.45 188 -117 7.80 0.0 4 February 7, 2000 0.70 NM -82 3.60 0.0 140 November 9, 1999 0.61 NM NM -82 3.60 0.0 0 June 10, 1999 0.60 NM NM -82 3.60 0.0 0 June 10, 1999 0.42 NM NM -82 3.60 0.0 0 June 30, 1998 0.42 NM NM -3.10 0.0 0 June 30, 1998 0.42 NM NM -3.10 0.0 0 May 1, 2003 0.00 NM NM NM -3.10 0.0 0 May 1, 2003 0.00 NM NM NM -3.10 0.0 0 May 1, 2003 0.00 151 0.0 0.0 0.0 89 June 10, 1999 0.42 NM NM -3.10 0.0 0 May 1, 2003 0.00 0.51 0.0 0.0 0.0 88 July 24, 2003 0.00 0.51 0.0 0.0 43 1.15 4.3 19 July 24, 2000 0.51 0.0 0.0 0.0 43 1.15 4.3 19 July 30, 2002 0.63 0.0 -43 1.15 4.3 19 July 30, 2002 0.63 0.0 -43 1.15 4.3 19 July 30, 2002 0.65 58.7 108 3.20 0.0 30 February 21, 2001 1.54 320 320 0.0 9.7 -26 1.05 0.0 30 February 21, 2001 1.54 320 320 0.0 9.7 -26 1.05 0.0 30 May 1, 2003 0.00 9.7 -26 1.05 0.0 30 May 22, 2001 1.27 50 193.9 0.47 0.1 31 March 13, 2001 0.56 58.7 108 3.20 0.0 30 May 22, 2001 1.50 1.50 1.50 1.50 1.50 1.50 1.50 1	1							
May 22, 2001								
March 13, 2001		, , ,						
November 2, 2000	·						0.0	0
Mey 31, 2000	1			_	-94	4.10	0.0	28
February 7, 2000		August 9; 2000	0.40	123		ľ		
November 9, 1999 0.61 NM NM 3.50 0.0 0 0 0 0 0 0 0 0						ľ	1	i i
MW-4 July 24, 2003 0.00 183.0 128 0.00 0.0 0								
MW-4	1							
MW-4	1							
MW-4								
May 1, 2003								
January 16, 2003 3.83 15.4 113 0.04 5.9 26	MW-4				7-1 100-10-1 110-10-1 110-1		0.0	8
October 30, 2002 0.63 0.0 -43 1.15 4.3 19		May 1, 2003	0.51	40.0	89	L		
July 30, 2002								
May 7, 2002						1		
February 21, 2002	i I					1 .		
November 19, 2001 0.56 58.7 -108 3.20 0.0 37 August 8, 2001 1.54 320 320 0.09 6.0 30 May 22, 2001 1.27 50 193.9 0.47 0.1 31 March 13, 2001 0.72 190 9.4 0.51 3.2 48 November 2, 2000 0.60 ND -39 0.00 4.5 45 August 9, 2000 0.46 83 -50 0.32 1.0 14 May 31, 2000 0.50 26.8 -40 0.25 0.5 40 February 7, 2000 1.30 NM -31 1.56 0.0 1 November 9, 1999 0.12 NM NM 0.99 0.5 23 August 23, 1999 0.15 NM NM 0.87 0.5 28 June 10, 1998 0.15 NM NM 0.91 0.4 10 June 30, 1998 1.30 NM NM 0.39 4.5 42 MW-5 July 24, 2003 0.00 27.4 -39 0.25 0.0 30 May 1, 2003 0.09 16.3 2 0.47 56.0 1 January 16, 2003 4.58 8.9 -16 0.74 4.5 51 October 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.00 4.5 -23 0.64 7.2 54 February 21, 2002 2.65 3.42 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.25 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.49 NM NM 0.77 2.0 32 August 8, 2001 0.99 NM 18 0.84 0.0 47 November 9, 1999 0.75 NM NM 0.77 2.0 32 August 23, 1999 0.75 NM NM 0.50 1.6 6								
August 8, 2001 1.54 320 320 0.09 6.0 30 May 22, 2001 1.27 50 193.9 0.47 0.1 31 March 13, 2001 0.72 190 9.4 0.51 3.2 48 November 2, 2000 0.60 ND -39 0.00 4.5 45 A5 August 9, 2000 0.46 83 -50 0.32 1.0 14 May 31, 2000 0.50 26.8 -40 0.25 0.5 40 February 7, 2000 1.30 NM -31 1.56 0.0 1 November 9, 1999 0.12 NM NM 0.99 0.5 23 August 23, 1999 0.15 NM NM 0.81 0.4 110 June 30, 1998 1.30 NM NM 0.81 0.4 110 June 30, 1998 1.30 NM NM 0.93 0.9 7 December 30, 1997 4.5 51 October 30, 2002 0.00 0.00 -54 0.85 7.9 27 July 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.30 4.58 8.9 -16 0.74 4.5 51 October 30, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.96 November 2, 2000 0.98 16.7 49 1.00 0.74 4.5 51 November 2, 2000 1.97 490 80 0.00 0.75 November 2, 2000 1.97 490 80 0.00 0.75 November 2, 2000 1.97 490 80 0.00 0.00 26 November 2, 2000 1.97 490 80 0.00 0.00 26 November 2, 2000 1.97 490 80 0.00 0.00 26 November 2, 2000 1.97 490 80 0.00 0.00 26 November 2, 2000 1.97 490 80 0.00 0.00 26 November 3, 1999 0.27 November 3, 1999 0.25 November 3, 1999 0								····
May 22, 2001 1.27 50 193.9 0.47 0.1 31 March 13, 2001 0.72 190 9.4 0.51 3.2 48 November 2, 2000 0.60 ND -39 0.00 4.5 45 August 9, 2000 0.46 83 -50 0.32 1.0 14 May 31, 2000 0.50 26.8 -40 0.25 0.5 40 February 7, 2000 1.30 NM -31 1.56 0.0 1 November 9, 1999 0.12 NM NM 0.99 0.5 23 August 23, 1999 0.15 NM NM 0.81 0.4 10 June 30, 1998 1.30 NM NM 0.81 0.4 10 June 30, 1998 1.30 NM NM 0.93 0.9 7 December 30, 1997 <0.1 NM NM 0.93 4.5 42 MW-5 MW-5 MW-5 MW-5 MW-5 August 23, 1999 0.15 NM NM NM 0.83 0.9 7 December 30, 1997 <0.1 NM NM 0.83 4.5 42 MW-5 MW-5 MW-5 MW-7 August 2, 2003 0.00 16.3 2 0.47 56.0 1 January 16, 2003 4.58 8.9 -16 0.74 4.5 51 October 30, 2002 0.00 0.0 -54 0.85 7.9 27 July 30, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 598 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 25 May 31, 2000 0.48 27.2 -25 0.35 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 47 November 9, 1999 0.27 NM NM NM 0.72 2.0 32 August 9, 1999 0.75 NM NM NM 0.50 1.6 6								i i
March 13, 2001 0.72 190 9.4 0.51 3.2 48	1							31
August 9, 2000 0.46 83 -50 0.32 1.0 14 May 31, 2000 0.50 26.8 -40 0.25 0.5 40 February 7, 2000 1.30 NM -31 1.56 0.0 1 November 9, 1999 0.12 NM NM 0.99 0.5 23 August 23, 1999 0.15 NM NM 0.67 0.5 28 June 10, 1999 0.15 NM NM 0.81 0.4 10 June 30, 1998 1.30 NM NM 0.81 0.4 10 December 30, 1997 c.0.1 NM NM 0.39 4.5 42 MW-5 May 1, 2003 0.00 27.4 -39 0.25 0.0 30 May 1, 2003 4.58 8.9 -16 0.74 4.5 51 October 30, 2002 0.00 0.0 -54 0.85 7.9 27 July 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.00 47 November 9, 1999 0.27 NM NM NM 0.72 2.0 32 August 9, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM NM 0.50 1.6 6		1	•			0.51	3.2	48
May 31, 2000	Ì	November 2, 2000	0.60	ND	-39			
February 7, 2000]			1		E .		£
November 9, 1999 0.12 NM NM 0.99 0.5 23	1							1
August 23, 1999 June 10, 1998 0.15 0.15 NM NM NM NM NM 0.81 0.81 0.4 0.4 10 10.4 June 30, 1998 December 30, 1997 1.30 0.1 NM NM NM NM 0.93 0.99 0.99 7 MW-5 July 24, 2003 May 1, 2003 January 16, 2003 January 16, 2003 July 30, 2002 July 30, 2003 July]							
June 10, 1999 0.15 NM NM 0.81 0.4 10 June 30, 1998 1.30 NM NM 0.93 0.9 7 December 30, 1997 <0.1 NM NM 0.39 4.5 42 MW-5								
June 30, 1998 1.30 NM NM 0.93 0.9 7		1 -						
MW-5 July 24, 2003 0.00 27.4 -39 0.25 0.0 30 May 1, 2003 0.09 16.3 2 0.47 56.0 1 January 16, 2003 4.58 8.9 -16 0.74 4.5 51 October 30, 2002 0.00 0.0 -54 0.85 7.9 27 July 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 0.48 27.2 -25 0.35 0.0 50 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 0.72 2.0 32 August 23, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM NM 0.50 1.6 6								
MW-5 July 24, 2003 0.00 27.4 -39 0.25 0.0 30 May 1, 2003 0.09 16.3 2 0.47 56.0 1 January 16, 2003 4.58 8.9 -16 0.74 4.5 51 October 30, 2002 0.00 0.0 -54 0.85 7.9 27 July 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56	L							
May 1, 2003		11.	and the state of the					
January 16, 2003	MW-5	- '				i -		
October 30, 2002 0.00 0.0 -54 0.85 7.9 27 July 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM </td <th></th> <td></td> <td></td> <td></td> <td></td> <td>l.</td> <td></td> <td></td>						l.		
July 30, 2002 0.37 27.5 -43 0.28 0.8 38 May 7, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM <th></th> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>•</td>								•
May 7, 2002 0.00 45 -23 0.64 7.2 54 February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM			ł .			I .		
February 21, 2002 2.65 34.2 104 0.69 0.0 67 November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM <th></th> <td></td> <td>h .</td> <td></td> <td></td> <td></td> <td></td> <td>1</td>			h .					1
November 19, 2001 1.10 8.5 -33 1.05 3.5 27 August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1998 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM			i .					1
August 8, 2001 1.35 300 103 0.73 0.2 37 May 22, 2001 1.20 593 167 1.10 14.8 13 March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6	1	November 19, 2001		8.5	-33	1.05		27
March 13, 2001 1.01 35.36 34.2 0.33 1.0 45 November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6			1.35	300		0.73		
November 2, 2000 0.56 ND 49 1.02 6.5 31 August 9, 2000 1.97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6								
August 9, 2000 1,97 490 80 0.00 0.0 26 May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6	1		i			· · · · · · · · · · · · · · · · · · ·		
May 31, 2000 0.48 27.2 -25 0.35 0.0 50 February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6								1
February 7, 2000 0.90 NM 18 0.64 0.0 47 November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6	1	I -		1				
November 9, 1999 0.27 NM NM 0.72 2.0 32 August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6	}			1				
August 23, 1999 0.75 NM NM 1.19 2.4 45 June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6	1							
June 10, 1999 0.25 NM NM 0.34 2.5 33 June 30, 1998 0.60 NM NM 0.50 1.6 6		1 '		1				
		1 • •		1	NM			
		June 30, 1998						
December 30, 1997 <0.1 NM NM 0.94 0.3 18	<u> </u>	December 30, 1997	<0.1	I NM	NM	0.94	0.3	18

Table 4
Groundwater Biodegradation Parameters
3609 International Boulevard, Oakland, California

Well	Date	Dissolved Oxygen (mg/L)	Turbidity (NTU)	Redox Potential (mV)	Ferrous Iron	Nitrate (mg/L)	Sulfate (mg/L)
1800 G. L.			a tradicional	Laker W. A		MER AND EAST OF	e Publication and the
MW-6	July 24, 2003	0.03	260.0	-69	3.30	0.0	. 0
	May 1, 2003	0.58	470.0	-66	2,29	0.0	13
	January 16, 2003	3.71	99.7	-70	2.78	0.0	25
	October 30, 2002	NM	. NM	NM	0.95	0.0	0
	July 30, 2002	1.39	127.0	-58	3.30	11.0	36
	May 7, 2002	0.00	263	-110	2.25	0.0	23
	February 21, 2002	0.54	149	-40	6.20	0.0	41
	November 19, 2001	NA	NA	NA	NA ·	NA	. NA
	August 8, 2001	NA	NA	NA	NA NA	NA	· NA
	May 22, 2001	0.12	413	-9.5	1.30	0.0	17
	March 13, 2001	0.75	83	-42.1	2.63	1.3	79
	November 2, 2000	0.80	618	-34	2.65	0.0	16
	August 9, 2000	0.65	1,000	-33	4.10	2.5	0
	May 31, 2000	0.72	111	-62	3.27	0.0	0
	February 7, 2000	1,25	NM	-51	3.02	0.0	0
	November 9, 1999	0.22	NM	NM	7.00	0.0	0
	August 23, 1999	0.55	NM	NM	3.30	0.0	9
	June 10, 1999	0.61	NM	NM	2.52	0.0	23
	June 30, 1998	2.50	NM	NM	. 0.40	0.7	4
	December 30, 1997	<0.1	NM	NM	0.30	<0.1	5
	Call Call Call	to Anthologistic Service	San Palanak I	Control of the Control			
MW-7	July 24, 2003	2.83	91.8	-77	0.61	0.0	2
	May 1, 2003	0.69	36.0	-34	1.06	0.7	9
	January 16, 2003	3.79	110.0	-33	0.35	0.0	17
	October 30, 2002	7.90	23.5	-86	0.97	0.7	0
	July 30, 2002	1.15	16.6	-64	0.68	0.0	28
	May 7, 2002	0.00	531 .	- 6 2	1.79	0.0	20
	February 21, 2002	0.26	118	-6	1.77	0.0	0
	November 19, 2001	0.98	8.9	-14	1.14	0.0	21
	August 8, 2001	1.62	140	-18	0.51	0.0	13
	May 22, 2001	1,71	49.8	56	0.79	0.0	12
	March 13, 2001	0.79	110	-10.4	3.30	0.0	40
	November 2, 2000	. 0.58	ND	-11.6	0.27	3.5	30
	August 9, 2000	0.26	131	-33	0.95	0.0	17
	May 31, 2000	0.30	34.9	-52	0.72	0.0	28
	February 7, 2000	0,91	NM	-19	0.53	0.0	41
	November 9, 1999	0.14	NM	NM	0.99	0.0	25
	August 23, 1999	0.65	NM	NM	1.40	0.0	20
	June 10, 1999	0.15	NM	NM	0.19	0.0	22
	June 30, 1998	1.00	NM	NM	0.78	0.5	4
	December 30, 1997	1.20	NM	NM	0.23	0.2	32
	en Linder State			d Galacter Control	ALTRICA DE LO MANTO	State State Control	na Laberta Period

Table 4
Groundwater Biodegradation Parameters
3609 International Boulevard, Oakland, California

	,	Dissolved Oxygen	Turbidity	Redox Potential	Ferrous Iron	Nitrate	Sulfate
Well	Date	(mg/L)	(NTU)	(mV)	(mg/L)	(mg/L)	(mg/L)
8-WM	July 24, 2003	0.00	610.0	-129	1.68	0.0	a
	May 1, 2003	0.73	193.0	-100	1.90	0.0	0
	January 16, 2003	3.21	145.0	-115	3.30	0.5	0
	October 30, 2002	0.00	<999	-132	3.30	2.6	40
	July 30, 2002	0.18	157.0	-124	1.38	0.0	1
	May 7, 2002	0.00	308	-113	0.80	0.0	2
j	February 21, 2002	0.00	567	-64	3.08	0.0	0
	November 19, 2001	0.46	53.5	-142	>3.3	0.0	1
	August 8, 2001	1.24	990	-62	1.50	0.8	25
	May 22, 2001	1.16 ⁻	179	-8.8	3.30	0.0	5
	March 13, 2001	0.48	110	-76	3.30	2.1	12
	November 2, 2000	-	350	-104.9	7.33	-	16
	August 9, 2000	0.50	94	-91	3.30	0.0	7
	May 31, 2000	0.45	13	-95	3.30	0.0	0
	February 7, 2000	0.65	NM	-90	3.46	0.0	0
	November 9, 1999	0.38	NM	NM	8.90	0.0	0
	August 23, 1999	0.20	NM	NM	8.20	0.0	13
	June 10, 1999	0.10	NM	NM	4.70	0.0	0
	June 30, 1998	1.30	NM	NM	2.82	<0.1	3
	December 30, 1997	2.50	NM	NM	3.35	0.1	<1
				以外决定 。			
MW-10	July 24, 2003	0.00	40.4	1	0.00	0.0	1
	May 1, 2003	1.74	11.2	16	0.00	1.3	10
	January 16, 2003	4.83	23.0	-8	0.25	3.1	, 1
}	October 30, 2002	0.47	0.0	-19	0.66	3.7	14
1	July 30, 2002	0.09	12.7	34	0.18	0.0	25
	May 7, 2002	0.00	123	1 9	0.00	0.0	18
	February 21, 2002	0.15	12.6	. 85	. 0.49	0.0	4
	November 19, 2001	0.89	3	45	0.99	2.7	12
	August 8, 2001	1.56	19.6	52	0.00	0.0	11
	May 22, 2001	1.76	19.56	105	0.10	1.7	13
	March 13, 2001	0.65	32.11	28	0.23	0.0	0
ŀ	November 2, 2000	0.53	ND	26.7	0.42	1.3	13
:	August 9, 2000	0.45	116	19	0.40	0.0	0
	May 31, 2000	0.40	22.4	17	0.29	0.0	O O
	February 7, 2000	0.82	NM	55	0.00	0.0	0
	November 9, 1999	0.44	NM	NM	0.37	0.0	12
	August 23, 1999	0.50	NM	NM	0.52	. 0.0	9
	June 10, 1999	0.20	NM	NM	0.25	0.0	0
	June 30, 1998	0.90	NM	NM	0.38	<0.1	<1
ł	December 30, 1997	<0.1	MM	NM	2.21	0.3	<1

Table 4 **Groundwater Biodegradation Parameters** 3609 International Boulevard, Oakland, California

Well	Date	Dissolved Oxygen (mg/L)	Turbidity (NTU)	Redox Potential (mV)	Ferrous Iron (mg/L)	Nitrate (mg/L)	Sulfate (mg/L)
							e amaginaka
MW-11	July 24, 2003	0.00	26.1	-35	0.00	0.0	3
	May 1, 2003	4.08	138.0	55	0.22	3.3	47
	January 16, 2003	9.49	4.0	9	0.25	2.6	32
	October 30, 2002	NM	NM	NM	NM	NM	NM
	July 30, 2002	0.21	6.8	-22	0.18	6.7	31
	May 7, 2002	0.00	155	-29	0.49	4.6	28
	February 21, 2002	2.52	168	31	0.00	0.0	40
	November 19, 2001	0.72	8.4	-18	2.30	1.0	30
	August 8, 2001	NA	NA	NA NA	NA NA	NA	NΑ
	May 22, 2001	2.13	32.3	40.5	0.53	0.0	20
	March 13, 2001	0.79	111	114 <u>.7</u>	0.34	0.0	78
	November 2, 2000	0.60	ND	17	0.44	1.5	21
	August 9, 2000	0.48	42	10	0.80	1.5	.0
	May 31, 2000	-0.50	12	-15	0.69	5.2	10
	February 7, 2000	1.10	NM	-14	0.75	0.0	24
	November 9, 1999	0.22	NM	- NM	0.06	0.0	21
	August 23, 1999	0.60	NM	NM	0.92	0.0	52
	June 10, 1999	0.19	NM	NM	0.28	0.0	0
	June 30, 1998	2.20	NM	NM	0.15	1.2	6
	December 30, 1997	<0.1	NM	NM	0.32	3.5	35
SANCE COUNTY	A PROPERTY.	o estados de la	ted New York Street, or		En 19 at Chicago Maria		STAN STAN
MW-12	July 24, 2003	0.00	19.0	-98	1.13	0.0	0 .
	May 1, 2003	1.41	15.0	-89	1.97	0.0	0
	January 16, 2003	4.55	210.0	-7 <u>9</u>	2.00	1.0	00
	October 30, 2002	0.30	0.0	-84	2.24	0.0	0
	July 30, 2002	0.29	1,7	-60	2.37	3.3	0
	May 7, 2002	0.00	53.1	-67	2.00	0.0	13
	February 21, 2002	0.56	4.9	-6	1.43	0.0	0
	November 19, 2001	0.92	20	-72	2.29	0.0	2
	August 8, 2001	1.66	72	3	2.46	0.0	0
	May 22, 2001	1.76	6.28	-18.9	2.38	1.9	0
	March 13, 2001	0.64	8.42	-5.6	1.44	0.0	0
	November 2, 2000	0.60	19	12	1.93	0.0	6
	August 9, 2000	0.31	56	-48	2.84	0.0	0
	May 31, 2000	0.29	7.7	-54	2.11	0.0	0
	February 7, 2000	0.62	NM	-42	1.53	0.0	0
	November 9, 1999	0.34	NM	NM	2.21	3.1	9

Notes:

NA: Not analyzed, MW-3 not analyzed on November 19, 2001 due to free product, ND: Not Detected NM: Not Measured

The turbidity reading for MW-8 was above the allowable equipment tolerance of the equipment MW-6 not analyzed on November 19, 2001, well was inaccessible due to property obstacles.

Table 5
Groundwater Analytical Data
July 24, 2003

3609 International Boulevard, Oakland, California

Monitoring Well	TPH-g (μg/L)	Benzene (μg/L)	Toluene (μg/L)	Ethyl- Benzene (μg/L)	Total Xylenes (μg/L)	MtBE ¹ (μg/L) 8021B/8260B
MW-1	36,000	4,800	1,800	1,300	5,600	23000/ 25000
MW-2	220	3.9	4.3	7	14.5	<2.0
MW-3	31,000	4,700	990	1,400	5,200	15000/ 16000
MW-4	<50	1	<0.5	<0.5	<0.5	2.3/ < 0.5
MW-5	300	<0.5	1.9 C	0.76	<0.5	<2.0
MW-6	29,000	1,600	520	1,500	4,400	<200
MW-7	230	< 0.5	1.3 C	< 0.5	0.63	8.2/ 5.9
MW-8	12,000	460	54 C	910	435	830/ 890
MW-10	750	160	4	58	6.66 C	110/79
MW-11	340	19 C	3.2	0.58	0.89	<2.0
MW-12	2,200	32 C	16 C	<0.5	9,2	80/ 66

Notes

< : Not detected above laboratory reporting limits.

^C Presence confirmed, but the results percent difference exceed 40%.

^H Heavier hydrocarbons may have contributed to the quantitation.

¹ MtBE was analyzed using the EPA Method 8021B and confirmed using 8260B.

Table 6
Historical Groundwater Analytical Data
3609 International Boulevard, Oakland, California

Monitoring Well	Date	TPH-g (μg/L)	Benzene (μg/L)	Toluene (μg/L)	Ethyl-Benzene (μg/L)	Total Xylenes (μg/L)	MtBE EPA 8260B (µg/L)
100 20 20 2	SECTION OF		te di albia di	erana (经有效的 类的	N. Carlo	LIKE BURE TO A
MW-1	7/24/03	36,000	4,800	1,800	1300	5,600	25,000
	5/1/03	59,000	3,100	2,700	1500	7,000	14,000
	1/16/03	62,000	3,500	6,000	1600	9,700	48,000
	10/30/02	27,000	2,200	2,400	950	4,500	34,000
	7/30/2002	29,000	2,400	2,500	920	4,400	13,000
	5/7/2002	53,000	4,400	5,100	1300	7,000	32,000
	2/21/2002	260,000	3,700	12,000	3,700	19,200	23,000
	11/19/2001	41,000	2,700	5,100	1,000	4,570	74,000
	8/8/2001	14,820	852	342	568	1,606	2,000
	5/22/2001	4,900	310	81	82	- 388	150
	3/13/2001	14,570	1,005	440	108	2,030	16
	11/2/2000	7,050	435	52	ND	689	10
	8/9/2000	11,000	638	<5	<5	<5	17.1
	5/31/2000	15,610	610	350	310	1,400	<5
	2/7/2000	40,000	2,280	1,380	8	6,130	47
	11/9/1999	10,000	693	15	<5	3,471	50
	8/23/1999	19,750	678	463	893	2,938	38
	6/10/1999	25,000	1,110	1,460	1,330	5,265	77
	3/16/1999	17,000	480	860	850	3,000	190
	12/16/1998	65,000	2,500	2,400	2,300	9,500	160
	12/30/1997	27,000	2,300	2,100	1,400	5,100	NA
	4/10/1997	NA	NA	NA	NA .	NA	NA
	12/9/1996	NA	- NA	NA	NA	NA	NA
	4/3/1996	31,000	98	120	63	170	NA NA
	1/3/1996	30,000	71	73	50	120	NA NA
	10/2/1995	59,000	140	130	140	390	NA NA
	6/5/1995	21,000	950	650	570	150	NA NA
	3/6/1995	32,000	190	. 160	150	490	NA NA
	12/2/1994	80,000	3,800	6,600	2,300	11,000	NA NA
	10/5/1994	320,000	24,000	21,000	2,600	15,000	I IVA

Table 6
Historical Groundwater Analytical Data
3609 International Boulevard, Oakland, California

<u> </u>	<u> </u>		······································			Total	MtBE
Monitoring		TPH-g	Benzene	Toluene	Ethyl-Benzene	Xylenes	EPA 8260B
Well	Date	(μg/ L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μ g/ L)
Later Coll Service							a se
MW-2	7/24/03	220	3.9	4.3	7	14.5	<2.0
	5/1/03	1,300	14.0	88	78	271	<2.0
	1/16/03	510	5.1	30	24	92	<2.0
	10/30/02	<50	<0.5	<0.5	<0.5	0.64	· <2.0
	7/30/2002	180	11	6.3	9.4	27	<2.0
	5/7/2002	1,800	31	140	110	348	<2
	2/21/2002	1,700	26	180	95	360	<2
	11/19/2001	470	13	64	22	83	14
	8/8/2001	125	4	4	3	11	NĐ
	5/22/2001	870	37	75	55	179	2.7
	3/13/2001	932	18	34	1.3	225	ND
	11/2/2000	ИD	ND	ND	ND	ND	ND
	8/9/2000	<50	<5	<5	<5	<5	<5
	5/31/2000	2,930	130	330	130	570	<5·
	2/7/2000	6,400	372	639	46	134	8
	11/9/1999	<50	<5	< 5	<5	<5	<5
	8/23/1999	60	6	9	4 ′	11	ND
	6/10/1999	3,500	290	428	211	744	ND
	3/16/1999	7,600	730	830	610	1,900	55
	12/16/1998	26,000	1,400	1,600	880	9,500	<5
	9/29/1998	29,000	290	180	160	360	<0.5
	6/30/1998	25,000	2,000	2,000	1,300	4,300	NA NA
	12/30/1997 4/10/1997	35,000	4,900	4,900	1,600	7,000 0	NA ND
	12/9/1996	53,000 6,200	150 11	110 7	37 2	14	ND ND
	4/3/1996	27,000	0	92	44	13	₹ NA
	1/3/1996	46,000	160	130	93	240	NA NA
	10/2/1995	46,000	160	130	93	240	NA.
	6/5/1995	8,000	220	330	350	660	NA
	3/6/1995	490	3	3	3	1	NA
MW-3	7/24/03	31,000	4,700	990	1,400	5,200	16,000
	5/1/03	48,000	5,800	1,400	1,600	7,400	5,900
	1/16/03	35,000	2,900	1,300	860	5,200	13,000
	10/30/02	70,000	4,900	5,100	2,100	11,900	21,000
	7/30/2002	45,000	8,900	1,700	1,600	5,600	2,600
	5/7/2002	54,000	6,700	3,200	1,800	7,100	9,100
	2/21/2002	62,000	6,000	7,600	1,900	9,200	12,000
	11/19/2001	NA	NA	NA	NA 	NA	NA 50
	8/8/2001	41,750	3,485	2,670	1,255	5,420	52
	5/22/2001	44,000	5,400	3,100	1,400	6,400	200
	3/13/2001	14,754	2,250	140	ND 676	1,284	110
	11/2/2000	48,000	6,789	4,816	676 883	7,258	83 176
	8/9/2000 5/31/2000	76,000 68,000	8,900 15,000	5,636 8,900	1,500	7,356 7,400	17 6 <5
	2/7/2000	44,000	6,090	3,360	1,500 <5	5,780	276
	11/9/1999	26,000	3,218	1,319	<5	6,697	126
	8/23/1999	64,000	7,484	8,052	1,744	9,749	141
	6/10/1999	46,000	8,245	6,425	1,015	7,173	274
	3/16/1999	45,000	4,100	6,400	1,000	6,100	470
	12/16/1998	51,000	5,700	3,900	1,200	6,300	410
	1/3/1996	150,000	510	410	210	650	NA
	10/2/1995	150,000	510	410	210	65	NA
	6/5/1995	350,000	20,000	42,000	5,800	36,000	NA
	3/6/1995	350,000	20,000	42,000	5,800	36,000	NA _
	12/2/1994	250,000	19,000	22,000	4,400	28,000	NA
L	10/5/1994	3,000,000	190,000	740,000	310,000	130,000	NA .

Table 6
Historical Groundwater Analytical Data
3609 International Boulevard, Oakland, California

Monitoring						Total	MiBE
		TPH-g	Benzene	Toluene	Ethyl-Benzene	Xylenes	EPA 8260B
Well	Date	(μg/L)	(μg/L)	(μg/L)	(μg/L)	, (μg/L)	(μg/L)
MW-4	7/24/03	<50	1	<0.5	<0.5	<0.5	<0.5
	5/1/03	120	27	1.8	9.	14.6	<2.0
	1/16/03	310	49	2.5	13	26.7	<2.0
i F	10/30/02	320	69	0.99	8.8	5.49	<2.0
	7/30/2002	450	20	24	19	74	<2.0
	5/7/2002	570	72	29	27	74	<2
	2/21/2002	450	63	4.1	22	28.7	<2
	11/19/2001	670	180	5	17	53	ND
<u> </u>	8/8/2001	133	12	2.2	3.9	9	ND
	5/22/2001	80	12	1.9	4.1	9.8	ND
	3/13/2001	62	ND	· ND	3.2	8.7	ND
i F	11/2/2000	ND	5.30	ND	ND	. 8	ND
i l	8/9/2000	370	5.08	<5	<5	<5	<5
	5/31/2000	552	42	19	16	67	<5
1	2/7/2000	7,800	1,200	61	<5	781	<5
	11/9/1999	<50	<5	<5	<5	<5	<5
i I	8/23/1999	660	497	41	54	. 145	6
	6/10/1999	1,000	298	44	19	64	13
	3/16/1999	600	200	35	19	56	11
i i	12/16/1998	1,400	590	33	28	94	24
i I	9/29/1998	6,200	910	77	68	200	18
	6/30/1998	1,700	780	160	54	200	NA
l [12/30/1997	2,300	410	270	100	1,500	NA
i l	4/10/1997	ND	ND	ND	· ND	ND	ND
	12/9/1996	4,000	14	6	4	12	ND
	4/3/1996	1,900	12	8	5	14	NA
	1/3/1996	9,300	230	110	10 -	29	NA NA
MW-5	7/24/03	300	<0.5	1.9 C	0.76	<0.5	<2.0
i I	5/1/03	130	<0.5	<0.5	1	<0.5	3.1
	1/16/03	450 Y	<0.5	<0.5	4	0.54	2.1
i i	10/20/2002	.77	<0.5	<0.5	<0.5	<0.5	<2.0
1	7/30/2002	110	<0.5	<0.5	0.77	<0.5	<0.5
l	5/7/2002	160	<0.5	0.78 C	2	2.15	2.3
	2/21/2002	290	3.5	2	6.2	6.2	<0.5
	11/19/2002	920	17	160	26	135	40
ļ [8/8/2001	258	1	1.1	3.4	7.3	1.4
1	5/22/2001	180	ND	ND	2.1	0.57	4.4
 	3/13/2001	382	6.1	1.9	6.6	5.9	ND
[11/2/2000	ND	ND	ND	ND	ND	ND
[]	8/9/2000	<50	<5	<5	<5	<5	<5
	5/31/2000	627.4	7.4	24	12	32.4	<5 -
	2/7/2000	70	<5	<5	<u><5</u>	7	<5
1	11/9/1999	<50	<5	<5	<5 ND	<5	<5 ND
]	8/23/1999	120	ND	4	ND	4	ND ND
1	6/10/1999	270	4	3	6	4	ND 10
	3/16/1999	650	3	1	16 ND	2 2	10 ND
]	12/16/1998	1,400	1 1	1	ND	3	ND <.5
]	9/29/1998	270	2	1 -5	. 3 15	<10	NA NA
]	6/30/1998	400 790	<5 82	<5 66	59	160	NA NA
[12/30/1997 4/10/1997	790 NA	NA	NA NA	NA NA	NA	NA NA
]	12/9/1996	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
[4/3/1996	780	1	1	5	4	NA NA
]	1/3/1996	1,500		1	4	5	NA NA
	10/2/1995	1,500	 	1	4	5	NA NA

Table 6
Historical Groundwater Analytical Data
3609 International Boulevard, Oakland, California

					·	Total	MtBE '
Monitoring		TPH-g	Benzene	Toluene	Ethyl-Benzene	Xylenes	EPA 8260B
Well	Date	(μg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)	. (μg/L)
Living No. 10							ar de maria de la f
MW-6	7/24/03	29,000	1,600	520	1,500	4,400	<200
	. 5/1/03	150,000 H	1,400	780	2,500	8,700	<40
	1/16/03	12,000	730	230	740	1,690	<20
	10/30/02	22,000	1,200	620	1,300	2,800	<20
	7/30/2002	24,000	1,000	410	1,400	3,770	<20
	5/7/2002	10,000	400	160	470	970	<2
	2/21/2002	14,000	440	180	750	1,020	<10
	11/19/2001	NA	NA	NA	NA	NA	NA
	8/8/2001	NA	NA	NA	NA	NA	NA
	5/22/2001	27,000	760	450	1,600	4,270	ND
	3/13/2001	15,637	713	459	238	2,363	ND
	11/2/2000	19,000	1,387	618	ND	5,250	ND
	8/9/2000	24,000	1,306	870	<5	5,162	<5
	5/31/2000	21,700	1,700	1,200	17	3,600	<5
	2/7/2000	17,000	1,360	521	<5	4,150	6
	11/9/1999	40,000	1,084	130	<5	10,940	<5
	8/23/1999	42,000	3,806	3,649	1,554	7,996	10
	6/10/1999	18,500	2,060	1,650	735	3,170	ND
	3/16/1999	37,000	3,900	4,300	1,600	7,000	180
	1/3/1996	120,000	350	310	200	610	NA
MW-7	7/24/03	230	<0.5	1.3 C	<0.5	0.63	5.9
	5/1/03	280	<0.5	<0.5	<0.5	<0.5	11
	1/16/03	220 Y	<0.5	<0.5	0.78	0.55	19
	10/30/02	350	<0.5	2.1 C	<0.5	3.1 C	43
	7/30/2002	270	5.3	1.3 C	2.3	8.1	46
	5/7/2002	560	15	28.0	9.2	44.0	37
	2/21/2002	380	<0.5	2.5	2	3.8	78
	11/19/2001	1,700	24	220	41	205	69
	8/8/2001	610	3.7	3	6.2	18.9	10
	5/22/2001	370	ND	9.1	1.3	2.3	28
*	3/13/2001	82	. 0.97	ND	0.76	ND	78
	11/2/2000	50	ND	ND	ND	ND	9.1
	8/9/2000	80	<5	<5	<5	<5	11.7
	5/31/2000	494.9	4,9	22	4.2	21.9	29
	2/7/2000	80	<5	<5	<5	<5	23
! i	11/9/1999	290	<5	9	<5	<5	12
	8/23/1999	570	5	10	ND	ND	ND
1	6/10/1999	320	3	7	4	3	26
	3/16/1999	300	3	1	1	1	62
	12/16/1998	990	5	10	5	20	160
	9/29/1998	1,800	1	1	1	2	68
	6/30/1998	620	4	<5	9	<10	NA
	12/30/1997	1,400	130	98	75	200	NA
	4/10/1997	NA	NA	NA	NA	NA	NA NA
	12/9/1996	NA	NA	NA	NA	NA	NA
	4/3/1996	1,900	2	3	5	7	NA
	1/3/1996	3,300	9	12	17	45	NA
	10/2/1995	NA	10	12	17	NA	3,300

Table 6
Historical Groundwater Analytical Data
3609 International Boulevard, Oakland, California

		7 -54.	_		50 I B	Total	MtBE
Monitoring		TPH-g	Benzene	Toluene	Ethyl-Benzene	Xylenes	EPA 8260B
Well	Date	(μg/L)	(µg/L)	(μg/L)	(μg/L)	(μg/L)	(μg/L)
	2000 100 1 mm at 100 mm at 100 mm	(* 12 AV AV A	and the state of the				
MW-8	7/24/03	12,000	460	54 C	910	435	890
	5/1/03	18,000	380	33 C	1,000	516	540
	1/16/03	8,100	300-	29	370	302	1,100
ļ	10/30/02	18,000	950	,75	1,400	1,269	700
1	7/30/2002	8,400	340	78	530	517	1,200
1	5/7/2002	9,000	360	56	560	622	2,100
	2/21/2002	240,000	1,400	<25	4,200	6,560	<100
	11/19/2001	13,000	600	270	750	1,200	400
	8/8/2001	5,620	153	46	373	345	174
	5/22/2001	3,100	110	28	140	194	410
	3/13/2001	2,360	81	16	71	270	221
1	11/2/2000	3,000	278	350	209	980	21
	8/9/2000	22,000	632	5.38	<5	2,686	37.3
	5/31/2000	25,940	940	130	1,600	3,960	75
	2/7/2000	44,200	1,080	617	<5	4,160	240
	11/9/1999	10,500	92	<5	<5	3,414	769
	8/23/1999	58,000	5,379	2,438	3,001	6,960	639 988
	6/10/1999	39,500	3,610	1,635	2,175	5,913	ì
	3/16/1999	22,000	1,800	470	2,000	2,000	820
	12/16/1998	61,000	6,300	1,700	2,200	4,400 7,300	1,300 NA
	6/30/1998	54,000	4,600	2,800	3,500 2,100	4,700	NA NA
	12/30/1997 4/10/1997	28,000 24,000	6,000 86	1,600 55	∠,100 50	100	ND ND
	12/9/1996	27,000	88	43	44	80	ND ND
	4/3/1996	58,000	250	170	140	330	NA .
	1/3/1996	94,000	310	250	180	480	NA NA
MW-10	7/24/03	750	160	4	58	6.66 C	79
11111-10	5/1/03	2,500	650	10	190	15.81 C	180
	1/16/03	17,000	870	11	290	27	270
	10/30/02	550	130	3.00	31.0	2.7	70
	7/30/2002	160	26	0.55	8.1	1.0	72
	5/7/2002	3,400	660	13	260	48.0	270
	2/21/2002	4,700	1,100	20	370	63.7	500
	11/19/2001	3,500	900	260	310	258	410
	8/8/2001	242	35	1	11	230	64
}	5/22/2001	2,900	630	11	200	31	270
1	1	2,900 4,935	969	18	200 41	72	630
	3/13/2001	4,935 ND	ND ND	ND	ND	ND	145
	8/9/2000	6,800	1,055	26	54	53.8	1,283
	5/31/2000	4,400	1,500	25 25	390	107,1	580
1	2/7/2000	4,400 <50	1,500 <5	25 <5	<5	<5	448
	11/9/1999	2,950	1,134	20	< 5	70	652
ŀ	8/23/1999	2,950 3,250	2,135	97	600	248	1,800
l	6/10/1999	4,200	1,168	34	264	154	1,195
1	3/16/1999	4,200	15	28	420	250	2,800
Ī	12/16/1998	8,700	3,800	51	790	420	1,800
	9/29/1998	9,900	5,400	66	970	620	2,600
	12/30/1997	10,000	5,300	76	1,100	780	NA
	4/10/1997	1,000	21	9	3	3	ND .

Table 6
Historical Groundwater Analytical Data
3609 International Boulevard, Oakland, California

Monitoring Well	Date	TPH-g (μg/L)	Benzene (μg/L)	Toluene (μg/L)	Ethyl-Benzene (μg/L)	Total Xylenes (µg/L)	MtBE TEPA 8260B (µg/L)
Translation is		100	1717 01 10 1		Company of the Company	自由 的人的是	
MW-11	7/24/03	340	19 C	3.2	0.58	0.89	<2.0
	5/1/03	280	17	1.5 C	8	4.10	<2.0
	1/16/03	700	32	5.7	25	14.10	<2.0
	10/30/02	NA	NA	NA	NA	NA	NA
	7/30/2002	120	5.6	<0.5	0.61	0.53	<2.0
	5/7/2002	280	16	3	7.6	7.6	<2
	2/21/2002	.560	34	20	32	37.3	< 0.5
	11/19/2001	300	7.9	26	5.1	28.9	ND
	8/8/2001	NS	NS	NS	NS	NS	NS
	5/22/2001	280	12	8.3	3.3	9.8	12
	3/13/2001	273	8.6	2.1	10	14	ND
	11/2/2000	60	ND	ND	ND	ND	ND
	8/9/2000	590	10.5	5.94	<5	7.75	<5
	5/31/2000	. 477	27	13	9.5	29.0	<5
	2/7/2000	700	20	15	<5	35	< 5
	11/9/1999	<50	<5	. <5	<5	<5	<5
	8/23/1999	170	4	4	ND -	6	ND
	6/10/1999	4,600	1,240	35 .	290	159	1,291
	3/16/1999	710	30	6	53	84	8
	12/16/1998	650	27	4	25	33	>0.5
	9/29/1998	170	7	1	4	9	22
	6/30/1998	1,100	45	24	71	100	NA
	12/30/1997	710	66	97	59	190	NA
MW-12	7/24/03	2,200	32 C	16 C	<0.5	9.20	66
	5/1/03	2,200	58	<0.5	4.2 C	4.1 C	96
	1/16/03	2,300	65	<0.5	11	4.00	86
	10/30/02	2,600	71	<0.5	<0.5	10.3	- 84
	7/30/2002	2,200	57	<0.5	11	2.6	100
	5/7/2002	2,700	74	<0.5	20	5.1	94
	2/21/2002	2,500	77	< 0.5	5.7	7.4	95
	11/19/2001	3,000	81	69	13	73	120
	8/8/2001	2,090	71	1.8	3	4	142
	5/22/2001	31,000	1,200	ND	95	165	1,900
	3/13/2001	1,517	13	5.6	5.5	11	214
	11/2/2000	1,010	9.3	19.0	ND	7.40	215
	8/9/2000	1,730	15.4	12.4	<5	<5	185
	5/31/2000	3,930	230	10	34	12	200
	2/7/2000	4,000	351	37	<5	24	513
	11/9/1999	80	<5	<5	<5	<5	229

Notes:

MtBE was analyzed using the EPA Method 8021B and confirmed using 8260B.

ND, <: Not Detected above laboratory reporting limits.

NA: Not Analyzed

Presence confirmed, but confirmation concentration differed by more than a factor of two.

NS: Not Sampled

Y: Sample exhibits fuel pattern which does not resemble standard.

Table 7

Total Volume of Water Treated, Historical Operational Data, and Effluent and GAC-1 Analytical Results
3609 International Boulevard, Oakland, California

		Meter	Lab Results	For Effluent	and GAC-1	T]	
		Reading	(concentrat	ions in ug/L)				
Month	Date	(gallons)	MtBE ²	TPH-g	Benzene	Toluene	Ethylbenzene	Total Xylenes
	Added Asserting							
July	7/21/2003	1,995,240	< 5.0 40	< 50 < 50	< 5.0 < 5.0	< 5.0 < 5.0	< 5.0 < 5.0	< 5.0 < 5.0
			40	< 50	V 5.0	V 5.0	V 3.0	V J.0
	7/9/2003	1,990,260	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
			36	< 50	< 5.0	< 5.0	< 5.0	< 5.0
June	6/18/2003	1,978,560	Carb	on Change-o	ut of 2000 lb	vessel and 5	i5 gallon polishir I	ng vessel
	6/10/2003	1.972.780	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
	GITGIEGG	1,012,100	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
May	5/21/2003	1,951,830	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
			< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
	5/1/2003	1,918,270	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
		.,,	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
April	4/11/2003	1,882,440	< 5.0 < 5.0	< 50 < 50	< 5.0 < 5.0	< 5.0 < 5.0	< 5.0 < 5.0	< 5.0 < 5.0
		THE STATE OF THE S			< 5.0	< 5.U	5.0 	< 5.0
March	3/19/2003	1,846,490	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
matari	OI TOIZOGO	1,040,400	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
				Ĵ				
February	2/25/2003	1,804,960	repla	iced 55-gallor	polishing ve	ssel with nev	w 55 gallon cart	on drum
				1		<u> </u>		
	2/19/2003	1,791,720	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
		.,,,,,,,,	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
January	1/27/2003	1,733,500	< 5.0 < 5.0	< 50 < 50	< 5.0	< 5.0 < 5.0	< 5.0 < 5.0	< 5.0 < 5.0
			< 5.0	< 50	< 5.0	< 5.0	<u> </u>	V 5.0
	1/2/2003	1,675,600	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
•			< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
No company of the second								
Describes				50			< 5.0	·
December	12/10/2002	1,672,870	< 5.0 < 5.0	< 50 < 50	< 5.0 < 5.0	< 5.0 < 5.0	< 5.0	< 5.0 < 5.0
			- 0.0	- 00	- 0.0	1 3.0	10.0	0.0
November	11/22/2002	1,668,650	< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
			< 5.0	< 50	< 5.0	< 5.0	< 5.0	< 5.0
	11/13/2002	1,664,780	renlace	ed gasket on	top of 2000 l	h GAC vacci	l el, slight leak wa	e detected
	11/13/2002	1,004,780	Теріасс	T gasker on	10p 01 2000 1	GAC Yessi	i, siigi ii leak wa	is delected
	11/7/2002	1,663,880	Carb	on Change-o	ut of 2000 lb	vessel and 5	5 gallon polishir	ng vessel
October	10/16/02 ³	1,661,590	< 310	2,000 Y Z	< 310	< 310	< 310	< 310
\$417 <u>8717888</u>	and the stand Plant is purificated at the stands of		< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
September	9/19/2002	1,653,600	< 5	< 50	< 5	< 5	< 5	< 5
- opternoer	3/13/2002	1,000,000	< 5	< 50	< 5	< 5	< 5	< 5
August	8/23/2002	1,641,650	1	< 50	< 0.5	< 0.5	< 0.5	< 0.5
	-	-	< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
July	7/23/2002	1,632,834	<5.0	< 50	<5.0	<5.0	<5.0	<5.0
	1	, .,	-0.0	- 00	-0.0			

Table 7
Total Volume of Water Treated, Historical Operational Data, and Effluent and GAC-1 Analytical Results 3609 International Boulevard, Oakland, California

		Meter	Lab Results	For Effluent	1 and GAC-1			
		Reading	(concentrati	ions in ug/L)				
Month	Date	(gallons)	MtBE ²	TPH-g	Benzene	Toluene	Ethylbenzene	Total Xylenes
Mar Ada Car	· (数字) (数数数	THE WAR	areas and	1.0346	* 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			CALL DISTRICT
June	6/24/2002	1,610,050	1.7	< 50	< 0.5	< 0.5	< 0.5	< 0.5
			< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
May	5/30/2002	1,571,630	< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
	5,00,0000	4.540.000	< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
	5/20/2002	1,548,000	rem	ovea newly in			lled another cor	npressor
	5/8/2002 5/1/2002	1,538,850 1,529,650	-	- In	stalled new 5	ew compres		
	5/1/2002	1,529,650	 	111	Stalled new 5	S gallon GA	C vessei	
April	4/24/2002	1.528.740	< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
Дри	4/24/2002	1,020,140	< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
	4/1/2002	1,478,500	 				n compressor	
10 D & .			Market Color					MARY CONTRACTOR
March	3/25/2002	1,478,420					reatment system	
maron.	3/18/2002	NR		periorne	replaced pist	•	•	•
	3/14/2002	1.478.330		co	moressor not			
	07.172002	1,110,000		1	1	1	1	Ī
February	2/27/2002	1,449,830	< 0.5	< 50	< 0.5	< 0.5	< 0.5	< 0.5
			1.1	< 50	< 0.5	< 0.5	< 0.5	< 0.5
January	1/22/2002	1,381,370	< 2.0	< 50	< 0.5	< 0.5	< 0.5	< 0.5
			< 2.0	< 50	< 0.5	< 0.5	< 0.5	< 0.5
			A PARTY		Mark Control	werth by th		
December	12/12/2001	1,311,340	ND	ND	ND	ND	ND	ND
			ND	ND	ND	ND	ND	ND
				<u> </u>	<u> </u>			NB
November	11/2/2001	1,272,660	ND	ND	ND	ND _	ND .	ND ND
THE SHARESHIP IN THE SALES THE STATE OF		SPANNERS OF SPECIAL SECURIOR	0.6	ND	ND	ND	ND	NU The Market
September	9/28/2001	NA	ND	ND ND	ND ND	ND	ND NC	ND ND
	 	 	ND	ND	ND	ND .	ND	עאַ
August	8/22/2001	1,243,100	ND	ND	ND	ND	ND	ND
August	6/22/2001	1,243,100	ND ND	ND	ND ND	ND ND	ND.	ND
	+	 	INU	NU -	110	140	,,,,	1
July	7/26/2001	1.227.270	ND	ND	ND	ND	ND	ND
',	1,,20,2001	1,227,270	ND	ND ND	ND	ND	ND	ND
	7/11/2001	1,226,730	NA	NA.	NA NA	NA	NA	NA
	+	1	NA.	NA	NA.	NA	NA	NA

Table 7
Total Volume of Water Treated, Historical Operational Data, and Effluent and GAC-1 Analytical Results
3609 International Boulevard, Oakland, California

		Meter	Lab Results	For Effluent	and GAC-1			
		Reading	(concentrati	ons in ug/L)				
Month	Date	(gallons)	MtBE ²	TPH-g	Benzene	Toluene	Ethylbenzene	Total Xylenes
					A PART OF			
June	6/29/2001		NA	NA NA	NA	NA	NA	NA
*****		, ,,==-	ND	ND	ND	ND	ND	ND
	6/26/2001	NR			installed n	ew compres	ssor	
	6/16/2001	1,216,580	NA	NA	NA	NA	NA	NA
			NA	NA	NA	NA	NA	NA
				compre	essor not work	king, repaire	ed compressor	
	6/7/2001	1,216,580	NA	NA	NA	NA	NA	NA
			NA	NA .	NA	NA	NA	NA
Mari	5/20/2001	4 205 400	NIA.	KIA	NA NA	NA NA	NA.	NA NA
May	5/30/2001	1,205,198	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
	6/22/2004	1 104 200	. 		NA NA	NA NA	NA NA	NA NA
	5/23/2001	1,194,390	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
	5/17/2001	1 102 260	ND ND	ND ND	ND	ND ND	ND ND	ND
	5/17/2001	1,182,360	ND	ND ND	ND	ND ND	ND	ND
	5/10/2001	1,166,850	NA	NA NA	NA NA	NA NA	NA NA	NA NA
	3/10/2001	1,100,030	NA NA	NA NA	NA NA	NA NA	NA NA	NA.
	5/5/2001	1,151,600	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
	3/3/2001	1,131,000	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
- · · · -			IVA	INA	192	11/2	ING	1 17 1
April	4/28/2001	1,135,690	NA	NA	NA	NA	NA	NA
, .p.,	4,20,200.	1,100,000	NA	NA	NA.	NA	NA	NA
	4/21/2001	1.113.570	NA	NA.	NA.	NA	NA	NA
		1,110,010	NA	NA	NA.	NA	NA	NA
	4/11/2001	1,082,700	NĀ	ND	ND	ND	ND	ND
		.,===,:==	ND	ND	ND	ND	ND	ND
	4/6/2001	1,065,540	NA	NA	NÄ	NA	NA	NA
		,	NA	NA	NA	NA	NA	NA
<u> </u>				100				
March	3/29/2001	1,036,330	NA	NA	NA NA	NA .	NA	NA NA
			NA	NA	NA.	NA	<u>NA</u>	<u>NA</u>
	0/21/202	1 200 272		1 332		vas re-starte		NA
	3/21/2001	1,036,070	NA	NA	NA	NA NA	NA NA	NA NA
		<u> </u>	NA	NA	NA halt spalage	NA NA		INA
	2/17/2001	1.025.100	N/A	I NA		ed on compr	NA NA	I NA
	3/17/2001	1,035,100	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
	3/13/2001	1,032,500	ND ND	ND ND	ND ND	ND	ND ND	ND ND
	3/13/2001	1,002,000	NA NA	NA NA	NA NA	NA NA	NA NA	NA NA
	3/2/2001	996.520	NA NA	NA NA	NA NA	NA.	NA NA	NA NA
	0/2/2001	1 300,020	NA.	NA NA	NA.	NA	NA	NA
	3/1/2002	NR	1		m re-started			
February	2/28/2002	. NR	Carbon Ch				vashed algae fro	m holding tank
				clea	ned 2000 lb	GAC, re-sta	rted system	,
L	0/40/0004	075 400	ļ	Complete	alaut darrin fa		no and alconing	<u> </u>
	2/10/2001	975,490	-	System:	snut down for T	mamtenand	ce and cleaning.	1
lanuary	1/29/2001	957,880	ND	ND	ND	ND	ND	ND
January	1/23/2001	337,000	ND ND	ND ND	ND	ND	ND	ND

Table 7
Total Volume of Water Treated, Historical Operational Data, and Effluent and GAC-1 Analytical Results
3609 International Boulevard, Oakland, California

	f	Meter	Lab Result	s For Effluent	1 and GAC-1	ļ	1	T
	i i	Reading	(concentra	tions in ug/L)		<u> </u>		
Month	Date	(gallons)	MtBE ²	TPH-g	Benzene	Toluene	Ethylbenzene	Total Xylenes
的感染物的	\$P\$1.4% 的人类		1. 1.4.1.4.	10.24		数据4000000000000000000000000000000000000	A Forest Page Sci. ()	enterna was
December	12/5/2000	883,000	ND	ND	ND	ND	ND	ND
			ND	ND	ND	ND	ND	ND
November	11/24/2000	NR	ND	ND	ND	ND	ND	ND
			ND	ND	ND	ND	ND	ND
	11/1/2000	842,000	ND	ND	ND	ND	ND	ND
	,	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ND	ND	ND	ND	ND	ND
			A CONTRACTOR	(* 17 J. J. J.	**************************************	P. 178 1 3 12	A PROPERTY OF A SECOND	A Esta a laterative de Esta
October	10/1/2000	809,000	ND	ND	ND	ND	ND	ND
			ND	ND	ND	ND	ND	ND
August	8/27/2000	781,000	ND	ND	ND	ND	ND	ND
raguer	8/24/2000		1		zer meter rep	laced at 77	5.000 gallons	
•		,		T	T		ĺ	
July	7/26/2000	726,000	ND	ND	ND ND	ND	ND	ND
	7/19/2000	718,000	ND	ND	ND	ND	ND	ND
	7/13/2000	712,000	ND	ND	ND	ND	ND	ND
	7/7/2000		ND	ND	ND	ND	ND	ND
Dirik artetahasa al	English California (1995)		And the second					asknistatis bili 2000
June	6/29/2000	700,000	ND	ND	ND _	ND	ND	ND
	6/21/2000		ND	ND	ND	ND	ND	ND
	6/16/2000		ND	ND	ND	ND	ND	ND
	6/10/2000	651,200	ND	ND	ND	ND	ND	ND
May	5/31/2000	629,000	ND	ND	ND	ND	ND	ND
	5/23/2000		ND	ND	ND	ND	ND	ND
	5/18/2000	570,000	ND	ND	ND	ND	ND	ND
	5/10/2000		ND	ND	ND	ND	ND	ND
April	4/30/2000	488.300	ND ND	ND ND	ND	ND	ND	ND ND
API II	4/18/2000		ND ND	ND ND	ND ND	ND	ND	0.51
	4/10/2000	400,000					n until April 29, 2	
	4/10/2000	440,200	ND	I ND	ND	ND	ND	ND
	4/4/2000		ND	ND	ND	ND	ND	ND
	4/2/2000			perfo	rmed a carbo	n change-o	ut on GAC-1	

Table 7
Total Volume of Water Treated, Historical Operational Data, and Effluent and GAC-1 Analytical Results
3609 International Boulevard, Oakland, California

		Meter	Lab Results	For Effluent	and GAC-1			
	1	Reading	(concentrati	ions in ug/L)		·		
Month	Date	(gallons)	MtBE 2	TPH-g	Benzene	Toluene	Ethylbenzene	Total Xylenes
				100 10 No. 20 1		1.7 17 5	CONTRACTOR	
March	3/31/2000			aced GAC-2 v	with a special	GAC design	ed for removal	of MtBE
	3/24/2000	388,000	ND	ND	ND	ND	ND	ND
	3/17/2000	357,100	ND	ND	ND	ND	ND	ND
	3/10/2000	329,000	ND	ND	ND	ND	ND	ND
	3/3/2000	300,000	tr	ansfer overhe	eated, repaire	d pump, res	tarted system 3	/6/00
]				
February	2/25/2000	274,000	ND	ND	ND	ND	ND	ND
	2/18/2000	233,000	ND	ND	ND	ND	ND	ND
	2/11/2000	190,000	ND	ND	ND	ND	ND	ND
	2/4/2000	160,800	ND	ND	ND	ND	ND	ND
January	1/28/2000	,	ND	ND	ND	ND	ND	ND
	1/21/2000		МD	ND	ND	ND	ND	ND
	1/17/2000	NR			l was replace			
							h 55 gallon GA0	
	1/14/2000	83,500	185	ND	NĎ	ND	ND	ND
	2 7 4 2 7 7 7 7 7							
December	12/23/1999	51,680	1486	NA	ND	МD	ND	ND
			ND	NA	ND	ND	ND	МĐ
	12/16/1999	30,450	963	NA NA	ND	ND	ND	ND
			ND	NA	ND	ND .	ND	ND
	12/9/1999	9,000	230	ND	ND	ND	ND	ND
	<u> </u>		Pumping be	gan on Dece	mber 6, 1999			

Notes:

- 1 Effluent is equivalent to PSP#1
- 2 MTBE was detected using EPA Method 8260B
- 3 Lab data as shown for Oct. 2002 is erroneous data. During lab analysis a high detection of 2-Butanone was detected in only the effluent sample. The influent sample for 2-Butanone was at only 20 ppb. This caused a high dilution factor causing a high non-detectable value. The high TPH-g value was misrepresentative due to the Y and Z flags.
- ND, <: Not Detected above laboratory reporting limits
- NA: Not Analyzed
- NR: Not recorded. Totalizer reading not recorded.
- Y: Sample exhibits fuel pattern which does not resemble standard
- Z: Sample exhibits unknown single peak or peaks

Table 8

Total Mass of Petroleum Hydrocarbons Removed by Vapor Extraction System
3609 International Boulevard, Oakland, California

**		PID (ppmv)	Flow Rate	Time Elapsed	Air Flow	Mass Removed 1
Date	Time	Influent	Effluent	(ft^3/min)	(Hours)	(Liters)	(Pounds)
7/24/2000	5:00	394	0	85	0	0	0.00
7/25/2000	5:15	38	2	95	24	3,914,096	1.01
7/26/2000	5:05	207	1	80 -	48	3,228,121	4.52
7/27/2000	9:00	160	5	92	64	2,500,944	2.71
7/28/2000	4:30	141	7	87	96	4,656,139	4.44
7/29/2000	1:30	225	8	85	117	3,032,734	4.62
7/30/2000	- 9:00	226	12	85	136	2,816,110	4.31
7/31/2000	3:00	141	5	85	166	4,332,478	4.13
8/1/2000	5:00	135	4	8 0	192	3,533,942	3.23
8/2/2000	4:00	80	4	80	215	3,126,180	1.69
8/3/2000	5:00	60	5	85	240	3,610,398	1.47
8/4/2000	3:00	57	4	85	262	3,177,150	1.23
8/5/2000	2:00	97	8	87	285	3,399,721	2.23
8/6/2000	12:00	114	8	80	307	2,990,259	2.31
8/7/2000	12:00	93	9	85	331	3,465,982	2.18
8/8/2000	4:30	152	10	85	360	4,115,854	4.23
8/10/2000	10:00	173	1	85	377	2,527,279	2.96
8/11/2000	7:00	78	4	70	410	3,924,715	2.07
8/12/2000	9:00	100	6.	70	424	1,665,031	1.13
8/13/2000	5:00	107	9	70	456	3,805,784	2.75
8/14/2000	12:30	122 ·	5	70	476	2,319,150	1.91
8/15/2000	6:00	103	12	70	505	3,508,457	2.44
8/16/2000	12:30	112	0 .	70	524	2,200,219	1.67
8/18/2000	9:00	90	0	75	568	5,670,449	3.45
8/21/2000	12:00	74	5	80	643	10,194,065	5.10
8/24/2000	12:00	68	13	80	712	9,378,540	4.31
8/27/2000	12:30	68.5	2	80	785	9,854,263	4.57
8/31/2000	1:30	52	6	80	882	13,184,324	4.64
9/4/2000	12:30	54	5	80	977	12,912,482	4.72
9/7/2000	12:00	55	3	80	1,048	9,718,342	3.62
9/11/2000	4:30 ²	141	0	80	1,149	13,660,047	13.03
9/14/2000	9:30	-56	5	80	1,214	8,834,856	3.35
9/18/2000	2:00	4 6	9.5	80	1,314	13,660,047	4.25
9/18/2000	4:30 ³	34	0	80	1,317	339,802	0.08
9/21/2000	4:30	43	1	80	1,389	9,786,302	2.85
9/25/2000	5:30	55	6	80	1,486	13,184,324	4.91
9/28/2000	9:00	47.5	7.5	80	1,550	8,766,896	2.82

Table 8

Total Mass of Petroleum Hydrocarbons Removed by Vapor Extraction System
3609 International Boulevard, Oakland, California

		PID (opmv)	Flow Rate	Time Elapsed	Air Flow	Mass Removed
Date	Time	Influent	Effluent	(ft^3/min)	(Hours)	(Liters)	(Pounds)
10/1/2000	1:00	38.5	6	80	1,626	10,329,986	2.69
10/5/2000	3:00⁴	28.5	3	80	1,724	13,320,245	2.57
10/5/2000	5:00	36	0	80	1,726	271,842	0.07
10/8/2000	3:00	28.5	3.	80 .	1,796	9,514,460	1.83
10/14/2000	3:00	24.5	2.5	80	1,940	19,572,604	3.24
10/17/2000	2:00	36.5	3.5	80	2,011	9,650,381	2.38
10/20/2000	8:30	18.5	3.5	-80	2,078	9,038,737	1.13
10/25/2000	2:00	38	3.7	80	2,203	17,058,068	4.39
10/29/2000	10:00	35	4	80	2,295	12,504,719	2.96
11/2/2000	4:00	30.5	4	80	2,397	13,863,928	2.86
11/7/2000	4:00	30	6	. 80	2,517	16,310,504	3.31
11/19/2000	12:00	92.7	5.5	80	2,801	38,601,525	24.20
11/24/2000	13:30	25	6.5	- 80	2,923	16,514,385	2.79
11/29/2000	15:00	14.5	3.5	80	3,044	16,514,385	1.62
12/4/2000	16:30	10,7	1	80	3,190	19,776,486	1.43
12/13/2000	15:30	24	3	80	3,405	29,222,986	4.74
12/28/2000	14:30	10	6	85	3,764	51,845,314	3.51
1/4/2001 ⁵	14:00	8.7	3.7	85	3,907	20,723,684	1.22
8/8/2001	15:00	217	0	85	3,907	0	0
9/6/2001	12:00	85	0	85	4,048	20,362,644	11.71
9/13/2001	16:00	186	8	85	4,220	24,839,538	31.26
9/18/2001	15:00	184	. 9	85	4,344	17,907,574	22.29
9/21/2001 ⁶				·	4,344	0	0
10/12/01 ⁷					4,344	0	0
10/23/2001	17:00	114	58	87	4,344	0	0
10/25/01 ⁴	15:00	133	0	85	4,390	6,643,132	5.98
10/29/2001 ⁸	13:20	569	0	85	4,485	13,647,304	52.53
11/7/2001	15:30	177	0	87	4,679	28,675,904	34.34
11/16/2001	15:00	117	Ó	87	4,894	31,853,904	25.21
11/21/01 ⁹	12:00	85	72	87	5,011	17,294,231	9.94
2/15/02 ¹⁰	16:30	49	0	80	5,011.5	67,960	0.02
2/16/2002	15:45	50	0	80	5,035	3,160,160	1.07
2/21/2002	16:00	37	4	80	5,155	16,344,484	4.09
2/27/2002	10:30	11	0	83	5,294	19,530,979	1.45
3/7/02 11	12:20	10		80	5,488	26,429,812	1.79
6/12/2002 ¹²	16:15	53	2	75	NA	NA	NA
6/17/2002	1 1:00	28	2	80	114.75	15,593,148	0.96
6/24/2002	11:20	24	3.1	80	168.33	22,866,400	1.21
7/5/2002	13:25	20	5	80	264.09	35,873,552	1.58
7/11/2002	15:30	26	8.0	80	144.09	19,572,752	1.12
7/23/2002	10:10	28	7.5	83	287.78	40,557,673	2.50
8/9/2002	12:20	7.5	0	80	408.09	55,434,983	0.91

Table 8 Total Mass of Petroleum Hydrocarbons Removed by Vapor Extraction System 3609 International Boulevard, Oakland, California

		PID (r	pmv)	Flow Rate	Time Elapsed	Air Flow	Mass Removed 1
Date	Time	influent	Effluent	(ft^3/min)	(Hours)	(Liters)	(Pounds)
8/15/2002 ¹¹	15:00	7.0	1	80	144.11	19,575,902	0.30
8/23/2002 ¹³	15:20	NA	NA	NA	NA	NA	NA
8/26/2002	11:15	14.0	2.0	80	71.83	9,757,387	0.30
9/11/2002	10:10	34.4	0	80	383.95	52,156,428	3.95
9/19/2002	10:55	8.8	1.1	80	192.75	26,183,160	0.51
9/25/2002	10:30	18.8	1.8	80	144.75	19,662,840	0.81
10/2/2002	8:10	17.1	2.5	80	168.75	22,923,000	0.86
10/9/2002		PID mai	function	80	168.75	22,923,000	NA
10/16/2002	13:45	17.0	4.0	80	168.75	22,923,000	0.86
10/24/2002		16.5	6.4	80	192.75	26,183,160	0.95
11/1/2002		21.1	0.0	85	192.75	27,819,608	1.29
11/6/2002	10:12	PID mal	function	87	NA		
11/7/2002		17:5	0.0	85	24.75	3,572,168	0.14
11/13/2002	11:30	15.0	0.0	85	144.75	20,891,768	0.69
11/22/2002	14:30	6.6	0.0	80	219.00	29,748,960	0.43
11/22/2002		sys	tem shut-do	wn due to rain	y season and low	influent readir	igs
5/9/2003	10:30	0.1	0.0	82	0	0	0
5/12/2003	10:30	0.4	0.3	85	72.00	10,391,760	0.01
5/21/2003	11:00	2.2	2.2	. 83	216.50	30,512,21 1	0.15
6/4/2003	10:30	2.5	0.1	82	335.50	46,713,678	0.26
6/10/2003	10:30	2.2	0.08	82	144.00	20,049,984	0.10
6/16/2003	12:15	2.1	0.07	82	146.25	20,363,265	0.09
6/24/2003	16:55	2.6	80.0	82	196.75	27,394,683	0.16
6/30/2003	11:30	2.2	0.1	82	138.50	19,284,186	0.09
7/16/2003	12:00	2.2	0.22	82	384.50	53,536,242	0.26
7/21/2003	10:50	2.1	0.21	82	119.00	16,569,084	80.0
7/28/2003	11:15	2.2	0.22	168.25	23,426,457	0.11	
		L	Total Ma	ss of Petrole	ım Hydrocarbor	s Removed =	410.22
			Av	erage Daily F	Removal Rate (p	ounds / day)=	0.37
The representati	ve molecular	weight of hydro	carbone was as	sumed to be 78 c	ram/mole and used		

The representative molecular weight of hydrocarbons was assumed to be 78 gram/mole and used

Table 8

Total Mass of Petroleum Hydrocarbons Removed by Vapor Extraction System 3609 International Boulevard, Oakland, California

			**								
ŀ		PID (p	opmv)	Flow Rate	Time Elapsed	Air Flow	Mass Removed 1				
Date	Time	Influent	Effluent	(ft^3/min)	(Hours)	(Liters)	(Pounds)				

the measured temperature of Vapor (36 °C) in converting ppm-v to ppm on mass basis.

² System accidentally shut down from main box, readings taken 30 minutes after startup.

³ GAC Replaced

⁴ GAC-1 removed, new GAC installed at effluent end

⁵ SVE System turned off for rainy season due to low influent concentrations

⁶ system down, hoses disconnected and GAC moved for replacement

⁷ system down for electrical repair

⁸ Carbon change-out of three drums, moved new effluent drum on 10/25/01 to GAC-1

system shut-down due to high effluent value

¹⁹ System re-started (since November 21, 2001), installed new 4-55 gallon vapor phase carbon vessels, repaired blower

¹¹ System was shut-down due to low influent reading

¹² System was restarted on 6/12/02


¹³ System was re-started but no readings were taken

FIGURES





Figure 1: Site vicinity map.




25

50

0

Figure 2: Site map showing location of groundwater monitoring wells, French drain, SVE system, and GAC system.








Figure 3: Groundwater elevation contour map in feet. July 24, 2003.






Figure 4: Contour map of dissolved Oxygen concentrations in the groundwater. July 24, 2003.






Figure 5: Contour map of Ferrous Iron concentrations in the groundwater. July 24, 2003.







Figure 6: Map of Nitrate concentrations in the groundwater. July 24, 2003.






approximate scale in feet
0 25 50

Figure 7: Contour map of Sulfate concentrations in the groundwater. July 24, 2003.






approximate scale in feet 0 25 50

Figure 8: Contour map of TPH-g concentrations in the groundwater. July 24, 2003.






approximate scale in feet 0 25 50

Figure 9: Contour map of Benzene concentrations in the groundwater. July 24, 2003.







approximate scale in fee


Figure 10: Contour map of MtBE (EPA Method 8260B) concentrations in the groundwater. July 24, 2003.














Figure 12. Cumulative mass of TPH-g and MtBE removed from groundwater since the installation of the treatment system.



APPENDIX A

Field Measurements of Physical, Chemical, and Biodegradation Parameters of Groundwater Samples



	Casing Diameter:		<u> </u>	inches	•		Addres	s:	3609 International Blvd.	
	Depth of Well:	_3	0	feet			,		Oakland, CA	
	Top of Casing Elevation:	40	2.11	feet						
	Depth to Groundwater:	12.		feet			Date:		7/24/03	
•	Groundwater Elevation:	27	67	feet			Sample	r:	Tony Perini	
ì	Water Column Height:	17.	56	feet					Roy Zarrin	
	Purged Volume:	/	/_	gallons						
				*						
J	Purging Method:			Bailer			Pump	•		
1	Sampling Method:			Bailer .	•		Pump		·-	
								,	•	
	Color:	Nο			Yes			Describe:	cloudy	
					163	_		Describe:		_
)	Sheen:	No	3		Yes			Describe:	-	
•	Odor:	No			Yes			Describe:	Beton and	
Ì									petro opor	-

Project No.:

2331

Field Measurements:

Well No.:

Time	Vol (gallons)	Temp (°C)	рH	E.C. (μS/cm)	D.O. (mg/L)	ORP (mV)	Turbidity (NTU)	NO3 ⁻¹ (mg/L)	\$O ₄ -2 (mg/L)	Fe ⁺² (mg/L)
3:19 PM	1.0	20.4	8.23	905	4.05	-104	124	(3)	(g. =)	(1.11g/ Z)
3:21 pm	3.0	20.6	7.96	892	0.0	-104				
3:23 pm	5.5	20.5	7.45	899		-95	1			
3:25 pm	7.0	20.4	7.17	858	0.34	-101	60.9			
3527 PM	9-0	203	7.14	820	0.26	-105	172			
3:28 Pm	11	20.3	7.16		0.43	-107	217			
3:30PM		80	.m81	دحا				0	0	3.30
										1



_							4				
	Casing Diameter:		4	inches			Addres	s:	3609 International Blvd.		
•	Depth of Well:	7	3/	feet					Oakland, CA		
	Top of Casing Elevation:	40	2.71	- feet							
	Depth to Groundwater:		23	- feet			Date:	•	7/24/03		
•	Groundwater Elevation:	28	.48	- feet			Sample	r:	Tony Perini		
	Water Column Height:	18.	77	feet			•		Roy Zarrin		
	Purged Volume:	1		_ _gallons					Troy modernie	,	
	· · · · · · · · · · · · · · · · · · ·										
ì										•	
	Purging Method:			Bailer			Pump	=			
	Sampling Method:			Bailer .	=		Pump	F=-7		-	
į	. 3	•		Daile,	-		rump				
,	0-1					_			11		
1	Color:	No			Yes			Describe:	misky		
	Sheen:	No			Yes			Describe:	·	-	
			_					pesonipe,			
l	Odor:	No			Yes			Describe:			
ı									•		

Project No.:

2331

Field Measurements:

Well No.:

Time	Vol (gallons)	Temp (°C)	pH	E.C. (μS/cm)	D.O. (mg/L)	ORP (mV)	Turbidity (NTU)	NO3 ⁻¹ (mg/L)	SO ₄ -2	Fe ⁺²
2:22 /M	1.0		7.68	613	4-81	124	985	(mg/L)	(mg/L)	(mg/L)
2:24 pm	3.5		7.40	621	0.0	/22				
2:26 PM	7.0	20.2	7.27	617	0.0	122	174		·	
2:28 PM	10	20.2	7.25	614	0.0	122.	177			
2:30 PM	12	20.2	7-24	615	0.0	122	56.2			
2:35 pm	sam	ples						0.0	23	0.0



	Well No.:	Δn	W-	3			Project	No.:	2331	
1	Casing Diameter:			inches			Addres	s:	3609 International Blvd.	
	Depth of Well:	31	<u>_5</u> 0	feet			·		Oakland, CA	
	Top of Casing Elevation:	4	0.91	feet		•		,		
l	Depth to Groundwater:	_12	:94	_feet			Date:		7/24/03	
,	Groundwater Elevation:	27	7.97	feet			Sample	r:	Tony Perini	
1	Water Column Height:	18	56	feet					Roy Zarrin	
	Purged Volume:		<u>'</u>	gallons			-		•	
)										
	Purging Method:			Bailer			Pump			
	Sampling Method:	•		Bailer ,			Pump			
•	Color:	No			Yes		•	Describe:	Black	_
	Sheen:	No			Yes		<u>-</u>	Describe:	rambou sheen	_
1	Odor:	No	□		Yes		•	Describe:	petro	_
	-									

Field Measurements:

Time	Vol	Temp	рН	E.C.	D.O.	ORP	Turbidity	NO3 ⁻¹	SO₄ ⁻²	Fe ⁺²
	(galions)	(°C)		(µS/cm)	(mg/L)	(mV)	(NTU)	(mg/L)	(mg/L)	(mg/L)
4:25 PM	1.0	20.2	7.18	918	3.48	-102	152		~	
4:27 pm	4.0	20.1	7.07	92/	0.0	-114	760			
4:29 pm	6.0	20.1	7.07	919	0.0	-120	16.0			
4:31 PM	8.0	20.2	7.09	915	0.0	-125	43.5			
4:33PM	11		7.09		0.0	-128	52.3			33
4:35 PM		క,	amp	les	ep			0.0	် စ	3.3
·										



				-				2001	
Ì	Casing Diameter:		2_	inches		Address	5:	3609 International Blvd.	
•	Depth of Weil:	_2	6	feet				Oakland, CA	
	Top of Casing Elevation:	40	0.01	feet		,			
ĺ	Depth to Groundwater:	/2.	44	feet		Date:	•	7/24/03	
	Groundwater Elevation:	27.	57	feet		Sample	r: .	Tony Perini	
	Water Column Height:	13.5		feet		,		Roy Zarrin	
ì	Purged Volume:	7.		gallons				To a second	
•									
	Purging Method:			Bailer		Pump	=		
Ì	Sampling Method:			Bailer .		Pump			
J B	Color:	No			Yes 🗷	•	Describe:	darly	
	Sheen:	No			Yes □		Describe:	-	_
1	Odor:	No			Yes □		Describe:		

Project No.:

2331

Field Measurements:

Well No.:

Time	Vol (gallons)	Temp (°C)	рH	E.C. (μS/cm)	D.O. (mg/L)	ORP (mV)	Turbidity (NTU)	NO3 ⁻¹ (mg/L)	SO ₄ ⁻² (mg/L)	Fe ⁺²
1:25 PM	1.0		7.73		4.45	124	929	(mg/L/	(mg/L/	(mg/L)
1:26 PM	3.0		7.39		0.0	127	252			
	5.5	19.30	7.28	571	0.0	128	168			
1:29 PM	7.5	19.20	7.24	569	0.0	12.8	183			
1:35 PM		. •	Sam	Ples	<u></u>			4/8	8	0.0
	<u></u>							0.0		
<u> </u>										



•
•

Time	Vol	Temp	рН	E.C.	D.O.	ORP	Turbidity	NO3 ⁻¹	SO ₄ -2	Fe ⁺²
	(gallons)	(°C)		(μS/cm)	(mg/L)	(mV)	(NTU)	(mg/L)	(mg/L)	(mg/L)
11:54 AM	0.5	20.8	7.79	7/3	6.94	38	152		-	
11:56 AM	2.0	20.9	7.40	698	0.0	29	77			
11:58 Am	5.0	20.7	7.27	704	0.0	-20	273			
12 PM	7.5	20.7	7.26	700	0.0	-39	27.4			
12:05 PM	San	uples	•					0.0	30	0.25
	<u> </u>									



feet feet feet feet feet feet feet gellons feet gallons		Project Address Date: Sample	ss:	2331 3609 International Blvd. Oakland, CA 7/24/03 Tony Perini Roy Zarrin
feet feet feet feet feet gellons		Date: Sample		Oakland, CA 7/24/03 Tony Perini
feet feet feet gallons		Sample	er:	7/24/03 Tony Perini
feet feet gallons		Sample	er:	Tony Perini
feet gallons		Sample	er:	Tony Perini
gallons				
gallons	0	Pump	•	,
Bailer		Pump	•	
Bailer		Pump	•	
Bailer .	=	Pump		
		-		
1	Yes 🗷		Describe:	Black
1.	Yes 🗹	•	Describe:	-
	Yes □		Describe:	
ا	•	Yes 🗹	Yes 🗹	Yes Describe:

	Time	Vol	Temp	рН	E.C.	D.O.	ORP	Turbidity	NO3 ⁻¹	SO ₄ -2	Fe ⁺²
-		(gallons)	(°C)		(μS/cm)	(mg/L)	(mV)	(NTU)	(mg/L)	(mg/L)	(mg/L)
L	3:53 pm	1.0	20.0	7-24	835	3-25	-59	628			
	3:55 PM	3-0	20-3	7.09	716	0.31	-62	2/4			
	3:56 PM	5.0	19-9	7.07	7/1	0.10	-65	220		·	
	3:58 PM	8.5	19.7	7.08	703	0.03		260			· · · · · · · · · · · · · · · · · · ·
-	4 pm	Sav	up bea						0.0	٥.٥	3.3
\downarrow						,					
L				· ·					,		



	Well No.:	Mo	W-	?		Project	No.;	2331
Ì	Casing Diameter:		2	inches		Addres	s:	3609 International Blvd.
j	Depth of Well:	2	6	feet				Oakland, CA
_	Top of Casing Elevation:	39.	94	feet			_	
	Depth to Groundwater:		72	- feet		Date:	·	7/24/03
,	Groundwater Elevation:	28.	22	- feet		Sample	er:	Tony Perini
	Water Column Height:	14.	28	- feet				Roy Zarrin
	Purged Volume:			gallons				,
•				. •				•
1								
J	Purging Method:			Bailer		Pump	\times	
1	Sampling Method:			Bailer .		Pump		
j								
•	Color:	No			Yes		Describe:	
	Channe		_					
•	Sheen:	No	ď		Yes		Describe:	
Ì	Odor:	No	ď		Yes		Describe:	
						•		
				4				
	Ciald Management.							

Field Measurements

Time	Vol (gallons)	Temp (°C)	pН	E.C. (μS/cm)	D.O. (mg/L)	ORP (mV)	Turbidity (NTU)	NO3 ⁻¹ (mg/L)	SO ₄ -2 (mg/L)	Fe ⁺² (mg/L)
12:32	1		7.64	35.3			28.8	, , ,	, ,	(
12:34	2	22.1	7.51	379	2.60	-38	422			 -
12:37	3	21.6	7.5Z	443	i _ · · · · · · ·	-77	91.8			·
12:40			mp					0.0	2.0	0.61
		<u> </u>								
				ļ]

Jotes obstruction of well not samples Well need to be replaced.



MW-8

inches

feet

feet

	Depth to Groundwater: Groundwater Elevation: Water Column Height: Purged Volume:	11. 27. 15. 5.		feet feet feet gallons		Date: Sample	r:	7/24/03 Tony Perini Roy Zarrin
	Purging Method: Sampling Method:			Bailer Bailer .		Pump Pump		
ì	Color:	No	0		Yes □		Describe:	Black
	Sheen:	No			Yes 🗷	<i>'</i> ,	Describe:	
1	Odor:	No			Yes ™		Describe:	slight odor

Project No.:

Address;

2331

Oakland, CA

3609 International Blvd.

Field Measurements:

Well No.:

Casing Diameter:

Top of Casing Elevation: 39.38

Depth of Well:

Time	Voi	Temp	рH	E.C.	D.O.	ORP	Turbidity	NO3 ⁻¹	SO ₄ -2	Fe ⁺²
	(gallons)	(°C)		(μS/cm)	(mg/L)	(mV)	(NTU)	(mg/L)	(mg/L)	(mg/L)
2:51	/	19.9	7.42	605	5.13	- 88	631			
2:53	2	20.0	7.23	622	0.18	-108	641			
2:55	4	20.0	7.20	660	0.0	-124	636			
2:56	5.5	19.8	7.20	675	0.0	-129	610		· •	
3:00		5	amp	100				0	0	1.88
						<u> </u>				
·										
									· · · · · · · · · · · · · · · · · · ·	



Casing Diameter: Depth of Well: Depth of Well: Depth to Groundwater: Depth to Goldand, CA Depth to Galland, CA Depth	· · · · · · · · · · · · · · · · · · ·			-			•	*				
Depth of Well: Top of Casing Elevation: Depth to Groundwater: Groundwater Elevation: Water Column Height: Purged Volume: Date: Topy Perini Roy Zarrin Pump Pump Sampling Method: Bailer Pump Color: No Yes Describe: Color: No Yes Describe: Color: No Describe: Color: Color: No Describe: Color: Color: No Describe: Color: C	Casing Diameter:		2_	_			Addres	s:	3609 International Blvd.			
Top of Casing Elevation: 36.71 feet Depth to Groundwater: 10.76 feet Groundwater Elevation: 25.75 feet Water Column Height: 12.64 feet Purged Volume: 5.5 gallons Purging Method: Bailer □ Pump ■ Sampling Method: Bailer ■ Pump □ Color: No □ Yes □ Describe: Cloudy Sheen: No □ Yes □ Describe: □	Depth of Well:	23	.40	feet				,				
Groundwater Elevation: Water Column Height: Purged Volume: Bailer □ Pump ■ Sampling Method: Bailer □ Pump □ Color: No □ Yes □ Describe: Odor: Odor: Odor: Sampler: Tony Perini Roy Zarrin Pump □ Roy Zarrin Pump □ Describe: Cloudy Describe:	Top of Casing Elevation:	_3	6.71	feet					, ,			
Groundwater Elevation: Water Column Height: Purged Volume: Bailer □ Pump ■ Sampling Method: Bailer □ Pump □ Color: No □ Yes □ Describe: Odor: Odor: Odor: Sampler: Tony Perini Roy Zarrin Pump □ Roy Zarrin Pump □ Describe: Cloudy Describe:	Depth to Groundwater:	10	.76	feet			Date:		7/24/03			,
Water Column Height:	Groundwater Elevation:	25.	95	feet	•		Sample	r:				
Purging Method: Sampling Method: Bailer □ Pump □ Sampling Method: Bailer □ Pump □ Color: No □ Yes □ Describe: Color: Other:	Water Column Height:	12	.64	feet			•		-			
Sampling Method: Bailer Pump Color: No Yes Describe: Cloudy Sheen: No Yes Describe:	Purged Volume:	5	.5	- galions						,		
Sampling Method: Bailer Pump Color: No Yes Describe: Cloudy Sheen: No Yes Describe:	•			_								
Sampling Method: Bailer Pump Color: No Yes Describe: Cloudy Sheen: No Yes Describe:	•									•		
Sampling Method: Bailer ■ Pump □ Color: No □ Yes ☞ Describe: Cloudy Sheen: No ☞ Yes □ Describe:	Purging Method:			Bailer		•	Pump	M				
Color: No Describe: Cloudy Sheen: No Yes Describe:	Compline Methed.	•					-			-		
Sheen: No 🗹 Yes 🗆 Describe:	sampung wetnoo:			Bailer.			Pump					
Sheen: No 🗹 Yes 🗆 Describe:											•	
Odov	Color:	No			Yes			Describe:	cloudy			
Odov	Sheen	Nia	136			_						
Odor: No 🗗 Yes 🗆 Describe:	Oliccii.	INO	<u>-1</u>		Yes	i)		Describe:		· 	<u> </u>	
	Odor:	No	┏∕		Yes			Describe:			•	
				•								

Project No.:

2331

Field Measurements:

Well No.:

Time	Vol	Temp	рĦ	E.C.	D.O.	ORP	Turbidity	NO3 ⁻¹	SO ₄ -2	Fe ⁺²
	(gallons)	(°C)	<u> </u>	(μS/cm)	(mg/L)	(mV)	(NTU)	(mg/L)	(mg/L)	(mg/L)
10:39 AM	0.5	20.0	8.09	678	7.0	-35	320	<u> </u>		
10:41 Am	2.0	19.9	7.52	662	0.10	-16	66.4			
10:42 Am	4.0	19.8	7.41	658	0.0	-4	41.9			
10:43 AM	5.5	19.8	7.35	658	0.0	1	40.4			
10:45 AM			Son	Me				0,0	,	0.0
									1.0	er e
	, ,							· · · · · · · · · · · · · · · · · · ·		



	Well No.: Casing Diameter: Depth of Well: Top of Casing Elevation: Depth to Groundwater: Groundwater Elevation: Water Column Height: Purged Volume:	145 12.	3 0 - 10	feet			Project I Address Date: Sampler	:	2331 3609 International Blvd. Oakland, CA 7/24/03 Tony Perini Roy Zarrin	
]	Purging Method: Sampling Method: Color:	No		Bailer Bailer	□ Ves □	ı	Pump Pump	■ Describe:		•
	Sheen: Odor:	No No			Yes 🗅	I		Describe:		-

Field Measurements:

Time	Vol (gallons)	Temp (°C)	pН	E.C. (μS/cm)	D.O. (mg/L)	ORP (mV)	Turbidity (NTU)	NO3 ⁻¹ (mg/L)	SO ₄ ⁻² (mg/L)	Fe ⁺² (mg/L)
10:09 Am	1.0	19.10	9.93	603	4.64	58	67.9			
10:10 Am	2.0	18.90	8.12	614	0,10	56	43.6			
10:12 AM	3.0	18.90	7.62	6Z 2	0.0	8	33.4			
10:14 AM 10:15 AM	5.0	18.80	7.42	62/	0.0	-35	26.1			
10:15 AM	54	mp le	۵					0.0	3.0	0,0

well not survey due to obstruction in area survey and casing, unable to set up survey equipment



Well No.:	MU	v-17	2		Project I	No.:	2331	·
Casing Diameter:		Ч	inches		Address	:	3609 International Blvd.	
Depth of Well:					,	. *:	Oakland, CA	
Top of Casing Elevation:	<u>36.</u>	84	feet					
Depth to Groundwater:	11. 4		feet		Date:	•	7/24/03	`
Groundwater Elevation:	<u> 25.</u>		feet		Sampler	:	Tony Perini	٠
Water Column Height:	18.	56	feet				Roy Zarrin	
Purged Volume:		<u> </u>	gallons					
Purging Method:			Bailer		Pump			
Sampling Method:			Bailer .	•	Pump	D		
Colors	No			Yes		Describe:		
Sheen:	No			Yes		Describe:		
Odor:	Νo			Yes		Describe:		

Field Measurements:

Time	Vol (galions)	Temp (°C)	рН	E,C. (μS/cm)	D.O. (mg/L)	ORP (mV)	Turbidity (NTU)	NO3 ⁻¹ (mg/L)	SO ₄ -2 (mg/L)	Fe ⁺² (mg/L)
11:09 Am	1.0	19.8	7.67		6.12		81.6			(3)
11:11 Am	4.0	19.6	7-36	665	0-0	-106	22.2	¥		
11:13. AM	6.0	19.6	7.33	66 4	0.0	-106	20.8		,	
# 11:15 Am	8.0	19.9	7.32	658	1.51	-102	27.3			
11:30 AM	+011	19.7	7. 29	659	0.0	-98	19			
11:35 AM	5a	my/e	0					0.0	0.0	1.13
										,

10ks: changes bathey on 4-22 meke

Appendix B

Chain of Custody Form and Laboratory Report of Third Quarter 2003 Monitoring Event



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (510) 486-0900

ANALYTICAL REPORT

Prepared for:

SOMA Environmental Engineering Inc. 2680 Bishop Dr. Suite 203 San Ramon, CA 94583

Date: 04-AUG-03 Lab Job Number: 166533 Project ID: 2331

Location: 3609 Int'l Blvd., Oakland

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

Project Manager

Reviewed by:

Operations Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of ____

CHAIN OF CUSTODY

Page ____of ___

Curtis & Tompkins, Ltd.

Analytical Laboratory Since 1878

166533

Analyses

	2323 Fifth Street Berkeley, CA 94710 (510)486-0900 Phone	,				NY PERN		/_/	409	,				ļ								
Projec	(510)486-0532 Fax t No: 2331	Samp Repoi				Tony Perir		<i>=</i>	7721					GCMS								
Projec	t Name:3609 Internation	al Bivd, Oakland Comp	an	y :	,	SOMA Envir	oni	nen	tal			ָ ֪֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖	- 19	8260				:	}			
Turna	round Time: Standard	Telep	họi	ne:		925-244-660	00					2021 6										
		Fax:	_			925-244-660						μ	֓֞֞֞֜֞֜֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֜֜֜֓֓֓֓֡֓֜֜֡֓֓֡֓֡֓֡֓֡֓֡֓֡֓֡֓֡֓֡֓֡֓֡֡֡֓֜֡֡֓֡֡֓	Confirmation								
		,	l V	la	trix			Pres	serva	itive	8015	į	<u> </u>	ξĺ								
Lab No.	Sample ID.	Sampling Date Time	Soil	Water	Waste	# of Containers	달	H ₂ SO ₄	HNO3	OE	TPHa 8	BTEX -		MIBE								
-1	MW-1	7/24/03 3:30 AM	П	1		3-VOAs	1				7	<u> </u>	<u> </u>									
	MW-2	2:35 PM												ı								
-3	MW-3	4:35PM		\prod			Ŀ							\coprod								
-٤	MW-4	1:35 PM									Ц	L	Ц	Ц								
	MW-5	12:05PM					Ц				Ш	Ŀ	Ш	Ц	<u>.</u>							
- 6	MW-6	4 PM		Ш			Ш					1	Ш	Ш			Ш					
-7	MW-7	12:40 PW					Ш				Ш		Ш	Ц								
-8	MW-8	3 pm	Ш	Ţ		4	1	<u> </u>		y	<u>4</u>	د ،	<u>'</u>	V		<u> </u>	Ш					
	MM O		Ĺ								-	\perp	4	_					_	\dashv		
-9	MW-10	T 10:45 PM		I	Ш	<u> </u>	1				丁	<u>- -</u>	<u>d</u> .	ᅱ		_			_	\bot		
	MW-11	10:15 84			Ш		Ц	<u> </u>			Ш	╀	Ц	Ц		ļ				_		
-1(MW-12	J- 11:35 PM	<u> </u>	7		*	4	<u> </u>		1	1	<u> </u>	叮	4		<u> </u>		<u> </u>	\dashv	_		
							<u>L</u> _	<u>L</u>			$-\!$		丄	\perp		<u>L.</u> .				丄		
Notes	EDF OUTPUT REQU	IRED	•			WISHED BY:					R	EC	E۱۱	/EC	BY:			_,	,			
	6rub Sample					Perni				// <i>o3</i> DATE/TI	/E	1	X	B	108	1/h	7/]	43	Q _I	PIN	/TIME
	Re Cold	eceived A On Jos Ambient Da Intact								DATE/TII	1E									[DATE	/TIME
	<u> </u>	- (DATE/TI	ΛE									£	DATE	E/TIME



	Curtis &	Tompkins Labor	atories Anal	lytical Report
Lab #: Client: Project#:	166533 SOMA Environmental 2331	Engineering Inc.	Location: Prep:	3609 Int'l Blvd., Oakland EPA 5030B
Matrix: Units:	Water ug/L		Sampled: Received:	07/24/03 07/24/03

Field ID: Type: Lab ID:

MW-1 SAMPLE 166533-001 Diln Fac: Batch#: Analyzed:

100.0 83197 07/28/03

Analyte	Result	RL	Analysis
Gasoline C7-C12	36,000	5,000	8015B
MTBE	23,000	200	EPA 8021B
Benzene	4,800	50	EPA 8021B
Toluene	1,800	50	EPA 8021B
Ethvlbenzene	1,300	50	EPA 8021B
m,p-Xylenes	4,200	50	EPA 8021B
o-Xylene	1,400	50	EPA 8021B

Surrogate	*REC	Limits	Analysis
Trifluorotoluene (FID)	114	57-150	8015B
Bromofluorobenzene (FID)	119	65-144	8015B
Trifluorotoluene (PID)	106	54-149	EPA 8021B
Bromofluorobenzene (PID)	118	58-143	EPA 8021B

Field ID:

MW-2

1.000 83153 07/25/03 Diln Fac: Batch#: SAMPLE 166533-002 Type: Lab ID: Analyzed:

Analyte	Result	RL	Analysis
Gasoline C7-C12	220	50	8015B
MTBE	ND	2.0	EPA 8021B
Benzene	3.9	0.50	EPA 8021B
Toluene	4.3	0.50	EPA 8021B
Ethylbenzene	7.0	0.50	EPA 8021B
m,p-Xylenes	11	0.50	EPA 8021B
o-Xvlene	3.5	0.50	EPA 8021B

	Surrogate	%REC	Limits	Analysis
ı	Trifluorotoluene (FID)	109	57-150	8015B
	Bromofluorobenzene (FID)	111	65-144	8015B
- 1	Trifluorotoluene (PID)	102	54-149	EPA 8021B
	Bromofluorobenzene (PID)	112	58-143	EPA 8021B



	Curtis &	Tompkins Labor	atories Analyt	
Lab #: Client: Project#:	166533 SOMA Environmental	Engineering Inc.	Location: Prep:	3609 Int'l Blvd., Oakland EPA 5030B
Matrix: Units:	Water ug/L		Sampled: Received:	07/24/03 07/24/03

Field ID: Type: Lab ID:

MW-3 SAMPLE 166533-003 Diln Fac: Batch#: Analyzed: 100.0 83197 07/28/03

Result	RL	Analysis	
31,000	5,000	8015B	
15,000	200		
4.700	50	EPA 8021B	
		EPA 8021B	
	31,000	31,000 5,000 15,000 200 4,700 50 990 50 1,400 50 4,000 50	31,000 5,000 8015B 15,000 200 EPA 8021B 4,700 50 EPA 8021B 990 50 EPA 8021B 1,400 50 EPA 8021B 4,000 50 EPA 8021B

Surrogate	*REC	Limits	Analysis
Trifluorotoluene (FID)	105	57-150	8015B
Bromofluorobenzene (FID)	116	65-144	8015B
Trifluorotoluene (PID)	105	54-149	EPA 8021B
Bromofluorobenzene (PID)	114	58-143	EPA 8021B

Field ID: Type: Lab ID:

MW-4 SAMPLE 166533-004 Diln Fac: Batch#: Analyzed: 1.000 83153 07/25/03

Analyte	Result	RL	Analysis
Gasoline C7-C12	ND	50	8015B
MTBE	2.3	2.0	EPA 8021B
Benzene	1.0	0.50	EPA 8021B
Toluene	ND	0.50	EPA 8021B
Ethylbenzene	ND	0.50	EPA 8021B
m,p-Xylenes	ND	0.50	EPA 8021B
o-Xylene	ND	0.50	EPA 8021B

Surrogate	REC	Limits	Analysis
Trifluorotoluene (FID)	104	57-150	8015B
Bromofluorobenzene (FID)	113	65-144	8015B
Trifluorotoluene (PID)	105	54-149	EPA 8021B
Bromofluorobenzene (PID)	115	58-143	EPA 8021B

C= Presence confirmed, but RPD between columns exceeds 40% ND= Not Detected RL= Reporting Limit Page 2 of 7



Curtis & Tompkins Laboratories Analytical Report 3609 Int'l Blvd., Oakland 166533 Location: Lab #: EPA 5030B Client: SOMA Environmental Engineering Inc. Prep: Project# 07/24/03 07/24/03 Sampled: Matrix: Water Received: Units: uq/L

Field ID: Type: Lab ID: MW-5 SAMPLE 166533-005 Diln Fac: Batch#: Analyzed: 1.000 83153 07/25/03

Analysis RL Analyte Result 8015B Gasoline C7-C12 300 50 EPA 8021B ND 2.0 MTBE 0.50 EPA 8021B ND Benzene 1.9 C 0.50 **EPA 8021B** Toluene EPA 8021B EPA 8021B 0.50 Ethylbenzene 0.76 m,p-Xylenes o-Xylene 0.50 ND ND 0.50 EPA 8021B

Surrogate	*REC	Limits	Analysis
Trifluorotoluene (FID)	117	57-150	8015B
Bromofluorobenzene (FID)	114	65-144	8015B
Trifluorotoluene (PID)	114	54-149	EPA 8021B
Bromofluorobenzene (PID)	111	58-143	EPA 8021B

Field ID: Type: Lab ID: MW-6 SAMPLE 166533-006 Diln Fac: Batch#: Analyzed: 100.0 83197 07/28/03

Analyte	Result	RL	Analysis
Gasoline C7-C12	29,000	5,000	8015B
MTBE	ND	200	EPA 8021B
Benzene	1,600	50	EPA 8021B
Toluene	520	50	EPA 8021B
Ethylbenzene	1,500	50	EPA 8021B
m,p-Xylenes	3,400	50	EPA 8021B
o-Xylene	1,000	50	EPA 8021B

,	Surrogate	%REC	Limits	Analysis
į	Trifluorotoluene (FID)	104	57-150	8015B
	Bromofluorobenzene (FID)	118	65-144	8015B
	Trifluorotoluene (PID)	105	54-149	EPA 8021B
3	Bromofluorobenzene (PID)	116	58-143	EPA 8021B



	Curtis &	Tompkins Labor	atories Ana	lytical Report
	166533 SOMA Environmental	Engineering Inc.	Location: Prep:	3609 Int'l Blvd., Oakland EPA 5030B
Project#: Matrix: Units:	2331 Water ug/L		Sampled: Received:	07/24/03 07/24/03

Field ID: Type: Lab ID:

MW-7 SAMPLE 166533-007 Diln Fac: Batch#: Analyzed: 1.000 83153 07/25/03

Analyte	Result	RIL	<u>Analysis</u>
Gasoline C7-C12	230	50	8015B EPA 8021B
MTBE	8.2 ND	2.0 0.50	EPA 8021B
Benzene Toluene	1.3 C	0.50	EPA 8021B
Ethylbenzene	ND 0.63	0.50 0.50	EPA 8021B EPA 8021B
m,p-Xylenes o-Xylene	ND	0.50	EPA 8021B

1	Surrogate	%REC	Limits	Analysis
ij	Trifluorotoluene (FID)	117	57-150	8015B
	Bromofluorobenzene (FID)	119	65-144	8015B
	Trifluorotoluene (PID)	115	54-149	EPA 8021B
li	Bromofluorobenzene (PID)	115	<u> 58-143</u>	EPA 8021B

Field ID: Type: Lab ID: MW-8 SAMPLE 166533-008 Diln Fac: Batch#: Analyzed: 10.00 83197 07/28/03

Analyte	Resu :	RL	Analysis 8015B	
Gasoline C7-C12	12,000 830	500 20	EPA 8021B	
MTBE Benzene	460	5.0	EPA 8021B	
Toluene	54 C	5.0	EPA 8021B EPA 8021B	
Ethylbenzene	910 410	5.0 5.0	EPA 8021B	
m,p-Xylenes o-Xylene	`	5.0	EPA 8021B	

Surrogate	*REC	Limits	Analysis
Trifluorotoluene (FID)	134	57-150	8015B
Bromofluorobenzene (FID) Trifluorotoluene (PID)	125 120	65-144 54-149	8015B EPA 8021B
Bromofluorobenzene (PID)	121	58-143	EPA 8021B



Curtis & Tompkins Laboratories Analytical Report 3609 Int'l Blvd., Oakland Location: 166533 Lab #: EPA 5030B Prep: Client: SOMA Environmental Engineering Inc. Project#: 2331 07/24/03 Sampled: Water Matrix: 07/24/03 Received: Units: uq/L

Field ID: Type: Lab ID:

MW-10 SAMPLE 166533-009 Diln Fac: Batch#: Analyzed: 1.000 83153 07/25/03

Aralyte	Result	RL	Analysis
Gasoline C7-C12	750	50	8015B
MTBE	110	2.0	EPA 8021B
Benzene	160	0.50	EPA 8021B
Toluene	4.0	0.50	EPA 8021B
Ethylbenzene	58	0.50	EPA 8021B
m,p-Xylenes	6.1	0.50	EPA 8021B
o-Xylene	0.56_C	0.50	EPA 8021B

Surrogate	*REC	Limits	Analysis
Trifluorotoluene (FID)	124	57-150	8015B
Bromofluorobenzene (FID)	108	65-144	8015B
Trifluorotoluene (PID)	114	54-149	EPA 8021B
Bromofluorobenzene (PID)	106	<u> 58-143</u>	EPA 8021B

Field ID:

MW-11 SAMPLE Diln Fac:

1.000 83153 07/25/03

Type: Lab ID: 166533-010 Batch#: Analyzed:

Analysis Result RL Analyte Gasoline C7-C12 50 8015B 340 2.0 EPA 8021B ND MTBE 0.50 EPA 8021B 19 C Benzene EPA 8021B 3.2 0.50 Toluene EPA 8021B 0.58 0.50 Ethylbenzene 0.50 EPA 8021B m,p-Xylenes o-Xylene 0.89 EPA 8021B 0.50 ND

, 	Surrogate	%REC	Limits	Anelysis
	Trifluorotoluene (FID)	143	57-150	8015B
1	Bromofluorobenzene (FID)	118	65~144	8015B
	Trifluorotoluene (PID)	130	54-149	EPA 8021B
'	Bromofluorobenzene (PID)	117	58-143	EPA 8021B

C= Presence confirmed, but RPD between columns exceeds 40% ND= Not Detected RL= Reporting Limit Page 5 of 7



	Curtis &	Tompkins Labor	atories Ana	lytical Report
Lab #: Client: Project#:	166533 SOMA Environmental 2331	Engineering Inc.	Location: Prep:	3609 Int'l Blvd., Oakland EPA 5030B
Matrix: Units:	Water ug/L		Sampled: Received:	07/24/03 07/24/03

Field ID: Type: Lab ID: MW-12 SAMPLE 166533-011 Diln Fac: Batch#: Analyzed: 1.000 83153 07/25/03

Result		RL	Analysis	
2,200		50	8015B	
		2.0	EPA 8021B	
	C	0.50	EPA 8021B	
		0.50	EPA 8021B	
	•		EPA 8021B	
4	1			
	2,200 80 32 16 ND	2,200 80 32 C 16 C	2,200 50 80 2.0 32 C 0.50 16 C 0.50 ND 0.50 4.1 0.50	2,200 50 8015B 80 2.0 EPA 8021B 32 C 0.50 EPA 8021B 16 C 0.50 EPA 8021B ND 0.50 EPA 8021B 4.1 0.50 EPA 8021B

Surrogate	*REC	Limits	Anal	Y818
Trifluorotoluene (FID)	90	57-150	B015B	
Bromofluorobenzene (FID)	139	65-144	8015B	•
Trifluorotoluene (PID)	148	54-149	EPA 8021B	·
Bromofluorobenzene (PID)	121	58-143	EPA 8021B	

Type: Lab ID: Diln Fac: BLANK QC220167 1.000 Batch#: Analyzed: 83153 07/25/03

Anglyte	Regult	RL	Analysis
Gasoline C7-C12	ND	50	8015B
MTBE	ND	2.0	EPA 8021B
Benzene	ND	0.50	EPA 8021B
Toluene	ND	0.50	EPA 8021B
Ethylbenzene	ND	0.50	EPA 8021B
m,p-Xylenes	ND	0.50	EPA 8021B
o-Xvlene	ND	0.50	EPA 8021B

Surrogate	*REC	Limits	Analyels
Trifluorotoluene (FID)	98	57-150	8015B
Bromofluorobenzene (FID)	101	65-144	8015B
Trifluorotoluene (PID)	101	54-149	EPA 8021B
Bromofluorobenzene (PID)	103_	58-143	EPA 8021B

C= Presence confirmed, but RPD between columns exceeds 40% ND= Not Detected RL= Reporting Limit Page 6 of 7



	Curtis &	Tompkins Labor	ratories Ana	lytical Report
Lab #: Client: Project#:	166533 SOMA Environmental 2331	Engineering Inc.	Location: Prep:	3609 Int'l Blvd., Oakland EPA 5030B
Matrix:	Water		Sampled:	07/24/03
Units:	uq/L		Received:	07/24/03

Type: Lab ID: Diln Fac: BLANK QC220381 1.000 Batch#: Analyzed: 83197 07/28/03

Analyte	Result	RL	Analysis	
Gasoline C7-C12	ND	50	8015B	
MTBE	ND	2.0	EPA 8021B	
Benzene	ND	0.50	EPA 8021B	
Toluene	ND	0.50	EPA 8021B	
Ethylbenzene	ИD	0.50	EPA 8021B	
m,p-Xylenes	ND	0.50	EPA 8021B	
o-Xylene	ND	0.50	EPA 8021B	

Surrogate	₹RBC	Limits	Analysis
Trifluorotoluene (FID)	99	57-150	8015B
Bromofluorobenzene (FID)	111	65-144	8015B
Trifluorotoluene (PID)	97	54-149	EPA 8021B
Bromofluorobenzene (PID)	111	58-143	EPA 8021B

Sample Name : 166533-001,83197

: G:\GC05\DATA\209G005.raw FileName

TVHBTXE Method Start Time : 0.00 min

24.73

Plot Offset: 5 mV Scale Factor: 1.0

End Time : 25.00 min

Sample #: bl


Page 1 of 1

Date: 7/28/03 03:49 PM Time of Injection: 7/28/03 03:23 PM

High Point : 195.30 mV Low Point : 4.96 mV

Plot Scale: 190.3 mV

MW-1



Sample Name : 166533-002,83153

FileName : G:\GC05\DATA\206G008.raw

Start Time : 0.00 min

: TVHBTXE End Time : 25.00 min

Scale Factor: 1.0 Plot Offset: 7 mV Sample #: al

Page 1 of 1


Date: 7/28/03 09:52 AM
Time of Injection: 7/25/03 03:22 PM

High Point : 156.41 mV

Low Point : 6.86 mV Plot Scale: 149.6 mV

MW-2

Response [mV]



Page 1 of 1 Sample #: b1 Sample Name : 166533-003,83197 Date : 7/29/03 09:52 AM FileName : G:\GC05\DATA\209G006.raw Time of Injection: 7/28/03 03:57 PM Method : TVHBTXE Low Point : 7.37 mV High Point : 145.84 mV Start Time : 0.00 min End Time : 25.00 min Plot Scale: 138.5 mV Scale Factor: 1.0 Plot Offset: 7 mV MW-3 Response [mV] 0.79 1.06 1.52 - 1.64 1.74 C-6 $\frac{2}{2300}$ -2.51 ≥<u>3.5</u>8 4.04 C-7 4.53 5.27 TRIFLUO -5.54 -6.18 6.66 7.41 C-8 - 7.89 8.34 8.61 9.02 9.46 0 70 10 70 -11.55-11.76 12.78 13.58 -13.81 14.31 BROMOF -14.83 C-10 -- ·15.12 15.62 15.86 -16.22 16:53 17.12 17.39 18.308.10 18.66 ≿19.21 19.28 19.85² 28:42 28.78 21.29 C-12 > 21.73 21.96 22.26 22.67

23.06 23.29

Sample Name : 166533-005,83153

fileName : G:\GC05\DATA\206G018.raw

: TVHBTXE Method

Start Time : 0.00 min Scale Factor: 1.0

End Time : 25.00 min

Plot Offset: 7 mV

Sample #: a1

Page 1 of 1


Date: 7/28/03 09:52 AM

Time of Injection: 7/25/03 08:57 PM Low Point : 6.89 mV

High Point : 159.29 mV

Plot Scale: 152.4 mV

MW-5 Response [mV]



Page 1 of 1 Sample Name : 166533-006,83197 Sample #: bl : G:\GC05\DATA\209G007.raw Date: 7/29/03 09:52 AM FileName Time of Injection: 7/28/03 04:30 PM TVHBTXE Method End Time : 25.00 min Plot Offset: 7 mV High Point : 146.45 mV Low Point : 7.26 mV Start Time : 0.00 min Plot Scale: 139.2 mV Scale Factor: 1.0 MW-6 Response [mV] 0.79 - 1-151.21 1.52 -1.64 C-6 2.51 $\leq \frac{3}{3}.38$ C-7 -4.04 4.57 5.32 TRIFLUO --5.54 6.15 6.67 7.39 C-8 ---- 7.89 8.32 8.**98** 9.08 9.45 9.65 18.42 11.29 11.55 - 11.76 -12.78 13.52 13.81 BROMOF ---14.32 > 14.83 15.13 C-10 15.56 15.86 -16.22 _____18.29^{18.10} -18.65 >-19.01 >-19.28 -19.63**2**8:**2**1 <u>2</u>8.39 ≻ 21.28 C-12

24.75

Sample Name : 166533-007,83153

: G:\GC05\DATA\206G019.raw

FileName Method : TVHBTXE Start Time : 0.00 min

MW-

End Time : 25.00 min Scale Factor: 1.0 Plot Offset: 7 mV

Sample #: a1

Date: 7/28/03 09:52 AM
Time of Injection: 7/25/03 09:30 PM


Low Point : 6.62 mV


High Point : 166.25 mV


Page 1 of 1

Plot Scale: 159.6 mV

Response [mV]









Page 1 of 1

Sample Name : 166533-010,83153

Sample #: a1 Date : 7/28/03 09:58 AM : G:\GC05\DATA\206G021.raw FileName Time of Injection: 7/25/03 10:37 PM Method : TVHETXE High Point : 922.70 mV Start Time : 0.00 min End Time : 25.00 min Low Point : ~31.20 mV Scale Factor: Plot Offset: -31 mV Plot Scale: 953.9 mV MW-11 Response [mV] 0.78 1.05 -0.95 ≤ 1.22 C-6 <u>-1.52</u> 1.68 2.27 - 2.51 > 3.38 **≻3.82** 4.59 5.27 5.53 TRIFLUO -6.11 6.68 7.24 7.65 ⊒C-8 8.03 8.39 8.66 9.03 9.46 10.03 10.33 10.33 10.89 12.27 12.91 13.47 13.81 BROMOF -14,31 14.82 15.13 15.55 16.17 C-10 18.72 17.12 17.78 > 18.09 18.59 19.00 19.36 19.62 20.21 28.55 21.25 C-12 21.70 21.99 22.25 22.68 23.01 23.26 23.68 24.25 24.35







	Curtis &	Tompkins Labor	atories An	alytical Report
Lab #:	166533		Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2331		Analysis:	EPA 8021B
Type:	LCS	****	Diln Fac:	1.000
Lab ID:	QC220168		Batch#:	83153
Matrix:	Water		Analyzed:	07/25/03
Units:	ug/L			

Analyte	Spiked	Result	%REC	Limits	
Gasoline C7-C12	N	Ά			
MTBE	10.00	11.05	111	63-133	
Benzene	10.00	10.46	105	78-123	
Toluene	10.00	10.14	101	79-120	
Ethylbenzene	10.00	10.04	100	80-120	
m,p-Xylenes	20.00	20.77	104	76-120	
o-Xylene	10.00	10.32	103_	80-121	

Surrogate	Res	ult %REC	Limits	
Trifluorotoluene (FID)	NA			
Bromofluorobenzene (FID)	NA			
Trifluorotoluene (PID)		102	54-149	
Bromofluorobenzene (PID)		105	58-143	



	Curtis & Tompk	ins Laboratories Anal	ytical Report
Lab #:	166533	Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental Engine	ering Inc. Prep:	EPA 5030B
Project#:	2331	Analysis:	8015B
Type:	LCS	Diln Fac:	1.000
Lab ID:	QC220169	Batch#:	83153
Matrix:	Water	Analyzed:	07/25/03
Units:	ug/L		

Analyte	Spiked		Result	%RE(: Limits
Gasoline C7-C12	1,000		991.3	99	80-120
MTBE		AN			
Benzene		NA			
Toluene		NA			
Ethylbenzene		NА			
m,p-Xylenes o-Xylene		NA			
o-Xylene		AN			

Surrogate	Result %	REC Limits	
Trifluorotoluene (FID)	11.	7 57-150	
Bromofluorobenzene (FID)	11:	L 65-144	
Trifluorotoluene (PID)	NA		
Bromofluorobenzene (PID)	AN		



	Curtis & Tompkins Labor	ratories Ana	lytical Report
Lab #:	166533	Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental Engineering Inc.	Prep:	EPA 5030B
Project#:	2331	Analysis:	EPA 8021B
Type:	LCS	Diln Fac:	1.000
Lab ID:	QC220382	Batch#:	83197
Matrix:	Water	Analyzed:	07/28/03
Units:	ug/L	-	

Analyte	Spiked	Result	%RE(' Limits	
Gasoline C7-C12	1	JA			
MTBE	10.00	10.03	100	63-133	
Benzene	10.00	9.761	98	78-123	
Toluene	10.00	9.298	93	79-120	
Ethylbenzene	10.00	9.517	95	80-120	
m,p-Xylenes	20.00	19.18	96	76-120	
o-Xylene	10.00	9.716	97	80-121	

Surrogate	Resu	:lt %rec	Limita	
Trifluorotoluene (FID)	NA			
Bromofluorobenzene (FID)	NA			i
Trifluorotoluene (PID)		89	54-149	
Bromofluorobenzene (PID)		104	58-143	



	Curtis & Tompkins Labor	atories Anal	ytical Report
Lab #:	166533	Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental Engineering Inc.	Prep:	EPA 5030B
Project#:	2331	Analysis:	8015B
Туре:	LCS	Diln Fac:	1.000
Lab ID:	QC220383	Batch#:	83197
Matrix:	Water	Analyzed:	07/28/03
Units:	ug/L		

Analyte	Spiked	Result	%REC	' Limits
Gasoline C7-C12	1,000	1,044	104	80-120
MTBE		NA		
Benzene		NA		•
Toluene		NA		
Ethylbenzene		NA		·
<pre>m,p-Xylenes o-Xylene</pre>		NA		
o-Xylene		NA		

Trifluorotoluene (FID) Bromofluorobenzene (FID) Trifluorotoluene (PID) NA Promofluorobenzene (PID) NA	Surrogate	Rest	ilt krbC	: Limits	
Trifluorotoluene (PID) NA	Trifluorotoluene (FID)		111	57-150	
	Bromofluorobenzene (FID)		117	65-144	
Promofluorobon-one (PID) NA	Trifluorotoluene (PID)	NA			
BIOMOTIMOTOBENZENE (FIB) NA	Bromofluorobenzene (PID)	NA NA			



		Curtis &	Tompkins 1	Labor	atories Analyt	ical Report
Lab #:	16653	3	7,00		Location:	3609 Int'l Blvd., Oakland
Client:	SOMA	Environmental	Engineering	Inc.	Prep:	EPA 5030B
Project#:	2331				Analysis:	8015B
Field ID:		ZZZZZZZZ Z			Batch#:	83153
MSS Lab ID	:	166471-004			Sampled:	07/22/03
Matrix:		Water	•		Received:	07/22/03
Units:		ug/L			Analyzed:	07/25/03
Diln Fac:		1.000				

Type:

MS

Lab ID:

QC220215

Analyte MSS	Result	Spiked	Result	%REC	Limits
Gasoline C7-C12	21.92	2,000	2,121	105	76-120
MTBE		1	NΑ		
Benzene		1	NA.		
Toluene		1	NA .		
Ethylbenzene		1	AV.		į
m,p-Xylenes		1	Al		
o-Xylene		<u> </u>	AL		

Surrogate	Re	sult %REC	Limits	
Trifluorotoluene (FID)		133	57-150	
Bromofluorobenzene (FID)		129	65-144	
Trifluorotoluene (PID)	NA		•	
Bromofluorobenzene (PID)	NA			

Type:

MSD

Lab ID:

QC220216

Analyte	Spiked	Result	%RBC	Limits	RPD	Lim
Gasoline C7-C12	2,000	2,099	104	76-120	1	20
MTBE		NA				
Benzene		NA				
Toluene		NA				
Ethylbenzene		NA				
m,p-Xylenes		NA				
o-Xylene		NA				

Surrogate	j	esult *REC Limits
Trifluorotoluene (FID)		132 57-150
Bromofluorobenzene (FID)		128 65-144
Trifluorotoluene (PID)	NA	
Bromofluorobenzene (PID)	AM	

NA= Not Analyzed

RPD= Relative Percent Difference

Page 1 of 1



	Curtis &	Tompkins Labor	atories Analyt	ical Report
Lab #: 1	66533		Location:	3609 Int'l Blvd., Oakland
Client: S	OMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#: 2	331		Analysis:	8015B
Field ID:	ZZZZZZZZZZ		Batch#:	83197
MSS Lab ID:	166554-002		Sampled:	07/25/03
Matrix:	Water		Received:	07/25/03
Units:	ug/L		Analyzed:	07/28/03
Diln Fac:	1.000			

Type:

MS

Lab ID:

QC220462

Analyte	MSS Result	Spiked	Result	%RE(2 Limits
Gasoline C7-C12	22.72	2,000	1,900	94	76-120
MTBE			NA		
Benzene			NA		
Toluene		•	NA		
Ethylbenzene			NA		
m,p-Xylenes			NA		
o-Xylene			NA		

Surrogate	Resi	ilt %RBC	Limits	
Trifluorotoluene (FID)		121	57-150	
Bromofluorobenzene (FID)		135	65-144	
Trifluorotoluene (PID)	NA			
Bromofluorobenzene (PID)	NA			

Type:

MSD

Lab ID:

QC220463

Analyte	Spiked	Result	*RBC	Limits	RPD	Lim
Gasoline C7-C12	2,000	1,905	94	76-120	0	20
MTBE		NA				
Benzene		NA				
Toluene		NA				
Ethylbenzene		NA				
m,p-Xylenes o-Xylene		NA				
o-Xylene		NA				

Surrogate	Resu	lt %REC	Limits	
Trifluorotoluene (FID)		110	57-150	-
Bromofluorobenzene (FID)		120	65-1:44	
Trifluorotoluene (PID)	NA	•		
Bromofluorobenzene (PID)	AN			

NA= Not Analyzed

RPD= Relative Percent Difference

Page 1 of 1



	Purgeable Aro	matics by G	C/MS
Lab #: Client: Project#:	166533 SOMA Environmental Engineering Inc. 2331	Location: Prep: Analysis:	3609 Int'l Blvd., Oakland EPA 5030B EPA 8260B
Field ID: Lab ID: Matrix: Units: Diln Fac:	MW-1 166533-001 Water ug/L 166.7	Batch#: Sampled: Received: Analyzed:	83249 07/24/03 07/24/03 07/29/03

Analyte	Result	KL	
MTBE	25,000	83	
Surrogata	RREC Limits		

Surrogate	¥REC	Limite	
1,2-Dichloroethane-d4	99	77-129	
Toluene-d8	96	80-120	
Bromofluorobenzene	98	80-123	



		Purgeable Arc	matics by	GC/MS	
Lab #: Client:	166533	Projection Inc	Location:	3609 Int'l Blvd., Oakl EPA 5030B	and
Project#:	SOMA Environmental	angineering inc.	Prep: Analysis:	EPA 8260B	
Field ID:	MW - 3		Batch#:	83249	
Lab ID:	166533-003		Sampled:	07/24/03	
Matrix:	Water		Received:	07/24/03	
Units:	ug/L		Analyzed:	07/29/03	
Diln Fac:	100.0				

Analyte	Result	RL	
MTBE	16,000	50	

Surrogate	%REC	Limits
1,2-Dichloroethane-d4	102	77-129
Toluene-d8	97	80-120
Bromofluorobenzene	101	80-123



		Purgemble Aro	matics by	GC/MS
Lab #:	166533		Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2331	•	Analysis:	EPA 8260B
Field ID:	MW-4		Batch#:	83249
Lab ID:	166533-004		Sampled:	07/24/03
Matrix:	Water		Received:	07/24/03
Units:	ug/L		Analyzed:	07/29/03
Diln Fac:	1.000		·	

Analyte	Result	RL.
MTBE	ИD	0.5

Surrogate %REC Limits				
1,2-Dichloroethane-d4	106	77-129		
Toluene-d8	97	80-120		
Bromofluorobenzene	103	80-123		



	Purgeabl	e Aromatics by GC	/ms
Lab #:	166533	Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental Engineering	Inc. Prep:	EPA 5030B
Project#:	2331	Analysis:	EPA 8260B
Field ID:	MW - 7	Batch#:	83249
Lab ID:	166533-007	Sampled:	07/24/03
Matrix:	Water	Received:	07/24/03
Units:	ug/L	Analyzed:	07/29/03
Diln Fac:	1.000		

	Rasult	RL	
MTBE	5.9	0.5	

Surrogate	*RBC	Limits	
1,2-Dichloroethane-d4	108	77-129	
Toluene-d8	99	80-120	
Bromofluorobenzene	104	80-123	



		Purgeable Aro	matics by	gc/ms
Lab #:	166533		Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:			Analysis:	EPA 8260B
Field ID:	MW - 8		Batch#:	83249
Lab ID:	166533-008		Sampled:	07/24/03
Matrix:	Water		Received:	07/24/03
Units:	ug/L		Analyzed:	07/29/03
Diln Fac:	6.250			

Analyte	Result	RL
MTBE	890	3.1

Surrogate %REC Limits					
1,2-Dichloroethane-d4	102	77-129			
Toluene-d8	99	80-120			
Bromofluorobenzene	102	80-123			



		Purgeable Aro	matics by	gc/ms
Lab #:	166533		Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2331		Analysis:	EPA 8260B
Field ID:	MW-10		Batch#:	83249
Lab ID:	166533-009		Sampled:	07/24/03
Matrix:	Water		Received:	07/24/03
Units:	ug/L		Analyzed:	07/29/03
Diln Fac:	1.000			

Analyte	Destile	RL	
MTBE	79	0.5	

Surrogate	%REC	Limite
1,2-Dichloroethane-d4	105	77-129
Toluene-d8	98	80-120
Bromofluorobenzene	100	80-123



		Purgeable Arc	mmatics by G	С/МБ
Lab #:	166533		Location:	3609 Int'l Blvd., Oakland
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2331		Analysis:	EPA 8260B
Field ID:	MW-12	**************************************	Batch#:	83249
Lab ID:	166533-011		Sampled:	07/24/03
Matrix:	Water		Received:	07/24/03
Units:	ug/L		Analyzed:	07/29/03
Diln Fac:	1.000			

Analyte	Result	RL	
MTBE	66	0.5	

Surrogate	%REC	Limits
1,2-Dichloroethane-d4	107	77-129
Toluene-d8	102	80-120
Bromofluorobenzene	102	80-123



Purgeable Aromatics by GC/MS 3609 Int'l Blvd., Oakland Location: 166533 Lab #: EPA 5030B SOMA Environmental Engineering Inc. Prep: Client: EPA 8260B Project#: 2331 Analysis: 1.000 BLANK Diln Fac: Type: 83249 Batch#: Lab ID: QC220587 07/29/03 Matrix: Water Analyzed: Units: ug/L

Analyte	Result	RL.
MTBE	ND	0.5

Surrogate	%REC	Limits
1,2-Dichloroethane-d4	106	77-129
Toluene-d8	97	80-120
Bromofluorobenzene	109	80-123



Purgeable Aromatics by GC/MS

Lab #: 166533 Location: 3609 Int'l Blvd., Oakland

Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B Project#: 2331 Analysis: EPA 8260B

 Matrix:
 Water
 Batch#:
 83249

 Units:
 ug/L
 Analyzed:
 07/29/03

Diln Fac: 1.000

Type:

BS

Lab ID:

QC220585

Analyte	Spikad	Result	¥REC	: Limite	
MTBE	50.00	53.56	107	69-124	

Surrogate	SREC	Limits
1,2-Dichloroethane-d4	100	77-129
Toluene-d8	97	80-120
Bromofluorobenzene	96	80-123

Type:

BSD

Lab ID:

QC220586

Analyte	Spiked			Limits	RPI	Lin
MTBE	50.00	54.84	110	69-124	2	20

Surrogate	%REC	Limits	
1,2-Dichloroethane-d4	105	77-129	
Toluene-d8	101	80-120	
Bromofluorobenzene	99	80~123	

Appendix C

Laboratory Reports and Chain of Custody Forms for Groundwater Extraction Treatment System



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 9471O, Phone (51O) 486-0900

ANALYTICAL REPORT

Prepared for:

SOMA Environmental Engineering Inc. 2680 Bishop Dr. Suite 203 San Ramon, CA 94583

Date: 30-JUL-03 Lab Job Number: 166439

Project ID: 2333

Location: 3609 International Blvd

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

roject Manager

Reviewed by:

Operations Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of _____

CHAIN OF CUSTODY

Page	0	of

Curtis & Tompkins, Ltd.

Analytical Laboratory Since 1878 2323 Fifth Street Berkeley, CA 94710 (510)486-0900 Phone (510)486-0532 Fax

C&T LOGIN # 166 439

Analyses

	<u> </u>			-
Project	No:	2333		Report To:

Project Name:3609 International Blvd., Oakland Company:

Turnaround Time: Standard

Sampler: Mehran NOWTOOZ

Tony Perini SOMA Environmental

925-244-6600 Telephone:

925-244-6601 Fax:

& MTBE 8021B 8015 Preservative Matrix H₂SO₄ HNO₃ Soil Water Waste TPHg 8 BTEX # of **Sampling Date** # 이 Containers 도 Lab Sample ID. Time No. 3-VOAs 12:01 PM 7/21,03 Influent 3-VOAs GAC-1 12:05 PM 7/21/63 3-VOAs PSP#1 Preservation Correct? Yes I No I N/A Received □ On Ice ☐ Cold ☐ Ambient ☐ Intact **RECEIVED BY:** RELINQUISHED BY:

Notes: EDF OUTPUT REQUIRED

Grab Sample

Confirm MtBE by EPA Method 8260B

Totalizer Reading:

7/21/03 DATE/TIME H-100mcon


7/21/03/3:10 DATE/TIME

DATE/TIME

DATE/TIME

DATE/TIME

DATE/TIME



Curtis & Tompkins Laboratories Analytical Report Lab #: 166439 Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc.

Prep: EPA 5030B

Project#: 2333

Matrix: Water Sampled: 07/21/03 Units: ug/L Received: .07/21/03 Batch#: 83036 Analyzed: 07/22/03

ield ID:

INFLUENT

Lab ID:

166439-001

Type:

SAMPLE

Analyte	Result	RL	Diln Fa	c Analys
Gasoline C7-C12	6,400	500	10.00	8015B
MTBE	3,100	50	10.00	EPA 8021B
Benzene	1,000	50	10.00	EPA 8021B
Toluene	190	5.0	1.000	EPA 8021B
Ethylbenzene	69	5.0	1.000	EPA 8021B
π,p-Xylenes	950	50	10.00	EPA 8021B
b-Xylene	320	5.0	1.000	EPA 8021B

Surrogate	%REC	Limits	Diln	Fac Analysis
Trifluorotoluene (FID)	117	57-150	10.00	8015B
Bromofluorobenzene (FID)	127	65-144	10.00	8015B
Trifluorotoluene (PID)	121	54-149	1.000	EPA 8021B
Bromofluorobenzene (PID)	111	58-143	1.000	EPA 8021B

ld ID:

GAC-1 SAMPLE Lab ID:

166439-002

Diln Fac:

1.000

Analyte	Result	RL	Analysis
Gasoline C7-C12	ND	50	8015B
MTBE	40	5.0	EPA 8021B
Benzene	ND	5.0	EPA 8021B
Toluene	ND	5.0	EPA 8021B
Ethylbenzene	ND	5.0	EPA 8021B
n,p-Xylenes b-Xylene	ND	5.0	EPA 8021B
b-Xylene	ND	5.0	EPA 8021B

Surrogate	%REC	Limits	Analysis
Frifluorotoluene (FID)	95	57-150	8015B
Bromofluorobenzene (FID)	113	65-144	8015B
Trifluorotoluene (PID)	96	54-149	EPA 8021B
Bromofluorobenzene (PID)	113	58-143	EPA 8021B

= Not Detected

= Reporting Limit

Page 1 of 2



Curtis & Tompkins Laboratories Analytical Report Lab #: 166439 Location: 3609 International Blvd SOMA Environmental Engineering Inc. Client: Prep: EPA 5030B Project#: 2333 Matrix: Water Sampled: 07/21/03 Units: ug/L Received: 07/21/03 Batch#: 83036 Analyzed: 07/22/03

Field ID:

PSP#1

Lab ID:

166439-003

Type:

SAMPLE

Diln Fac:

1.000

Analyte	Result	RL	Analysis
Gasoline C7-C12	ND	50	8015B
MTBE	ND	5.0	EPA 8021B
Benzene	ND	5.0	EPA 8021B
Toluene	ND	5.0	EPA 8021B
Ethylbenzene	ND	. 5.0	EPA 8021B
n,p-Xylenes o-Xylene	ND	5.0	EPA 8021B
o-Xylene	ND	5.0	EPA 8021B

Surrogate	%REC	Limits	Analysis
Trifluorotoluene (FID)	93	57-150	8015B
Bromofluorobenzene (FID)	121	65-144	8015B
Trifluorotoluene (PID)	95	54-149	EPA 8021B
Bromofluorobenzene (PID)	122	58-143	EPA 8021B

Type: Lab ID: BLANK QC219800 Diln Fac:

1.000

Analyte	Result	RL	Analysis
Gasoline C7-C12	ND	50	8015B
TBE	ND	5.0	EPA 8021B
Benzene	ND	5.0	EPA 8021B
Toluene	ND	5.0	EPA 8021B
Ethylbenzene	ND	5.0	EPA 8021B
n,p-Xylenes e-Xylene	ND	5.0	EPA 8021B
-Xylene	ND	5.0	EPA 8021B

Surrogate	%REC	Limits	Analysis
rifluorotoluene (FID)	95	57-150	8015B
Bromofluorobenzene (FID)	106	65-144	8015B
Trifluorotoluene (PID)	97	54-149	EPA 8021B
romofluorobenzene (PID)	109	58-143	EPA 8021B

= Not Detected

Reporting Limit
Page 2 of 2



Curtis & Tompkins Laboratories Analytical Report

Lab #: 166439 Location: 3609 International Blvd

Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B

Project#: 2333

 Type:
 LCS
 Diln Fac:
 1.000

 Lab ID:
 QC219801
 Batch#:
 83036

 Matrix:
 Water
 Analyzed:
 07/22/03

Units: ug/L

Analyte	Spiked	Result	%REC	Limits	Analysis
Gasoline C7-C12	N.	A			
MTBE	20.00	19.68	98	63-133	EPA 8021B
Benzene	20.00	19.96	100	78-123	EPA 8021B
Toluene	20.00	19.07	95	79-120	EPA 8021B
Ethylbenzene	20.00	19.33	97	80-120	EPA 8021B
m,p-Xylenes o-Xylene	40.00	38.73	97	76-120	EPA 8021B
o-Xylene	20.00	19.38	97	80-121	EPA 8021B

Surrogate	%REC	Limits	Analysis
Frifluorotoluene (FID)	98	57-150	8015B
Bromofluorobenzene (FID)	107	65-144	8015B
Trifluorotoluene (PID)	99	54-149	EPA 8021B
Bromofluorobenzene (PID)	108	58-143	EPA 8021B



	Curtis & Tompkins	s Laboratories Analy	ytical Report
Lab #:	166439	Location:	3609 International Blvd
Client:	SOMA Environmental Engineeri	ng Inc. Prep:	EPA 5030B
Project#:	2333	Analysis:	8015B
Type:	LCS	Diln Fac:	1.000
Lab ID:	QC219802	Batch#:	83036
Matrix:	Water	Analyzed:	07/22/03
Units:	ug/L		

Analyte	Spiked	Result	%REC	Limits
Gasoline C7-C12	2,000	2,012	101	80-120
MTBE		NA		
Benzene		NA		
Toluene		NA		
Ethylbenzene n,p-Xylenes b-Xylene		NA		
n,p-Xylenes		NA		
b-Xylene		NA		

Surrogate	Re	sult %RE	C Limits	
Trifluorotoluene (FID)		117	57-150	
Bromofluorobenzene (FID)		116	65-144	
Trifluorotoluene (PID)	NA			
Bromofluorobenzene (PID)	NA			



		Curtis &	Tompkins I	abor	atories Analyt	ical Report
uab #:	16643	9			Location:	3609 International Blvd
Client:	SOMA	Environmental	Engineering	Inc.	Prep:	EPA 5030B
Project#:	2333				Analysis:	8015B
Field ID:		ZZZZZZZZZ			Batch#:	83036
MSS Lab ID	:	166471-001			Sampled:	07/22/03
Matrix:		Water			Received:	07/22/03
Units:		ug/L			Analyzed:	07/23/03
Diln Fac:		1.000				

MS

Lab ID:

QC219815

Gasoline C7-C12	23.64	2,000	1,926	95	76-120
ATBE			NA		
Benzene			NA		
[Oluene			NA		
Ethylbenzene			NA		
kthylbenzene m,p-Xylenes p-Xylené			NA		
p-Xylenė		•	NA		

Surrogate		Result	%REC	Limits	
Trifluorotoluene (FID)			112	57-150	
Bromofluorobenzene (FID)			118	65-144	
rifluorotoluene (PID)	NA				
Bromofluorobenzene (PID)	NA	•			

Type:

MSD

Lab ID:

QC219816

Analyte	Spikeđ	Result	%REC	Limits	RPD	Lim
Gasoline C7-C12	2,000	1,950	96	76-120	1,	20
NTBE		NA				
Benżene		NA				
Toluene		NA				
Ethylbenzene		NA				
n,p-Xylenes o-Xylene		NA				
o-Xylene		NA		<u> </u>		

Surrogate	Res	ult %REC	Limits	
Trifluorotoluene (FID)		106	57-150	
Bromofluorobenzene (FID)		115	65-144	
Trifluorotoluene (PID)	NA			
Bromofluorobenzene (PID)	NA			

NA= Not Analyzed RPD= Relative Percent Difference

<u>P</u>age 1 of 1



		Purgeable Arc	matics by Gu	:/MS
	6439		Location:	3609 International Blvd
Client: SO	MA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#: 23			Analysis:	EPA 8260B
Field ID:	INFLUENT	***************************************	Batch#:	83122
Lab ID:	166439-001	•	Sampled:	07/21/03
Matrix:	Water		Received:	07/21/03
Units:	ug/L	•	Analyzed:	07/25/03
Diln Fac:	2000			0 / 22/ 02

IMIBE		2,900	10	1
		-		
Surrogate	%REC	Limits		3
1,2-Dichloroethane-d4	93	77-129		1
Toluene-d8	88	80-120		
Bromofluorobenzene	101	80-123		l



		Purgeable Aro	matics by	GC/MS
Lab #:	166439		Location:	3609 International Blvd
Client:	SOMA Environmental E	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333		Analysis:	EPA 8260B
Field ID:	GAC-1		Batch#:	83122
Lab ID:	166439-002		Sampled:	07/21/03
Matrix:	Water		Received:	07/21/03
Units:	ug/L		Analyzed:	07/25/03
Diln Fac:	1.000		<u>.</u>	11, 13, 12

MTBE		34	0.5	
Surrogate	9.DE/	C Limita		
1,2-Dichloroethane-d4	96	77-129		
Toluene-d8	92	80-120		
Bromofluorobenzene	104	80-123		



Purgeable Aromatics by GC/MS

Lab #: 166439 Location: 3609 International Blvd

Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B Project#: 2333 Analysis: EPA 8260B

Type: BLANK Diln Fac: 1.000
Lab ID: QC220066 Batch#: 83122
Matrix: Water Analyzed: 07/24/03

Units: ug/L

Arr	alyte Result	RL	
MTBE	ND	0.5	

1,2-Dichloroethane-d4 98 77-129 Toluene-d8 90 80-120	
0.00 00.00	
Bromofluorobenzene 102 80-123	



Purgeable Aromatics by GC/MS

Lab #: 166439 Location: 3609 International Blvd

Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B Project#: 2333 Analysis: EPA 8260B

 Matrix:
 Water
 Batch#:
 83122

 Jnits:
 ug/L
 Analyzed:
 07/24/03

Diln Fac: 1.000

Type:

BS

Lab ID:

QC220063

Analyte	Spiked	· Hagnir	+REC	: Limits	
MTBE	50.00	45.11	90	69-124	

Surrogate	%REC	: Limits
1,2-Dichloroethane-d4	96	77-129
Toluene-d8	94	80-120
Bromofluorobenzene	93	80-123

ype:

BSD

Lab ID:

QC220064

Analyte	Spiked	Result	%REC	: Limits	RPI) Lin
MTBE	50.00	46.60	93	69-124	3	20

Surrogate	%REC	Limits		
1,2-Dichloroethane-d4	97	77-129		
Toluene-d8	95	80-120		
Bromofluorobenzene	96	80-123		



Curtis & Tompkins, Ltd., Analytical Laboratories. Since 1878

2323 Fifth Street, Berkeley, CA 9471O, Phone (510) 486-0900

ANALYTICAL REPORT

Prepared for:

SOMA Environmental Engineering Inc. 2680 Bishop Dr. Suite 203 San Ramon, CA 94583

Date: 22-JUL-03 Lab Job Number: 166254

Project ID: 2333

Location: 3609 International Blvd

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

roject Manager

Reviewed by:

Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of | 1

CHAIN OF CUSTODY

_		
Page	 _of	

Curtis & Tompkins, Ltd.

Analytical Laboratory Since 1878 2323 Fifth Street Berkeley, CA 94710 (510)486-0900 Phone

C&T LOGIN#	16625	4

Analyses

(510)486-0532 Fax	Gampier.	HENTON 100
Project No: 2333	Report To:	Tony Perini

Project Name:3609 International Blvd., Oakland Company:

Turnaround Time: Standard

SOMA Environmental

925-244-6600 Telephone:

Fax:

925-244-6601

		. ———	N	lat	rix]	P	res	erv	ativ	e	8015	Ξ			İ		•	-	
Lab No.	Sample ID.	Sampling Date Time	Soil	Water	waste	# of Containers	HCL	H ₂ SO ₄	HNO3	ICE		TPH9 80	BTEX &						•	
	Influent	7/9/03 1:30 PM	П	X	1	3-VOAs	X			X		X	X	_	_	_			\dashv	_
-à_	GAC-1	7/4,07 1:40 PM		\times		3-VOAs	X	1_		X			X	\dashv	\dashv		+	\dashv		_
-3	PSP#1	7/9,03 1:458		X		3-VOAs	\bowtie		<u> </u>	凶			X				\dashv		\dashv	_
1 - 7							1	1_	┞	_	\vdash	-				\dashv	\dashv	-	\dashv	_
F					1		<u> </u>	+	├	—		-	-					\dashv	\dashv	
			_	Ц			 	1	┼	↓_		-	-		┟╼╅	\dashv		-	\dashv	_
			1_	Ц	\dashv		┨—	╁-	1-	+-		-	├─	H					=	Ξ.
					4		#	丰	#	Τ.		-	\vdash	╂	\vdash		Pres	· F		Г.
			L			Received		1 00 l		╀-		<u> </u>	<u> </u>		┼┤	1	D-Ye	S].	μ
	,	·	L			Cold CAM	<u>bien</u>	1/1	 	<u>ıtact</u>		-	 -	<u> </u>	Ħ		Ħ	-		F
			L				+	+	+	#		<u> </u>	╄-	 	┥		\vdash			H
	 				\perp		<u> </u>	1.	1_	4_	 	 	\vdash	├ ─	$\vdash \vdash$					-
-								<u> </u>			<u> </u>	-	<u>L</u> .	<u></u>	Щ		<u> </u>			L
Notes	SEDE OUTPUT REQU	IRED	R	EL	INC	QUISHED BY	:					RI	ECE	IVE	DB	3Y:				
1140101																				

Notes: EDF OUTPUT REQUIRED **Grab Sample** Confirm MtBE by EPA Method 8260B **Totalizer Reading:**

INQUISHE	D BY:	·	HEC
			T
		7,4,37	1

k.A.	Alamas?	ች/ 4 _/ øኔ DATE/TIME	
1-1-	1/2 Chin		Į
			(
		DATE/TIME	

	7/9/03	
<		

DATE/TIM

DATE/TIME

DATE/TIME	

BE 8021B



Curtis & Tompkins Laboratories Analytical Report

Lab #: 3609 International Blvd 166254 Location:

Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B

Project#: 2333

Matrix: Water Sampled: 07/09/03 Units: ug/L 07/09/03 Received:

ield ID:

INFLUENT

Lab ID:

166254-001

уре:

SAMPLE

Analyte	Result	RL	Diln Pac	Batch#	Analyzed	Analysis
Gasoline C7-C12	9,300	50	1.000	82810	07/11/03	8015B
MTBE	4,300	25	5.000	82840	07/13/03	EPA 8021B
Benzene	1,100	25	5.000	82840	07/13/03	EPA 8021B
Toluene	310	5.0	1.000	82810	07/11/03	EPA 8021B
Ethylbenzene	110	5.0	1.000	82810	07/11/03	EPA 8021B
m,p-Xylenes	970	25	5.000	82840	07/13/03	EPA 8021B
o-Xylene	370	25	5.000	82840	07/13/03	EPA 8021B

Surrogate	%REC	Limite	Diln	Fac Batch#	Analyzed	Analysis
Trifluorotoluene (FID)	107	57-150	1.000	82810	07/11/03	8015B
Bromofluorobenzene (FID)	103	65-144	1.000	82810	07/11/03	8015B
Trifluorotoluene (PID)	133	54-149	5.000	82840	07/13/03	EPA 8021B
Bromofluorobenzene (PID)	116	58-143	5.000	82840	07/13/03	EPA 8021B

ield ID:

GAC-1

SAMPLE

Lab ID:

166254-002

Diln Fac:

1.000

Batch#:

82840

Analyzed:

07/13/03

Analyte	Result	RL	Analysis	
Gasoline C7-C12	ND	50	8015B	
MTBE	36	5.0	EPA 8021B	
Benzene	ND	5.0	. EPA 8021B	
Toluene	ND	5.0	EPA 8021B	
Ethylbenzene	ND	5.0	EPA 8021B	
m,p-Xylenes	ND	5.0	EPA 8021B	
Ethylbenzene m,p-Xylenes o-Xylene	N D	5.0	EPA 8021B	

Surrogate	%REC	Limits	Analysis
Trifluorotoluene (FID)	105	57-150	8015B
Bromofluorobenzene (FID)	107	65-144	8015B
Trifluorotoluene (PID)	109	54-149	EPA 8021B
Bromofluorobenzene (PID)	116	58-143	EPA 8021B

D= Not Detected

L= Reporting Limit

age 1 of 3

GC04 TVH 'J' Data File FID

Sample #: al

Page 1 of 1

nple Name : 166254-001,82810 leName : G:\GC04\DATA\1920 thod : TVHBTXE : G:\GC04\DATA\192J006.raw Date: 7/12/03 12:31 PM Time of Injection: 7/11/03 12:52 PM Start Time : 0.00 min End Time : 26.00 min Low Point : 8.06 mV High Point: 1094.43 mV Scale Factor: 1.0 Plot Offset: 8 mV Plot Scale: 1086.4 mV INFLUENT Response [mV] 0.29 0.29 1.15 --1.45 -1.60 1.80 **≈1.98** 2.17 -2.44 C-6 -3.43€3.81 .01 --4.21 ---4.47 C-7 -5.16 5.69 TRIFLUO --7.74 8.09 -8.47 C-8 --8.95 3:45 -10.07 -10.4912.57 12.79 -13.81 -14.81 15.06 >--15.35 BROMOF-15.84 C-10 ---16.29 16.15 ----16.90 -17.27 17.75 18.14 -18.4518.78 --19.18 19.70 >-20.05 --20.32 -20.70 22.87 23.08 23.84 24.06 24.41 25.02 >-25.49



Curtis & Tompkins Laboratories Analytical Report

Lab #: Location: 3609 International Blvd

Client: SOMA Environmental Engineering Inc. EPA 5030B Prep:

Project#: 2333

Sampled: 07/09/03 Received: 07/09/03 Units: ug/L

ield ID:

PSP#1 SAMPLE Diln Fac:

1.000

уре:

Batch#:

82810

Lab ID:

166254-003

Analyzed:

07/11/03

Analyte	Result	RL	Analysis
Gasoline C7-C12	ND	50	8015B
MTBE	ND	5.0	EPA 8021B
Benzene	ND	5.0	EPA 8021B
Toluene	ND	5,0	EPA 8021B
Ethylbenzene	ND	5.0	EPA 8021B
m,p-Xylenes o-Xylene	ND	5.0	EPA 8021B
o-Xylene	ND	5.0	EPA 8021B

Surrogate	%REC	Limits	Analysis
Trifluorotoluene (FID)	103	57-150	8015B
Bromofluorobenzene (FID)	102	65-144	8015B
Trifluorotoluene (PID)	108	54-149	EPA 8021B
Bromofluorobenzene (PID)	110	58-143	EPA 8021B

Lab ID:

BLANK QC218944 Batch#:

82810

<u>D</u>iln Fac:

1.000

Analyzed:

07/11/03

Analyte	Result	RL	Analysis
Gasoline C7-C12	ND	50	8015B
MTBE	ND	5.0	EPA 8021B
Benzene	ND	5.0	EPA 8021B
Toluene	ND	5.0	EPA 8021B
L Ethylbenzene	ND	5.0	EPA 8021B
m,p-Xylenes o-Xylene	ND	5.0	EPA 8021B
o-Xylene	ND	5.0	EPA 8021B


Surrogate	%REC	Limits	Analysis
Trifluorotoluene (FID)	101	57-150	8015B
Bromofluorobenzene (FID)	99	65-144	8015B
Trifluorotoluene (PID)	106	54-149	EPA 8021B
Bromofluorobenzene (PID)	104	58-143	EPA 8021B

ND= Not Detected

L= Reporting Limit

Page 2 of 3

GC04 TVH 'J' Data File FID





Curtis & Tompkins Laboratories Analytical Report Lab #: Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc. Prep: **EPA 5030B** Project#: 2333 Matrix: Water 07/09/03 Sampled: Units: ug/L Received: 07/09/03

уре:

BLANK

ab ID:

QC219069

Batch#: Analyzed: 82840 07/12/03

Diln Fac: 1.000

Analyte Result RL Analysis Gasoline C7-C12 ND 50 8015B MTBE ND5.0 EPA 8021B Benzene ND 5.0 EPA 8021B Toluene ND 5.0 EPA 8021B Ethylbenzene ND EPA 8021B 5.0 m,p-Xylenes ND 5.0 EPA 8021B o-Xylene ND 5.0 EPA 8021B

Surrogate	%REC	Limits	Analysis
Trifluorotoluene (FID)	96	57-150	8015B
Bromofluorobenzene (FID)	90	65-144	8015B
Trifluorotoluene (PID)	102	54-149	EPA 8021B
Bromofluorobenzene (PID)	99	58-143	EPA 8021B



Total Volatile Hydrocarbons

Lab #: 166254 Location: 3609 International Blvd

Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B Project#: 2333 Analysis: 8015B

 Project#: 2333
 Analysis:
 8015B

 Type:
 LCS
 Diln Fac:
 1.000

 Lab ID:
 QC218946
 Batch#:
 82810

Matrix: Water Analyzed: 07/11/03

Units: ug/L

Analyte	Spiked	Result		: Limits
Gasoline C7-C12	1,000	882.8	88	80-120

001109616	*REC	Limits
Trifluorotoluene (FID)	114	57-150
Bromofluorobenzene (FID)	96	65-144



	Benzene, Toluene	, Ethylbenzene,	Xylenes
Lab #:	166254	Location:	3609 International Blvd
	SOMA Environmental Engineering In	nc. Prep:	EPA 5030B
Project#:	2333	Analysis:	EPA 8021B
Type:	BS	Diln Fac:	1.000
Lab ID:	QC218945	Batch#:	82810
Matrix:	Water	Analyzed:	07/11/03
Units:	ug/L	<u>-</u>	

Analyte	Spiked	Result	%RBC	Limits
MTBE	10.00	11.14	111	63-133
Benzene	10.00	10.43	104	78-123
Toluene	10.00	10.29	103	79-120
Ethylbenzene	10.00	9.610	96	80-120
m,p-Xylenes	20.00	19.53	98	76-120
m,p-Xylenes o-Xylene	10.00	9.994	100	80-121

	2048AN	Limits
Frifluorotoluene (PID)	91	54-149
Bromofluorobenzene (PID)	89	58-143



Total Volatile Hydrocarbons Lab #: 166254 Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc. EPA 5030B Prep: 8015B Project#: 2333 Analysis: Туре: LCS Diln Fac: 1.000 Lab ID: QC219070 Batch#: 82840 Matrix: Water Analyzed: 07/12/03 Units: ug/L

Analyte		Result	%REC	Limits
Gasoline C7-C12	3,000	2,651	88	80-120

Surrogate	%REC	Limits
Trifluorotoluene (FID)	114	57-150
Bromofluorobenzene (FID)	100	65-144



	Benzane	, Toluene, E	thylbenzene,	Xylenes
Lab #:	166254		Location:	3609 International Blvd
Client:	SOMA Environmental Eng	gineering Inc.	Prep:	EPA 5030B
Project#:	2333		Analysis:	EPA 8021B
Type:	LCS		Diln Fac:	1.000
Lab ID:	QC219071		Batch#:	82840
Matrix:	Water	•	Analyzed:	07/12/03
Units:	ug/L		-	

A nalyte	Spiked	Result	%REC	Limits
MTBE	20.00	19.35	97	63-133
Benzene	20.00	20.67	103	78-123
Toluene	20.00	20.35	102	79-120
Ethylbenzene	20.00	18.70	93	80-120
m,p-Xylenes o-Xylene	40.00	37.44	94	76-120
o-Xylene	20.00	19.54	98	80-121

Surrogate	%REC	Limits
Trifluorotoluene (PID)	97	54-149
Bromofluorobenzene (PID)	99	58-143



			Total Volatil	a Wydrogarb	one
1 1/	1.555		TOCAL YOURCES		
Lab #:	16625			Location:	3609 International Blvd
Client:		Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333			Analysis:	8015B
Field ID:		PSP#1		Batch#:	82810
MSS Lab II):	166254-003		Sampled:	07/09/03
Matrix:		Water		Received:	07/09/03
Units:		ug/L		Analyzed:	07/11/03
Diln Fac:		1.000		-	

ире:

MS

Lab ID:

QC218996

Analyte	MSS Result	Spiked	Result	%R	EC Limits
Gasoline C7-C12	26.12	2,000	1,797	89	76-120

Surrogate	*REC	Limits
Frifluorotoluene (FID)	119	57-150
Bromofluorobenzene (FID)	99	65-144

Type:

MSD

Lab ID:

QC218997

Analyte	Spiked	Result	CONTRACTOR	Limite	RPD	Lim
Gasoline C7-C12	2,000	1,788	. 88	76-120	0	20

Surrogate		Limits
Frifluorotoluene (FID)	119	57-150
Bromofluorobenzene (FID)	99	65-144



				-	
		Benze	ene, Toluene, E	thylbenzene	, Xylenes
_Lab #:	16625			Location:	3609 International Blvd
Client:	AMOR	Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333			Analysis:	EPA 8021B
Field ID:		ZZZZZZZZZZ		Batch#:	82840
MSS Lab ID) :	166274-003		Sampled:	07/09/03
Matrix:		Water		Received:	07/10/03
Units:		ug/L		Analyzed:	07/12/03
Diln Fac:		1.000			

ype:

MS

Lab ID:

QC219078

Analyte	MSS Result	Spiked	Result	%REC	Limits
MTBE	<0.4200	20.00	29.52	148	38-149
Benzene	<0.09400	20.00	23.82	119	75-128
Toluene	<0.1200	20.00	24.07	120	79-127
E thylbenzene	<0.08300	20.00	21.66	108	78-124
m,p-Xylenes	<0.07100	40.00	45.44	114	67-121
n,p-Xylenes o-Xylene	<0.1100	20.00	22.90	115	77-131

Surrogate	%REC	Limits
Trifluorotoluene (PID)	107	54-149
Bromofluorobenzene (PID)	113	58-143

уре:

MSD

Lab ID:

QC219079

Analyte	Spiked	Result	% PRC	Limits	RPD	Leism
MTBE	20.00	29.66	148	38-149	0	38
Benzene	20.00	22.83	114	75-128	4	20
Toluene	20.00	23.60	118	79-127	2	20
Ethylbenzene	20.00	21.69	108	78-124	0	20
m,p-Xylenes	40.00	44.11	110	67-121	3	20
m,p-Xylenes o-Xylene	20.00	22.55	113	77-131	2	20

Surrogate	%REC	Limits
Trifluorotoluene (PID)	104	54-149
Bromofluorobenzene (PID)	104	58-143



		Purgeable Arc	omatics by GC/	'MS
wab #: lient: Project#: Field ID: wab ID: Matrix: Units: Jiln Fac:	INFLUENT 166254-001 Water ug/L	Engineering Inc.	Location: Prep: Analysis: Batch#: Sampled: Received: Analyzed:	3609 International Blvd EPA 5030B EPA 8260B 82849 07/09/03 07/09/03 07/14/03

Attalyte TTBE		Result 3,400	RL 17	
Surrogate 1,2-Dichloroethane-d4 coluene-d8 bromofluorobenzene	% REC 108 97 102	Limits 77-129 80-120 80-123	17	
(_



ab #:		Purgeable Arc	omatics by G	C/Ms
lient: Project#:	166254 SOMA Environmental 2333	Engineering Inc.	Location: Prep:	3609 International Blvd EPA 5030B
Type: _ab ID: !atrix:	BLANK QC219110 Water		Analysis: Diln Fac: Batch#:	EPA 8260B 1.000 82849
Units:	ug/L		Analyzed:	07/14/03

		ND	0.5
Surrogate 1,2-Dichloroethane-d4 Toluene-d8 Bromofluorobenzene	*REC 110 97 104	Timite 77-129 80-120 80-123	

⁼ Not Detected = Reporting Limit ge 1 of 1



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (510) 486-0900, Fax (510) 486-0532

ANALYTICAL REPORT

Prepared for:

SOMA Environmental Engineering Inc. 2680 Bishop Dr. Suite 203 San Ramon, CA 94583

Date: 23-JUN-03

Lab Job Number: 165746 Project ID: 2333

Location: 3609 International Blvd

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

Reviewed by:

rations Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of ______

CHAIN OF CUSTODY

Pageof	
--------	--

DATE/TIME

DATE/TIME

Analyses

8260 GCMS

DATE/TIME

DATE/TIME

Curtis & Tompkins, Ltd.

Analytical Laboratory Since 1878 2323 Fifth Street Berkeley, CA 94710 (510)486-0900 Phone (510)486-0532 Fax

C&T LOGIN # 163746

Sampler:

Mehran Nowroozi

Report To:

Tony Perini

Project Name: 3609 International Blvd., Oaklanc Company:

SOMA Environmental


Turnaround Time: Standard

Project No: 2333

Telephone:

925-244-6600

		Fax:				92	5-244-660	1_				=	,	出			l				Ì					
			M	atr	ix	1	[P	res	erv	ative		8015	MTBE												
Lab No.	Sample ID.	Sampling Date Time	Soil	Water	Wasic	Co	# of ontainers	로	H ₂ SO ₄	HNO3	핑		TPHg 80	⋖	3										<u> </u>	
		742 27 227 124	\vdash	x	1	\top	3 Vo A5	X			Х		X	X		↓_	<u> </u>	_	\bot		4	_	<u>-</u>	+		4
L	Influent	6/10/03 10:30 AM	П	$\overline{\mathbf{x}}$	1		3 VoAs	Χ			X	_ .	X	X		┸	┷	_		_	\dashv	\dashv	_}	+	+	_
·	GAC-1	6,10,01 10.40 AA		x	1	1	3VoAS	X			X		X	X		1_	<u> </u>	_	\bot	\dashv	\dashv	\dashv		\dashv		4
·	PSP#1	6,10,17 10 TO AN	T		十	1								_	1	1_	<u> </u>		_	_	-	\dashv	—├-	+		\dashv
<u> </u>			T	1	\top	1								1		1		_	ᅪ	_			_	\dashv	-	_
	· · · · · · · · · · · · · · · · · · ·		1	1	_	1						_	L	\perp		4	4	_	\dashv	_	4	-	}-	-	+	_
		, W		1	1						\sqcup			\downarrow		1	4-	_	\dashv	-	_	\dashv		-	\dashv	_
	1				丁					_		_		Ļ	==	┿	+	+	4	_	 	-		\rightarrow	╬	
			1							<u> </u>			\perp	4		- -				tion				\dashv	$+\!\!+$	_
			1	П	十	P.	caived E	\overline{a}	nlce			Ц	L	Щ		_ _		Yes.	_#	L N	<u>-</u> 4	LN∦	4 -	\dashv	╫	-
			\top	17	古	₹ . lic	_ □ Ambie	Ī.	N	1		Ц	_	Ш	4	4	#	#	#	#	=	=	\Rightarrow	\Rightarrow	╧┼╴	-
			11					17						1		_	4	+	-	-	\dashv		\dashv	\dashv	\dashv	
<u> </u>			十	$ \cdot $		十		I						\perp		L_						1		_		
23 - 6 -	ALTOUT DECLIE	ED	R	EL	INC	QUIS	SHED BY:				_ •		R	EC	EIV	ED	BY	<u>':</u>								
Note	s: EDF OUTPUT REQUIF	KED		<u> </u>					\bigcirc	`		E/TIN	A.		6	; -	0	-02	<u>ئے</u>		\geq		$Z_{\underline{}}$	DATI	LS E/TIM	ΛE



Total Volatile Hydrocarbons 3609 International Blvd EPA 5030B Lab #: 165746 Location: Prep: Analysis: Client: SOMA Environmental Engineering Inc. 8015B <u>Project#:</u> 2333 82102 Batch#: Matrix: Water 06/10/03 06/10/03 Sampled: Units: ug/L Diln Fac: 1.000 Received:

ield ID:

INFLUENT

90

Lab ID:

165746-001 06/12/03

Type:

SAMPLE

Analyzed:

Analy	te	R	esult		RL	
Gasoline C7-C12		9	,500		50	
Surrog	ate	%REC	វិទ្ធិកាស់ស្តី	8		
Trifluorotoluene	(FID)	134	57-15	0		

65-144

eld ID:

GAC-1

<u> Bromofluorobenzene (FID)</u>

Lab ID:

165746-002

pe:

SAMPLE

Analyzed:

06/12/03

Analyte		Result	RL	
Gasoline C7-C12	N	ĮD	50	
Surrogate	%REC	Limits		
Trifluorotoluene (FID)	87	57-150		
Bromofluorobenzene (FID)	89	65-144		

Field ID:

ype:

PSP#1

SAMPLE

Lab ID:

165746-003

Analyzed:

06/11/03

Gasoline C7-C12	NI.	50	
Surrogate	! %REC	Limite	
Trifluorotoluene (F	FID) 89	57-150 [,]	

Bromofluorobenzene (FID) 88 65-144

Type: Lab ID:

BLANK

QC216164

Analyzed:

06/11/03

· · · · · · · · · · · · · · · · · · ·			
			000000000000000000000000000000000000000
			9000-00000-000000
有特殊有关与			
	3 773	F.O.	
Figgoline ("/-[']2	NII)	50	
Gasorine Cr CIZ	112		


Surrogate	%REC	Limits	
Trifluorotoluene (FID)	87	57-150	
Bromofluorobenzene (FID)	88	65-144	

D= Not Detected L= Reporting Limit Page 1 of 1

Chromatogram

<u>Sa</u>mple Name : 165746-001,82102 Page 1 of 1 Sample #: c1 leName : G:\GC05\DATA\162G022.raw Date: 6/12/03 02:22 AM : TVHBTXE Time of Injection: 6/12/03 01:57 AM art Time : 0.00 min End Time : 25.00 min Low Point : -30.28 mV High Point : 907.60 mV Scale Factor: 1.0 Plot Offset: -30 mV Plot Scale: 937.9 mV INFLUENT Response [mV] C-6 1.72 -1.89 -3.31 4.11 F-4.50 ≥ 55252 TRIFLUO --6.07 6.57 7.16 C-8 7.80 --8.29 -8.57 -8.98 9.41 -9.78 -10.12 -10.48 -11.29 11.62 -11.86-12.95 14.06 **BROMOF** ------14.62 15.18 C-10 -15.52 -16.32 -16.73-17.2617.71 -18.0218.40 --18.79 **19.00** -19,40 -19.81 >-20.11 **≫**20.48 ≥21.38 -21.74 -22.06 > 22.32 C-12 -22.81

Chromatogram






Total Volatile Hydrocarbons Lab #: 165746 Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc. EPA 5030B Prep: Project#: 2333 8015B Analysis: Type: LCS Diln Fac: 1.000 Lab ID: 82102 QC216165 Batch#: Matrix: 06/11/03 Water Analyzed:

Analyte	Spiked	Result	%RE	C Limits	
Gasoline C7-C12	1,000	958.0	96	80-120	

Trifluorotoluene (FID) 97 57-150	Surrogate	%REC	: Limits
Bromofluorobenzene (FTD) 83 65-144		97	57-150
	Bromofluorobenzene (FID)	83	65-144

Units:

ug/L



		Total Volatil	e Hydrocarl	bons
Lab #: 1	L65746		Location:	3609 International Blvd
	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#: 2	2333		Analysis:	8015B
Field ID:	PSP#1	 	Batch#:	82102
MSS Lab ID:	165746-003		Sampled:	06/10/03
Matrix:	Water		Received:	06/10/03
Units:	ug/L		Analyzed:	06/11/03
Diln Fac:	1.000		_	

ype:

MS

Lab ID:

QC216202 .

Analyte	MSS Kesuic	Spiked 2 000	1 03U	96	76-120
Basoline C/-CI2	713.00	2,000		<u> </u>	70 120

Surrogate	%REC	Limits
Trifluorotoluene (FID)	106	57-150
Bromofluorobenzene (FID)	95	65-144

туре:

MSD

Lab ID:

Gasoline C7-C12	2,000	1,916	96	76-120	1	20
Surrogate	%REC Limits					

Surrogate	%REC	Limita
Trifluorotoluene (FID)	105	57-150
Bromofluorobenzene (FID)	93	65-144



		Purgeable Aro	matics by	GC/MS
⊸ ab #:	165746		Location:	3609 International Blvd
lient:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333		Analysis:	EPA 8260B
Field ID:	INFLUENT		Batch#:	82091
ab ID:	165746-001		Sampled:	06/10/03
Matrix:	Water		Received:	06/10/03
Units:	ug/L		Analyzed:	06/11/03
piln Fac:	25.00			

Analyte	Regult	RL	
MTBE	3,600	130	
enzene	1,100	130	
Toluene	390	130	1
Ethylbenzene	130	130	
Ethylbenzene n,p-Xylenes b-Xylene	1,100	130	
-Xylene	310	130	

Surrogate	%REC	Limits		
,2-Dichloroethane-d4	99	77-129		
Toluene-d8	96	80-120		
Bromofluorobenzene	101	80-123		



		Purgeable Aro	matics by	GC/MS
Lab #:	165746		Location:	3609 International Blvd
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333		Analysis:	EPA 8260B
Field ID:	GAC-1		Batch#:	82091
ab ID:	165746-002		Sampled:	06/10/03
Matrix:	Water		Received:	06/10/03
Units:	ug/L		Analyzed:	06/11/03
Diln Fac:	1.000			

Analyte	Result	RL	
MTBE	ND	5.0	
Benzene	ND	5.0	
Toluene	ND	5.0	
Ethylbenzene	ND	5.0	
Ethylbenzene n,p-Xylenes b-Xylene	ND	5.0	
b-Xylene	ND	5.0	

Surrogate	%REC	Limits	
.,2-Dichloroethane-d4	101	77-129	·
Toluene-d8	96	80-120	
Bromofluorobenzene	105	80-123	



	Purg	geable Aromatics by GC/	MS
hab #:	165746	Location:	3609 International Blvd
:lient:	SOMA Environmental Engine	ering Inc. Prep:	EPA 5030B
Project#:	2333	Analysis:	EPA 8260B
Field ID:	PSP#1	Batch#:	82091
ab ID:	165746-003	Sampled:	06/10/03
Matrix:	Water	Received:	06/10/03
Units:	ug/L	Analyzed:	06/11/03
iln Fac:	1.000		

Analyte	Result	RL	
MTBE	ND	5.0	
enzene	ИD	5.0	
Toluene	ND	5.0	ļ
Ethylbenzene	ND	5.0	
i,p-Xylenes 	ND ·	5.0	
⊸ -Xylene	ND	5.0	

Surrogate	%REC	Limits
.,2-Dichloroethane-d4	100	77~129
Toluene-d8	91	80-120
Bromofluorobenzene	103	80-123



		Purgeable Aro	matics by	GC/MS
iab #:	165746		Location:	3609 International Blvd
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333		Analysis:	EPA 8260B
Type:	BLANK		Diln Fac:	1.000
⊿ab ID:	QC216131		Batch#:	82091
Matrix:	Water		Analyzed:	06/11/03
Units:	ug/L			

	Regult		
		RL	
MTBE	ND	5.0	
Benzene	ND	5.0	
Coluene	ND	5.0	
Ethylbenzene	ND	5.0	· ·
Ethylbenzene m,p-Xylenes b-Xylene	ND	5.0	
-Xylene	ND	5.0	

Surrogate %REC Limits 1,2-Dichloroethane-d4 100 77-129 Foluene-d8 91 80-120 Bromofluorobenzene 103 80-123	
Rromofluorobenzene 103 80-123	
Blowoli dolobenzene 103 00-123	



Purgeable Aromatics by GC/MS ab #: 165746 3609 International Blvd Location: SOMA Environmental Engineering Inc. Client: EPA 5030B Prep: Project#: 2333 EPA 8260B Analysis: Matrix: Water Batch#: 82091 Jnits: ug/L 06/11/03 Analyzed: biln Fac: 1.000

Туре:

BS

Lab ID:

QC216128

Analyte	Spiked	Result	%REC	Limits
Benzene	50.00	49.65	99	80-120
Toluene	50.00	53.46	107	80-120

Surrogate	%REC	Limits	
1,2-Dichloroethane-d4	102	77-129	
Toluene-d8	101	80-120	
romofluorobenzene	96	80-123	

rype:

BSD

Lab ID:

Analyte	Spiked			Limits	RPC	Lim
Benzene	50.00	48.21	96	80-120	3	20
Toluene	50.00	51.31	103	80-120	4	20

Surrogate	%REC	Limits	
l,2-Dichloroethane-d4	98	77-129	
Toluene-d8	98	80-120	
TOTAGE GO	90	00-120	
Bromofluorobenzene	96	80-123	



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (510) 486-0900

ANALYTICAL REPORT

Prepared for:

SOMA Environmental Engineering Inc. 2680 Bishop Dr. Suite 203 San Ramon, CA 94583

Date: 29-MAY-03

Lab Job Number: 165379 Project ID: 2333

Location: 3609 International Blvd

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

Project Manage

Reviewed by:

Operations Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of _______

CHAIN OF CUSTODY

Curtis & Tompkins, Ltd.

Analytical Laboratory Since 1878 2323 Fifth Street Berkeley, CA 94710 (510)486-0900 Phone (510)486-0532 Fax

Analyses

Report To:

Sampler:

Fax:

Tony Perini

Project Name:3609 International Blvd., Oaklanc Company:

SOMA Environmental

Mehran Nowroozi

Turnaround Time: Standard

Project No: 2333

925-244-6600 Telephone:

925-244-6601

Preservative Matrix Soil Water Waste H2SO₄ HNO₃ # of Sampling Date Lab Sample ID. Containers Time No. 3 VOAS X 5/21,03 lo GAM Influent 3 VOAS X 5/21/03 10:55 AM GAC-1 340A5 X 5/21,03 Him An PSP#1

X X X T PHg 8015	X X X BTEX & MTBE 8260 GCMS									i.				
\vdash	╀	┼-	╁	╁	╁	+	╫	\dashv		\vdash	╁╌	十	╁	1
-	\dagger	+	+	+	+	1					I			
				1	I		1			L		<u> </u>	1	4
┟	-	+	=	=	+	<u> </u>	Orto		_	\vdash		\vdash	+	\dashv
H	+	+	Pi	esei Yes	Vall	on C No	ф	N	/A	╁	十	H	+	┪
H		$\frac{1}{2}$		-123	丰	#	丰	=	=	╁			工	
		1	-				I							
	I			\int	\prod									4
R	RECEIVED BY:													

5-21-03

Notes: EDF OUTPUT REQUIRED

RELINQUISHED BY:

4. Moura-2

5/21/03 DATE/TIME

DATE/TIME

DATE/TIME

DATE/TIME

DATE/TIME

21,35 pr

DATE/TIME



Total Volatile Hydrocarbons

Lab #: 165379 Client: SOMA Environmental Engineering Inc.

Location: 3609 International Blvd EPA 5030B Prep:

Project#`: Matrix: Water

8015B 05/21/03 Analysis: Sampled: 05/21/03 Received:

ug/L Units: Batch#: <u>8Ĭ639</u>

| Bromofluorobenzene (FID)

Field ID:

INFLUENT SAMPLE

Diln Fac: Analyzed: 5.000

Type: ab ID:

165379-001

05/23/03

Analyte Result Gasoline C7-C12 9,100

Surrogate Frifluorotoluene (FID) Limits 135 68-145

ield ID:

ıb ID:

Type:

GAC-1

SAMPLE

Diln Fac:

1.000

119

66-143

165379-002

05/23/03 Analyzed:

<u> 250</u>

Analyte Result Anal Gasoline C7-C12 ND 50

Surrogate *REC Limits Trifluorotoluene (FID) 112 68-145 Bromofluorobenzene (FID) 112 66-143

eld ID:

Type: Lab ID:

PSP#1 SAMPLE 165379-003

Diln Fac:

Analyzed:

1.000

05/22/03

Result Analyte asoline C7-C12 50

Surrogate Frifluorotoluene (FID) %REC Limits 68-145 66-143 113 117 <u> Bromofluorobenzene (FID)</u>

BLANK QC214307 Diln Fac:

Analyzed:

1.000 05/22/03

Result RL Analyte <u> Fasoline C7-C12</u> 50

Surrogate FREC Limits Trifluorotoluene (FID) 68-145 112 <u> Bromofluorobenzene (FID)</u> 109 66-143

GC04 TVH 'J' Data File FID

Sample #: a1 Date : 5/23/03 11:08 AM <u>Sample Name : 165379-001,81639,tvh only</u> Page 1 of 1 : G:\GC04\DATA\142J028.raw leName thod : TVHBTXE Time of Injection: 5/23/03 10:53 AM start Time : 0.00 min End Time : 26.00 min Low Point: 40.82 mV High Point: 462.02 mV Scale Factor: 1.0 Plot Offset: 41 mV Plot Scale: 421.2 mV INFLUENT Response [mV] -1.221.50 <u>1.67</u> ≤2.09 2.29 -2.53-3.61 -4.04 ≥4.43 ≥=4.70 C-7 5.41 **5.88 6.70** 6.86 TRIFLUO -7.26 7.54 -8.00 -8.38 -8.75 C-8 -9.24 9.69 9.98 -10.33 -10.76 -11.16 -11.74 12.86 -13.07 -14.10 14.77 BROMOF --15.64 **≻-16.14** C-10 = 16.5916.44 -17.19 -17,56 -18.05 -18.42 -18.75 -----19.48 C-12 -20.00 -20.34 --20.62 -21.00 ≥21.63 -22.18 -22.58 >-22.90 -23.27 >-23.49 24.89 -25.51

GCO4 TVH 'J' Data File FID

imple Name : ccv/lcs,qc214309,81639,03ws0682,5/5000 Page 1 of 1 Sample #: Date: 5/23/03 11:08 AM : G:\GC04\DATA\142J002.raw ethod : TVHBTXE Time of Injection: 5/22/03 12:53 PM End Time : 26.00 min Low Point : 51.13 mV High Point : 246.61 mV Start Time : 0.00 min Scale Factor: 1.0 Plot Offset: 51 mV Plot Scale: 195.5 mV Gasoline Response [mV] 8:35 C-6 -1.29 -1,50 -1.66 1.78-1.88 2.29 -2.51 2.77 <u>-4.05</u> =4.641 5.41 -5.91 -6,86 -8.06 8,63 C-8 9.24 9.73 9.98 10.34 10.84 >-11<u>.42</u> -11.73 2.97 12.60 12.85 -13.07 13.58 -14.10 **BROMOF-**15.64 16.13 C-10 --16.43 -16.58 **⊏16.85** 17.19 -17.56 16.39 18.38 -18.75 ===149.646 20.00 -20 35 - 20 61 27.290 *22.59* -22.89 -23.27 -23.78 23.78 C-12 24.48 -24.9225.51



Total Volatile Hydrocarbons Lab #: 165379 Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc. EPA 5030B Prep: Project#: 2333 8015B Analysis: Type: LCS Diln Fac: 1.000

Type: LCS Diln Fac: 1.000
Lab ID: QC214309 Batch#: 81639
Matrix: Water Analyzed: 05/22/03
Units: ug/L

Analyte		Result		Limits
Gasoline C7-C12	2,000	1,985	99	79-120

Surrogate	%REC	Limits
Trifluorotoluene (FID)	134	68-145
Bromofluorobenzene (FID)	121	66-143



			Total Volatil	e Hydrocar	bons
Lab #:	1653	79		Location:	3609 International Blvd
Client:	SOMA	Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333			Analysis:	8015B
Field ID:	*	ZZZZZZZZZ		Batch#:	81639
MSS Lab II	D:	165391-001		Sampled:	05/21/03
Matrix:		Water		Received:	05/22/03
_Units:		· ug/L		Analyzed:	05/23/03
oiln Fac:		1.000		-	

MS

Lab ID: QC214327

Analyte !		Spiked	Result	%RE(! Limits
Gasoline C7-C12	29.77	2,000	2,012	99	67-120

Surrogate	%REC	Limits
Trifluorotoluene (FID)	137	68-145
Bromofluorobenzene (FID)	126	66-143

Type:

MSD

Lab ID: QC214328

Analyte	Spiked	Result	%REC	Limits	RED	Lim
Gasoline C7-C12	2,000	2,020	99	67-120	0	20

Surrogate	%REC	Limits
Frifluorotoluene (FID)	134	68-145
Bromofluorobenzene (FID)	119	66-143



			Purgeable Aro	matics by G	ec/ms
			_	•	
Lab #:	1653	79		Location:	3609 International Blvd
:lient:	SOMA	Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333		•	Analysis:	EPA 8260B
Field ID:		INFLUENT		Batch#:	81634
ab ID:		165379-001		Sampled:	05/21/03
Matrix:		Water		Received:	05/21/03
Units:		ug/L		Analyzed:	05/22/03
iln Fac:		20.00		-	

Analyte	Result	RL	
MTBE	3,400	100	
Benzene	1,300	100	
Toluene	620	100	
Ethylbenzene	170	100	
n,p-Xylenes 	1,400	100	•
-b-Xylene	430	100	

Surrogate	%REC	Limits	
,2-Dichloroethane-d4	113	77-130	1
Toluene-d8	105	80-120	j
Bromofluorobenzene	92	80-120	-



		Purgeable Arc	matics by GC	:/MS
Lab #:	165379		Location:	3609 International Blvd
	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:	2333		Analysis:	EPA 8260B
Field ID:	GAC-1		Batch#:	81616
Lab ID:	165379-002		Sampled:	05/21/03
Matrix:	Water		Received:	05/21/03
Units:	ug/L		Analyzed:	05/21/03
Diln Fac:	1.000			33, 22, 33

	Result	RL
MTBE	ND	5.0
Benzene	ND	5.0
Toluene	ND	5.0
Ethylbenzene	ND	5.0
m,p-Xylenes	ND	5.0
Ethylbenzene m,p-Xylenes b-Xylene	ND	5.0

Toluene-d8 92 80-120 Bromofluorobenzene 92 80-120	Surrogate	%REC	C Limits
D	1,2-Dichloroethane-d4	103	77-130
Bromofluorobenzene 92 80-120		92	80-120
	Bromofluorobenzene	92	80-120



		Purgeable Arc	matics by	GC/NS
Lab #:	165379		Location:	3609 International Blvd
Client:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:		•	Analysis:	EPA 8260B
Field ID:	PSP#1		Batch#:	81616
Lab ID:	165379-003		Sampled:	05/21/03
Matrix:	Water		Received:	05/21/03
Units:	ug/L		Analyzed:	05/21/03
Diln Fac:	1.000		•	· ·

Analyte	Result	RL .
MTBE	ND	5.0
Benzene	MD.	5.0
Toluene	ND	5.0
Ethylbenzene	ND	5.0
Ethylbenzene m,p-Xylenes b-Xylene	ND	5.0
b-Xylene	ND	5.0

·			
Bromofluorobenzene	92	80-120	·
Toluene-d8	84	80-120	
1,2-Dichloroethane-d4	91	77-130	
Surrogate	%REC	! Limits	



Purgeable Arcmatics by GC/MS

Lab #: 165379 Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B

Project#: 2333 Analysis: EPA 8260B

Type: BLANK Diln Fac: 1.000

Lab ID: QC214213 Batch#: 81616 Matrix: Water Analyzed: 05/21/03

Units: ug/L

Analyte	Result	RL	
MTBE	ND	5.0	
Benzene	ND	5.0	
Toluene	ND.	5.0	
Ethylbenzene	ND	5.0	
Ethylbenzene m,p-Xylenes D-Xylene	ND	5.0	
o-Xylene	ND	5.0	

Bromofluorobenzene	96	80-120
Poluene-d8	93	80-120
.,2-Dichloroethane-d4	103	77-130
	*REC	Limits



	Purgeable Aro	matics by	GC/MS
Lab #:	165379	Location:	3609 International Blvd
Client:	SOMA Environmental Engineering Inc.	Prep:	EPA 5030B
Project#:	2333	Analysis:	EPA 8260B
Type:	BLANK	Diln Fac:	1.000
Lab ID:	QC214281	Batch#:	81634
Matrix:	Water	Analyzed:	05/22/03
Units:	ug/L		

Analyte	Result	RL	
MTBE	ND	5.0	
Benzene	ND	5.0	
Toluene	ND	5.0	
Ethylbenzene	ND	5.0	
Ethylbenzene m,p-Xylenes b-Xylene	ND	5.0	
o-Xylene	ND	5.0	

Surrogate	*REC	Limits
,2~Dichloroethane-d4	110	77-130
Coluene-d8	103	80-120
Bromofluorobenzene	94	80-120



Purgeable Aromatics by GC/MS Lab #: 165379 Location: 3609 International Blvd Client: SOMA Environmental Engineering Inc. Prep: EPA 5030B Project#: 2333 . Analysis: EPA 8260B Matrix: Water Batch#: 81616 Units: ug/L Analyzed: 05/21/03

Type:

Diln Fac:

BS

1.000

Lab ID:

QC214211

Analyte	Spiked	Recult		7887.56
Benzene	50,00	Δ7 72	95	76 120
Toluene	50.00	46.97	93	76-120 79-120
		40.57	24	79-120

Bromofluorobenzene	86	80-120	
Foluene-d8	95	80-120	
1,2-Dichloroethane-d4	102	77-130	
Surrogate	#REC	Limite	

ype:

Toluene-d8

romofluorobenzene

BSD

Lab ID:

QC214212

enzene	FA 05	Result	*RB	Limite		Li
oluene	50.00	46.00	92	76-120	4	20
Jidene	50.00	45.35	91	79-120	4	20

80-120

80-120

95

88



Purgeable Arcmatics by GC/MS

Lab #: 165379 Client: SOMA Environmental Engineering Inc.

Water

Project#: 2333

Location: Prep:

3609 International Blvd

EPA 5030B

Analysis:

EPA 8260B

Batch#: 81634 Analyzed: 05/22/03

Jnits: ug/L biln Fac: 1.000

Type:

Matrix:

BS

Lab ID:

QC214279

Analyte		Depuls	45P/1	
			DAVE	THERE US
Benzene	50.00	49.76	100	76-120
		-2.70		,0 120
Toluene	50.00	54.95	110	79-120

Bromofluorobenzene	90	30-120	
Coluene-d8	101	30-120	
1,2-Dichloroethane-d4	113	77-130	
Surrogate	*REC	Simits	

BSD

Lab ID:

Analyte	501 KAO	\$200 (\$100 \$100 \$100 \$100 \$100 \$100 \$100 \$	%RBC		RPD	Lim
Benzene	50.00	47.65	95	76-120	4	20
Toluene	50.00	51.09	102	79-120	7	20

Surrogate	%REC	Limits	
1,2-Dichloroethane-d4	111	77-130	
Toluene-d8	99	80-120	·
romofluorobenzene	90	80-120	



Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 9471O, Phone (510) 486-0900

ANALYTICAL REPORT

Prepared for:

SOMA Environmental Engineering Inc. 2680 Bishop Dr. Suite 203 San Ramon, CA 94583

Date: 15-MAY-03

Lab Job Number: 165046

Project ID: 2333

Location: 3609 International Blvd

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signatures. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis.

Reviewed by:

Project Manager

Reviewed by:

rations Manager

This package may be reproduced only in its entirety.

NELAP # 01107CA

Page 1 of 12

CHAIN OF CUSTODY FORM

Page ____of ___

DATE/TIME

DATE/TIME

	& Tomp								-			CÉT 1/2 5 (1/					Ana	alys	es ₹°¹	۲۰٫۰٫۰	r [.]	
Analytic	al Laboratory 2323 Fifth S Berkeley, C (510)486-09 (510)486-05	treet A 94710 00 Phone			Sam	pler:		<u>ر و</u>	. \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			C&T 165046										
Project No:	2333	.			Repo	ort To:	6	70	n y		6	erini										
Project Nan	ne: Oakl	and Int			Company: Some Inv																	
Project P.O	•••				Tele	phone:		9 =	۲5	_=	2	44-6600	104	\$ 5 X	7	ļ						
Turnarounc	l Time:				Fax:								- નિ	** **	(A)							
			М	atrix			P	res	erva	ativ	<u>e</u>		-	اہرا	1			İ				
Laboratory Number	Sample ID.	Sampling Date Time	Soil	Waste	Con	# of tainers	HCL	H ₂ SO	HNO3	CE		Field Notes	8015	8260	8260							
-	EFPCUENT	5/1,03	[])				X			\times			+	X	X	_		+	+	+		\dashv
	GAC-IL	5/1/03 em	<u> </u>	4			X			\succeq			(*)	\Rightarrow	$\ddot{\otimes}$	\dashv	-+		- -			-
λ	INFLUENT	5,1,03 em		X			X			\succeq			+×	~	M			\dashv	+	+		\dashv
1 _			<u> </u>					_	_	-			-			\neg		+	+	+-	 	-
0			╽.			<u> </u>	-			-			+-	 				\dashv				1
r e			\vdash	-1-1						_	<u> </u>		+	\vdash	-		-		十	+		-
Oan			\vdash	\dashv	_		 				-		+	1			_		+	+-		7
<u> </u>	<u> </u>		╀	-1-1			╁╌				 		1	1				1	\neg	\top		٦
0			\vdash				-		 	-			\top	\top								٦
Δ	 		┼┼	+	-		+	Ė	\vdash	 	-			\top	 							
<u> </u>			H	+	H		+	一	╁	 	-								\Box			
		 	+	+	-		+	\dagger														
Notes:		<u>.l</u>	1_1	1	 !		1	1	1	'	R	ELINQUISHED BY:				RE	CEI	<u> </u>	BY		·····	
F	PF- 04	trul						<u> </u>	<u> </u>	10	انما	WOOD DATE/TIN	IE .	1	e f	D 51.6	≥	2	5/1 <u>/</u>	OS NATE/	5.30 TIME)pln
	–						_					DATE/TIN	1E				<i>I</i> '			ATE/	TIME	
1											,		- 1									

Signature



Total Volatile Hydrocarbons 3609 International Blvd Location: 165046 ab #: EPA 5030B Prep: Analysis: SOMA Environmental Engineering Inc. <u>C</u>lient: 80<u>15B</u> 2333 05/01/03 Project#: Sampled: Water atrix: 05/01/03 Received: ug/L hits:

ld ID:

asoline C7-C12

atch#:

PSP-1 SAMPLE

B1243

Diln Fac: Analyzed:

1.000 05/02/03

Lab ID:

165046-001

Analyte

Kesult 50 ND

RREC Limits Surrogate rifluorotoluene (FID) romofluorobenzene (FID) 68-145 97 109 66-143

eld ID:

GAC-1 SAMPLE

165046-002

Diln Fac: Analyzed: 1.000

05/02/03

Result Analyte

50 soline C7-C12 %REC LABORES Surrogate

94 68-145 rifluorotoluene (FID) <u>107</u> 66-143 romofluorobenzene (FID)

eld ID:

ne: ab ID: INFLUENT

SAMPLE 165046-003 Diln Fac:

Analyzed:

5.000

05/03/03

Result Amalyte 250 12,000 asoline C7-C12 SRECH INDICES Surrogate 68-145 109 Trifluorotoluene (FID) 66-143 Bromofluorobenzene (FID) 109


BLANK QC212772 Diln Fac: Analyzed:

1.000 05/02/03


Result Analyte Gasoline_C7-C12 lea made s %REC Surrogate 68-145 95 Trifluorotoluene (FID) 104 66-143 Bromofluorobenzene (FID)


D= Not Detected L= Reporting Limit age 1 of 1

GC07 TVH 'A' Data File RTX 502



GC07 TVH 'A' Data File RTX 502





Total Volatile Hydrodarbons 3609 International Blvd Location: 165046 EPA 5030B SOMA Environmental Engineering Inc. Prep: ient: 8015B Analysis: Project#: 2333 1.000 Diln Fac: LCS pe: 81243 Batch#: QC212774 b ID: 05/02/03 Analyzed: Water Matrix: ug/L

1			Pesili	%REC	Limits
. !	Analyte	spired	1.011	101	79-120
1	Gasoline C7-C12	1,000	2,010		

П	· · · · · · · · · · · · · · · · · · ·			
		**********	Limits	
,	Servocace		CO 345	
	Trifluorotoluene (FID)	108	68-145	·
1	romofluorobenzene (FID)	104	66-143	

Inits:



1	Total Volstil	e Hydrocarbo	
ab #: 1650 lient: SOMA Project#: 2333	Environmental Engineering Inc.	Location: Prep: Analysis:	3609 International Blvd EPA 5030B 8015B
piolectw. 2333 mield ID: SS Lab ID: Vatrix: Units: iln Fac:	PSP-1 165046-001 Water ug/L 1.000	Batch#: Sampled: Received: Analyzed:	81243 05/01/03 05/01/03 05/02/03

ne:

MS

Lab ID:

QC212775

	346.60 (December	Spiked	Result	*RE	Limits
Analyte	MSS Xesuro	2 000	1 917	96	67-120
asoline C7-C12	<18.00	2,000			

Surrogate	%REC	Linits	1
rifluorotoluene (FID)	114	68-145	
romofluorobenzene (FID)	116	66-143	1

_ype:

MSD

Lab ID:

		Pagnit	%REC	Limits	RPD:	Lim
Analyte	Spakeu	1 231	92	67-120	5	20
Gasoline C7-C12	2,000	1,051				

Surrogate	%REC	: Limits	
Trifluorotoluene (FID)	112	68-145	·
Bromofluorobenzene (FID)	113	66-143	



		Purgeable Aro	matics by (
m ab #:	165046		Location:	3609 International Blvd
lient:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
Project#:		<u> </u>	Analysis:	EPA 8260B
Field ID:	PSP-1		Batch#:	81241
ab ID:	165046-001	•	Sampled:	05/01/03
matrix:	Water		Received:	05/01/03
Units:	ug/L		Analyzed:	05/02/03
iln Fac:	1.000			


Result	RL	
ND	5.0	ļ
ND	5.0	
ND	5.0	i
ND	5.0	
ND	5.0	i
ND	5.0	
	ND ND ND ND ND	ND 5.0 ND 5.0 ND 5.0 ND 5.0 ND 5.0

Surrogate	%REC	Limits
,2-Dichloroethane-d4	117	77-130
. Toluene-d8	109	80-120
Bromofluorobenzene	98	80-120



Analyte	Result	RL
MTBE	ND ·	5.0
	ND	5.0
Coluene	ND	5.0
Ethylbenzene	ND	5.0
n-Xvlenes	ND	5.0
Benzene Foluene Ethylbenzene n,p-Xylenes b-Xylene	ND	5.0

Surrogate	%REC	Limits	
1,2-Dichloroethane-d4	108	77-130	
Foluene-d8	103	80-120	ŀ
Bromofluorobenzene	96	80-120	



		Purgeable Aro	matics by	/ GC/MS
ab #:	165046		Location:	
lient:	SOMA Environmental	Engineering Inc.	Prep:	EPA 5030B
roject#:	2333		Analysis:	EPA 8260B
ield ID:	INFLUENT		Batch#:	81241
ab ID:	165046-003		Sampled:	05/01/03
atrix:	Water		Received:	05/01/03
nits:	ug/L		Analyzed:	05/02/03
iln Fac:	25.00			

Analyte	Result	RL	
TBE	4,200	130	
enzene	1,400	130	
Toluene	760	130	
Ethylbenzene	310	130	
, p-Xylenes	1,600	130	
Ethylbenzene ,,p-Xylenes o-Xylene	500	130	

Surrogate	%REC	Limits		
,2-Dichloroethane-d4	110	77-130	•	
Toluene-d8	99	80-120		
<pre>promofluorobenzene</pre>	97	80-120		



	Purgeable Arc	omatics by (GC/MS
_ ab #:	165046	Location:	3609 International Blvd
lient:	SOMA Environmental Engineering Inc.	Prep:	EPA 5030B
Project#:	2333	Analysis:	EPA 8260B
Type:	BLANK	Diln Fac:	1.000
ab ID:	QC212767	Batch#:	81241
atrix:	Water	Analyzed:	05/02/03
Units:	ug/L		•

	Analyte	Result	RL	
MTBE		ND	5.0	
enzen	e	ND	5.0	
oluen	e	ND	5.0	
Ethylb	enzene	ND	5.0	
Ethylb m,p-Xy	lenes	ND	5.0	
-Xyle	ne	ND	5.0	

Surrogate	*REC	Limits		
, 2-Dichloroethane-d4	103	77-130		İ
oluene-d8	101	80-120	•	
Bromofluorobenzene	98	80-120		



Purgeable Aromatics by GC/MS

ab #: 165046

SOMA Environmental Engineering Inc.

?roject#: 2333

lient:

Matrix: nits:

iln Fac:

Location:

3609 International Blvd

EPA 5030B

Prep: Analysis:

EPA 8260B

Batch#:

Analyzed:

81241

05/02/03

BS

Water

ug/L 1.000

Lab ID:

QC212764

Analyte	Spiked		%REC	Limits
Benzene	50.00	48.65	97	76-120
<u>T</u> oluene	50.00	52.23	104	79-120

I	Surrogate	%RE(2 Limits		
Ì	1,2-Dichloroethane-d4	91	77-130		
ı	oluene-d8	98	80-120		
ı	romofluorobenzene	92	80-120	 	

BSD

Lab ID:

Analyte	Spiked	Result	%RBC	Limits	RPD	Lim
enzene	50.00	48.16	96	76-120	1	20
Toluene	50.00	52.83	106	79-120	1	20

			·	
Surrogate	%REC	Limits		
1,2-Dichloroethane-d4	90	77-130		
Toluene-d8	99	80-120		!
romofluorobenzene	92	80-120		