





Storm drain Alice St Sample w-2
7/18/91



San Capped off pipe in between parking
spaces 12 & 13 Alice St Structure basement
taken 10:30 AM 7/18/91 Sample w-3



Storm drain Alice Basement
Sample w-2 taken 7/18/91



Sample taken from hoist room opening
W-1 at Harrison St parking structure
11:45 7/18/91

1432 Harrison


Prabu called 7/17/91

wants to sample - re:

- basement drain
- capped off pipe in between
space 127 B
- wash room sump
- Gasoline tanks



1432 Harrison St wash room Sump Sample
S-1 taken underneath steel plate & soil
7/18/91 11:05 AM



Capped off pipe Alice St basement
between spaces 127 B
Sample W-3 collected 7/18/91 10:30



pipeline samples Alice St basement
1/14/92