RO27/

| UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT | | | |
|--|--|--|--|
| EMERGENCY YES NO REPORT DATE OM 7 M 2 d 2 d 9 y / y | | FOR LOCAL AGENCY USE ONLY THEREBY CERTIFY THAT I HAVE DISTRIBUTED THIS INFORMATION ACCORDING TO THE DISTRIBUTION SHOWN ON THE INSTRUCTION SHEET ON THE BACK PAGE OF THIS FORM THE BACK PAGE OF THIS FORM | |
| REPORTED BY | NAME OF INDIVIDUAL FILING REPORT PHON PAUL SMITH (41 REPRESENTING OWNER/OPERATOR REGIONAL BOARD | · · | |
| | Alameda County Hazardous Materials 80 Swan Way Room 200 Oakland CA 201 | | |
| RESPONSIBLE | NAME | CONTACT PERSON | PHONE |
| | Better Homes Realty UNKNOWN ADDRESS 5942 MacArthur Blvd | Lynn Worthington Oakland | (415) 562-8600 |
| SITE LOCATION | FACILITY NAME (IF APPLICABLE) | OPERATOR | PHONE 946Q5 |
| | ADDRESS 3055 35th Avenue CROSS STREET | Oakland CA A | lameda 94605 |
| D AGENCIES | School Street | CONTACT PERSON | PHONE |
| | Alameda County Hazardous Materials | | (415) 271-4320 PHONE |
| | Sall Flancisco Bay | Lester Feldman | 415)264-1255 QUANTITY LOST (GALLONS) |
| SUBSTANCES | Gasoline © | | X UNKNOWN |
| DISCOVERY/ABATEMENT | DATE DISCOVERED HOW DISCOVERED INVENTORY CONTROL SUBSURFACE MONITORING NUISANCE CONDITIONS Q 1 M 1 J 7 J 9 1 TANK TEST TANK REMOVAL OTHER | | |
| | DATE DISCHARGE BEGAN METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY) M M O D Y Y V X UNKNOWN REMOVE CONTENTS X CLOSE TANK & REMOVE REPAIR PIPING HAS DISCHARGE BEEN STOPPED ? REPAIR TANK CLOSE TANK & FILL IN PLACE CHANGE PROCEDURE X YES NO #YES, DATE Q J 1 D 7 D 9 1 Y REPLACE TANK OTHER | | |
| SOURCE/ CAUSE | | REPTURE/FAILURE | SPILL OTHER |
| CASE | CHECK ONE ONLY WHO TERMINED SOIL ONLY GROUNDWATER DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED). CHECK ONE ONLY | | |
| CURRENT | NO ACTION TAKEN PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED POLLUTION CHARACTERIZATION LEAK BEING CONFIRMED PRELIMINARY SITE ASSESSMENT UNDERWAY POST CLEANUP MONITORING IN PROGRESS REMEDIATION PLAN CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY) CLEANUP UNDERWAY | | |
| REMEDIAL | CHECK APPROPRIATE ACTION(S) SEE BACK FOR DETAILE) CAP SITE (CD) EXCAVATE & DISPOSE (ED) PUMP & TREAT GROUNDWATER (GT) REPLACE SUPPLY (RS) CONTAINMENT BARRIER (CB) NO ACTION REQUIRED (NA) TREATMENT AT HOOKUP (HU) VENT SOIL (VS) | | |
| COMMENTS | RP HAS NOT PROVIDED OUR OFFICE WI site during sampling noted contami been provided on the amount and ex | TH REMOVAL REPORT. Spec nation. To date, no info tent of contamination. | ialist at the ormation has |

HSC 05 (8/90)