Environmental Management Company 6001 Bollinger Canyon Rd, L4050 P.O. Box 6012 San Ramon, CA 94583-2324 Tel 925-842-1589 Fax 925-842-8370 Karen Streich Project Manager R > 774
Alameda County

JUN 2 7 2003

Environmental Health

ChevronTexaco

June 25 , 2003

Alameda County Health Care Services 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

| Re: | Chevron Ser | vice Station # | | |
|--------|--------------|--|---------------|--|
| | Address: | 7225 Bancroft Avenue, Oakland, CA | | |
| | | | June 24, 2003 | |
| I have | reviewed the | attached routine groundwater monitoring report dated | | |

I agree with the conclusions and recommendations presented in the referenced report. The information in this report is accurate to the best of my knowledge and all local Agency/Regional Board guidelines have been followed. This report was prepared by Gettler-Ryan, Inc., upon whose assistance and advice I have relied.

This letter is submitted pursuant to the requirements of California Water Code Section 13267(b)(1) and the regulating implementation entitled Appendix A pertaining thereto.

I declare under penalty of perjury that the foregoing is true and correct.

Sincerely,

Karen Streich Project Manager

Kuren Sheich

Enclosure: Report

Alameda County



JUN 2 7 2003

Environmental Health

June 10, 2003 G-R #386433

TO:

Mr. Robert Foss

Cambria Environmental Technology, Inc.

5900 Hollis Street, Suite A Emeryville, CA 94608 CC: Ms. Karen Streich

Chevron Products Company

P.O. Box 6004

San Ramon, California 94583

FROM:

Deanna L. Harding

Project Coordinator Gettler-Ryan Inc.

6747 Sierra Court, Suite J Dublin, California 94568 **RE:** Chevron Service Station

#9-3322 7225 Bancroft Avenue

Oakland, California

WE HAVE ENCLOSED THE FOLLOWING:

| COPIES | DATED | DESCRIPTION |
|--------|--------------|---|
| 1 | June 6, 2003 | Groundwater Monitoring and Sampling Report Second Quarter - Event of May 2, 2003 |

COMMENTS:

This report is being sent for your review. Please provide any comments/changes and propose any groundwater monitoring modifications for the next event prior to *June 24, 2003*, at which time the final report will be distributed to the following:

cc: Mr. Don Hwang, Alameda County Health Care Services, Dept. of Environmental Health, 1131Harbor Bay Parkway, Suite 250, Alameda, CA 94502-6577

Mr. Amar Sidhu, 32875 Bluebird Loop, Fremont, CA 94555

Enclosures

June 6, 2003 G-R Job #386433

Ms. Karen Streich Chevron Products Company P.O. Box 6004 San Ramon, CA 94583

RE: Second Quarter Event of May 2, 2003

Groundwater Monitoring & Sampling Report

Chevron Service Station #9-3322

7225 Bancroft Avenue Oakland, California

Dear Ms. Streich:

This report documents the most recent groundwater monitoring and sampling event performed by Gettler-Ryan Inc. (G-R) at the referenced site. All field work was conducted in accordance with G-R Standard Operating Procedure - Groundwater Sampling (attached).

Static groundwater levels were measured and the wells were checked for the presence of separate-phase hydrocarbons. Static water level data, groundwater elevations and separate-phase hydrocarbon thickness (if any) are presented in the attached Table 1. A Potentiometric Map is included as Figure 1.

Groundwater samples were collected from the monitoring wells and submitted to a state certified laboratory for analyses. The field data sheets for this event are attached. Analytical results are presented in the table(s) listed below. The chain of custody document and laboratory analytical report are also attached.

No. 7285

Please call if you have any questions or comments regarding this report. Thank you.

Sincerely,

Deanna L. Harding Project Coordinator

Robert C. Mallory

Registered Geologist, No. 7285

Figure 1:

Potentiometric Map

Table 1:

Groundwater Monitoring Data and Analytical Results

Table 2:

Groundwater Analytical Results - Oxygenate Compounds Standard Operating Procedure - Groundwater Sampling

Attachments: Standard Operatin Field Data Sheets

Chain of Custody Document and Laboratory Analytical Reports




Table 1
Groundwater Monitoring Data and Analytical Results
Chevron Service Station #9-3322

vron Service Station #9-3 7225 Bancroft Avenue Oakland, California

| | | | | | SPH | | | 150 | 87 | X | MTBE |
|----------|-------|---------|-------|----------------|------------|-------------------------|--------------|-------------|------------|------------|--------------|
| WELL ID/ | TOC* | GWE | DTW | SPHT | REMOVED | TPH-G | В | T | E (aph) | X (ppb) | (ppb) |
| DATE | (fi.) | (msl) | (ft.) | (ft.) | (gallons) | (ррв) | (ppb) | (ppb) | (pph) | SUPUL. | <i>1000</i> |
| MW-1 | | | | | | | | | | | -0.FA |
| 02/08/98 | 40.41 | 26.53 | 13.88 | | | 130,000 | 9,700 | 8,200 | 3,200 | 15,000 | <250 |
| 06/16/98 | 40.41 | 26.18 | 14.23 | | | 96,000 | 15,000 | 12,000 | 2,600 | 11,000 | 1,300 |
| 07/29/98 | 40.41 | 22.59 | 17.82 | | | 370,000 | 19,000 | 14,000 | 5,800 | 15,000 | <2,500 |
| 08/13/98 | 40.41 | 22.01 | 18.40 | | | 120,000 | 19,000 | 16,000 | 2,900 | 14,000 | <1,000 |
| 11/24/98 | 40.41 | 19.61 | 20.80 | | | 100,000 | 26,000 | 18,000 | 4,000 | 22,000 | 2,000 |
| 02/03/99 | 40.41 | 22.96 | 17.45 | - - | | 110,000 | 27,000 | 16,000 | 3,800 | 22,000 | <2.5 |
| 06/07/99 | 40.41 | 24.29** | 16.44 | 0.40 | 0.03 | | | | | | |
| 09/07/99 | 40.41 | 19.97** | 20.71 | 0.34 | 0.01 | | | | | | |
| 10/27/99 | 40.41 | 18.93** | 21.75 | 0.34 | 0.03 | | | | | | |
| 02/08/00 | 40.41 | 22.44 | 17.97 | 0.00 | 0.00 | 147,000 | 19,600 | 13,700 | 4,020 | 21,300 | <2,500 |
| 05/05/00 | 40.41 | 24.36 | 16.05 | 0.00 | 0.00 | 150,000 ² | 28,000 | 17,000 | 4,400 | 23,000 | <1,000 |
| 07/28/00 | 40.41 | 21.21 | 19.20 | 0.00 | 0.00 | 76,000 ² | 20,000 | 15,000 | 3,400 | 23,000 | 1,200 |
| 11/26/00 | 40.41 | 20.44** | 20.18 | 0.26 | 0.264 | NOT SAMPLE | D DUE TO THE | PRESENCE OF | F SPH | | |
| 02/09/01 | 40.41 | 22.40** | 18.03 | 0.03 | 0.26^{4} | NOT SAMPLE | D DUE TO THE | PRESENCE O | F SPH | | |
| 05/11/01 | 40.41 | 25.31 | 15.10 | 0.00 | 0.00 | 89,000 ² | 21,000 | 12,000 | 3,200 | 14,000 | <500 |
| 08/30/01 | 40.41 | 20.05** | 20.42 | 0.07 | 0.264 | NOT SAMPLE | D DUE TO THE | PRESENCE OF | F SPH | | |
| 11/21/01 | 40.41 | 20.11** | 20.52 | 0.27 | 0.00 | NOT SAMPLE | D DUE TO THE | PRESENCE OF | F SPH | | |
| 02/05/02 | 40.41 | 25.79** | 14.63 | 0.01 | 0.00 | 130,000 | 16,000 | 13,000 | 4,200 | 23,000 | <30 |
| 04/01/02 | 37.40 | 25.03 | 12.37 | 0.00 | 0.00 | | | | | | · |
| 08/05/02 | 37.40 | 24.46 | 12.94 | 0.00 | 0.00 | 230,000 | 12,000 | 9,000 | 5,500 | 28,000 | 280 |
| 11/04/02 | 37.40 | 17.37 | 20.03 | 0.00 | 0.00 | 130,000 | 24,000 | 15,000 | 3,900 | 20,000 | <60 |
| 02/03/03 | 37.40 | 23.22 | 14.18 | 0.00 | 0.00 | 100,000 | 13,000 | 8,900 | 3,000 | 15,000 | <130 |
| 05/02/03 | 37.40 | 24.12 | 13.28 | 0.00 | 0.00 | 140,000 | 9,900 | 5,900 | 4,200 | 21,000 | <130 |
| | | | | | | | | | | | |
| MW-2 | | | | | | 2 4 3 2 2 | 120 | 170 | 450 | 1,900 | 2,300 |
| 02/08/98 | 38.73 | 31.13 | 7.60 | - - | | 24,000 | 130 | 170 | 450 310 | | 2,300 260 |
| 06/16/98 | 38.73 | 29.61 | 9.12 | | | 8,900 | 31 | 46 | 310 | 1,100 | |
| 07/29/98 | 38.73 | 27.06 | 11.67 | | | 7,600 | 15 | 21 | 150 | 480 | 82 |
| 08/13/98 | 38.73 | 26.32 | 12.41 | | | 14,000 | 26 | 80 | 500 | 2,100 | 32 |
| 11/24/98 | 38.73 | 23.10 | 15.63 | | | 37,000 | 63 | 220 | 1,300 | 7,100 | 770 |
| 02/03/99 | 38.73 | 27.16 | 11.57 | | - | 16,000 | 140 | 110 | 850 | 3,100 | 900 |

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron Service Station #9-3322

evron Service Station #9-3: 7225 Bancroft Avenue Oakland, California

| | | | | | SPH | | | | | | |
|----------------------|-------|----------------|-------|-----------|-------------|--------------------|--------|-------|-------|--------|-------------|
| WELL ID/ | TOC* | GWE | DTW | SPHT | REMOVED | TPH-G | В | T | E | X | MTBE |
| DATE | (ft.) | (msl) | (ft.) | (ft.) | (gallons) | (ppb) | (ppb) | (ppb) | (ppb) | (ppb) | (ppb) |
| MW-2 (cont) | | | | | | | | | | | 160 |
| 06/07/99 | 38.73 | 27.78 | 10.95 | | | 4,300 | <10 | <10 | 120 | 260 | 160 |
| 09/07/99 | 38.73 | 26.00 | 12.73 | _ | | 10,700 | 50.5 | <25 | 297 | 1,020 | <250 |
| 10/27/99 | 38.73 | 26.02 | 12.71 | | | 7,240 | 53.8 | 31.9 | 234 | 654 | 448 |
| 02/08/00 | 38.73 | 28.59 | 10.14 | | ** | 10,100 | 42.9 | 18.4 | 424 | 1,480 | 206 |
| 05/05/00 | 38.73 | 28.61 | 10.12 | 0.00 | 0.00 | 7,800 ² | 34 | 22 | 320 | 1,100 | 170 |
| 07/28/00 | 38.73 | 26.16 | 12.57 | 0.00 | 0.00 | $6,700^2$ | 40 | 13 | 490 | 540 | 190 |
| 11/26/00 | 38.73 | 26.83 | 11.90 | 0.00 | 0.00 | 8,200 ² | 21 | 9.5 | 400 | 1,100 | 120 |
| 02/09/01 | 38.73 | 26.53 | 12.20 | 0.00 | 0.00 | $11,200^3$ | <50.0 | <50.0 | 629 | 1,380 | 282 |
| 05/11/01 | 38.73 | 29.75 | 8.98 | 0.00 | 0.00 | 6,800 ² | 39 | 19 | 370 | 1,100 | 67 |
| 08/30/01 | 38.73 | 25.83 | 12.90 | 0.00 | 0.00 | 17,000 | 67 | <25 | 750 | 2,100 | 360 |
| 11/21/01 | 38.73 | 25.61 | 13.12 | 0.00 | 0.00 | 3,500 | 14 | <5.0 | 100 | 51 | 610 |
| 02/05/02 | 38.73 | 30.38 | 8.35 | 0.00 | 0.00 | 10,000 | 5.5 | <10 | 330 | 960 | 63 |
| 04/01/02 | 35.72 | 27.91 | 7.81 | 0.00 | 0.00 | | | | · | _ | |
| 08/05/02 | 35.72 | 19.81 | 15.91 | 0.00 | 0.00 | 8,800 | 18 | 8.2 | 220 | 630 | 220 |
| 11/04/02 | 35.72 | 21.58 | 14.14 | 0.00 | 0.00 | 14,000 | 28 | 10 | 670 | 1,600 | 4 40 |
| 02/03/03 | 35.72 | 25.72 | 10.00 | 0.00 | 0.00 | 7,200 | 6.2 | 2.7 | 140 | 430 | 50 |
| 05/02/03 | 35.72 | 27.41 | 8.31 | 0.00 | 0.00 | 12,000 | <20 | 3.9 | 350 | 1,500 | 150 |
| | | | | | | | | | | | |
| MW-3 | 39.51 | 24.91 | 14.60 | | | 94,000 | 12,000 | 4,400 | 2,000 | 10,000 | 8,000 |
| 02/08/98 | 39.51 | 25.53 | 13.98 | | | 38,000 | 5,600 | 1,400 | 1,200 | 4,700 | 6,300/4,600 |
| 06/16/98 07/29/98 | 39.51 | 22.14 | 17.37 | <u></u> | | 58,000 | 4,100 | 700 | 1,300 | 4,200 | 4,100 |
| | 39.51 | 21.29 | 18.22 | | | 43,000 | 6,800 | 1,900 | 1,600 | 6,800 | 2,300 |
| 08/13/98 | 39.51 | 19.06 | 20.45 | | · | 40,000 | 5,000 | 800 | 1,600 | 6,800 | 6,000/4,400 |
| 11/24/98 | 39.51 | 22.03 | 17.48 | | | 47,000 | 7,100 | 1,600 | 1,900 | 9,000 | 5,000 |
| 02/03/99 | | 23.76 | 15.75 | | 48 | 27,000 | 2,500 | 540 | 1,200 | 3,900 | 2,800 |
| 06/07/99 | 39.51 | 23.76 19.80 | 19.71 | | | 44,000 | 3,930 | 1,170 | 1,760 | 7,130 | 3,440 |
| 09/07/99 | 39.51 | 19.80 | 20.42 | | | 28,200 | 2,030 | 620 | 1,260 | 5,080 | 1,710 |
| 10/27/99 | 39.51 | | | | | 25,300 | 2,000 | 668 | 1,210 | 5,330 | 1,760 |
| 02/08/00 | 39.51 | 21.76 | 17.75 | 0.00 | 0.00 | $27,000^2$ | 2,600 | 960 | 1,500 | 5,200 | 2,500 |
| 05/05/00 | 39.51 | 23.87 | 15.64 | 0.00 | 0.00 | 7,400 ² | 950 | 360 | 840 | 3,200 | 1,700 |
| 07/28/00 | 39.51 | 21.28 | 18.23 | 0.00 | 0.00 | /, + ∪∪ | 7,00 | 200 | 0.10 | 2,200 | ., |

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron Service Station #9-3322

evron Service Station #9-33 7225 Bancroft Avenue Oakland, California

| WELL ID/ | TOC* | GWE | DTW | SPHT | SPH REMOVED | TPH-G | В | т | E | X | мтве |
|-------------|-------|-------|-------|-------|----------------|---------------------|--------------|--------|--------|--------|--------------|
| DATE | (ft.) | (msl) | (fi.) | (ft.) | (gallons) | <u>(ppb)</u> | (ррв) | (ppb) | (ppb) | (ppb) | (ррв) |
| | | | | | | | | | | | |
| MW-3 (cont) | | | | 0.00 | 0.00 | 20,000 ² | 1,800 | 690 | 1,400 | 5,500 | 1,600 |
| 11/26/00 | 39.51 | 20.13 | 19.38 | 0.00 | | 31,200 ³ | 1,980 | <50.0 | 1,770 | 7,220 | 2,170 |
| 02/09/01 | 39.51 | 21.79 | 17.72 | 0.00 | 0.00 | 18,000 ² | 3,000 | 780 | 1,600 | 5,500 | 1,800 |
| 05/11/01 | 39.51 | 24.86 | 14.65 | 0.00 | 0.00 | | 570 | 180 | 610 | 1,900 | 880 |
| 08/30/01 | 39.51 | 20.16 | 19.35 | 0.00 | 0.00 | 9,400 | | | 1,500 | 6,100 | 1,200 |
| 11/21/01 | 39.51 | 19.47 | 20.04 | 0.00 | 0.00 | 29,000 | 1,100 | 450 | | 2,400 | 1,100 |
| 02/05/02 | 39.51 | 25.42 | 14.09 | 0.00 | 0.00 | 16,000 | 820 | 210 | 830 | | |
| 04/01/02 | 36.53 | 24.32 | 12.21 | 0.00 | 0.00 | | | | | | 830 |
| 08/05/02 | 36.53 | 22.22 | 14.31 | 0.00 | 0.00 | 11,000 | 310 | 92 | 380 | 820 | |
| 11/04/02 | 36.53 | 17.50 | 19.03 | 0.00 | 0.00 | 32,000 | 1,900 | 540 | 1,800 | 5,900 | 1,500 |
| 02/03/03 | 36.53 | 22.58 | 13.95 | 0.00 | 0.00 | 19,000 | 1,100 | 240 | 920 | 2,900 | 1,100 |
| 05/02/03 | 36.53 | 23.46 | 13.07 | 0.00 | 0.00 | 18,000 | 1,200 | 270 | 1,100 | 2,500 | 1,400 |
| | | | | | | | | | | | • |
| MW-4 | 40.04 | 37.07 | 13.17 | | | <50 | 0.52 | <0.5 | <0.5 | <0.5 | 6.0 |
| 02/02/99 | 40.24 | 27.07 | | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 06/07/99 | 40.24 | 23.83 | 16.41 | | | <50 . | <0.5 | <0.5 | <0.5 | <0.5 | <5.0 |
| 09/07/99 | 40.24 | 19.34 | 20.90 | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 10/27/99 | 40.24 | 18.65 | 21.59 | | | <50 <50 | <0.5 <0.5 | <0.5 | <0.5 | <0.5 | <5.0 |
| 02/08/00 | 40.24 | 23.08 | 17.16 | | _ | | | <0.50 | <0.50 | <0.50 | <2.5 |
| 05/05/00 | 40.24 | 24.22 | 16.02 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <0.50 | <2.5 |
| 07/28/00 | 40.24 | 21.12 | 19.12 | 0.00 | 0.00 | <50 | <0.50 | | <0.50 | <0.50 | <2.5 |
| 11/26/00 | 40.24 | 20.32 | 19.92 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.500 | <0.500 | <2.50 |
| 02/09/01 | 40.24 | 22.79 | 17.45 | 0.00 | 0.00 | <50.0 | <0.500 | <0.500 | | | <2.5 |
| 05/11/01 | 40.24 | 25.22 | 15.02 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <0.50 | <2.5 <2.5 |
| 08/30/01 | 40.24 | 19.91 | 20.33 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <0.50 | |
| 11/21/01 | 40.24 | 20.49 | 19.75 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 02/05/02 | 40.24 | 26.18 | 14.06 | 0.00 | 0.00 | <50 | < 0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 04/01/02 | 37.29 | 25.23 | 12.06 | 0.00 | 0.00 | | | | | | |
| 08/05/02 | 37.29 | 20.24 | 17.05 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 11/04/02 | 37.29 | 17.56 | 19.73 | 0.00 | 0.00 | <50 | < 0.50 | <0.50 | < 0.50 | <1.5 | <2.5 |
| 02/03/03 | 37.29 | 23.24 | 14.05 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 05/02/03 | 37.29 | 24.44 | 12.85 | 0.00 | 0.00 | <50 | < 0.5 | <0.5 | <0.5 | <1.5 | <2.5 |

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron Service Station #9-3322

evron Service Station #9-33 7225 Bancroft Avenue Oakland, California

| معواوت والا | | A19.224 | PARTY I | Christ | SPH REMOVED | TPH-G | В | Т | E | X | МТВЕ |
|-------------|-------|---------|--------------|-----------|----------------|---------------------|---------|---------|-------------|---------|-------|
| WELL ID/ | TOC* | GWE | DTW | SPHT | (gallons) | (ppb) | (ppb) | (ppb) | (ppb) | (ppb) | (ppb) |
| DATE | (f1.) | (msl) | <u>(ft.)</u> | (ft.) | (guaons) | <u> </u> | 8444 | NVP-07 | | | |
| MW-5 | | | | | | | | | | • | |
| 02/02/99 | 40.37 | 21.57 | 18.80 | | | 72 | 2.7 | <0.5 | < 0.5 | <0.5 | 11 |
| 06/07/99 | 40.37 | 23.39 | 16.98 | | 44 | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 09/07/99 | 40.37 | 19.24 | 21.13 | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | 6.92 |
| 10/27/99 | 40.37 | 18.45 | 21.92 | | | <50 | 2.39 | < 0.5 | < 0.5 | <0.5 | 21.3 |
| 02/08/00 | 40.37 | 21.39 | 18.98 | · | | <50 | 10.6 | <0.5 | <0.5 | <0.5 | 21.7 |
| 05/05/00 | 40.37 | 23.48 | 16.89 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | <0.50 | <0.50 | 3.8 |
| 07/28/00 | 40.37 | 20.88 | 19.49 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | < 0.50 | <0.50 | <2.5 |
| 11/26/00 | 40.37 | 19.68 | 20.69 | 0.00 | 0.00 | <50 | 0.57 | <0.50 | < 0.50 | < 0.50 | 15 |
| 02/09/01 | 40.37 | 21.50 | 18.87 | 0.00 | 0.00 | <50.0 | < 0.500 | < 0.500 | < 0.500 | < 0.500 | 9.11 |
| 05/11/01 | 40.37 | 24.47 | 15.90 | 0.00 | 0.00 | <50 | < 0.50 | <0.50 | < 0.50 | <0.50 | <2.5 |
| 08/30/01 | 40.37 | 19.76 | 20.61 | 0.00 | 0.00 | <50 | < 0.50 | <0.50 | < 0.50 | < 0.50 | 9.5 |
| 11/21/01 | 40.37 | 19.33 | 21.04 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | 7.3 |
| 02/05/02 | 40.37 | 25.16 | 15.21 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | <2.5 |
| 04/01/02 | 37.40 | 23.95 | 13.45 | 0.00 | 0.00 | | | | | | |
| 08/05/02 | 37.40 | 19.86 | 17.54 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | < 0.50 | <1.5 | 2.7 |
| 11/04/02 | 37.40 | 17.33 | 20.07 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | 6.3 |
| 02/03/03 | 37.40 | 22.37 | 15.03 | 0.00 | 0.00 | <50 | < 0.50 | 0.60 | < 0.50 | <1.5 | <2.5 |
| 05/02/03 | 37.40 | 23.44 | 13,96 | 0.00 | 0.00 | <50 | <0.5 | <0.5 | < 0.5 | <1.5 | <2.5 |
| 05/02/05 | | | | | | | | | • | · | |
| MW-6 | | | | | | | | | | 170 | -250 |
| 02/02/99 | 39.84 | 21.36 | 18.48 | | | 14,000 | 5,600 | <50 | 150 | 160 | <250 |
| 06/07/99 | 39.84 | 23.39 | 16.45 | | | 1,500 | 1,100 | 33 | 25 | 34 | 200 |
| 09/07/99 | 39.84 | 19.35 | 20.49 | | | 6,550 | 2,940 | 81.5 | 177 | 84 | 865 |
| 10/27/99 | 39.84 | 18.61 | 21.23 | | | 3,680 | 1,240 | 29.6 | 115 | 14.9 | 735 |
| 02/08/00 | 39.84 | 21.44 | 18.40 | | | 17,300 | 8,920 | <100 | 378 | 211 | 2,610 |
| 05/05/00 | 39.84 | 23.48 | 16.36 | 0.00 | 0.00 | 4,200 ² | 1,900 | 98 | 170 | 290 | 1,300 |
| 07/28/00 | 39.84 | 20,90 | 18.94 | 0.00 | 0.00 | 1,200 ² | 660 | 30 | 83 | 36 | 650 |
| 11/26/00 | 39.84 | 19.71 | 20.13 | 0.00 | 0.00 | 7,600 ² | 4,300 | 63 | 360 | 110 | 2,000 |
| 02/09/01 | 39.84 | 21.44 | 18.40 | 0.00 | 0.00 | 18,200 ³ | 7,090 | <100 | 45 7 | 169 | 2,930 |
| 05/11/01 | 39.84 | 24.39 | 15.45 | 0.00 | 0.00 | 2,600 ² | 2,300 | 31 | 88 | 40 | 990 |
| 08/30/01 | 39.84 | 19.82 | 20.02 | 0.00 | 0.00 | 2,500 | 1,600 | - 50 | 160 | 100 | 1,900 |

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron Service Station #9-3322

evron Service Station #9-33 7225 Bancroft Avenue Oakland, California

| | | | | | , | | | | | | |
|---|---------------|--------------|--------------|---------------|-----------------------------|----------------|------------|-------------|------------|-------------|------------------------|
| WELL ID/ DATE | TOC* (fl.) | GWE (msl) | DTW (fi.) | SPHT (fl.) | SPH REMOVED (gallons) | TPH-G (ppb) | B (ppb) | T (ppb) | E (ppb) | X (ppb) | MTBE (ppb) |
| D/A V A POSSESSESSESSESSESSESSESSESSESSESSESSESSE | (JL) | (1).31) | V/ | | | | | | | | . |
| MW-6 (cont) | | | | | | | | | | | |
| 11/21/01 | 39.84 | 19.22 | 20.62 | 0.00 | 0.00 | 25,000 | 8,800 | 150 | 620 | 330 | 2,900 |
| 02/05/02 | 39.84 | 24.04 | 15.80 | 0.00 | 0.00 | 1,400 | 400 | 6.8 | 27 | 20 | 480 |
| 04/01/02 | 36.90 | 23.08 | 13.82 | 0.00 | 0.00 | | | | | | |
| 08/05/02 | 36.90 | 19.85 | 17.05 | 0.00 | 0.00 | 1,200 | 300 | 5.1 | 11 | 3.7 | 250 |
| 11/04/02 | 36.90 | 17.34 | 19.56 | 0.00 | 0.00 | 7,500 | 2,000 | 29 | 140 | 39 | 1,300 |
| 02/03/03 | 36.90 | 22.28 | 14.62 | 0.00 | 0.00 | 630 | 160 | <5.0 | 9.2 | 2.7 | 260 |
| 05/02/03 | 36.90 | INACCESSIBI | | | | _ | _ | | | | |
| J3) V2(03 | 50.70 | I WICOZODIA | | | • | | | | | | |
| | | | | | | | | | • | | |
| MW-8 | | | | | | | | | | * | _ |
| 04/01/02 ⁶ | 37.21 | 26.11 | 11.10 | 0.00 | 0.00 | 1,200 | 8.6 | <0.50 | 2.5 | 2.5 | <2.5/<2 ⁵ |
| 08/05/02 | 37.21 | 21.07 | 16.14 | 0.00 | 0.00 | 560 | 11 | < 0.50 | < 0.50 | <1.5 | <2.5/<25 |
| 11/04/02 | 37.21 | 18.24 | 18.97 | 0.00 | 0.00 | 780 | 5.1 | < 0.50 | 1.1 | 1.9 | <2.5/<25 |
| 02/03/03 | 37.21 | 24.00 | 13.21 | 0.00 | 0.00 | 230 | 3.7 | < 0.50 | 0.54 | <1.5 | <10/0.6 ⁵ |
| 05/02/03 | 37.21 | 25.09 | 12.12 | 0.00 | 0.00 | 180 | 2.5 | <0.5 | <0.5 | <1.5 | <2.5/<0.5 ⁵ |
| 03/02/03 | 37.21 | 23.07 | 12.12 | | ••• | | | | | . • | |
| MW-9 | | | | | | | | | • | | |
| 04/01/02 ⁶ | 35.03 | 24,41 | 10.62 | 0.00 | 0.00 | 94 | 1.5 | < 0.50 | <0.50 | <1.5 | 25/19 ⁵ |
| 08/05/02 | 35.03 | 20.18 | 14.85 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | <0.50 | <1.5 | 18/15 ⁵ |
| 11/04/02 | 35.03 | 17.55 | 17.48 | 0,00 | 0.00 | <50 | <0.50 | 1.7 | <0.50 | 2.1 | 24/21 ⁵ |
| 02/03/03 | 35.03 | 22.52 | 12.51 | 0.00 | 0.00 | <50 | 1.9 | < 0.50 | < 0.50 | <1.5 | 17/16 ⁵ |
| 05/02/03 | 35.03 | 23.35 | 11.68 | 0.00 | 0.00 | <50 | 0.6 | <0.5 | <0.5 | <1.5 | 21/18 ⁵ |
| 03/02/03 | 33.03 | 23.33 | 11.00 | | | | | | | | |
| MW-10 | | | | | | • | | | | | |
| 04/01/02 ⁶ | 35.53 | 23.81 | 11.72 | 0.00 | 0.00 | <50 | <0.50 | <0.50 | <0.50 | <1.5 | 6,1/5 ⁵ |
| 08/05/02 | 35.53 | 19.73 | 15.80 | 0.00 | 0.00 | <50 | <0.50 | < 0.50 | < 0.50 | <1.5 | 5.1/5 ⁵ |
| 11/04/02 | 35.53 | 17.22 | 18.31 | 0.00 | 0.00 | <50 | <0.50 | < 0.50 | <0.50 | <1.5 | 5.5/5 ⁵ |
| 02/03/03 | 35.53 | 22.11 | 13.42 | 0.00 | 0.00 | <50 | < 0.50 | < 0.50 | < 0.50 | <1.5 | 2.8/35 |
| 05/02/03 | 35.53 | 23.08 | 12.45 | 0.00 | 0.00 | <50 | <0.5 | <0.5 | <0.5 | <1.5 | <2.5/<0.5 ⁵ |

Table 1
Groundwater Monitoring Data and Analytical Results
Chevron Service Station #9-3322

7225 Bancroft Avenue
Oakland, California

| WELL ID/ DATE | TOC* | GWE (msl) | DTW (fl.) | SPHT (ft.) | SPH REMOVED (gallons) | TPH-G (ppb) | B (ppb) | T <i>(ppb)</i> | E (ppb) | X (ppb) | MTBE (ppb) |
|------------------|-------------|--------------|--------------|---------------|-----------------------------|----------------|------------|-------------------|---------------|------------|----------------|
| JA) BP | (J.19) | (1165)2 | 0.3 | | | | | | | | • |
| TRIP BLANK | | | | | | | | | | • | |
| 02/08/98 | . <u>_</u> | | | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 06/16/98 | - | | | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 07/29/98 | | | | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
|)8/13/98 | •• | | | | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 1/24/98 | | | | | | <50 | < 0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
| 02/02/99 | | | | _ | | <50 | <0.5 | <0.5 | <0.5 | <0.5 | <2.5 |
|)2/03/99 | | <u> </u> | | | | <50 | < 0.5 | < 0.5 | <0.5 | <0.5 | <2.5 |
| 06/07/99 | | | | | | <50 | < 0.5 | < 0.5 | <0.5 | <0.5 | <2.5 |
| 19/07/99 | | •• | | | | <50 | <0.5 | < 0.5 | < 0.5 | <0.5 | <5.0 |
| 0/27/99 | | -4 | | | | <50 | <0.5 | < 0.5 | < 0.5 | <0.5 | <2.5 |
| | •• | | | | | <50 | <0.5 | < 0.5 | <0.5 | <0.5 | <5.0 |
| 02/08/00 | | | | <u></u> | | <50 | < 0.50 | <0.50 | <0.50 | < 0.50 | <2.5 |
| 05/05/00 | | | <u></u> | | | <50 | < 0.50 | < 0.50 | < 0.50 | < 0.50 | <2.5 |
| 07/28/00 | | | | | | <50 | <0.50 | <0.50 | < 0.50 | < 0.50 | <2.5 |
| 11/26/00 | | | | •• | | <50.0 | <0.500 | <0.500 | <0.500 | < 0.500 | <2.50 |
| 02/09/01 | | | | | | <50 | <0.50 | <0.50 | < 0.50 | < 0.50 | <2.5 |
| 05/11/01 | | | | | | <50 | <0.50 | <0.50 | <0.50 | < 0.50 | <2.5 |
| 08/30/01 | | | | | | -50 | 3.23 | | | | |
| QA | | | | | | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 11/21/01 | | | | | | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 02/05/02 | · | | | _ | _ | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 04/01/02 | | | | | | <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 08/05/02 | | | | | | <50 <50 | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 10/04/02 | | | | | | | <0.50 | <0.50 | <0.50 | <1.5 | <2.5 |
| 02/03/03 | - | | | | | <50 | | <0.50 <0.5 | <0.50 <0.5 | <1.5 | <2.5 |
| 05/02/03 | - | | - | - | | <50 | <0.5 | <0.5 | ~0.3 | ~1.3 | ال الله الله ا |

Table 1

Groundwater Monitoring Data and Analytical Results

Chevron Service Station #9-3322 7225 Bancroft Avenue Oakland, California

EXPLANATIONS:

Groundwater monitoring data and laboratory analytical results prior to May 5, 2000, were compiled from reports prepared by Blaine Tech Services, Inc.

TOC = Top of Casing

TPH-G = Total Petroleum Hydrocarbons as Gasoline

MTBE = Methyl tertiary butyl ether

(ft.) = Feet

B = Benzene

(ppb) = Parts per billion

GWE = Groundwater Elevation

T = Toluene

-- = Not Measured/Not Analyzed

(msl) = Mean sea level

E = Ethylbenzene

QA = Quality Assurance/Trip Blank

DTW = Depth to Water

X = Xylenes

SPHT = Separate Phase Hydrocarbon Thickness

SPH = Separate Phase Hydrocarbons

- TOC elevations were surveyed in April 2002, by Morrow Surveying. Elevations are based on City of Oakland Benchmark designated 3787 in field book 1595, page 50; cut square northerly curb on Krause Ave., approx. 37 feet westerly of PL westerly of 73rd Ave., (Elevation = 33.82 feet).
- GWE corrected for the presence of free product; correction factor: [(TOC DTW) + (SPHT x 0.8)].
- Confirmation run.
- Laboratory report indicates gasoline C6-C12.
- Laboratory report indicates weathered gasoline C6-C12.
- Product and water removed.
- 5 MTBE by EPA Method 8260.
- Well development performed.

Table 2
Groundwater Analytical Results - Oxygenate Compounds

Chevron Service Station #9-3322 7225 Bancroft Avenue Oakland, California

| WELLID | DATE | TBA (ppb) | MTBE (ppb) | DIPE <i>(ppb)</i> | ETBE (ppb) | TAME (ppb) |
|----------|-----------------------------|--------------|---------------|----------------------|---------------|---------------|
| MW-8 | 04/01/02 | <1 00 | <2 | <2 | <2 | <2 |
| 171 44-0 | 08/05/02 | <100 | <2 | <2 | <2 | <2 |
| | 11/04/02 | <100 | <2 | <2 | <2 | <2 |
| | 02/03/03 | <5 | 0.6 | <0.5 | <0.5 | <0.5 |
| | 05/02/03 | <5 | <0.5 | <0.5 | <0.5 | <0.5 |
| | 0.4/0.1/0.0 | ~100 | 19 | <2 | <2 | <2 |
| MW-9 | 04/01/02 | <100 | 15 | <2 | <2 | <2 |
| | 08/05/02 | <100 | 21 | <2 | <2 | <2 |
| | 11/04/02 | <100 | 16 | <0.5 | <0.5 | 0.8 |
| | 02/03/03 05/02/03 | <5 <5 | 18 | <0.5 | <0.5 | 0.8 |
| MW-10 | 04/01/02 | <100 | 5 | <2 | <2 | <2 |
| | 08/05/02 | <100 | 5 | <2 | <2 | <2 |
| • | 11/04/02 | <100 | 5 | <2 | <2 | <2 |
| | 02/03/03 | <5 | 3 | <0.5 | <0.5 | <0.5 |
| | 05/02/03 | <5 | <0.5 | <0.5 | <0.5 | <0.5 |

EXPLANATIONS:

TBA = Tertiary butyl alcohol

 $MTBE = Methyl \ tertiary \ butyl \ ether$

DIPE = Di-isopropyl ether

 $ETBE = Ethyl \ tertiary \ butyl \ ether$

TAME = Tertiary amyl methyl ether

(ppb) = Parts per billion

ANALYTICAL METHOD:

EPA Method 8260 for Oxygenate Compounds

STANDARD OPERATING PROCEDURE - GROUNDWATER SAMPLING

Gettler-Ryan Inc. field personnel adhere to the following procedures for the collection and handling of groundwater samples prior to analysis by the analytical laboratory. Prior to sample collection, the type of analysis to be performed is determined. Loss prevention of volatile compounds is controlled and sample preservation for subsequent analysis is maintained.

Prior to sampling, the presence or absence of free-phase hydrocarbons is determined using an interface probe. Product thickness, if present, is measured to the nearest 0.01 foot and is noted in the field notes. In addition, all depth to water level measurements are collected with a static water level indicator and are also recorded in the field notes, prior to purging and sampling any wells.

After water levels are collected and prior to sampling, if purging is to occur, each well is purged a minimum of three well casing volumes of water using pre-cleaned pumps (stack, suction, Grundfos), or disposable bailers. Temperature, pH and electrical conductivity are measured a minimum of three times during the purging. Purging continues until these parameters stabilize.

Groundwater samples are collected using disposable bailers. The water samples are transferred from the bailer into appropriate containers. Pre-preserved containers, supplied by analytical laboratories, are used when possible. When pre-preserved containers are not available, the laboratory is instructed to preserve the sample as appropriate. Duplicate samples are collected for the laboratory to use in maintaining quality assurance/quality control standards. The samples are labeled to include the job number, sample identification, collection date and time, analysis, preservation (if any), and the sample collector's initials. The water samples are placed in a cooler, maintained at 4°C for transport to the laboratory. Once collected in the field, all samples are maintained under chain of custody until delivered to the laboratory.

The chain of custody document includes the job number, type of preservation, if any, analysis requested, sample identification, date and time collected, and the sample collector's name. The chain of custody is signed and dated (including time of transfer) by each person who receives or surrenders the samples, beginning with the field personnel and ending with the laboratory personnel.

A laboratory supplied trip blank accompanies each sampling set. For sampling sets greater than 20 samples, 5% trip blanks are included. The trip blank is analyzed for some or all of the same compounds as the groundwater samples.

As requested by Chevron Products Company, the purge water and decontamination water generated during sampling activities is transported by IWM to McKittrick Waste Management located in McKittrick. California.



| lient/Facility #: | 7225 Bancroft A | venue | | Event Date: | 5/2/4 | 3 | | (inclus |
|---|-------------------------------------|---|--|---|-------------------|----------------------|-----------------|--------------------------------------|
| ite Address: | | Venue | | Sampler: | Jim | Hezzaw | | ` |
| ity: | Oakland, CA | | <u> </u> | Sampler. | <u> Jami</u> | //6/6/545 | | |
| · · · · · · · · · · · · · · · · · · · | MW- / | Date N | Aonitored: | 5/2/03 | Well C | ondition: | ok | |
| /ell ID | | Date N | normoreat | 7 (2) | - | | | |
| Vell Diameter | | • | Volume | 3/4"= 0.02 | 1"= 0.04 | 2"= 0.17 | 3"= 0.38 | |
| otal Depth | 33.96 ft. | | Factor (V | | 5"= 1.02 | | 12"= 5.80 | |
| epth to Water | 13.28 ft. 20.68 xVF | .17 | - 3.5/ | _x3 (case volume) = | Estimated Pu | roe Volume: | 10.5 gal. | |
| | 20.68_xvF | | | _ NO (case voicine) | Time Sta | | (2 | 400 tirs) |
| urge Equipment: | | Sampl | ing Equipmen | t: | Time Bai | | | 400 hrs) |
| isposable Bailer | × | Dispos | able Bailer | × | Depth to | Product: | | ft |
| itainless Steel Baile | | Pressu | ıre Bailer | | Depth to | | | f1 |
| Stack Pump | | Discre | te Bailer | | | rbon Thiokness | | ft |
| Suction Pump | | Other: | | | Visual Co | onfirmation/Des | scription: | |
| Grundfos | | | | | Skimme | / Absorbant S | ock (circle one |) |
| Other: | | | | | Amt/Ren | noved from Ski | mmer: | gal |
| J.11107. | | | | | | noved from We | | gal |
| | | | | | Product | Transferred to: | | |
| | ate: 1115 /5/3 ate: gpm. | Sedimen | er Conditions Water Colo It Description | n: C Volume: | _ | əl. | yes_ | - - |
| Sample Time/D Purging Flow R | ate: 1115 /5/3 ate:gpm. er? | Sediment f yes, Time | Water Colo | n: <u> </u> | | al. 0.0. 19/L) | ORP (mV) | - - - |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 | ate: 1115 /5/3 ate: gpm. er? Volume | Sedimen f yes, Time | Water Colorst Description Conductivity (umhos/cm) | Volume: Temperature (*/F) | 10017 10 98 | al. 0.0. 19/L) | ORP | - - - |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 | ate: 1115 /5/3 ate: gpm. er? Volume | Sedimen f yes, Time | Water Colorst Description Conductivity (umhos/cm) | Volume: Temperature (*/F) | | al. 0.0. 19/L) | ORP | - - |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 | ate: 1115 /5/3 ate: gpm. er? Volume | Sediment yes, Time | Water Colo It Description Conductivity (umhos/cm) 928 932 970 | Temperature (*/F) 20.0 19.8 | | al. 0.0. 19/L) | ORP | - |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 | ate: 1115 /5/3 ate: gpm. er? Volume | Sedimen f yes, Time pH (5.81 (5.72 (5.72 (5.73) | Water Colo It Description Conductivity (umhos/cm) 928 932 970 | Volume: Temperature (a/F) 20.0 19.8 19.9 | GULT GE | al. D.O. ng/L) | ORP (mV) | |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 | ate: 1115 /5/3 ate:gpm. er? | Sedimen f yes, Time pH (5-8/ (-72- | Water Colors Water Colors Description Conductivity (umhos/cm) 928 932 970 ORATORY IN | Volume: Temperature (**F*) 20.0 19.8 19.9 VFORMATION PE LABORATO LANCASTE | GOLY | ANAL | ORP (mV) | - - - - - - - - |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 | ate: 1115 /5/3 ate:gpm. er? | Sediment yes, Time pH (0.81 | Water Color It Description Conductivity (umhos/cm) 9232 9732 970 ORATORY IN | Volume: Temperature (a/F) 20.0 19.8 19.9 VERNATION PE LABORATO | ORY TPH-G | ANAL (8015)/BTEX+ | ORP (mV) | - - - - - - |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 SAMPLE ID MW- J | ate: 1115 /5/3 ate:gpm. er? | Sediment yes, Time | Water Color It Description Conductivity (umhos/cm) 928 932 940 ORATORY IN PRESERV. TYL | Volume: Temperature (**F*) 20.0 19.8 19.9 VFORMATION PE LABORATO LANCASTE | ORY TPH-G | ANAL | ORP (mV) | |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 SAMPLE ID MW- J | ate: 1115 /5/3 ate:gpm. er? | Sediment yes, Time | Water Color It Description Conductivity (umhos/cm) 928 932 940 ORATORY IN PRESERV. TYL | Volume: Temperature (**F*) 20.0 19.8 19.9 VFORMATION PE LABORATO LANCASTE | ORY TPH-G | ANAL (8015)/BTEX+ | ORP (mV) | |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 SAMPLE ID MW- J | ate: 1115 /5/3 ate:gpm. er? | Sediment yes, Time pH 9-81 -72 LAB REFRIG. YES | Water Colo It Description Conductivity (umhos/cm) 928 932 970 ORATORY IN PRESERV. TYI HCL HCL | Volume: Temperature (**F*) 20.0 19.8 19.9 VFORMATION PE LABORATO LANCASTE | ORY TPH-G | ANAL (8015)/BTEX+ | ORP (mV) | |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 SAMPLE ID MW- J | ate: 1115 /5/3 ate:gpm. er? | Sediment yes, Time pH 9-81 -72 LAB REFRIG. YES | Water Colo It Description Conductivity (umhos/cm) 928 932 970 ORATORY IN PRESERV. TYI HCL HCL | Volume: Temperature (**F*) 20.0 19.8 19.9 VFORMATION PE LABORATO LANCASTE | ORY TPH-G | ANAL (8015)/BTEX+ | ORP (mV) | |
| Sample Time/D Purging Flow R Did well de-wat Time (2400 hr.) 1052 1059 1105 SAMPLE ID MW-1 | ate: 1115 /5/3 ate:gpm. er? | Sediment yes, Time pH 9-81 -72 LAB REFRIG. YES | Water Colo It Description Conductivity (umhos/cm) 928 932 970 ORATORY IN PRESERV. TYI HCL HCL | Volume: Temperature (**F*) 20.0 19.8 19.9 VFORMATION PE LABORATO LANCASTE | ORY TPH-G | ANAL (8015)/BTEX+ | ORP (mV) | |



| Client/Facility #: | ChevronTexaco | #9-332 | 2 | Job Number: | 386433 | |
|--|---------------|----------------|-------------------------------|--------------------|-----------------------------------|---------------------------------------|
| Site Address: | 7225 Bancroft | Avenu e | | Event Date: | 5/2/03 | (inclusiv |
| City: | Oakland, CA | | | Sampler: | Jim HERR | 'en |
| Well ID | MW- 2 | Date | : Monitored: | 5/2/03 | Well Condition: | ok |
| Well Diameter | in. | | Volume | 3/4"= 0.02 | 1"= 0.04 2"= 0.17 3" | = 0.38 |
| Total Depth | 29.88 ft. | • | Factor (VF | | | "= 5.80 |
| Depth to Water | 8.31 ft. | | , ,,, | | 1 | 1 10 |
| | 31.57 × | F | <u> </u> | x3 (case volume) = | Estimated Purge Volume: | gal. |
| | | _ | F | _ | Time Started: | (2400 hrs) |
| Purge Equipment: | ✓ | | pling Equipment | · × | Time Bailed: | (2400 tars) |
| Disposable Bailer | | - | osable Bailer ssure Bailer | | Depth to Product: Depth to Water: | |
| Stainless Steel Baile Stack Pump | | | crete Bailer | | Hydrocarbon Thickness: | ft |
| Suction Pump | | | er: | | Visual Confirmation/Descr | iption: |
| Grundfos | | | | | Skimmer / Absorbant Soc | k (circle one) |
| Other: | | | | | Amt Removed from Skimi | |
| | | | | | Amt Removed from Well: | |
| | | | | | Product Transferred to: | |
| Purging Flow Rinds Did well de-water Time (2400 hr.) /225 /23/ /23/ | | | Conductivity (umhos/cm) 367 | | | ORP (mV) |
| SAMPLE ID | (#) CONTAINER | LA REFRIG. | BORATORY IN | · , | RY ANALYS | SES |
| MW- 2 | 3 x voa vial | YES | HCL | LANCASTE | | BE(8021) -OR- |
| MW- | x voa vial | YES | HCL | LANCASTE | | BE(9021)/ |
| V | | | | | 5 OXYS(8260) | |
| COMMENTS: | New to | ve 7 | ó Kep | | | · |
| | <u> </u> | | ě | | | · · · · · · · · · · · · · · · · · · · |
| Add/Repi | aced Lock: | | 14 + ₹10 ₁ g + | Add/Replaced | Plug: Size: | |



| | ChevronTexaco | 9-3322 | | Job Number: | 386433 | | | _ |
|---|--|-----------------|---|---|-----------------------------------|------------------|--------------------------------|-----------------|
| Site Address: | 7225 Bancroft | Avenue | | Event Date: | 5/2/ | 03 | | (inclus |
| City: | Oakland, CA | | | Sampler: | Jim | Heric | POIN | _ |
| Well ID | | Date M | onitored: | 5/2/03 | Well Cor | ndition: | oK | |
| Well Diameter | 2 in. | | Volume | 3/4"= 0.02 | 1"= 0.04 | 2"= 0.17 | 3"= 0.38 | 1 |
| Total Depth | 32.91 ft. | | Factor (VF | | | 7= 1.50 | 12"= 5.80 | |
| Depth to Water | 13.07 fl. 19.84 xvi | <u>.,,7</u> , | <u>3.37</u> | x3 (case volume) = | Estimated Purge | Volume: | 10.11 gal | |
| Purge Equipment: | | | ng Equipment | | Time Started | j: | (| 2400 hrs) |
| Disposable Bailer | × | | ible Bailer | × | Time Bailed: Depth to Pro | | | 2400 hrs) ft |
| Stainless Steel Baild | er — — — | Pressur | | | Depth to Wa | | | |
| Stack Pump | | Discrete | | | Hydrocarbor | 1 Thicknes | \$: <u>/</u> | ft |
| Suction Pump | | Other:_ | | | Visual Confi | rmation/Pt | scription: | |
| Grundfos | | _ | | | Skimmer / A | be or bant S | Sock (circle on | <u>e)</u> |
| Other: | | ", | | | | | immer: | |
| | ·· ······ | | | | Amt Remov | ed from W | ell: | gal |
| | | | | | Product Tra | nsferred to | <u> </u> | |
| | | | | | | | | |
| Purging Flow R Did well de-wat Time (2400 hr.) 1341 1323 | Volume (gal.) | If yes, Time: _ | onductivity mhos/cm) | Volume: | gal. D.O. (mg/L) | · | ORP (mV) | |
| Did well de-wat | Volume (gal.) | of yes, Time: | onductivity | Volume: | D.O. (mg/L) | ANAL | (mV) | |
| Time (2400 hr.) 1361 137 1323 SAMPLE ID MW-3 | Volume (gal.) (#) CONTAINER x voa vial | LABOI | onductivity mhos/cm) 832 834 RATORY INF | Volume: Temperature (#/F) / 9.2 / 9.6 / 9.9 CORMATION LABORATOR LANCASTER | D.O. (mg/L) | ANAL 5)/BTEX+ | (mV) .YSES MTBE(8021) -4 | OR- |
| Time (2400 hr.) 1361 1317 1323 | Volume (gal.) (#) CONTAINER | LABOI | onductivity mhos/cm) 832 834 RATORY INF | Volume: Temperature (#/F) / 9.2 / 9.6 / 9.9 CORMATION LABORATOR | D.O. (mg/L) Y TPH-G(801: | ANAL | (mV) | OR. |
| Time (2400 hr.) 1361 137 1323 SAMPLE ID MW-3 | Volume (gal.) (#) CONTAINER x voa vial | LABOI | onductivity mhos/cm) 832 834 RATORY INF | Volume: Temperature (#/F) / 9.2 / 9.6 / 9.9 CORMATION LABORATOR LANCASTER | D.O. (mg/L) | ANAL | (mV) .YSES MTBE(8021) -4 | OR- |



| Client/Facility #: | ChevronTexaco | #9-3322 | | Job Number: | 386433 | |
|----------------------------------|------------------------|-------------------|---------------------------|--------------------|---|----------------------|
| · • | 7225 Bancroft A | venue | | Event Date: | 5/2/03 | (inclu |
| City: | Oakland, CA | | | Sampler: | Jim Her | RON |
| Weli ID | MW- 4/ | Date I | Monitored: | 5/2/03 | Well Condition: | OK |
| Well Diameter | 2 in. | | Volume | 3/4"= 0.02 | 1"= 0.04 2"= 0.17 | 3"= 0.38 |
| Total Depth | 30,26 ft. | | Factor (V | | 5"= 1.02 6"= 1.50 | 12"= 5.80 |
| Depth to Water | 12.85 ft. 17.41 xVF | .17 | 2.95 | x3 (case volume) = | Estimated Purge Volume | 8.87 _{gal.} |
| Purge Equipment: | | | ling Equipmen | | Time Started: | (2400 hrs |
| Disposable Bailer | <i>></i> | | sable Bailer | ~ | Depth to Product: | (2490111) |
| Stainless Steel Baller | | • | ure Bailer | | Depth to Water: | |
| Stack Pump | | Discre | ete Bailer | | Hydrocarbon Thickn | |
| Suction Pump | | Other | | | Visual Confirmation | escription: |
| Grundfos | | | | | Skimmer / Alesorbai | |
| Other: | | | | | | Skimmer: ga |
| | | | | | Amt Removed from Product Transferred | |
| | | | | | | |
| Purging Flow Ra Did well de-wate | | Sedimer | Water Colont Description: | n: //ورا | 115 | |
| Time | Volume | р Н | Conductivity | Temperature | D.O. | ORP |
| (2400 hr.) | (gal.) | | (umhos/cm) | (e/F) | (mg/L) | (mV) |
| 0925 | | 8.6/ | <u>431</u> | 20.3 | | |
| 0931 | | <u> 7.69</u> | 44/ | 19.0 | | |
| 0936 | | 7.45 _ | 438 | <u> 18-7</u> | | |
| | | | | NFORMATION | | , |
| SAMPLE ID | (#) CONTAINER | | PRESERV. TY | | | NALYSES |
| MW- | 3 x voa vial | YES | HCL HCL | LANCASTE | | X+MTBE(8021) -OR- |
| 1 | voa via | YES | HCL | 253,00 | 2 5 OXYS(0260) | 22 |
| COMMENTS: | New tu | d to | Kev | | | |
| COMMILITIE: | 10000 1 | | | | | |
| Add/Repla | ced Lock: | | <u> </u> | Add/Replaced | l Plug: | Size: |



| lient/Facility #: | ChevronTexac | p #9-3322 | | Job Number: | 386433 | | | _ |
|---|---------------------------------------|-------------------|--------------------------|----------------------|----------------|----------------------------|-----------------------------|-----------------|
| ite Address: | | | | Event Date: | 5/2/03 | | | _ _(inclusiv |
| ity: | Oakland, CA | | | Sampler: | Jim | Her | Ron | • |
| Vell 1D | MW- 5 | Date N | Monitored: 5 | 1/2/03 | Well C | Condition: | OK | |
| Vell Diameter | 2 in. | | Volume | 3/4"= 0.02 | 1"= 0.04 | 2"= 0.17 | 3*= 0.38 | 1 |
| otal Depth | 31.55 ft. | | Factor (VF | | 5*= 1.02 | 6"= 1.50 | 12"= 5.80 |] . |
| Depth to Water | 13.96 ft. | , J7 | = 2.99 | x3 (case volume) = | Estimated Pu | rge Volume: | 8,97 _{gal.} | |
| | <u> </u> | | | | Time Sta | rted: | (2 | 400 hrs) |
| ourge Equipment: | 1.0 | | ing Equipment | | Time Bai | | | 2400 hrs) ft |
| Disposable Bailer | | | able Bailer | × | | Product: Water: | | '\ |
| Stainless Steel Baild | er | | ire Bailer | | | rbon Thickne | ss: | ft |
| Stack Pump | | | te Bailer | | | onfirmation/D | | |
| Suction Pump | · · · · · · · · · · · · · · · · · · · | Other. | | | ⁻I | | Sock (circle one | |
| Grundfos | | | | | | | Sock (circle one kimmer: | |
| Other: | | | | | | | Vell: | |
| | | | | | Froduct | Transferred t | o: | |
| Purging Flow F Did well de-wa Time (2400 hr. | ter? NO | If yes, Time | Conductivity (u mhos/cm) | | C | al. O.O. ng/L) | ORP (mV) | |
| | | | | | | | | _ |
| SAMPLE ID | (#) CONTAINER | | ORATORY IN | | RY | ANA | ALYSES | _ |
| SAMPLE ID | (#) CONTAINER x voa vial | REFRIG. | | | R TPH-G | (8015)/BTEX | +MTBE(8021) - | DR- |
| | | REFRIG. I | PRESERV. TYP | E LABORATO | R TPH-G | (8015)/BTEX (8015)/BTEX | | OR- |
| MW- 5 | x voa vial | REFRIG. 1 YES YES | HCL HCL | E LABORATO LANCASTE | R TPH-G | (8015)/BTEX | +MTBE(8021) - | DR- |



| ient/Facility#: | | | | | | |
|--------------------------|--------------------------|-----------------------|-------------------------|-------------------------------------|---|------------------------------|
| · · | 7225 Bancroft | Avenue | E | vent Date: | 5/2/03 | (inclus |
| - | Oakland, CA | | | ampler: | Jim HERROI | |
| | | | | - | | |
| /ell 1D | MW- 26 | Date | Monitored: 5 | 72/03 | Well Condition: | et see |
| ell Diameter | 2 in. | | | | | |
| - | ft. | | Volume | 3/4"= 0.02 | | "= 0.38 !"= 5.80 |
| otal Depth | | | Factor (VF) | 4*= 0.66 | 5"= 1.02 6"= 1.50 12 | - 5.80 |
| epth to Water | <u>ft.</u> | : | | ? | stimated Purge Volume: | nal |
| • | x | /F | = ^, | 5 (case volume) – L | | |
| urge Equipment: | | Sam | pling Equipment: | | Time Started: Time Bailed: | |
| | | | osable Bailer | | Depth to Product: | |
| isposable Bailer | | - | ssure Bailer | | Depth to Water: | |
| tainless Steel Bailer | | | rete Bailer | | Hydrocarbon Thickness: | ft |
| tack Pump uction Pump | | | ere baller | | Visual Confirmation/Desc | ription: |
| rundfos | | | | | Skimmer / Absorbant Soc | k (circle one) |
| Other: | | | | | Amt Removed from Skim | |
| | | | | | Amt Removed from Well: | ga |
| | | | • | | Product Transferred to: | |
| Did well de-wate | r? | If yes, Tim | ne: | Volume: | gal. | |
| Time | Volume | рН | Conductivity (umhos/cm) | Temperature (C/F) | D.O. (mg/L) | ORP (mV) |
| (2400 hr.) | (gal.) | | | | | |
| (2400 nr.) | (gal.) | | | | | |
| | | | BORATORY INFO | | | SES |
| SAMPLE ID | (#) CONTAINER | REFRIG. | PRESERV. TYPE | LABORATOR | RY ANALY | |
| SAMPLE ID MW- | (#) CONTAINER | REFRIG. YES | PRESERV. TYPE HCL | LABORATOF LANCASTER | RY ANALY R TPH-G(8015)/BTEX+M | TBE(8021) -OR- |
| SAMPLE ID | (#) CONTAINER | REFRIG. YES | PRESERV. TYPE | LABORATOR | RY ANALY R TPH-G(8015)/BTEX+M R TPH-G(8015)/BTEX+M | TBE(8021) -OR- |
| SAMPLE ID MW- | (#) CONTAINER | REFRIG. YES | PRESERV. TYPE HCL | LABORATOF LANCASTER | RY ANALY R TPH-G(8015)/BTEX+M | TBE(8021) -OR- |
| SAMPLE ID MW- | (#) CONTAINER | REFRIG. YES | PRESERV. TYPE HCL | LABORATOF LANCASTER | RY ANALY R TPH-G(8015)/BTEX+M R TPH-G(8015)/BTEX+M | TBE(8021) -OR- |
| SAMPLE ID MW- MW- | (#) CONTAINER x voa via | REFRIG. YES YES | PRESERV. TYPE HCL HCL | LABORATOF LANCASTEI LANCASTEI | RY ANALY R TPH-G(8015)/BTEX+M R TPH-G(8015)/BTEX+M | TBE(8021) -OR- TBE(8021)/ |
| SAMPLE ID MW- MW- | (#) CONTAINER | REFRIG. YES YES | PRESERV. TYPE HCL HCL | LABORATOF LANCASTEI LANCASTEI | RY ANALY R TPH-G(8015)/BTEX+M TPH-G(8015)/BTEX+M 5 OXYS(8260) | TBE(8021) -OR- TBE(8021)/ |



| nevronTexaco 225 Bancroft A akland, CA MW- 8 2 in. 29,94 ft. 2,/2 ft. | Date | Monitored: | 3/4"= 0.02 | 5/2/03 5/2/03 Well Condition: 1"= 0.04 | oK 3*= 0.38 |
|--|------------------------------|--|--|--|--|
| MW- 8 2 in. 29.94 ft. 2./2 ft. | Date | Monitored: | /2/0) 3/4°= 0.02 | Well Condition: | oK 3*= 0.38 |
| 2 in. 29,94 ft. 2,/2 ft. | , 7 | Volume Factor (VF) | 3/4"= 0.02 | 1"= 0.04 2"= 0.17 | 3"= 0.38 |
| 29.94 ft. 2.12 ft. | ・ノフ | Factor (VF) | - | * * | |
| 2.12 ft. | . 1フ | Factor (VF) | - | | |
| | . 17 | | | U = 1.02 U = 1.00 | 12"= 5.80 |
| | · <u> </u> | _ <u>= 3,62</u> x3 | (case volume) = Es | stimated Purge Volume: | 9.06 gal. |
| | | - No Family - and | | Time Started: | (2400 hr (2400 hr |
| ~ | | pling Equipment: osable Bailer | Y | Time Bailed: Depth to Product: | (2400 H |
| | • | ssure Baller | | Depth to Water: | |
| | | _ | | Hydrocarbon Thicknes | |
| | | _ | | Visual Confirmation/D | escription: |
| | | | | Skimmer / Absorbant | Sock (circle one) |
| | | | | Amt Removed from S | kimmer: § |
| | | | | | |
| | | | | Product Transferred t | U |
| | | | \mathcal{P}_{\bullet} | | |
| | | _ | | | ves |
| : 1200 151 | | | Clover | | 700 |
| : gpm. | | • | 1.767 | | |
| <u> </u> | If yes, Tim | ie: | Volume: | gal. | |
| | | Conductivity | Temperature | D.O. | ORP |
| | pН | (umhos/cm) | (4 /F) | (mg/L) | (mV) |
| - رکّی | 760 | 526 | 18.7 | | |
| | | | 19.1 | | |
| - | | | | | |
| | <u>(8)</u> | <u> </u> | · / . G | | |
| | | | <u> </u> | | |
| | LA | | | | |
| (#) CONTAINER | REFRIG. | | | • | ALYSES |
| Leiv sov x | YES | HCL | 1 | | |
| 6 x voa vial | YE\$ | HCL | LANCASTER | 5 OXYS(8260) | |
| <u> </u> | | | | | |
| | | | 1 | Į. | |
| 2 | Volume (gal.) (#) CONTAINER | 1/30 Weath | Water Color: Second Secon | Other: 1/30 Weather Conditions: Ra. | Other: Other: Other: Other: Skimmer / Absorbant Amt Removed from Ward Removed fr |



| Client/Facility #: Cl | hevronTexaco | #9-3322 | <u></u> J | ob Number: | 386433 | |
|---|----------------|----------------------|---|------------------------|---|------------------|
| | 225 Bancroft A | | | vent Date: | 5/2/03 | (inclusiv |
| | akland, CA | | | Sampler: | Jim HERMON | |
| Well ID | MW- 9 | Date | Monitored: 5 | 12/03 | Well Condition: | K |
| Well Diameter | 2 in. | | | 3/4"= 0.02 | 1"= 0.04 2"= 0.17 3"= 0.3 | 18 |
| Total Depth | 29.96 ft. | | Volume Factor (VF) | 3/4 = 0.02 4"= 0.66 | 5"= 1.02 6"= 1.50 12"= 5. | • |
| Depth to Water | 11.68 ft. | , 7 | <u> </u> | | Estimated Purge Volume: | 2 _{0al} |
| | 18.28 xvF | _117 | _ = x. | 3 (case volume) = | Time Started: | (2400 brs) |
| Purge Equipment: | | Samı | pling Equipment: | _ | Time Bailed: | (2400 hrs) |
| Disposable Bailer | > | Dispo | osable Bailer | <u> </u> | Depth to Product: | f |
| Stainless Steel Bailer | | Press | sure Bailer _ | | Depth to Water: | <u></u> |
| Stack Pump | | Discr | ete Bailer | | Hydrocarbon Thickness: | ft |
| Suction Pump | | Othe | r: | | Visual Confirmation/Description | n: |
| Grundfos | | | | | Skimmer / Mosorbant Sock (cir | rcle one) |
| Other: | | | | | Amt Reproved from Skimmer: | gal |
| Other | | | | | Amt Removed from Well: | gal |
| | | | | | Preduct Transferred to: | |
| Sample Time/Date Purging Flow Rate Did well de-water? Time (2400 hr.) 1355 1359 1406 | Volume (gal.) | Sedime f yes, Tim | Water Color: ent Description: e: Conductivity (umhos/cm) (624 (645 65) BORATORY INF | Volume: | gal. | RP nV) |
| SAMPLE ID | (#) CONTAINER | REFRIG. | PRESERV. TYPE | | | |
| ~101VV- | X vos viat | YES | HCL | DANCAST | | |
| MW- G | 6 x voa vial | YES | HCL | LANCAST | ER TPH-G(8015)/BTEX+MTBE(5 OXYS(8260) | 8021)/ |
| COMMENTS | New 7 | الماسية | talcon | | | |
| COMMENTS: | , | | | · | | |
| Add/Replac | ed Lock: | | | Add/Replace | d Plug: Size/ | |



| Client/Facility #: | ChevronTexac | o #9-3322 | <u> </u> | ob Number: | 380433 | | · | |
|--|--|--|---|--|---------------------------------|--------------------------------|------------------|-----------------|
| Site Address: | 7225 Bancroft | Avenue | E | vent Date: | 5/2/03 | | (inclus | |
| City: | Oakland, CA | | S | Sampler: | <u> </u> | n Hel | PRON | - |
| Well ID | MW- 10 | Date | Monitored: 5 | 12/07 | Well C | ondition: | OK | - |
| Well Diameter | 2 in. | | Volume | 3/4"= 0.02 | 1"= 0.04 | 2*= 0.17 | 3"= 0.38 | } |
| Total Depth | 29.89 ft. | | Factor (VF) | 4"= 0.66 | 5"= 1.02 | 6"= 1.50 | 12"= 5.80 | |
| Depth to Water | 12.45 ft. | vf , 17 | = 2.96 x | 3 (case volume) = | Estimated Pu | rge Volume: | 8.89 gai. | |
| | | _ | | | Time Star | | | 2400 hrs) |
| Ourge Equipment: | | • | pling Equipment: | X | •Time Bail | | | 2400 hrs) fi |
| Disposable Bailer | | - ', | osable Bailer sure Bailer | | | Product: Water: | | · |
| Stainless Steel Bail | er | | sure baller rete Bailer | · | | bon Thicknes | 58. | ft |
| Stack Pump Suction Pump | | Othe | • | | Visual Co | onfirmation/2 | escription: | |
| Grundfos | | | | | | | Sock (circle one | |
| Other: | | • | | | | | kimmer: | ga |
| | | | | | | noved from W Transferred to | | 9¢ |
| | | | | | Product | (Tallalelled (| · | |
| Start Time (pur Sample Time/I Purging Flow I Did well de-wa | Date: <u>/ 5 </u> | Sedime | Water Color: ent Description: e: | | | | 10 | |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr | Date: /505 /5 Rate:gpm. ater? | Sedime | ent Description: e: Conductivity (umhos/cm) | 1176 | 9a 9a | | ORP (mV) | - |
| Sample Time/l Purging Flow I Did well de-wa Time (2400 hr | Date: /505 /5 Rate:gpm. ater?Volume | Sedime If yes, Tim | ent Description: e: | Volume: | 9a 9a | ii. | ORP | |
| Sample Time/l Purging Flow l Did well de-wa Time (2400 hr | Date: /505 /5 Rate:gpm. ater?Volume | Sedime If yes, Tim | Conductivity (umhos/cm) | Volume: Temperature | 9a 9a | ii. | ORP | |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr / 447 | Date: /505 /5 Rate:gpm. ater?Volume | Sedime If yes, Tim PH 7./6 6.92 6.74 | Conductivity (umhos/cm) | Volume: Temperature (P/F) 18.2 19.0 | 9a 9a | ii. | ORP | |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr / 447 | Date: // 05 /5 Rate: — gpm. ater? Volume (gal.) | Sedime If yes, Tim PH 7./6 6.92 6.74 | Conductivity (umhos/cm) 5 2C 5 61 7 F 3 BORATORY INF | Volume: Temperature (R/F) 18.2 18.1 19.0 ORMATION LABORATO | | ali. .O. g/L) | ORP (mV) | |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr / 44/ / 456 SAMPLE II | Date: // 05 /5 Rate: — gpm. ater? Volume (gal.) 3 | Sedime If yes, Tim PH 7./6 6.92 6.74 LA REFRIG. | conductivity (umhos/cm) 5 2C 5 6 1 7 F 3 BORATORY INF PRESERV. TYPE HCL | Volume: Temperature (R/F) 18.2 18.1 19.0 ORMATION LABORATO | ga D (m | al. .O. .g/L) ANA | ORP (mV) | |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr /447 /4486 | Date: // 05 /5 Rate: — gpm. ater? Volume (gal.) | Sedime If yes, Tim PH 7./6 6.92 6.74 LA REFRIG. | Conductivity (umhos/cm) 5 2C 5 61 7 F 3 BORATORY INF | Volume: Temperature (R/F) 18.2 18.1 19.0 ORMATION LABORATO | ga D (m) RY RY RY TPH-G R TPH-G | al. .O. .g/L) ANA | ORP (mV) | _ |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr / 447 /47 48 /47 66 SAMPLE II MW-) | Date: // 05 /5 Rate: — gpm. Ater? Volume (gal.) (gal.) (gal.) (gal.) (yal.) (yal. | Sedime If yes, Tim PH 7./6 6.92 6.79 LA REFRIG. YES | Conductivity (umhos/cm) 5 26 5 6 6 7 F 3 BORATORY INF PRESERV. TYPE HCL | Volume: Temperature (%F) 18.2 18.1 19.0 ORMATION LABORATO LANCASTE LANCASTE | ga D (m) RY RY RY TPH-G R TPH-G | ANA (8015)/BTEX | ORP (mV) | |
| Sample Time/I Purging Flow I Did well de-wa Time (2400 hr / 44/ /4/ 48/ /4/ 56 | Date: // 05 /5 Rate: — gpm. Ater? Volume (gal.) (gal.) (gal.) (gal.) (yal.) (yal. | Sedime If yes, Tim PH 7./6 6.92 6.79 LA REFRIG. YES | conductivity (umhos/cm) 5 2C 5 6 1 7 F 3 BORATORY INF PRESERV. TYPE HCL | Volume: Temperature (%F) 18.2 18.1 19.0 ORMATION LABORATO LANCASTE LANCASTE | ga D (m) RY RY RY TPH-G R TPH-G | ANA (8015)/BTEX | ORP (mV) | |

Chevron California Region Analysis Request/Chain of Custody

| Lancaster Laboratories Where quality is a science. | | Acct. #: [0 | 904 Sample #: 4 | ncaster Laboratories use only 039250-58 | y SCR#: |
|--|--------------------|--|---|---|---|
| · · · · · · · · · · · · · · · · · · · | 503-0 | | | ses Requested | 3 -4 510860 |
| Facility #: SS#9-3322 G-R#386433 Global ID#T0600 | | Matrix | | rvation Codes | Preservative Codes |
| Site Address: 7225 BANCROFT AVE., OAKLAND, CA | | | XH H | | H = HCl T = Thiosulfate |
| | | | 1 | | N = HNO ₃ B = NaOH S = H ₂ SO ₄ O = Other |
| Chevron PM: KS Lead Consultant: CAN | MBRIA | ا و ا | | | ☐ J value reporting needed |
| Consultant/Office: G-R, Inc., 6747 Sierra Court, Suite J, De | | Potable NPDES | | | Must meet lowest detection limits |
| Consultant Prj. Mgr.: Deanna L. Harding (deanna@grinc. | com) | Soll Water Dotable Do | D 8021 🗮 O | | possible for 8280 compounds |
| Consultant Phone #: 925-551-7555 Fax #: 925-5 | 51-7899 | 50 | GRO GRO DRO (| 0.24 | 8021 MTBE Confirmation |
| Sampler: Vin HERROY | <u></u> | Air | 14 14 14 16 16 | | ☐ Confirm highest hit by 8260 ☐ Confirm all hits by 8260 |
| Service Order #: Non SAR: | | Nul Aii | + MTBE 828 8015 MOD DR 8015 MOD DR hill scan Oxygenates | R. | Run oxy s on highest hit |
| Date Sample Identification Collected C | Time collected 50 | Soil Water Oil □ Total N | BIEX+MIBE 8260 TPH 8015 MOD GRC TPH 8015 MOD DRO 8280 Null scan | | Run oxy s on all hits |
| (DA 5/9/03) | X X | 2 2 | XX | | Comments / Remarks |
| | 115 X | X 3 | XX | | |
| | 250 X | X | | | |
| | 330 X | Y 3 | XX | | 1 |
| | 950 X | | | | |
| | 630 X | X /3 | XX | | 4 |
| | 200 | X | | | |
| | 415 X | X 6 | | | <u>.</u> |
| mw-10 7 1 | 505 X | - X 0 | | | - |
| | | | | - - - - - | - |
| | | | ┠╼╏╼╏╼╏╼┠ | | - |
| | | - - - | | - - - - - - | - |
| Turnaround Time Requested (TAT) (please circle) | Relinquished | | Date 5/2/02 / | ime Received by: | Date Time |
| STD. TAT 72 hour 48 hour | Relinquished by: | | Date T | Time Received by | Dale Time |
| 24 hour 4 day 5 day | | ··· | N 5/5/07 | W- W W- | mag 5/8/3 1300 |
| Data Package Options (please circle if required) | Refinition by: | 1) - | Date | me Received by: | Date Time 5/5/53 |
| QC Summary Type I — Full | Relinquished by Co | ommercial Carrier: U | | Received by: | 2 3/3/03 Date Time |
| Type VI (Raw Data) | UPS Fede | Ex Other) | AX bom | - Dual | (1/// |
| Disk | Temperature Upon | Receipt 3.5 | c° | Custody Seals Intact? | Yes No |

3460 Rev. 7/30/01

25. Lencaster, PA 17605-2425 •717-656-2300 Fax: 717-656-2881 • www.kancesterlabs.com

ANALYTICAL RESULTS

Prepared for:

ChevronTexaco 6001 Bollinger Canyon Rd L4310

> San Ramon CA 94583 925-842-8582

> > Prepared by:

Lancaster Laboratories 2425 New Holland Pike Lancaster, PA 17605-2425

SAMPLE GROUP

The sample group for this submittal is 850860. Samples arrived at the laboratory on Tuesday, May 06, 2003. The PO# for this group is 99011184 and the release number is STREICH.

| Client Description | | | Lancaster Labs Number |
|--------------------|------|-------|-----------------------|
| QA-T-030502 | NA | Water | 4039250 |
| MW-1-030502 | Grab | Water | 4039251 |
| MW-2-030502 | Grab | Water | 4039252 |
| MW-3-030502 | Grab | Water | 4039253 |
| MW-4-030502 | Grab | Water | 4039254 |
| MW-5-030502 | Grab | Water | 4039255 |
| MW-8-W-030502 | Grab | Water | 4039256 |
| MW-9-W-030502 | Grab | Water | 4039257 |
| MW-10-W-030502 | Grab | Water | 4039258 |

ELECTRONIC COPY TO

Gettler-Ryan

Attn: Cheryl Hansen

1 COPY TO

Cambria C/O Gettler- Ryan

Attn: Deanna L. Harding



Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-856-2681 • www.lancasterlabs.com

Questions? Contact your Client Services Representative Teresa L Cunningham at (717) 656-2300.

Respectfully Submitted,

Robert E. Mellinger Senior Chemist, Coordinator



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax:717-656-2681 • www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. 4039250

Collected:05/02/2003 00:00

Account Number: 10904

Submitted: 05/06/2003 11:45

ChevronTexaco

Reported: 05/19/2003 at 13:09

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

QA-T-030502

Water

San Ramon CA 94583

Facility# 93322

Job# 386433

7225 Bancroft Ave-Oakland T0600102079 QA

| CAT | | · | As Received | As Received Method | | Dilution |
|-------|--|-------------------------------------|-----------------------------------|---------------------------|-------|----------|
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01729 | TPH-GRO - Waters | | | | | |
| 01730 | TPH-GRO - Waters | n.a. | N.D. | 50. | υg/1 | 1 |
| 02159 | The reported concentration of gasoline constituents eluting start time. A site-specific MSD sample was performed to demonstrate BTEX, MTBE | prior to the Co s not submitted | for the project. | A LCS/LCSD | | |
| 02161 | Benzene | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| 02164 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 02166 | Ethylbenzene | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 02171 | Total Xylenes | 1330-20-7 | N.D. | 1.5 | ug/l | 1 |
| 02172 | Methyl tert-Butyl Ether | 1634-04-4 | N.D. | 2.5 | ug/l | 1 |
| | A site-specific MSD sample was performed to demonstrate | as not submitted precision and a | for the project couracy at a bate | . A LCS/LCSD ch level. | | |

GRD

| | | Laboratory | Chro: | nicle | | Dilution | | |
|-------|-------------------|-------------------------------|--------|------------------|--------------|----------|--|--|
| CAT | | Analysis | | | | | | |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor | | |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/08/2003 23:28 | Jamie A Lutz | 1 | | |
| 02159 | BTEX, MTBE | SW-846 B021B | 1 | 05/08/2003 23:28 | Jamie A Lutz | 1 | | |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 05/08/2003 23:28 | Jamie A Lutz | n.a. | | |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

4039251 Lancaster Laboratories Sample No.

Collected: 05/02/2003 11:15

by JH

Account Number: 10904

Submitted: 05/06/2003 11:45

Reported: 05/19/2003 at 13:09

ChevronTexaco

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-1-030502

Grab

Water

San Ramon CA 94583

Facility# 93322

Job# 386433

GRD

7225 Bancroft Ave-Oakland T0600102079 MW-1

| CAT No. | Analysis Name | CAS Number | As Received Result | As Received Method Detection Limit | Units | Dilution Factor |
|---|--|----------------------------------|-------------------------------------|---|--------------------------------------|----------------------------|
| 01729 | TPH-GRO - Waters | | | | | |
| 01730 | TPH-GRO - Waters The reported concentration of I gasoline constituents eluting p start time. A site-specific MSD sample was was performed to demonstrate p | orior to the C6 not submitted | (n-hexane) TPH- for the project. | GRO range A LCS/LCSD | ug/l | 50 |
| 02159 | BTEX, MTBE | | | | | |
| 02161 02164 02166 02171 02172 | Benzene Toluene Ethylbenzene Total Xylenes Methyl tert-Butyl Ether A site-specific MSD sample was was performed to demonstrate p | | | | ug/l ug/l ug/l ug/l ug/l | 50 50 50 50 50 |

The reporting limits were raised because sample dilution was necessary to bring target compounds into the calibration range of the system.

| | | Laboratory | Chro: | nicle | | Dilution | | | |
|-------|-------------------|-------------------------------|--------|------------------|--------------|----------|--|--|--|
| CAT | Analysis | | | | | | | | |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor | | | |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/08/2003 21:05 | Jamie A Lutz | 50 | | | |
| 02159 | BTEX. MTBE | SW-846 8021B | 1 | 05/08/2003 21:05 | Jamie A Lutz | 50 | | | |
| 01146 | CC VON Water Pren | SW-846 5030B | 1 | 05/08/2003 21:05 | Jamie A Lutz | n.a. | | | |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17805-2425 • 717-656-2300 Fax: 717-656-2881 • www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW 4039252

Collected:05/02/2003 12:50

by Ji

Account Number: 10904

San Ramon CA 94583

Submitted: 05/06/2003 11:45

Reported: 05/19/2003 at 13:10

ChevronTexaco

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-2-030502

Grab Water

GRD

Facility# 93322 Job# 386433

7225 Bancroft Ave-Oakland T0600102079 MW-2

| CAT | | | As Received | As Received Method | | Dilution |
|-------|---|-----------------------------------|-------------------------------------|-------------------------|-------|----------|
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01729 | TPH-GRO - Waters | | 1 | | | |
| 01730 | TPH-GRO - Waters | n.a. | 12,000. | 250. | ug/l | 5 |
| | The reported concentration of Tigasoline constituents eluting pastert time. A site-specific MSD sample was a was performed to demonstrate pro- | rior to the C6 not submitted : | (n-hexane) TPH- for the project. | GRO range A LCS/LCSD | | |
| 02159 | BTEX, MTBE | | | | | |
| 02161 | Benzene . | 71-43-2 | N.D. | 20. | ug/l | 5 |
| 02164 | Toluene | 108-88-3 | 3.9 | 2.5 | ug/l | 5 |
| 02166 | Ethylbenzene | 100-41-4 | 350. | 2.5 | ug/l | 5 |
| 02171 | Total Xylenes | 1330-20-7 | 1,500. | 7.5 | ug/l | 5 |
| 02172 | Methyl tert-Butyl Ether | 1634-04-4 | 150. | 13. | ug/l | 5 |
| | A site-specific MSD sample was was performed to demonstrate pr | | • • | | | |

Due to the presence of an interferent near its retention time, the normal reporting limit was not attained for benzene. The presence or concentration of this compound cannot be determined due to the presence of this interferent.

| | | Laboratory | Chro | nicle | | |
|-------|-------------------|-------------------------------|--------|------------------|--------------|---------------|
| CAT | | - | | Analysis | | Dilution |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/09/2003 01:14 | Jamie A Lutz | 5 |
| 02159 | BTEX, MTBE | SW-846 8021B | 1 | 05/09/2003 01:14 | Jamie A Lutz | 5 |
| 01146 | GC VOA Water Pren | SW-846 5030B | 1 | 05/09/2003 01:14 | Jamie A Lutz | n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 • 717-656-2300 Fax: 717-856-2681 • www.lancasterlabs.com

Page 1 of 1

4039253 Lancaster Laboratories Sample No. WW

Collected:05/02/2003 13:30

by JH

Account Number: 10904

Submitted: 05/06/2003 11:45

ChevronTexaco

Reported: 05/19/2003 at 13:10

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-3-030502

Water

San Ramon CA 94583

GRD

Facility# 93322 Job# 386433 7225 Bancroft Ave-Oakland T0600102079 MW-3

| CAT No. | Analysis Name | CAS Number | As Received Result | As Received Method Detection Limit | Units | Dilution Factor |
|---|--|---|---|---|--------------------------------------|-----------------------|
| 01729 | TPH-GRO - Waters | | | | | |
| 01730 | TPH-GRO - Waters The reported concentration of gasoline constituents eluting start time. A site-specific MSD sample was was performed to demonstrate p | prior to the co | for the project. | A LCS/LCSD | ug/l | . 5 |
| 02159 | BTEX, MTBE | | | | | |
| 02161 02164 02166 02171 02172 | Benzene Toluene Ethylbenzene Total Xylenes Methyl tert-Butyl Ether A site-specific MSD sample was was performed to demonstrate p | 71-43-2 108-88-3 100-41-4 1330-20-7 1634-04-4 s not submitted precision and a | 1,200. 270. 1,100. 2,500. 1,400. for the project | 2.5 2.5 2.5 7.5 13. . A LCS/LCSD | ug/l ug/l ug/l ug/l ug/l | 5 5 5 5 5 |

| | | Laboratory | Chro | nicle Analysis | | Dilution |
|---------------------|-----------------------------------|--|-------------|--------------------------------------|--------------------------------|--------------------|
| CAT No. 01729 | Analysis Name TPH-GRO - Waters | Method N. CA LUFT Gasoline | Trial# 1 | Date and Time 05/09/2003 01:50 | Analyst Jamie A Lutz | Factor 5 |
| 02159 | BTEX, MTBE | Method SW-846 8021B SW-846 5030B | | 05/09/2003 01:50 05/09/2003 01:50 | Jamie A Lutz Jamie A Lutz | 5 n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 +717-656-2300 Fax: 717-656-2681 * www.lancasterlabs.com

Page 1 of 1

Lancaster Laboratories Sample No. WW 4039254

Collected:05/02/2003 09:50

bv JH

Water

Account Number: 10904

San Ramon CA 94583

Submitted: 05/06/2003 11:45

Reported: 05/19/2003 at 13:10

ChevronTexaco

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-4-030502

Grab

....

Facility# 93322

Job# 386433

GRD

7225 Bancroft Ave-Oakland T0600102079 MW-4

| CAT No. | Analysis Name | CAS Number | As Received Result | As Received Method Detection Limit | Units | Dilution Factor |
|------------|---|---|--------------------------------------|---|-------------|--------------------|
| 01729 | TPH-GRO - Waters | | , | | | |
| 01730 | TPH-GRO - Waters | n.a. | N.D. | 50. | ug/l | 1 |
| 02159 | start time. A site-specific MSD sample w was performed to demonstrate BTEX, MTBE | as not submitted precision and a | for the project couracy at a bate | . A LCS/LCSD ch level. | | |
| 02161 | Benzene | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| • | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 02164 | • • | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 02166 | Ethylbenzene | 1330-20-7 | N.D. | 1.5 | ug/l | 1 |
| 02171 | Total Xylenes | | N.D. | 2.5 | ug/l | 1 |
| 02172 | Methyl tert-Butyl Ether A site-specific MSD sample was performed to demonstrate | 1634-04-4 was not submitted precision and a | for the project | . A LCS/LCSD | | |

| | | Laboratory | Cnro | Nicie Analysis | | Dilution |
|---------------------|-----------------------------------|--|-------------|--------------------------------------|------------------------------------|-----------|
| CAT No. 01729 | Analysis Name TPH-GRO - Waters | Method N. CA LUFT Gasoline | Trial# 1 | Date and Time 05/08/2003 16:40 | Analyst Martha L Seidel | Factor 1 |
| 02159 01146 | BTEX, MTBE GC VOA Water Prep | Method SW-846 8021B SW-846 5030B | 1 1 | 05/08/2003 16:40 05/08/2003 16:40 | Martha L Seidel Martha L Seidel | ı n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

4039255 Lancaster Laboratories Sample No.

Collected:05/02/2003 10:30

by JH

Account Number: 10904

San Ramon CA 94583

Submitted: 05/06/2003 11:45

Reported: 05/19/2003 at 13:10

ChevronTexaco

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-5-030502

Water Grab

GRD

7225 Bancroft Ave-Oakland T0600102079 MW-5

| CAT No. | Analysis Name | CAS Number | As Received Result | As Received Method Detection Limit | Units | Dilution Factor |
|----------------|--|---------------------|-----------------------|---|----------------|--------------------|
| 01729 | TPH-GRO - Waters | | | | | |
| 01730 | TPH-GRO - Waters | n.a. | N.D. | 50. | ug/l | 1 |
| | <pre>start time. A site-specific MSD sample w was performed to demonstrate</pre> | was not submitted | for the project. | A LCS/LCSD | | |
| 02159 | BTEX, MTBE | · precipion and a | | | | |
| | * | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| 02161 | BTEX, MTBE | | | | ug/l ug/1 | 1 1 |
| 02161 02164 | BTEX, MTBE Benzene Toluene | 71-43-2 | N.D. | 0.5 | - . | 1 1 1 |
| 02161 | BTEX, MTBE | 71-43-2 108-88-3 | N.D. N.D. | 0.5 0.5 | ug/l | 1 1 1 |

| | | Laboratory | Chro | nicle | | |
|-------|-------------------|-------------------------------|--------|------------------|--------------|----------|
| CAT | • | | | Analysis | | Dilution |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/08/2003 18:00 | Jamie A Lutz | 1 |
| 02159 | BTEX, MTBE | SW-846 8021B | 1 | 05/08/2003 18:00 | Jamie A Lutz | 1 |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 05/08/2003 18:00 | Jamie A Lutz | n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

4039256 Lancaster Laboratories Sample No.

Collected: 05/02/2003 12:00

Account Number: 10904

Submitted: 05/06/2003 11:45

Reported: 05/19/2003 at 13:10

ChevronTexaco

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-8-W-030502

Water

San Ramon CA 94583

Facility# 93322

Job# 386433

GRD 7225 Bancroft Ave-Oakland T0600102079 MW-8

M8322

| | | | | As Received | | |
|-------|---|------------|-------------|--------------------|-------|----------|
| CAT | | | As Received | Method | | Dilution |
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01729 | TPH-GRO - Waters | | ; | | | |
| 01730 | TPH-GRO - Waters | n.a. | 180. | 50. | ug/l | 1 |
| | A site-specific MSD sample was was performed to demonstrate p | | | | | |
| 02159 | BTEX, MTBE | | | • | | |
| 02161 | Benzene | 71-43-2 | 2.5 | 0.5 | ug/l | 1 |
| 02164 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 02166 | Ethylbenzene | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 02171 | Total Xylenes | 1330-20-7 | N.D. | 1.5 | ug/l | 1 |
| 02172 | Methyl tert-Butyl Ether | 1634-04-4 | N.D. | 2.5 | ug/l | 1 |
| | A site-specific MSD sample was was performed to demonstrate; | | | | | |
| 01595 | Oxygenates by 8260B | | | | | |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | N.D. | 0.5 | ug/l | 1 . |
| 02011 | di-Isopropyl ether | 108-20-3 | N.D. | 0.5 | ug/l | 1 |
| 02013 | Ethyl t-butyl ether | 637-92-3 | N.D. | 0.5 | ug/l | 1 |
| 02014 | t-Amyl methyl ether | 994-05-8 | N.D. | 0.5 | ug/l | .1 |
| 02015 | t-Butyl alcohol | 75-65-0 | N.D. | 5. | ug/l | 1 |
| | | | | | | |

| Laboratory Chronicle | le |
|----------------------|----|
|----------------------|----|

| | | паротасоту | CILLO | 111010 | | |
|-------|----------------------|-------------------------------|--------|------------------|--------------|----------|
| CAT | | _ | | Analysis | | Dilution |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/08/2003 19:20 | Jamie A Lutz | 1 |
| 02159 | BTEX, MTBE | SW-846 8021B | 1 | 05/08/2003 19:20 | Jamie A Lutz | 1 |
| 01595 | Oxygenates by 8260B | SW-846 8260B | 1 | 05/15/2003 20:14 | John B Kiser | 1 |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 05/08/2003 19:20 | Jamie A Lutz | n.a. |
| 01163 | GC/MS VOA Water Prep | SW-846 5030B | 1 | 05/15/2003 20:14 | John B Kiser | n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax:717-656-2681 • www.lancasterlabs.com

Page 1 of 1

4039257 Lancaster Laboratories Sample No.

Collected:05/02/2003 14:15

Account Number: 10904

Submitted: 05/06/2003 11:45

Reported: 05/19/2003 at 13:10

ChevronTexaco

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

San Ramon CA 94583

MW-9-W-030502

GRD

Facility# 93322 Job# 386433

7225 Bancroft Ave-Oakland T0600102079 MW-9

M9322

| CAT No. | Analysis Name | CAS Number | As Received Result | As Received Method Detection Limit | Units | Dilution Factor |
|------------|---|---------------|-----------------------|---|-------|--------------------|
| 01729 | TPH-GRO - Waters | | | | | |
| 01730 | TPH-GRO - Waters A site-specific MSD sample was was performed to demonstrate pr | | | | ug/l | 1 |
| 02159 | BTEX, MTBE | | | | | |
| 02161 | Benzene | 71-43-2 | 0.6 | 0.5 | ug/l | 1 |
| 02164 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 |
| 02166 | | 100-41-4 | N.D. | 0.5 | ug/l | 1 |
| 02171 | • | 1330-20-7 | N.D. | 1.5 | ug/l | 1 |
| 02172 | . - | 1634-04-4 | 21. | 2.5 | ug/l | 1 |
| 02112 | A site-specific MSD sample was was performed to demonstrate p | not submitted | for the project. | A LCS/LCSD 1 level. | - | |
| 01595 | Oxygenates by 8260B | | | | | |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | 18. | 0.5 | ug/l | · 1 |
| 02011 | di-Isopropyl ether | 108-20-3 | N.D. | 0.5 | ug/l | 1 |
| 02013 | Ethyl t-butyl ether | 637-92-3 | N.D. | 0.5 | ug/l | 1 |
| 02014 | t-Amyl methyl ether | 994-05-8 | 0.8 | 0.5 | ug/l | 1 |
| 02015 | t-Butyl alcohol | 75-65-0 | N.D. | 5. | ug/l | 1 |

| CAT | | Laboratory | Chro | nicle Analysis | | Dilution |
|-------|----------------------|-------------------------------|--------|-------------------|--------------|----------|
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/08/2003 19:55 | Jamie A Lutz | 1 |
| 02159 | BTEX, MTBE | SW-846 8021B | 1 | 05/08/2003 19:55 | Jamie A Lutz | 1 |
| 01595 | Oxygenates by 8260B | SW-846 8260B | 1 | 05/16/2003 10:10 | John B Kiser | 1 |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 05/08/2003 19:55 | Jamie A Lutz | n.a. |
| 01163 | GC/MS VOA Water Prep | SW-846 5030B | 1 | 05/16/2003 10:10 | John B Kiser | n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 1 of 1

4039258 Lancaster Laboratories Sample No.

Collected: 05/02/2003 15:05

Account Number: 10904

Submitted: 05/06/2003 11:45

ChevronTexaco

Reported: 05/19/2003 at 13:10

6001 Bollinger Canyon Rd L4310

Discard: 06/19/2003

MW-10-W-030502

Grab

Water

San Ramon CA 94583

Facility# 93322

Job# 386433

GRD

7225 Bancroft Ave-Oakland T0600102079

10322

| | | • | | As Received | | D17L1 |
|-------|--|---------------|-----------------|--------------------|-------|----------|
| CAT | | | As Received | Method | | Dilution |
| No. | Analysis Name | CAS Number | Result | Detection Limit | Units | Factor |
| 01729 | TPH-GRO - Waters | | • | | | |
| 01730 | TPH-GRO - Waters | n.a. | N.D. | 50. | ug/l | 1 |
| | A site-specific MSD sample was was performed to demonstrate pr | | | | • | |
| 02159 | BTEX, MTBE | | | | | |
| 02161 | Benzene | 71-43-2 | N.D. | 0.5 | ug/l | 1 |
| 02164 | Toluene | 108-88-3 | N.D. | 0.5 | ug/l | 1 . |
| 02166 | Ethylbenzene | 100-41-4 | N.D. | 0.5 | ug/l | ı |
| 02171 | Total Xylenes | 1330-20-7 | N.D. | 1.5 | ug/l | 1 |
| 02172 | Methyl tert-Butyl Ether | 1634-04-4 | N.D. | 2.5 | ug/l | 1 |
| | A site-specific MSD sample was | not submitted | for the project | . A LCS/LCSD | | |
| | was performed to demonstrate p | | | | | |
| 01595 | Oxygenates by 8260B | | | | | |
| 02010 | Methyl Tertiary Butyl Ether | 1634-04-4 | N.D. | 0.5 | ug/l | 1 |
| 02011 | di-Isopropyl ether | 108-20-3 | N.D. | 0.5 | ug/l | 1 |
| 02013 | Ethyl t-butyl ether | 637-92-3 | N.D. | 0.5 | ug/l | 1 |
| 02014 | t-Amyl methyl ether | 994-05-8 | N.D. | 0.5 | ug/l | 1 |
| 02015 | t-Butyl alcohol | 75-65-0 | N.D. | 5. | ug/l | 1 |

| | | Laboratory | Chro | | | |
|-------|----------------------|-------------------------------|--------|------------------|--------------|----------|
| CAT | | | | Analysis | | Dilution |
| No. | Analysis Name | Method | Trial# | Date and Time | Analyst | Factor |
| 01729 | TPH-GRO - Waters | N. CA LUFT Gasoline Method | 1 | 05/08/2003 20:29 | Jamie A Lutz | 1 |
| 02159 | BTEX, MTBE | SW-846 8021B | 1 | 05/08/2003 20:29 | Jamie A Lutz | 1 |
| 01595 | Oxygenates by 8260B | SW-846 8260B | 1 | 05/16/2003 10:42 | John B Kiser | 1 |
| 01146 | GC VOA Water Prep | SW-846 5030B | 1 | 05/08/2003 20:29 | Jamie A Lutz | n.a. |
| 01163 | GC/MS VOA Water Prep | SW-846 5030B | 1 | 05/16/2003 10:42 | John B Kiser | n.a. |



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax:717-656-2681 • www.lancasterlabs.com

Page 1 of 2

Quality Control Summary

Client Name: ChevronTexaco

Group Number: 850860

Reported: 05/19/03 at 01:10 PM

Laboratory Compliance Quality Control

| Analysis Name | Blank <u>Result</u> | Blank MDL | Report <u>Units</u> | LCS %REC | LCSD %REC | LCS/LCSD <u>Limits</u> | RPD | RPD Max |
|-----------------------------|------------------------|--------------|------------------------|-------------|--------------|---------------------------|-----|---------|
| Batch number: 03128A56B | Sample n | umber(s): | 4039250-40 | 39258 | | | | |
| TPH-GRO - Waters | N.D. | 50. | ug/l | 98 | 101 | 70-130 | 4 | 30 |
| Benzene | N.D. | 0.5 | ug/l | 115 | 118 | 80-118 | 3 | 30 |
| Toluene | N.D. | 0.5 | ug/l | 112 | 115 | 82-119 | 3 | 30 |
| Ethylbenzene | N.D. | 0.5 | uq/l | 113 | 116 | 81-119 | 3. | 30 |
| Total Xylenes | N.D. | 1.5 | ug/l | 114 | 117 | 82-120 | 3 | 30 |
| Methyl tert-Butyl Ether | N.D. | 2.5 | ug/1 | 114 | 115 | 79-127 | 1 | 30 |
| Batch number: P031352AA | Sample n | umber(s): | 4039256 | | | | | |
| Methyl Tertiary Butyl Ether | N.D. | 0.5 | ug/l | 101 | | 77-127 | - | |
| di-Isopropyl ether | N.D. | 0.5 | ug/l | 100 | | 74-125 | | |
| Ethyl t-butyl ether | N.D. | 0.5 | ug/l | 108 | | 74-120 | | |
| t-Amyl methyl ether | N.D. | 0.5 | ug/l | 100 | | 79-113 | | |
| t-Butyl alcohol | N.D. | 5. | ug/l | 107 | | 53-147 | | |
| Batch number: P031352AB | Sample n | umber(s): | 4039257-40 | | | | | |
| Methyl Tertiary Butyl Ether | N.D. | 0.5 | ug/l | 101 | | 77-127 | | |
| di-Isopropyl ether | N.D. | 0.5 | υ g /1 | 100 | | 74-125 | | |
| Ethyl t-butyl ether | N.D. | 0.5 | ug/l | 108 | | 74-120 | | |
| t-Amyl methyl ether | N.D. | 0.5 | ug/l | 100 | | 79-113 | | |
| t-Butyl alcohol | N.D. | 5 | ug/l | 107 | | 53-147 | | |

Sample Matrix Quality Control

| | MS | MSD | MS/MSD | | RPD | BKG | DUP | DUP | Dup RPD |
|-----------------------------|--------|----------|---------------|----------|------------|------|------|------------|------------|
| Analysis Name | %REC | %REC | <u>Limits</u> | RPD | <u>MAX</u> | Conc | Conc | <u>RPD</u> | <u>Max</u> |
| Batch number: 03128A56B | Sample | number | (s): 40392 | 50-40392 | 258 | • | | | |
| TPH-GRO - Waters | 104 | | 70-130 | | | • | | | |
| Benzene | 113 | | 67-136 | | | | • | | |
| Toluene | 114 | | 78-129 | | | | | | |
| Ethylbenzene | 115 | | 75-133 | | | • | | | |
| Total Xylenes | 113 | | 86-132 | | | | | | |
| Methyl tert-Butyl Ether | 114 | | 66-136 | | | | | | - |
| Batch number: P031352AA | Samp1 | e number | c(s): 40392 | 56 | | | | | |
| Methyl Tertiary Butyl Ether | 105 | 105 | 69-134 | 0 | 30 | | | | |
| di-Isopropyl ether | 105 | 103 | 75-130 | 2 | 30 | | | | |
| Ethyl t-butyl ether | 112 | 113 | 73-123 | 1 | 30 | | | | |
| t-Amyl methyl ether | 102 | 103 | 77-117 | 1 | 30 | | | | |
| t-Butyl alcohol | 110 | 111 | 39-155 | 1 | 30 | | | | |
| Batch number: P031352AB | Sampl | e number | r(s): 40392 | 57-4039 | 258 | | | | |
| Methyl Tertiary Butyl Ether | 105 | 105 | 69-134 | 0 | 30 | | | | |
| di-Isopropyl ether | 105 | 103 | 75-130 | 2 | 30 | | | | |
| Ethyl t-butyl ether | 112 | 113 | 73-123 | 1 | 30 | | | • | |
| t-Amyl methyl ether | 102 | 103 | 77-117 | 1 | 30 | | | | |
| t-Butyl alcohol | 110 | 111 | 39-155 | 1 | 30 | | | • | |

*- Outside of specification

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The background result was more than four times the spike added.



2425 New Holland Pike, PO Box 12425, Lancaster, PA 17605-2425 •717-656-2300 Fax: 717-656-2681 • www.lancasterlabs.com

Page 2 of 2

Quality Control Summary

Client Name: ChevronTexaco

Group Number: 850860

Reported: 05/19/03 at 01:10 PM

Surrogate Quality Control

Analysis Name: BTEX, MTBE

| | Trifluorotoluene-F | Trifluorotoluene-P | | |
|--|---|--|--|---|
| 4039250 | 93 | 106 | | |
| 4039251 | 103 | 112 | | |
| 4039252 | 99 | 117 | | |
| 4039253 | 105 | 118 | | |
| 4039254 | 90 | 103 | | |
| 4039255 | 93 | 105 | | |
| 4039256 | 100 | 111 | | |
| 4039257 | 92 | 108 | i | |
| 4039258 | 90 | 104 | | |
| Blank | 91 | 105 | } | |
| LCS | 95 | 104 | | |
| LCSD | . 91 | 105 | | |
| MS | 98 | 105 | | |
| Limits: | 57-146 | 66-136 | | |
| | | | | |
| Analysis N | Name: Oxygenates by 8260B | • | | |
| Analysis N Batch numb | Name: Oxygenates by 82608 Der: P031352AA Dibromofluoromethane | 1,2-Dichloroethane-d4 | Tdluene-d8 | 4-Bromofluorobenzene |
| Batch numb | per: P031352AA Dibromofluoromethane | 1,2-Dichloroethane-d4 | 95 | 92 |
| 4039256 | per: P031352AA Dibromofluoromethane | 106 | 95 95 | 92 90 |
| Batch numb 4039256 Blank | per: P031352AA Dibromofluoromethane 93 94 | 106 103 | 95 | 92 90 92 |
| Batch numb 4039256 Blank LCS | per: P031352AA Dibromofluoromethane 93 94 93 | 106 103 105 | 95 95 | 92 90 92 93 |
| Batch numb | per: P031352AA Dibromofluoromethane 93 94 | 106 103 | 95 95 95 | 92 90 92 |
| Batch numb 4039256 Blank LCS MS | 93 94 93 92 | 106 103 105 104 | 95 95 95 96 | 92 90 92 93 |
| Batch numb 4039256 Blank LCS MS MSD Limits: Analysis | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B | 106 103 105 104 107 | 95 95 95 95 96 | 92 90 92 93 92 |
| Batch numb 4039256 Blank LCS MS MSD Limits: Analysis | 93 94 93 92 93 92 93 | 106 103 105 104 107 | 95 95 95 95 96 | 92 90 92 93 92 |
| Batch numb 4039256 Blank LCS MS MSD Limits: Analysis: Batch num | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B ber: P031352AB | 106 103 105 104 107 | 95 95 95 95 96 95 85-112 Toluene-d8 | 92 90 92 93 92 83-113 4-Bromofluorobenzen |
| Batch numb 4039256 Blank LCS MS MSD Limits: Analysis Batch num 4039257 | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B ber: P031352AB Dibromofluoromethane | 106 103 105 104 107 82-112 1,2-Dichloroethane-d4 | 95 95 95 96 95 85-112 Toluene-d8 | 92 90 92 93 92 83-113 4-Bromofluorobenzen 90 |
| Batch number 1995 Analysis Batch number 1995 Bat | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B ber: P031352AB Dibromofluoromethane 94 95 | 106 103 105 104 107 82-112 1,2-Dichloroethane-d4 | 95 95 95 95 96 95 85-112 Toluene-d8 | 92 90 92 93 92 83-113 4-Bromofluorobenzen 90 90 89 |
| Batch numb 4039256 Blank LCS MS MSD Limits: Analysis Batch num 4039257 4039258 Blank | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B ber: P031352AB Dibromofluoromethane 94 95 93 | 106 103 105 104 107 82-112 1,2-Dichloroethane-d4 | 95 95 95 96 95 85-112 Toluene-d8 | 92 90 92 93 92 83-113 4-Bromofluorobenzen 90 90 89 |
| Batch numb 4039256 Blank LCS MS MSD Limits: Analysis Batch num 4039257 4039258 Blank LCS | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B ber: P031352AB Dibromofluoromethane 94 95 93 93 | 106 103 105 104 107 82-112 1,2-Dichloroethane-d4 102 106 106 105 | 95 95 95 96 95 85-112 Toluene-d8 94 95 95 | 92 90 92 93 92 83-113 4-Bromofluorobenzen 90 90 89 92 93 |
| Hatch number 1995 Analysis Batch number 1995 Batch number 1995 Blank | per: P031352AA Dibromofluoromethane 93 94 93 92 93 81-120 Name: Oxygenates by 8260B ber: P031352AB Dibromofluoromethane 94 95 93 | 106 103 105 104 107 82-112 1,2-Dichloroethane-d4 | 95 95 95 96 95 85-112 Toluene-d8 94 95 95 | 92 90 92 93 92 83-113 4-Bromofluorobenzen 90 90 89 |

*- Outside of specification

(1) The result for one or both determinations was less than five times the LOQ.

(2) The background result was more than four times the spike added.



Explanation of Symbols and Abbreviations

The following defines common symbols and abbreviations used in reporting technical data:

| N.D. | none detected | BMQL | Below Minimum Quantitation Level |
|----------|-----------------------|----------|----------------------------------|
| TNTC | Too Numerous To Count | MPN | Most Probable Number |
| IU · | International Units | CP Units | cobalt-chloroplatinate units |
| umhos/cm | micromhos/cm | NTU | nephelometric turbidity units |
| C | degrees Celsius | F | degrees Fahrenheit |
| meg | milliequivalents | lb. | pound(s) |
| g | gram(s) | kg | kilogram(s) |
| ug | microgram(s) | mg | milligram(s) |
| . ml | milliliter(s) | 1 | liter(s) |
| m3 | cubic meter(s) | ul | microliter(s) |

- less than The number following the sign is the <u>limit of quantitation</u>, the smallest amount of analyte which can be reliably determined using this specific test.
- > greater than
- J estimated value The result falls within the Method Detection Limit (MDL) and Limit of Quantitation (LOQ).
- ppm parts per million One ppm is equivalent to one milligram per kilogram (mg/kg), or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter of gas per liter of gas.
- ppb parts per billion
- Dry weight basis

Results printed under this heading have been adjusted for moisture content. This increases the analyte weight concentration to approximate the value present in a similar sample without moisture. All other results are reported on an as-received basis.

Inorganic Qualifiers

U.S. EPA CLP Data Qualifiers:

Organic Qualifiers

| | | | ~ |
|-------|--|---|--|
| Α | TIC is a possible aldol-condensation product | В | Value is <crdl, but="" th="" ≥idl<=""></crdl,> |
| В | Analyte was also detected in the blank | E | Estimated due to interference |
| С | Pesticide result confirmed by GC/MS | M | Duplicate injection precision not met |
| D | Compound quantitated on a diluted sample | N | Spike sample not within control limits |
| Ē | Concentration exceeds the calibration range of | S | Method of standard additions (MSA) used |
| _ | the instrument | | for calculation |
| N | Presumptive evidence of a compound (TICs only) | U | Compound was not detected |
| P | Concentration difference between primary and | W | Post digestion spike out of control limits |
| • | confirmation columns >25% | * | Duplicate analysis not within control limits |
| U | Compound was not detected | + | Correlation coefficient for MSA < 0.995 |
| X,Y,Z | Defined in case narrative | | · |

Analytical test results for methods listed on the laboratories' accreditation scope meet all requirements of NELAC unless otherwise noted under the individual analysis.

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff. This report shall not be reproduced except in full, without the written approval of the laboratory.

WARRANTY AND LIMITS OF LIABILITY - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL LANCASTER LABORATORIES BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF LANCASTER LABORATORIES AND (B) WHETHER LANCASTER LABORATORIES HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Lancaster Laboratories which includes any conditions that vary from the Standard Terms and Conditions of Lancaster Laboratories and we hereby object to any conflicting terms contained in any acceptance or order submitted by client.