



Chevron  
7225 Bancroft  
Oakland

10-9-98



10-9-98



10-9-98

MCVO

Dispenser nearest USTs Building



← Bavercroft Ave

↓ 73 rd  
Ave



↓ 73 rd  
Bavercroft →

7225 Bavercroft Ave, Oakland 8/27/96  
85617187379-2M 1438 9352  
COPIES & ENLARGEMENTS CALL 800-421-1030  
Sampling of piping trenches.

7225 Bavercroft Ave, Oakland 8/27/96  
85617187379-2M 1438 9353  
COPIES & ENLARGEMENTS CALL 800-421-1030  
Sampling of piping trenches Juliet Skinner



7225 Bavercroft Ave, Oakland 8/27/96  
85617187379-2M 1438 9356  
COPIES & ENLARGEMENTS CALL 800-421-1030  
Stained fill material excavated from above  
clay at dispenser closest to USTs. - Juliet Skinner



7225 Bancroft Ave, Oakland 8/27/96  
 05617107379-24 1438 9348  
 COPIES & ENLARGEMENTS CALL 800-421-1030  
 Picture of 3 former dispensers. Dispenser  
 in foreground is northernmost. - Juliet S.

7225 Bancroft Ave, Oakland 8/27/96  
 05617107379-24 1438 9348  
 COPIES & ENLARGEMENTS CALL 800-421-1030  
 Northernmost dispenser & piping & vent line  
 trenches. - Juliet S.



7225 Bancroft Ave, Oakland 8/27/96  
 05617107379-24 1438 9350  
 COPIES & ENLARGEMENTS CALL 800-421-1030  
 Sampling beneath northernmost  
 dispenser. - Juliet S.

7225 Bancroft Ave, Oakland 8/27/96  
 Juliet S. 05617107379-24 1438 9351  
 COPIES & ENLARGEMENTS CALL 800-421-1030  
 Sample collected from piping trench adjacent  
 to middle dispenser had strong odor in fill  
 above clay. Fives moisture & broken water lines.



7225 Baveroff Ave, Oakland 8/27/66

05617107379-24 1438 9355

COPIES & ENLARGEMENTS CALL 800-421-1030

Soil sample collected from native clay at  
dispenser located nearest to W2. To N, water  
above clay was smelly & stained. *Juliet Spun*



7225 Baveroff Ave, Oakland 8/27/66

05617107379-24 1438 9354

COPIES & ENLARGEMENTS CALL 800-421-1030

Soil sample from piping trench. All native  
soil was black & clayey. *Juliet Spun*