

P.O. BOX 1601, OXNARD, CALIFORNIA 93032 (805) 644-5892 • FAX (805) 654-0720

August 3, 1990

Larry Seto
Hazardous Materials Specialist
Alameda County Health Care Services Agency
Hazardous Materials Program
80 Swan Way, Room 200
Oakland, California 94621

RE: Desert Petroleum station #796 2844 Mountain Boulevard Oakland, CA

Dear Mr. Seto:

Enclosed is a copy of station #796's site assessment report for your review and comment. Four borings were advanced and sampled, and then completed as groundwater monitoring wells. Hydrocarbon contamination was found in both the soil and groundwater. However, it appears to be concentrated near the super-unleaded tank.

If you have any questions or concerns, please give me a call.

Sincerely,

Wendy J. Wittl

Seniór Project Geologist

encl.

cc: Desert Petroleum, J. R.



P.O. BOX 1601, OXNARD, CALIFORNIA 93032 (805) 644-5892 • FAX (805) 654-0720

Site Assessment Report for Desert Petroleum Station #796 (dba Arco) 2844 Mountain Boulevard Oakland, California

> prepared for Desert Petroleum, Inc. 2060 Knoll Drive Ventura, CA 93003

prepared by
RSI - Remediation Service, Int'l
P.O. Box 1601
Oxnard, CA 93032
(805) 644-5892

July 25, 1990

TABLE OF CONTENTS

			Page
1.0	INTR	ODUCTION	2
		Site Description Background Summary	2
2.0	SITE	ASSESSMENT	3
	2.2	Assessment Procedures Findings - Soil Findings - Groundwater	3 5 6
3.0	CONC	LUSIONS	7
4.0	LIMI'	TATIONS	8
FIGU	JRES		
2.	Site :	ion Map Plan dwater Elevation Map 5/30/90	
TABI	LES		
2. 3.	Summa: Summa:	Construction Data ry of Analytical Results for Soil ry of Analytical Results for Groundwater dwater Data	
APPE	ENDICE	S	
Α.	Descr	g Logs iption of Boring Techniques and Sampling Procedures al Monitoring Well Construction Diagram	
в.	Ground Field	dwater Sampling Procedures Logs	
	Chain	ial Laboratory Reports of Custody	
D.	Alame	da County Well Permit	

1.0 INTRODUCTION

This report presents the data and findings of additional environmental assessment work completed at Desert Petroleum's station #796. This station operates under the Arco trade name and is located at 2844 Mountain Boulevard, Oakland, Alameda County, California (Figure 1). See Containing elevated levels of hydrocarbons was discovered during the replacement of supply lines between the underground storage tanks and the pumps.

Remediation Service, Int'l (RSI) has been retained to further delineate the gasoline contamination.

1.1 Site Description

The site is occupied by a retail gasoline outlet supplying regular, regular-unleaded and super-unleaded gasolines. The gasoline underground storage tanks have capacities of 3,000 gallons (super unleaded), 4,000 gallons (regular) and 10,000 gallons (regular unleaded). Surface improvements include a cashiers building, two pump islands and canopy (Figure 2).

1.2 Background Summary

Soil contamination was initially identified during replacement of the gasoline supply lines. Four soil samples were collected from beneath the previous supply lines in the vicinity of the fuel pumps, under the direction of Alameda County Health Care Services personnel. Laboratory analysis of the samples showed total petroleum hydrocarbon (TPH) concentrations ranging from 8 to 87 parts per million (ppm). An additional sample taken near the

edge of the super unleaded tank had a TPH concentration of 8,400 ppm.

The next phase of characterization was conducted by On-Site Technologies. Their excavation work started on July 7, 1989 and continued through August 18. Soil was removed from the south end of the super unleaded tank, creating a hole approximatel in radius and 12 feet deep. All excavated dirt was stockpiled onsite in three separate locations. Soils uncovered by the excavation consisted of clays and gravelly clays. Groundwater flowed into the excavation and stabilized at 8.5 to 8.7 feet below grade.

Laboratory analyses of soil and water samples indicated a fairly confined plume of hydrocarbon contamination in the soil at the southern end of the super-unleaded tank. TPH concentrations for soil samples from the excavation ranged from 2 to 3,300 ppm. A groundwater sample obtained from the excavation contained a TPH concentration of 160 ppm.

1 1 1 1 1 1 1

2.0 SITE ASSESSMENT

2.1 Assessment Procedures

Under the supervision of an RSI geologist four soil borings, RS-1 through RS-4, were advanced and sampled on May 29 and 30, 1990 (Figure 2). Each boring was completed as a 4-inch PVC-cased groundwater monitoring well. During drilling operations soil

samples were collected every 5 feet, starting at 5 feet beneath ground surface (bgs) down to the total depth of each boring.

These samples were used for laboratory analysis, field testing and soil description. The boring logs, a description of drilling and soil sampling operations and a well construction diagram are included in Appendix A. Table 1 presents well construction specifics.

All drilling was done by:
Kvilhaug Drilling
1109 Landini Lane
Concord, CA 94520
License Number 482390

Both soil and groundwater samples were transported to a California certified laboratory for analysis of benzene, toluene, ethyl benzene and total xylenes (BTXE) and total petroleum hydrocarbons (TPH) using EPA methods 8020 and 8015.

All samples were analyzed by:
Superior Analytical Laboratory, Inc.
1385 Fairfax Street, Suite D
San Francisco, CA 94124

Table 2 presents a summary of analytical results for soil samples and Table 3 gives a summary of analytical results for groundwater samples. The complete laboratory reports and chain of custody documents are included in Appendix C.

Groundwater was encountered during drilling in all borings.

Upon completion of the wells, each well was developed by surging and bailing. All the wells went dry after a very short time.

Approximately 25 gallons were recovered from RS-2 and RS-4, 35 gallons from RS-3 and 50 gallons from RS-1. After sufficient recharge into the wells, groundwater samples were collected.

The primary purpose for well development is to ensure maximum groundwater flow into the well, with as little sediment as possible. At this site the adequacy of well development was severely limited by the very slow rate of groundwater recharge. Since the possible presence of a free product or dissolved phase was unknown, no additional water was added to the wells for development purposes.

2.2 Finding - Soil

The site is underlain by primarily fine-grained sediments to a depth of 25 feet. The two northwestern borings, RS-2 and RS-3; penetrated clay or silt layers with minor constituents of sand and/or gravel. The two southern borings, RS-1 and RS-4, have clay layers interbedded with silty or clayey sand beds. The proportion of sand layers to clay layers in these latter two borings is almost equal.

Three soil samples from each boring were selected for analyses, except for RS-3 which had only two samples chosen. Moderate concentrations of TPH were found in RS-1 at 10 feet (58 ppm) and in RS-2 at 5 feet (22 ppm) and 8 feet (240 ppm). Low levels of BTEX, below 1 ppm, were identified in all the other soil samples.

2.3 Findings - Groundwater

Groundwater occurs at very shallow depths at the site.

water levels collected on May 30 ranged from 6 ft to 8.34 ft

bgs (Table 4). A groundwater elevation map was contoured based
on the May 30 measurements (Figure 3). The local gradient
appears to be to the southwest, which is expected based on the
topography.

Analytical results show that there are low to moderate levels of hydrocarbons in groundwater. The State standards for TPH and BTX maximum contaminant levels in drinking water were exceeded in RS-2. The analytical results from RS-1 were very similar, except xylenes were within standards. Only benzene exceeded the drinking water standards in RS-3 and RS-4; the other compounds were well below allowable drinking water concentrations.

3.0 CONCLUSIONS

The presence of hydrocarbons was identified both in the soil and in the groundwater in all four borings. The two borings, RS-1 and RS-2, nearest the suspected leak source (over spill from the super-unleaded tank), had the highest hydrocarbon concentrations. All three tanks were precision tested and determined to be "tight". The other two borings, RS-3 and RS-4, had very low concentrations in both the soil and groundwater. RS-3 is upgradient of the tank and RS-4 is down-gradient of the suspected leak source. Significant soil contamination appears to be located near the super-unleaded tank. Even though groundwater

is found at 6 ft to 8 ft bgs, no free product was found and elevated dissolved phase concentrations also appear to be located near the super unleaded tank.

4.0 LIMITATIONS OF INVESTIGATIONS

The discussion and recommendation presented in this report are based on the following:

- The professional performance of the personnel who conducted the investigations.
- 2. The observations of the field personnel.
- 3. The results of laboratory analyses performed by a state certified laboratory.
- 4. Any referenced documents.
- 5. Our understanding of the regulations of the State of California; also, if applicable, other local regulations.

The services performed by Remediation Service Int'l have been conducted in a manner consistent with the level of care and skill ordinarily exercised by members of our profession currently practicing under similar conditions in the State of California. Please note that contamination of soil and/or groundwater must be reported to the appropriate agencies in a timely manner. No other warranty, expressed or implied, is made.

Wendy J. Wittl

Senior Project Geologist

Robert C. Micha

Registered Geo/100


ROBERT C.


솻

MICHAEL No. 3849

☆

OF CALIFO






Monitoring Well Location

Approximate Scale: 1" = 25'





Approximate Scale: 1" = 25'

TABLE 2

Desert Petroleum Station #796

Summary of the Analytical Results for (mg/kg)

Well I.D.	Depth (ft)	Benzene	Toluene	Xylenes	Ethyl Benzene	TPH
RS-1	5	0.59	0.53	0.76	0.085	9
RS-1	10	6.20	8.00	5.20	0.850	58
RS-1	28	0.004	0.003	ND	ND	ND <1
RS-2	5	1.10	0.85	2.50	0.26	22
RS-2	8	1.30	7.30	20.0	2.90	240
RS-2	25	0.059	0.08	0.068	ND	1
RS-3	5	0.084	0.014	0.030	0.004	ND <1
RS-3	25		0.009	0.020	ND	ND <1
RS-4	5	0.079	0.006	0.028	0.004	ND <1
RS-4	7	0.037	0.006	0.006	ND	ND <1
RS-4	25	0.006	0.007	0.006	ND	ND <1

TPH - Total Petroleum Hydrocarbons

ND not detected

TABLE 3

Desert Petroleum Station #796

Summary of Analytical Results for Groundwater (mg/l)

Well I.D.	Benzene	Toluene	Xylenes	Ethylbenzene	TPH
RS-1	0.37	0.42	0.32	0.04	2.7
RS-2 RS-3	7.2 0.002	4.8 0.001	3.3 0.15	0.30 0.001	23. 0.33
RS-4	0.009	0.011	0.049	0.009	0.44

TABLE 4

Desert Petroleum Station #796

Groundwater Data

All Measurements in Feet

Well I.D.	Depth To	Wellhead	Groundwater
	Groundwater	Elevation	Elevation
RS-1	7.20	689.25	682.05
RS-2	7.06	689.00	681.94
RS-3	6.00	690.00	684.00
RS-4	8.34	689.06	680.72

Elevation of RS-3 estimated based on U.S.G.S. togographical map of the area. Elevation of other wellheads referenced to R-3.

TABLE 1
DESERT PETROLEUM STATION #796

WELL CONSTRUCTION DATA

All Measurements in feet, unless otherwise noted.

Well I.D.	RS-1	RS-2	RS-3	RS-4
DATE CONSTRUCTED TYPE OF CASING CASING DIAMETER	05/29/90	05/30/90	05/30/90	05/30/90
	PVC	PVC	PVC	PVC
	4 INCH	4 INCH	4 INCH	4 INCH
TOTAL DEPTH BLANK CASING SLOTTED CASING SLOT SIZE	31	25	25	25
	0 - 5	0 - 5	0 - 5	0 - 5
	5 - 30	5 ~ 25	5 - 25	5 - 25
	0.02 INCH	0.02 INCH	0.02 INCH	0.02 INCH
CEMENT	0 - 2	0 - 2	0 - 2	0 - 2
BENTONITE PLUG	2 - 4	2 - 4	2 - 4	2 - 4
FILTER PACK	4 - 31	4 - 25	4 - 25	4 - 25
TYPE OF PACK	#3 SAND	#3 SAND	#3 SAND	#3 SAND

LEGEND SHEET FOR BORING LOGS

BORING LOG SYMBOLS

MONITORING WELL SYMBOLS

\boxtimes	Modified California Sampler (blow count)
-------------	---


Concrete Seal



















Known Contact

Slotted Section of Casing

Gradational Contact

LITHOLOGIES



CLAY



Silty CLAY



Sandy CLAY



SILT



Clayey SILT



Sandy SILT



SAND



Clayey SAND



Silty SAND



Gravels & Gravel-Sand Mixtures



All Silty or Clayey Gravels



Bedrock



Fill



Asphalt/ Concrete



DEFINITION OF TERMS USCS CLASSIFICATION FOR SOILS						
	PRIMARY DIVISIONS		SYM- BOLS	SECONDARY DIVISIONS		
	GRAVELS	CLEAN GRAVELS	GW	Well graded gravels, gravel-sand mixtures, little or no fines		
S TER TZE	MORE THAN HALF OF COARSE FRACTION IS	(LESS THAN 5% FINES)	GP	Poorly graded gravels or gravel-sand mixtures, little or no fines		
SOIL ALE LARG	LARGER THAN NO.4 SIEVE SIZE	GRAVELS	GM	Silty gravels, gravel-sand-silt mixtures, non-plastic fines		
AINED AN H IS SIE		WITH FINES	GC	Clayey gravels, gravel-sand-clay mixtures, plastic fines		
COARSE GRAINED SOILS MORE THAN HALF OF MATERIAL IS LARGER THAN NO.200 SIEVE SIZE	SANDS	CLEAN SANDS	sw	Well graded sands, gravelly sands, little or no fines		
OARS MOR MATE N NO	MORE THAN HALF OF COARSE FRACTION IS	(LESS THAN 5% FINES)	SP	Poorly graded sands, gravelly sands, little or no fines		
OF THA	SMALLER THAN NO.4 SIEVE SIZE	SANDS WITH FINES	SM	Silty sands, sand-silt mixtures, non-plastic fines		
			SC	Clayey sands, sand-clay mixtures, plastic fines		
IZB IZB	SILTS AND CLA	ve	ML	Inorganic silts and very fine sands, rock flour, silty or clayey fine sands or clayey silts with slight plasticity		
ED SOILS HALF OF S SMALLER SIEVE SIZE	LIQUID LIMIT LESS THAN 5		CL	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, lean clays		
VED S I HAI IS SN SIE	LESS THAN 5	08	OL	Organic silts and organic silty clays of low plasticity		
GRAINED THAN H		AV0	МН	Inorganic silts, micaceous or diatomaceous fine sandy or silty soils, elastic silts		
FINE GRAINE MORE THAN MATERIAL IS THAN NO.200	SILTS AND CL		СН	Inorganic clays of high plasticity, fat clays		
MA THAL	LIQUID LIMIT IS GREATER THAN 50%			Organic clays of medium to high plasticity, organic silts		
	HIGHLY ORGANIC SOILS	3	Pt	Peat and other highly organic soils		

1

-

:

, DESERT PETROLEUM STATION #796

Oakland, CA

Date: 5/29/90

Time Started/Finished: 12:15/3:30 Sampling Method: Mod Cal Rig Type: Mobile B-61 HSA Drilling Contractor: Kvilhaug

MONITORING WELL: RS-1

Sheet 1 of 1

Logged By: BJM

Casing Size & Type: 4" PVC

Screen Size & Type: 4" PVC; 0.020" Slots

Drawing Contractor, Kylinaug						Datum/neterence.
DEPTH SAM (FEET) IN		PID ppm	BLOWS PER HALF FOOT		uscs	SOIL DESCRIPTION AND NOTES
0					CL	SILTY CLAY, BLACK.
5		90	5, 18, 40		T	SILTY CLAY, BLACK TO GREENISH-GREY, STIFF, DAMP, MODERATE HYDROCARBON ODOR.
10		130	7, 14, 20		CL	SILTY CLAY, TAN AND GREENISH-GREY MOTTLED, STIFF, VERY DAMP TO WET, MOBERATE HYDROCARRON BOOK
15		2	12, 12, 12	1000	SM	<u>SILTY SAND</u> WITH MINOR <u>GRAVEL</u> (<10%), TAN, VERY FINE-FINE GRAINED, SLIGHTLY STIFF, WET, NO HYDROCARBON ODOR.
20		5	15, 25, 25		SM	SILTY SAND AND GRAVEL, TAN-BROWN, FAIRLY STIFF, SAND IS FINE-COARSE GRAINED, POORLY SORTED, GRAVEL UP TO 1 1/2" DIAMETER, WET, NO HYDROCARBON ODOR.
25		<1	6, 12, 22		CL	<u>CLAY</u> WITH MINOR <u>SAND</u> (≤5%), TAN, STIFF, DAMP, <u>SAND</u> IS VERY COARSE GRAINED, NO HYDROCARBON ODOR.
30		<1	8, 12, 30		sc	CLAYEY SAND AND GRAVEL, TAN, FAIRLY STIFF. SAND IS FINE-COARSE GRAINED, POORLY SORTED. GRAVEL UP TO 1/4" DIAMETER, VERY DAMP, NO HYDROCARBON ODOR.
35 —						TD AT 31 FEET. CSG AT 30 FEET.
40						
45 —						

Sheet 1 of 1

DESERT PETROLEUM STATION #796

Oakland, CA Date: 5/30/90

Time Started/Finished: 9:30/12:00

Sampling Method: Mod Cal Rig Type: Mobile B-61 HSA Drilling Contractor: Kvilhaug

MONITORING WELL: RS-2

Logged By: BJM

Casing Size & Type: 4" PVC

Screen Size & Type: 4" PVC; 0.020" Slots

	Drilling Contractor, Kvilnaug			iog		Datum/neterence.
DEPTH (FEET)	SAMPLE INT.	PID ppm	BLOWS PER HALF FOOT	WELL ' DETAILS	uscs	SOIL DESCRIPTION AND NOTES
0					CL	SILTY CLAY, BLACK. SILTY CLAY, DARK GREY-BLACK, STIFF, DAMP, SLIGHT
5 — — —		180	7, 19, 30 7, 15, 32		T	HYDROCARBON ODOR. SANDY CLAY WITH MINOR GRAVEL (≤5%), TAN AND GREY-GREEN MOTTLED, FAIRLY STIFF, VERY DAMP. SAND IS FINE GRAINED, STRONG HYDROCARBON ODOR.
10		120	7, 15, 35		CL	SANDY CLAY, AS ABOVE, SLIGHT HYDROGARBON GOOR.
15 — —		6	7, 18, 30			SANDY CLAY WITH MINOR GRAVEL (10-20%), TAN, FAIRLY STIFF, DAMP, SAND IS FIINE-COARSE GRAINED, POORLY SORTED, GRAVEL TO 1/2" DIAMETER. NO HYDROCARBON ODOR.
20 —		3	5, 15, 20		CL	SANDY CLAY AND GRAVEL (≤5%), AS ABOVE.
25 — —		<1	8, 12, 20		CL	SANDY CLAY AND GRAVEL (≤5%), AS ABOVE. TD AT 25 FEET. CSG AT 25 FEET.
30 —						
35 —						
40 —						
45 — —						

DESERT PETROLEUM STATION #796

Oakland, CA Date: 5/30/90

Time Started/Finished: 12:30/2:30 Sampling Method: Mod Cal Rig Type: Mobile B-61 HSA Drilling Contractor: Kvilhaug

MONITORING WELL: RS-3

Sheet 1 of 1

Logged By: BJM

Casing Size & Type: 4" PVC

Screen Size & Type: 4" PVC; 0.020" Slots

Drilling Contractor: Kvilhaug						Datum/Reference:
DEPTH (FEET)	SAMPLE INT.	PID ppm	BLOWS PER HALF FOOT	WELL DETAILS	uscs	SOIL DESCRIPTION AND NOTES
o					cl.	CLAY, BLACK, STIFF, DAMP, NO HYDROCARBON ODOR.
5	\times	7	5, 13, 25		₩ HL	CLAYEY SILT, TAN AND GREY MOTTLED, STIFF, DAMP, NO HYDROCARBON ODOR.
10 —		<1	5, 13, 17		CL	SANDY CLAY, TAN, FAIRLY STIFF, VERY DAMP, NO HYDROCARBON ODOR
15 —		1	7, 12, 15		CL	SANDY CLAY WITH MINOR GRAVEL (≤5%) WITH THIN INTERBEDDED (4° THICK) OF <u>CLAYEY SAND</u> . TAN, FAIRLY STIFF, WEET. <u>SAND</u> IS FINE-COARSE GRAINED, POORLY SORTED. NO HYDROCARBON ODOR.
20 — —		<1	6, 12, 16		,	SANDY CLAY WITH MINOR <u>GRAVEL</u> (≤5%), TAN, STIFF, VERY DAMP TO WET, NO HYDROCARBON ODOR.
25 — —		<1	8, 15, 20		CL	SANDY CLAY, AS ABOVE. TD AT 25 FEET.
30 —						CSG AT 25 FEET.
35 —						
40 		·				
45 — —						

DESERT PETROLEUM STATION #796

Oakland, CA

Date: 5/30/90

Time Started/Finished: 3:00/6:00 Sampling Method: Mod Cal Rig Type: Mobile B-61 HSA Drilling Contractor: Kvilhaug

MONITORING WELL: RS-4

Sheet 1 of 1

Logged By: BJM

Casing Size & Type: 4" PVC

Screen Size & Type: 4" PVC; 0.020" Slots

Drining Contractor, Kvintady						Data i Prie i e i e i e i e i e i e i e i e i e
DEPTH (FEET)	SAMPLE INT.	PID PID	BLOWS PER HALF FOOT	WELL DETAILS	USCS	SOIL DESCRIPTION AND NOTES
5		15 22 161	7, 25, 40 7, 15, 25 6, 12, 15		sc sc CL	CLAYEY SAND WITH MINOR GRAVEL (<5%), GREENISH-GREY, FAIRLY STIFF, FINE GRAINED, DAMP, SUSHI MARKARSON, ODOR. CLAYEY SAND, TAN AND GREENISH-GREY MOTTLED, FAIRLY STIFF, FINE GRAINED, DAMP, SUGHT HYDROCARBON ODOR. SANDY CLAY, TAN AND GREENISH-GREY MOTTLED, STIFF, DAMP, MODERATE HYDROCARBON ODOR.
15 — —		<1	6, 12, 20		CL	SANDY SILTY CLAY, TAN, STIFF, VERY DAMP, NO HYDROCARBON ODOR.
20 —		<1	7, 9, 12		sc	CLAYEY SAND WITH MINOR GRAVEL (<5%), TAN, FINE GRAINED, FAIRLY STIFF, VERY DAMP, NO HYDROCARBON ODOR.
25 —		<1	7, 12, 30		CL	<u>SANDY CLAY</u> WITH MINOR <u>GRAVEL</u> (≤5%), TAN, STIFF, DAMP, NO HYDROCARBON ODOR.
30 —						TD AT 25 FEET.
40 — — — 45 — —						

DESCRIPTION OF BORING TECHNIQUES AND SAMPLING PROCEDURES

Under the supervision of a Remediation Service Int'l - (RSI) geologist, the soil borings are advanced using a truck mounted hollow-stem auger. Each auger flight is 5 feet in length with an inner diameter of 3.5 inches and an outer diameter of 8 inches. A pilot assembly, in conjunction with the auger head which is fitted with cutting blades, helps advance the auger through the soil and prevents solids from entering the hollow-stem portion of the auger. The hollow auger acts as a "temporary casing" preventing collapse of the borehole wall. Soil cuttings are carried up to the surface via the auger flights.

When the desired sample depth is reached, the drill bit and center plug are removed from the auger stem and replaced with a Modified California Split Spoon sampler. Usually, sampling is done at the end of each 5 foot auger flight. The sampler consists of an outer 12 to 18 inch long "split barrel" sampler in which a thin-walled set of rings is inserted. These rings are brass or stainless steel cylinders, each 2.0 to 3.25 inches in diameter and 3 to 6 inches long.

A 140 pound hammer is used to drive the sampler into the formation below the bottom of the auger flight, thereby filling all of the sampling rings with soil. This method allows for collection of an undisturbed soil sample, preventing introduction of overburden soil by the drilling process. The number of hammer blows (blows per foot, BPF) to advance the sampler a given distance is recorded on the boring log. This gives an indication of the amount of force required to recover the sample.

After retrieving and dismantling the sampler, all the thin tube rings are removed. The bottom ring is immediately sealed for laboratory analysis by covering both ends with teflon sheeting, plastic caps and securing the caps with tape. If some of the soil in the bottom ring has fallen out or appears to have been disturbed during the recovery operation, the second to last ring is used. This ring is labeled and placed in an ice chest for cold storage pending transportation to the laboratory. This packaging protocol is designed to prevent loss of volatiles from the soil sample, and to prevent any cross contamination. Standard chain of custody procedures are followed for all samples.


Soil from the second ring is used for field analysis of possible hydrocarbon contamination. The sample is placed in a Ziploc bag, sealed and allowed to volatilize for a HNU Photoionization Analyzer (PID) measurement. A head-space measurement is taken by breaking the seal just enough to insert the probe. The highest reading is recorded. However, if the reading stabilizes at a significantly different level, this also is noted. The PID has a detection range from 0.1 ppm to 2000 ppm for hydrocarbon vapors, when calibrated with a benzene standard.

Soils in the remaining rings are used for the field descriptions. The field data includes a written soils description, the Unified Soil Classification code, and any notable odors, staining or contamination. Also recorded are unusual drilling conditions, equipment malfunctions or other observations of field conditions for future reference. All data are included on the boring logs.

An alternative method to the use of brass rings is glass jars for sample collection. This method still utilizes the split spoon sampler, but no brass rings are inserted. Instead, soil from the base of the sampler is encapsulated in a glass jar. The jar is then treated in the same manner as soil samples in brass rings. The remaining soil in the sampler is used for field analysis and description.

To prevent any cross - contamination, the augers are steam cleaned prior to drilling each boring. The split spoon sampler is cleaned using a three step process commonly referred to as a "three bucket wash". This consist of first a trisodium phosphate wash, followed by a tap water rinse and finally a deionized water rinse. This process is completed between each sample run.

All cuttings and excess sample material recovered during the drilling operations are placed in 55 gallon DOT hazardous waste drums pending laboratory analysis results. Proper disposal is the client's responsibility.



NO SCALE
TYPICAL ONLY

TYPICAL MONITORING WELL CONSTRUCTION



SAMPLING PROCEDURES FOR GROUNDWATER MONITORING WELLS

- Top of casing or wellhead is surveyed and referenced to datum point.
- 2. Equipment is decontaminated using a three bucket wash. This consists of: (1) washing the equipment in water with trisodiumphosphate detergent; (2) rinsing with tap water; and, (3) rinsing with deionized water.
- 3. Depth to water, depth to free product (if present) and total depth of well is measured.
- 4. The well is bailed or pumped either until dry, or until 4 to 5 casing volumes of water have been removed. The water is discharged into a DOT hazardous waste drum which is labeled and left on site pending laboratory analysis of water sample.
- 5. After the well has recovered, a sample is taken using a teflon bailer and placed in a VOA vial such that no headspace is present. The vial is sealed, labeled, and cooled.
- 6. The field data sheet is completed with all pertinent information.
- 7. All the equipment is decontaminated using the 3-bucket wash.
- 8. The samples are transported to the laboratory as soon as possible following chain of custody procedures.
- 9. Wells are sampled from the cleanest to the most contaminated.
- 10. Site conditions are noted which may potentially contaminate the sample . . . any smoke, vapors from running engines, etc.

PROJECT NAME DP 796	SAMPLE:
LOCATION Ofkland	WELL X
WELL NUMBER DS- \	SURFACE WATER
	SEEP
SAMPLER By	OTHER (DESCRIBE)
_1 /	
DATE OF SAMPLING 5/30/90	•
WEATHER CONDITIONS CLEMB 4 COOL	
DEPTH TO FREE PRODUCT	
DEPTH TO WATER 7.35	
DATUM ELEVATION (msl)	•
GROUNDWATER ELEVATION (msl)	•
TOTAL WELL DEPTH 30	•
WATER LEVEL MEASURING EQUIPMENT TO PASSE	•
FREE PRODUCT LEVEL MEASURING EQUIPMENT	
EVACUATION EQUIPMENT PUC BALCER	
GALLONS TO BE EVACUATED (4 casing vols.) 55	
TIME OF EVACUATION START (1:45	
TOTAL GALLONS EVACUATED DAY & 50	
TOTAL GALLONS EVACUATED DAY & 50	
CAMPITUG FOULDWIND A	
SAMPLING EQUIPMENT DISPOSABLE BALLER	
SAMPLING TIME START FINISH 6:00	
SAMPLING RATE (ml/min.)	
APPEARANCE OF SAMPLE CLEAR	
FIELD OBSERVATIONS AND/OR PROBLEMS ENCOUNTERED	
	·
	<u> </u>
EQUIPMENT DECONTAMINATION 3 BUCKET WASH	· · · · · · · · · · · · · · · · · · ·
w	,
, , , , , , , , , , , , , , , , , , ,	
SAMPLES HAND CARRIED/SHIPPED ON 6/190	AT (2:30
(date)	(time)
(date)	(
VIA TO Suppose	- CAA
(carrier and shipper's number) labo	ratory
(cattret and surppet a number)	
FOR ANALYSIS OF TPH (645), BTEX	
FOR ANALYSIS OF 1 PHT (GAS), (SIZA	

PROJECT NAME DP 796	SAMPLE:
LOCATION DAKLAND	WELL ×
WELL NUMBER 25-2	SURFACE WATER
	SEEP
SAMPLER SMM	OTHER (DESCRIBE)
_ j _ 1	
DATE OF SAMPLING 5/31/90	
WEATHER CONDITIONS Sunty cool	
DEPTH TO FREE PRODUCT	
DEPTH TO WATER ((.60	•
DATUM ELEVATION(msl)	
GROUNDWATER ELEVATION(ms1)	•
TOTAL WELL DEPTH 25	•
WATER LEVEL MEASURING EQUIPMENT LATT. POSSE	
FREE PRODUCT LEVEL MEASURING EQUIPMENT	
EVACUATION EQUIPMENT PUC BARRE	
GALLONS TO BE EVACUATED (4 casing vols.) 46	
TIME OF EVACUATION START 7:15 FINISH 7:45	
TOTAL GALLONS EVACUATED DAY & 25	
SAMPLING EQUIPMENT DISPOSABLE BALLER	
SAMPLING TIME START FINISH 10:40	
SAMPLING RATE (ml/min.)	
APPEARANCE OF SAMPLE CLEAR	
FIELD OBSERVATIONS AND/OR PROBLEMS ENCOUNTERED	
EQUIPMENT DECONTAMINATION 5 BULLET WASH	
	-
SAMPLES HAND CARRIED/SHIPPED ON 6/1 90	AT (2:30
(date)	(time)
(440-)	, ,
VIA TO Superior	LAB
(carrier and shipper's number) To Superial	oratory
(Our rate discrete discrete)	. •
FOR ANALYSIS OF TOH (AS) BLEX	·

PROJECT NAME DO 766	•	SAMPLE:	
LOCATION OAKLAND	•	WELL X	
WELL NUMBER 25-3		SURFACE WA	TER
		SEEP	-
SAMPLER BYM		OTHER (DES	CRIBE)
-)			·
DATE OF SAMPLING 5(3(90	•		•
WEATHER CONDITIONS CLOUDY - COOL	•		•
DEPTH TO FREE PRODUCT			
DEPTH TO WATER 6.00		•	
DATUM ELEVATION(msl)			
GROUNDWATER ELEVATION (msl)	•		•
TOTAL WELL DEPTH >5'		-	
	· ·		
WATER LEVEL MEASURING EQUIPMENT	INT. PROBE		
FREE PRODUCT LEVEL MEASURING EQUI	IPMENT "		
EVACUATION EQUIPMENT PUC BALL			
GALLONS TO BE EVACUATED (4 casing			
TIME OF EVACUATION START (:55		······································	
TOTAL GALLONS EVACUATED Dey @			
			
SAMPLING EQUIPMENT DISS. BALLER	_		
-	INISH 10:50		
SAMPLING RATE (ml/min.)			
APPEARANCE OF SAMPLE CLEAR			
FIELD OBSERVATIONS AND/OR PROBLEM	MS ENCOUNTERED		
TILLE ODGILLITIES IND, OR INODELL			
HOUTDVENE DEGONMANTHAMION.			· · · · · · · · · · · · · · · · · · ·
EQUIPMENT DECONTAMINATION 3 Bu	CREAT WAS EL		
	ŗ		
SAMPLES HAND CARRIED/SHIPPED ON_	6/1/94		3=
SAMPLES HAND CARRIED/SHIPPED ON_	<u>\(\text{\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\(\text{(\)\)}})})\ext{\(\text{(\(\)})}\)}</u>	AT\2_	<u> </u>
	(date)		(time)
	6	1	
VIA	TO Superior labo		
(carrier and shipper's number)	labo	ratory ,	
FOR ANALYSIS OF THE (Cots)	BIEX		

PROJECT NAME DP 796	SAMPLE:
LOCATION DALLAND	WELL 💥
WELL NUMBER DS-4	SURFACE WATER
	SEEP
SAMPLER BW	OTHER (DESCRIBE)
ν <i>,</i> ,	
DATE OF SAMPLING 5(31(90	•
WEATHER CONDITIONS CLOSE COOL	
DEPTH TO FREE PRODUCT -	
DEPTH TO WATER 9,77	
DATUM ELEVATION(msl)	
GROUNDWATER ELEVATION (msl)	
TOTAL WELL DEPTH 25	•
	'
WATER LEVEL MEASURING EQUIPMENT	INT. PROBE
FREE PRODUCT LEVEL MEASURING EQUIP	PMENT "
EVACUATION EQUIPMENT PUC BALL	<u>fr</u>
GALLONS TO BE EVACUATED (4 casing	vols.) 40
TIME OF EVACUATION START 8:25	FINISH 8:45
TOTAL GALLONS EVACUATED DAY @ 25	-
SAMPLING EQUIPMENT DISPOSABLE	BALLER
	NISH (0:30
SAMPLING RATE (ml/min.)	
APPEARANCE OF SAMPLE	
FIELD OBSERVATIONS AND/OR PROBLEMS	S ENCOUNTERED
EQUIPMENT DECONTAMINATION 3	المدال ال
	·
SAMPLES HAND CARRIED/SHIPPED ON	6(1(90 AT 12:30
SAMPLES MAND CARRIED/SMIPPED ON	(date) (time)
	(4455)
VIA	TO SUPERIOR LAB
(carrier and shipper's number)	TO Superior Lab
(carrier and surbber a namer)	<u> </u>
FOR ANALYSIS OF TOHE () T	STEX

SUPERIOR ANALYTICAL LABORATORY, INC.

1555 Burke, Unit I · San Francisco, Ca 94124 · Phone (415) 647-2081

CERTIFICATE OF ANALYSIS

LABORATORY NO.: 52093

DATE RECEIVED: 06/01/90 DATE REPORTED: 06/12/90

CLIENT: REMEDIATION SERVICE, INT'L

CLIENT JOB NO.: DP 796

ANALYSIS FOR TOTAL PETROLEUM HYDROCARBONS by Modified EPA SW-846 Method 5030 and 8015

LAB #	Sample Identification	Concentration (mg/kg) Gasoline Range
1	RS-1 5'	9
2	RS-1 10'	58
5	RS-1 28'	ND<1
6	RS-2 5'	22
8	RS-2 8'	240
11	RS-2 25'	1
12	RS-3 5'	ND<1
16	RS-3 25'	ND<1
17	RS-4 5'	ND< 1
18	RS-4 7'	ND<1
22	RS-4 25'	ND< 1
		Concentration (ug/L)
23	RS-1	2700
24	RS-2	23000
25	RS-3	330
26	RS-4	440
na/ka -	narts per million (nnm)	

mg/kg - parts per million (ppm)
ug/L - parts per billion (ppb)

Minimum Detection Limit for Gasoline in Soil: 1mg/kg Minimum Detection Limit for Gasoline in Water: 50ug/L

QAQC Summary:

Daily Standard run at 2mg/L: RPD Gasoline = <15% MS/MSD Average Recovery = 82%: Duplicate RPD = 4%

Richard Srna, Ph.D.

Laboratory Director

SUPERIOR ANALYTICAL LABORATORY, INC.

1555 Burke, Unit I · San Francisco, Ca 94124 · Phone (415) 647-2081

CERTIFICATE OF ANALYSIS

LABORATORY NO.: 52093

CLIENT: REMEDIATION SERVICE, INT'L

CLIENT JOB NO.: DP 796

DATE RECEIVED: 06/01/90

DATE REPORTED: 06/12/90

ANALYSIS FOR BENZENE, TOLUENE, ETHYL BENZENE & XYLENES by EPA SW-846 Methods 5030 and 8020

LAB				Concentr	Concentration(ug/kg) Ethyl					
#	Sample	Identification	Benzene	Toluene	Benzene	Xylenes				
		<u> </u>								
1	RS~1	5'	590	530	85	760				
2	RS-1	10'	6200	8000	850	5200				
5	RS-1	28'	4	3	ND<3	ND<3				
6	RS-2	5'	1100	850	260	2500				
8	RS-2	8'	1300	7300	2900	20000				
11	RS-2	25'	59	80	ND<3	68				
12	RS-3	5'	84	14	4	30				
16	RS-3	25'	4	9	ND<3	20				
17	RS-4	5'	79	6	4	28				
18	RS-4	7'	37	6	ND<3	6				
22	RS-4	25'	6	7	ND<3	6				
				Concent	tration (u	ıg/L)				
23	RS-1		370	420	40	320				
24	RS-2		7200	4800	300	3300				
25	RS-3		2	1	1	150				
26	RS-4		9	11	9	49				

ug/kg or ug/L - parts per billion (ppb)

Minimum Detection Limit in Soil: 3.Oug/kg Minimum Detection Limit in Water: 0.3ug/L

QAQC Summary:

Daily Standard run at 20ug/L: RPD = <15%

MS/MSD Average Recovery = 95% : Duplicate RPD = <2%

Richard Srna, Ph.D.

OUTSTANDING QUALITY AN

	KSI			Chain of	Cu	sto	dy	Re	CO	rd		/	A	#	52093	
Proje Proje Samp P.O.	: _ wendy - -	1: Sc	555 in J	rior Analytical Laboratory Burke St. Unit 1 Francisco, CA 94124) 647-2081												
Sample Number	Date	Time	Location	Matrix	Number of Containers	Sample Preservation	TPH as Gasoline	втхе .	TPH as Diesel	Oil & Grease	8010	8240				
1 5-1	5/29/90		5′	SOIL		(CE	×	х⁄								
RS-1 RS-1	/		<u>lo′</u>			/	Х	<u> </u>								
154			15'			[/_									HOLD	
25-1			25'									<u></u>			HOL D	
25-1	/		28′				X	×								
25-1 25-2	5/30/90		5′				X	×							 	
26-2 25-2	, .		81				X	X							HOLD K	Inalyso
25-2			(O'				X	γ.							Hold	Per Bry
RS-2 RS-2			<u>≀</u> 5′											_	HOLD	
RS-2			<u> </u>												HO1 D	
RS-2			25'				X	Х								
25-3	(5′				χ									·
elinquished	By (Signatur		te/Time Received	By (Signature)		Date/	Time		REM	IARK	S:					
Buch	los	6	/1/90 12:30 1.													j
<u>:</u>			2 .													
-			3													
			4.	cely a		G/1	140	12,3	}							
		<u></u>		100/		-//									· · · · · · · · · · · · · · · · · · ·	

Chain of Custody Record

Proje Samp	oct No	6 655 man	Superior Analytical Laboratory 1555 Burke St. Unit 1 San Francisco, CA 94124 (415) 647-2081													
Sample Number	Date	Matrix	Number of Containers	Sample Preservation	TPH as Gasoline	втхЕ	TPH as Diesei	Oil & Grease	8010	8240						
RS -3	5/30/90	•	<u>lo′</u>	501L		ILF						 		 	HOLD	
RS-3			15'	/		1									HOLD	-
RS-3			201			\prod									HOC-D	
RS-3			251				×	Х						_	100-0	
RS-4			5'				У	Х								
RS-4			7 ′				X	Χ							HOLD AV	lalysia por BME,
RS-4	_		10'				<u>×</u>	X	-						Hold	per BM-
RS-4		_	15'												HOLD	
RS-4	/		20 1												HOLD	
RS-4	<u> </u>		251			7	X	X						-	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
										\Box					· · · · · · · · · · · · · · · · · · ·	
inquished B	y (Signature)		P/Time Received By (Signal (2:36)	gnature)		Date/I	îme	ر	REMA	ARKS	<u> </u>					
		2														
-			3.		1											
			Elano			9/1/	6	12.	3.)_	_						

Chain of Custody Record

	3	and the same of th																		
Sample Number	Date	Time	Loc	ation	Matrix	Number of Containers	Sample Preservation	TPH as Gasoline	втхе .	TPH as Diesel	Oil & Grease	8010	8240				:			
R5-1	5/30/90	6:00			WARED		HEJ	X	×											
25-2	5/3/190	(0)4(0)			1		1	×	×											
25-3	(10:50						X	X											_
25-4)	(০:3০		·				λ	X											
				<u> </u>					,											
																-		-		
				·																
						<u>.</u>														
				···																
Relinquished E				Received By (Sig	gnature)		Date/	Time		REM	IARK	 S:						<u> </u>	 .	
Birth	402-	_ 6	1/40 12:30	1.						1										
				2										ē						,]
				3.]										
			<u>.</u>	Elam	M.	4	6/1	190	12:	/2)	<u>-</u>		·	····						