

March 8, 2001 Project No. 400301-03

Ms. Malika Ramachandran, P.E Senior Civil Engineer Alameda Public Works Department Alameda Point, Building 1, Room 110 950 West Mall Square Alameda, California 94501

Subject.

Dissolved Lead Analysis

2756 Main Street Alameda, California

Dear Ms. Ramachandran.

Ninyo & Moore is pleased to present dissolved lead results from a sample collected at the former Dales Bar site located at 2756 Main Street, Alameda, California. The purpose of the sample collection was to present results to the State Regional Water Quality Control Board (RWQCB) in order to satisfy site closure requirements

The subject site is located near the northeast corner of Main Street and Singleton Avenue in the City and County of Alameda, California. The site was formerly occupied by a gas station that reportedly contained up to seven underground storage tanks (USTs).

A representative of our firm collected one groundwater sample (identified as WB-13) from a hand augured exploratory boring on February 27, 2000. The boring was augured to approximately 3 feet below ground surface (bgs) to obtain one groundwater sample for laboratory testing The approximate location of the boring is indicated on the Boring Location Map (Figure 1)

The groundwater was pumped from the boring through the school tubing and a 0.45-micron filter into a clean and dry 500-millititer plastic container. The sample was placed in a cooler with ice and transported via a courier to McCambell Analytical Laboratories in Pacheco. California

York R. Gorzolla, R.G., R.E.A.

Manager of Environmental Sciences

The sample was analyzed for dissolved lead using EPA Method 6010/200.7. Results of the analysis indicated the groundwater sample was non-detect for dissolved lead A copy of the analytical results are attached.

We appreciate this opportunity to be of service to The City of Alameda on this project. If you have any questions regarding this report, please contact the undersigned.

Sincerely,

NINYO & MOORE

Kris M. Larson

Senior Staff Environmental Geologist

KML/YRG/jms

0.0.01


Attachments: Boring Location Map

Laboratory Analytical Data

Distribution: (1) via fax: (510) 749-5867

(1) addressee

Alnyo Adoore



110 2nd Avenue South, #D7, Pacheco, CA 94553-5560 Telephone: 925-798-1620 Fax: 925-798-1622 http://www.mccampbell.com E-mail: main@mccampbell.com

Ninyo & Moore 675 Hegenberger Road. Ste 220			ent Project ID: #	400301-03;	Date Sampled: 02/27/01			
		Ala	meda 		Date Received: 02/28/01			
Oakland, CA 94621-1919			ent Contact: Kris	s Larson	Date Extracted: 03/01/01			
Email: not available			ent P.O:		Date Analyzed: 03/01/01			
Lead* EPA analytical methods 6010/200.7, 239.2*								
Lab ID	Client ID	Matrix	Extraction °	Lea	·d*	% Recovery Surrogate		
60977	WB-13	w	Dissolved	ND		N/A		
					<u> </u>			
					i			
								

ı		<u> </u>			<u> </u>		
Reporting Limit unless otherwise		s	TTLC	3.0 mg/kg			
	stated, ND means not detected above	W	W Dissolved 0 005 mg/L				
	the reporting limit		STLC,TCLP	0 2 mg/L			
	* soil and sludge samples are reported in mg/kg, wipe samples in ug/wipe, and water samples and all STLC / SPLP / TCLP extracts						

DISTIC extractions are performed using STLC methodology except that denonized water is substituted for citric acid buffer as the extraction field. DISTIC results are not applicable to STLC regulatory limits.

"Lead is analysed using EPA method 6010 (ICP)for soils, sludges STLC & TCI P extracts and method 239.2 (AA Furnace) for water

² EPA exacution methods 1311(TCLP), 3010-3020(water TTLC), 3040(organic matrices, TTLC), 3050(solids, TTLC), STLC - CA Title 22

 [&]quot;surrogate diluted out of range N/4 means surrogate not applicable to this analysis."

Siraporting himbiralised dealmatrix interference.

[•] liquid sample that contains greater than ~2 vol. % sediment, this sediment is extracted with the liquid, in accordance with EPA methodologies and can significantly effect reported metal concentrations.

110 2nd Ave. South, #D7, Pacheco, CA 94553-5560 Telephone: 925-798-1620 Fax: 925-798-1622

http://www.mccampbell.com E-mail: main@mccampbell.com

QC REPORT

Date:

3/01/01-03/02/01

Matrix:

Water

Extraction:

Dissolved

	Concentration:		mg/L	%Red	covery		
Compound	Sample	MS	MSD	Amount Spiked	MS	MSD	RPD
SampleID: 22101				Instr	ument: I	CP-1	
Lead	0.000	8.1	8.7	10.00	, 81	87	7.1

X

24682 ZNM 31 MCCAMPBELL ANALYTICAL INC. CHAIN OF CUSTODY RECORD THE 2rd AVENUE SOCIETION PACIFICO, CA 91551 SSOL TURN AROUND TIME QTelephone (925) 298-1620 Fax: (925) 798-1622 Report to 1115/11/2500 RUSH 24 HR 48 HR 72 HR Analysis Request Other Comments EPA 693 - 8030 PCB's ONL' FPA 624 - 8240 - 8260 SAMPLING METHOD PRESERVED MATRIX SAMPLEB TOCATION Date Time 15 | 15 | S 111.13-13H HI HIDANI 60977 DALES 115504V60 BARIL VOIS ORGINETALS OTHER PRESERVATION GOOD CONDITION APPROPRIATE CONTAINERS Relanguistica By Received By Remarks Buyler SAMPLE FIELD FILTERLY
WIO.45 MICHAN FILTERLY
Somple NOT PRESUND Relingitished Its lime Received By 1) D8M 3.75 Received Hy: