

white -env.health
yellow -facility
pink -files

ALAMEDA COUNTY, DEPARTMENT OF
ENVIRONMENTAL HEALTH
Hazardous Materials Inspection Form

1131 Harbor Bay Pkwy
Alameda CA 94502
510/567-6700

II, III

Site ID # _____ Site Name McClymonds HS Today's Date 12/27/96
Site Address 2607 Myrtle St.
City Oak Zip 94607 Phone _____

____ MAX AMT stored > 500 lbs, 55 gal., 200 cft.?
Inspection Categories:
____ I. Haz. Mat/Waste GENERATOR/TRANSPORTER
____ II. Hazardous Materials Business Plan, Acutely Hazardous Materials
____ III. Under ground Storage Tanks

water sample +
5 wall sample

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

9:53 onsite.

Comments:

They pumped 4500 gal of water from pit so far. Dave estimates they removed 200 gal diesel product from pit. Estimated size of stockpiles: Day 1 is ~60 yd³ + Day 2 is ~60 yd³. Randy said gw was at 5'9" this am before pumping, + is now at 7'3" bgs. No more floating product on gw. Took water sample: TPHd + BTEX. We have preliminary results for soil samples. ND BTEX on all 3 walls + 2 SP samples. Max pit wall was 310 ppm TPHd. Due to lack of BTEX, overex of walls is not necessary. We still need to sample 5 wall. 10:35 Took 5 wall sample from west side at 6' (clay, HC odor, greenish) (S) 10:40 5 wall sample from middle at ~6' (clay, slight HC odor, slightly greenish) (SS). Pumped gw manifest # 96416 813 (going to Evergreen, 4500 gal). Pit is now ready to be backfilled. 10:45 Noted a dark brown sheen on edges of gw in pit. The SP from 12-26 has not yet been sampled. ACC wants to pit observation well in during backfilling.

11:10

Contact ACC Environmental Dave DeRust
Title Senior Geologist
Signature Dave DeRust

Inspector J. Eberste
Signature J. Eberste

II, III

white - env. health
yellow - facility
pink - files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

1131 Harbor Bay Pkwy
Alameda CA 94502
510/567-6700

Hazardous Materials Inspection Form

II, III

Site ID # _____ Site Name McClymonds HS Today's Date 12/24/96
Site Address 2706 Myrtle St.
City Oakland Zip 94607 Phone _____

____ MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- ____ I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- ____ II. Hazardous Materials Business Plan, Acutely Hazardous Materials
- ____ III. Under ground Storage Tanks

Soil sampling

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

9:50 onsite

Comments:

Dave said they removed ~4000 gal water this am + ~4000 gal yesterday pm. He already took 2 soil samples, from N + W walls at ~7.5' bgs; Soil is silty clay. I saw them sample E wall at ~7' bgs. Pea gravel remains in pit. Strong HC odors.

10:10 offsite

Contact ACC Environmental
Title Dan DeMont
Signature Dan DeMont

Inspector _____
Signature [Signature]

II, III

white -env.health
yellow -facility
pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

1131 Harbor Bay Pkwy
Alameda CA 94502
510/567-6700

Hazardous Materials Inspection Form

II, III

Site ID # _____ Site Name M^cClaymonds HS Today's Date 12/23/96

Site Address 2607 Myrtle St.

City Oakland Zip 94607 Phone _____

page 1 of 2

MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

- I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- II. Hazardous Materials Business Plan, Acutely Hazardous Materials
- III. Under ground Storage Tanks

Removal of 5000 gal UST.

GGTR is writing TR report.

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

10:00 onsite. Dave Dement

Comments:

said they removed ~4500 gal fm UST on 12/20, + ~1/3 was product. Left pit open over weekend, when we had alot of rain. Pit is now full of product + presumably water, but is being vacuumed by American Valley. UST is 7' diam x 16' long; ~5000 gal. Dave said UST rinsate had flash pt. of 160; so it may contain solvents or gasoline. Rinsate was rejected at Erickson; it may have to go to L.A. We will analyze samples for TPHg + HVOCs as well as TPHd + BTEX. There are 2 fill ports: one was on top of UST + one is remote (on 26th St.). It will have to be grouted. 11:00 still pumping gw + product. 11:25 I was informed that Erickson was mistaken on the rinsate flash pt. Therefore, we will analyze samples for TPHd + BTEX only. 11:30 finished removing water + product. (4500 gal manifest # 96590424 to Evergreen). 11:55 offsite for lunch.

Contact John Carver
Title Engineer
Signature [Signature]

Inspector _____
Signature [Signature]

II, III

white -env.health
yellow -facility
pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

1131 Harbor Bay Pkwy
Alameda CA 94502
510/567-6700

Hazardous Materials Inspection Form

II, III

Site ID # _____ Site Name McClmonds HS Today's Date 12/23/96
Site Address 2607 Myrtle St.
City Oak Zip 94607 Phone _____

page 2 of 2

____ MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:

____ I. Haz. Mat/Waste GENERATOR/TRANSPORTER

____ II. Hazardous Materials Business Plan, Acutely Hazardous Materials

____ III. Under ground Storage Tanks

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

10:45 onsite again.

Comments: they the UST (Fiberglass) broke into pieces & is being removed in pieces onto Dexanna truck under manifest # 95996534 1:30 Steve Ng of Oakland Unified School District onsite. Pit still has gw w/ product at ~3.5' bgs. They plan to pump it out again this pm. It may require 2 more loads of trucks. UST appeared to have holes, as noted during pumpout.

2:15 left site

Contact John Carver

Title ENGINEER

Signature [Signature]

Inspector Jennifer Eberle II, III

Signature [Signature]