Wickham, Jerry, Env. Health

Subject:

RO0303 Shell 230 MacArthur Oakland

Due Date:

Friday, January 06, 2006

Status:

Not Started

Percent Complete:

0%


Total Work: Actual Work: 0 hours 0 hours

Owner:

Wickham, Jerry, Env. Health

Dave Gibbs of Cambria called on 3/23/2006. Not able to put SB-9 in the street due to proximity of storm drain and not able to move the well to sidewalk due to City of Oakland concerns. Moving it to north will bring it too close to well MW-4. Therefore, well SB-9 will not be installed. Instead, will move SB-8 to the west as close to property line as possible.

Dave Gibbs of Cambria called on 4/6/2006. Not able to get boring SB-5 in due to concrete with rebar at 3-4 feet. Tried moving to NW. I reviewed map and suggested moving location NW of dispenser. Purpose was to get near line but moving boring my defeat the purpose. Will put in boring if they can clear with air knife or hand auger.



					7)	L.	2
1		W			<u>1</u> = ==		1
		No.				\$	-1 1
	REMARKS	REMARKS			2744 4 84/0		
Date	The state of the s	Date is		Tall	REMARKS		1
9/27	EN Results of soil boung reported		Date	By	1	-	
1121	verlally by ENSCO - one boung	3/19/10 2 report - MW-4 Still	ļ				* -
	showed a TPH level of 490 ppm	about 2 ppm; report makes no mention of the two additions	b.				Carama .
	right above the water Table. a	wells to vere to be installed,		1	**************************************	1	
	Shallow GW survey in Ato	Call Extellects - Doug young				D	S
-	area will be performed.	Call Extellects - Doug Young will look into it & get back					TOTAL SAIDS
13/11	Review quarterly report that	Do me,					
	- includes written results of soil					TEAR IS	
	Boung conducted 8/89. No						81
	Justin action other Dan continu						
6/21/90	By granting GW montoring proposed Deglopper Survey performed to		-			i	
0 21	asses location for additional rella						
	workplay to be subsulted soon,						
7/26	Workplan submitted and approved.				6	-	
10 25	Workplan submitted and approved. Go Rever a po. O reconstruction,						
	MW-4, In Box mother good				- V		
11	Trao hour levels of 2-4 ppm						
4	gasoline over the post few quarters. It star 3 wells on gits have consistently shown "ND results.						
. X	1 2 h other 3 wells on gits have						