PROPERTY SERVICES, INC.

ENVIRONMENTAL INVESTIGATIONS

July 19, 1999

5 04233

REPORT OF SOIL AND GROUNDWATER INVESTIGATION AND SAMPLING OF FOUR WELLS

Karen Langmaid San Lorenzo Unified School District 15510 Usher Street San Lorenzo, CA 94580

RE: Arroyo School, 15701 Lorenzo Avenue, San Lorenzo, CA

STID: 4233

Dear Ms. Langmaid:

Thank you for contracting with Allcal Property Services, Inc. (ALLCAL) to write this report of a soil and groundwater investigation and sampling of four wells at the above-referenced property. The investigation and sampling of wells were conducted according to an April 16, 1999, work plan submitted by ALLCAL and conditionally approved in an April 21, 1999, letter (attached) by the Alameda County Health Care Services Agency (ACHCSA) to you (Client). In addition to the scope of work proposed in ALLCAL's work plan, the ACHCSA requested that the top-of-casing (TOC)elevations of the four wells be surveyed relative to mean sea level (MSL) and that methyltertiary-butyl-ether (MTBE), if detected during the groundwater investigation, be confirmed using Method 8260.

Background

The following background is summarized from the ACHCSA's October 21, 1998, letter and from other consultant reports contained in the ACHCSA's project file.

In January 1991, one 45-gallon, gasoline, underground storage tank (UST) and one 6,000-gallon, diesel UST were removed from the site (see attached SITE PLAN for tank locations). Soil samples collected from the gasoline UST excavation were analyzed for total petroleum hydrocarbons as gasoline and diesel (TPHG and TPHD, respectively) and total lead. No samples were analyzed for benzene, toluene, ethylbenzene, and xylenes (BTEX). Results of chemical analyses detected only low concentrations of lead. Soil samples collected from the diesel UST excavation were analyzed for TPHD, total oil & grease (TOG), and BTEX. Results of chemical analyses detected TPHD and

PROTECTION 1: 00

TOG at concentrations of up to 300 parts per million (ppm) and 2,000 ppm, respectively.

As an investigation of soil contamination in the area of the former diesel UST, 16 soil borings were drilled in January 1991. Soil borings 14 through 16 were converted into monitoring wells MW-1 through MW-3, respectively. Results of chemical analyses of soil samples from these borings detected TPHD and TOG at concentrations of up to 1,720 ppm and 5,685 ppm, respectively. Results of chemical analyses of groundwater samples from the wells detected TPHD at concentrations of up to 300 parts per billion (ppb).

Four additional soil borings were drilled in the area of the former diesel UST on August 10, 1992, and one of the borings was converted into groundwater monitoring well MW-4. Results of chemical analyses of soil samples from these borings detected TPHD and TOG at concentrations up to 210 ppm and 975 ppm, respectively, and low concentrations of toluene, ethylbenzene, and xylenes.

Quarterly groundwater monitoring of the site's four wells was conducted regularly for TPHD, TOG, and BTEX until March 23, 1993. Results of chemical analyses detected low concentrations of TPHD in one or more wells, with the exception of the April, 14, 1992, event when no TPHD was detected in any of the wells. TOG and BTEX were never detected, with the exception that toluene was detected at low concentrations in one or more wells on July 15, 1991, and April 14, 1992.

Details of the above work and results of chemical analyses are documented in various reports by LW Environmental Services, Inc. (LW) on file at the ACHCSA's office.

ACHCSA Request for Additional Information

In an August 16, 1992, letter to the Client, the ACHCSA requested additional work and information prior to considering site closure. The requested work consisted of: (1) Drilling a soil boring immediately down-gradient of the former gasoline UST excavation for the collection of one soil and one "grab" groundwater sample for chemical analysis. The ACHCSA requested the soil sample be analyzed for TPHG and BTEX, and the groundwater sample be analyzed for TPHG, BTEX, and MTBE. (2) Drilling a soil boring adjacent to former soil boring SB-2 for collection of soil samples at 5 and 10 feet below grade and for chemical analysis for TPHD and polynuclear aromatics (PNAs). (3) Sampling the four groundwater monitoring wells and analyzing the samples for TPHG, TPHD, BTEX, and MTBE.

WORK CONDUCTED

The following work was conducted by ALLCAL:

- Submitted an April 16, 1999, work plan to the Client and the ACHCSA for their comment and approval.
- Sampled four groundwater monitoring wells and analyzed the samples for TPHG,
 TPHD, BTEX, and MTBE. Measured depth to groundwater in each well and

determined groundwater gradient (direction of groundwater flow). The Client had contracted with a certified land surveyor to measure TOC's relative to MSL.

- Obtained a soil boring permit from the Alameda County Public Works Agency (ACPWA), marked the locations of the proposed soil boring adjacent to former boring SB-2 and the proposed boring down-gradient of the former gasoline tank, and "cleared" each boring location of underground utilities.
- Drilled two soil borings. Drilled boring SB-2A adjacent to former boring SB-2 to a depth of about 11 feet and drilled boring SB-1G at the location of the former gasoline UST to a depth of about 28 feet.
- Collected soil samples at depths of about 5 and 10 feet below grade in boring SB-2A and analyzed the samples for TPHD and PNAs. Collected one soil sample at the depth of about 23.5 feet and a "grab" groundwater sample from boring SB-1G and analyzed both samples for TPHG, BTEX, and MTBE.
- Sealed the borings with neat Portland cement.
- Prepared this report.

Details of the above work are presented below.

Sampled Groundwater Monitoring Wells/Surveyed TOC's Relative to MSL

ALLCAL's first task of the above work consisted of sampling the four wells and determining direction (gradient) of groundwater flow.

A review of seven of LW's gradient maps, ranging in date from January 1991, through May 1993, found that the north direction indicated on each map was in error by almost 180 degrees; subsequently, the direction of reported groundwater flow was not correct. Also, the horizontal scale, as measured from map to map, was variable; and beginning with the December, 1992, map, the location of well MW-3 changed significantly from earlier maps. Lastly, the TOC elevations of the wells were measured relative to an arbitrary on-site datum instead of MSL.

Well Elevation Survey:

At the request of the ACHCSA to survey the TOC elevations relative to MSL to an accuracy of .01 foot, the Client contracted with certified land surveyor Greenwood & Moore, Inc., located in Castro Valley, California, to conduct the survey. On May 26, 1999, the wells were surveyed relative to Bench Mark "C" cut in the southeasterly curb return at Grant Avenue and Via Alamitos Street. The bench mark is at an elevation of 21.807 feet MSL (see attached Monument Record). The surveyed elevations are documented in the attached drawing by Greenwood & Moore, Inc.

Well Sampling:

ALLCAL sampled the four wells on June 2, 1999. Before sampling, depth-to-water was measured to the nearest .05 foot in each well from the TOC using an electronic water level meter, and each well was checked for floating product using a dedicated disposable polyethylene bailer. No floating product was observed in any of the wells.

Sampling was conducted by purging each well of about 25 liters (3 wetted well volumes) with a dedicated polyethylene bailer. (Because a dedicated bailer was used for each well, no decontamination was necessary between sampling events.) Temperature, pH, and electrical conductivity were monitored and purging continued until they stabilized (see attached RECORDS OF WATER SAMPLING). After purging was completed, water samples were collected in laboratory-provided 40-milliliter, sterilized, glass vials and 1-liter amber bottles having Teflon-lined screw caps. The bottles were immediately sealed and labeled to include: date, time, sample location, project number, and sampler name. The samples were immediately stored in an iced-cooler for transport to California Department of Health Services certified McCampbell Analytical Inc. laboratory, located in Pacheco, California, accompanied by chain-of-custody documentation.

Purged water is stored on site in a labeled 55-gallon drum.

The water samples were analyzed for TPHG, TPHD, BTEX, and MTBE by EPA Methods GCFID 5030/8015 modified, GCFID 3550/8015 modified, 8020, and 8020, respectively. Additionally, a trip blank sample was analyzed for TPHG and BTEX.

Results of Groundwater Gradient Determination:

On June 2, 1999, direction of groundwater flow was mapped to be west-southwest with a gradient of about .006 feet/foot. See attached GROUNDWATER GRADIENT MAP-6/2/99.

Results of Chemical Analyses:

No analytes were detected in any of the wells, with the exception that TPHD was detected in well MW-4 at a concentration of 130 ppb. The laboratory noted that diesel range compounds were significant, but there was no recognizable pattern. See the attached certified analytical report.

Drilled Soil Borings

Pre-field Activities:

Prior to drilling soil borings, ALLCAL: (1) obtained a soil boring permit (attached, Number 99WR260) from the ACPWA), (2) visited the site to mark the locations of the two borings, (3) subcontracted Fast-Tek Engineering (C57 license 589008) to drill the soil borings and "cleared" each location of underground utilities, and (5) gave 48 hours' notice to the ACHCSA prior to drilling the borings.

Locations of Soil Borings:

On June 29, 1999, ALLCAL drilled soil borings SB-2A and SB-1G at the approximate locations shown in the attached SITE PLAN. At the request of the ACHCSA, boring SB-2A was drilled adjacent to former boring SB-2 in the area of the former 6,000-gallon diesel UST. The ACHCSA had requested that boring SB-1G be drilled at a location immediately down-gradient of the former 45-gallon gasoline UST. No "clear" drill site could be established immediately down-gradient of the former gasoline tank location due to a complex of underground storm drains and appurtenant electrical lines. Consequently, boring SB-1G was drilled at the same location where the former UST is believed to have been in service.

Soil and Groundwater Assessment Methodology:

(1) Soil Boring and Sampling Procedures

The soil borings were drilled with the Geoprobe System, small diameter (about 2-inch) drill casing, direct-push technology. Soil samples were collected as core into polyethylene terephthalate glycol (PETG) liners enclosed within the drill casing. Samples were collected in 2- and 4-foot depth intervals by hydraulically driving the casing and enclosed PETG liner at selected depths. Boring SB-2A was drilled to a total depth of about 11 feet; soil core was discretely collected at the depth intervals of 4 to 6 feet and 9 to 11 feet (2-foot depth intervals). Boring SB-1G was drilled to a total depth of about 28 feet; soil core was collected continuously (in 4-foot depth intervals) to the boring's total depth. After driving each 2- or 4-foot interval, the drill casing and enclosed liner were retrieved and the soil core was examined for apparent contamination (inspected visually for discoloration and sniffed for odor) and construction of lithologic logs. Logs were prepared for each boring (attached), according to the Unified Soil Classification System, by a California Registered Geologist.

In boring SB-2A, at the request of the ACHCSA, soil samples were collected for chemical analyses at the depths of 5 and 10 feet. In boring SB-1G, a soil sample was collected for chemical analysis at the depth of 23.5 feet.

To minimize the potential for cross-contamination, a clean shoe was attached to the drill casing between sampling events and prior to beginning each boring.

(2) "Grab" Groundwater Sampling Procedures

Groundwater was encountered in the boring of SB-1G at the depth of about 25 feet. A "grab" groundwater sample was collected by inserting 1-inch PVC screen and casing into the boring and allowing groundwater to enter the screened interval. A sample was collected into a stainless steel bailer and decanted into laboratory-provided and preserved 40 milliliter bottles having Teflon-lined caps

(3) Sealing of Borings and Handling of Wastes

After all soil and groundwater samples were collected, each boring was sealed to grade with neat Portland Cement Type I/II.

Drill cuttings (waste) are stored on site in a labeled, 5-gallon pail. The label shows contents, date stored, suspected contaminant, expected date of removal, company name, contact person, and telephone number.

(4) Sample Handling Methods

Soil samples collected for chemical analyses were preserved in their PETG liners. The ends of the liners were covered with Teflon sheeting followed by plastic end-caps.

The "grab" groundwater sample was stored in laboratory-provided, 40-milliliter, HCL-preserved VOAs having Teflon-lined plastic caps.

Both soil and groundwater samples were labeled to show site name, project number, date, time, sample name, depth collected, and sampler name; and stored in an iced-cooler.

(5) Chemical Analyses

The soil samples collected from boring SB-2A were analyzed for TPHD and PNAs.

The soil and "grab" groundwater sample collected from boring SB-1G were analyzed for TPHG, BTEX, and MTBE.

All samples were delivered under chain-of-custody to California Department of Health Services certified McCampbell Analytical Inc. laboratory, located in Pacheco California, for chemical analysis. Analysis for TPHD and PNA were by EPA Methods GCFID 5030/8015 and 8270, respectively. Analysis for TPHG, BTEX, and MTBE were by EPA Methods GCFID 5030/8015, 8020, and 8020, respectively.

Soil Boring Profiles:

In boring SB-2A, a dry, grey to red-brown, sandy gravel was encountered beneath the asphalt and base-rock surface to a depth of about 5.5 feet; no odor was detected. From about 5.5 feet to the total depth explored. 11 feet, a dry, dark green to black clay with a slight hydrocarbon odor was present; at the depth of about 9 feet, hydrocarbon odor became stronger.

In boring SB-1G, a dry brown sand was encountered from grade to a depth of 6 feet. From 6 to 7 feet, a dry brown sandy gravel with broken rock (appeared to be fill material) was present. From 7 to 11 feet, a damp brown sand was present; the sand was wet at 11 feet (not enough water to collect a sample). From 11 feet to 20 feet, a damp clay was present; the clay was dark brown to 16 feet and red-brown from 16 to 20 feet. From 20 feet to 28 feet, a brown sand was present that became

saturated at 25 feet. No odors or apparent contamination was detected in the boring.

See attached EXPLORATORY BORING LOGS.

Results of Soil and Groundwater Chemical Analyses:

(1) Soil Boring SB-2A

In boring SB-2A, TPHD was detected at the depths of 5 and 10 feet at concentrations of 3.1 ppm and 1,600 ppm. The laboratory noted that, in the sample collected at the depth of 5 feet, diesel range compounds are significant with no recognizable pattern, and oil range compounds are significant. The laboratory also noted that, in the sample collected at the depth of 10 feet, aged diesel? is significant. No PNAs were detected.

(2) Soil Boring SB-1G

In Boring SB-1G, the soil and "grab" groundwater samples were nondetectable for all analytes.

See the attached certified analytical reports for detailed results of chemical analyses.

CONCLUSIONS AND RECOMMENDATIONS

Diesel UST:

Groundwater contamination by TPHD was found only in cross-gradient well MW-4 at a concentration of 130 ppb. No TPHG, BTEX, or MTBE was detected in any of the wells. The absence of contamination in down-gradient well MW-3, cross-gradient well MW-2, and up-gradient well MW-1 suggests that the diesel plume is small in aerial extent and stable. It is believed that this shallow water is not currently used or will be used as a source of drinking water.

In boring SB-2A, TPHD was detected at the depths of 5 and 10 feet at concentrations of 3.1 ppm and 1,600 ppm, respectively. The laboratory noted that aged diesel? is significant in the chromatogram at the TPHD at 10 feet. No PNAs were detected in either of the samples. It is ALLCAL's opinion that the TPHD remaining in the soil presents no risk to human health.

Based on the California Regional Water Quality Control Board-San Francisco Bay Region's (RWQCB) January 5, 1996, letter, the diesel UST site appears to be a low risk soils and groundwater case and can be officially closed. It is recommended the drummed purge water be hauled off site and disposed of by recycling. It is also recommended that the wells be destroyed since they are potential pathways for re-contaminating the groundwater.

Gasoline UST

Based on nondetectable analytical results for all analytes for soil and groundwater samples, the site appears to present no risk to human health. It is recommended the site be officially closed and the

containerized soil cuttings be disposed of on site in a gardening area.

LIMITATIONS

This report is based on subsurface exploration and laboratory analyses of soil and groundwater samples. The chemical analytical results for the samples are considered applicable to that boring or location from which they were collected. The soil groundwater encountered in the borings is believed to be representative of the site; however, it may vary in character between observation points. The conclusions contained herein are based on the field observations, analytical data, and professional judgment which is in accordance with current standards of professional practice. Representations made of soil and groundwater conditions between sample locations are extrapolations based on professional opinions and judgments and accepted industry practice. Therefore, ALLCAL cannot and will not provide guarantees, certifications, or warranties that the subject property is or is not free of all contaminated soil or groundwater, and such assessments are provided only in order that the Client may make an informed decision.

The extent of testing and data collections directly affects the statistical confidence level of all work performed. As a practical matter, to reach or even approach a 100 percent statistical confidence level would be prohibitively expensive. Therefore, if a reassessment of the subject property becomes necessary in the future, ALLCAL will not reassess the area at its own cost. No other warranty is expressed or implied.

The findings and conclusions of this report are valid as of the present time; however, the passing of time could change the conditions of the subsurface due to natural processes or the influence of man. Accordingly, the findings of this report may be invalidated, wholly or partly, by changes beyond ALLCAL's control. Therefore, this report should not be relied upon after an extended period of time without being reviewed by a Civil Engineer or Registered Geologist.

FOF CALIFO

If you have any questions, please call me.

Sincerely,

cc:

John V. Mrakovich, Ph.D. Registered Geologist No. 4665

Juliet Shin, Hazardous Materials Specialist Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

ALAMEDA COUNTY

HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



April 21, 1999

Ms. Karen Langmaid San Lorenzo Unified School District 15510 Usher Street San Lorenzo, CA 94580

ENVIRONMENTAL HEALTH SERVICES **ENVIRONMENTAL PROTECTION (LOP)** 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

STID: 4233

Re:

Workplan for investigations at Arroyo School, located at 15701 Lorenzo Avenue,

San Lorenzo, CA

Dear Ms. Langmaid.

This office has reviewed AllCal Property Services, Inc.'s workplan, dated April 16, 1999, proposing further investigations for the above site. This workplan is acceptable to this office with the following additional requirements:

- It appears that the on-site monitoring wells were initially surveyed to an arbitrary on-site datum instead of to Mean Sea Level. These wells must be surveyed to Mean Sea Level to an accuracy of 0.01 foot, prior to determining groundwater gradient directions.
- Per the Regional Water Quality Control Board's (RWQCB) guidelines, a second groundwater sample must be collected from proposed boring SB-1G and placed on hold. If the first groundwater sample collected from this boring identifies MTBE using Method 8020, RWQCB recommends that the second sample be analyzed for MTBE using Method 8260 to verify the initial concentrations.

The workplan shall be implemented within 45 days of the date of this letter (i.e., by June 02, 1999), and a report documenting the work shall be submitted within 45 days after completing field activities. Any requests for extensions, or modifications of the required tasks, shall be submitted to this office in writing.

If you have any questions or comments, please contact me at (510) 567-6763.


Sincerely,

Juliet Shin

Hazardous Materials Specialist

Cc: John Mrakovich

> AllCal Property Services, Inc. 27973 High Country Drive Hayward, CA 94542-2530




Greenwood & Moore, Inc.

19131 REDWOOD ROAD, CASTRO VALLEY, CA 94546 OFFICE: 510-581-2772 FAX: 510-581-6913

FB. 95

PROJECT: Monito Survey at 1 SanLorenzo	oring Well Prroyo H.S. for Unified Sch. Dist	JOB NO. 99051
BY: G.Glenn	DATE: 05/26/99	SHEET
	REVISED:	1 OF 1



101 1	NE I	
_	3	

CALIFORNIA COORDINATE SYSTEM

S	HEE	T
1	OF	1

į	HORIZONTAL	CONTROL DATA	LATITUDE		.,	Y(HORTH)	
					433,6XX		
	TYPE -		LONGITUDE	LONGITUDE		X(EAST)	
_	ORDER -	<u> </u>	<u> </u>		1,526	,7XX	
	SCA	STATION (NAME,		BET)		(YEAR RECOVERED)	
	,		BM"C", AL			<u> </u>	1977
П			INDEX SHEET		E SHE	ET)	
			SAN LEANI				23B
11			ALAMEDA	COSTA	- #	OTHER COUNTY	
	AGENCY	COP	COUNTY X	COSTA COUNTY			
ĺ.							
		CONTROL DATA	TO STATION	OR MARK		UTH CLOCKWISE FRID SOUTH	GRID
	ELEVATION IN FEET	DATUM	GRID N	ORTH_	180	000'00"000	DISTANCE
	1 <u>63 1</u> 700.	MEAN SEA LEVEL	TRUE N	прти		-	134
il	-21.792-		· · · · · · · · · · · · · · · · ·	OK I K			FEET
	21.807	1			ı	:	
	ORDER-		 				
	SEC <u>O</u>	ND	11				·
11	3						
	. 197 <i>4</i>	NGS Adj.		1			
11	,						
			11				
Н							
1 1	AGENCY Ala. Co.	copIreland]] .	1			}
'	` .						L—
٦ (DESCRIPTION, PLAT,	REMARKS, ETC.=	•				•
	•						
	BM"C"						-

A "T" cut in southeasterly curb return at Grant and Via Alamitos. "T" is left $16'^{\pm}$ centerline Sta. $0+57^{\pm}$ Via Alamitos.

SM -1 2-6-53

Former Elev.

21.792

PROJECT NO.: 137 DATE: 6/2/99	WELL NO.: <u>MW-1</u>
PROJECT NAME: SLUSY	WELL DIAMETER: 2
PROJECT LOCATION: ARROYO SCHOOL	TOC ELEV: 22.07
SAMPLER: ALLCAL	LOCK NO.:
ANALYSES: TAKS / BTEX / MTBE / TOHD	
WELL DEPTH (from construction detail): 24.5	
WELL DEPTH (measured): 24.30 SOFT BOTTOM?:	
DEPTH TO WATER: 10.44 TIME: 9.29	
PRESSURE (circle one)?: YES OR NO	
IF YES, WAS PRESSURE (circle one): POSITIVE OR NEGATIVE?	
WATER VOLUME IN WELL: 2.2 GAL	
[2-INCH CASING = 0.16GAL/FT] [4-INCH CASING = 0.65GAL/FT]	
[6-INCH CASING = 1.47 GAL/FT] [1 GAL = 3.78 L]	
	LOCATION MAP
CALCULATED PURGE VOL. (GAL): 6.65 (L): 25 ACTUAL PURGE	VOL. (GAL): (L): 25
_	IOD: BAILER
On the state of th	

FIELD MEASUREMENTS

Time	Depth to Water (FT)	Vol (L)	Temp (Deg. F)	pН	EC X/03	Clarity	Turbidity (NTU)	Remarks
9:52		1	62.5	9.39	9.59	,		CLEAR
10:00		10	61.9		4.84			
10:07		15		8.36				
10:10		20	63.7	7.95	6.94			
10:14		22	64.1	7.99	7.36			
10:0			63.2	8.04	628	1		V
	SNO	10	25	ļ	ļ			
	1							

SIGNATURE:_	9.	Mechanis
		

WATER	VOL.	IN DRUM		
NEE	D NEV	/ DRUM?	·	

PROJECT NO.: 137 DATE: 6/2/99	well no.: <u>MW-Z</u>
PROJECT NAME: SLUSD	WELL DIAMETER: 2
PROJECT LOCATION: ARROYO SCHOOL	TOC ELEV: 21.95
SAMPLER: ALICAL	LOCK NO.:
ANALYSES: TONG /BTEY/MTBE /TOH)	
WELL DEPTH (from construction detail): 24,50	
WELL DEPTH (measured): 24.45 soft bottom?:	
DEPTH TO WATER: 10.47 TIME: 9.3/	
PRESSURE (circle one)?: YES OR NO	
IF YES, WAS PRESSURE (circle one): POSITIVE OR NEGATIVE?	
WATER VOLUME IN WELL: 2.24 GAL [2-INCH CASING = 0.16 GAL/FT] [4-INCH CASING = 0.65 GAL/FT] [6-INCH CASING = 1.47 GAL/FT] [1 GAL = 3.78 L]	
	LOCATION MAP
calculated purge vol. (gal): 6.71 (l): 25.37 actual purg	E VOL. (GAL): (L): 25

PURGE METHOD: POLYETHYLENE BAILER SAMPLE METHOD: BAILER

FIELD MEASUREMENTS

Time	Depth to Water (FT)	Vol (L)	Temp (Deg. F)	pН	EC ×/00	Clarity	Turbidity (NTU)	Remarks
10:40	-	/	66.0	8,93	5.53			CLEAR
10:47		10	65.3	8.99	6.38)		(
10:52	 		64.7					
10:56			64.9					
11:00		22	64.6	8.08	6.68	Í		V
11:04		25	Cde.6	7.96	6.72			SUGATLY CLOURY
	Spl	a)	11:15	<u> </u>		<u> </u>		/
	<u> </u>			<u> </u>	<u> </u>			

SIGNATURE:	\mathcal{L}	Mrs	for	P

WATER	VOL. I	N DRUM:	
NEEL) NEW	DRUM?:	<u> </u>

RECORD OF WATER SAMPLING

PROJECT	No.: /37	DATE:_	6/2/9	9				WELL NO.: MW-3
	NAME: 52		• •					WELL DIAMETER: 2"
PROJECT	LOCATION: _	PRRO	VO 5C	HOOL				TOC ELEV: 21.91
	R: ALLCA	•	, 					LOCK NO.:
ANALYS	ES: TPHS/	STEX	/MTBE	JTPI	43		ſ	
	EPTH (from cons			·				
	EPTH (measured)							
DEPTH	TO WATER:/	2.70	TIM	IE: <u>9</u>	35	-		
PRESSU	RE (circle one)?:	YES	OR (NO)					
IF YES,	WAS PRESSURE	(circle	one): POS	SITIVE C	R NEGA	TIVE?		
WATER	VOLUME IN W	ÆLL:	2.2	GAL				
•	CASING $= 0.16$		-			9.65 GAL/J	FT]	
[6-INCH	CASING = 1.47	GAL/F	r) [1 G	SAL = 3.	78L]			
								LOCATION MAP
CALCU	LATED PURGE	VOL. (GAL): 6.	59 (L)	: 24.8	9 ACTU	JAL PURGE	VOL. (GAL): (L): 25
								HOD: BAILER
	,	7	,			ASUREN		
							,	
Time	Depth to Water (FT)	Vol (L)	Temp (Deg. F)	рΉ	EC X/00	Clarity	Turbidity (NTU)	Remarks
1/:20			64.9	7.93				CLEAR
11:35	Į i	10	650	1	1			PLACK SUSPENDED MATERIAL
11:4		,	65.0	1	1	-		/
; <u> </u>		70	1	1	7.98	į.		
11:4	1	1	640	T	1	1		
11:4		1	64.8	1	Ł	J		
11.50		123	65.2	7.57	8.22		<u> </u>	V
	Sple	12	:00	-	-	-		
			<u> </u>	 	 			
		<u> </u>		<u></u>	<u> </u>			
		~^	1 /	1 1	9			R VOL. IN DRUM:
SIGN	ATURE:	. 11	Suppo	end		-	NE	EED NEW DRUM?:

PROJECT NO.: 137 DATE: 6/2/99	WELL NO.: MW-4
PROJECT NAME: SLUSS	WELL DIAMETER: 2 *
PROJECT LOCATION: ARROYO SCHOOL	TOC ELEV: 22.28
SAMPLER: ALLCAL	LOCK NO.:
ANALYSES: TONG/BTEK/MTBE/TPH)	
WELL DEPTH (from construction detail): 23.5	
WELL DEPTH (measured): 23.78 SOFT BOTTOM?:	
DEPTH TO WATER: 10.86 TIME: 9.40	
PRESSURE (circle one)?: YES OR NO	
IF YES, WAS PRESSURE (circle one): POSITIVE OR NEGATIVE?	
WATER VOLUME IN WELL: 2.07 GAL	
[2-INCH CASING = 0.16GAL/FT] [4-INCH CASING = 0.65GAL/FT]	
[6-INCH CASING = 1.47 GAL/FT] [1 GAL = 3.78 L]	
	LOCATION MAP
= and any attention to the control of the control o	· · · · · · · · · · · · · · · · · · ·


PURGE METHOD: POLYETHYLENE DAILER SAMPLE METHOD: BAILER

FIELD MEASUREMENTS

Time	Depth to Water (FT)	Vol (L)	Temp (Deg. F)	pН	EC X/000	Clarity	Turbidity (NTU)	Remarks
12:12		/	62.9	10.15	3.12			CLEAL
12:20			63.8	11.10	3/2			CLEAR CLOUDY WITH PLACK SUSPICIONED MATERIAL
12:25			63.8	ļ.				
12:28		1	63.6	11.18	2.19			
12:31			64.0	10.76	162			
12:3/		25	63.7	1058	1.84			V
	Spl @	12	45					POSSINE HYROCHRBON
								DOSINE HYROCHRBON

SIGNATURE:_	2	Machonel
	$\overline{\mathcal{O}}$	

WATER	VOL.	IN DRUM	ſ:	
NEE	D NEV	V DRUM?	?:	



PHCNE NO. : 5103815490

TO 95818490



ALAMEDA COUNTY PUBLIC WORKS AGENCY

WATER RESOURCES SECTION

951 TURNER COURT, SUITE 300. HAYWARD. CA 94545-2651 PHONE (\$10) 670-5575 ANDREAS GODFREY FAX (\$10) 670-5262 (\$10) 670-\$246 ALVIN KAN

WWW V 441 A 141 A							
DRILLING PERMIT APPLICAT	ION	CATIC	ICA	APPL	PERMIT	ILLING	DRI

FOR APPLICANT TO COMPLETE	FOR OFFICE USE
LOCATION OF PROJECT /510/ LORENZO AVE.	PERMIT NUMBER 99WR260
SAN LORENZO, CA	
344,000,04	WELL NUMBER
California Coordinates Source & Assumed &	
California Coordinates Source ft. Accaracy ± ft. CCN ft. CCE ft.	Permit Conditions
APN	Circled Permit Requirements Apply
CLIENT	A. GENERAL
Name SAN LORENTO UNIFIED SCHOOL DIST. Address (SSIO USHER ST Phone STO 3)7 4874	1. A permit application should be submitted so as to
Address 15510 USHER 57 Phone 570 317 4874 City 5AN LOREN 20 2ip 94580	Arrive at the ACPWA office five days prior to
	proposed starting date. 2. Submit to ACPWA within 60 days after completion of
APPLICANT	permitted work the original Department of Water
Name JOHN MERICOVICH	Resources Water Well, Drillers Report or equivalent for
ALLCAL PROPERTY SVS Tux 5705818490	well projects, or drilling logs and location sketch for
Address 27973 HIGH COUNTRY DO Phone 510 SEL 7 820	acotechnical projects.
CIO HAYWARD Zip 94547	3. Permit is vaid if project not begun within 90 days of
Marie States of Maries States States and States and States	approval date.
TYPE OF PROJECT	B. Water supply wells
Well, Construction Geotechnicz, Investigation Cathodic Protection Geograph	1. Minimum surface seat thickness is two inches of
J Chicago	coment grout placed by tremis
Water Supply Contamination	2. Minimum seal depth is 50 feet for municipal and
Monitoring O Well Destruction I	industrial wells or 20 feet for domestic and irrigation
PROPOSED WATER SUPPLY WELL USE	wells unless a lesser depth is specially approved.
and the same of th	C. Groundwater monitoring wells
	including piezometers
Municipal D Infigution D	1. Minimum surface seal thickness is two inches of
Industrial D Other D	cement grout placed by tremic.
DRILLING METHOD:	2. Minimum seed depth for monitoring wells is the
A P. S. W. A. M. C.	maximum depth practicable or 20 feet
	D. GEOTECHNICAL
Cable 13 Other > BIRECT PUSH	Backfill bare hale with compacted cuttings or heavy
DRILLER'S LICENSE NO. CST GZUUGI	beatonite and upper two feet with compacted material.
	In areas of known or suspected contamination, tremité
WELL PROJECTS	cement grout shall be used in place of compacted cuttings. E. CATHODIC
Drill Hole Diameter B. Maximum	Fil) has above anode zone with concrete placed by tremic.
Casing Diameter in. Depth ft.	F. WILL DISTRUCTION
Surface Seal Depth ft. Number	Sec attached.
	G. SPECIAL CONDITIONS
GEGTECHNICAL PROJECTS	
Number of Borings 2 Maximum Hole Diameter 2 in Depth 20 A	
Hole Diameter 2 in. Depth 20 A.	
ESTIMATED STARTING DATE 6/29/99	/ /
ESTIMATED COMPLETION DATE 6/29/49	APPROVED MAN 10 . DATE (-1/299
The state of the s	DATE TO THE
	14 1-
I hereby agree to comply with all requirements of this permit and	// V / / 1
Alamees County Ordinance No. 73-68	// / /
^	// { /
APPLICANTION DOWN A DOWN	* •
SIGNATURE TOWN MAN AND THE PROPERTY OF THE PARTY OF THE P	
THE PART IN PROPERTY OF THE PARTY OF THE PAR	

JUN 29 1999 AP: 29

EXPLORATORY BORING LOG

Project Number: 137

Boring Number:

SB-2A

Project Name:

Arroyo School San Lorenzo, CA

Page Number:

1 of 1

By: ALLCAL PROPERTY SERVICES, INC

Date: 6/29/99

Surface Elevation: NA

Dy. ALL	CAL INC	MENTI SERVI	CLO, INC	Date.	0/29/99	Surface Elevation: NA
RECOVERY (in/in.)	VAPORS (ppm)	PENETRATION (blows/ft.)	GROUND- WATER LEVEL	DEPTH (ft.)	SOIL TYPE	DESCRIPTION
					20.00	0.005 FT.: ASPHALT UNDERLAIN BY BASE ROCK.
24/24				5 <u> </u>	GP	0.5 - 5.5 FT.: SANDY GRAVEL (GP), GREY TO RED-BROWN, MEDIUM TO COARSE-GRAINED, DRY, NO ODOR.
				-	CL	5.5 - 11.0 FT.: CLAY (CL), DARK GREEN TO BLACK, FIRM, SANDY, SILTY, DRY, SLIGHT HYDROCARBON ODOR.
24/24				10 _		@ 9.0 FT.: HYDROCARBON ODOR.
				_		TOTAL DEPTH OF BORING = 11 FEET.
				15		
				20 _		
				25 <u> </u>		
				30 _		

Remarks:

BORING DISCRETELY CORED WITH 20 - INCH O D , DIRECT-PUSH GEOPROBE SYSTEM SAMPLES COLLECTED IN 1.75-BY 36 - INCH PETG LINER BORING SEALED TO GROUND SURFACE WITH CEMENT SLURRY

EXPLORATORY BORING LOG

Project Number: 137

Boring Number: SB-1G

Project Name:

Arroyo School San Lorenzo, CA Page Number: 1 of 1


By: ALLCAL PROPERTY SERVICES, INC

Date: 6/29/99

Surface Elevation: NA

BY: ALLCAL PROPERTY SERVICES, INC			Date: 6/29/99		5/29/9	Surface Elevation: NA	
RECOVERY (in/in.)	VAPORS (ppm)	PENETRATION (blows/ft.)	GROUND- WATER LEVEL	DEPTH (ft.)	SAMPLES	SOIL TYPE	DESCRIPTION
36/48						SP	0.00 - 6.0 FT.: SAND (SP), BROWN, MEDIUM-GRAINED, SOME FINE GRAVEL, DRY, NO ODOR.
36/48				5		GP	6.0 - 7.0 FT.: SANDY GRAVEL (GP), BROWN, MEDIUM TO COARSE-GRAINED, ANGULAR FRAGMENTS (BROKEN ROCK), ROOTS, DRY, NO ODOR.
36/48				10		SP	7.0 - 11.0 FT.: SAND (SP), BROWN, FINE-GRAINED, SILTY, DAMP (WET @ 11 FT.), NO ODOR.
48/48				15		CL	11.0 - 16.0 FT.: CLAY (CL), DARK BROWN, FIRM, ROOTS, DAMP, NO ODOR. @ 14 FT.: BLACK WITH FINE GRAVEL, DAMP, NO ODOR. @ 16 FT.: SAMPLE SHOE WET.
48/48					_ _ _	CL	16.0 - 20.0 FT.: CLAY (CL), RED BROWN, CHANGING TO LIGHT BROWN, FIRM, SANDY, GRAVELLY, DAMP, NO ODOR.
48/48				20	_		@ 20 FT.; SOFT. 20.0 - 28.00 FT.: SAND (SP), BROWN, ALTERNATING LAYERS OF FINE TO MEDIUM-GRAINED AND VERY FINE-GRAINED SAND, CLAYEY, MOIST TO WET NO ODOR.
48/48			_	25		SP	@ 24 FT.: SAND IS MEDIUM-GRAINED.
				30	-		TOTAL DEPTH OF BORING = 28 FEET
,					-		

Remarks: Boring continuously cored with 20 - Inch o D, Direct-Push, Geoprobe system samples collected in 175- By 48 - Inch petg liner Boring sealed to Ground surface with Cement Slurry



ALLCAL Property Services	Client Project ID: #137; Arroyo School	Date Sampled: 06/02/99
27973 High Country Drive		Date Received: 06/02/99
Hayward, CA 94542-2530	Client Contact: John Mrakovich	Date Extracted: 06/02/99
	Client P.O:	Date Analyzed: 06/02/99

06/09/99

Dear John:

Enclosed are:

- 1). the results of 5 samples from your #137; Arroyo School project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Yours truly.

Angel by del fel Edward Hamilton, Lab Director

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com E-mail: main@mccampbell.com

ALLCAL Property Services	Client Project ID: #137; Arroyo School	Date Sampled: 06/02/99
27973 High Country Drive		Date Received: 06/02/99
Hayward, CA 94542-2530	Client Contact: John Mrakovich	Date Extracted: 06/02-06/03/99
	Client P.O:	Date Analyzed: 06/02-06/03/99


Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline*, with Methyl tert-Butyl Ether* & BTEX*

EPA methods 5030, modified 8015, and 8020 or 602; California RWOCB (SF Bay Region) method GCFID(5030)

Lab ID	Client ID	Matrix	TPH(g) ⁺	MTBE	Benzene	Toluene	Ethylben- zene	Xylenes	% Recovery Surrogate
12485	MW-1	W	ND	ND	ND	ND	ИD	ND	107
12486	MW-2	W	ND	ND	ND	ND	ND	ND	107
12487	MW-3	w	ND	ND	ND	ND	ND	ND	104
12488	MW-4	w	ND	ND	ND	ND	ND	ND	103
12489	Trip Blank	w	ND	ND	ND	ND	ND	ND	104
								 	
Reporting	ng Limit unless ise stated; ND	w	50 ug/L	5.0	0.5	0.5	0.5	0.5	
means no	t detected above porting limit	S	1.0 mg/kg	0.05	0.005	0.005	0.005	0.005	1

^{*} water and vapor samples are reported in ug 'L, wipe samp'es in ug wipe, soil and sludge samples in mg 'kg, and all TCLP and SPLP extracts in ug L

The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation a) unmodified or weakly modified gasoline is significant, b) heavier gasoline range compounds are significant(aged gasoline?), c) lighter gasoline range compounds (the most mobile fraction) are significant, d) gasoline range compounds having broad chromatographic peaks are significant, biologically altered gasoline?, e) TPH pattern that does not appear to be derived from gasoline (?), f) one to a few isolated peaks present, g) strongly aged gasoline or diesel range compounds are significant, h) lighter than water immiscible sheep is present, i) liquid sample that contains greater than ~5 vol. % sediment, j) no recognizable pattern



[&]quot; cluttered chromatogram, sample peak coelutes with surrogate peak

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com E-mail: main@mccampbell.com

ALLCAL Pro	perty Services	Client Pro	eject ID: #137; Arroyo School	Date Sampled: 06	5/02/99		
27973 High C	-		•	Date Received: 0	6/02/99		
Hayward, CA	94542-2530	Client Co	ntact: John Mrakovich	Date Extracted: 0	6/02/99		
		Client P.C):	Date Analyzed: 0	6/03/99		
EPA methods ma			C23) Extractable Hydrocarbon mia RWQCB (SF Bay Region) method				
Lab ID	Client ID	Matrix	TPH(d) ⁺		% Recovery Surrogate		
12485	MW-1	w	ND		103		
12486	MW-2	w	ND		104		
12487	MW-3	w	ND		103		
12488	MW-4	w	130,b		101		
				-			
Reporting Lin	mit unless otherwise ans not detected above	w	50 ug/L				
the re	eporting limit	s	1.0 mg/kg				

^{*} water and vapor samples are reported in ug L, wipe samples in ug/wipe, soil and sludge samples in mg kg, and all TCLP / STLC / SPLP extracts in ug L

^{*} cluttered chromatogram resulting in coeluted surrogate and sample peaks, or, surrogate peak is on elevated baseline, or, surrogate has been diminished by dilution of original extract

^{*}The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation a) unmodified or weakly modified diesel is significant, b) diesel range compounds are significant, no recognizable pattern, c) aged diesel? is significant), d) gasoline range compounds are significant, e) medium boiling point pattern that does not match diesel (?), f) one to a few isolated peaks present, g) oi range compounds are significant, h) lighter than water immiscible sheen is present, i) liquid sample that contains greater than ~5 vol % sediment

Date: 06/03/99

Matrix: WATER

	Concent	ration	(ug/L)		% Reco	very	
Analyte	Sample			Amount			RPD
	(#12230)	MS	MSD	Spiked	MS	MSD	
TPH (gas)	0.0	101.9	104.7	100.0	101.9	104.7	2.7
Benzene	0.0	9.4	9.3	10.0	94.0	93.0	1.1
Toluene	0.0	9.6	9.5	10.0	96.0	95.0	1.0
Ethyl Benzene	0.0	9.9	9.8	10.0	99.0	98.0	1.0
Xylenes	0.0	29.8	29.4	30.0	99.3	98.0	1.4
TPH(diesel)	0.0	7527	7383	7500	100	98	1.9
TRPH (oil & grease)	0	29100	28600	23700	123	121	1.7

RPD = (MS - MSD) / (MS + MSD) \times 2 \times 100

[%] Rec. = (MS - Sample) / amount spiked x 100

	Telepho	McCAN ne. (510) 798	110 2 nd A' PACH		UTH,	#D7			79	8-16	<u>·</u> 22					TU	RN	A	CF ROI		IN	OF		JST D	ГО		Ĺ]	COF	CD DH 8	OUR	
}-	Report To: JOH			/ B	ill To									1					Ana	lysis	s Re	ques	t						Oth	er	工	Comments
	Company: ALLC					· · · · ·									T	Œ				\top	T	T										
		73 HIGH C													}	Grease (5520 E&F/B&F)						Ì							Ī		ı	
_	HAVE	UHRY, C	1 94	1542										801SY MTBE	1	%F.				-			310		[1	-		
-	Tele. (510) 58/2	2-320		F	ax: (5									_ §	i	8	18.1				ı	1	Įõ						-		-	
	Project #: /37			P	roject	Nam	ie: /	921	Roy	0	SZX	100	<u> </u>	_] 🖁	1	18	2	ĺ	ခါ	Ì.			827		1	_						
Ī	Project Location:	SAN LON	RENZO	CA										្នាដូ	ł	l sa	륋		80			-	135		\	010			1	1	1	
	Sampler Signature													(602/8020		5	g		705		0	,	\ \ \ \			776		ļļ			ļ	
_	(Y	LING]	S		MA	TRI	X	N pp	ETH	IOD RVED	′၂ နို့	15));;	2		A 6			7]	733	İ					
					ري ا	iner	 	1			 ``	1361	YEL		8	I E	Ē	30	回	စ္က	08	} e	2 2	121	iş.	421	1			1		
	SAMPLE ID	LOCATION	!		# Containers	Type Comtainers						-		Ħ	TPH as Diesel (8015)	Total Petroleum Oil &	Total Petroleum Hydrocarbons (418.1)	EPA 601 / 8010	BTEX ONLY (EPA 602 / 8020)	EPA 608 / 8080	EPA 608 / 8080 PCB's ONLY EPA 634 / 8340 / 8340	01.02 1.50 V.T.	PAH's / PNA's by EPA 625 / 8270 / 8310	CAM-17 Metals	LUFT 5 Metals	Lead (7240/7421/239,2/6010)						
	SAMELEID	LOCATION	Date	Time	错	S	片		8	2 K			ا ات	, S	38 E	湿	Pe	8	20	88 8	§ §	5 č	} \[\sigma	1-17	T.5	(72)			į,			
			[ပ္ပ	Ě	Water	Soil		員	Jce	딦		BTEX&	표	o Ez	a	PA.	1	<u> </u>	¥ i	4	: ₹	18	岂	Cead	RCI		į			40401
_						·	J 1	S.	4 0	,	╂╼╼╾┼	141	1		Ψ,	 -	$ \Box $		-		_ -	4-	+-	 	╀	ļ	_		¦′			1.248
	MW-1	MW-L	42/99	10:25	3	2-40 1-470	X				M		_	<u> X</u>	$ \times$	`				_	_ _	_ _	- -	-	 				-	1		1248
	MW-2	MCV-Z		11:15	1	1	$\ \ $			-										_ _		_ _	_ _		<u> </u>				_))		1440
		MW-3	 	12:00		П					T			77	17															1		1248
_	MW-3			12:45	17	1	17	\dashv	1		17		_ _	- 4	TV							[_		[, 0
_	MW-4	MW-4	- <u>"</u> -	16.43	 	<u> </u>	╬┪		-+-		╂┤		1	1.5	1-3	·					{-	-1-	- -		-				_	,		124
-	Rip Blanck	·			ļ		-	-		+					=		(<u> </u>			-			-		 -					_ <u>`</u>		
_	·]]	_	_	_}_			Ц-		-					-			-	-					-			124
					<u> </u>									_]								-		-	<u> </u>]		}-	i		, ,
					ļ"—					ĺ		l	-								. [.	_ _	1_		<u> </u>					_	_ _	
			· · · · · · · · · · · · · · · · · · ·		1									1						ı	Í	1	1							_l_	[_	
-	·····		ļ		 			_	1					-							-			1	VO	S	73.G	ME	ALS (THE	1	
_			l		 -		\vdash						+	-1-	CE	₩.	-5				_	PRE	SURV	MO	1						_ _	
_					}	<u> </u>				-}	\vdash		+	-	600	DC	DNO	TIO					HOPF		<u> </u>			={		7	- -	
					<u></u>					_}				_}	H	DSI	X	AB	ENT			GDN	HAIN	915_		_		-+			-}-	
									_ _						4_				_	\prod		_ _	1_	-			{			- -	-}-	
-								71	İ	1		ı	İ							_		_	_	<u> </u>			{	_	L	_ _	_ _	
-								11	7		\Box		1	1										1								
ī	Rehnquished By/	/)	Date	Time:	Rece	vedis	yk /	1	片		1			R	ema	irks:	لىسىن <i>جرا</i> ر	<u>ا</u>	171	 3,/==	٦.	-7,		16 V) [0	///	= //	2/4	1 1	21	T4.
	Median		6/2/99	2:22		///\	X		(N)	W	^)/T		•
	Kelingurshed B		Dates	Time	Roce	(Ved)	/∆- y:	$\langle v \rangle$			_			1														-		,,,	•	
^	Inla		1328 N	ZZS/	1	$\gamma / $	- 4	, : ·	1	u				l		- /-	+16,	H	<i>±</i> 5√		01	16.6	=14	12	"	101	4					

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com E-mail: main@mccampbell.com

ALLCAL Property Services	Client Project ID: #137; Arroyo School	Date Sampled: 06/29/99
27973 High Country Drive		Date Received: 06/29/99
Hayward, CA 94542-2530	Client Contact: John Mrakovich	Date Extracted: 06/29/99
	Client P.O:	Date Analyzed: 06/29/99

07/06/99

Dear John:

Enclosed are:

- 1). the results of 4 samples from your #137; Arroyo School project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Yours truly, Augle Pychli for

Edward Hamilton, Lab Director

ALLCAL Property Services	Client Project ID: #137; Arroyo School	Date Sampled: 06/29/99
27973 High Country Drive	_	Date Received: 06/29/99
Hayward, CA 94542-2530	Client Contact: John Mrakovich	Date Extracted: 06/29/99
	Client P.O:	Date Analyzed: 07/01-07/02/99

Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline*, with Methyl tert-Butyl Ether* & BTEX*

EPA meth	ods 5030, modified	1 8015, and 8	020 or 602; Cal	ifomia RW(QCB (SF Bay 1	Region) met		30)	
Lab ID	Client ID	Matrix	TPH(g) ⁺	MTBE	Benzene	Toluene	Ethylben- zene	Xylenes	% Recovery Surrogate
14663	SB1G-23.5- 24.0	S	ND	ND	ND	ND	ND	ND	111
14664	SB1G-W	w	ND,i	ND	ND	ND	ND	ND	104
_ ·									
									
	<u> </u>						 		
	<u> </u>								
									
Reporti	ng Limit unless ise stated; ND	w	50 ug/L	5.0	0.5	0.5	0.5	0.5	
means no	t detected above porting limit	S	1.0 mg/kg	0.05	0.005	0.005	0.005	0.005	

^{*} water and vapor samples are reported in ug L, wipe samples in ug wipe soil and sludge samples in mg kg, and all TCLP and SPLP extracts in ug L

^{*} cluttered chromatogram, sample peak coelutes with surrogate peak

The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation a) unmodified or weakly modified gasoline is significant, b) heavier gasoline range compounds are significant (aged gasoline²), c) lighter gasoline range compounds (the most mobile fraction) are significant, d) gasoline range compounds having broad chromatographic peaks are significant biologically altered gasoline², e) TPH pattern that does not appear to be derived from gasoline (2), f) one to a few isolated peaks present, g) strongly aged gasoline or diesel range compounds are significant, h) lighter than water immiscible sheen is present, j) liquid sample that contains greater than ~5 vol. % sediment, j) no recognizable pattern

ALLCAL Property Services	Client Project ID: #137; Arroyo School	Date Sampled: 06/29/99
27973 High Country Drive		Date Received: 06/29/99
Hayward, CA 94542-2530	Client Contact: John Mrakovich	Date Extracted: 06/29/99
	Client P.O:	Date Analyzed: 06/29-07/05/99

Diesel Range (C10-C23) Extractable Hydrocarbons as Diesel *

EPA methods modified 8015, and 3550 or 3510; California RWQCB (SF Bay Region) method GCFID(3550) or GCFID(3510)

Lab ID	Client ID	Matrix	TPH(d) ⁺	% Recovery Surrogate
14661	SB2A-5.0-5.5	S	3.1,g,b	107
14662	SB2A-10.0-10.5	S	1600,c	103
·				
Reporting I	Limit unless otherwise eans not detected above	W	50 ug/L	
the:	reporting limit	S	1.0 mg/kg	

^{*} water and vapor samples are reported in ug'L wipe samples in ug wipe, soil and sludge samples in mg kg, and all TCLP / STLC / SPLP extracts in ug L

^{*} cluttered chromatogram resulting in coeluted surrogate and sample peaks, or, surrogate peak is on elevated baseline, or surrogate has been diminished by dilution of original extract

^{*}The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation a) unmodified or weakly modified diesel is significant, b) diesel range compounds are significant, no recognizable pattern, c) aged diesel? is significant, d) gasoline range compounds are significant e) medium boiling point pattern that does not match diese! (?), f) one to a few isolated peaks present, g) oil range compounds are significant, h) lighter than water immiscible sheen is present, i) liquid sample that contains greater than ~5 vol. % sediment

ALLCAL Property Services	Client Project ID: #137; Arroy	o School	Date Sampled: 06	/29/99				
27973 High Country Drive			Date Received: 06	Date Received: 06/29/99				
Hayward, CA 94542-2530	Client Contact: John Mrakovid	;h	Date Extracted: 06	5/29/99				
	Client P.O:		Date Analyzed: 07	7/06/99	····			
Polynuc EPA methods 625 (modified 610) and 3	clear Aromatic Hydrocarbons (1 3510 or 8270 (modified 8100) and 3550	PAH / PNA) by GC-MS					
Lab ID	14661		14662	Report	ing Limit			
Client ID	SB2A-5.0-5.5	SB	2A-10.0-10.5	 	W,STLC			
Matrix	S		S	s	TCLP			
Compound	Concent	ration*		mg/kg	ug/L			
Acenaphthene	ND		ND<5	0.33	10			
Acenaphthylne	ND		ND<5	0.33	10			
Anthracene	ND		ND<5	0.33	10			
Benzo(a)anthracene	ND		ND<5	0.33	10			
Benzo(b)fluoranthene	ND		ND<5	0.33	10			
Benzo(k)fluoranthene	ND		ND<5	0.33	10			
Benzo(g,h,i)perylene	ND		ND<5	0.33	10			
Benzo(a)pyrene	ND		ND<5	0.33	10			
Chrysene	ND		ND<5	0.33	10			
Dibenzo(a,h)anthracene	ND		ND<5	0.33	10			
Fluoranthene	ND		ND<5	0.33	10			
Fluorene	ND		ND<5	0.33	10			
Indeno(1,2,3-cd)pyrene	ND		ND<5	0.33	10			
Naphthalene	ND		ND<5	0.33	10			
Phenanthrene	ND		ND<5	0.33	10			
Pyrene	ND		ND<5	0.33	10			
% Recovery Surrogate 1	87		93		 			
% Recovery Surrogate 2	112		115	1				
Comments			J	1,700				

^{*} water and vapor samples are reported in ug L, soil and sludge samples in mg kg, wipes in ug wipe and all TCLP / STLC / SPLP extracts in ug 'L

ND means not detected above the reporting limit, N'A means analyte not applicable to this analysis.

^{*} surrogate diluted out of range or surrogate coelutes with another peak

⁽h) a lighter than water imm scible sheen is present, (i) liquid sample that contains >~5 vol. % sediment. (j) sample diluted due to high organic content

Date: 07/01/99

Matrix:

WATER

	Concent	ration	(ug/L)		% Reco	very	
Analyte	Sample			Amount			RPD
	(#14478) 	MS	MSD	Spiked	MS	MSD	
TPH (gas)	0.0	106.3	109.4	100.0	106.3	109.4	2.8
Benzene	0.0	9.5	10.4	10.0	95.0	104.0	9.0
Toluene	0.0		10.5	10.0	96.0	105.0	9.0
Ethyl Benzene	0.0	9.8	10.6	10.0	98.0	106.0	7.8
Xylenes	0.0	29.4	32.0	30.0	98.0	106.7	8.5
TPH(diesel)	0.0	7729	7375	7500	103	98	4.7
TRPH (oil & grease)	N/A	N/A	N/A	A\n	n/a	N/A	n/A

% Rec. = (MS - Sample) / amount spiked \times 100

RPD = $(MS - MSD) / (MS + MSD) \times 2 \times 100$

Date: 06/27/99-06/28/99 Matrix: SOIL

	Concent	ration	(mg/kg)		% Reco	very	
Analyte	Sample			Amount			RPD
	(#09036)	MS	MSD	Spiked	MS	MSD	ļ
				 			!
TPH (gas)	0.000	2.181	2.203	2.03	107	109	1.0
Benzene	0.000	0.196	0.200	0.2	98	100	2.0
Toluene	0.000	0.202	0.206	0.2	101	103	2.0
Ethylbenzene	0.000	0.206	0.208	0.2	103	104	1.0
Xylenes	0.000	0.584	0.604	0.6	97	101	3.4
TPH(diesel)	0	288	290	300	96	97	0.7
TRPH (oil and grease)	0.0	25.7	25.4	20.8	124	122	1.2

% Rec. = (MS - Sample) / amount spiked x 100

 $RPD = (MS - MSD) / (MS + MSD) \times 2 \times 100$

Date: 07/01/99

Matrix: SOIL

	Concent	ration	(mg/kg)		% Reco	very	
Analyte	Sample			Amount			RPD
Į	(#00685)	MS	MSD	Spiked	MS	MSD	
						·	
TPH (gas)	0.000	2.128	2.174	2.03	105	107	2.1
Benzene	0.000	0.198	0.200	0.2	99	100	1.0
Toluene	0.000	0.204	0.206	0.2	102	103	1.0
Ethylbenzene	0.000	0.206	0.208	0.2	103	104	1.0
Xylenes	0.000	0.600	0.612	0.6	100	102	2.0
TPH(diesel)	0	302	305	300	101	102	0.8
TRPH (oil and grease)	0.0	23.4	23.8	20.8	113	114	1.7

\$ Rec. = (MS - Sample) / amount spiked x 100

RPD \approx (MS - MSD) / (MS + MSD) x 2 x 100

QC REPORT FOR SVOCs (EPA 8270/625/525)

Date: 07/06/99

Matrix: SOIL

	Concentr	ation	(ug/Kg,m	<u></u>	% Reco		
Analyte	Sample		Ì	Amount			RPD
!	(#02568)	MS	MSD	Spiked	MS	MSD	
Phenol	0	115	106	100	115	106	16.3
2-Chlorophenol	0	102	101	100	102	101	1.0
1, 4-Dichlorobenzene	0	87	87	100	87	87	0.0
N-nitroso-di-n-propyl	0	59	57	100	59	57	3.4
1, 2, 4-Trichlorobenz	0	83	85	100	83	85	2.4
4-Chloro-3-methylphen	0	109	111	100	109	111	1.8
4-Nitrophenol	٥	84	85	100	84	85	1.2
Acenaphthene	0	61	55	100	61	55	10.3
2, 4- Dinitrotoluene	0	78	77	100	78	7 7	1.3
Pentachlorophenol	0	88	77	100	88	77	13.3
Pyrene	0	85	85	100	85	85	0.0

% Rec. = (MS - Sample) / amount spiked x 100

 $RPD = (MS - MSD) / (MS + MSD) \times 2 \times 100$

157762AC5

	McCAN	4BELL	ANAL	YTI	CAL	IN	Ċ.						T					\mathbf{C}	HA	ΙN	<u>1 O</u>	F	CU	เรา	O'	$\overline{\mathrm{D}}$	Z R	EC	CO	RI)	
		10 2 nd A	VENUE SC	UTH,											TU	JRI	۸V	RO	UN	۱D	TIN	ИE			1			_		ζ		Ø
Telephot	ne (510) 798-		ieco, ca s	14553	F	ax: f	510	1 79	8-16	22														RU	SH	2	24 H	OU	R 4	48 I	JOL	IR 5 DAY
Report To John			13	ill To									- -		_			An	alys	is F	equ	est							Oil	ıer		Comments
Company ACLCA															6	$\overline{}$																
	3 HIGH CO													.	(B&)																	
	IARD, CA		42										_ \f	1	Grease (5520 E&F/B&F)			1		•	<u> </u>		3310									
Tele (570) 581/2	320		F	ax: (5	70) 5	<u> </u>	(ويم	49	0_				_ \{\bar{\}}		20 1	<u>∞</u>							(§									
Project #: /37				roject	Nam	e: /	9/2	<u>euy</u>	<u>0 S</u>	CH	OUC		<u>-ا</u> ۽َ	3	6.53	2 S		50		>		1	8			🧟						
Project Location:	SAN LORI	ENZO	L GA	١							·····		_ §	3	reas	I po		(0208 / 8020)		볽			625			8						
Sampler Signature	John			_	,					T 1	IET!	OD	6	3	্থ	100		602		3.s.	9		PA			9.7%						
:	,	SAM	PLING	ł	ETS.	.	MA	TRI	X 		ESET			(8015)	Total Petroleum Oil	Total Petroleum Hydrocarbons (418.1)		PA		EPA 608 / 8080 PCB's ONLY	EPA 624 / 8240 / 8260		PAH'S (PNA) 8 by EPA 625 (8270) 8310	ا ا		Lead (7240/7421/239.2/6010)						
				eg.	Type Comtainers									3 3	enm	Eng	EPA 601 / 8010	λ.	EPA 608 / 8080	88	3240	EPA 625 / 8270	Š.	CAM-17 Metals	LUFT 5 Meals	742		l				
SAMPLE ID	LOCATION	75.4	m:	Containers	Ę				וע				Į	TPH as Diesel	et l	eff	5	Z	% %	8	24/	757		2	5 M	77						
		Date	Time	ğ	e e	Water			Other		HCI	္ခ်ီ]၂	Cther	3 3	<u> </u>	ᇤ	A 66	EX	A 6(A 6	A 6	A 6	H.S	Ψ	丘	등 ()						
				#	Ļ	B≷	Soil	۲ S	ဦ ဦ	ğ	H	= 8	5 ¤	j F	: ြင	: 2	曲	П	뮵	ㅂ	댐	EP	PA	Ü	ב	ដ	R				,	
SB2A-5,0.5,5	SB-2A	6/24/99	9:10	7	DETS		X			X				>	<								X								t ;	14661
SBZA-10.0-10.5			9:15	1			X			X			_ .	X									X								,	
SD1G-23.5-240			11:05	/	V		X		_ _	X			_[>		Ţ		[_	ļ										_			1	14662
	SD-19_	\\\	11:25	3_	40ML	X	_			X			_ ×	-											٠		****	** ***			1 1	14663
		·	.]		ļ				-			_	- .	- .	- -					-												
				 						_	_}	-	-1			.	.)							~							: 1 : :	14664
												_	_											·			-				i	
			<u> </u>				_											1								- 1						
,		10	F/ID					מממ	ED VAT	יים	VUAS	100	8GIA	1ETAI	S[O	THEA																
			DOD CON	DITTON	V			COO	EAVAT Drri/	UV	34	4		4			,						_									
		Ĥ	AD SPAC	PARS	NT			ירודים ירוורי	ANNER ANNER		1			-		`\																
		· · · · · · · · · · · · · · · · · · ·			111		-	H	HINER	P =		•	7 -	-		1															ł	
							十		+		\neg	十	- -	_	- -	+-	-															
								+	╁		\dashv	\dashv	- -	- -	- -	- -	╁														_	***************************************
<u></u>							\dashv					- -		-	-		·		-		-				_	_		_				
Rehnquished (By) /		Date	Time:	Ream	ved B							上		 }em	arks	<u></u>	ــــــــــــــــــــــــــــــــــــــ								لا							
$\sim \infty$		14 Sifa	2:30	<i>' / :</i>	1		_	١,	M	M	Q_		'			M	773	ć	26	57	50	74	Ъ.	,	01	VF	1R	n	6	01	74	*
Refinguished By Date Time: Received By:				-			HO	-					_	- /																		
	Mora	9/24/	350		JVV)		Λ	ρ_{s}	ll	VA.			1	, ,	<u> </u>		,	«	احد	- •												
Relinquished By	110000	10ate	Time:		ived B	_	. 1-1	بيدات	IVVV	ب ر,			-																			
			Į l	ļ																							·					