17.

1: .

(925) 933-5360 Walnut Creek, California

## JONAS & ASSOCIATES INC. Environmental Consultants

FAX / TELECOPY TRANSMITTAL

From:	Romena Jonas	of: J&A							FAX #: (925) 933 - 5362									
To:	Madhulla Logan	County EHCS					FAX #: (510) 337 - 9335											
Date:	e: 11 / 16/ 1998					Project: Continental General Tire Oakland												
Time:				Pro	jec	t#:	:	1		1	2 E T		1		1674			
Attacl	aments:					Ä	1	•	4756-	#				11				
1)										•								
2)											<del></del> .		<del></del>		*			
3)					1													
Numb	er of Attached Pages (no	t inc	luding trans	mitte	al p	age	e): :	3										



## JONAS & ASSOCIATES INC.

## Environmental Consultants

2815 Mitchell Drive, Suite 209 · Welnut Creek, CA 94598 · Tel: (510) 933-5360 · Fax: (510) 933-5362

November 16, 1998

Ms. Madhulla Logan
Alameda County Environmental Health Care Services
1131 Harbor Bay Parkway, 2nd Floor
Alameda, California 94502
(510) 337-9335

Subject: Addendum to the November 10, 1998 Work Plan for

Additional Site Investigation/Remediation."

Project: Oakland Continental General Tire

J&A #: GT-213

Dear Ms. Logan:

As you requested, presented below are modifications to our November 10, 1998 "Work Plan for Additional Site Investigation/Remediation" for the Continental General Tire's facility located at 1201 14th Avenue, in Oakland, California.

- » Groundwater in Pit E and Basins B1 and B2 will be pumped for one month. Pumping will occur for three days each week, typically on Mondays, Wednesdays, and Fridays. Each pit or basin will be pumped to remove accumulated groundwater. Pumped groundwater will be discharged into a holding tank.
- A new monitoring well, identified as MW-4, will be installed downgradient of Basins B1 and B2. Please see Figure 1 for the proposed location of monitoring well MW-4 and Figure 2 with a schematic diagram for well construction. All four monitoring wells shall be sampled as presented in the November 10, 1998 "Work Plan for Additional Site Investigation/Remediation."

Please contact us with your approval or a request for further modification.

Should you have any question or comment, please contact Mark or Romena Jonas at (925) 933-5360.

Sincerely,

JONAS & ASSOCIATES INC.

Romena Jonas

Principal

attachments: Figures 1 and 2.

cc: Mike McNally. Continental General Tire. Inc.

Reviewed by:

Mark Jonas, R.G.

Registered Geologist #6392

8ltr1116.gt3

FROM JONAS ASSOCIATES 925 933 5362

11-16-1998 2:35PM