



KAPREALIAN ENGINEERING, INC.

Consulting Engineers

PO BOX 996 • BENICIA, CA 94510

(707) 746-6915 • (707) 746-6916 • FAX (707) 746-5515

TRANSMITTAL PAGE

DATE: 9/25/90

TO: Carburine Chedick
Alameda County Health Dept.

FROM: KEI Transmittal

Number of Pages 4
(including cover):

SUBJECT: Bp-Alameda Park and Lincoln
Arched - please find a sample
Sheet

(707) 746-6915

If any problems occur in receiving, please
call the number listed above.

Belinda C. Vega
Belinda C. Vega
Laboratory Director



KAPREALIAN ENGINEERING, INC.
CHAIN OF CUSTODY

SAMPLE: Hard SITE NAME & ADDRESS: BP Station - ALAMEDA
Park St / Lincoln Ave

ANALYSES REQUESTED: TPH - C, BTEX, Total lead

TURN AROUND TIME: 24 Hrs

SAMPLE NO.	DATE	TIME	SOIL	WATER	GRAB	CONT.	NO. OF CONT.	SAMPLING LOCATION	ANALYSES REQUESTED		
									TPH - C	BTEX	Total lead
D1	9/21/90		✓	✓		1		Beneath Dispenser	✓	✓	✓
D2	9/21/90		✓	✓		1			✓	✓	✓
D3	9/21/90		✓	✓		1			✓	✓	✓
D4	9/21/90		✓	✓		1			✓	✓	✓

REMARKS:
 Please stop at the start of 568-569

Relinquished by: (Signature) <u>[Signature]</u>	Date/Time <u>9/21/90 9:05</u>	Received by: (Signature) <u>[Signature]</u>
Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time	Received by: (Signature)

The following MUST be completed by the laboratory accepting samples for analysis:

- Have all samples received for analysis been stored in ice? ✓
- Will samples remain refrigerated until analyzed? ✓
- Did any samples received for analysis have head space? NO
- Were samples in appropriate containers and properly packaged? ✓

Signature: [Signature] Title: [Signature] Date: 9/21/90