September 30, 1999

QUARTERLY GROUNDWATER MONITORING REPORT AUGUST 27, 1999 GROUNDWATER SAMPLING ASE JOB NO. 3412

at
Former Chan's Shell Station
726 Harrison Street
Oakland, CA 94602

Prepared by:
AQUA SCIENCE ENGINEERS, INC.
208 W. El Pintado
Danville, CA 94526
(925) 820-9391

1.0 INTRODUCTION

Site Location (Site), See Figure 1
Former Chan's Shell Station
726 Harrison Street
Oakland, CA 94602
(510) 444-6583

Responsible Party
Kin Chan
4328 Edgewood Avenue
Oakland, CA 94602

Environmental Consulting Firm
Aqua Science Engineers, Inc. (ASE)
208 W. El Pintado
Danville, CA 94526
Contact: Robert Kitay, Senior Geologist
(925) 820-9391

Agency Review
Larry Seto
Alameda County Health Care Services Agency (ACHCSA)
1131 Harbor Bay Pkwy., Suite 250
Alameda, CA 94502
(510) 567-6700

California Regional Water Quality Control Board (RWQCB) San Francisco Bay Region 1515 Clay Street, Suite 1400 Oakland, CA 94612 Contact: Mr. Chuck Headlee (510) 622-2433

The following is a report detailing the results of the August 27, 1999 quarterly groundwater sampling at the above-referenced site. This sampling was conducted as required by the ACHCSA and RWQCB. ASE has prepared this report on behalf of Kin Chan, property owner. This report is intended to supplement the ASE report: "Report of Soil and Groundwater Assessment" dated January 8, 1999.

2.0 GROUNDWATER FLOW DIRECTION AND GRADIENT

On August 27, 1999, ASE associate geologist Ian Reed measured the depth to groundwater in monitoring wells MW-1, MW-3, and MW-4 using an electric water level sounder. The surface of the groundwater was also checked for the presence of free-floating hydrocarbons or sheen. No free-floating hydrocarbons or sheen were observed in any site monitoring well. Monitoring well MW-2 was inaccessable due to car parked over the well. Groundwater elevation data is presented in Table One.

TABLE ONE
Groundwater Elevation Data
Chan's Former Shell Station

Well I.D.	Date of Measurement	Top of Casing Elevation (relative to project datum)	Depth to Water (feet)	Groundwater Elevation (project data)
MW-1	12-15-98	31.95	17.32	14.63
11111	03-04-99	51.95	17.52	16.43
	06-17-99		16.90	15.05
	08-27-99		17.39	14.56
MW-2	12-15-98	32.40	18.03	14.37
	03-04-99		16.11	16.29
	06-17 - 99		17.72	14.68
	08-27-99	Inaccessable		7 110 0
MW-3	12-15-98	31.61	17.26	14.35
	03-04-99		15.47	16.14
	06-17-99		16.92	14.69
	08-27-99		17.40	14.21
MW-4	12-15-98	32.53	17.59	14.94
	03-04-99	1 = 100	15.88	16.65
	06 -17-99		17.14	15.39
	08-27-99		17.65	14.88

A groundwater potentiometric surface map is presented as Figure 2. The groundwater flow direction is to the southwest with a gradient of approximately 0.011-feet/foot. This gradient and flow direction are consistant with previous results and neighboring sites. The water table has dropped approximately 0.5-feet this quarter.

3.0 GROUNDWATER SAMPLE COLLECTION AND ANALYSIS

Prior to sampling, monitoring wells MW-1, MW-3, and MW-4 were purged of four well casing volumes of groundwater using dedicated polyethylene Monitoring well MW-2 was inaccessable due to a car parked over bailers. the well, and therefore was not sampled. Petroleum hydrocarbon odors were present during the purging and sampling of all three groundwater monitoring wells sampled. The parameters pH, temperature and conductivity were monitored during the well purging, and samples were not collected until these parameters stabilized. Groundwater samples were collected from each well using dedicated polyethylene bailers. The samples were decanted from the bailers into 40-ml volatile organic analysis (VOA) vials, pre-preserved with hydrochloric acid. The samples were capped without headspace, labeled and placed in coolers with wet ice for transport to McCambell Analytical, Inc. of Pacheco California (DHS #1644) under appropriate chain-of-custody documentation. Well sampling field logs are presented in Appendix A.

The well purge water was placed in 55-gallon steel drums, labeled, and left on-site for temporary storage.

The groundwater samples were analyzed by McCambell Analytcal, Inc. for total petroleum hydrocarbons as gasoline (TPH-G) by EPA Method 5030/8015M, benzene, toluene, ethylbenzene and total xylenes (collectively known as BTEX) by EPA Method 8020 and methyl tertiary butyl ether (MTBE) by EPA Method 8020. A MTBE confirmation was performed by EPA Method 8260 on detections only. The analytical results for this sampling period are presented in Table Two. The certified analytical report and chain-of-custody documentation are included as Appendix B.

TABLE TWO

Certified Analytical Results for GROUNDWATER Samples Chan's Former Shell Station

All results are in parts per billion (ppb)

Well ID					· .	
& Dates				Ethyl-	Total	
Sampled	TPH-G	Benzene	Toluene	benzene	Xylenes	MTBE
2011 4						
<u>MW-1</u>	.					
07/03/97	18,000	2,700	350	450	900	7,400
12/05/98	18,000	1,500	270	260	560	14,000
03/04/99	44,000	2,800	400	440	960	43,000
06/17/99	33,000	2,200	250	460	660	25,000
08/27/99	6,000	1,000	97	190	230	14,000/
						16,000*
MW-2						
<u>M W - 2</u> 12/05/98	< 50	20 E	-0.5	0.7	2.5	_
03/04/99		< 0.5	< 0.5	< 0.5	< 0.5	<5
06/17/99	Inaccessable < 50		parked ov		.	
08/17/99	. – •	< 0.5	< 0.5	< 0.5	< 0.5	<5
00141177	Inaccessable	due to	car park	ed over w	ell	
<u>MW-3</u>						
12/05/98	6,500	< 50	50	60	50	3,900
03/04/99	2,800	< 25	< 25	< 25	< 25	3,900 1,600
06/17/99	1,000	< 10	< 10	< 10	< 10	
08/27/99	230	< 0.5	0.51	0.5	1.0	1,400
	- ¥		VIJI	V • J	1.0	1,500/ 1,600*
		•				1,000
<u>MW-4</u>						
12/05/98	880	3	< 0.5	< 0.5	< 0.5	950
03/04/99	3,800	< 25	< 25	< 25	< 25	3,700
06/17/99	2,700	< 25	< 25	< 25	< 25	2,700
08/27/99	440	4.7	1.1	0.58	1.3	1,600/
					1.0	1,700*
DHSMCL	NE			MILES MALES AND SECURE OF THE	BBBRG 2 Commission	2002/2012 Annual 40000 (2000) 1 10 1000 (2000)
EATTO-IMPE	S. FRENÇ PER	L	150	700	1,750	13

Notes:

DHS MCL = California Department of Health Services maximum contaminant level for drinking water.

NE = DHS MCL not established

Non-detectable concentrations noted by the less than sign (<) followed by the laboratory detection limit.

^{*} EPA Method 8020/EPA Method 8260 (MTBE confirmation)

4.0 CONCLUSIONS

TPH-G and BTEX concentrations decreased in groundwater samples collected from all three monitoring wells sampled this quarter. Most of the concentrations this quarter are, in fact, historic lows. MTBE concentrations decreased from last quarter's results in groundwater samples collected from monitoring well MW-1 and MW-4. The MTBE results for groundwater samples collected from monitoring well MW-3 are very similar to last quarter's results.

The benzene and MTBE concentrations detected in groundwater samples collected from monitoring wells MW-1 and MW-4 exceeded California Department of Health Services (DHS) maximum contaminant levels (MCLs) for drinking water. The MTBE concentration in groundwater samples collected from monitoring well MW-4 also exceeded the DHS MCL for drinking water.

5.0 **RECOMMENDATIONS**

ASE recommends continued monitoring of the site on a quarterly basis. The next groundwater sampling is scheduled for December 1999.

6.0 REPORT LIMITATIONS

The results of this report represent the conditions at the time of the groundwater sampling, at the specific locations where the groundwater samples were collected, and for the specific parameters analyzed by the laboratory. It does not fully characterize the site for contamination resulting from sources other than the former underground storage tanks and associated plumbing at the site, or for parameters not analyzed by the laboratory. All of the laboratory work cited in this report was prepared under the direction of independent CAL-EPA certified laboratory. The independent laboratory is solely responsible for the contents and conclusions of the chemical analysis data.

Aqua Science Engineers appreciates the opportunity to provide environmental consulting services for this project, and trust that this report meets your needs. Please feel free to call us at (925) 820-9391 if you have any questions or comments.

Respectfully submitted,

AQUA SCIENCE ENGINEERS, INC.

Ian T. Reed

Associate Geologist

Robert E. Kitay, R.G., R.E.A.

Senior Geologist

Rold E. Kitz




Attachments: Figures 1 and 2

Appendices A and B

cc: Mr. Larry Seto, Alameda County Health Care Services

Mr. Chuck Headlee, RWQCB, San Francisco Bay Region




SITE LOCATION MAP

FORMER CHAN'S SHELL STATION 726 HARRISION STREET OAKLAND, CALIFORNIA

Aqua Science Engineers

Figure 1



MW-1

LEGEND

ASE Monitoring Well

(14.69') Groundwater elevation, relative to MSL

Groundwater elevation contour

7TH STREET

GROUNDWATER ELEVATION CONTOUR MAP - 8/27/99

726 HARRISON STREET OAKLAND, CALIFORNIA

AQUA SCIENCE ENGINEERS

Figure 2

APPENDIX A

Well Sampling Field Logs



WELL SAMPLING FIELD LOG

Project Name and Address:	CHAN Former Shell Station
7-15 # 3417	Date of sampling: 8-27-99
Well Name: MW-1	Sampled by: ITR
Total depth of well (feet): 2	Date of sampling: \$-27-99 Sampled by: ITR 7-21 Well diameter (inches): 2"
70 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	TTOOT IV
This leads of floating product if	any:
Thickness of Hoading product if	any: 9 82
Depth of well casing in water (i	ng volume (gallons): 1, 7
Number of gallons per well cash Number of well casing volumes	to be removed:
Number of well casing volumes	be purged before sampling (gallons): 6.7
Req'd volume of groundwater to	Andrea le legit
Equipment used to purge the w	ell: <u>Addressed bailer</u> Time Evacuation Finished: 1030
Time Evacuation Began. 1015	Time Evacuation rimshed
Approximate volume of grounds	water purged: 7.0
Did the well go dry?:	After how many gallons:
Time samples were collected:	1035 ling: 17.45 npling: 90°L
Depth to water at time of samp	ling:
Percent recovery at time of san	npling:
Sample color: gray clear	Odor: Slight HC oder
Description of sediment in sam	ple:
CHEMICAL DATA	
Volume Purged Temp	pH Conductivity
1 10 1	4.98 581
ζ. (<i>,9,8</i>	3.37 5.78 5.09 509
3 90.2	5.78 501
3 40.2 4 68.9	F188 509
SAMPLES COLLECTED	
billi bbo combotibe	
Sample # of containers Volume & t	ype container Pres Iced? Analysis
MU-1 3 HOMI	



WELL SAMPLING FIELD LOG

Project Name and Address:	CHAN former shell station
Job #:3412	Date of sampling: &-17-ag
Well Name: Mw-3	
Total depth of well (feet):	29.66 Well diameter (inches): 2"
Depth to water before sampling	(feet): 17.40'
Thickness of floating product if	any:
Thickness of floating product if Depth of well casing in water (f	eet): 7.26
	ing volume (gallons): 1.2
Number of well casing volumes	to be removed: 4
	be purged before sampling (gallons): 5
Equipment used to purge the w	ell: <u>dedicated bailer</u>
Time Evacuation Began: 0950	Time Evacuation Finished Locs
Approximate volume of groundy	water purged:5
Did the well go dry?:_ No	After how many gallons:
Time samples were collected:	1010
Depth to water at time of samp	ling: 17.46
Percent recovery at time of san	npling: 95h
Samples collected with:	deducated boiler
Sample color: goy due	Odor: Shout He odor
Description of sediment in samp	ole:
*	
CHEMICAL DATA	
Volume Purged Temp	pH Conductivity
76.1	5,36 437
2 699	5.40 498
3 1.9.9	541 510
<u>4</u> 70.0	5.39 459
SAMPLES COLLECTED	
Sample # of containers Volume & tvi	pe container Pres Iced? Analysis
MU-3 3 40 m	1 VOAS I V TPH-G-/BIEX/MOTE
·	



WELL SAMPLING FIELD LOG

Project Name a Job #:	3417	Data of	compling	C. 77L-9	
Well Name:	MW-4	Sampled	bv:	iTZ-	
Total depth of	well (feet):	29.97	Well diam	eter (inches):	7 (
-			(4	
Depth to water Thickness of flo Depth of well of	pating product i	f any:	No	FMS	
Depth of well of	casing in water	(feet):	1	2,32	
Number of gall	ons per well ca	sing volume	(gallons):	2.	
Number of well	casing volume	s to be remo	oved:	4	
Rea'd volume o	f groundwater	to be purged	before samp	pling (gallons):	<u> </u>
Equipment used	to purge the	well:	dedicate	ed bailer.	
Time Evacuatio	n Began: <u>1040</u>	Ti	me Evacuati	ion Finished:	1047
Approximate vo	olume of groun	dwater purge	d:	<u>8</u>	
Did the well go	dry?: <u> </u>	Af	fter how ma	ny gallons:	· ~
Time samples	were collected:_		1030		
Depth to water	at time of sam	ipling:	<u>(+.87</u>		
Percent recover	y at time of s	ampling:	954.		
Samples collect Sample color: _	ed with:		Alduco	Jeal Barler	0
Sample color: _	9/64 (C601	O	dor:	01941 ITC 02	tor
Description of	sediment in sai	nple:			
CHEMICALD	A 170 A -			*	,
CHEMICAL D.	AIA				
Volume Purged	<u>Temp</u>	Нq	Conductiv	itv	
Υ.	70.1	4.38	54	\	
	(,4,8		<u> کی ک</u>	<u>-</u> と	
3		3,3 <u>5</u>	(30)	
4	30.0		670		
		·			
SAMPLES COL	LECTED				
	ntainers <u>Volume &</u>			Analysis	,
Mb-43	40-m	1 UOAS		19H-G-/BTEX	MTBE_
	- 			· 	
					
	· · · · · · · · · · · · · · · · · · ·		<u></u>		
,			,	in the second	

APPENDIX B

Certified Analytical Report and Chain of Custody Documentation

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com E-mail: main@mccampbell.com

Aqua Science Engineers, Inc	Client Project ID: #3412; Chan, Former	Date Sampled: 08/27/99	
2411 Old Crow Canyon Rd, #4	Shell Station	Date Received: 08/27/99	
San Ramon, CA 94583	Client Contact: Ian T. Reed	Date Extracted: 08/27/99	
	Client P.O:	Date Analyzed: 08/27/99	

09/03/99

Dear Ian:

Enclosed are:

- 1). the results of 3 samples from your #3412; Chan, Former Shell Station project,
- 2). a QC report for the above samples
- 3). a copy of the chain of custody, and
- 4). a bill for analytical services.

All analyses were completed satisfactorily and all QC samples were found to be within our control limits. If you have any questions please contact me. McCampbell Analytical Laboratories strives for excellence in quality, service and cost. Thank you for your business and I look forward to working with you again.

Yourstruly.

Edward Hamilton, Lab Director

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com E-mail: main@mccampbell.com

Aqua Science Engineers, Inc	Client Project ID: #3412; Chan, Former	Date Sampled: 08/27/99	
2411 Old Crow Canyon Rd, #4	Shell Station	Date Received: 08/27/99	
San Ramon, CA 94583	Client Contact: Ian T. Reed	Date Extracted: 08/27-09/03/99	
	Client P.O:	Date Analyzed: 08/27-09/03/99	

Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline*, with Methyl tert-Butyl Ether* & BTEX*

Lab ID	Client ID	Matrix	TPH(g)⁺	МТВЕ	Benzene	Toluene	Ethylben- zene	Xylenes	% Recovery Surrogate
18142	MW-1	w	6000,a	14,000	1000	97	190	230	108
18143	MW-3	w	230,j	1500	ND	0.51	ND	1.0	119
18144	MW-4	w	440,a	1600	4.7	1.1	0.58	1.3	108
					The second second				
			: 						
	<u>-</u>					174			
Reporting	g Limit unless	W	50 ug/L	5.0	0.5	0.5	0.5	0.5	
otherwise stated; ND means not detected above the reporting limit		S	1.0 mg/kg	0.05	0.005	0.005	0.005	0.005	

^{*} water and vapor samples are reported in ug/L, wipe samples in ug/wipe, soil and sludge samples in mg/kg, and all TCLP and SPLP extracts in ug/L

Edward Hamilton, Lab Director

^{*} cluttered chromatogram; sample peak coelutes with surrogate peak

^{*}The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (?); f) one to a few isolated peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen is present; i) liquid sample that contains greater than ~5 vol. % sediment; j) no recognizable pattern.

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560 Telephone: 925-798-1620 Fax: 925-798-1622 http://www.mccampbell.com E-mail: main@mccampbell.com

Aqua Science Engineers, Inc 2411 Old Crow Canyon Rd, #4		Client	Project ID: #3412; Chan, Former	Date Sampled: 08/27/99		
			Station	Date Received: 08/27/99		
San Ramon, C	·	Client	Contact: Ian T. Reed	Date Extracted: 09/01/99		
		Client	P.O:	Date Analyzed: (09/01/99	
	······································		Methyl tert-Butyl Ether *			
EPA method 820	60 modified					
Lab ID	Client ID	Matrix	MTBE*		% Recovery Surrogate	
18142	MW-1	w	16,000		118	
18143	MW-3	W	1600		118	
18144	MW-4	W	1700		118	
					,	
Reporting Limi	t unless otherwise	W	1.0 ug/L			
stated; ND means	s not detected above orting limit	S	5.0 ug/kg			

^{*} water samples are reported in ug/L, soil and sludge samples in ug/kg, wipe samples in ug/wipe and all TCLP / STLC / SPLP extracts in ug/L

Edward Hamilton, Lab Director

DHS Certification No. 1644

h) lighter than water immiscible sheen is present; i) liquid sample that contains greater than ~5 vol. % sediment.

QC REPORT FOR HYDROCARBON ANALYSES

Date: 08/27/99-08/28/99

Matrix:

WATER

1	Concent	ration	(ug/L)		% Reco	very	
Analyte	Sample			Amount			RPD
	(#17000)	MS	MSD	Spiked	MS	MSD	
			<u> </u>		ļ	 -	······································
 TPH (qas)	1 0.0	100.0	97.9	100.0	 100.0	97.9	2.1
Benzene	0.0	9.2	9.2	10.0	92.0	92.0	0.0
Toluene	0.0	9.1	9.1	10.0	91.0	91.0	0.0
Ethyl Benzene	0.0	9.3	9.2	10.0	93.0	92.0	1.1
Xylenes	0.0	27.8	27.5	30.0	92.7	91.7	1.1
TPH(diesel) 	0.0	8564	8457	7500	114	113	1.3
		••					
TRPH	0	19400	19100	23700	82	81	1.6
(oil & grease) 					l İ		

% Rec. = (MS - Sample) / amount spiked x 100

RPD = ((MS - MSD) / (MS + MSD)) \times 2 \times 100 "~

QC REPORT FOR VOCs (EPA 8240/8260)

Date: 09/01/99-09/02/99 Matrix: WATER

	Concentration (ug/kg,u			•	% Recovery		
Analyte	Sample (#18613)	MS	MSD 	Amount Spiked	MS	MSD	RPD
1,1-Dichloroethe	0	97	101	100	97	101	4.0
Trichloroethene	0	87	115	100	87	115	27.7
EDB	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Chlorobenzene	0	106	120	100	106	120	12.4
Benzene	j o	102	115	100	102	115	12.0
Toluene	j o	103	123	100	103	123	17.7
İ					İ		

% Rec. = (MS - Sample) / amount spiked \times 100

RPD = $\{MS - MSD\}$ / $\{MS + MSD\}$ x 2 x 100

Aqua Science Engineers, Inc. 208 W. El Pintado Road Danville, CA 94526 (925) 820-9391 FAX (925) 837-4853

Chain of Custody

FAX (925) 837-4853			PAGE OF 1	
SAMPLER (SIGNATURE)	(PHONE NO.) (925)822-4391	PROJECT NAME ADDRESS	THAN, former Shull Station JOBNO. 3412 726 Harrison Street, OAKLAND, CA DATE 8-27-99	_
ANALYSIS REQU	AS / MTBE & BTEX 030/8015-8020) ASOLINE (030/8015)	TPH-DIESEL (EPA 3510/8015) PURGEABLE HALOCARBONS (EPA 601/8010) PURGEABLE AROMATICS (EPA 602/8020).	CAM 17 METALS (EPA 628/8020) SEMI-VOLATILE ORGANICS (EPA 625/8270) OIL & GREASE (EPA 525/8270) OIL & GREASE (EPA 5520) LUFT METALS (S) (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 6010+7000) PCBS & PESTICIDES (EPA 8010) PUEL OXYGENATES (EPA 8260) WHTDE USAYGENATES (EPA 8260) WHTDE USAYGENATES (EPA 8260) WHTDE USAYGENATES	COMPOSITE
		TPH-C (EPA) (EPA) (EPA)		
MW-4 V 1050	ater 3 7. 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3		1814	
			1814	44
GOOD CONDITION APPRO	VOAS TO RO METALS OTHER ROPRIATE TIAINERS			
(elignature) (clime) (elignature) (time) (elignature) (time) (figure figure) (figure figure) (figure figure	RECEIVED BY: (signature) (time) (signature) (date) (printed name) (date) Company-		(time) (signature) (time)	