

PROTESTICAL 97 JH 22 AM SIZI

January 10, 1997 # 2(16

Messrs. Aaron and Stanley Wong 2200 E. 12th Street Oakland, CA 94606

Re: Fourth Quarter Report, 1996, Credit World Auto Sales, 2345 E. 14th Street, Oakland, CA 94601

Dear Messrs. Wong:

Tank Protect Engineering of Northern California, Inc. (TPE) is pleased to submit this quarterly letter report of environmental services conducted at the subject site. Previous work conducted prior to January 1, 1996 is summarized in TPE's Fourth Quarter Report, 1995. Credit World Auto Sales, 2345 E. 14th Street, Oakland, CA 94601. Work conducted after January 1, 1996 is summarized, and work conducted during the subject quarter is presented in detail below.

Work performed by TPE during first quarter, 1996:

- February 14, 1996 Submitted a Fourth Ouarter Report, 1995, Credit World Auto Sales, 2345 E, 14th Street, Oakland, CA 94601 to Messrs. Wong for their approval and delivery to the Alameda County Health Care Services Agency (ACHCSA).
- March 20, 1996 Loosened well caps on all wells to allow depth-to groundwater to stabilize to atmospheric pressure for groundwater gradient determination.
- March 22, 1996 Measured depth-to-groundwater and free product thickness in wells MW-1 through TMW-5 for evaluation of groundwater

flow direction and gradient and collected 5 groundwater samples for analysis for total petroleum hydrocarbons as gasoline (TPHG), and methyl t-butyl ether, benzene, toluene, ethylbenzene, and xylenes (MBTEX). Additionally, a trip blank was analyzed for TPHG and MBTEX.

Work performed by TPE during second quarter, 1996:

- May 6, 1996 Submitted a <u>First Quarter Report, 1996, Credit World Auto Sales, 2345 E, 14th Street, Oakland, CA 94601</u> to Messrs. Wong for their approval and delivery to the ACHCSA.
- . May 21, 1996 through June 7, 1996 Backfilled excavation with remediated onsite material, overexcavation of contaminated soil and remediation of stockpiled soil.
- June 18, 1996 Loosened well caps on all wells to allow depth-to groundwater to stabilize to atmospheric pressure for groundwater gradient determination.
- June 20, 1996 Measured depth-to-groundwater and free product thickness in wells MW-1 through TMW-4 for evaluation of groundwater flow direction and gradient and collected groundwater samples from wells MW-1 through TMW-4 for analysis for TPHG and MBTEX. Additionally, a trip blank was analyzed for TPHG and MBTEX.
- . June 24, 1996 Redeveloped well TMW-5 for sampling.
- June 26, 1996 Sampled well TMW-5 for analysis for TPHG and MBTEX.

Work performed by TPE during third quarter, 1996:

July 30, 1996 - Submitted a <u>Second Quarter Report</u>, 1996, <u>Credit World Auto Sales</u>, 2345 E, 14th Street, <u>Oakland</u>, <u>CA 94601</u> to Messrs. Wong for their approval and delivery to the ACHCSA.

- July 1, 1996 through September 30, 1996 Conducted excavation, soil remediation and backfilling activities.
- . September 23, 1996 Loosened well caps on wells MW-1, MW-3, and TMW-4 to allow depth-to groundwater to stabilize to atmospheric pressure for groundwater gradient determination. Wells MW-2 and MW-5 were inaccessible.
- September 24, 1996 Measured depth-to-groundwater and free product thickness in wells MW-1, MW-3, and TMW-4 for evaluation of groundwater flow direction and gradient and collected groundwater samples from wells MW-1 through TMW-4 for analysis for TPHG and MBTEX. Additionally, a trip blank was analyzed for TPHG and MBTEX.
- September 30, 1996 Measured depth-to-groundwater and free product thickness in wells MW-2 and TMW-5 for evaluation of groundwater flow direction and gradient, and collected groundwater samples from both wells for analysis for TPHG and MBTEX. Additionally, a trip blank sample was analyzed for TPHG and MBTEX. Supervised the removal of about 545 gallons of hydrocarbon contaminated groundwater and petroleum products.

WORK PERFORMED BY TPE DURING FOURTH QUARTER, 1996

- October 1 through 4, 1996 TPE conducted stockpile soil remediation and verification sampling
- October 3, 1996 ACHCSA issues a letter titled Status of Subsurface Investigation at 2345 E. 14th St. Oakland, CA 94601, Former Taxi, Taxi.
- October 28, 1996 Backfilled the excavation to grade.

- November 26 and December 9 and 13, 1996 Repair and redevelop TMW-5.
- December 27, 1996 Measured depth-to-groundwater and free product thickness in wells MW-1 through TMW-5 for evaluation of groundwater flow direction and gradient and collected groundwater samples from wells MW-1 through TMW-5 for analysis for TPHG and MBTEX. Additionally, a trip blank was analyzed for TPHG and MBTEX.

Details of work conducted during the fourth quarter are presented below.

Site Activities

On October 3, 1996 ACHCSA issued the above letter requesting no further soil excavation be conducted until the offsite investigation is completed (see attached).

During the this quarter, TPE conducted stockpile soil remediation verification soil sampling and backfilled the remaining excavation to grade. An interim report of remediation activities will be presented to Messrs. Wong and to ACHCSA in the near future.

Monitoring well TMW-5 was damaged during backfill activities that took place in May, 1996. On September 30, 1996 the well was uncovered again and found to be about one-half silted full. On November 26 and December 9 and 13, 1996 TPE repaired and redeveloped TMW-5 (see attached Records of Well Development).

Groundwater Gradient

Due to the large amount of precipitation received during the month of December 1996, well caps were not loosened prior to making depth-to-groundwater measurements for evaluation of groundwater flow direction and gradient.

On December 27, 1996 depth-to-groundwater was measured from the top of casing (TOC) in wells MW-1, MW-3, and TMW-4 to the nearest 0.01 foot using an electronic Keck Instrument, Inc., KIR-89 interface probe. A minimum of 3 repetitive measurements were made for each level determination to ensure accuracy. Depth-to-groundwater was subtracted from the TOC elevation, measured relative to mean sea level, to calculate the elevation of the groundwater level in each well (see attached Table 1). When floating product was present, the groundwater elevation was corrected by multiplying the floating product thickness by a density of .75 and adding the resultant value to the groundwater elevation.

Attached Figure 1 is a groundwater gradient map constructed from the data collected on December 27, 1996. Groundwater flow direction was to the north and northwest with a gradient about 0.024 and 0.029 feet per foot, respectively. Average groundwater elevations, changes in average groundwater elevations, groundwater gradients, and groundwater flow directions are tabulated in attached Table 2.

Groundwater Sampling and Analytical Results

On December 27, 1996 groundwater samples were collected from groundwater monitoring wells MW-1 through TMW-5. Before sampling, the wells were purged of about 25 to 46 liters of water with dedicated polyethylene bailers and until the temperature, conductivity, and pH of the water in the wells had stabilized (see attached Records of Water Sampling). Since dedicated bailers were used for each well sampled, no decontamination was necessary between sampling events. The water samples were collected in laboratory provided, sterilized, 40-milliliter glass vials having Teflon-lined screw caps; measured for turbidity and labeled with project name, date, time collected, sample number, and sampler name. The samples were immediately stored in an iced-cooler for transport to California State Department of Health Services (DHS) certified Entech Analytical Labs, Inc., located in Sunnyvale, California accompanied by chain-of-custody documentation. All groundwater samples and a trip blank sample, MW-6, were analyzed for TPHG by the United States Environmental Protection Agency (EPA) Method 8015M and for MBTEX by the Modified EPA Method 8020.

Floating product was observed in wells MW-1, MW-2, and MW-3; with thicknesses of .09 feet, 7.57 feet, and 0.06 feet respectively. Attached Table 3 summarizes the thickness of floating product measured in each well. The floating product was removed by purging at the time of sampling. Hydrocarbon odor and/or sheen were observed in all wells except TMW-4.

Purge water is stored on site in 55-gallon drums labeled to show material stored, known or suspected chemical contaminant, date filled, expected removal date, company name, contact person, and telephone number.

See attached protocols for TPE's sample handling, groundwater monitoring well sampling, and quality assurance and quality control procedures.

Chemical analyses detected TPHG and some or all MBTEX chemicals in all wells except well TMW-4. TPHG was detected in wells MW-1, MW-2, MW-3, and TMW-5 at concentrations of 24,000 parts per billion (ppb), 29,000 ppb, 5,800 ppb and 78,000 ppb, respectively. The reader is referred to attached Table 4 for a summary of MBTEX concentrations detected in the wells.

Well TMW-4 and the trip blank sample (MW-6) were nondetectable for TPHG and MBTEX.

All analytical results are summarized in attached Table 4 and documented in an attached certified analytical report and a chain-of-custody.

RECOMMENDATIONS

Messrs. Aaron and Stanley Wong are currently waiting on approval from the California Underground Storage Tank Fund to begin the offsite investigation.

TPE recommends that quarterly groundwater sampling of all 5 groundwater monitoring wells be continued to evaluate gradient, monitor contaminant concentrations and to continue removal of free product from the wells. During the subject quarter,

concentrations of TPHG and MBTEX fluctuated in all wells except TMW-4 which was nondetectable.

The next sampling event is due on about March 21, 1997.

An additional copy of this report has been included for your delivery to:

Mr. Barney Chan
Alameda County Health Care Services Agency
Department of Environmental Health
1131 Harbor Bay Parkway
Alameda, CA 94502-6577

TPE recommends that this quarterly report be submitted with a signed cover letter from Messrs. Aaron and Stanley Wong.

If you have any questions, please call TPE at (510) 429-8088.

RED GEO

LEE N. HUCKINS No. 6286

Sincerely,

Do Aluckins

Lee Huckins

Registered Geologist

Jeff Farhoomand, M.S.

Principal Engineer

Expiration Date 5/31/97

TABLE 1
GROUNDWATER ELEVATION

| Well Name | Date | TOC ¹ Elevation (Feet MSL ⁴) | Depth-to-Water From TOC (Feet) | Depth to Product From TOC (Feet) | Corrected ³ Groundwater Elevation (Feet MSL) |
|-----------|-----------------------|--|-----------------------------------|-------------------------------------|--|
| MW-1 | 08/23/91 ⁵ | 100.00 ² | 15.42 | NA ⁹ | 84.58 |
| | 04/16/92 ⁶ | 27.33 ⁷ | 16.66 | 11.54 | 14.518 |
| | 06/11/93 | | 12.61 | 12.60 | 14.73 |
| | 08/17/93 | | 14.40 | 13.63 | 13.50 ⁷ |
| | 03/31/94 | | 12.64 | ND | 14.69 |
| | 06/27/94 | | 14.32 | 13.16 | 13.88 |
| | 09/16/94 | | 15.86 | 13.64 | 13.14 |
| | 03/31/95 | | 11.82 | 9.48 | 17.27 |
| | 06/28/95 | | 13.50 | 12.60 | 14.51 |
| | 09/28/95 | | 14.27 | 13.96 | 13.29 |
| | 12/26/95 | | 11.77 | 11.62 | 15.67 |
| | 03/22/96 | | 10.52 | 10.44 | 16.87 |
| | 06/20/96 | | 13.38 | 12.49 | 14.63 |
| | 09/24/96 | | 14.60 | 13.40 | 13.63 |
| | 12/27/96 | | 9.17 | 9.08 | 18.23 |
| MW-2 | 08/23/91 ⁵ | 98.585 ² | 13.77 | NA | 84.815 |
| | 04/16/92 ⁶ | 25.92 ⁷ | 15.38 | 12.57 | 12.65 ⁸ |
| | 06/11/93 | | 13.185 | ND ¹⁰ | 12.74 |
| | 08/17/93 | | 14.04 | 14.03 | 11.89 |
| | 03/31/94 | | 13.61 | 13.07 | 12.72 ⁸ |
| | 06/27/94 | | 14.24 | 13.44 | 12.28 |
| | 09/16/94 | | 17.82 | 13.36 | 11.45 |
| | 03/31/95 | | 16.72 | 9.28 | 14.78 |
| | 06/28/95 | | 13.50 | 12.77 | 12.97 |
| | 09/28/95 | | 14.63 | 14.09 | 11.70 |
| | 12/26/95 | | 12.58 | 11.68 | 14.01 |
| | 03/22/96 | | 11.46 | 11.31 | 14.57 |
| | 06/20/96 | | 13.08 | 12.71 | 13.12 |

TABLE 1
GROUNDWATER ELEVATION

| Well Name | Date | TOC ¹ Elevation (Feet MSL ⁴) | Depth-to-Water From TOC (Feet) | Depth to Product From TOC (Feet) | Corrected ³ Groundwater Elevation (Feet MSL) |
|-----------|-----------------------|--|-----------------------------------|-------------------------------------|--|
| MW-2 | 09/30/96 | | 16.67 | 12.92 | 12.06 |
| | 12/27/96 | | 15.74 | 8.17 | 15.86 |
| MW-3 | 08/23/915 | 99.25 ² | 15.07 | NA | 84.18 |
| | 04/16/92 ⁶ | 27.57 ⁷ | 14.14 | 13.98 | 13.55 ⁸ |
| | 06/11/93 | | 14.275 | ND | 13.30 |
| | 08/17/93 | | 15.77 | ND | 11.80 |
| | 03/31/94 | | 14.35 | ND | 13.22 |
| | 06/27/94 | | 14.77 | ND | 12.80 |
| | 09/16/94 | | 15.42 | 15.37 | 12.19 |
| | 03/31/95 | • | 12.98 | 12.52 | 14.94 |
| | 06/28/95 | | 14.20 | 14.15 | 13.41 |
| | 09/28/95 | | 15.17 | ND | 12.40 |
| | 12/26/95 | | 13.33 | 13.27 | 14.28 |
| | 03/22/96 | | 12.81 | 12.77 | 14.79 |
| | 06/20/96 | | 13.95 | 13.88 | 13.67 |
| | 09/24/96 | | 14.86 | 14.82 | 12.74 |
| | 12/27/96 | | 11.04 | 10.98 | 16.58 |
| TMW-4 | 08/17/93 | 26.50 ⁷ | 13.26 | ND | 13.24 |
| | 03/31/94 | | 12.40 | ND | 14.10 |
| | 06/27/94 | | 12.84 | ND | 13.66 |
| | 09/16/94 | | 13.58 | ND | 12.92 |
| | 03/31/95 | | 10.23 | ND | 16.27 |
| | 06/28/95 | | 12.21 | ND | 14.29 |
| | 09/28/95 | | 13.38 | ND | 13.12 |
| | 12/26/95 | | 11.32 | ND | 15.18 |
| | 03/22/96 | | 10.54 | ND | 15.96 |
| | 06/20/96 | | 12.14 | ND | 14.36 |
| | 09/24/96 | | 13.01 | ND | 13.49 |

TABLE 1
GROUNDWATER ELEVATION

| Well Name | Date | TOC ¹ Elevation (Feet MSL ⁴) | Depth-to-Water From TOC (Feet) | Depth to Product From TOC (Feet) | Corrected ³ Groundwater Elevation (Feet MSL) |
|-----------|------------------------|--|-----------------------------------|-------------------------------------|--|
| TMW-4 | 12/27/96 | | 9.51 | ND | 16.99 |
| TMW-5 | 08/17/93 | 26.51 ⁷ | 12.98 | 12.95 | 13.55 |
| | 03/31/94 | | 11.39 | ND | 15.12 |
| | 06/27/94 | | 12.24 | ND | 14.27 |
| | 09/16/94 | | 13.02 | 12.97 | 13.53 |
| | 03/31/95 | | 7.38 | ND | 19.13 |
| | 06/28/95 | | 11.31 | 11.25 | 15.25 |
| | 09/28/95 | | 14.42 | ND | 12.09 |
| | 12/26/95 | | 10.16 | 10.11 | 16.38 |
| | 03/22/96 | - | 7.59 | 7.54 | 18.96 |
| · | 06/26/9611 | - | 7.12 | ND | NA |
| | 09/30/9611 | | 7.42 | ND ¹⁰ | NA ⁹ |
| | 12/27/96 ¹¹ | | 6.38 | ND | NA |

¹ TOP-OF-CASING.

² RELATIVE TO SITE DATUM ESTABLISHED BY ESE.

³ ELEVATION CORRECTED FOR FLOATING PRODUCT USING 0.75 DENSITY FOR GASOLINE.

⁴ MEAN SEA LEVEL.

⁵ WATER LEVEL MEASUREMENTS BY ESE.

⁶ WATER LEVEL MEASUREMENTS BY NKJ.

⁷ TOC SURVEYED 8/10/93 BY PROFESSIONAL ENGINEER.

⁸ CORRECTED GROUNDWATER ELEVATION BY TANK PROTECT ENGINEERING

⁸ CORRECTED GROUNDWATER ELEVATION BY TANK PROTECT ENGINEERING.

⁹ NOT AVAILABLE.

¹⁰ NOT DETECTED.

¹¹ WELL TOP DESTROYED DURING REMEDIATION

TABLE 2 GROUNDWATER GRADIENTS, FLOW DIRECTIONS, AND ELEVATION DATA

| Date | Average Groundwater Elevation (Feet-MSL ¹) | Change in Average Groundwater Elevation (Feet) | Groundwater Gradient | Groundwater Flow Direction |
|-----------------------|---|--|-------------------------|-------------------------------|
| 04/16/92 | 13.57 | | .021 | NW |
| 06/11/93 | 13.59 | 0.02 | .026 | NW |
| 08/17/93 | 12.80 | -0.79 | .029 | RADIAL |
| 03/31/94 | 13.97 | +1.17 | .050 | RADIAL |
| 06/27/94 | 13.38 | -0.59 | .020 | RADIAL |
| 09/16/94 | 12.65 | -0.73 | .01790411 | RADIAL |
| 03/31/95 | 16.48 | +3.83 | .075 | RADIAL |
| 06/28/95 | 14.09 | -2.39 | .025053 | RADIAL |
| 09/28/95 | 12.52 | -1.57 | .025 | NW |
| 12/26/95 | 15.09 | +2.57 | .048 | RADIAL |
| 03/22/96 | 16.23 | +1.14 | .034132 | RADIAL |
| 06/20/96 ² | 13.95 | -2.28 | .016 | NW |
| 09/30/96 ² | 12.98 | -0.97 | .019 | NW |
| 12/27/96 ² | 16.41 | +3.43 | .024029 | N-NW |

 ¹ MEAN SEA LEVEL.
 ² DOES NOT INCLUDE DATA FOR TMW-5; WELL TOP DESTROYED DURING REMEDIATION ACTIVITIES.

TABLE 3
SUMMARY OF FLOATING PRODUCT THICKNESS

| Well Name | Date | Depth-to-Water From TOC ¹ (Feet) | Depth-to-Product From TOC (Feet) | Product Thickness (Feet) |
|-----------------|-----------------------|--|-------------------------------------|--------------------------|
| MW-1 | 04/16/92 ² | 16.66 | 11.54 | 5.12 |
| | 06/11/93 | 12.61 | 12.60 | 0.01 |
| | 08/17/93 | 14.40 | 13.63 | 0.77 |
| | 03/31/94 | 12.64 | ND | |
| | 06/27/94 | 14.32 | 13.16 | 1.16 |
| | 09/16/94 | 15.86 | 13.64 | 2.22 |
| | 03/31/95 | 11.82 | 9.48 | 2.34 |
| | 06/28/95 | 13.50 | 12.60 | 0.90 |
| | 09/28/95 | 14.27 | 13.96 | 0.31 |
| | 12/26/95 | 11.77 | 11.62 | 0.15 |
| | 03/22/96 | 10.52 | 10.44 | 0.08 |
| | 06/20/96 | 13.38 | 12.49 | 0.089 |
| | 09/24/96 | 14.60 | 13.40 | 1.20 |
| | 12/27/96 | 9.17 | 9.08 | 0.09 |
| MW-2 | 04/16/92 ² | 15.38 | 12.57 | 2.81 |
| | 06/11/93 | 13.185 | ND ³ | |
| | 08/17/93 | 14.04 | 14.03 | 0.01 |
| | 03/31/94 | 13.61 | 13.07 | 0.54 |
| | 06/27/94 | 14.24 | 13.44 | 0.80 |
| | 09/16/94 | 17.82 | 13.36 | 4.46 |
| | 03/31/95 | 16.72 | 9.28 | 7.44 |
| | 06/28/95 | 13.50 | 12.77 | 0.73 |
| | 09/28/95 | 14.63 | 14.09 | 0.54 |
| | 12/26/95 | 12.58 | 11.68 | 0.90 |
| | 03/22/96 | 11.46 | 11.31 | 0.15 |
| . . | 06/20/96 | 13.08 | 12.71 | 0.37 |
| | 09/30/96 | 16.67 | 12.92 | 3.75 |

TABLE 3
SUMMARY OF FLOATING PRODUCT THICKNESS

| Well Name | Date | Depth-to-Water From TOC ¹ (Feet) | Depth-to-Product From TOC (Feet) | Product Thickness (Feet) |
|-----------|-----------------------|---|-------------------------------------|--------------------------|
| MW-2 | 12/27/96 | 15.74 | 8.17 | 7.57 |
| MW-3 | 04/16/92 ² | 14.14 | 13.98 | 0.16 |
| | 06/11/93 | 14.275 | ND | |
| | 08/17/93 | 15.77 | ND | |
| | 03/31/94 | 14.35 | ND | |
| | 06/27/94 | 14.77 | ND | |
| | 09/16/94 | 15.42 | 15.37 | |
| | 03/31/95 | 12.98 | 12.52 | 0.46 |
| | 06/28/95 | 14.20 | 14.15 | 0.05 |
| | 09/28/95 | 15.7 | ND | |
| | 12/26/95 | 13.33 | 13.27 | 0.06 |
| | 03/22/96 | 12.81 | 12.77 | 0.04 |
| | 06/20/96 | 13.95 | 13.88 | 0.07 |
| | 09/24/96 | 14.86 | 14.82 | 0.04 |
| | 12/27/96 | 11.04 | 10.98 | . 0.06 |
| TMW-4 | 08/17/93 | 13.26 | ND | |
| | 03/31/94 | 12.40 | ND | |
| | 06/27/94 | 12.84 | ND | |
| | 09/16/94 | 13.58 | ND | |
| | 03/31/95 | 10.23 | ND | |
| | 06/28/95 | 12.21 | ND | |
| | 09/28/95 | 13.38 | ND | |
| | 12/26/95 | 11.32 | ND | |
| | 03/22/96 | 10.54 | ND | |
| | 06/20/96 | 12.14 | ND | |
| | 09/24/96 | 13.01 | ND | |
| | 12/27/96 | 9.51 | ND | |
| TMW-5 | 08/17/93 | 12.98 | 12.95 | 0.03 |

TABLE 3
SUMMARY OF FLOATING PRODUCT THICKNESS

| Well Name | Date | Depth-to-Water From TOC ¹ (Feet) | Depth-to-Product From TOC (Feet) | Product Thickness (Feet) |
|-----------|------------|---|-------------------------------------|--------------------------|
| TMW-5 | 03/31/94 | 11.39 | ND | |
| | 06/27/94 | 12.24 | ND | |
| | 09/16/94 | 13.02 | 12.97 | 0.05 |
| | 03/31/95 | 7.38 | ND | |
| | 06/28/95 | 11.31 | 11.25 | 0.06 |
| | 09/28/95 | 14.42 | ND | |
| | 12/26/95 | 10.16 | 10.11 | 0.05 |
| | 03/22/96 | 7.59 | 7.54 | 0.05 |
| | 06/20/9611 | 7.12 | ND | |
| | 09/30/9611 | 7.42 | ND | |
| | 12/27/96 | 6.38 | ND | |

¹ TOP-OF-CASING.

² RELATIVE TO SITE DATUM ESTABLISHED BY ESE.

³ ELEVATION CORRECTED FOR FLOATING PRODUCT USING 0.75 DENSITY FOR GASOLINE.

⁴ MEAN SEA LEVEL

⁵ WATER LEVEL MEASUREMENTS BY ESE.

⁶ WATER LEVEL MEASUREMENTS BY NKJ.

⁷ TOC SURVEYED 8/10/93 BY PROFESSIONAL ENGINEER.

⁸ CORRECTED GROUNDWATER ELEVATION BY TANK PROTECT ENGINEERING.

⁹ NOT AVAILABLE.

¹⁰ NOT DETECTED.

¹¹ WELL TOP DESTROYED DURING REMEDIATION

TABLE 4
SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb¹)

| Sample ID Name | Date | TPHG | Methyl t- Butyl Ether | Benzene | Toluene | Ethyl- benzene | Xylenes |
|--|----------|---------|--------------------------|---------|---------|-------------------|---------|
| MW-1 | 08/17/93 | 110,000 | NA ² | 270 | 690 | 730 | 3,100 |
| | 03/28/94 | 34,000 | NA | 4,900 | 1,800 | 1,200 | 4,000 |
| | 06/27/94 | 21,000 | NA | 12,000 | 810 | 760 | 2,500 |
| ······································ | 09/16/94 | 37,000 | NA | 7,900 | 2,400 | 1,300 | 3,300 |
| | 03/31/95 | 43,000 | NA | 8,100 | 1,900 | 1,000 | 4,200 |
| | 06/28/95 | 80,000 | NA | 7,900 | 3,200 | 1,800 | 7,300 |
| | 09/28/95 | 24,000 | <1,200 | 4,900 | 470 | 470 | 1,700 |
| · · · · · · · · · · · · · · · · · · · | 12/26/95 | 61,000 | <1,200 | 12,000 | 4,200 | 1,500 | 5,500 |
| | 03/22/96 | 19,000 | <2,500 | 6,000 | 47 | 260 | <750 |
| | 06/20/96 | 15,000 | 910 | 2,900 | 100 | 240 | 98 |
| | 09/24/96 | 20,000 | 340 | 4,800 | 220 | 300 | 770 |
| | 12/27/96 | 24,000 | <5.0 | 5,900 | 440 | 310 | 740 |
| MW-2 | 08/17/93 | 49,000 | NA | 94 | 240 | 250 | 980 |
| - | 03/28/94 | 14,000 | NA | 4,200 | <250 | 910 | 1,400 |
| | 06/27/94 | 24,000 | NA | 4,400 | 72 | 1,100 | 1,700 |
| ···· | 09/16/94 | 40,000 | NA | 2,300 | 250 | 2,000 | 4,100 |
| . - | 03/31/95 | 28,000 | NA | 4,000 | <120 | 1,100 | 1,400 |
| | 06/28/95 | 40,000 | NA | 2,700 | 130 | 1,700 | 2,900 |
| - 1 | 09/28/95 | 7,500 | <62 | 420 | 14 | 250 | 190 |
| | 12/26/95 | 22,000 | <250 | 1,300 | 88 | 950 | 1,800 |
| | 03/22/96 | 9,800 | <1,200 | 2,200 | <120 | 400 | <380 |
| | 06/20/96 | 35,000 | 550 | 770 | < 0.50 | 240 | < 0.50 |
| | 09/30/96 | 58,000 | <5.0 | 1,600 | 230 | 2,200 | 4,000 |
| | 12/27/96 | 29,000 | < 5.0 | 2,100 | < 0.50 | 1,200 | 1,800 |
| MW-3 | 08/17/93 | 9,600 | NA | 4.1 | 17 | 28 | 54 |
| | 03/28/94 | 8,400 | NA | 2,400 | 56 | 67 | 200 |
| | 06/27/94 | 9,900 | NA | 3,300 | <22 | <25 | 73 |
| | 09/16/94 | 16,000 | NA | 2,300 | 80 | 620 | 240 |


TABLE 4
SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb1)

| Sample ID Name | Date | ТРНС | Methyl t- butyl ether | Benzene | Toluene | Ethyl- benzene | Xylenes |
|-------------------|----------|---------|--------------------------|---------|---------|-------------------|---------|
| MW-3 | 03/31/95 | 16,000 | NA | 2,800 | 70 | <25 | 920 |
| | 06/28/95 | 11,000 | NA | 2,300 | 32 | 81 | 240 |
| | 09/28/95 | 6,300 | <420 | 1,900 | <42 | 200 | <120 |
| | 12/26/95 | 25,000 | <250 | 3,800 | 97 | 94 | 1,600 |
| | 03/22/96 | 16,000 | 250 | 3,100 | 75 | 69 | 350 |
| | 06/20/96 | 8,500 | 220 | 1,400 | 28 | 140 | 15 |
| | 09/24/96 | 12,000 | < 5.0 | 2,400 | 87 | 340 | 110 |
| | 12/27/96 | 5,800 | 240 | 1,700 | 28 | < 0.50 | 42 |
| TMW-4 | 08/17/93 | 150 | NA | < 0.50 | 0.8 | 1.4 | 3.7 |
| | 03/28/94 | <50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 06/27/94 | < 50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 09/16/94 | <50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 03/31/95 | <50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 06/28/95 | < 50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 09/28/95 | < 50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 12/26/95 | < 50 | <5.0 | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 03/22/96 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 06/20/96 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| | 09/24/96 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| | 12/27/96 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| TMW-5 | 08/17/93 | 120,000 | NA | 340 | 730 | 790 | 3,600 |
| | 03/28/94 | 70,000 | NA | 23,000 | 1,500 | 4,100 | 15,000 |
| | 06/28/94 | 56,000 | NA | 26,000 | 940 | 5,500 | 26,000 |
| | 09/16/94 | 96,000 | NA | 17,000 | 720 | 3,500 | 12,000 |
| | 03/31/95 | 64,000 | NA | 13,000 | 470 | 2,800 | 6,100 |
| | 06/28/95 | 65,000 | NA | 9,000 | 240 | 2,600 | 5,300 |
| | 09/28/95 | 79,000 | <1,200 | 17,000 | 1,800 | 2,700 | 7,000 |
| | 12/26/95 | 110,000 | <1,200 | 24,000 | 2,300 | 4,100 | 10,000 |
| | 03/22/96 | 56,000 | <2,500 | 11,000 | 800 | 2,300 | 4,500 |

TABLE 4 SUMMARY OF GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb¹)

| Sample ID Name | Date | ТРНС | Methyl t- butyl ether | Benzene | Toluene | Ethyl- benzene | Xylenes |
|--------------------|----------|--------|--------------------------|---------|---------|-------------------|---------|
| TMW-5 | 06/26/96 | 30,000 | 830 | 4,000 | 180 | 1,500 | 2,500 |
| | 09/30/96 | 6,900 | < 5.0 | 1,600 | 79 | 130 | 370 |
| | 12/27/96 | 78,000 | <5.0 | 12,000 | 1,900 | 2,900 | 9,700 |
| MW-6 ³ | 03/22/96 | < 50 | <5.0 | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 06/20/96 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| | 12/27/96 | < 50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| TMW-6 ⁴ | 08/17/93 | < 50 | NA | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| | 03/28/94 | < 50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 06/27/94 | <50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 09/16/94 | <50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 03/31/95 | < 50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 06/28/95 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 09/28/95 | <50 | NA | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 12/26/95 | <50 | < 5.0 | < 0.50 | < 0.50 | < 0.50 | <1.5 |
| | 09/24/96 | < 50 | <5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |
| | 09/30/96 | < 50 | <5.0 | < 0.50 | < 0.50 | < 0.50 | < 0.50 |

¹ PARTS PER BILLION.
² NOT ANALYZED.
³ SAME AS TMW-6 (TRIP BLANK).
⁴ TRIP BLANK.



RECORD OF WELL DEVELOPMENT

| | NO.: 247 | | | -96 | WELL NO .: JMW-5 |
|-----------|------------------------------|--------------------|---------------------|--|---|
| PROJECT | NAME: Cr | ed.+ | WELL DIAMETER: 2 24 | | |
| PROJECT | LOCATION:_ | | TOC ELEV: | | |
| DEVELOP | ER: <u>Jam</u> | es B | ender | | LOCK NO.: |
| | PTH (from con | | | | |
| | | | | т воттом?: <u>4es</u> | Miller |
| | | | | ME: 1:50 PM | |
| | E (circle one)?: | | Ě | | |
| IF YES, W | AS PRESSURE | circle | one): POSI | TIVE OR REGATIVE? | 3 |
| | 1 | | | ₹ | Profession of the state of the |
| | VOLUME IN W CASING = 0.16 | | T EATST | CH CASING = 0.65 GAL/FT] | \$0 2 2 2 2 2 2 2 2 2 |
| • , | CASING = 0.10 | | - | L = 3.78L] | [E.] |
| | | | | | |
| itec | | | | | LOCATION MAP |
| | ? | | ~ , | | • |
| DEVELO | PMENT METH | IOD: | | u bamb | |
| FLOATIN | G PRODUCT | | | YES G NO D | |
| | | PRESENT PRESENT | | YES NO LI | |
| • | | | | FIELD MEASUREMENTS | |
| Time | Depth to | Vol | Clarity | Rem | arks |
| | Water (FT) | (Gal) | (NTU'S) | | '. |
| 2,176 | 16.92 AT | 1501 | Modela | | |
| 3:15 | 10.017 | 20 | Mudely | · · | |
| | | | 4 | | |
| | | | ŧ, | 1 Miles | |
| | · | | | | |
| | | | | | · · |
| | | | | | |
| | | | | 1.6 | |
| TOTAL | VOLUME DE | VELOPET |) (GAT): | ZID) (I): W | ATER VOL. IN DRUM: 10 |
| | | _ | Z-Ber | A - 1 | - · |
| SIGNAT | URE: | mes | FRON | - Carrier Contract Co | NEED NEW DRUM?: 100 |
| | - | • | | (I)\ | |

RECORD OF WELL DEVELOPMENT

| PROJECT | NO.: 267 | DA | WELL NO .: MW-Z | | |
|-----------|------------------------|--|---------------------|--------------------------|--|
| PROJECT | NAME: CO | edit | WELL DIAMETER: Z *N | | |
| PROJECT | LOCATION:_ | 2345 | TOC ELEV: | | |
| DEVELOP | ER: | mes T | LOCK NO.: | | |
| WELL DE | PTH (from con | struction | detail): | | |
| WELL DE | PTH (measured | D:19, | <u>ь О</u> sof | T BOTTOM?: YES | |
| DEPTH T | O WATER: | 7,00 | TII | ME: | The state of the s |
| PRESSUR | E (circle one)? | YES | OR NO | | ~mw.z |
| IF YES, V | vas pressuri | E (circle | one): POS | TIVE OR NEGATIVE? | |
| WATER ' | VOLUME IN V | VELI: | 7.0 | 14 | |
| | | | | CH CASING = 0.65 GAL/FT] | |
| - : | CASING = 1.4 | | - | | |
| | | | | | |
| | | | | | LOCATION MAP |
| | | | | and the second | |
| DEVELO | PMENT MET | HOD: | 41009 | Print & Charac | |
| FLOATIN | | PRESEN PRESEN PRESEN | T: | YES NO D | |
| | | | | FIELD MEASUREMENT | rs |
| Time | Depth to Water (FT) | Vol (Gal) | Clarity (NTU'S) | | Remarks |
| 1506 | | 35- | clear | Oder | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | <u> </u> | | |
| TOTAL | VOLUME DE | VELOPE | O (GAL): | 55_(L): | WATER VOL. IN DRUM: NO |
| SIGNAT | URE: Jas | ner | 7-Ben | 55 (L): | NEED NEW DRUM?: ~~ |
| | - | | | | |

| PROJECT | NO.: <u>267</u> | DATE | FR1 12 | 121/96 | • | | | WELL NO.: <u>MU</u> −1 |
|-----------|---|-----------------|------------------|---------------------|--|-----------------|--------------------|--|
| PROJECT | NAME: CRA | DIT | WORL | .D | | | | WELL DIAMETER: 2" |
| PROJECT | LOCATION: 2 | 345 Dakle | E. 14 | H 5 | <u>t_</u> | | | TOC ELEV: |
| SAMPLER | L. Huck | | "C TRA | AHTA | M | | | LOCK NO.: |
| ANALYSE | s: TPHO | \$, | BTE | <u> </u> | | * * | | 180 |
| WELL DE | PTH (from con PATING PR PTH (measured | l): <u>34.3</u> | 34 SOF 9.69,9 | 9.10, 9. T BOTTO | οΜ?: <u>Υ</u> <u> </u> |) . <u>s</u> | | |
| | O WATER: <u>/4</u> | ., | \sim | TE: <u>11:26</u> | , 11:21 | | | MW-1 |
| | E (circle one)?: VAS PRESSURI | | ~ | STTIVE (| OR NEGA | ATIVE? | _ | 3. |
| ir ies, v | AO I REGOOR | 2 (011010 | . One). To | | JK 11201 | | | |
| WATER ! | VOLUME IN V | VFI I · | 4.0 | SAL. | | | | N ² |
| | CASING = 0.16 | | | | SING = | 0.65 GAL/ | FT] | (3) |
| • | CASING = 1.4° | | | SAL = 3 | | | - | and the same of th |
| C | | | ·. · | | - | | | LOCATION MAP |
| | METHOD: | <u>oly</u> | Bay | e v FIEI | LD ME | sal ASUREN | MPLE METI MENTS | vol. (GAL): (L): 46 tod: Poly Bailer |
| | | patin | | | | Clarity | Turbidity | Remarks |
| Time | Depth to Water (FT) | Vol (L) | Temp (Deg. F) | pН | EC | Ciarry | (NTU) | Nonman |
| 11:36 | | 1 | | | | clear | | Mod Gas Odor |
| 155 | | 4-1 | 62.5 | 6.92 | 1270 | | | Strong abor |
| 1156 | | | 6.60 | | 1370 | | Slight | <i>(</i> , |
| 1157 | | 4-3 | 67,0 | 691 | 1370 | | ţſ | 11 |
| 1128 | | 4.4 | | 6.87 | 13Z0 | | 11 | í, |
| 1159 | | 45 | 67.3 | 656 | 1310 | | 1,1 | 21 |
| 1700 | | | | | 1350 | | V1 |) t |
| | | 46 | 47.4 | 6.85 | 1,22,0 | | | , |
| 1705 | | pped | <u> </u> | | | | 20050 | Sampled Well |
| 12:05 | | <u>l</u> | | 1 | <u>L</u> | ļ <u></u> | 144,3 | Dampled Well |

SIGNATURE: 1 & Lauthan

WATER VOL. IN DRUM: FULL
NEED NEW DRUM?:_____

| PROJECT NO.: 267 | _ DATE: | FRI 12 | 127/9 | 6 | | | WELL NO.: MW | -7 |
|--|--|-------------------------------------|-------------------------|--|-----------------|--------------------|--|----------|
| PROJECT NAME: <u>CRE</u> | DIT | WORLD | w . | | | | WELL DIAMETER: 2" | |
| PROJECT LOCATION:_ | 2345 | E. 14t | h St | <u>. </u> | | | TOC ELEV: | |
| SAMPLER: L. Huck | cins | ./ c | Tran | <u>tha</u> m | * | | LOCK NO.: | |
| ANALYSES: TPH | G., | BIE | X | | ** | [| 9 /8,, | |
| WELL DEPTH (from co | nstruction | detail): | | | • | ļ | MW-2 RX | S |
| WELL DEPTH (measure FIDATING PROFIDED FROM PROFIDED FROM PRESSURE (circle one)? IF YES, WAS PRESSUR 33.24-10.74 WATER VOLUME IN VIOLENCH CASING = 0.14 | 15.74 18.74 18.74 E (circle X 0.16 WELL:_ | OR (0) one): POS = 2.8 T] [4-11] | IE: <u>10:</u> SITIVE C | 17, 10. DR NEGA L SING = 0 | 118 | FT] | Blog. | \ / |
| | | ٠. | | • | | | LOCATION MAP | |
| CALCULATED PURGE | | | <u> </u> | | SAI | MPLE METI | | |
| | Bai | 1 R'R" | | | ASUREM | . (| | = |
| Time Depth to Water (FT) | Vol (L) | Temp (Deg. F) | рН | EC | Clarity | Turbidity (NTU) | Remarks | |
| | | 63.7 | 7 07 | 1.19 | ijery Cloudy | | Extremely Odiferous | |
| 10.28 | 77 | | | 1.14 | | - | n | |
| 10:40 | 27 | 65.0 | | | | | | |
| 10:41 | 28 | 65.6 | 6.95 | | | | .: | |
| 10:42 | 29 | 66.2 | | | | | 11 | |
| 10:43 | 30 | | 685 | | | | 1, | 1 |
| 10:44 | 31 | 66.1 | | 1.15 | | | N1. | 1 |
| 10:45 | 32 | 66.Z | 6.80 | 11.11 | | - | | \dashv |
| 10:50 | | | | | Cloud > | 103.4 | Sampled Well sleen | |
| CIGNATURE: | | 1 - | 11. | | | WATE | R VOL. IN DRUM: FUCL EED NEW DRUM?: | |

| | - | 1.61 16 | | | | | | WELL NO.: NVW |
|---|---|---|---|-----------------------------|--------------------------------|---------------------------|--|------------------|
| PROJECT NAME: CRE | DIT | WORL | Þ | | | * | WELL | DIAMETER: 2" |
| PROJECT LOCATION: | 345 | E 14 | th 51 | <u>-</u> | | | | TOC ELEV: |
| SAMPLER: L. HUCK | کمراد اه <i>ب</i> آل <i>ا</i> ح / | C Tr | anth | aw | | , | ٠. | LOCK NO.: |
| ANALYSES: TPH | <u> </u> | BTE | (| | ٠. | | | fr. |
| WELL DEPTH (from con FLOATING PR WELL DEPTH (measured | ODUC | T - 10.94 | 10.98, T BOTT | 0.78 0M?:_ Ύ€ | <u>25</u> _ | | | * |
| DEPTH TO WATER: 11:0 | 4,11:0 | 4;11.04- TIM | /E: <u>/2</u> | :11 | - | | R | - |
| PRESSURE (circle one)? | | - | | | ٠. | | B _ 3 | <u> </u> |
| IF YES, WAS PRESSURI 35.00 (1.04 57 23.76 \(\pi\), 16 = 3 WATER VOLUME IN \(\pi\) [2-INCH CASING = 0.1 | .B3 VELL:_ | 3.8 | 3 <i>G</i> A | <u>L</u> | ATIVE? 0.65 GAL/ | FT] | MW-3 | Not I |
| [6-INCH CASING = 1.4 | 7GAL/F | T] [1 C | SAL = 3. | 78 L] | | | · | 1 |
| | | * . * | • | | | | LO | CATION MAP |
| CALCULATED PURGE | VOL. (| GALI: | , 5 (L) | : 43, | 5_actu | IAL PURGE | VOL. (GAL): | (L):44 |
| V. 22 | • | · · · — | ` | | | | , | • |
| | I_{γ} | Baile | · · · | | SA | MPLE METH | HOD: Poly | Bailer |
| purge method: Po | . /y | Baile | | LD ME | sal AŞUREN | | HOD: Poly | Bailer |
| | , | | FIE | LD ME | AȘUREN | | · | Bailer |
| PURGE METHOD: Po No f/o Time Depth to | ating Vol | prod Temp | FIE | LD ME | AȘUREN | MENTS | · | Bayler emarks |
| PURGE METHOD: Portion No. 1/6 Time Depth to Water (FT) | ating | Prod Temp (Deg. F) | FIEI uc+ pH | EC EC | ASUREN | MENTS Ler Turbidity | · | emarks |
| PURGE METHOD: Po No f/o Time Depth to Water (FT) | vol (L) | Temp (Deg. F) | FIE | EC /25 | ASUREN S+ 6a Clarity | MENTS Ler Turbidity (NTU) | Very Stressen on W | ng Odor-ga |
| PURGE METHOD: Po No flo Time Depth to Water (FT) 12:15 | vol (L) | Temp (Deg. F) 63.0 | FIEI vc+ pH 7,40 | EC 1.05 | ASUREN | MENTS Ler Turbidity (NTU) | Very Streets Street | ng Odar-ga |
| PURGE METHOD: Po No f/o Time Depth to Water (FT) 12:15 12:31 | voi (L) 1 39 | Prod Temp (Deg. F) 62.8 63.0 | FIEI vc+ pH 7.40 7.59 7.40 | EC 1.05 1.06 | Clarity Clear Cloudy | MENTS Ler Turbidity (NTU) | Very Streets on we Very Stra | ng Odor-gai |
| PURGE METHOD: Po No flo Time Depth to Water (FT) 12:15 12:31 12:32 | vol (L) 1 39 40 41 | Temp (Deg. F) 62.8 63.0 64, 2 | FIEI vc+ pH 7.40 7.59 7.40 7.37 | EC 1.05 1.06 1.06 | Clarity Clear Cloudy | MENTS Ler Turbidity (NTU) | Very Streets on Wery Stra | ng Odorga |
| PURGE METHOD: Po No flo Time Depth to Water (FT) 12:15 12:32 12:32 | voi (L) 1 39 40 41 42 | Temp (Deg. F) 62.8 63.0 64.2 64.5 64.7 | FIEI vc+ pH 7.40 7.59 7.40 7.37 7.17 | EC 1.05 1.06 1.05 | Clarity Clear Cloudy | MENTS Ler Turbidity (NTU) | Very Stro Sø-sken en un Very Stra (1 "1 | ng Odorga |
| PURGE METHOD: Po No flo Time Depth to Water (FT) 12:15 12:31 12:32 12:34 | vol (L) 1 39 40 41 42 43 | Temp (Deg. F) 62.8 63.0 64, 2 64, 5 64.7 64.7 | FIEI vc+ pH 7.40 7.59 7.40 7.37 7.17 | EC 1.05 1.06 1.05 1.06 1.05 | Clarity Clear Cloudy | MENTS Ler Turbidity (NTU) | Very Street Stre | ng Odorga |
| PURGE METHOD: Po No flo Time Depth to Water (FT) 12:15 12:32 12:32 | voi (L) 1 39 40 41 42 | Temp (Deg. F) 62.8 63.0 64.2 64.5 64.7 | FIEI vc+ pH 7.40 7.59 7.40 7.37 7.17 | EC 1.05 1.06 1.05 1.06 1.05 | Clarity Clear Cloudy Cloudy | MENTS Ler Turbidity (NTU) | Very Stra So-shen on we Very Stra 11 11 | ng Odor-gai |
| PURGE METHOD: Po No flo Time Depth to Water (FT) 12:15 12:31 12:32 12:34 | vol (L) 1 39 40 41 42 43 | Temp (Deg. F) 62.8 63.0 64, 2 64, 5 64.7 64.7 | FIEI vc+ pH 7.40 7.59 7.40 7.37 7.17 | EC 1.05 1.06 1.05 1.06 1.05 | Clarity Clear Cloudy Cloudy | MENTS Ler Turbidity (NTU) | Very Streets on Wery Stra | ng Odor-ga |

| PROJECT NO.: 267 DATE FRI 12/27/96 | WELL NO. TWU-4 |
|--|---------------------|
| PROJECT NAME: CREDIT WORLD | WELL DIAMETER: 2" |
| PROJECT LOCATION: 2345 E 14+ s+ | TOC ELEV: |
| SAMPLER: L. HUCKINS / C Trantham | LOCK NO.: |
| ANALYSES: TPHG, BTEX | 184 |
| WELL DEPTH (from construction detail): | /7° |
| WELL DEPTH (measured): 33.87 SOFT BOTTOM?: Yes | |
| DEPTH TO WATER: 9.51 TIME: 9:35 | TMW-4 |
| PRESSURE (circle one)?: YES OR NO | ₹9, \ ♥ |
| IF YES, WAS PRESSURE (circle one): POSITIVE OR NEGATIVE? | |
| 24.36 × 0.16 = 3.9 WATER VOLUME IN WELL: 3.9 GAL | Ne Me |
| [2-INCH CASING = 0.16 GAL/FT] [4-INCH CASING = 0.65 GAL/FT] | (c |
| [6-INCH CASING = 1.47GAL/FT] [1 GAL = 3.78L] | Fr. S. |
| 3.9 x 3 (Purge Vol) = 11.7 GAL | LOCATION MAP |
| CALCULATED PURGE VOL. (GAL): 11.7 (L): 44.2 ACTUAL PURGE | vol. (gal): (L): 45 |
| | HOD: Poly Bailer |
| FORGE MIDITION. TOTAL | |

FIELD MEASUREMENTS

| Time | Depth to Water (FT) | Vol (L) | Temp (Deg. F) | рΗ | EC | Clarity | Turbidity (NTU) | | Remarks | |
|-------|------------------------|------------|------------------|------|--------|----------------|--------------------|----------|-----------|---|
| 9:41 | | 1 | 63.9 | 7.16 | 1. Z.5 | Vear | • | No | Odor | <u></u> |
| 10:00 | | 40 | 63.3 | | | mod. cloudy | | n | ,1 | |
| 10:01 | · | 4-1 | 65.2 | | 1.09 | ıl / | | -03 | 1) | #> |
| 10:02 | _ | 4-2 | 65,9 | | 1.10 | 71 | | 11 | į) | • |
| 10:03 | , | 43 | 66.3 | İ | 1 | n | | U | J 1 | |
| 10:04 | | 44 | 66.6 | | 1 | ٠.٠ | | () | 1.7 | |
| 10:0 | | 45 | 66.6 | | | | | 11 | /1 | |
| | · · | | | | | | | <u> </u> | | |
| 10:10 | | | | | | | 7200 | Sav | rolled We | <u>/) </u> |

| SIGNATURE: C | 2 | 1 | ultran | |
|--------------|---|---|--------|--|
| | | | | |

| WATER | VOL. IN | DRUM:_ | FULL |
|-------|---------|--------|------|
| NEE | D NEW I | RUM?:_ | |

| PROJECT | NO.: <u>267</u> | DATE | FRI 12 | 127/96 | | | | WELL NO.: TMW- |
|-----------------------------------|---|-------------------------------------|--|------------------------------------|---------------------------------|-----------|---------------------------------|--|
| PROJECT | NAME: CRE | DIT | WORLD | | | | | WELL DIAMETER: 2" |
| PROJECT | LOCATION:_ | 2345 | E. 14 | 5 st | | | | TOC ELEV: |
| SAMPLER | : L. Huck | ins | / C T | rant | barn | | | LOCK NO.: |
| | s: TPHG | / | • | . , | | | ĺ | <u>ltt</u> |
| | PTH (from con | • | | | | | | (xt) |
| WELL DE FLOI DEPTH T | PTH (measured タイルタ PRO O WATER: 子 | i): <u>20.</u> / DUCT 6 -27 6 | <u>2 </u> | T BOTTO 6-33 ME: <u> 0</u> ; | ом?: <u> Ү</u> | <u>-</u> | | TMW-5 |
| PRESSUR | E (circle one)? | : YES | OR NO | | | | | \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ |
| IF YES, V | VAS PRESSURI | E (circle | one): PO | SITIVE (| OR NEGA | TIVE? | | |
| [2-INCH 6] [6-INCH 6] 8 · 3 | метнор:_ 72 | 6 GAL/F 7 GAL/F VOL. (| T] [4-II T] [1 G | GAL = 3. | 78L] : <u>2</u> 9•9 LD ME | actu | IAL PURGE MPLE METI MENTS | , . 1 |
| Time | Depth to Water (FT) | Vol (L) | Temp (Deg. F) | pН | EC | Clarity | Turbidity (NTU) | Remarks |
| | | 1 | | 7 | 122 | clear | | slight Gas odor |
| 11:0Z | · | 20 | | = | | clear | | 11 11 11 |
| 11.10 | | 20 | 64.7 | | | 11 | - | 11 11 11 |
| 11.11 | | 21 | 66.0 | 7.21 | | | | 1: (1 11 |
| 11:12 | | ZZ | 66,1 | | 1,37 | 11 | | |
| 11:12 | | <u>Z3</u> | 66.2 | 7.20 | 1 | 11 | | 10 10 10 |
| 11:13 | | 24 | 66.1 | | 1.39 | /1 | | k u 'r |
| 11:19 | | 25 | 66.0 | 7.18 | 1.38 | " | | 10 (0 19 |
| 11: (5 | | | | | | <i>t'</i> | 200 Scale 62,4 | Sampled Well |

SIGNATURE: C & Traultar

WATER VOL. IN DRUM: FULL

NEED NEW DRUM?:

HEALTH CARE SERVICES



DAVID J. KEARS, Agency Director

October 3, 1996 StID # 2116

Mr. Stanley Wong 2200 E. 12th St. Oakland CA 94606

Dear Mr. Wong:



ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION (LOP) 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

(510) 567-6700 FAX (510) 337-9335

PARTY OF THE PROPERTY OF i wollagicosusi isiaini vit tatia Vicialiani

Re: Status of Subsurface Investigation at 2345 E. 14th St., Tobal

高大型的建筑 为一定主命性如何。如

Oakland CA 94601, Former Taxi Taxi Plane Include a sector of the and

desired by the state of the sta

This letter serves to recount a recent conversation with Mr. Lee Huckins of Tank Protect Engineering (TPE). Among the items discussed was the continued offsite investigation at the above site. The overexcavation activities has delayed the offsite investigation proposed in TPE's August 4, 1995 workplan. I would like to inform you of the significant items of our conversation as well approve and request implementation of the offsite investigation.

At this time, no further soil excavation is requested. I am aware that soil contamination may still exist in the northern portion of the property, however, offsite investigation should be performed prior to any additional soil excavation.

Monitoring well TMW-5 was being considered for closure since it had been damaged during the excavation activities. It was decided that this well should remain since it is nearest the source of the release and could be used in future remediation.

Your consultant was requested to investigate the various options for free product removal and implement an appropriate one. Several of the monitoring wells have consistently detected free product, therefore, a removal system must be implemented as soon as possible.

In regards to the previously proposed offsite investigation, the proposal to install up to nine offsite borings is accepted by our office. Please be aware that since the August 1995 proposal date, additional boring techniques are commonly in use. Therefore, you are encouraged to use any of the rapid site assessment techniques ie Geoprobe, Hydropunch etc. In addition, you should begin your offsite investigation radially outward from the former tank pit area. The extreme borings on E. 14th St. and Miller Ave. should be done only if necessary. Based on the boring locations, permits will be required to gain drilling access. Please initiate the permit procedures as soon as possible. You should also be aware that offsite monitoring wells Mr. Stanley Wong StID # 2116 2345 E. 14th St. October 3, 1996 Page 2.

will be required to determine the extent of the groundwater plume. You may want to consider installing permanent wells immediately after the initial investigation so this could be done under the same permit.

Please include a status of the above items in your future quarterly monitoring reports.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Barney M Cham

Hazardous Materials Specialist

C: Mr. L. Huckins, TPE, 2821 Whipple Rd., Union City, CA 94587 B. Chan, files

ssi2345

SAMPLE HANDLING PROCEDURES

Soil and groundwater samples will be packaged carefully to avoid breakage or contamination and will be delivered to the laboratory in an iced-cooler. The following sample packaging requirements will be followed.

- . Sample bottle/sleeve lids will not be mixed. All sample lids will stay with the original containers and have custody seals affixed to them.
- Samples will be secured in coolers to maintain custody, control temperature and prevent breakage during transportation to the laboratory.
- . A chain-of-custody form will be completed for all samples and accompany the sample cooler to the laboratory.
- . Ice, blue ice or dry ice (dry ice will be used for preserving soil samples collected for the Alameda County Water District) will be used to cool samples during transport to the laboratory.
- Water samples will be cooled with crushed ice. In the Alameda County Water District, water samples will be buried in the crushed ice with a thermometer, and the laboratory will be requested to record thermometer temperature at the time of receipt.
- . Each sample will be identified by affixing a pressure sensitive, gummed label or standardized tag on the container(s). This label will contain the site identification, sample identification number, date and time of sample collection and the collector's initials.
- . Soil samples collected in brass tubes will be preserved by covering the ends with Teflon tape and capping with plastic end-caps. The tubes will

be labeled, sealed in quart size bags and placed in an iced-cooler for transport to the laboratory.

All groundwater sample containers will be precleaned and will be obtained from a State Department of Health Services certified analytical laboratory.

Sample Control/Chain-of-Custody: All field personnel will refer to this workplan to verify the methods to be employed during sample collection. All sample gathering activities will be recorded in the site file; all sample transfers will be documented in the chain-of-custody; samples will be identified with labels; all sample bottles will be custody-sealed. All information is to be recorded in waterproof ink. All TPE field personnel are personally responsible for sample collection and the care and custody of collected samples until the samples are transferred or properly dispatched.

The custody record will be completed by the field technician or professional who has been designated by the TPE project manager as being responsible for sample shipment to the appropriate laboratory. The custody record will include, among other things, the following information: site identification, name of person collecting the samples, date and time samples were collected, type of sampling conducted (composite/grab), location of sampling station, number and type of containers used and signature of the TPE person relinquishing samples to a non-TPE person with the date and time of transfer noted. The relinquishing individual will also put all the specific shipping data on the custody record.

Records will be maintained by a designated TPE field employee for each sample: site identification, sampling location, station number, date, time, sampler's name, designation of the sample as a grab or composite, notation of the type of sample (e.g., groundwater, soil boring, etc.), preservatives used, onsite measurement data and other observations or remarks.

GROUNDWATER MONITORING WELL SAMPLING PROCEDURES

Groundwater monitoring wells will not be sampled until at least 24 to 72 hours (according to local regulatory guidelines) after well development. Groundwater samples will be obtained using a bladder pump, clear Teflon bailer or dedicated polyethylene bailer. Prior to collecting samples, the sampling equipment will be thoroughly decontaminated to prevent introduction of contaminants into the well and to avoid cross-contamination. Monitoring wells will be sampled after 3 to 10 wetted casing volumes of groundwater have been evacuated and pH, electrical conductivity and temperature have stabilized as measured with a Hydac Digital Tester. If the well is emptied before 3 to 10 well volumes are removed, the sample will be taken when the water level in the well recovers to 80% or more of its initial water level.

When a water sample is collected, turbidity of the water will be measured and recorded with a digital turbidimeter. Degree of turbidity will be measured and recorded in nephelometric turbidity units (NTU).

TPE will also measure the thickness of any floating product in the monitoring wells using an interface probe or clear Teflon or polyethylene bailer. The floating product will be measured after well development but prior to the collection of groundwater samples. If floating product is present in the well, TPE will recommend to the client that product removal be commenced immediately and reported to the appropriate regulatory agency.

Unless specifically waived or changed by the local, prevailing regulatory agency, water samples will be handled and preserved according to the latest United States Environmental Protection Agency methods as described in the Federal Register (Volume 44, No. 233, Page 69544, Table II) for the type of analysis to be performed.

Development and/or purge water will be stored on site in labeled containers. The disposal of the containers and development and/or purge water is the responsibility of the client.

MEASUREMENTS

<u>Purged Water Parameter</u>: During purging, discharged water will be measured for the following parameters.

| <u>Parameter</u> | Units of Measurement |
|----------------------------|----------------------|
| pН | None |
| Electrical Conductivity | Micromhos |
| Temperature | Degrees F or C |
| Depth to Water | Feet/Hundredths |
| Volume of Water Discharged | Gallons |
| Turbidity | NTU |

<u>Documentation:</u> All parameter measurements will be documented in writing on TPE development logs.

QUALITY ASSURANCE AND QUALITY CONTROL PROCEDURES

The overall objectives of the field sampling program include generation of reliable data that will support development of a remedial action plan. Sample quality will be checked by the use of proper sampling, handling and testing methods. Additional sample quality control methods may include the use of background samples, equipment rinsate samples and trip and field blanks. Chain-of-custody forms, use of a qualified laboratory, acceptable detection limits and proper sample preservation and holding times also provide assurance of accurate analytical data.

TPE will follow a quality assurance and quality control (QA/QC) program in the field to ensure that all samples collected and field measurements taken are representative of actual field and environmental conditions and that data obtained are accurate and reproducible. These activities and laboratory QA/QC procedures are described below.

<u>Field Samples</u>: Additional samples may be taken in the field to evaluate both sampling and analytical methods. Three basic categories of QA/QC samples that may be collected are trip blanks, field blanks and duplicate samples.

Trip blanks are a check for cross-contamination during sample collection, shipment, and laboratory analysis. They are water samples that remain with the collected samples during transportation and are analyzed along with the field samples to check for residual contamination. Analytically confirmed organic-free water will be used for organic parameters and deionized water for metal parameters. Blanks will be prepared by the laboratory supplying the sample containers. The blanks will be numbered, packaged and sealed in the same manner as the other samples. One trip blank will be used for sets greater than 20 samples. The trip blank is not to be opened by either the sample collectors or the handlers.

The field blank is a water sample that is taken into the field and is opened and exposed at the sampling point to detect contamination from air exposure. The water

sample is poured into appropriate containers to simulate actual sampling conditions. Contamination due to air exposure can vary considerably from site to site.

The laboratory will not be informed about the presence of trip and field blanks, and false identifying numbers will be put on the labels. Full documentation of these collection and decoy procedures will be made in the site log book.

Duplicate samples are identical sample pairs (collected in the same place and at the same time), placed in identical containers. For soils, adjacent sample liners will be analyzed. For the purpose of data reporting, one is arbitrarily designated the sample, and the other is designated as a duplicate sample. Both sets of results are reported to give an indication of the precision of sampling and analytical methods.

The laboratory's precision will be assessed without the laboratory's knowledge by labeling one of the duplicates with false identifying information. Data quality will be evaluated on the basis of the duplicate results.

Laboratory QA/QC: Execution of a strict QA/QC program is an essential ingredient in high-quality analytical results. By using accredited laboratory techniques and analytical procedures, estimates of the experimental values can be very close to the actual value of the environmental sample. The experimental value is monitored for its precision and accuracy by performing QC tests designed to measure the amount of random and systematic errors and to signal when correction of these errors is needed.

These methods The QA/QC program describes methods for performing QC tests. standards (both blanks, calibration standards, check involve analyzing method Environmental Protection Agency-certified United independent States and the Internal OC also requires standards), duplicates, replicates and sample spikes. adherence to written methods, procedural documentation and the observance of good laboratory practices.

408 7351554

Entech Analytical Labs, Inc.

CA ELAP# 1369

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587-1233 Attn: Lee Huckins

| Date: | 1/2/97 |
|----------------|-----------|
| Date Received: | 12/30/96 |
| Date Analyzed: | 1/1/97 |
| Project: | 267122796 |
| Sampled By: | Client |

Certified Analytical Report

Water Sample Analysis:

| Test | MW-1 | MW-2 | MW-3 | MW-4 | Units | PQL | EPA Method# |
|---------------|----------|----------|----------|----------|----------|-------------------|----------------|
| Sample Matrix | Water | Water | Water | Water | | | |
| Sample Date | 12/27/96 | 12/27/96 | 12/27/96 | 12/27/96 | | | |
| Sample Time | 12:05 | 10:50 | 12:40 | 10:10 | | | |
| Lab# | C18172 | C18173 | C18174 | C18175 | | | |
| DF-Gas/BTEX | 200 | 200 | 20 | 1 | | | |
| TPH-Gas | 24,000 | 29,000 | 5,800 | ND | μg/liter | 50.0 μg/l | 8015M |
| MTBE | ND | ND | 240 | ND | μg/liter | 5.0 μg/l | 8020 |
| Benzene | 5,900 | 2,100 | 1,700 | ND | μg/liter | 0.5 μ g/ l | 8020 |
| Toluene | 440 | ND | 28 | ND | μg/liter | 0.5 µg/l | 8020 |
| Ethyl Benzene | 310 | 1,200 | ND | ND | μg/liter | 0.5 μα/1 | 8020 |
| Xylenes | 740 | 1,800 | 42 | ND | μg/liter | 0.5 μg/l | 8020 |

1. DLR=DF x PQL

2. Analysis performed by Entech Analytical Labs, Inc. (CAELAP #1369)

Michael N. Golden, Lab Director

DF=Dilution Factor DLR=Detection Reporting Limit PQL=Practical Quantitation Limit ND=None Detected at or above DLR

Environmental Analysis Since 1983

Entech Analytical Labs, Inc.

CA ELAP# 1369

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

408 7351554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587-1233 Attn: Lee Huckins

| Date: | 1/2/97 |
|----------------|----------------|
| Date Received: | 12/30/96 |
| Date Analyzed: | 12/30-12/31/96 |
| Project: | 267122796 |
| Sampled By: | Client |

Certified Analytical Report

Water Sample Analysis:

| Test | MW-5 | MW-6 | Units | PQL | EPA Method# |
|---------------|----------|----------|-------------------|-------------------|----------------|
| Sample Matrix | Water | Water | | | |
| Sample Date | 12/27/96 | 12/27/96 | | | |
| Sample Time | 11:15 | 12:40 | | | |
| Lab# | C18176 | C18177 | | | |
| DF-Gas/BTEX | 400 | 1 | | | |
| TPH-Gas | 78,000 | ND | ug/liter | 50.0 µg/l | 8015M |
| MTBE | ND | ND | μg/liter | 5.0 µg/l | 8020 |
| Benzene | 12,000 | ND | μ g/ liter | 0.5 μg/l | 8020 |
| Toluene | 1,900 | ND | μg/liter | 0.5 μ g/ l | 8020 |
| Ethyl Benzene | 2,900 | ND | ug/liter | 0.5 µg/l | 8020 |
| Xylenes | 9,700 | ND | μg/liter | 0.5 µg/l | 8020 |

DLR=DF x PQL

2. Analysis performed by Entech Analytical Labs, Inc. (CAELAP #1369)

Michael N. Golden, Lab Director

DF=Dilution Factor **DLR=Detection Reporting Limit** POL-Practical Quantitation Limit ND-None Detected at or above DLR

Environmental Analysis Since 1983

(510) 429-8088 = (800) 523-8088 = Eax (510) 429-8089

LAB: <u>ENTECH ANALYTICAL LABS</u>, IN

TURNAROUND: 48 hr

P.O. #: 1371

CHAIN OF CUSTODY

PAGE 1 OF 1

| N . 121 UNIPE | HUC! | TIMS | CITY, | CA 945 | Inan Tham 187 (415) 429-8088 | (1) TYPE OF CON- TAINER | 13 to 12 to | | | | | | RUSH |
|------------------|--------|--------------|--------|--------|--|--|---|----------------|----------|-----------|------|------|--|
| ID WO. | 1996 | TIME | SOIL | WATER | PERILLING DOCESTON | 2-40 m | Ľ | / \$7 | <u>~</u> | <u> </u> | 7 | 7 | 3/2/72 |
| w~1 | 12/07 | 12:05 | | Ϋ́ | · | VOA S | X | X | | 1 | 1 | 1 | 0,21/0 |
| | , , | | | × | | (4 | K | K | | | 1 | | C18173 |
| 1-2 | T - 1 | | | メ | | 11 | X | X | \neg | A | H | n | MTBB C18174 |
| <u>u ~3</u> | | . 1 | | × | Sample ID 15 Thow-4 | li. | X | X | | | T | T | C18175 |
| <u>u - 4</u> | | | 1 | × | Somple 50 15 TMW-5 | - 11 | Ϋ́ | X | | | 1 | 7 | C18176 |
| w^5 | 12/27 | u:15 | | | | 1 | ť | V | | # | 十 | 十 | C18177 |
| w-6 | 12/27 | 12:40 | | ×. | (78) | | ╁ | H | - | \forall | + | 十 | |
| | | | | | · | | ╂╴ | | | + | † | ╁ | |
| | ļ | | | · | 1 | | 十 | Н | | + | + | 十 | |
| inquish | | | | | 1 // 1 | ne ist yet | stur | - | le Li | nqui | ehe: | d by | by : (Signature) Date / Time Received by : (Signature) |
| L L delupal | nad by | (Sign | atura) | 12/3 | 191135 OW to Time Rhoutwed | by : (5196) | tur | -3 R | ol i | aqule | shed | t by | by : (Signature) Date / Time Received by : (Signature) |
| inquish | ad hv | (Sign | ature) | Da | to / Time Received for [Signature] | Laberatory by | / | † | Da | to / | Tie | | Remarks |

DATE:____

1