2037

Alameda County

MAY 0 5 2003

Environmental Health

May 1, 2003

Mr. Amir Gholami Alameda County Health Care Services Agency 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577

Re:

Site Summary and Groundwater Monitoring Report

2345 International Boulevard (formerly E. 14th Street)

Oakland, California

Fuel Leak Case No. RO0000327



Dear Mr. Gholami:

On behalf of Mr.'s Aaron and Stanley Wong, Cambria Environmental Technology, Inc. (Cambria) has prepared this *Site Summary, Conduit Study and Monitoring Report* for the site referenced above. As requested by the Alameda County Health Care Services Agency, this report incorporates fourth quarter 2002 monitoring results.

We look forward to working with you on this project. If you have any questions or comments, please contact me at (510) 420-3307 or Mr. Bob Clark-Riddell at (510) 420-3303.

Sincerely,

Cambria Environmental Technology, Inc.

Mary C. Holland-Ford

Project Geologist

cc: Mr. Stanley Wong, 2200 East 12th Street, Oakland, California 94606

H:\Sb-2004 (UST Fund)\Stanley Wong (Credit Auto)\Correspondence\Transmittal letter May 2003.doc

Cambria Environmental Technology, Inc.

5900 Hollis Street Suite A Emeryville, CA 94608 Tel (510) 420-0700 Fax (510) 420-9170

■C A M B R I A

SITE SUMMARY, CONDUIT STUDY AND MONITORING REPORT

Credit World Auto Sales 2345 International Boulevard Oakland, California 94601 Cambria Project No. 513-1000

April 30, 2003

Prepared for:

Mr. Stanley Wong 2200 East 12th Street Oakland, California 94606

Prepared by:

Cambria Environmental Technology, Inc. 5900 Hollis Street, Suite A Emeryville, California 94608

Mary C. Holland-Ford

Project Geologist

Bob Clark-Riddell, P.E.

Principal Engineer

Cambria Environmental Technology, Inc.

5900 Hollis Street Suite A Emeryville, CA 94608 Tel (510) 420-0700 Fax (510) 420-9170

SITE SUMMARY, CONDUIT STUDY AND MONITORING REPORT Credit World Auto Sales 2345 International Boulevard Oakland, California

TABLE OF CONTENTS



1.0 INTRODUCTION	L
2.0 SITE BACKGROUND	I
2.1 SITE USE, LOCATION AND DESCRIPTION 2.2 SITE INVESTIGATION 2.3 SITE REMEDIATION 2.3.1 Soil Excavation 2.3.2 SPH Removal 2.3.3 Bio-Remediation System 2.3.4 Vacuum Truck Operations	2 3 4 4 5
3.0 RECENT ACTIVITIES	;
3.1 GEOLOGIC CROSS SECTIONS	7
4.0 SUBSURFACE CONDITIONS	ì
4.1 GEOLOGY)
5.0 RISK EVALUATION 13	į
5.1 SOIL 14 5.2 GROUNDWATER 15	
6.0 CONCLUSIONS16	į
7.0 RECOMMENDED ACTIVITIES 18	į
7.1 ADDITIONAL INVESTIGATION, WELL REPLACEMENT, AND WELL SURVEYING 18 7.2 FEASIBILITY TESTING 18 7.3 INTERIM REMEDIAL ACTIVITIES 18 7.4 QUARTERLY MONITORING AND SAMPLING 19	

FIGURES

Figure 1 - Vicinity Map

Figure 2 – Site Plan

Figure 3 – Geologic Cross Section A-A'

Figure 4 – Geologic Cross Section B-B'

Figure 5 - Utility and Conduit Map

Figure 6 - Groundwater Elevation Contour Map

Figure 7 – Separate Phase Hydrocarbon Thickness

Figure 8 – Historical TPHg Concentrations in Soil

Figure 9 - Historical Benzene Concentrations in Soil

Figure 10 - Historical Benzene Concentrations in Groundwater



TABLES

Table 1 - Groundwater Flow Direction and Gradient

Table 2 – Soil Analytical Data

Table 3 – Groundwater Analytical Data

Table 4 – Well Completion Data

Table 5 – Summary of SPH Removal

APPENDIX

Appendix A - Background Information

Appendix B - City of Oakland Subsurface Utility Map

Appendix C - City of Oakland Bench Mark Data from Renner Surveying & Engineering

SITE SUMMARY, CONDUIT STUDY AND MONITORING REPORT

Credit World Auto Sales 2345 International Boulevard Oakland, California Cambria Project No. 513-1000

April 30, 2003



1.0 INTRODUCTION

Cambria Environmental Technology, Inc. (Cambria) is pleased to submit this *Site Summary, Conduit Study and Monitoring Report* (Report) for the above-referenced site on behalf of Mr. Stanley Wong. As requested by the Alameda County Health Care Services Agency (ACHCSA) on September 9, 2002, this report summarizes historical site activities and subsurface conditions, and presents our conclusions and recommendations for the site. This report also describes recent activities conducted by Cambria to facilitate evaluation of the site conditions. The recent activities conducted by Cambria include preparation of geologic cross-sections, a conduit study, groundwater monitoring, and free product removal. As verbally requested by new regulatory case worker Amir Gholami, this report discusses hydrocarbon trends, plume stability, methyl tert-butyl ether, and chlorinated hydrocarbons, and includes a risk evaluation. Mr. Gholami requested comparison of contaminant concentrations to risk-based screening levels (RBSLs) established by the San Francisco Bay Regional Water Quality Control Board (RWQCB).

2.0 SITE BACKGROUND

Site background information is presented below. Boring logs, analytical results and additional information from previous investigations is presented in Appendix A.

2.1 Site Use, Location and Description

The site located is located in a commercial/residential area at the southwest corner of the intersection of International Boulevard (formerly East 14th Street) and Miller Avenue in Oakland, California (Figure 1). The site is at an elevation of approximately 23 feet above mean sea level, based on City of Oakland datum. The site is currently operated by Credit World Auto Sales, a

used car dealership. One building occupies the site, and the building is used as an office and automotive service bay. The remainder of the site is a paved parking area (Figure 2).

In August 1988, SCS removed four underground storage tanks (USTs) along with two dispenser islands and associated piping from the site (Figure 2). Soil samples from the fuel tank showed concentration of total petroleum hydrocarbons as gasoline (TPHg) and benzene. Soil samples from the used oil excavation area showed impact of total petroleum hydrocarbons as diesel (TPHd) and total oil and gas (TOG).



2.2 Site Investigation

Several phases of soil and groundwater assessments have been conducted at the site since 1988. Soil and groundwater analytical results from these investigations is summarized in Tables 2 and 3, respectively.

November 1988: California Environmental Consultants (CEC) advanced three soil borings to assess the extent hydrocarbon impact in the soil and groundwater in the vicinity of the former UST locations. Borings B-1 and B-2 were advanced adjacent to the former fuel USTs. TPHg and benzene, toluene ethylbenzene, and xylenes (BTEX) were detected in the soil and groundwater samples from both borings. Boring B-3, located near the former used oil UST location, showed concentrations of TOG and BTEX in soil and groundwater samples.

May to August 1991: Earth Systems Environmental advanced five onsite borings (TH-1 through TH-5) and installed three groundwater monitoring wells (MW-1 through MW-3) at the site to further delineate the onsite hydrocarbon impact. Borings B-1 and B-2 were advanced adjacent to the former fuel USTs. TPHg and BTEX were detected in the soil and groundwater. Soil and groundwater samples from boring B-3, located near the former used oil UST location, showed concentrations of TOG and BTEX. Groundwater was encountered 19 feet below grade surface (bgs) during this assessment.

July 1993: Tank Protect Engineering (Tank Protect) installed two monitoring wells (TMW-4 and TMW-5) at the site. No petroleum hydrocarbons were detected in soil samples from borings for wells TMW-4 and TMW-5. Separate-phase hydrocarbons (SPH) were observed in wells MW-1, MW-2 and TMW-5 and was removed by hand bailing. Groundwater flow direction beneath the

site ranged from north-northeast to west-southwest with an average gradient of 0.029 feet/feet during this assessment. Tank Protect concluded that confined and unconfined groundwater is present beneath the site, and that wells MW-2 and MW-3 monitor an upper, unconfined water bearing zone while MW-1, TMW-4, and TMW-5 monitor both the upper unconfined zone and a lower, confined water bearing zone. Tank Protect concluded that sands logged in well MW-2 are characteristic of a buried stream channel, trending north-south beneath and across the site.



April 1997 to May 1997: Tank Protect advanced five borings (SB-1 through SB-5) to assess the offsite hydrocarbon impact. TPHg was detected in soil and water samples from boring SB-5 and benzene was detected in boring SB-2. Benzene and methyl tert-butyl ether (MTBE) were detected in groundwater from boring SB-5. No petroleum hydrocarbons or MTBE were detected in soil and groundwater samples from borings SB-1, SB-3, and SB-4. Tank Protect concluded that northern and southern extent of the hydrocarbon plume has been defined.

May 2001: Sequoia Environmental (Sequoia) advanced seven onsite borings (SB-1 through SB-7), converting boring SB-7 into monitoring well MW-6. No MTBE was detected in all soil samples. SPH was detected in wells MW-1, MW-2, MW-3 and TMW-5, and 4.5 gallons of SPH was removed by hand bailing from the monitoring wells. MTBE was not detected in all groundwater samples Sequoia reports groundwater flow to the west-southwest during this assessment.

Groundwater Monitoring: Groundwater monitoring of site wells was conducted regularly between August 1991 and December 1999, and was conducted once in 2001 and once again in 2002. Groundwater analytical data and groundwater elevation data is summarized in Table 3. Results of the groundwater monitoring are described later in this report.

2.3 Site Remediation

In August 1988, SCS removed four USTs, two dispensers and associated piping from the site (Figure 2). Several remedial activities have been conducted since UST removal.

2.3.1 Soil Excavation

December 1994 through October 1996: Tank Protect conducted multiple phases of soil excavation and verification sampling at the site. As shown on Figure 2, the excavation was conducted around the UST area in the center of the site, and the depth of the excavation ranged

from 12 feet to 19 feet bgs. A total of 1,550 cubic yards (cy) of soil was excavated. Approximately 1,019 cy of the excavated soil was stockpiled on site, remediated via aeration and hydrogen peroxide treatment, and placed back into the excavation cavity with the approval of the ACHCSA. Approximately 531 cy of soil was removed from the site and disposed of at a licensed facility. The final verification samples detected a TPHg maximum concentration of 110 milligrams per kilogram (mg/kg) in sidewall samples, and 66 mg/kg in excavation bottom samples. Additional information on excavation activities and confirmation sampling results is presented in Appendix A.



2.3.2 SPH Removal

Due to the presence of SPH in site wells, Tank Protect installed a free product recovery system and bailed site wells during groundwater monitoring events. Groundwater monitoring and sampling results and SPH thickness information is presented in Table 3.

The free product removal system first consisted of a selective oil skimmer, down-well mounted bladder product pump, and two product storage drums. Tank Protect reported that trace quantities of free product were removed during between July 27 and August 18, 1995. To enhance free product recovery, Tank Protect installed a continuously operating free product recovery system in August 1997. Tank Protect reported removing 3 to 5 gallons of SPH between August 20, 1997 and January 14, 1998. SPH removal by manual bailing by Cambria is described below and summarized in Table 5.

2.3.3 Bio-Remediation System

A bio-remediation system was installed and operated at the site by Sequoia between March 2002 and July 2002. According to Sequoia, this system pumped water from four wells (MW-1, MW-2, MW-3 and TMW-5) into four "bioreactor" tanks containing microbes, nutrients, and hydrogen peroxide. The treated, microbe-rich water was then injected into the subsurface through an infiltration well (MW-1). Monthly project updates submitted by Sequoia do not provide detailed information about system layout, startup, or operation. Between March 2002 and July 2002, four bio-treatment events were reported where treated, microbe-rich water was injected into well MW-1. The system was shut down and removed in July 2002. Groundwater samples collected by Sequoia on June 20, 2002 after the initiation of bio-remediation activities were generally

consistent with historical groundwater hydrocarbon concentration trends. Insufficient data is available to assess the effectiveness of the bio-remediation system.

2.3.4 Vacuum Truck Operations

Vacuum truck operations were conducted by Sequoia on July 20, 2002 as an interim remedial measure. Vacuum truck operations were performed to remove the SPH found in wells MW-2, MW-3 and TMW-5. Details are not available describing the length of vacuum truck operations or amount of SPH and groundwater recovered.



3.0 RECENT ACTIVITIES

Cambria prepared geologic cross-sections, conducted a conduit study, monitored site groundwater wells, and bailed SPH from site wells. These activities were required by ACHCSA and are described below.

3.1 Geologic Cross Sections

To illustrate the site's stratigraphic and hydrogeologic characteristics, Cambria constructed geologic cross sections A-A' and B-B' from boring logs (see Figures 3 and 4). The geologic cross sections illustrate that the stratigraphy consists primarily of low to moderately permeable clays and silts with interbedded higher permeability sand and gravel layers to the total depth explored of 36 feet bgs. Two water-bearing units were encountered, and confined and unconfined conditions may be present at the site. Soil analytical results and historic high and low groundwater depths are shown on the cross sections. The site geology and hydrogeology are described further in Section 4.

3.2 Conduit Study

Cambria performed a conduit study to evaluate the potential for subsurface utility conduits to serve as preferential pathways for hydrocarbon migration. To obtain information regarding buried utilities in the site vicinity, Cambria contacted the City of Oakland, Pacific Bell, Pacific Gas & Electric (PG&E), and East Bay Municipal Utilities District (EBMUD). The location, diameter and approximate depth of subsurface conduits beneath and adjacent the site are shown on Figure 5. A



subsurface utility map from the City of Oakland Department of Engineering is included in Appendix B. Based on the City of Oakland map and telephone conversations with Pacific Bell, PG&E and EBMUD, the depth to nearby utilities ranges from approximately 3 to 18 feet bgs. A telephone line is located at approximately 3.5 feet bgs along International Blvd. A sanitary sewer crosses the site (presumably shallower than 5 feet bgs) and enters a 10-inch diameter sanitary sewer beneath the middle of International Boulevard, which is located at approximately 8 to 9 feet bgs (approximate 15 feet flow line elevation). A water line crosses the site (presumably shallower than 5 feet bgs) and enters a 36-inch diameter water main near the other side of International Blvd located at 5 feet bgs. A 24-inch diameter storm drain, also on the other side of International Blvd, is located approximately 3 feet bgs (top of conduit) to 5 feet bgs (bottom of conduit; approximate 18 feet flow line elevation). A sanitary sewer (presumably 6- or 8-inch diameter) is located near the other side of Miller Avenue at approximately 8 to 9 feet bgs (approximate 14 feet flow line elevation). A 75-inch diameter storm drain is located beneath Miller Avenue at approximately 10 to 16 feet bgs, with an approximate 7 feet flow line elevation as it passes the site. Overhead electrical service runs along Miller Avenue.

To compare sewer and utility depths to groundwater depth, Cambria reviewed existing surveying information. Because surveying datum information was not provided in reviewed reports, Cambria contacted the Renner Survey Company of Burlingame, California, who researched old records and determined that the site wells were surveyed to the City of Oakland bench mark datum (See Appendix C).

As described below, site groundwater has historically fluctuated primarily between approximately 9 and 17 feet bgs, and has occasionally risen to approximately 6 feet bgs at some locations. This information suggests that onsite utility conduits and the shallow offsite storm drain beneath International Boulevard, which are shallower than 6 feet bgs, have not historically intersected site groundwater. The two offsite sanitary sewer conduits, located at approximately 8 to 9 feet bgs, do not likely intersect groundwater during its typical fluctuation between 9 to 17 feet bgs, but likely do intersect groundwater during the occasional groundwater rise to approximately 6 feet bgs. Although groundwater could occasionally intersect these sanitary sewer conduits, the prevalent clay in the shallow site subsurface would limit the potential for hydrocarbons to migrate to nearby conduits. Furthermore, groundwater analytical results from offsite borings SB-1, SB-3 and SB-4, located between the site and the sanitary sewers, suggests hydrocarbons have not migrated offsite

toward the sanitary sewers. As described below, no hydrocarbons were detected in soil or groundwater from these borings.

Our primary concern is the 75-inch storm drain beneath Miller Avenue located approximately 60 feet from site well SB-7/MW-6, which had SPH detected (0.04 feet) for the first time during monitoring in December 2002. This 75-inch diameter storm drain, located at approximately 16 feet bgs, apparently intersects groundwater almost year round and could be located within the upper sandy water-bearing unit. However, groundwater analytical results from offsite boring SB-1 (installed in 1997 and located between the site and storm drain) suggest that hydrocarbons have not migrated offsite toward the offsite storm drain (no hydrocarbons were detected in soil or groundwater from boring SB-1).



3.3 Groundwater Monitoring

Cambria conducted gauging and monitoring of site wells on October 21, 2002 and December 27, 2002. During the October 2002 gauging event, groundwater monitoring wells MW-1, MW-3 and MW-6 were not accessible. SPH thickness was observed in wells MW-2 and TMW-5 at 0.24 feet and 0.10 feet, respectively. SPH was not observed in well TMW-4. Depth to groundwater in site wells ranged from 13.6 to 16.98 feet bgs. During the December 27, 2002 monitoring event, SPH was observed in all site wells and groundwater sample collection was not performed due to the presence of SPH. Groundwater monitoring data is summarized on Table 3. A groundwater elevation contour map for December 27, 2002 is presented as Figure 6.

To more accurately estimate the groundwater flow direction at the site, Cambria has estimated the top of casing elevation for wells MW-3 and TMW-4. Site records indicate that other site wells were surveyed to the Oakland datum in June 2001, while wells MW-3 and TMW-4 were not resurveyed at that time. The resurveying in June 2001 by the Renner Survey Company effectively lowered the groundwater elevation of the other site wells (MW-1, MW-2, and TMW-5) by an average of 2.80 feet. Cambria assumes that the wells were previously surveyed to NGVD 29 datum, which is approximately 3 feet higher than the City of Oakland datum. To estimate the top of casing (TOC) elevation for wells MW-3 and TMW-4 with respect to City of Oakland datum, Cambria subtracted 3 feet from the prior TOC elevation from August 1993. Figure 6 and Table 3 present the revised groundwater elevation based on the Oakland datum.

3.4 SPH Removal Activities

During the December 2002 monitoring event, SPH was observed in all site wells. Cambria technicians removed approximately 13.5 liters (21.78 pounds) of SPH from site wells by hand bailing on December 27, 2002. To estimate prior SPH removal by hand bailing and/or well purging by Tank Protect, Cambria multiplied the tabulated SPH thickness (feet) by the well casing area (i. e., 2-inch diameter casing = 0.60 liters per foot) for each purging/bailing event. Cambria estimates that approximately 69.6 pounds of SPH were bailed and/or purged by others. In addition, Tank Protect reported that a continuous free product recovery system removed approximately 3 to 5 gallons (18.3 to 30.5 pounds) between August 1997 and January 1998. As summarized on Table 5, Cambria estimates that 121.88 pounds of petroleum hydrocarbons have been removed from site wells to date.



4.0 SUBSURFACE CONDITIONS

The site geology, hydrogeology, chemicals of concern (COC), and hydrocarbon distribution in soil and groundwater are described below.

4.1 Geology

The site is located within the Coast Range geomorphic province of California. In general, the Coast Range province consists of Jurassic eugeosynclinal basement rocks and Cretaceous and Cenozoic sedimentary and volcanic rocks that have been faulted and folded with a northwest-southeast trend. The site lies within the Bay Plains Basin. Sediments beneath the site consist of coalescing alluvial deposits from the Diablo Range to the east known as the San Leandro Cone. According to the USGS Professional paper 943, the site is located on quaternary age alluvial deposits consisting of medium-grained, unconsolidated moderately sorted permeable fine sand, silt, and clayey silt with thin beds of coarse sand.

The site geology consists primarily of low to moderately permeability clays and silts with interbedded higher permeability sand and gravel layers to the total depth explored of 36 feet bgs. Aggregate base material (fill) under site asphalt at approximately one foot bgs is underlain by dry gray to black or brown clay ranging to total depths of $7\frac{1}{2}$ to 12 feet bgs, with damp gray to green clay to ranging from approximately 17 to 23 feet bgs. This shallow clay is underlain by a

discontinuous water-bearing unit from approximately 17 to 27 feet bgs, which consists of silty to clayey sand grading to brown clayey sand. The silty/clayey sand unit is shallowest near wells MW-2 and SB-7/MW-6. This water-bearing unit is underlain by gravelly clay to a depth of 32½ feet bgs. A deeper relatively permeable sand and gravel layer is present in boring for wells MW-1 and TMW-4 at depths of 31.5 to 35 feet bgs and 30.5 to 32.5 feet, respectively. It cannot be determined if the lower and upper higher permeability sand layers shown in the geologic cross sections are interconnected or separated by the lower permeability clay layers. Geologic cross-sections are shown on Figures 3 and 4. The upper and lower sand units may be discontinuous, and may be confined or unconfined.



The boring logs presented in Appendix A illustrate that wells MW-1 and MW-3 appear to be screened across two water-bearing units. Well TMW-4, screened from 14 to 34 feet bgs, may also be screened across the two water-bearing units; the well screens the lower water-bearing unit at 30 to 32.5 feet bgs and may encounter thin sand stringer units at approximately 15 feet bgs (Figure 4). Similarly, well MW-2 is screened from 15 to 35 feet bgs, and may encounter thin sand stringer units near the lower water-bearing unit at approximately 32 to 36 feet bgs (Figure 3). Based on historic high and low water levels shown on Figures 3 and 4, all site well screens are often fully submerged by site groundwater.

4.2 Hydrogeology

Major groundwater bearing materials beneath the Bay Plain Basin occur at depths ranging from 50 feet to more than 1,000 feet bgs. Groundwater from these aquifers is presently used largely for irrigation and industrial purposes. Regionally, groundwater flow is generally to from the Diablo Range toward San Francisco Bay. The nearest surface water body to the site is Brooklyn Basin Tidal Canal located ½ mile to the west.

Since 1991, the depth to groundwater beneath the site has ranged from approximately 6.5 to 17 feet bgs. However, the groundwater depth has typically fluctuated between approximately 10 to 15 feet bgs. The historical high and low groundwater depths are shown on Figures 3 and 4. Historically, the groundwater flow direction has varied significantly, generally flowing either northwestward or radially outward from the center of the site. Cambria and previous site consultants have inferred a radial direction of groundwater flow based on groundwater elevation data from site wells dating back to August 1993. A radial groundwater flow direction could be



explained by water mounding within the UST cavity (from August 1993 to September 1994) or within the UST excavation (after December 1994 when excavation commenced). It is also possible that infiltrating rainwater enters the former UST excavation area through the asphalt cap or via the onsite water and sanitary sewer conduits presumably located in the unsaturated zone. The radial groundwater flow direction could also be explained by the apparent screening of some site wells across two water-bearing units. The well screen intervals (particularly well MW-1) could also contribute to groundwater mounding beneath the site since the lower water-bearing unit may be confined. However, as described in Section 4.1, the actual groundwater flow direction may be different if based on wells with appropriate screening. Wells are screened for up to 20 feet in length, are screened across two water-bearing units, and are often fully submerged by site groundwater. The well screen intervals do not allow proper evaluation of SPH thickness in the subsurface. Well completion data is summarized on Table 4. The estimated groundwater flow direction from past monitoring events is summarized on Table 1.

4.3 Hydrocarbon Distribution

The COCs at this site are petroleum hydrocarbons as described below. The extent of hydrocarbons in the site subsurface has been assessed by several investigations since 1988. One investigation in 1997 evaluated the offsite extent of hydrocarbons using soil borings. Described below are the COCs and the distribution of hydrocarbons in soil and groundwater.

4.3.1 Chemicals Of Concern

During site investigation activities, only petroleum hydrocarbons and MTBE have been detected in analyzed soil and groundwater. The detected petroleum hydrocarbons are predominately in the gasoline, oil and grease ranges. Oil and grease has been detected primarily near the former used oil UST.

MTBE has been detected in groundwater from one boring grab sample [12 micrograms per liter (µg/L)] and sporadically in select wells by Environmental Protection Agency (EPA) Method 8020. MTBE detection have *not* been confirmed by EPA Method 8260 analysis. No MTBE was detected in site soil. This information suggests that MTBE may not be a COC at this site, and that groundwater analysis by EPA Method 8260 is merited for any detected MTBE by EPA Method 8020.

During removal of the former fuel USTs and the used oil UST (and during an investigation in 1988), select soil and groundwater samples were analyzed for volatile organic compounds (VOCs) by EPA Method 8260 and for halogenated VOCs (HVOCs) by EPA Method 8010. No HVOCs were detected in analyzed samples. Only BTEX compounds detected in samples analyzed for VOCs by EPA Method 8260. MTBE, VOC and HVOC data is presented in Tables 2 and 3. For purposes of the hydrocarbon distribution presented below, petroleum hydrocarbons are considered the COCs for the site.



4.3.2 Soil

Petroleum hydrocarbons were detected in 21 of the 25 borings with analyzed soil samples. Soil analytical results are summarized in Table 2. The extent of TPHg and benzene in soil is shown on Figures 8 and 9, respectively. The vertical extent of TPHg is shown on geologic cross-sections on Figures 3 and 4.

Soil analytical results indicate that petroleum hydrocarbons are primarily located in the capillary fringe and saturated zone at depths ranging from approximately 10 to 25 feet bgs. Shallower unsaturated soil has presumably been remediated by site excavation activities. Limited shallow soil data is available, and the maximum TPHg concentration detected in shallow (<10 feet bgs) was 2.4 mg/kg at 5.5 feet bgs in TMW-5, which was overexcavated around and adjacent the former USTs.

TPHg concentrations in soil are highest north and northwest of former UST excavation area (see Figure 8). The maximum detected TPHg concentrations in subsurface (≤ 10 feet bgs) soil are 4,320 mg/kg TPHg in MW-2 at 10 feet bgs, 1,800 mg/kg in SB-3 at 15 feet bgs, and 450 mg/kg in TH-4 at 19.5 feet bgs. Benzene concentrations in soil are also highest north and northwest of the former UST area, although elevated benzene concentrations are also detected southwest of the former USTs. The maximum benzene concentration detected was 61 mg/kg at 15 feet bgs in B-5, but this sample location from the 1988 UST removal may have been overexcavated. The maximum TOG concentration detected was 1,600 mg/kg in TH-4 at 19.5 feet bgs. This sample was near the former used oil UST location in the northwestern portion of the site.

The lateral extent of hydrocarbons in soil appears to be adequately defined by onsite and offsite borings in all directions, except for benzene in the west and southwest directions. No BTEX

1997. TPHg was detected in only one of the four offsite borings, at a concentration of 91 mg/kg (SB-5). However, the three offsite borings with no TPHg or BTEX detected were apparently sampled in the saturated zone, at depths of approximately 22 and 27 feet bgs. The one boring sampled near the presumed capillary fringe (SB-5 sampled at 11.5 to 12 feet bgs) had the TPHg detection of 91/ mg/kg. While *soil* sampling may not have adequately characterized capillary fringe soil, *groundwater* analytical results from these four offsite borings suggests that petroleum hydrocarbons have only migrated offsite in the northwest direction (near SB-5). No hydrocarbons were detected in grab groundwater north or south of the site, based on results from SB-1, SB-3 and SB-4 described below.

compounds were detected by the four offsite borings (SB-1, SB-3, SB-4, and SB-5) installed in




4.3.3 Groundwater

Groundwater monitoring data and analytical results indicate that SPH is present across the site in all monitoring wells, the SPH plume is not stable, elevated benzene is present onsite, and the hydrocarbon extent is not fully characterized. Groundwater analytical results and monitoring data are summarized in Table 3. The current and historic maximum SPH thickness observed in the site wells is presented in Figure 7. The historical extent of benzene concentration in groundwater is shown on Figure 10.

Cambria observed SPH in all site wells during the most recent monitoring event on December 27, 2002. As shown on Figure 7, the SPH thickness on this date ranged from 0.04 feet (MW-6) to 0.43 feet (MW-2). Most importantly, SPH was detected for the first time in wells TMW-4 and MW-6 during this monitoring event. The maximum SPH thickness reported is site wells has been 7.44 feet in MW-2 (March 1995), 4.36 feet in well MW-1 (June 2001), 0.46 feet in MW-3 (March 1995), and 0.10 feet in TMW-5 (December 2002) (see Figure 7). This indicates that the greatest SPH thickness has been observed north of the former USTs (MW-2) and west-southwest of the former USTs (MW-1 and MW-3). In general, SPH thickness increases when the groundwater elevation lowers, as especially observed in wells MW-1 and MW-3. The SPH appears to be primarily located in the upper sand unit, and is likely present in historic smear zone comprised of clayey soil and possibly thin interbedded sand units. In well MW-2, the SPH thickness is typically highest when the groundwater elevation rises, possibly due to the rising water table entering the upper sand unit where elevated TPHg was detected in soil and SPH is likely present. The submerged well screen is likely effecting the SPH thickness observed in well MW-2. The detection of SPH for the first time in perimeter site wells TMW-4 and MW-6 could be

explained by SPH migration caused by groundwater mounding and the inferred radial groundwater flow direction. The SPH detection could also be explained by historic high groundwater elevation for wells TMW-4 and MW-6 during the recent monitoring.

Groundwater analytical results suggest that dissolved hydrocarbons are present across most of the site, with the highest concentrations near the former UST area. The historical benzene concentrations detected in site groundwater are shown on Figure 9. The highest benzene concentrations (>10,000 µg/L) have been detected in 26,000 µg/L in well TMW-5 (in the former UST area), 17,000 µg/L in boring B-2 immediately adjacent TMW-5, and 14,000 µg/L in boring B-1 just southwest of the former UST area. Elevated benzene concentrations (>1,000 µg/L) have been detected southwest of the former UST area (MW-1, MW-3, MW-6 and SB-5), and north of the former UST (MW-2).



5.0 RISK EVALUATION

To evaluate the potential risk from residual hydrocarbons, Cambria conducted a risk evaluation using the RWQCB guidance document Application of Risk Based Screening Levels and Decision Making to Sites With Impacted Soil and Groundwater (RWQCB 2001). To conduct the risk evaluation, Cambria compared residual contaminant concentration data to Tier 1 Risk Based Screening Levels (RBSLs) ('final RBSLs') established by the RWQCB. For constituents whose residual concentrations exceed the Tier 1 RBSLs, Cambria conducted a Tier 2 risk evaluation in



accordance with the RWQCB guidance document. The Tier 2 risk evaluation involves modifying the Tier 1 RBSLs based on site-specific considerations. This risk evaluation can assist with the establishment of target cleanup levels for residual contaminants in soil and groundwater. This risk evaluation does not consider or apply to SPH present in the site subsurface.

5.1 Soil



Soil analytical results and select RBSLs for the COCs are summarized on Table 2. Table 2 shows the Tier 1 *final* RBSLs for both residential and commercial categories where site groundwater is not considered a current or potential drinking water resource. Cambria included the residential RBSLs due to the presence of residences north of the site; the building southwest of the site is commercial. Table 2 also shows the 'Tier 2' RBSLs for indoor air impacts, for residential and commercial categories. Cambria presents the RBSLs for surface soil (\leq 3 meters bgs). The RBSLs for *subsurface* soil (\geq 3 meters bgs) are identical or similar to the surface soil RBSLs and would be applicable to most soil analytical results which are \geq 3 meters bgs.

Petroleum hydrocarbon concentrations in soil exceeding the Tier 1 RWQCB RBSLs for surface soil have been detected in several borings at the site. As shown on Table 2, concentrations of TPHg, TOG, benzene, ethylbenzene and xylenes in some borings exceed the commercial Tier 1 final RBSLs. Figures 8 and 9 present the historical TPHg and benzene concentrations in soil, respectively, with concentrations exceeding the commercial final RBSL shown in bold. TPHg and benzene concentrations exceeding the Tier 1 final RBSLs are located nearby the former UST area, with one benzene RBSL exceedance further from the former UST area, located along the southwest property boundary at 20 feet bgs in SB-5 (2001).

To conduct a 'Tier 2' evaluation, Cambria considered modifying Tier 1 RBSLs based on site-specific considerations. All the final RBSLs (except for benzene) are derived for the risks associated with petroleum hydrocarbons leaching from soil into groundwater. Since the impacted soil is primarily in the capillary fringe/saturated zone, and since groundwater data is present, Cambria assumes that soil leaching is not a regulatory concern. With the site fully paved and no nearby ecological receptors, Cambria assumes that the RBSL protective of indoor air impact would be the appropriate RBSL for the site. Again, the indoor air impact RBSLs for residential and commercial site use are summarized on Table 2. If indoor air impact is considered the only potential completed pathway for exposure to residual compounds, only select benzene

concentrations exceed the indoor air impact RBSL (commercial use). Figure 9 presents benzene concentrations exceeding the indoor air impact RBSL, which is the same as the Tier 1 RBSL for benzene. These exceedences are located near the former USTs and along the southwest property boundary at 20 feet bgs. No RBSLs for indoor air impacts are established for TPH compounds in soil.

5.2 Groundwater



Groundwater analytical results and select RBSLs for the COCs are summarized on Table 3. Table 3 shows the Tier 1 *final* RBSLs for sites where groundwater is not considered a current or potential drinking water resource. Table 3 also shows the 'Tier 2' RBSLs for indoor air impacts. The groundwater RBSLs are not differentiated into residential and commercial categories.

Petroleum hydrocarbon concentrations in groundwater exceeding the Tier 1 RWQCB RBSLs for surface soil have been detected in several borings/wells at the site. As shown on Table 3, concentrations of TPHg, TOG, benzene, toluene, ethylbenzene, xylenes, and MTBE in some groundwater samples exceed the commercial Tier 1 final RBSLs.


To conduct a 'Tier 2' evaluation, Cambria considered modifying Tier 1 RBSLs based on site-specific considerations. The site Tier 1 final RBSLs are derived for the risks associated with protection of aquatic life. With the site fully paved and no nearby ecological receptors, Cambria assumes that the RBSL protective of indoor air impact would be the appropriate RBSL for the site. Again, the indoor air impact RBSLs are summarized on Table 3. No RBSLs for indoor air impacts are established for TPH compounds in groundwater.

If indoor air impact is considered the only potential completed pathway for exposure to residual compounds, only select benzene concentrations exceed the indoor air impact RBSL. Because site surface soil consists primarily of clay, Cambria used the benzene RBSL associated with fine-grained soil (5,800 µg/L) rather than coarse-grained soil (84 µg/L). Figure 10 presents benzene concentrations exceeding the indoor air impact RBSL. The benzene RBSL exceedences are located primarily near the former UST area (TMW-5, B-1 and B-2). While RBSL exceedences were also detected along the southwest property boundary in a grab sample from boring SB-5, groundwater samples from nearby monitoring well MW-3 are likely more representative of dissolved benzene concentrations near the southwest boundary of the site.

6.0 CONCLUSIONS

Cambria concludes the following based on our review of the site conditions:

1. Separate-phase hydrocarbons and elevated concentrations of petroleum hydrocarbons are present in site soil and groundwater. These petroleum hydrocarbons are primarily TPHg and BTEX compounds, and TOG near the former used oil UST location. Although MTBE has been detected sporadically in groundwater, MTBE has not been confirmed by EPA Method 8260 analysis. If MTBE is confirmed in the subsurface, the MTBE would likely be from another source since the USTs were removed in 1988 prior to common MTBE use.



- 3. Separate-phase hydrocarbons (i.e., free product) have been detected in all six site wells and are likely primarily located in the capillary fringe area and submerged in the upper sandy unit at the site. SPH thickness is typically greatest when groundwater levels decrease and expose the SPH, although SPH thickness is greatest in well MW-2 when the groundwater level rises into the upper sand unit. The recent detection of SPH in perimeter site wells TMW-4 and MW-6 for the first time suggests that the SPH plume in not stable.
- 4. Petroleum hydrocarbons in soil are primarily located in the capillary fringe and saturated zone at depths ranging from approximately 10 to 25 feet bgs, with the highest concentrations detected north and northwest of former UST excavation area and elevated benzene concentrations southwest of the former USTs. Shallower unsaturated soil has presumably been remediated by site excavation activities. The lateral extent of hydrocarbons in soil



appears to be adequately defined by onsite and offsite borings in all directions, except for benzene in the west and southwest directions.

- 5. Hydrocarbons are present in groundwater across most of the site, with the highest concentrations near the former UST area. The horizontal extent of the dissolved hydrocarbon plume has been adequately characterized in all directions except the southwest and eastern directions. With the recent detection of SPH in TMW-4, the hydrocarbon plume is not adequately characterized in the eastern direction. With benzene and other hydrocarbons detected in each of the five borings/wells along the southwestern property boundary, the extent of dissolved hydrocarbons is not adequately characterized in the southwest direction. Offsite assessment in this direction has been constrained by the large building on the adjacent property.
- 6. Results of the conduit study indicate that dissolved hydrocarbons and SPH are migrating toward the 75-inch diameter storm drain beneath Miller Avenue located approximately 60 feet from site well MW-6. This storm drain, located at approximately 13 to 16 feet bgs, apparently intersects groundwater year-round, is fully submerged by groundwater periodically, and could be located within the upper sandy water-bearing unit. Groundwater analytical results from offsite boring SB-1, located between the site and the storm drain, suggest that hydrocarbons have not migrated offsite toward the offsite storm drain.
- 7. Our risk evaluation indicates while TPH, TOG and BTEX concentrations in soil and groundwater exceed Tier 1 RBSLs, only benzene exceeds the proposed 'Tier 2' RBSLs based on site-specific considerations. The proposed Tier 2 RBSL for benzene is the RBSL for indoor air impact. The Tier 2 RBSL exceedences for benzene are located nearby the former UST area and along the southwest property boundary at 20 feet bgs.
- 8. Although SPH and elevated petroleum hydrocarbons are present in the site subsurface, the migration and exposure to residual hydrocarbons can be managed. The current site capping by the building foundation and site pavement helps manages the risk. Site remediation would abate residual hydrocarbons and further reduce the risk associated with the subsurface hydrocarbons.



7.0 RECOMMENDED ACTIVITIES

Based on our conclusions for the site, Cambria offers the recommendations presented below.

7.1 Additional Investigation, Well Replacement, and Well Surveying

Cambria recommends preparation of a workplan to further define the extent of hydrocarbons at the site. The proposed investigation would assess offsite soil and groundwater south and east of the site, beyond the recent observation of free product in site wells TMW-4 and MW-6. The investigation would further evaluate conditions between the site and the 75-inch diameter storm drain beneath Miller Avenue, which could act as a conduit for hydrocarbon migration. The investigation would include continuous coring to further evaluate soil hydrogeology and the depth of SPH. The workplan would also evaluate the existing well screen intervals and propose abandonment and replacement of wells. Finally, the investigation workplan would propose well installation for feasibility testing (recommended below). In conjunction with the additional investigation, Cambria recommends surveying of wells MW-3 and TMW-4 (and any new wells) to the City of Oakland datum. The other site wells have been surveyed to the Oakland datum, while wells MW-3 and MW-4 are presumably surveyed to NGVD 29 datum, which is approximately 3 feet higher than the Oakland datum.

7.2 Feasibility Testing

To facilitate evaluation of appropriate remedial alternatives, Cambria recommends conducting a feasibility test. The feasibility test would most likely use dual-phase extraction techniques to assess hydrocarbon recovery rates, vapor flow rates, groundwater extraction rates, SPH recovery rates and thickness in the formation, and radius of influence. Results of the feasibility testing would be used in preparation of a corrective action plan for site remediation. Cambria recommends preparation of a feasibility test plan in conjunction with the investigation workplan.

7.3 Interim Remedial Activities

Because of the unstable SPH plume and the continued presence of SPH in site wells, Cambria recommends implementing hydrocarbon recovery using passive skimmers and hand bailing. During the recent monitoring event Cambria hand bailed approximately 13.5 liters of SPH from

site wells. To enhance SPH recovery, Cambria recommends installing passive SPH skimmers in wells MW-1 and MW-2, which have historically contained the highest SPH thickness at the site. The passive skimmers consist of an active buoy assembly designed to remove free product to a sheen. The buoy allows free product but not water to collect in the 2 liter (0.53 gallon) collection canister. The buoy system is equally effective with water table fluctuations as great as 24 inches.



Cambria proposes hand bailing of the remaining site wells that contain SPH. Cambria proposes monitoring/emptying of the skimmers and hand bailing on a monthly basis during the winter and spring months, and on a semi-monthly (every two weeks) during the dry summer and fall months. The monitoring, emptying and bailing schedule would be modified as dictated by the actual SPH recovery rates in the individual wells. SPH recovery may be discontinued upon implementation of a more permanent corrective action.

7.4 Quarterly Monitoring and Sampling

Cambria recommends continued quarterly groundwater monitoring to further evaluate SPH thickness, groundwater flow direction, and plume stability. All groundwater wells will be gauged and inspected for SPH on a quarterly basis. Groundwater samples will be collected from site wells without SPH and analyzed for TPHg by modified EPA Method 8015, and BTEX and MTBE by EPA Method 8020, with confirmation analysis for detectable MTBE by EPA Method 8260. Quarterly groundwater monitoring and SPH removal reports will be prepared.

H\Sb-2004 (UST Fund)\Stanley Wong (Credit Auto)\Summary Report\Site Summary Report.doc

Table 1. Groundwater Flow Direction and Gradient
Credit World Auto Sales
2345 International Boulevard, Oakland, California

Date Measured	Hydraulic Gradient	Flow Direction
04-16-92	0.021	Northwest
06-11-93	0.026	Northwest
08-17-93	0.029	Radial
03-31-94	0.050	Radial
06-27-94	0.020	Radial
09-16-94	0.0179-0.0411	Radial
03-31-95	0.075	Radial
06-28-95	0.025-0.053	Radial
09-28-95	0.025	Northwest
12-26-95	0.048	Radial
03-22-96	0.034-0.132	Radial
06-20-96	0.016	Northwest
09-30-96	0.019	Northwest
12-27-96	0.024-0.029	North-Northwest
03-07-97	0.020-0.035	North-Northwest
06-28-97	0.027-0.04	Northwest
09-18-97	0.02-0.026	Radial
12-30-97	0.025-0.030	North-Northwest
03-25-98	0.021-0.033	Radial
06-29-98	0.013-0.019	Northwest
10-02-98	0.011-0.019	Northwest
12-08-98	0.23	Northwest
03-26-99	0.01	North-Northwest
06-15-99	0.01	Northwest
09-15-99	0.011	North-Northwest
12-28-99	0.02	North-Northwest

Table 2. Soil Analytical Data - Credit World Auto Sales
2345 International Boulevard, Oakland, California

Sample	Date	Depth	TPHg	TPHd	TOG	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	VOCs	HVOCs
Location	Sampled	(feet)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)
Residential Final RI Risk Driver	BSL - non drink	ing water	400 soil leaching	500 soil leaching	500 soil leaching	0.180 indoor air	8.4 soil leaching	24 soil leaching	1.0 soil leaching	1.0 soil leaching	N/A	N/A
Commercial Final R	RSL - non drin	king water	400	500	500	0.39	8.4	24	1.0	1.0	N/A	N/A
Risk Driver			soil leaching		soil leaching	indoor air	soil leaching	soil leaching	soil leaching	soil leaching		
Residential RBSL - in	ndoor air impac	:t	NE	NE	NE	0.180	30	76	210	3.4 (68)	N/A	N/A
Commercial RBSL - i		•	NE	NE	NE	0,390	89	220	210	12 (290)	N/A	N/A
COMMENCIAL) (EDC)	тисот ан тра	.,	NE	IND.	INE.	0.330	- 67	220	210	11 (150)	1417.	1011
SCS Engineers (U	IST Removal	Sampling										
B-1	8/25/1988	15	360			0.3	2.2	3.4	31			
B-2	8/25/1988	15	1,500			3.0	6.4	2.5	160			
B-3	8/25/1988	15	130			0.17	0.4	1.3	10			
B-4	8/25/1988		150			0.8	1.9	8.7	86			
B-5	8/25/1988		790			61	1.3	4.8	30	_	-	
B-6	8/25/1988		1,300			1.5	4.7	9.6	75	••		
B-7	8/25/1988			110	570	(<5.0)	(<5.0)	(5.0)	(48)		ND*	
B-8	8/25/1988			65	780	(<5.0)	(<5.0)	(5.0)	(12)	_	ND*	
California Enviro	nmental Cons	sultants										
B-1	10/3/1988	15	3.4			0.31	< 0.1	<0.1	0.14			
B-2	10/3/1988	15	83			1.6	1.1	1.8	9.6			
B-3	10/3/1988	15			88	(0.36)	(0.65)	(0.47)	(0.85)		ND*	ND
Earth Systems En												
TH-1	8/21/1991	15-15.5	2,775			1.235	1.060	1.625	5.280		-	
TH-2	8/21/1991	10-10.5	360			<0.005	<0.005	<0.005	0.770			
TH-2	8/21/1991	29.5-30	50			<0.005	<0,005	<0.005	<0.005			••
TH-3 TH-3	8/22/1991 8/22/1991	10-10.5	10	-	60	<0.005	<0.005	<0.005	<0.005			
TH-4	8/22/1991	18.5-19 10-10.5	10 25		20 40	<0.005 <0.005	<0.005 <0,005	<0.005 <0.005	<0.005 0.175			
TH-4	8/22/1991	19.5-20	450		1,600	<0.005	<0.005	<0.005	<0.005			
TH-5	8/22/1991	10-10.5	10		1,000	<0.005	<0.005	<0.005	<0.005			
TH-5	8/22/1991	18-18.5	<5.0			<0.005	<0.005	<0.005	<0.005			
MW-1	5/22/1991	10-10.5	150			0.460	0.365	0.305	0.960			
MW-1	5/22/1991	15-15.5	255			1.505	4.255	4.015	4.270			
MW-2	8/21/1991	10-10.5	4,320			7.275	6.620	3.470	13.815			
MW-2	8/21/1991	15-15.5	160			<0.005	<0.005	<0.005	<0.005			
MW-3	8/22/1991	10-10.5	50		90	<0.005	<0.005	<0.005	< 0.005			
MW-3	8/22/1991	15-15.5	25		40	<0.005	<0.005	< 0.005	<0.005			
Tank Protect Eng	ineering											
TMW-4	7/22/1993	5.5-6	< 0.500			<0.0050	< 0.0050	< 0.0050	<0.015			••
TMW-4	7/22/1993	10.5-11	<0.500			< 0.0050	<0.0050	< 0.0050	<0.015			
TMW-4	7/22/1993	15.5-16	0.940	**		< 0.0050	<0.0050	<0.0050	<0.015		••	-
TMW-5	7/23/1993	5.5-6	2.4			0.026	<0.0050	<0.0050	0.053			
TMW-5	7/23/1993	10.5-11	14	••		0.900	<0.0050	1.6	<0.140		-	
TMW-5	7/23/1993	15.5-16	16			0.840	<0.0050	0.690	1.3		••	
SB-1	4/01/1007	26 5 22	~1.0			~0.00s	<0.005	<0.005	<0.005	<0.05		
SB-1 SB-2	4/21/1997	26.5-27	<1.0 3.7			<0,005	<0.005	<0.005 0.042	<0.005 <0.005	<0.05 <0.05		
SB-2 SB-3	4/21/1997	16.5-17	3.7 <1.0			0.012	0.0071	<0.005	<0.005	<0.05 <0.05		-
SB-4	5/1/1997 5/1/1997	21.5-22 21.5-22	<1.0 <1.0			<0.005 <0.005	<0.005 <0.005	<0.005 <0.005	<0.005	<0.05	-	
SB-5	5/1/1997	21.5-22 11.5-12	<1.0 91			<0.003 <0.005	<0.005	<0.005	<0.005	<0.05		
J1-3	VI 1/11/1	11.5-12	7.1			-0,003	.0.003	-0.000	-5.000	-5.02		

Table 2. Soil Analytical Data - Credit World Auto Sales
2345 International Boulevard, Oakland, California

Sample Location	Date Sampled	Depth (feet)	TPHg (mg/kg)	TPHd (mg/kg)	TOG (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethylbenzene (mg/kg)	Xylenes (mg/kg)	MTBE (mg/kg)	VOCs (mg/kg)	HVOC: (mg/kg)
Residential Final RE Risk Driver	BSL - non drink	ing water	400 soil leaching	500 soil leaching	500 soil leaching	0.180 indoor air	8.4 soil leaching	24 soil leaching	1.0 soil leaching	1.0 soil leaching	N/A	N/A
Commercial Final R Risk Driver	BSL - non drin	king water	400 soil leaching	500 soil leaching	500 soil leaching	0.39 indoor air	8.4 soil leaching	24 soil leaching	1.0 soil leaching	1.0 soil leaching	N/A	N/A
Residential RBSL - in	idoor air impac	t	NE	NE	NE	0.180	30	76	210	3.4 (68)	N/A	N/A
Commercial RBSL - i	ndoor air impa	et	NE	NE	NE	0.390	89	220	210	12 (290)	N/A	N/A
Sequoia Environn	<u>iental</u>											
SB-1	5/22/2001	10	240			< 0.04	0.19	0.19	0.45	< 0.20		••
SB-1	5/22/2001	15	3.0			< 0.005	0.005	0.009	0.013	<0.05		
SB-2	5/22/2001	10	89			< 0.005	<0.005	0.033	0.25	< 0.10		
SB-2	5/22/2001	15	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05	-	-
SB-2	5/22/2001	20	<1.0			< 0.005	< 0.005	< 0.005	<0.005	< 0.05	-	-
SB-3	5/22/2001	10	300			<0.01	<0.01	0.76	1.2	< 0.20		
SB-3	5/22/2001	15	1,800			3.3	5.5	48	53	<2.0		**
SB-3	5/22/2001	20	8.5			0.009	0.023	0.10	0.12	< 0.05	-	_
SB-4	5/22/2001	10	<1.0			< 0.005	< 0.005	< 0.005	<0.005	< 0.05	_	_
SB-4	5/22/2001	15	230		**	0.23	< 0.005	1.5	1.1	< 0.10		
SB-4	5/22/2001	20	<1.0			< 0.005	< 0.005	< 0.005	< 0.005	< 0.05		
SB-5	5/22/2001	15	25			0.035	<0.005	0.10	0.11	< 0.05	_	_
SB-5	5/22/2001	20	1.9			0.62	< 0.005	< 0.005	<0.005	< 0.05		
SB-6	5/22/2001	10	<1.0		••	< 0.005	< 0.005	< 0.005	<0.005	< 0.05		
SB-7 (MW-6)	5/22/2001	10	18			< 0.005	< 0.005	0.056	0.11	< 0.05		
SB-7 (MW-6)	5/22/2001	15	68			0.28	0.25	0.36	0.35	< 0.10	_	_
SB-7 (MW-6)	5/22/2001	20	<1.0			< 0.005	< 0.005	< 0.005	<0.005	< 0.05	_	

Abbreviations and Notes:

1,300 = concentrations exceeding commercial final RBSLs shown in bold.

TPHg = Total petroleum hydrocarbons as gasoline

Benzene, Toluene, Ethylbenzene, Xylenes by EPA Method 8020, and by 8260 if in parenthesis

MTBE methyl tert butyl ether by EPA Method 8020

VOCs = volatile organic compounds by EPA Method 8260

ND = not detected above laboratory detection limits

ND* = not detected with the exception of reported concentrations for benzene, toluene, ethylbenzene and xylenes

HVOCs = halogenated volatile organic compounds by EPA Method 8010

mg/kg = Milligrams per kilogram

<n = Below detection limit of n mg/kg

-- = Not analyzed

Residential RBSLs = Table B-1 - Risk Based Screening Level Components for Surface Soil (Potentially Impacted Groundwater is not a Current or Potential Source

of Drinking Water) for commercial/industrial reuse for established by the SFBRWQCB, Interim Final December 2001. (The risk driver is also shown). MTBE RBSL for coarse soil (fine soil).

Commercial RBSLs = Table B-2 - Risk Based Screening Level Components for Surface Soil (Potentially Impacted Groundwater is not a Current or Potential Source

of Drinking Water) for commercial/industrial reuse for established by the SFBRWQCB, Interim Final December 2001. (The risk driver is also shown). MTBE RBSL for coarse soil (fine soil).

RBSLs for indoor air = Tables B-1 and B-2 from SFBRWQCB above, Interim Final December 2001

Table 3. Groundwater Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Sample ID/	Date	Casing	Depth to	Depth to	SPH	GW					· · · · · · · · · · · · · · · · · · ·			
Well ID	Sampled	Elevation	GW	SPH	Thickness	Elevation	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	TOG	VOCs
		(feet)	(feet bgs)	(feet bgs)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
Final RBSL -	- Potential Dri	nking Water S	ource				100	1,0	40	30	13	5.0	640	N/A
	Risk l	Driver					human toxicity	aquatic life	aquatic life	aquatic life	aquatic life	taste & odor	aquatic life	
Final RBSL -	- Not a Potenti	al Drinking W	ater Source				500	46	130	290	13	1,800	640	N/A
	Risk l	Driver					aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	
RBSL - Indo	or Air Impact						NE	84 (5800)	76000 (530000)	170,000	150000 (160000)	50000(4.9E+05)	NE	N/A
California l	Environment	al Consultar	ıts											
B-1-W	10/3/1988	_	_		_	_	67,000	14,000	2,400	2,500	9,100			
B-2-W	10/3/1988						110,000	17,000	2,600	3,000	12,000		_	**
B-3-W	10/3/1988	_	_	_				(490)	(160)	(770)	(1,300)	-	290,000	ND*
Tank Prote	ct Engineeri	10												
SB-IW	4/21/1997	<u></u>					<50	<0.50	<0.50	<0.50	<0.50	<5.0	_	
SB-2W	4/21/1997						6,100	870	35	17	28	<5.0		
SB-3W	5/1/1997						<50	<0.50	<0.50	<0,50	< 0.50	<5.0	_	
SB-4W	5/1/1997	_				••	<50	<0.50	< 0.50	<0.50	<0.50	<5.0		
SB-5W	5/1/1997	~		••			890	5.4	<0.50	1.4	<0.50	12		-
Sequoia En	vironmental													
SB-1	5/22/2001	-	-		••		11,000	8.1	23	81	7.1	<20		••
SB-2	5/22/2001					-	1,200	< 0.5	3.5	5,5	<0.5	<5.0		
SB-3	5/22/2001	_	_		_		53,000	790	110	2,000	2,000	<200		
SB-4	5/22/2001				_	_	170,000	420	<45	1,500	800	<200		-
SB-5	5/22/2001						27,000	8,400	99	230	120	<500		
SB-6	5/22/2001		-		_	_	50	<0.5	<0.5	<0.5	<0.5	<5.0	-	
Monitoring	Well Sampli													
MW-1	12/30/1997	27.33 ^b	10.96	10,79	0.17	16.51	61,000	4,300	1,800	1,600	6,900	1,400		
MW-1	3/24/1998	27.33	9.33		0.00	00.81	24,000	1,000	1,000	1,300	4,300	2,000		
MW-1	6/29/1998	27.33	12.20	-	0.00	15.13	130,000	3,800	370	1,200	4,200	3,300		
MW-1	10/2/1998	27,33	13.46		0.00	13.87	22,000	66	21	26	140	<0.50		
MW-I	12/10/1998	27,33	10.49	_	0.00	16.84	32,000	4,600	970	1,700	4,900	<250	_	
MW-I	3/26/1999	27,33	9.44		0.00	17.89	230,000	370	290	280	720	<0.50		
MW-I	6/11/1999	27.33	12.56	12.55	0.01	14.78	180,000	210	170	220	400	<0.50	-	
MW-1	9/15/1999	27.33	14,85	13.85	1.00	13,28	21,000	3,800	280	590	2,200	<250		
MW-1	12/28/1999	27.33	14.50	13.18	1.32	13.89	27,000	48	36	46	83	<0,5		_
MW-1	6/13/2001	24.37°	15.83	11.47	4.36	12.03								
MW-1	12/27/2002	24.37	8.31	8.15	0.16	16.19	_	_						

Table 3. Groundwater Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Sample ID/ Well ID	Date Sampled	Casing Elevation	Depth to GW	Depth to SPH	SPH Thickness	GW Elevation	ТРНд	Benzene	Toluene	Ethylbenzene	Xylenes	МТВЕ	TOG	VOCs
		(feet)	(feet bgs)	(feet bgs)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
Final RBSL -	Potential Dri	rking Water S	Source				100	1.0	40	30	13	5.0	640	N/A
	Risk I)river					human toxicity	aquatic life	aquatic life	aquatic life	aquatic life	taste & odor	aquatic life	
Final RBSL -	Not a Potenti	al Drinking V	Vater Source				500	46	130	290	13	1,800	640	N/A
	Risk I	Oriver					aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	
RBSL - Indoo	r Air Impact						NE	84 (5800)	76000 (530000)	170,000	150000 (160000)	50000(4.9E+05)	NE	N/A
MW-2	8/23/1991	98.585	13.77	-	0,00	84.82	10,000	<5	<5	<5	<5	_		
MW-2	4/16/1992	25,92 ^b	15.38	12.57	2.81	12.79				-				
MW-2	6/11/1993	25.92	13.19		0.00	12.74						_	_	
MW-2	8/17/1993	25.92	14.04	14,03	0.01	11.89	49,000	94	240	250	980			
MW-2	3/28/1994	25.92	13.61	13.07	0.54	12.74	14,000	4,200	<250	910	1,400	-	_	
MW-2	6/27/1994	25.92	14,24	13,44	0.80	12.32	24,000	4,400	72	1,100	1,700		_	
MW-2	9/16/1994	25.92	17.82	13,36	4.46	11.67	40,000	2,300	250	2,000	4,100			
MW-2	3/31/1995	25,92	16.72	9.28	7.44	15.15	28,000	4,000	<120	1,100	1,400			
MW-2	6/28/1995	25.92	13,50	12,77	0,73	13.00	40,000	2,700	130	1,700	2,900			
MW-2	9/28/1995	25.92	14.63	14.09	0.54	11.72	7,500	420	14	250	190	<62	-	
MW-2	12/26/1995	25.92	12,58	11.68	0.90	14.06	22,000	1,300	88	950	008,1	<250	-	
MW-2	3/22/1996	25.92	11.46	11.31	0.15	14.58	9,800	2,200	<120	400	<380	<1,200		
MW-2	6/20/1996	25,92	13.08	12.71	0.37	13.14	35,000	770	< 0.50	240	< 0.50	550		••
MW-2	9/30/1996	25.92	16.67	12.92	3.75	12.25	58,000	1,600	230	2,200	4,000	<5.0		
MW-2	12/27/1996	25.92	15.74	8.17	7.57	16.24	29,000	2,100	< 0.50	1,200	1,800	<5.0		
MW-2	3/7/1997	25.92	12.55	_	0.00	13.37	13,000	1,300	37	290	180	<5.0	_	
MW-2	6/28/1997	25,92	11.98	11.94	0.04	13.97	12,000	840	<0.50	640	360	<5,0		••
MW-2	9/18/1997	25.92	13.44	13.44	0.00	12.48	12,000	680	<0.50	320	84	<5.0	_	
MW-2	12/30/1997	25,92	11.31		0.00	14.61	13,000	1,100	40	350	220	<5,0		
MW-2	3/25/1998	25.92	10.02	_	0.00	15.90	8,100	1,300	51	410	230	670		_
MW-2	6/29/1998	25.92	11.96		0.00	13.96	12,000	880	13	180	72	430		
MW-2	10/2/1998	25.92	13.74		0.00	12,18	47,000	140	100	110	200	< 0.50		
MW-2	12/10/1998	25.92	12.91	10.81	2.10	14.69	26,000	1,000	210	1,500	1,900	<1,000		_
MW-2	3/26/1999	25.92	9.06	8.86	0.20	17.02	110,000	190	150	120	380	< 0.50		**
MW-2	6/11/1999	25.92	12.18		0.00	13.74	190,000	310	250	320	540	<0.50		
MW-2	9/15/1999	25.92	15.59	12.59	3.00	12.73	25,000	720	<100	1,300	1,600	<1,000	_	
MW-2	12/28/1999	25.92	16.81	12,31	4,50	12.71	75,000	130	98	130	230	<0.50		
MW-2	6/13/2001	23.16°	14.84	11.69	3,15	10.84								_
MW-2	6/20/2002	23.16	14,80	14.10	0.70	8.92	53,000	2,200	140	3,300	3,000	<1,000		
MW-2	10/21/2002	23.16	16.98	16.74	0.24	6.37	-	, 	_		-	<u></u>		
MW-2	12/27/2002	23.16	13.58	13.15	0.43	9.92		_	_				_	
MW-3	8/23/1991	99.25ª	15.07		0.00	84.18	<5,000	<5	<5	<5	<5		 .	••
MW-3	4/16/1992	27.57 ^b	14.14	13.98	0.16	13,56			-					
MW-3	6/11/1993	27.57	14.28	_	0.00	13.30								••
MW-3	8/17/1993	27.57	15,77		0.00	11.80	9,600	4,1	17	28	54			••
MW-3	3/28/1994	27.57	14.35	_	0.00	13.22	8,400	2,400	56	67	200		_	

Table 3. Groundwater Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Sample ID/	Date	Casing	Depth to	Depth to	SPH	GW								-
Well ID	Sampled	Elevation	GW	SPH	Thickness	Elevation	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	TOG	VOCs
		(feet)	(feet bgs)	(feet bgs)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
Final RBSL -	Potential Dri	nking Water S	Source				100	1.0	40	30	13	5,0	640	N/A
	Risk I	Driver					human toxicity	aquatic life	aquatic life	aquatic life	aquatic life	taste & odor	aquatic life	
Final RBSL -	Not a Potenti	al Drinking V	Vater Source				500	46	130	290	13	1,800	640	N/A
	Risk I	Driver					aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	
RBSL - Indoo	or Air Impact						NE	84 (5800)	76000 (530000)	170,000	150000 (160000)	50000(4.9E+05)	NE	N/A
MW-3	6/27/1994	27,57	14.77		0.00	12,80	9,900	3,300	<22	<25	73			
MW-3	9/16/1994	27.57	15.42	15.37	0.05	12.19	16,000	2,300	80	620	240			
MW-3	3/31/1995	27,57	12.98	12.52	0,46	14.96	16,000	2,800	70	<25	920			
MW-3	6/28/1995	27.57	14.20	14.15	0.05	13.41	11,000	2,300	32	81	240			
MW-3	9/28/1995	27.57	15.17		0.00	12.40	6,300	1,900	<42	200	<120	<420	-	
MW-3	12/26/1995	27.57	13.33	13.27	0.06	14,29	25,000	3,800	97	94	1,600	<250		
MW-3	3/22/1995	27,57	12.81	12,77	0.04	14,79	16,000	3,100	75	69	350	250		
MW-3	6/20/1996	27,57	13.95	13.88	0.07	13.68	8,500	1,400	28	140	15	220	••	
MW-3	9/24/1996	27.57	14.86	14.82	0.04	12.74	12,000	2,400	87	340	110	<5.0		
MW-3	12/27/1996	27.57	11,04	10.98	0.06	16.58	5,800	1,700	28	<0.50	42	240		
MW-3	3/10/1997	27.57	13.80	_	0.00	13.77	9,000	1,700	<0.50	110	<0.50	<5.0		
MW-3	6/28/1997	27.57	13.72	13.66	0.06	13.90	15,000	2,200	<0.50	160	190	<5,0		
MW-3	9/18/1997	27.57	14.76		0.00	12.81	28,000	3,800	<0.50	100	<0.50	<5.0	 	
MW-3	12/30/1997	27.57	12.97		0.00	14.60	21,600	2,200	<0.50	31	<0.50	300	 	<u></u>
MW-3	3/24/1998	27.57	11.75		0.00	15.82	2,300	870	7.2	20	<0.50	85		
MW-3	6/29/1998	27.57	13.38		0.00	14.19	6,500	1,300	12	62	14	140		
MW-3	10/2/1998	27.57	14.42		0.00	13.15	11,000	31	27	35	69	<0.50		
MW-3 MW-3	12/10/1998	27.57	12.55		0.00	15.02	<2,500		68	42				
MW-3	3/26/1999	27.57	10.54		0.00	17.03	10,000	2,800 21			55	<250		
MW-3	6/15/1999	27.57	13,91		0.00	13.66	87,000	90	14 71	10	41	<0.50		
	9/15/1999		15,91		0,00		•			92	180	<0.50		-
MW-3 MW-3		27.57		14.01		12.87	8,700	2,100	71	110	66	<100		
	12/28/1999	27.57 24.57 ^e	15.16	14.91	0.25	12.61	4,300	7.7	5.2	7.2	13	<0.50	•-	
MW-3	6/13/2001	24.57 ^e	14.70	14.30	0.40	10.19	8,400	1,300	25	64	32	<20	_	-
MW-3	6/20/2002		14.68	14,66	0.02	9.91	7,200	1,100	23	66	15	<50		-
MW-3	12/27/2002	24.57°	11.37	11.20	0.17	13,34	_							
Th 4777 4	805000	26 50b	12.24		0.00	12.04	150	40.50						
TMW-4	8/17/1993	26.50 ^b	13.26		0,00	13,24	150	<0.50	0.8	1.4	3.7			-
TMW-4	3/28/1994	26.50	12.40		0.00	14.10	<50	<0.50	<0.50	<0.50	<1.5			_
TMW-4	6/27/1994	26.50	12.84		0.00	13.66	<50	<0.50	<0.50	<0.50	<1.5	-		-
TMW-4	9/16/1994	26.50	13.58	-	0.00	12.92	<50	<0.50	<0.50	<0.50	<1.5	•		-
TMW-4	3/31/1995	26.50	10.23		0.00	16.27	<50	<0.50	<0.50	<0.50	<1.5			
TMW-4	6/28/1995	26.50	12.21		0.00	14.29	<50	<0.50	<0.50	<0.50	<1,5		-	
TMW-4	9/28/1995	26.50	13.38		0.00	13.12	<50	<0.50	<0.50	<0.50	<1.5	<5.0	-	
TMW-4	12/26/1995	26.50	11.32	-	0.00	15.18	<50	< 0.50	< 0.50	<0.50	<1,5	<5.0		••
TMW-4	3/22/1996	26.50	10.54	_	0.00	15.96	<50	<0.50	<0.50	<0,50	<1.5	<5.0		
TMW-4	6/20/1996	26.50	12.14		0.00	14.36	<50	<0.50	<0.50	<0.50	<0.50	<5.0		
TMW-4	9/24/1996	26.50	13.01	_	0.00	13.49	<50	< 0.50	<0.50	<0.50	<0.50	<5.0		
TMW-4	12/27/1996	26.50	9.51		0.00	16.99	<50	<0.50	<0.50	<0.50	< 0.50	<5.0		

Table 3. Groundwater Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Sample ID/ Well ID	Date Sampled	Casing Elevation	Depth to GW	Depth to SPH	SPH Thickness	GW Elevation	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	MTBE	TOG	VOCs
Final DDCI	Detautial Dei	(feet) inking Water S	(feet bgs)	(feet bgs)	(feet)	(feet)	(ug/L) 100	(ug/L)	(ug/L) 40	(ug/L) 30	(ug/L)	(ug/L) 5.0	(ug/L) 640	(ug/L) N/A
rinui KBSL -		nking witter s Driver	ource				human toxicity	aquatic life	aquatic life	aquatic life	aquatic life	taste & odor	aquatic life	N/A
Final PRSI		ial Drinking V	Vator Source				500	46	130	290	13	1,800	640	N/A
r inui KDSL -		aa Drinking n Driver	ater source				aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	N/A
nnor r r		Dilver							<u> </u>	•			•	N7/4
RBSL - Indoo	•						NE	84 (5800)	76000 (530000)	170,000	150000 (160000)		NE	N/A
TMW-4	3/10/1997	26,50	11.92		00,0	14.58	<50	<0.50	<0.50	<0,50	<0.50	<5.0		_
TMW-4	6/27/1997	26.50	10.70		0.00	15.80	<50	<0.50	<0.50	<0.50	<0.50	<5.0		
TMW-4	9/18/1997	26.50	12.94		0.00	13.56	<50	<0.50	<0.50	<0,50	<0.50	<5.0		-
TMW-4	12/30/1997	26.50	10.92	_	0.00	15.58	<50	<0.50	<0.50	<0.50	. <0.50	<5.0		••
TMW-4	3/25/1998	26.50	9.60		0.00	16.90	<50	<0.50	<0.50	<0.50	<0.50	<5.0		
TMW-4	6/29/1998	26.50	11.32	_	0.00	15.18	<50	<0.50	<0.50	<0.50	<0.50	<5.0		••
TMW-4	10/2/1998	26,50	12.56	**	0.00	13.94	<50	<0.50	< 0.50	< 0.50	<0.50	<0.50		
TMW-4	12/10/1998	26.50	10.44	-	0.00	16.06	<50	<0.50	<0.50	<0.50	<0.50	<0.50		
TMW-4	3/26/1999	26,50	9.38		0.00	17.12	<50	<0.50	<0.50	<0.50	<0.50	<0.50		
TMW-4	6/15/1999	26,50	11.58	-	0.00	14.92	<50	<0.50	<0.50	<0.50	<0.50	<0.50		
TMW-4	9/15/1999	26.50	12.89	••	0.00	13,61	<50	< 0.50	<0.50	<0.50	<0.50	<5.0	-	
TMW-4	12/28/1999	23.50°	12.92	••	0,00	10.58	<50	< 0.50	<0.50	<0.50	<0.50	<0.50	••	
TMW-4	10/21/2002	23.50°	12.70		0.00	10.80	••						-	
TMW-4	12/27/2002	23.50°	9.07	8.95	0.12	14.53	_	-	-	-	_	••	-	
TMW-5	8/17/1993	26.51 ^b	12,98	12.95	0.03	13.55	120,000	640	730	790	3,600		••	
TMW-5	3/28/1994	26.51	11.39		0.00	15.12	70,000	23,000	1,500	4,100	15,000			-
TMW-5	6/28/1994	26.51	12.24		0.00	14,27	56,000	26,000	940	5,500	26,000	_		
TMW-5	9/16/1994	26.51	13.02	12.97	0.05	13.53	96,000	17,000	720	3,500	12,000			-
TMW-5	3/31/1995	26.51	7.38		0.00	19.13	64,000	13,000	470	3,500	6,100			
TMW-5	6/28/1995	26.51	11,31	11,25	0.06	15.25	65,000	9,000	240	2,600	5,390	_		
TMW-5	9/28/1995	26.51	14.42		0.00	12.09	79,000	17,000	1,800	2,700	7,000	<1,200	••	
TMW-5	12/26/1995	26.51	10.16	10.11	0.05	16,39	110,000	11,000	800	2,300	4,500	<1,200		
TMW-5	3/22/1996	26.51	7.59	7.54	0.05	18.96				-				
TMW-5	6/26/1996 ^d		7.12		0.00		30,000	4,000	180	1,500	2,500	830	••	
TMW-5	9/30/1996		7.42		0.00	••	6,900	1,600	79	130	370	<5.0		
TMW-5	12/27/1996	-	6.38		0.00		78,600	12,000	1,900	2,900	9,700	<5.0		
TMW-5	3/10/1997		11.12		0.00		84,000	9,900	1,100	2,600	8,800	<5.0	-	
TMW-5	8/17/19 9 7	-	12.98	12.95	0.03		_							
TMW-5	9/18/1997	-	12.00		0.00		65,000	8,000	<0.5	2,000	4,700	<5.0		_
TMW-5	12/30/1997	_	8.97		0.00		79,000	6,400	340	2,300	5,500	<5.0		
TMW-5	3/25/1998		7,32		0.00		20,000	6,000	260	2,700	5,800	2,400		_
TMW-5	6/29/1998		11.50		0.00				_					_
TMW-5	10/8/1998	-	12.56	_	0.00	_	46,000	120	98	120	240	<0.50		_
TMW-5	12/8/1998		10.14		0.00		46,000	5,900	320	2,290	5,400	<1,200	_	**
TMW-5	3/26/1999	_	7.08	_	0.00	_	35,000	69	61	37	120	<0,50		
TMW-5	6/11/1999		11.40		0.00	-	26,000	29	32	43	72	<0.50		

Table 3. Groundwater Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Sample ID/ Well ID	Date Sampled	Casing Elevation	Depth to GW	Depth to SPH	SPH Thickness	GW Elevation	ТРНg	Benzene	Toluene	Ethylbenzene	Xylenes	мтве	TOG	VOCs
ZI I DDAY		(feet)	(feet bgs)	(feet bgs)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
Final RBSL -		-	Source				100	1,0	40	30	13	5.0	640	N/A
EL LEBER		Driver					human toxicity	aquatic life	aquatic life	aquatic life	aquatic life	taste & odor	aquatic life	
Final RBSL -			Vater Source				500	46	130	290	13	1,800	640	N/A
		Driver					aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	
RBSL - Indoo	r Air Impact						NE	84 (5800)	76000 (530000)	170,000	150000 (160000)	50000(4.9E+05)	NE	N/A
TMW-5	9/15/1999		12,52	-	0.00	-	37,090	7,300	400	2,400	6,000	<1,000		-
TMW-5	12/28/1999		12.44		0.00		25,000	44	32	41	75	<0.50		
TMW-5	5/23/2001	23.85°	11.31		0.00	12.54	-							-
TMW-5	6/20/2002	23,85	11.29	11,24	0.05	12.60	51,000	5,100	290	2,300	5,800	<250		
TMW-5	10/21/2002	23.85	13.60	13.50	0.10	10.33		-						
TMW-5	12/27/2002	23.85	6,60	6,53	0.07	17.31		-	-	-	_	-		
MW-6	5/23/2001	23.81°	12.47	••	0.00	11.34	-	_						
MW-6	6/13/2001	23.81	12,47		0.00	11.34	7,600	1,400	42	19	14	<10		
MW-6	6/20/2002	23.81	12.45		00,0	11.36	79	5.7	<0.5	<0.5	<0.5	<5.0		
MW-6	12/27/2002	23.81	7.24	7,20	0.04	16.60	_	_	-				-	-
TRIP BLANK	8/17/1993						<50	<0.50	<0.50	<0.50	<0.50	••		
TRIP BLANK	3/28/1994						<50	<0.50	< 0.50	< 0.50	<1.5			
TRIP BLANK	6/27/1994		_				<50	< 0.50	< 0.50	< 0.50	<1.5			••
TRIP BLANK	9/16/1994		_				<50	<0.50	< 0.50	<0,50	<1.5	_		
TRIP BLANK	3/31/1995				_		<50	<0.50	< 0.50	< 0.50	<1.5	••		••
TRIP BLANK	6/28/1995		_				<50	< 0.50	<0.50	< 0.50	<1.5	<5.0		
TRIP BLANK	9/28/1995						<50	<0.50	< 0.50	< 0.50	<1.5			
TRIP BLANK	12/26/1995		_			••	<50	<0.50	< 0.50	<0.50	<1.5	<5.0		
TRIP BLANK	3/22/1996						<50	< 0.50	< 0.50	< 0.50	<1.5	<5.0		
TRIP BLANK	9/24/1996						<50	<0.50	<0.50	< 0.50	<0.50	<5.0		
TRIP BLANK	9/30/1996	-		_			<50	< 0.50	< 0.50	< 0.50	<0.50	<5,0		
TRIP BLANK	6/20/1996					••	<50	< 0.50	< 0.50	< 0.50	< 0.50	<5,0		
TRIP BLANK	12/27/1996					••	<50	<0.50	< 0.50	< 0.50	< 0.50	<5.0		
TRIP BLANK	3/10/1997			_			<50	<0.50	<0.50	< 0.50	< 0.50	<5.0		
TRIP BLANK	9/18/1997						<50	<0.5	<0.5	<0.5	<0.5	<5.0		
TRIP BLANK	12/30/1997			_			<50	<0.5	<0.5	<0.5	<0.5	<5.0		
TRIP BLANK	3/25/1998	••	••				<50	<0.5	<0.5	<0.5	<0.5	<5.0		••
TRIP BLANK	6/29/1998			-		-	<50	< 0.5	<0.5	<0.5	<0.5	<5.0		
TRIP BLANK	10/2/1998	-								_	_			
TRIP BLANK	12/10/1998													
TRIP BLANK	3/26/1999	-					<50	<0.50	<0.50	< 0.50	< 0.50	<0.50		
TRIP BLANK	6/15/1999	**					<50	<0.50	< 0.50	< 0.50	< 0.50	<0.50		_
TRIP BLANK	9/15/1999	-					33,000	6,200	300	2,000	4,800	<1,000		_
TRIP BLANK	12/28/1999						<50	<0.50	<0.50	<0.50	< 0.50	<0.50		••

Table 3. Groundwater Analytical Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Sample ID/ Well ID	Date Sampled	Casing Elevation	Depth to GW	Depth to SPH	SPH Thickness	GW Elevation	TPHg	Benzene	Toluene	Ethylbenzene	Xylenes	мтве	TOG	VOCs
		(feet)	(feet bgs)	(feet bgs)	(feet)	(feet)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
Final RBSL -	Potential Dri	nking Water S	ource				100	1.0	40	30	13	5.0	640	N/A
	Risk 1	Orive r					human toxicity	aquatic life	aquatic life	aquatic life	aquatic life	taste & odor	aquatic life	
Final RBSL -	Not a Potenti	al Drinking W	ater Source				500	46	130	290	13	1,800	640	N/A
	Risk I	Driver					aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	aquatic life	
RBSL - Indoo	r Air Impact						NE	84 (5800)	76000 (530000)	170,000	150000 (160000)	50000(4.9E+05)	NE	N/A

Abbreviations and Methods:

bgs = below grade surface

(ug/L) = micrograms per Liter

Depth to GW = Depth to groundwater relative to top of casing

SPH = Separate phase hydrocarbons

TOG = Total oil and grease by modified EPA Method 3550

TPHg = Total petroleum hydrocarbons as gasoline by modified EPA Method 8015

Benzene, Toluene, Ethylbenzene, Xylenes by EPA Method 8020, and by 8260 if in parenthesis

MTBE methyl tert butyl ether by EPA Method 8020

VOCs = volatile organic compounds by EPA Method 8260

ND* = not detected with the exception of reported concentrations for benzene, toluene, ethylbenzene and xylenes

GW Elevation = Groundwater elevation in relation to mean sea level; calculated according to the relationship GW elevation = TOC - DTW + (0.8)(SPH thickness)

- a = Relative to site datum established by Earth Systems Engineering
- b = Top of casing elevation surveyed 8/10/93 by professional engineer (assumed based on NGVD 29 datum that is approximately 3 feet higher than City of Oakland datum)
- c = Top of casing elevation surveyed 6/13/01 to City of Oakland datum by Renner Survey Company of Burlingame, CA. for Sequoia Environmental. Wells MW-3 and MW-4 were not surveyed
- d = Casing damaged during excavation activities; not surveyed
- e = Assumed top of casing elevation relative to City of Oakland datum, estimated by subtracting 3.00 feet from previous elevation presumably from NGVD 29 datum
- 1,300 = concentrations exceeding commercial final RBSLs (not a potential drinking water resource) shown in bold

Final RBSL - Potential Drinking Water Source = Table F-1 - Components for Groundwater Screening Levels (Groundwater is not a Current or Potential Drinking

Water Resource) established by the SFRWQCB, Interim Final December 2001. (The risk driver is also shown)

Final RBSL - Not A Potential Drinking Water Source = Table F-2 - Components for Groundwater Screening Levels (Groundwater is not a Current or Potential Drinking

Water Resource) established by the SFRWQCB, Interim Final December 2001. (The risk driver is also shown).

RBSLs for indoor air = Tables F-1 and F-2 from SFRWQCB above, Interim Final December 2001

Table 4. Well Completion Data - Credit World Auto Sales, 2345 International Boulevard, Oakland, California

Well No.	Installation Date	Boring Diameter (inches)	Well Diameter (inches)	Screen Size (inches)	Total Depth (feet bgs)	Surface Seal (feet bgs)	Sand Pack Interval (feet bgs)	Screened Interval (feet bgs)
MW- 1	5/22/1991	8	2	0.010	35	0-12	12-35	15-35
MW-2	8/21/1991	8	2	0.010	35	0-12	12-35	15-35
MW-3	8/22/1991	8	2	0.010	35	0-12	12-35	15-35
TMW-4	7/22/1993	8	2	0.010	36	0-12	12-34	14-34
TMW-5	7/23/1993	8	2	0.010	27	0-15	15-24	17-24
MW-6	5/22/2001	6.75	4	0.020	20	0-13	13-20	15-20

bgs = below ground surface

ft-msl = feet above mean sea level

Table 5. Separate Phase Hydrocarbon Removal - Credit World Auto Sales ternational Boulevard, Oakland, California

Sample ID/ Well ID	Date Sampled	Casing Elevation (feet)	Depth to GW (feet bgs)	Depth to SPH (feet bgs)	SPH Thickness (feet)	GW Elevation (feet)	Hydrocarbons Removed (liters)	Hydrocarbons Removed (lbs.)	Cumulative Hydrocarbons Removed (lbs.)
MW-1	12/30/1997	27.33	10.96	10.79	0.17	16.51	0.10	0.17	0.17
MW-1	6/11/1999	27.33	12.56	12.55	0.01	14.78	0.01	0.01	0.18
MW-1	9/15/1999	27.33	14.85	13.85	1.00	13.28	0.60	0.97	1.15
MW-i	12/28/1999	27.33	8.31	8,15	0.16	19.15	0,10	0,16	1,31
MW-1	6/13/2001	24.37	8.31	8.15	0.16	16.19	0.10	0,16	1.46
MW-1	12/27/2003	24.37	8.31	8.15	0.16	16,19	3.00	4.84	6.30
MW-2	6/28/1995	25.92	13.50	12,77	0.73	13.00	0.44	0.71	0.71
MW-2	9/28/1995	25.92	14.63	14.09	0.54	11,72	0.33	0.53	1,24
MW-2	12/26/1995	25.92	12,58	11.68	0.90	14.06	0.54	0.88	2.12
MW-2	3/22/1996	25.92	11.46	11.31	0.15	14,58	0.09	0.15	2.26
MW-2	6/20/1996	25.92	13.08	12.71	0.37	13.14	0.22	0.36	2.62
MW-2	9/30/1996	25.92	16.67	12.92	3.75	12,25	2.27	3,66	6.28
MW-2	12/27/1996	25,92	15.74	8.17	7.57	16.24	4.58	7.38	13.66
MW-2	6/28/1997	25.92	11.98	11.94	0.04	13.97	0.02	0.04	13.70
MW-2	9/18/1997	25.92	13.44	13.44	0.00	12.48	0.00	0.00	13.70
MW-2	12/10/1998	25.92	12,91	10.81	2.10	14.69	1.27	2.05	15.75
MW-2	3/26/1999	25.92	9.06	8.86	0,20	17.02	0.12	0.19	15,94
MW-2	9/15/1999	25.92	15.59	12.59	3.00	12,73	1,81	2.92	18.87
MW-2	12/28/1999	25.92	16.81	12.31	4.50	12.73	2.72	4.39	23.25
MW-2	6/13/2001	23.16	14.84	11,69	3.15	10,84	9.45	15.23	38.49
MW-2	6/20/2002	23,16	14.80	14.10	0.70	8.92	0.42	0.68	39.17
MW-2	10/21/2002	23.16	16.98	16.74	0.24	6,37	0.00	0,00	39,17
MW-2	12/27/2002	23.16	13.58	13.15	0.43	9.92	3.00	4.84	44.00
MW-3	4/16/1992	27.57	14.14	13.98	0.16	13,56	0,10	0.16	0,16
MW-3	9/16/1994	27.57	15.42	15.37	0.05	12,19	0.03	0,05	0,70
MW-3	3/31/1995	27.57	12.98	12.52	0.46	14.96	0.28	0.45	0.65
MW-3	6/28/1995	27.57	14.20	14.15	0.46	13.41	0.28	0.45	0.70
MW-3	12/26/1995	27.57	13.33	13.27	0.06	14.29	0.04	0.06	0.76
MW-3	3/22/1995	27.57	12.81	12.77	0.04	14.79	0.02	0.04	0.80
MW-3	6/20/1996	27.57	13.95	13,88	0.07	13.68	0.04	0.07	0.87
MW-3	9/24/1996	27.57	14.86	14.82	0.04	12.74	0.02	0.04	0.91
MW-3	12/27/1996	27.57	11.04	10.98	0,06	16.58	0.04	0.06	0.97
MW-3	6/28/1997	27,57	13.72	13.66	0.06	13.90	0.04	0.06	1.02
MW-3	12/28/1999	27.57	15.16	14.91	0.25	12.61	0.15	0.24	1.27
MW-3	6/13/2001	27,57	14.70	14.30	0.40	13.19	7.56	12.19	13.45
MW-3	6/20/2002	27.57	14.68	14,66	0.02	12.91	0.01	0.02	13.47
MW-3	12/27/2002	27.57	11.37	11.20	0.17	16.34	3.00	4.84	18.31
TMW-4	12/27/2002	26.50	9.07	8.95	0.12	17.53	1.50	2.42	2.42
TMW-5	8/17/1993	26.51	12.98	12,95	0.03	13.55	0,02	0.029	0.03
TMW-5	9/16/1994	26.51	13.02	12.97	0.05	13.53	0.03	0.049	0.08
TMW-5	6/28/1995	26.51	11,31	11,25	0,06	15.25	0,04	0,058	0.14
TMW-5	12/26/1995	26.51	10.16	10.11	0.05	16,39	0,03	0.049	0.19
TMW-5	3/22/1996	26,51	7.59	7.54	0.05	18.96	0.03	0.049	0.23

 Table 5.
 Separate Phase Hydrocarbon Removal - Credit World Auto Sales ternational Boulevard, Oakland, California

Sample ID/ Well ID	Date Sampled	Casing Elevation (feet)	Depth to GW (feet bgs)	Depth to SPH (feet bgs)	SPH Thickness (feet)	GW Elevation (feet)	Hydrocarbons Removed (liters)	Hydrocarbons Removed (lbs.)	Cumulative Hydrocarbons Removed (lbs.)
TMW-5	8/17/1997	-	12.98	12,95	0.03		0.02	0.029	0.26
TMW-5	5/23/2001	23.85	11.31		0.00	12.54	9,45	15.23	15.47
TMW-5	6/20/2002	23,85	11.29	11,24	0.05	12.60	0.03	0.049	15.52
TMW-5	10/21/2002	23.85	13.60	13.50	0.10	10.33	0.00	0.00	15.52
TMW-5	12/27/2002	23.85	13.60	13.50	0.10	10.33	1.50	2.42	17.93
MW-6	12/27/2002	23,81	7,24	7.20	0.04	16.60	1.50	2.42	2.42

Hydrocarbons removed by bailing or purging (lbs.) = 91.38

Hydrocarbons removed by free product removal system (see Note 1) (lbs) = 30.5

Total estimated hydrocarbons removed (lbs) = 121.88

When data is unavailable, hydrocarbon removal volume prior to 12/27/2002 is estimated by multiplying the well casing area (2" diameter casing = 0.60L/ft) by SPH thickness (feet)


^{1.} Tank Protect reported that the continuous free product removal system removed approximately 3 to 5 gallons between 8/20/97 and 1/14/98.

SPH Removal data provided for 5/23/01, 6/13/01, and 12/27/02 data.

bgs = below ground surface

Appendix A

Background Information





Site Plan Showing L. Pation of Throek Borings at 2345 back 14th Street, Oakland, CA. Scale 1"=25" 0 12.5 25

FIGURE NO.

CHO/SBW FABJECT NO

CALIFORNIA ENVIRONMENTAL CONSULTANTS

Field	E	y (fad a Jenna	DRAT			OR	ing	PROJECT No CEC/SBh 288 2 Oct 3,88 BORING No CLIENT West Coast Tank Testing B2 LOCATION 2345 East 14th Street Shoot 1 Shoot 1 Of 1 O
Ground	į g	- C	Exc. Gasalini Tanha Tanha	ENCHAIL COMMAND	Foot Park	**************************************		CME-55 Mobile Drill Rig Hote dis Sinches Casing Installation data
Pocket Torr vene	Pocket Penetrometer TSF	@lows/ft. of Pressure PBt	Type of Sample	Number Number	Depth	Semple	Bolf Group Symbol (U.S.C.S.)	Water level ▼ 19 ft 557 16 ft. Time 9.30 AM Date 10.03.88
	-		1.94	inch	Ft	•		DESCRIPTION 0-9" Asphalt/Base rock
			dia.	brass].			The print to buse took
			sleev	es	1 -			Black silty clay w/ gasoline odor.Damp
		3						
			B2-5	And Annual and Annual A			CL	Black to greenish silty clay w/ gasoling oder, begg, soft to med.still.
		3 8 10	B2-1(10		CL	Greenish, soft to med.stiff silty clay w/ some sand. Slight discoloration and damp.
					-			
		10 15 15	B2-1		15		CI.	Greenish to brown silty clay w/ some sand Med. stiff and Damp.Slight discoloration observed.
		· · · · · · · · · · · · · · · · · · ·			+			
							V	Water encountered at 19 feet.Boring bot
					ļ	7	Ļ	
CA	LIFO				N	VII	L RON	MENTAL CONSULTANTS AN JOSE, CA 95129 • (408) 725-2644

lola		···	DRAT	ORY	BO	OR total to a	<u> </u>	CLIENWest Coal. Tank Testing LOCATION 2345 East 17th Street LO
Torr vene	Peckel Penetrometer TSF	Blows/fl. or Pressure PSI	Type of Sample	So Bpie	Ft.	Semple	Son Group Symbol (U.S.C.S.)	Water fevel V 21ft 16 ft. Time 10.35 AM Date 10.03.88 DESCRIPTION
				inch				0-9" Asphalt/Base rock, dry.
			sleet		-		1	
		··			-		CL	Dry to damp black silty clay w/ sind. Some discoloration(reddish) & oily o
	 				} -			
		2			}	Z		
		3	B3-5		5		CL	Blackish to brown damp silty clay, soft
								w/ some reddish sand.
						\dashv		
		2				习		
		7	B3-1)	10		CL	Damp.brown silty clay w/ reddish sama
					}	_		soft to med.stiff. Oily odor
					Ŧ	4	À	
					+			
					+			
		5				\neq	F	
\dashv		12	B3-15		15		CL I	Damp.greenish and brown silty clay w/
1					1	コ	$\sum_{i} I_{i}$	Med stiff. Oily odor. Some discolorations
士					-	\dashv	-	
\dashv	— T				F		-	
1					†			
1					+	4	F	
二					+	┪.	Y.	Water encountered at 21 feet.Boring bot
—————————————————————————————————————	LIFO		<u>_</u>			ļ	J	MENTAL CONSULTANTS
A		DAU <i>i</i>	•	Æ				

LOG () EXPLORATORY BORING						OR	ING	PROJECT No CEC/SBI 08 2 Oct 3,88 CLIENT West Coa. Tank Testing B1 LOCATION 2345 East 14th street TS LOGGED BY ORILLEN Hew Drilling of
Groun	# 5 + 00 mg =	poring:	M. Erc.	A Except I	Kent Path	EAST 14 3E		Orilling method Solid Stem Auger CME-55 Mobile Drill Riq Molegia 6 inches Cooling Installation data
Pochet Torrene T&F	Peckel Pensiremeter TSF	Blows/ft. or Pressure P81	Type of the mole	Semple Number	eta-o Ft	elq#a@	Sell Greup Symbol (U.S.C.S.)	Water level V 19 ft CTV 16 ft. Time 8.30 AM Gate 10.00.30 DESCRIPTION
			l.94 dia. sleev	inch hrass es	-		CL	0-9" Asphalt/Base rock Damp silty clay. Soft and Blackish
		3 3 6	B1~5		5		CL	Blackish silty clay, soit to med.still with gasoline odor.
		4 6 10	RI-10		10		CL	Damp greenish to Black silty clay w/ some sand content. Slight discoloration observed.Med. stiff w/ gasoline odor.
		15 13 18	R1-11		15		CL &SM	Moist greenish silty sandy clay w/ fines Med.stiff to stiff w/ slight discoloration
							y	Ground water encountered at 19 feet. Boring bottom.
C	ALIFO			PY VALLE	N'	VI	I RON	MENTAL CONSULTANTS
			W. Com	VALL	-		IUE • SA	N JOSE, CA 95129 • (408) 725-2644

CALIFORNIA ENVIRONMENTAL CONSULTANTS



CHAIN	OF SAMPLE CUSTODY RECORD	a ama
Collector: Januar Shok	Date Sampled: 10:03:88 Time:	L3011
Location of Sampling: 234	5 East 14th Street	
Oak	land, CA	
Project Number: CEC SBW	9 · 82 · 2 Survey Number:	
Sample Type: Soll		·
Container Type and Condition: \mathcal{L}	rass Sheeres 2 inch & bindyforms on La	(0)
Contract Laboratory Record/Nan	ne SEQUOIA AMOUTICAL LAB 2549 Middle field	(W) (E) WOTO (
Sample ID	Field Information	
B, -15'	Soil Sounde for Bount by pour	15 dollar
	1	1
<u> B2-15' </u>	Soil Sample from Borning By from	15 depth
<u> </u>	soil sample from Bornit B3 pour	15 136
$-\frac{123-0}{}$	sad south to be my B3 how	Detapn
	<u>-</u>	
(T)A	B1-15 and B2-15	1
Analysis Requested Thalys	e and samples individual	b_{j}
1 Total Petrolum	Hydro Carons TOHG, EPA Tex	- Mutter So3
(2) B, T, x & E 17 8	MA Fat Method 8020	
	5 by (D) ENA 5030	
11 Another 03-1	2 81A Methres 8010 and 802	
Results Needed By:	3) Oil of Gream 503 D & F	-0.
Tresdits (Vocata by.		<u> </u>
Travel Blank: ☐ Yes	No Travel Blank to be Analyzed Separately:	□ Yes Ū No
Duplicate Samples: ☐ Yes		⊡ Yes Ü No
Field Blank: ☐ Yes		☐ Yes ☐ No
Background Soil Sample: ☐ Yes	No Background Soil Sample to be Analyzed Separately	: ☐ Yes ঢ় No
Chain of Custody:	Oct 3,80).
1. Field Personnet		
2.	0 ct 3 88	
Courier B. 2	10/3/98 22	30
Lab Lab	Date	<u></u>
(three byass Sleeves -	2/6 dia 2 (u. Jm)	
1117 HAPPY V	ALLEY AVENUE - CAN LOCE ON DESCO - (400) YOU DOA	



California Environmental Consultants 1117 Happy Valley Avenue San Jose, CA 95129

Attn: Munir Butt

Date Sampled: 10/03/88 Date Received: 10/03/88 Date Analyzed: 10/12/88 Date Reported: .10/31/88

Project:#CEC-SBW 9-88-2

TOTAL PETROLEUM FUEL HYDROCARBONS WITH BTEX DISTINCTION

Sample Number	Sample Description Soil	Low to Medium Boiling Point Hydrocarbons Ppm	Benzene ppm	Toluene ppm	Ethyl Benzene ppm	Xylenes ppm
8100025	B1-15'	3.4	0.31	N.D.	N.D.	0.14
8100026	B2-15'	83	1.6	1.1	1.8	

Detection Limits:

1.0

0.05

0.1

0.1

0.1

Method of Analysis: EPA 5030 or 3810/8015/8020

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

The second secon

Arthur G. Burton



California Environmental Consultants 1117 Happy Valley Avenue San Jose, CA 95129 Attn: Munir Butt

 Date
 Sampled:
 10/03/88

 Date
 Received:
 10/03/88

 Date
 Extracted:
 10/06/88

 Date
 Reported:
 10/31/88

Project: #CEC/\$BW 9-88-2

TOTAL OIL AND GREASE

Sample Number	Sample Description	Detection Limit	Gravimetric Petroleum Oil		
	Soil	mg/kg	mg/kg		
8100027	B3-15'	30	88		

Method of Analysis: EPA 3550 with trichlorotrifluoroethane and gravimetric determination.

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

A STATE OF THE STA



680 Chesapeake Drive - Redwood City, CA 94063 (415) 364-9222 - FAX (415) 364-9233

California Environmental Consultants

1117 Happy Valley Avenue San Jose, CA 95129

Attn: Munir Butt

Date Sampled: 10/03/88
Date Received: 10/03/88

Date Analyzed: 10/06/88 Date Reported: 10/31/88

Project: #CEC/SBW 9-88-2

HALOGENATED VOLATILE ORGANICS

Sample Number 8100027

Sample Description

Soil, B3-15'

Analyte	Detection	Limit	Sample Results
	µg∕kg		µg/kg
Bromodichloromethane	25		N.D.
Bromoform			N.D.
Bromomethane		* * * * * * * * * * * * *	. N.D.
Carbon tetrachloride			. N.D.
Chlorobenzene	. 25	* * * * * * * * * * *	. N.D.
Chloroethane	. 130		. N.D.
2-Chloroethylvinyl ether	. 25		N.D.
Chloroform	. 25		. N.D.
Chloromethane	_ 25		. N.D.
Dibromochloromethane	. 25	* * • • • • • • • • • •	. N.D.
1,2-Dichlorobenzene	. 50		. N.D.
1,3-Dichlorobenzene	50	******	. N.D.
1,4-Dichlorobenzene	50	**4 * - 5 * 4 * * \$. N.D.
1,1-Dichloroethane	, 25		. N.D.
1,2-Dichloroethane	25	*******	. N.D.
l,l-Dichloroethene	_ 25		. N.D.
trans-1,2-Dichloroethene	. 25		. N.D.
1,2-Dichloropropane	. 25	********	. N.D.
cis-1,3-Dichloropropene	. 25	*******	. N.D.
trans-1,3-Dichloropropene	25		. N.D.
Methylene chloride	. 50		. N.D.
1,1,2,2-Tetrachloroethane	. 25		. N.D.
Tetrachloroethene	. 25		N.D.
1,1,1-Trichloroethane	25		. N.D.
1,1,2-Trichloroethane	. 25		· ·
Trichloroethene	. 25	*******	- · · · · ·
Trichlorofluoromethane	25		
Vinyl chloride	50		
=	•		- 17 ± A7 5

Method of Analysis: EPA 5030/8010 Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

Arthur G. Burton



SEQUOIA ANALYTICAL

680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9222 • FAX (415) 364-9233

California Environmental Consultants 1117 Happy Valley Avenue

San Jose, CA 95129 Attn: Munir Butt Date Sampled: 10/03/88
Date Received: 10/03/88
Date Analyzed: 10/06/88
Date Reported: 10/31/88

Project: #CEC/SBW 9-88-2

AROMATIC VOLATILE ORGANICS

Sample Number

8100027

Sample Description

Soil, B3-15

Analyte	Detection Limit	Sample Results
	μg/kg	μg/kg
Benzene	· · · 25 ·	360
Chlorobenzene	25 .	N.D.
1,4-Dichlorobenzene	50 .	N.D.
1,3-Dichlorobenzene	50 .	N.D.
1,2-Dichlorobenzene	50 .	N.D.
Ethyl Benzene	25 .	470
Toluene	25 .	650
Xylenes	25	850

Method of Analysis: EPA 5030/8020


Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

Arthur G. Burton

CHAIN F SAWIFLE CUSTULE . COND
Collector: Tanker Shah Date Sampled: 10.03.88. Time: 2-30PM
Location of Sampling: 2315 East 14m Street
Dakland, A.
Project Number: CEC/SBW 9.87-2 Survey Number:
Sample Type: Grob Ground Worter
Container Type and Condition: Six humber foml Vots
Contract Laboratory Record/Name: SERVIS Analytical Car, 2549 Middle pull by laining al
Sample ID Field Information
bi-W Coras Esound Water Sande four soring Bi
Signature of the second
BI-W Corle Corner of Board Conde former Bo
br-W Grap Trourd Worley South from the
Analysis Requested: Thouse worter souther 1800 BI-W and BI-W
TRH G by EAA For Method 5030
(D) B, T, XX C by EPA Fet Method 602
(IL) Arabie water Sample B3-W by.
D EAA Meltra 5030 and
Results Needed By: 2 EAA 601 3 EAA 602, Q EAA 503 P.S.
Travel Blank: ☐ Yes ☐ No Travel Blank to be Analyzed Separately: ☐ Yes ☐ No
Duplicate Samples:
Field Blank:
Background Soll Sample: ☐ Yes ☐ No Background Soil Sample to be Analyzed Separately: ☐ Yes ☐ No
Chain of Custody:
Freid Personnel
2
Courier 9 71.
3
, voic

1117 HAPPY VALLEY AVENUE * SAN JOSE, CA 95129 * (408) 725-2644



California Environmental Consultants 1117 Happy Valley Avenue

San Jose, CA 95129 Attn: Munir Butt

Date Sampled: 10/03/88 Date Received: 10/03/88 Date Analyzed: 10/06/88 Date Reported: 10/31/88

#CEC-SBW 9-88-2 Project:

TOTAL PETROLEUM FUEL HYDROCARBONS WITH BTEX DISTINCTION

Sample Number	Sample Description Water	Low to Medium Boiling Point <u>Hydrocarbons</u> ppb	<u>Benzene</u> ppb	<u>Toluene</u> ppb	Ethyl <u>Benzene</u> ppb	<u>Xylenes</u> ppb	
8100017	Bl-W	67000	14000	2400	2500	9100 .	
8100018	B2-W	110000	17000	2600	3000	12000	

Detection Limits:

50

0.5

0.5

0.5

0.5

Method of Analysis: EPA 5030/8015/8020

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

Arthur G. Burton

California Environmental Consultants 1117 Happy Valley Avenue San Jose, CA 95129 Attn: Munir Butt

 Date Sampled:
 10/03/88

 Date Received:
 10/03/88

 Date Extracted:
 10/28/88

 Date Reported:
 10/31/88

Project: #CEC/SBW 9-88-2.

TOTAL OIL AND GREASE

Sample Number	Sample Description	Detection Limit	Gravimetric Petroleum Oil		
	Water	ppm	ppm		
8100019	B3-W	5.0	290		

Method of Analysis: EPA 3550 with trichlorotrifluoroethane and gravimetric determination.

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY



SEQUOIA ANALYTICAL

680 Chesapeake Drive - Redwood City, CA 94063 (415) 364-9222 · FAX (415) 364-9233

California Environmental Consultants

1117 Happy Valley Avenue

San Jose, CA 95129 Attn: Munix Butt

Date Sampled: 10/03/88

Date Received: 10/03/88

Date Analyzed: 10/06/88 Date Reported: 10/31/88

Project: #CEC/SBW 9-88-2

HALOGENATED VOLATILE ORGANICS

Sample Number

Sample Description

8100019 Water, B3-W

Analyte	Detection	Limit	Sample Results
	µg/L	•	μg/L
Bromodichloromethane			. N.D.
Bromoform			. N.D.
Bromomethane			. N.D.
Carbon tetrachloride	50		. N.D.
Chlorobenzene	50		. N.D.
Chloroethane	250		. N.D.
2-Chloroethylvinyl ether	50	* * * * * * * * * * *	. N.D.
Chloroform	25		. N.D.
Chloromethane	25		. N.D.
Dibromochloromethane	25		. N.D.
l,2-Dichlorobenzene	100		. N.D.
1,3-Dichlorobenzene	100		. N.D.
1,4-Dichlorobenzene	100		. N.D.
1,1-Dichloroethane	25	• • • • • • • • •	. N.D.
1,2-Dichloroethane	25		. N.D.
1,1-Dichloroethene	50		. N.D.
trans-1,2-Dichloroethene			. N.D.
1,2-Dichloropropane	25		. N.D.
cis-1,3-Dichloropropene	250		. N.D.
trans-1,3-Dichloropropene			. N.D.
Methylene chloride			. N.D.
1,1,2,2-Tetrachloroethane	25		. N.D.
Tetrachloroethene	25		. N.D.
1,1,1-Trichloroethane	25		. N.D.
1,1,2-Trichloroethane			N.D.
Trichloroethene			. N.D.
Trichlorofluoromethane		******	. N.D.
Vinyl chloride		******	. N.D.

Method of Analysis: EPA 5030/8010

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

Arthur G. Burton Laboratory Director

California Environmental Consultants 1117 Happy Valley Avenue San Jose, CA 95129 Attn: Munir Butt

Date Sampled: 10/03/88
Date Received: 10/03/88
Date Analyzed: 10/06/88
Date Reported: 10/31/88
Project: #CEC/SBW 9-88-2

AROMATIC VOLATILE ORGANICS

Sample Number 8100019

Sample Description
Water, B3-W

Analyte	Detection	Limit s	ample Results
	μg/L		µg/L
Benzene	25	• • • • • • • • • •	490
Chlorobenzene	50		N.D.
1,4-Dichlorobenzene	100		N-D-
1,3-Dichlorobenzene	100	*******	N.D.
1,2-Dichlorobenzene	100		N.D.
Ethyl Benzene	25	* * * * * * * * * * * * *	770
Toluene	25	* * * * * * * * * * * * *	160
Xylenes	25		1300

Method of Analysis: EPA 5030/8020

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

CALIFORNIA ENVIRONMENTAL CONSULTANTS



CHAIN OF SAMPLE	CUSTODY RECORD
1 - (´o b	Sampled: 11.02.88 Time: 11.A.M.
Location of Sampling: 2345 East 14 th	Street Street
Oakland, CA	
Project Number: CEC/SBIA.88.2.1	_Survey Number:
Sample Type:	
Container Type and Condition: Brass Sleeves	2 inch of 6 wellows on the
Contract Laboratory Record/Name: > QUOIA AN	2 inch & 6 inch long on ice. ALYTICAL LAB, 680 Ches aprake TY, Red wrote
Sample ID	प्या १५६। Field Information
Soil Sam	ble from aerater Pele 1(Gord
	good of the 1 Gorde
SP2 Soil Sam	the from alroter Pile 2 him
SPS Soil Som	le form acroter Pilo 3/hras
389	Le born resorter Pele 3 (Water
Analysis Requested: 1 Analyse SP, +S	Pro Sawfler vide videoly by:
The transfer of the state of th	46- 244 Test 19-40 15030
12 b, 1x tt by Fall TeAMINGO	0020
monse SP2 L. (D SED E. 1	
13 19 20 200	
Results Needed By: NOVEMBER 4. 85	Rease 503D & E. B (48 HOUR RUSHI)
VEMBER T, O	3 (48 HOUR RUSH!)
Travel Blank; ☐ Yes ₺ No Travel Bla	nk to be Analyzed Separately: Yes D No
Duplicate Samples: DYes DNo Duplicate	s to be Analyzed Consessed.
Field Blank: ☐ Yes ☐ No Field Blan	k to be Analyzed Separately: Yes D No Yes D No
	nd Soil Sample to be Analyzed Separately:
Chain of Custody:	
Field Personnel	Nov 2, 88
2	NOV 2, 88.
3. Kan Alex	/ Patp C
Lab	
(three bross Sleeves - 2/6" dia Henry	q, \
1117 HAPFY VALLEY AVENUE . SAN JE	DSE, CA 95129 • (408) 725-2644



(415) 364-9222 · FAX (415) 364-9233

California Environmental Consultants

1117 Happy Valley Avenue

San Jose, CA 95129 Attn: Munir Butt

Date Sampled: 11/02/88 Date Received: 11/02/88

Date Analyzed: 11/03/88 Date Reported: 11/07/88

Project: CEC/SBW9.88.2.1

TOTAL PETROLEUM FUEL HYDROCARBONS WITH BTEX DISTINCTION

Sample Number	Sample Description Soil	Low to Medium Boiling Point Hydrocarbons ppm	Benzene ppm	<u>Toluene</u> ppm	Ethyl Benzene ppm	Xylenes ppm
8110126	SPl	1.3	N.D.	N.D.	N.D.	N.D.
8110127	SP2	13	N.D.	N.D.	N.D.	N.D.

Detection Limits:

1.0

0.05

0.1

0.1

0.1

Method of Analysis: EPA 5030 or 3810/8015/8020

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY



SEQUOIL ANALYTICAL

680 Chesapeake Drive - Redwood City, CA 94063 (415) 364-9222 - FAX (415) 364-9233

California Environmental Consultants 1117 Happy Valley Avenue

San Jose, CA 95129 Attn: Munir Butt Date Sampled: 11/02/88
Date Received: 11/02/88
Date Analyzed: 11/03/88
Date Reported: 11/07/88

Project: CEC/SBW9.88.2.1

HALOGENATED VOLATILE ORGANICS

Sample Number

8110128

Sample Description

Soil, SP3

Analyte	Detection L	imit	Sample Results
	μg/kg		μg/kg
Bromodichloromethane			. N.D.
Bromoform			. N.D.
Bromomethane			. N.D.
Carbon tetrachloride			. N.D.
Chlorobenzene			. N.D.
Chloroethane			. N.D.
2-Chloroethylvinyl ether	. 5.0		. N.D.
Chloroform	. 5.0		. N.D.
Chloromethane			. N.D.
Dibromochloromethane	. 5.0		. N.D.
1,2-Dichlorobenzene	. 10		. N.D.
1,3-Dichlorobenzene			. N.D.
1,4-Dichlorobenzene			. N.D.
l, l-Dichloroethane			. ' N.D.
1,2-Dichloroethane			. N.D.
1,1-Dichloroethene			. N.D.
trans-1,2-Dichloroethene	. 5.0		N.D.
1,2-Dichloropropane	. 5.0		. N.D.
cis-1,3-Dichloropropene	. 5.0		. N.D.
trans-1,3-Dichloropropene	. 5.0		N.D.
Methylene chloride	. 10		. N.D.
1,1,2,2-Tetrachloroethane			. N.D.
Tetrachloroethene	. 5.0		N.D.
1,1,1-Trichloroethane	. 5.0		. N.D.
1,1,2-Trichloroethane	. 5.0		. N.D.
Trichloroethene	5.0	• • • • • • • • •	N.D.
Trichlorofluoromethane		*********	•
Vinyl chloride	. 10	• • • • • • • • •	

Method of Analysis: EPA 5030/8010

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY

Arthur G. Burton



SEQUOIA / NALYTICAL

680 Chesapeake Drive • Redwood City, CA 94063 (415) 364-9222 • FAX (415) 364-9233

California Environmental Consultants 1117 Happy Valley Avenue

San Jose, CA 95129 Attn: Munir Butt Date Sampled: 11/02/88
Date Received: 11/02/88

Date Analyzed: 11/03/88
Date Reported: 11/07/88

Project: CEC/SBW9.88.2.1

AROMATIC VOLATILE ORGANICS

ample Number

8110128

Sample Description

Soil, Sp3

nalyte	Detection I µg/kg	imit	Sample Results µg/kg
enzene	5.0	* * * * * * * ¢ ¢	. N.D.
hlorobenzene	5.0	* * * P * * 9 *	. N.D.
,4-Dichlorobenzene	10	* * * * * * * * * *	H.D.
,3-Dichlorobenzene	10		. k. () .
,2-Dichlorobenzene	10		. N.D.
thyl Benzene	5.0	• • • • • • •	. N.D.
oluene	5.0		
ylenes	5.0		. N.D.

ethod of Analysis: EPA 5030/8020

nalytes reported as N.D. were not present above the stated limit of detection.

QUOIA ANALYTICAL LABORATORY

thur G. Burton

California environmental Consultants 1117 Happy Valley Avenue San Jose, CA 95129 Attn: Munir Butt

Date Sampled: 11/02/88
Date Received: 11/02/88
Date Extracted: 11/02/88
Date Reported: 11/07/88

Project: CEC/SBW9.88.2.1

TOTAL OIL AND GREASE

Sample Number	Sample <u>Description</u> Soil	Detection Limit mg/kg	Gravimetric Petroleum Oil mg/kg
8110128	SP3	30	1300

Method of Analysis: EPA 3550 with trichlorotrifluoroethane and gravimetric determination.

Analytes reported as N.D. were not present above the stated limit of detection.

SEQUOIA ANALYTICAL LABORATORY







TABLE I
Results of Analysis


Sample	Benzene	Toluene	Ethylbenzene	Xylene	Gasoline	Total Lead
B-1	0.3	2.2	3.4	31	360	4.6
B-2	3.0	6.4	2.5	160	1,500	316
B-3	0.17	0.4	1.3	10	130	4.8
B-4	0.8	1.9	8.7	86	150	255
B-5	61	1.3	4.8	30	790	259
B-6	1.5	4.7	9.6	75	1,300	197


		T	otal	Oil & (503E)	Grease	Total Extractable as Diesel (8015	Hydrocarbons as Diesel)	
B-7				570		110		
B-8				783		65		
				· · · · · · · · · · · · · · · · · · ·				
	-0.14		ـ الم	PILES	WEED TO BE	SAMPLED 4 CESS	Now 100 APL	114












NOTE: TOTAL VOLUME OF STOCKPILE 42X17X6 = 4284 CFT 4284 CFT / 27 CFT/ CYD = 158.66 CYDS EACH CELL = 19.83 CYDS

LEGEND

VSP1-A NAME AND APPROXIMATE LOCATION

* OF SOIL SAMPLE





TANK PROTECT ENGINEERING


SITE PLAN: VERIFICATION STOCKPILE SAMPLING (7/12/95)


CREDIT WORLD AUTO SALES 2345 E. 14TH STREET DAKLAND, CA 94601


DATE	12/11/96
FIGURE	7
FILE #	267-7N
DRAVN BY	VK
CHECKED BY	LNH























TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	TPHG	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
B -1	10/03/88	15.0	3.4	NA ⁴	.310	<0.1	< 0.1	.140
B-2	10/03/88	15.0	83	NA	1.6	1.1	1.8	9.6
B-3	10/03/88	15.0	NA	NA	.360	.650	.470	.850
MW-1	05/22/91	10.0	150	NA	.460	.365	.305	.960
MW-1	05/22/91	15.0	255	NA	1.505	4.255	4.015	4.270
TH-1	08/21/91	15.0	2,775	NA	1.235	1.060	1.625	5.280
TH-2	08/21/91	10.0	360	NA	< 0.005	< 0.005	< 0.005	0.770
TH-2	08/21/91	30.0	50	NA	< 0.005	< 0.005	< 0.005	< 0.005
MW-2	08/21/91	10.0	4,320	NA	7.275	6.620	3.470	13.815
MW-2	08/21/91	15.0	160	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-3 ²	08/22/91	10.0	10	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-3 ²	08/22/91	19.0	10	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-4 ²	08/22/91	10.0	25	NA	< 0.005	< 0.005	< 0.005	0.175
TH-4 ²	08/22/91	20.0	450	NA	< 0.005	< 0.005	< 0.005	< 0.005
MW-3 ²	08/22/91	10.0	50	NA	< 0.005	< 0.005	< 0.005	< 0.005
MW-3 ²	08/22/91	15.0	25	NA	< 0.005	< 0.005	< 0.005	< 0.005
TH-5	08/22/91	10.0	10	NA .	< 0.005	< 0.005	< 0.005	< 0.005
TH-5	08/22/91	18.0	<5	NA	< 0.005	< 0.005	< 0.005	< 0.005
TMW-4	07/22/93	5.5-6.0	<.500	NA	< 0.005	< 0.005	< 0.005	<.015
TMW-4	07/22/93	10.5-11.0	<.500	NA	< 0.005	< 0.005	< 0.005	<.015
TMW-4	07/22/93	15.5-16.0	.940	NA	< 0.005	< 0.005	< 0.005	<.015
TMW-5	07/23/93	5.5-6.0	2.4	NA	.026	< 0.005	< 0.005	.053
TMW-5	07/23/93	10.5-11.0	14	NA	.900	< 0.005	1.6	<.140
TMW-5	07/23/93	15.5-16.0	16	NA	.840	< 0.005	.690	1.3
VS-1	12/06/94	19.5	1.3	NA	.010	.061	.027	.190
VS-2	12/06/94	14.5	51	NA	.61	.100	1.3	.940
VS-3	12/06/94	16.5	210	NA	1.1	.300	4.5	140

TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VS-4	12/06/94	14.5	20	NA	1.2	.094	.470	2.4
VS-5	12/06/94	13.5	100	NA	.440	<.150	2.2	8.5
VS-6	12/06/94	4.0	2.7	NA	.046	< 0.005	< 0.005	< 0.015
STK1-A,B,C,D	12/06/94	2.0-2.5	5.3	NA	<.014	<.014	.023	.12
STK2-A,B,C,D	12/06/94	2.0-2.5	9.2	NA	.015	<.014	.084	.300
STK3-A,B,C,D	12/06/94	3.5-4.0	45	NA	<.140	.180	.710	4.4
STK4-A,B,C,D	12/06/94	3.0-3.5	40	NA	.380	.140	.750	2.5
STK5-A,B,C,D	12/06/94	4.0-4.5	78	NA	.200	.780	1.2	8.1
STK6-A,B	12/06/94	2.0-2.5	9.8	NA	.052	< 0.015	.046	.240
VSP-1A	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-2B	05/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-3C	05/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-4D	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-5A	05/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	·<0.005	< 0.005
VSP-6B	05/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-7C	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-8D	05/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-9A	05/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP-10B	05/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-6	06/30/95	21.0	< 0.5	NA	< 0.005	< 0.005	< 0.005	< 0.015
VS-7	06/30/95	14.0	50	NA	.370	.070	.990	3.3
STK7(1-4)	07/03/95	3.0-3.5	290	NA	.560	.970	3.0	11.0
STK8(1-4)	07/03/95	2.0-2.5	49	NA	.100	.100	.550	1.8
STK9(1-4)	07/03/95	2.0-2.5	78	NA	.052	.036	.520	1.6
STK10(1,2,3,4)	07/03/95	3.0-3.5	22	NA	.012	.012	.032	.089
STK11(1,2,3,4) ³	07/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-8	07/03/95	16.0	33	NA	.036	.022	.066	.099

SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm1)

Sample ID Name	Date	Depth (Feet)	TPHG	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VS -9	07/05/95	15.0	42	NA	.060	.036	.089	.120
VS-10	07/05/95	15.0	130	NA	.180	.085	.250	.370
VS-11	07/05/95	16.0	81	NA	.073	.086	.160	.210
VS-12	07/05/95	21.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-13	07/05/95	16.0	75	NA	.048	.040	.078	.180
VSP 1A	07/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 2B	07/12/95	2.0-2.5	4.0	NA	< 0.005	.017	.026	.099
VSP 3C	07/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 4D	07/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 5A	07/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 6B	07/12/95	3.5-4.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 7C	07/12/95	1.0-1.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 8D	07/12/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VS-14	07/28/95	19.0	2.8	NA	.300	.016	.094	.140
VS-15	07/28/95	15.0	61	NA	.470	.042	1.2	.730
VS-16	07/28/95	16.0	38	NA	.400	.043	.420	.590
VS-17	07/28/95	19.0	14	NA	.120	.018	.150	.110
VS-18	07/28/95	14.0	590	NA	3.1	2.4	10	52
STK12(A-D)	07/28/95	2.0-2.5	-87	NA	.260	.140	1.6	3
STK13(A-D)	07/28/95	3.0-3.5	58	NA	.210	.097	.630	2.3
VSP 11A	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 12B	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 13C	10/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 14D	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 15A	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 16B	10/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 17C	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005

TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VSP 18D	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 19A	10/03/95	3.0-3.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 20B	10/03/95	1.5-2.0	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
VSP 21C	10/03/95	2.0-2.5	<1.0	NA	< 0.005	< 0.005	< 0.005	< 0.005
STK-1 A,B,C,D	05/24/96	2.0-3.0	170	< 0.005	.110	.160	.710	2.6
VS-2D	05/24/96	18.0	140	< 0.005	.170	.210	.280	1.5
VF-1	05/24/96	21.0	10	< 0.005	< 0.005	.0074	.0095	.037
STK-2 A,B,C,D	05/24/96	2.0-3.0	320	< 0.005	.100	.095	1.2	2.1
STK-1,A,B,C,D	05/29/96	2.5-3.0	1.7	< 0.005	< 0.005	< 0.005	.005	.017
STK-2A,B,C,D	05/29/96	2.5-3.0	140	< 0.005	.013	.026	.047	.094
VS-22	05/29/96	14.0	22	< 0.005	.0065	< 0.005	.020	.031
VS-23	05/29/96	19.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-24	05/29/96	14.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-25	05/29/96	19.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-26	05/29/96	14.0	66	< 0.005	.0063	.022	.024	.130
VS-27	05/29/96	18.0	3.9	< 0.005	< 0.005	< 0.005	< 0.005	.033
VS-28	05/29/96	12.5	450	< 0.005	.170	.120	.280	.390
STK-3A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	<0.005	< 0.005	< 0.005	< 0.005
STK-4A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-5A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-6A,B,C,D	05/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-29	05/30/96	12.5	470	< 0.005	.049	.085	.250	.760
VSP-20A	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-21B	07/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-22C	07/30/96	3.5-4.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-23D	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-24A	07/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005

TABLE 1
SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНG	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VSP-25B	07/30/96	3.5-4.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-26C	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-27D	07/30/96	2.5-3.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-28A	07/30/96	3.5-4.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-29B	07/30/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-20A,B,C,D	09/16/96	2.0-2.5	44	< 0.005	.075	.090	.110	.170
STK-22A,B,C,D	09/16/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
STK-23A,B,C,D	09/16/96	1.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VS-30	09/16/96	15	8.2	< 0.005	.040	.054	.250	.210
VS-31	09/16/96	14	110	< 0.005	.280	.210	.460	.490
STK-25A,B,C,D	09/17/96	1.0	210	< 0.005	.180	.098	.120	.240
STK-26A,B,C,D	09/17/96	1.0	31	< 0.005	.050	.063	.084	.250
VS-32	09/17/96	12	20	< 0.005	.120	.120	.130	.280
VS-33	09/17/96	12	7.5	< 0.005	.019	.034	.060	.200
VS-34	09/17/96	12	52	< 0.005	.190	.140	.630	.660
VS-35	09/17/96	12	29	< 0.005	.023	.130	.072	.500
STK-21A,B,C,D	09/17/96	1.0	90	< 0.005	.120	.084	.190	.320
STK-24A,B,C,D	09/17/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-30A	10/04/96	1.0-1.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-31B	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-32C	10/04/96	2.0-2.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-33D	10/04/96	1.0-1.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-34A	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-35B	10/04/96	2.0-2.5	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-36A	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-37B	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005
VSP-38C	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	<0.005	< 0.005	< 0.005

TABLE 1 SUMMARY OF SOIL SAMPLE ANALYTICAL RESULTS (ppm¹)

Sample ID Name	Date	Depth (Feet)	ТРНС	Methyl t- Butyl Ether	Benzene	Toluene	Ethyl- benzene	Xylenes
VSP-39D	10/04/96	1.5-2.0	<1.0	< 0.005	< 0.005	< 0.005	< 0.005	< 0.005

¹ PARTS PER MILLION.

² ALSO ANALYZED FOR TOTAL RECOVERABLE HYDROCARBONS BY ESE; SEE ESE 12/23/91 REPORT FOR ANALYTICAL RESULTS.

³ ALSO ANALYZED FOR TOTAL PETROLEUM HYDROCARBONS AS DIESEL: ALL ANALYTICAL RESULTS WERE NONDECTABLE.


NOT ANALYZED.

TABLE 2 SUMMARY OF EXCAVATION GROUNDWATER SAMPLE ANALYTICAL RESULTS (ppb^1)

Sample ID Name	Date	ТРНС	Benzene	Toluene	Ethyl- benzene	Xylenes
GB-1 ²	05/12/95	<50.0	<0.5	<0.5	<0.5	< 0.5

¹ PARTS PER BILLION.

² EXCAVATION SAMPLE



EB-BOVA-1



APPENDIX A
BORING LOGS

· -	CHEMICAL ANA	LYSES	!	ł	SAMPL	되 • .	
	Laboratory	1 Field	- E	DEPTH (feet)	d 2	U. B. C. S.	
WELL		T .	BLOW	155	TRITEROR NUMBER	0.2	
CONSTRUCTION			۱äğ	152		1	SOIL DESCRIPTION
Constitue	TPH	PID	٥ – ا	102	B 2	1 38	į –
Ţ.	(ng/Kg)	(ppm)	Į.	1 _		1 2	•
			i	10	 	1	
		!	!	!	! 		
	ļ	!	<u>!</u>	! -	! 	Ⅎ	
			!	<u> </u>	↓ ↓	-{	
ů		!	<u> </u>	<u> </u>	11	. j .	Sand Sitt to silk Sand with minor clay,
			4	5		ML	derkoreerish gray lease, dry
	<u> </u>	20	67	12		1500	and the last deposit of the last
		120		i	-	-1	CO TTELLO, PERY STIGAT GOOF
<u> </u>		<u> </u>		<u> </u>	<u> </u>	-	
		<u> </u>		<u>!</u>	<u> </u>	4	<u> </u>
		L	ļ	• 1	<u> </u>	₹.	Ground water in beat filled pit @ 9"
				//			Chan sitt to Silty Clay, dark anapoist
		20		10		MYCL	gray wet, loose, no stain no color
<u> </u>		70				1	37-7- 2001, 1883C, NO 8/8,2,46 626/
		!				-	
<u> </u>		!	_		<u> </u>		<u></u>
		1 1)	•	l I	į į	
				10		MLI	
		100		15	20143	MYCL	Same as above
	2775	~~		-	1000		
1		<u>, </u>		ļ	<u> </u>	4 ´ !	TO 16'
			i	!	1	4	
		<u> </u>		l	<u> </u>	1 1	· · · · · · · · · · · · · · · · · ·
1]	
		 			1	1	
 		! !	 ;	-		ł l	
<u> </u>		!!	!	!	 	{	
<u> </u>		<u> </u>			<u> </u>	! !	
			ŧ	·	İ	1 1	<u> </u>
		i				1 1	
		i 		- i		1 1	
		 	 ¦			()	
			!	!	!	! ;	
1			!		<u>!</u>	, ,	
1		<u> </u>	1		<u> </u>	l t	
				- 1	1	1	· · · · · · · · · · · · · · · · · · ·
			ĺ	1	Ĭ	ì	
 		- 1	}		 	l 1	
		!!	!	!	!	! !	
<u> </u>				!	 	! B	
		l				! [
		1	1	1	1	1	
		1	i			l [
				1	ī	1	
} -			- i				
			!		1 —		
<u> </u>	<u></u>						
111			<u>l</u>	1	<u> </u>		
		1	. 1			· •	
	i				1	i i	
 		 }		 }	1	h	
1-1-1		 1			 		
		!	<u></u> !		!	' F	
<u> </u>	·				<u> </u>	L	<u> </u>
		_ F	_ [4	<u> </u>	ł	
	i		i	T		r	
		}	 -	-i		}	
				-	 	}	
 			- 	!	 	J.	
	l					<u>L</u>	<u> </u>
			_ 1	1	<u> </u>		
					i	ſ	
						r	
		i -			 	F	
I			!			j -	
		<u>!</u> -	<u> </u>		!	<u>J</u> .	
	<u></u>				<u> </u>		
Geologisties &	- Mark Ma	pary	40.	R. 6.	10-	:/ler:5	8 / 5 nr 1 47 =
1	•					-	PLATE
Wong's	٠	-			i	LUG	of.BORING
a ong s	ا و منال فسیلی او		•		į.		
· ·						• •	TH-1
Project Number: 20	-8010-1		8	17/0	71	-	7 H-/ Page / ol/
	-0417 <u>7</u>		<u> </u>		- 1		

	CHEMICAL ANA	1 7555	ì		RYMPL	Εİ	1
.1 .	Laboratory	1 Field	-1	DEPTH		C.S.C.S.	1
WELL	0000121017	1	2000	F	HUNDER R	33	
CONSTRUCTION		1	1 2 2	15.	면 문	3.5	SOIL DESCRIPTION
1001.5.1.0	TPH	PID	٥ – ا	02	8 3	1 28	
	(eg/Kg)	Keem	<u> </u>	_م_ا	Я -	!	•
	7. 05	1	<u> </u>	<u> </u>	<u> 11</u>	_1	
		1	<u> </u>	1	11	_	
			1		11		
		1		1	11	3	
6			4	15		april	5:1ty Clay with truce time sound.
}i		30	7.	12] ~ mc	dark greenish gray, slightly moist medium denne good plasticity, us stain, trace a procerow like alo
]		11]	medium denne good plasticity
				1	TI]	we stain frace photocarban/ike no
		T			1	7	7
			4	/A		7	
	360	1050	77	10	804-	5 M/nL	Silt Sand and hoiner clay
 	700	i	<u> </u>	i i		1 1	light gray is h preeze, stoly moist
				i	 	_	lasse we stain strong sor
 		·		i -	 	1 1	78034, 20 17 20 10, 31 1 20 10 VI
			-			1	For they minareilt arenish brown, roist, wood
 		200	7/2	15		٠,	that they marrill presidence, moist, good exercisity, we stain, moderate a for
 		. 200	/ 7	i 	n —	5M/CL	
	· · · · · · · · · · · · · · · · · · ·	-			l:	 	Groweth found, significant clay and sift, yellowish brown, slightly maist, we staring
				-		1	yellowish a course, slightly Maist, we staring
 	 				<u> </u>	字? 一	very slight ador
<u> </u>			14	20		04	
		100	74			1 55	Part Chay minor sitt, granish house, moist,
					!!	{	good plasticity, no string trace abot
					!	{	
					<u> </u>	4 1	
<u> </u>		!	9	25		CL	
		20	20			1 55 1	Same as aware, maist, no afor
					<u> </u>	∤	
					<u> </u>	!]	
			(]]	
		50	<u> </u>	لحدا		: 1	<u></u>
	50	501	10,7		8014-5		Tame as above
			[1) v [TA31'
						!!	
					<u> </u>) <u>(</u>	
			(1	jl	
		1	j	(i [
					1	1 (
					1) (
		-) [
			- (· [
	i						
		1	 i		1	j t	
			- i		1		
		- i	Ţ			l t	
		 i	 	\dashv	1		
 					i		
	1	 ;	i	- i		1	
 				 i	 	 	
		 -	i	¦	1	, h	
 					 	 	<u> </u>
		 			 	<u> </u>	
1-1				 	-	 	
					 	ŀ	
						├ - ├	
 	<u></u>	1	<u>!</u>				
60-6-1-3-0		<u> </u>		<u> </u>	<u>. </u>	1/52: -	
GeologistiesE	· Mark May	gung	ee,	A. 6		://er: 5	PLATE
	_	-				_	I
		•			•	LOG	of. BORING
Wong's	Tanki				I		
					Ī	• •	TH-2 Page/81
Project Number: 65	-8714-1		#	12/1	/ I	,	/ // /- Page/ol/
	00177				· #		

						No. of the second	State of the state
WELL	CHEMICAL ANA Laboratory TPH (ng/Kg)	PID	ELOU COUNT	DEPTH	MCHBER A	U.S.C.S. Design.	SOIL DESCRIPTION
		12	<u> </u>	٦	 	4	
		 	<u> </u>	├—	+	-	
		\vdash]	
			4	5		حدر	Clay, truce sand, silt, yellanish framaps
		20	7/	 -	 	- /~~	derte greenish gray,
		_		1	 	<u> </u>	
				<u> </u>	!		
	10	NO	9.4	10	80/4-2	04	agenic Clay Sark graceist gray
	10	~		<u> </u>			us ofor
					!!	1	
			15	1	∐	-{	Est Clay mingrailt, light green moit.
		70	3,5	15		ادد	medium dence and plasticity
							no stain, minor behovemen like abor
				1	f 1	-	
	·	·	/2	20]	
	10	70	7.0	LV	80/4-9	C C P	Same as above, light brownish ye llow
		<u> </u>			 	 	slight odor
					-		
				25		1	
		100	1/2			دد	same as above, very moist no abor
						i	
	<u> </u>	j	<u> </u>				
		1	105	30		201	5: 1th Gravelly hand significant chap light
	<u> </u>	100	إكرز		Y 1	V-	yellowish brown, very moist, madiwa dance no stain no male TO3)
	i		i		i		
		!	!	{	<u> </u>	,	
		 	<u>1</u>				
			i				
					ļ		
1							
			. 1			·	
			!		ļ		
					-		
		- i	ij				
						[
						.	
						t	
						į	
					 	ŀ	
						ł	
						[
				- 	 		
GeologistiesE	- Mark May	موسع	ee,	A. 6	O.	:11er: 5	O/5 PLATE
Wong's	Tanki	:				LOG	of. BORING
Project Number: 65			8/	z/19	/	• •	TH-3 Pogo/al/
	7 · 7		-,				

					SAMPL	£.	1
	CHEMICAL ANAL	Y 5 2 5				i	1
	Laboratory	Field	콧도	= 1		35	
WELL			BLOU		AYERUA HUMBEN	U. B. C. B.	SOIL DESCRIPTION
CONSTRUCTION	TPH	PID	ن 🛥	راة	9 3	38	
1		(PPM)		DEPTH (feet)		1 2	
	(ng/Kg)	V/ J		-			
<u> </u>						7	
					1	1	
					1	7	
			7.	-			Clare lark argenish grave stightly
			3	-		- 26	Moist, wallen danse, good planticity
		80	-42			-1	No stain
					! 	┨╌╌	37 42/10
T	<u> </u>				 	- [
					 	[11 11 11 11 11 11 11 11 11 11
			4	10		30/66	Garrelly Char, Sand, South gray to black
	2.5	140	79		80/4	의 100	Statthenist, slightly Source, both stairs,
			<u> </u>		<u> </u>	_	makerate hydrocarter like ofor
					<u> </u>	_}	
			144			7	Fat Chy minorsilt, light green, noist,
	<u> </u>	20	129	75		7 66	medicalouse, good plasticity, us stain
		7.0	<u> </u>			7	Wight ador
					-	┪	
			<u> </u>	4	-	-L.,	
	<u> </u>	<u> </u>		<u>-</u>	-	- 5m	Chan C'M Sand Cake was a cotimotal
	<u> </u>		6	20		500	sedim dense is stain, ordered a for
	450	20	1/2		1014	<u>'''</u>	medium dense, no stain, moderate a dot
			<u> </u>	<u> </u>	<u> </u>	→ ∨	1021'
}					<u> </u>	ᅬ	
-			Π	1	l I		
				1]	
				1 .			
	<u> </u>	<u> </u>	<u>'</u>	`	 	7	
	<u> </u>		! -	•	 	-1	
	<u> </u>	!	! -	<u> </u>	 		
1	<u> </u>	<u>!</u>	<u>!</u> -	<u>. </u>	! :	-1	
	<u> </u>	<u>!</u>	<u> </u>	ļ	! !		
			<u> </u>		<u>! </u>		
	1	<u> </u>	<u>L</u>	!	!!		
		f	<u> </u>	1	Ц	_	
 				<u> </u>	<u> </u>		
					I I		
	<u> </u>	-	ì	ì	П		
	<u></u>		i 	i 	11		
			 	i	H		
<u> </u>	<u> </u>	!	-		 	_	
<u> </u>	<u> </u>		 	! 		┥ .	
[<u> </u>	!	1	₩	-{	
	<u> </u>	 	 	!	 	[
			<u> </u>	<u> </u>	 		
			1	 	!	-1 -	
				<u> </u>	<u> -</u>	-1	
	 				11	_1	
	† 	$\overline{}$	ī	i	11	_	
	 	<u> </u>	1	ī	П		
	 	-	1	i 	1	7	
	 	 	-	1-	i i	- լ	
	<u> </u>	 		!	++		
	<u> </u>	 	1	!	! 		
	<u> </u>	<u> </u>	 	 	! 		
	<u> </u>	<u> </u>	ļ	<u> </u>	 		
		1	<u>!</u>	!	 		
	1		<u> </u>	<u> </u>	!!		
				1	11	-1	
	1	1			11		
Geologisties	E . M. L. M.			R.	s. I.	Oriller:	TO S PLATE
20019111103	O THE WATER PARTY		<i>-</i>	,	· •	 ·	, , , , , , , , , , , , , , , , , , , ,
							CALBORING
	سد ۱				1	r O	G of BORING
Wong	's Tour	•			1		•
-					I	• .	TH-4 Page/d/
Broiser M	1.0000		•	1/2/	191	•	l str. m.
Project Number. 2	2-50197						

Martin and April 2011 and the Control of the Contro	The state of the s						
	CHEMICAL ANA	.Y5E5]	1	HOTEROWS ROTER OF THE STREET	틱 •.	
	Laboratory	Field	- <u>E</u>	DEPTH (feet)	₩	U. B. C. S. Desion.	
WELL			BLOU COUNT				
CONSTRUCTION			Z Q	152	监手	i in	SOIL DESCRIPTION
00,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	TPH	PID	-0	102	H 3	1 28	
•	(ng/Kg)	(ppm)	ŧ,	_	# *	3-	•
		'\\\ 	1	10	11	1	
	<u> </u>	 	!	! -	! 	-1	
	ļ	<u> </u>		! -	! 	4	
	<u> </u>			<u> </u>	!	4	
	!	<u> </u>		<u> </u>	<u> </u>	j	
*			3	İr		1	Fat Clay, miner time sand dark greensh gray
	<u> </u>	20	37	-		7 64	stightly moist medium Seuse,
				·		-	2 of add the officers
	<u></u> _				 	┫╻	good pasticity, no stein, no afor
	<u> </u>				! -		
	·					j	
			- I	, A	~ ·	1	Clay with silt sand, Sant greenish gray
		20	70	10	2014-14	7/100	Elishthemoist up stain no abor
} -	10	00	10			4,_	Clay with silt sand fart green therey Slightly moist, we stain no abor
						-{	
						 	
) [lI		1	<u> </u>	
			14	100		101.	Engenined and Chy light green.
} 		20	77. i	15		1/5M	tive grained sand, Chy, light green,
<u> </u>			- 3	-	1	1	
			!		-	100	
			!		-	<u> 루</u>	<u> </u>
· [<u> </u>] =	
i			7	- 4		<u> </u>	Sith Charge Sand, light yaltonsi gream
	20	10	24	ZV	80/4-15	100	sorvered, redundance, vestain, no obot
		70	77		1		TO 21'
<u> </u>					-	i ' i	70 67
			<u> </u>	!	<u> </u>		
	·	l		1	<u> </u>]	
		1	ī		1	}	
			1	<u>. i</u>	1	1	
					'	(
		!		¦	!	i I	
		!			!	!	
	(<u>i</u>	!	<u>!</u>	! !	·
		Ī	•	ŧ	!		:
		1		Ī	1]	
 			i	i	 	1 1	
ļ!		!		!	!	()	
<u> </u>		 !	!	!	 	f l	
<u> </u>		!		!	<u> </u>	ł I	
		1		{	<u>†</u>	•	
		1		- 1	1		
 		i		i	ì		
		}	 ;		! -	1	
<u> </u>					!		
<u> </u>		-			ļ		
<u> </u>	1			1	<u> </u>	1	
	i		. 1		ľ	1	
					1	 	
 				1		\ !	
 - - 						{ · }	
		Ţ			[! !	
	<u>l</u>				<u> </u>	; <u> </u>	
		1			<u>l</u> j	i i	
	l		i	1		ı	
	}	- i	i	- i		ı i	
 	 }-	 i	 -		i i	;	
 -			!	 !	<u> </u>	;	
1	1					· L	
				1		l [
				1		• [
			- i	 t		Ì	
			 {-			, <i>ì</i>	
 		<u>!</u> -	<u> </u>	 }	 	` }	
			<u> </u>		! 	<u>,</u>	
<u> </u>	<u> </u>			<u> </u>			
Geologisties	- Mark Ma	-	60.	A. 6.	100	1101.5	PLATE
"	<u>-</u> . 7	- 0					FLAIE
1							
\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \	، سيد ،	-			Ŧ	LUG	of.BORING
wong:	Taxi				ı		•
						• •	ナリッド。
Project Number.	د بده سری ه		-	1.16			TH-5
winder. 22	-5014-1			<u> </u>			

CON	WELL ISTRUCTION	TPH	PID	EL DU COURT	OEPTH (feet)	PETER STANFOR	U. S. C. S. DESIGN.	SOIL DESCRIPTION
WELL GAT	COVER	(eg/Kg)	(cem)	<u> </u>	10	<u>H</u>	-	
	, ,				<u> </u>		j	
N			<u> </u>		<u>!</u>	-	{	
			 	-	 _	<u> </u>	i	Organic Clay trace site sail served,
6. \	}		5	36	1		04	Lock grante black, very slightly maist,
1	6					ļ	l	molivadense, good dasticity no stein
-	4		<u> </u>	<u> </u>	<u> </u>	 	Ì	nonfor
-			 	5	·			
- 1	Bestoute	150	35	100	10	8014-1	04	Same as above miner oilt, shell frequents
7								moderate hydrocarton like abor
*			<u> </u>		<u> </u>	4		
				9				Fat Chy trace sitt, grayish brown 10: st,
	- 4	255	45	9 25	13	8014-2	رد	ned in face sood desticity area stails
					<u> </u>	<u> </u>	∇	strong oder
- (4	- \		1		<u> </u>		로	
-+	14			4				5. Hr. Grave II Fand gray saturated, Isase,
	, , , , , , , , , , , , , , , , , , ,		12	79	20		3M	gran stain, no demote a for
a								
7			<u> </u>	<u> </u>				
9				! 		-		
- 3					25.		5m	Jame as above brown, so stain, wo ofor
Ż						!		
4	<i>N</i>					-		
	}		-		30	-		Fat clay minor sand brown, saturated,
У	<u>Q</u>				70		دد	nedian here good photioity, no stain, no odo,
0/			<u>! </u>			-	sw.	wall grafed Earl
1		<u> </u>	1					
632					35		ou	well presed Grove! TD 35"
								TO 35'
1				i				
			 - 			1		
							-	
						ļ		
							٠	
- i								
<u> </u>			<u>! </u>			<u> </u>		
!					-	 		
			 i					
						<u> </u>		
			-			1	İ	
			<u> </u>			 		
(30-	lander to the				A C	1 10	1/08.	consolidated Testing PLATE
-		5 - Mark Ma		7 22	,-•, u			G of BORING
	Wong	5 Tanks	• -			1		
	•				_		• .	MW-1 Prolate
D	t Number: 62	a 00111		£	121	6 / E	•	hate, #1

WELL CONSTRUCTION	TPH	YSES Field PID	BLOU	DEPTH (feet)	NUMBER ASSESSED	U. S. C. S. DESIGN.	SOIL DESCRIPTION
EAL COLO	- 	1			-		
					il	1 1	
N .]	
*\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			13,0	5			5.14 Chy with niver gravely sand, Lank averish gray, slightly moist medium
		90	76				danse good electicity no stain.
7						L	very slight by Moserbar like after
			 		-		
Bestonite	4320	360	133	10	8014-6	5M	5:14 Sand stratty meist dark gray
000001						L	rouse, grown stain, strang ador
À					-		
			7	10	-	ĺ	Fift Clave, Sandwith minor gravel, light
,N	160	250	150	15	8014-7	3M/EL	greenish over, no st. modern dense.
N N					<u> </u>	모	no stain, very slight afor
N N			<u> </u>			=	
				20		300	same as above servated, no abor
0 0				20		SMEL	
9 1							
- \					i		
10 10				25	i	ا . ا	Fat Clay, orecrish brown, saturates
2 5		!		23 .	<u> </u>	C4	medium danse go Delosticity , 40
					1		staring an oder
- \		i			i		
9 3		!		30		د د	
7					<u> </u>		seme as above
	<u> </u>						
						دد	
277		!		35		├── - ─	same as above
					+	,	7035
					!		
						r	
		!			 		
					 		
		}			+		
 				<u>;</u>			
		- 1	!		 		
	i						
Geologistiese	•		p er,	A. 6		//er. 9 L O C	of. BORING
Wong	5 Tanki				1		·
Project Number.			8	/z/	,/	. /	nw-2 Propolati

Ţ

WELL CONSTRUCTION	Laboratory TPH (ng/Kg)	Field PID (ppm)	BLOW	DEPTH (feet)	STATE OF THE STATE	U.8.0.9. Destan.	SOIL DESCRIPTION
100	(/9//4)	1			<u> </u>		
					 		
N G		 					
0)			۲.	5			Kat Chy, trace grove / 4 filt Sand, Lank
4 4		40	36	- 1		64/5m	medium desse, good fastisity, no star
0 - 8		╫┈╢			-		no odor
10			9	10	901412	06	Drawic Chy, receich brown, mist, nedium dense good short is ty, no stair
Bestonite	50	w	ુન		yair ju		re obor
<u> </u>		-		<u> </u>			
- 1		1 1	5 13 19	15	Ø1/4-13	s m	silty send dank gray, maist, loose, mask
,,	2.5	70	79		W17-15		700 AV 8F
N		 					
N N						\$	
				20		D Sm/cc	5: 14 Claver Sand gray saturated,
1		╀┈╌╏					200, Vm 20124, NO 31010, 11 200.
19	<u> </u>	╁╌╏		-			
9 6	 				1		
7				25	<u> </u>	دد	Fat Clay greenish frown seturate
7		!!					nedium deuse good desticity
70	ļ	┼╼╼╏			-		20 3/2-12, NO 00/1-
- (2		i i					
N. W.		1 1		20	<u> </u>	CL	
7		!!		,	-	42	Same as above
9		 			 		
		 				 	
				35	ļ	-522	50/th, Sand light growing saturated loosly nothing as
SAC		-{{			<u> </u>	ľ	7033
		-					
	 	-				Ì	
					<u> </u>	•	
		1		<u> </u> -	ļ <u>. </u>		
	<u> </u>	-			 	ķ	
	 						
				<u> </u>	<u> </u>	Į	
	<u> </u>			!	 		
	 	┤──¦		 	H	l	
		1				}	
					! 	ł	
	 			}	 	i	
	<u> </u>	 		<u>i </u>		1	
						ł	
	1	لسل			11	-://er::	1015
Geologisties	5-Mark M	agan	y •••	, 17. 6	` [~		PLATI
					1	10	G of. BORING
Wona	's Tank	,			1.		•
					. 1	·· /	nw-3
Project Number: 2	ال دور مصوص مص		_	/2/1	6 / E	. /	restriction of the second seco

Ī

...



APPENDIX B ANALYTICAL REPORTS AND CHAIN OF CUSTODY

5327 Wingfoot Drive Bakersfield, CA 93306 (805) 872-4750

Laboratory Results For : Wong's Taxi Taxi 2345 East 14th Street Oakland, CA

Date Received : 5/24/91 Date Analyzed : 5/27/91 Analyst : J.S. Johnson Lab No. 910069

Sample Matrix ; Soils

	Benzene mg/kg	Toluene mg/kg	Ethylbenzene mg/kg	Xylenes mg/kg	Tot Pet Hyds mg/kg
мw-1@10'	.460	.365	.305	.960	150
MW-1@15'	1.505	4.255	4.015	4.270	255
QA/QC Sample % Recovery	86	79	97	102	86 Gasoline

All Results Reported in Milligrams per Kilogram ND = Non Detectable ; EPA 8020 (.005 mg/kg)EPA 8015 Modified for Gasoline (5 mg/kg)

Analysis of Volatile Aromatics ; EPA 8020

*Analysis of Total Petroleum Hydrocarbons; EPA 8015 MOdified for Gasoline

*The TPH Method for Gasoline is the Calif DOHS Recommended Procedure

Certificate Number: E739

Mobile Labs Inc.

5327 WINGFOOT DRIVE BAKERSFIELD, CALIFORNIA 93306

(805) 872-4750

CALIFORNIA • NEVADA • ARIZONA

CERTIFIED FULL SERVICE ON SITE ANALYTICAL LABORATORIES

SAMPLERS SAMPLE SAMPLE ID. NO.	O.: S-S (SIGNAT DATE	0/4- URE): Mag TIME	-/	SITE N	AME: // O A DDRESS SAMPLE MATRIX	sant 19th Street out	Z MO. OF MO. OF CONTAINERS			A CONTRACTOR OF THE PARTY OF TH	y		//		-	REMARKS
8014-1	5-22-91	/1:45AM	N		foil	mw-1210'	1	1								
8014-2				N	50i/	mw-1/2/15	1	1	1							
															···	
								ļ								
							-									
							_									
	-															
											-					
																· · · · · · · · · · · · · · · · · · ·
								-								
65.00	LIED BY	(0)(0)(4.7)	IDE)		<u>.</u>	DECEMED BY (SIGNATURE)	RELIN		IED D	V /61	CNAT	1165	لِــا			RECEIVED BY (SIGNATURE)
RELINQUIS	HED RA:	(SIGNATI	74E) [ATE	TIME	RECEIVED BY (SIGNATURE)	I LEFIN	wulst	ieu B	1 (3)	GIVA I	une)	D.	ATE	TIME	neceived of (SignA) une)
RELINQUIS	HED BY:	(SIGNATI	JRE) [DATE	TIME	RECEIVED BY (SIGNATURE)	RELIN	QUISF	IED B	Y (SI	GNAT	URE)	D	ATE	TIME	RECEIVED BY (SIGNATURE)
RELINQUIS			<u> </u>	ATE		RECEIVED FOR LABORATORY BY (SIGNATURE)	DATE Sby/		TIME 130	REM	MARK	S:	•	,		

5327 Wingfoot Drive Bakersfield, CA 93306 (805) 872-4750

Laboratory Results For : Wong's Taxi Taxi 2345 East 14th Street Oakland, CA

Date Received: 8/23/91 Date Analyzed: 8/24/91 Analyst : J.S. Johnson Lab No. 910124

Sample Matrix ; Soils

	Benzene mg/kg	Toluene mg/kg	Ethylbenzene mg/kg	Xylenes mg/kg	Tot Pet Hyds mg/kg
TH-1@15'	1.235	1.060	1.625	5.280	2775
TH-2@10 ·	ND	ND	ND	.770	360
TH-2@30 *	ND	ND	ND	ND	. 50
MW-2@10'	7.275	6.620	3.470	13.815	4320
MW-2@15'	ND	ND	ND	ND	160
TH-3@10'	ND	ND	ND	ND	10
TH-3@19'	ND	ND	ND	ND	10
TH-4@10'	ND	ND	ND	.175	25
TH-4@20'	ND	ND	ND	ND	450
MW-3@10'	ND	ND	ND	ND	50
MW-3@15'	ND	ND.	N D	ND	25
TH-5@10'	ND	ND	ND	ND	10
TH-5@18'	ND	ND	ND	ND	ND

All Results Reported in Milligrams per Kilogram ND = Non Detectable; EPA 8020 (.005 mg/kg)

EPA 8015 Modified for Gasoline (5 mg/kg)

Analysis of Volatile Aromatics; EPA 8020

*Analysis of Total Petroleum Hydrocarbons ; EPA 8015 Modified for Gasoline *The TPH Method for Gasoline is the Calif DOHS Recommended Procedure

Certificate Number : E739

5327 Wingfoot Drive Bakersfield, CA 93306 (805) 872-4750

Laboratory Results For : Wong's Taxi Taxi 2345 East 14th Street Oakland, CA

Date Received: 8/23/91
Date Analyzed: 8/24/91
Analyst: J.S. Johnson

Lab No. 910124

Sample Matrix Soil and Water

	• • • • • • • • • • • • • • • • • • • •				,
-	Benzene ug/L	Toluene ug/L	Ethy1benzene ug/L	Xylenes ug/L	Tot Pet Hyds ug/L // 🎺
MW-1 (Water)	2150	9345	2145	23,150	2,090,000
MW-2 (Water)	ND 🤞	ND	ND	ND	10,000 = %
MW-3 (Water)	N D	ND	ND	ND	ND

Sample I.D.	Total Recoverable Hydrocarbons mg/kg
TH-3@10'	60
TH-3@19'	20
TH-4@10'	40
TH-4@20'	1600
MW-3@10'	90
MW-3@15'	40

All Results Reported in Milligrams per Kilogram or Micrograms per Liter ND = Non Detectable; EPA 602 (5 ug/L)

EPA 8015 Modified for Gasoline (5000 ug/L)

EPA 418.1 (10 mg/kg)

Analysis of Volatile Aromatics; EPA 602

Analysis of Total Recoverable Hydrocarbons; EPA 418.1

*Analysis of Total Petroleum Hydrocarbons ; EPA 8015 Modified for Gasoline

*The TPH Method for Gasoline is the Calif DOHS Recommended Procedure

Certificate Number : E739

Jeff Gohnson, Chemist

CALIFORNIA ● NEVADA ● ARIZONA - ...

BAKERSFIELD, CALIFORNIA 93306

(805) 872-4750

CERTIFIED FULL SERVICE ON SITE ANALYTICAL LABORATORIES

PROJECT	NO ·			SITE	IANE.		<u> </u>		7	1 2	7	, ,	7	
58	" نگھر	914	/- <i>j</i>	i		y's Taxi	ERS		Ē		/ /		/	
SAMPLERS	S (SIGNA	TURE):		SITE A	DDRESS:		—dō <u>₹</u>	/	16/	' \V \/		//		REMARKS
mil	EM)	gal	gel/	2,	345	East 14 M Street	P SE			3 W		/ /		, TEMPINO
SAMPLE ID. NO.	DATE	TIME	СОМР	GRAB	SAMPLE MATRIX	SAMPLE LOCATION DESIGNATION	ON Ö	1	% d	ÿ vÿ	/ /			•
304-3	3/2/2/	10:2010			soil	TH-10151	1	1	1	A			Gas	Tank Only
824.4		11: 15AM			1	THE 8.10'	1	1	عر	30K				Tank ONLY
2014-5		12:3000			_	THE 230		1	2	A			Gars	Tank oak
8846		Z:007M)	.!			mur @ 101		12	2	ng .			Gars	Tank only
80147	-	ZIOPM			 	mura 151	$ \parallel$ $-$	2	2	Ryk.		_	695	Tank Only
8N48	422/4/	7.30AA	 		 	TH-3010		ν	2			64	ve an	I worde oil tanks
8049	 	8 ×200	!		 	THU3 @ 19"		2	2	2		a	s du	I wante oil tanks
8014-10	 	7:55An	1			TH-4 D10	-	2	2/			0	ran	Dwarte oil tanks
80/4-1		10:1514	<u> </u>			74-4 @20°			<u>y</u>	2		44	15 de	I waste oil manks
2014-12		11:15AM	1			Mars @ 101		u	1/			6.	vs an	I waste oil withs
B0/4-13		I SOM				MW-3 (8) 15	_ {}_	1				6	s der	I waste oil runks
8014-14		2.00	 			7HS 0 10		ν	2	W			Ges 7.	ant only
8014-15		2:25 PM		· · · · · · · · · · · · · · · · · · ·		THUS @ 18"	3		~	A PAR				Tank Only
					<u> </u>									•
RELINQUIS	HED BY	SIGNATI	IIRE) 1 -		<u></u>	RECEIVED BY (SIGNATURE)	Inti mo			V (616333	10 Et 1			Income and the second
ALLE HAGOIO	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	(SIGNATI	5112)	ATE	TIME	RECEIVED DT (SIGNATURE)	HELING	UISH	יבח מ,	Y (SIGNATI	UHE)	DATE	TIME	RECEIVED BY (SIGNATURE)
RELINQUIS	HED BY:	(SIGNATI	URE) D	ATE	TIME F	RECEIVED BY (SIGNATURE)	RELINO	UISH	ED B	Y (SIGNATI	JRE)	DATE	TIME	RECEIVED BY (SIGNATURE)
RELINQUIS	HED BY:	(SIGNAT	URE) C	ATE	TIME	RECEIVED FOR LABORATORY BY	DATE	1	IME	REMARKS	L S:		<u> </u>	<u>L </u>
Mark	1 R 1	Vagar	ge 7	3/9/5	5:30PM		8/23/	13	135]		,		
		" "		- /		() 00//]				

S


Mobile Labs Inc.


5327 WINGFOOT DRIVE BAKERSFIELD, CALIFORNIA 93306 CALIFORNIA • NEVADA • ARIZONA

(805) 872-4750

CERTIFIED FULL SERVICE ON SITE ANALYTICAL LABORATORIES


PROJECT	NO ·			İsit	E NAME:						7		7	, , , , , , , , , , , , , , , , , , , 		7	AL LABORATORIES
1	3-8c	0/4 TURE):	<u>~/</u>	1	E ADDRESS	ong's Taxi	<u></u>	CONTAINERS		S C			Ι,	/ /	/ /	/	REMARKS
	-/6	7/1/2			7.24	5 East 14 Street	واب.		/	W	, Q)	W	_ /	- /			NEWANKS
SAMPLE ID. NO.	DATE	TIME	CON			SAMPLE LOCATION DESIGNATION	ON	S	/ 8	8 V	\$/ v	%					•
MW-Z	8/23/4	9.30t	,		unte	nw-z	- 4	7	1	1	V						
MWY						MW-3			V	مرد	1						
mw/	123 P.J	1/20/1	_			mw-1			2	1	/						
			<u> </u>					_				ļ	ļ				
			-									<u> </u>					
			-			·	_	_				_					
	<u> </u>						_	_									
<u> </u>				-													
<u> </u>							_				ļ						
			ļ	_				\dashv									
			 					_				<u> </u>	_				
						<u> </u>		-									
								4								· <u> </u>	
		1	<u> </u>				_		_								
RELINQUIS	HED BY:	SIGNATI	JRE) I	DATE	TIME	RECEIVED BY (SIGNATURE)	T DE ()		1161	<u> </u>	V (C)]			1-2
	,,	= : = :		DATE	TIME	HEOLITED DI (SIGIRATURE)	RELI	NUL	HGIL	EN B	T (SI	JNA I	UHE)	D	ATE	TIME	RECEIVED BY (SIGNATURE)
RELINQUIS	HED BY:	SIGNATI	JRE)	DATE	TIME	RECEIVED BY (SIGNATURE)	RELI	NQI	JISH	ED B	Y (ŞIC	GNAT	URE)	D	ATE	TIME	RECEIVED BY (SIGNATURE)
RELINQUIS	HED BY	SIGNATI	IDE:	DATE	70.75	BECEIVED FOR LABORATOR	<u> </u>										
AL A		oldina!	- I	DATE		RECEIVED FOR LABORATORY BY (S/BNATURE)	DAT				FIE)	JARK	S:				
maye	rijag	rang l		<u> </u>	5:35pm	Je Mar	8/2	3/9	11	75					,		
											<u> </u>						





APPENDIX F

CERTIFIED ANALYTICAL REPORTS AND CHAIN-OF-CUSTODY DOCUMENTATION



ក្ស ស្តុំ ស្តុំ 00000 FT TMW-4 0 ASPHAL T DRILLED HOLE AGGREGATE BASE (GW) hrown dry no odor. CLAY (CL): black, scattered sand, dry. CEMENT no odor. VAULT BOX 5 CLAY (CL): brown. scattered sand, stiff to very stiff, dry, no odor. LOCKING CAP CEMENT BLANK CASING 10 BENTONITE CLAY (CL): mottled green/blue, scattered sand, gravelly at 14.5°, very stiff, dry, slight odor. 15 CLAY (CL): brown, very stiff, moist to wet. ne odor. CLAY (CL): brown, gravelly, sandy, very stiff to hard, moist, no odor. 20 _ GRAVEL PACK _ SLOTTED SCREEN 0.01 25 30 SAND (SP): brown, scattered gravel, medium dense, wet, no odor. CLAY (CL): brown, gravelly, very stiff, dry, no odor-BENTONITE 35 Boring terminated @ 34.5'. Sampled to 36.0'. SLIP CAP LEGEND Static Water Level WELL ID : THW-4 2345 EAST 14TH STREET, DAKLAND, CA TANK PROTECT ENGINEERING Figure :

LOG OF EXPLORATORY BORING

PROJECT NUMBER 267

BORING NO. TMW-5

PROJECT NAME

2345 EAST 14TH STREET, DAKLAND CA.

BY	LNH

DATE 7/23/93

SURFACE ELEV.

27 FT

RECOVERY	OVA (PPM)	PENETRA- TION (BLOWS/FT)	BROUND WATER LEVELS	DEPTH IN FT.	SAMPLES	GRAPHIC COLUMN	DESCRIPTION
							ASPHALT AGGREGATE BASE (GW): brown, dry, no odor.
		:					CLAY (CL): grey to black, scattered sand, firm to very stiff, dry, slight odor.
,75/1.5	0	7		5			
1.5/1.5	>1000	20	:	10	-		
			▽				CLAY (CL): light green to grey, gravelly @ 15.0'. hard, damp, slight odor.
1.2/1.5	>1000	>50					,
1.5/1.5	750	>50		20			SAND (SP): green to grey, clayey, silty, small layers 1" to 2" clay, scattered gravel, very dense, wet, slight odor.
1.5/1.5		>50					CLAY (CL): brown, gravelly, sandy, hard, dry, no odor.
1.2/1.5		39					/ Boring terminated @ 24.0'. Sampled to 27.0'
1.5/1.5		>50		25			,' ,'
1.5/1.5		49					, ,

REMARKS:

Boring drilled with continuous-flight, hollow-stem,

8-inch 0.0. augers. Samples collected in a 2.0-inch

I.D. California and standard penetration sampler.

APPENDIX E

LOGS OF EXPLORATORY BORINGS AND WELL COMPLETION DETAILS

LOG OF EXPLORATORY BORING PROJECT NUMBER 267 BORING NO. TMW-4 PROJECT NAME 2345 EAST 14TH STREET, OAKLAND CA. SURFACE ELEV. BY LNH DATE 7/22/93 27 FT PENETRA-LITHO-AECOVERY OVA GROUND WATER LEVELS TION Ĭ. GRAPHIC DESCRIPTION (FT/FT) (PPH) (BLOWS/FT) COLUMN **ASPHALT** AGGREGATE BASE (GW): brown, dry, no odor. CLAY (CL): black, scattered sand, dry, .75/1.5 CLAY (CL): brown, scattered sand, stiff to very stiff, dry, no odor. .75/1.5 20 CLAY (CL): mottled green/blue, scattered sand, gravelly at 14.5', very stiff, ∇ dry, slight odor. 1.5/1.5 26 15 _ CLAY (CL): brown, very stiff, moist to wet, no odor. 1.5/1.5 36 50 CLAY (CL): brown, gravelly, sandy, very 1.5/1.5 46 stiff to hard, moist, no odor. 1.5/1.5 43 1.5/1.5 33 25 1.5/1.5 44 1.0/1.5 28 SAND (SP): brown, scattered gravel, medium dense, wet, no odor. .1.0/1.5 CLAY (CL): brown, gravelly, very stiff, 30 dry, no odor. Boring terminated @ 34.5'. Sampled to 36.0'.

REMARKS: Boring drilled with continuous-flight, hollow-stem.


8-inch O.D. augers. Samples collected in a 2.0-inch


35


1.5/1.5


29

I.D. California and standard penetration sampler.











August 2, 1993

Mr. Marc Zomorodi Tank Protect Engineering 2821 Whipple Road Union City, California 94587

Dear Mr. Zomorodi:

Trace Analysis Laboratory received six soil samples on July 26, 1993 for your Project No. 267C072393, Credit Auto World (our custody log number 3465).

These samples were analyzed for Total Petroleum Hydrocarbons as Gasoline and Benzene, Toluene, Ethylbenzene, and Xylenes. Our analytical report and the completed chain of custody form are enclosed for your review.

Trace Analysis Laboratory is certified under the California Environmental Laboratory Accreditation Program. Our certification number is 1199.

If you should have any questions or require additional information, please call me.

Sincerely yours,

Scott T. Ferriman

Scott T. Ferremin

Project Specialist

Enclosures

3465 LOG NUMBER: DATE SAMPLED: 07/22/93 07/26/93 DATE RECEIVED: DATE EXTRACTED: 07/26/93 DATE ANALYZED: 07/27/93 08/02/93

CUSTOMER:

Tank Protect Engineering

REQUESTER:

Marc Zomorodi

PROJECT:

No. 267C072393, Credit Auto World, 2345 E. 14th Street

DATE REPORTED:

Sample Type: Soil TMW-4. Concen-Concen-Method and Reporting Reporting Reporting Concen-Constituent: <u>tration</u> <u>Limit</u> tration Limit Units tration Limit DHS Method: Total Petroleum Hydro-ND 500 940 500 carbons as Gasoline ND 500 ug/kg Modified EPA Method 8020 for: ND 5.0 ND Benzene ug/kg ND 5.0 ND 5.0 ND 5.0 Toluene 5.0 ug/kg ND Ethylbenzene ND 5.0 ND 5.0 5.0 ug/kg ND Xylenes ND 15 ND 15 15 ND ug/kg

Concentrations reported as ND were not detected at or above the reporting limit.

LOG NUMBER: 3465 DATE SAMPLED: 07/22/93 DATE RECEIVED: 07/26/93

DATE EXTRACTED: 07/26/93 DATE ANALYZED: 07/27/93

DATE REPORTED: 08/02/93

CUSTOMER:

Tank Protect Engineering

REQUESTER:

Marc Zomorodi

PROJECT:

No. 267C072393, Credit Auto World, 2345 E. 14th Street

Sample Type: Soil TMW-4. TMW-4, 4.5 TMW-4 Method and Concen-Reporting Reporting Concen-Concen-Reporting Constituent: <u>Units</u> tration Limit <u>tration</u> <u>Limit</u> tration DHS Method: Total Petroleum Hydrocarbons as Gasoline ND 500 500 940 500 ug/kg ND Modified EPA Method 8020 for: Benzene ND 5.0 ND 5.0 5.0 ug/kg ND Toluene ug/kg 5.0 ND 5.0 ND 5.0 ND Ethylbenzene ug/kg ND 5.0 ND 5.0 ND 5.0 Xylenes ND 15 ug/kg ND 15 ND 15

Concentrations reported as ND were not detected at or above the reporting limit.



PRIORITY ENVIRONMENTAL LABS

Precision Environmental Analytical Laboratory

August 23, 1993

PEL # 9308082

TANK PROTECT ENGINEERING, INC.

Attn: Jeff

Re: Six water samples for Gasoline/BTEX analysis.

Project name: Credit World Auto Sales Project location: 2345 E. 14th St.

Project number: 267081793

Date sampled: Aug 17, 1993

Date extracted: Aug 20-21, 1993

Date submitted: Aug 20, 1993 Date analyzed: Aug 20-21, 1993

RESULTS:

SAMPLE I.D.	Gasoline	Benzene	Toluene	Ethyl Benzene	Total Xylenes
	(ug/L)	(ug/L)	(ug/L)	(ug/L)	(ug/L)
MW-1	110000	270	690	730	3100
MW-2	49000	94	240	250	980
MW-3	9600	4.1	17	28	54
TMW-4	150	N.D.	0.8	1.4	3.7
TMW-5	120000	340	730	790	3600
TMW-6	N.D.	N.D.	N.D.	N.D.	N.D.
Blank	N.D.	N.D.	N.D.	N.D.	N.D.
Spiked	•		-		
Recovery	93.1%	84.2%	89.5%	92.0%	94.1%
Duplicate Spiked					
Recovery	87.8%	80.2%	81.6%	88.5%	93.0%
Detection					
limit	50	0.5	0.5	0.5	0.5
Method of	5030 /	. "			
Analysis		602	602	602	602

David Duong Laboratory Director

1764 Houret Court Milpitas, CA. 95035

Tel: 408-946-9636 Fax: 408-946-9663

Environmental Menagement

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAX(415)429-8089

"TOO"			
	T 7	 $-r_{\Lambda}$	

TURNAROUND: Norma

P.O. #: 659

CUA	T ኤፕ	OF	GUCTODY
CIM	$\mathbf{I}\mathbf{M}$	\mathbf{or}	CUSTODY

PAGE _ OF _

							17774			· · · · ·		_	-4-	ODI
Z67C 27	R NAME.	ADDRES	345 X	E. 14*	Street		(1)) A. W.			 \{\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	T }\&		REMARKS
Į.	Lee	, Hu	ckin	5			OF	1.4	¥/	\$ <i>`\</i>			7/ <u>.</u>	REMARKS
2821 WHIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088					CON- TAINER	1 /	\ <u>\</u>	/\$	/\$/	\ \$	13	*/ ₃ / /		
ID NO.	DATE	TIME	SOIL	VATER	SAMPLING	LOCATION		V.		\$/£	\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	<u>/</u> _{35	/6	
T/21W-4	7/22		×		4.5		Bruss	*	/					
T7100-4	7/22		X		95	•	Bress	X	*			1		
الماء «سلاليك	7/22		7		145		Bruss	d.	¥					
Tmu-5	7/23		4		4.5		Bass	1	L v	-	H	\dashv	-	
Tmu5	7/23		×		9.5		Briss	7	┢			1	1	
Wm-2	7/23		۴		14.5		Bruss	¥	¥					
						· · · · · · · · · · · · · · · · · · ·						\downarrow	4	
Relinquish Can He	Λ.		sture)	L 1:	5 / Time 5 10:16	Received b	v : (Signa	Lure 20		Rolf	nqui	she		by: (Signature) Date / Time Received by: (Signature)
Relinquish			ture)		/ Time	Received by	y : (Signa	ture	7 8	el i	nqui	shed	i by	by : (Signature) Date / Time Received by : (Signature)
Relinquish	d by :	(Signa	ture)	Date	/ Time	Received for L [Signature]	• •		7		931			Romarks Flu, Soil, 6-BT, SF, Y-1 5-Day TAT

DATE: 7 12 93

TANK PROTECTION ENGINEERING

Environmental Management

TANK PROTECT ENGINEERING

2821 WHIPPLE ROAD UNION CITY, CA 94587 (415)429-8088 (800)523-8088 FAK(415)429-8089

PEL # 9308082

INV # 23922

LAB: Priority Enu.

TURNAROUND: Norma

P.O. #: <u>684</u>

CHAIN OF CUSTODY

	793 NAME.	addres e Ho d, unio	S AND THE CLAIM! W CITY,	elephone S	ADDRESS LOCK Aut St NUMBER 87 (415) 42 SAMPLING I	29-8088	(1) TYPE OF CON- TAINER	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1					\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		REMARKS
Mw-1	8)17	1530		<i>‡</i>	······································		Z40ml Visis	1.7	×						
	7			×			z-40al Vials	k	٧						
mw-3	slu	1640		7			240me Vials	×	8		Ц				
Mu-4	8)17	صماا		乂			z40ma Vial	×	×		Ц				
Tmw.5		HIO		7			Z-Home vials	8	٧						
mw-6	8) ^U	1645		*			z Homul	×	ľ	_					
				:											
Relinquis Relinquis	u-len ned by	(Sign	ature)	8 30 Dat	ad 9.00 b / Time	Received b	y : (Signa Lyra	el	Q,	RoM	8	ishe	od 1	by:	(Signature) Date / Time Received by : (Signature) **Time Received by : (Signature) **Time Received by : (Signature)
Relinquish	ed by	; (Sign	ature)	8 Dat 1201	73 9 9 50 13 15 15 15 15 15 15 15 15 15 15 15 15 15	Received for [Signature]	DEL			D.	ate	/ T	ino		Remarks

DATE: 8-70-93

APPENDIX G

GROUNDWATER MONITORING WELL CONSTRUCTION PROCEDURES

BOREHOLE DESIGN

Casing Diameter: The minimum diameter of well casings will be 2 inches (nominal).

Borehole Diameter: The diameter of the borehole will be a minimum of 4 inches and a maximum of 12 inches greater than the diameter of the well casing. The minimum annular space will be 2.5 inches as measured from the outside diameter of the casing to the drill hole wall.

Shallow (Unconfined Zone) Wells: When unconfined groundwater is encountered the borehole will be advanced through the aquifer to an underlying clay layer or aquitard. The screened interval will begin a minimum of 5 feet above the saturated zone or above the anticipated seasonal high level of groundwater. The screen will extend the full thickness of the aquifer or no more than 15 feet into the saturated zone, whichever is reached first. The well screen will not extend into the aquitard, nor will the screened interval exceed 20 feet in length.

<u>Deep (Confined Zone) Wells</u>: Any monitoring well to be screened below the upper aquifer will be installed as a double-cased well. A steel conductor casing will be placed through the upper water-bearing zone to prevent aquifer cross-contamination.

The conductor casing will be installed in the following manner: a large diameter borehole (typically 18 inches) will be drilled until it is determined that the first competent aquitard has been reached. A low carbon steel conductor casing will be placed in the borehole to the depth drilled. Centralizers will be used to center the casing in the borehole. The annular space between the conductor casing and the formation will be cement-grouted from bottom to top by tremie pipe method. The grout will be allowed to set for a minimum of 72 hours.

Drilling will continue inside the conductor casing, with a drill bit of smaller diameter than the conductor casing. If additional known aquifers are to be fully penetrated, the procedure will be repeated with successively smaller diameter conductor casings.

The bottom of the well screen in a confined aquifer will be determined by presence or lack of a clay layer or aquitard as described above. The screened interval in a confined zone shall extend across the entire saturated zone of the aquifer or up to a length of 20 feet, which ever is less. The screened zone and filter pack will not cross-connect to another aquifer.

CONSTRUCTION MATERIALS

A Company of the Comp

Casing and Screen Materials: Well casing and screen will be constructed of clean materials that have the least potential for affecting the quality of the sample. The most suitable material for a particular installation will depend upon the parameters to be monitored. Acceptable materials include PVC, stainless steel, or low carbon steel.

Casing Joints: Joints will be connected by flush threaded couplers. Organic bonding compounds and solvents will not be used on joints.

Well Screen Slots: Well screen will be factory slotted. The size of the slots will be selected to allow sufficient groundwater flow to the well for sampling, minimize the passage of formation materials into the well, and ensure sufficient structural integrity to prevent the collapse of the intake structure.

Casing Bottom Plug: The bottom of the well casing will be permanently plugged, either by flush threaded screw-on or friction cap. Friction caps will be secured with stainless steel set screws. No organic solvents or cements will be applied.

<u>Filter Pack Material</u>: Filter envelope materials will be durable, water worn, and washed clean of silt, dirt, and foreign matter. Sand size particles will be screened silica sand. Particles will be well rounded and graded to an appropriate size for retention of aquifer materials.

Bentonite Seal Material: Bentonite will be pure and free of additives that may affect groundwater quality. Bentonite will be hydrated with clean water.

Grout Seal Material: Cement grout will consist of a proper mixture of Type 1/11 Portland cement, hydrated with clean water. Up to 3% bentonite may be added to the mixture to control shrinkage.

CONSTRUCTION PROCEDURES

<u>Decontamination</u>: All downhole tools, well casings, casing fittings, screens, and all other components that are installed in the well shall be thoroughly cleaned immediately before starting each well installation. When available, each component shall be cleaned with a high temperature, high pressure washer for a minimum of 5 minutes. When a washer is not available, components shall be cleaned with water and detergent or trisodium phosphate, rinsed in clean water, then rinsed in distilled water.

Soil and water sampling equipment and material used to construct the wells shall not donate to, capture, mask, nor alter the chemical composition of the soil and groundwater.

<u>Drilling Methods</u>: Acceptable drilling methods include solid and hollow-stem auger, percussion, direct circulation mud and air rotary, and reverse rotary. The best alternative is that which minimizes the introduction of foreign materials or fluids. If drilling fluid is employed, drilling fluid additives shall be limited to inorganic and non-hazardous compounds. Compressed air introduced into the borehole shall be adequately filtered to remove oil and particulates.

<u>Casing Installation</u>: The casing will be set under tension, when necessary, to ensure straightness. Centralizers will be used where necessary to prevent curvature or stress to the casing.

Sand Pack Installation: The sand pack will be installed so as to avoid bridging and the creation of void spaces. The tremie pipe method will be used where installation

conditions or local regulations require. Drilling mud, when used, will be thinned prior to packplacement. The sand pack shall cover the entire screened interval and rise a minimum of 2 feet above the highest perforation.

Bentonite Seal Placement: A bentonite seal will be placed above the sand pack by a method that prevents bridging. Bentonite pellets can be placed by free fall if proper sinking through annular water can be assured. Bentonite slurry will be placed by the tremie pipe method from the bottom upward. The bentonite seal will not be less than 1 foot in thickness.


Grout Seal Placement: The cement grout mixture will be hydrated with clean water and thoroughly mixed prior to placement. If substantial groundwater exists in the bore hole, the grout shall be placed by tremie pipe method from the bottom upward. In a dry borehole, the grout may be surface poured to a depth of 30 feet. Below a depth of 30 feet grout will be placed by tremie pipe. Grout will be placed in 1 continuous lift and will extend to the surface or to the well vault if the well head is completed below grade. A minimum of 5 feet of grout seal will be installed, unless impractical due to the shallow nature of the well.


The second secon


<u>Surface Completion</u>: The well head will be protected from fluid entry, accidental damage, unauthorized access, and vandalism. A watertight, locking cap will be installed on the well casing. Access to the casing will be controlled by a keyed lock.


Well heads completed below grade will be completed in a concrete and/or steel vault, installed to drain surface runoff away from the vault.


Well Identification: Each well will be labeled to show well number, depth, hole and casing diameter, and screened interval.











LOG OF EXPLORATORY BORING PROJECT NUMBER 267 **BORING NO. SB-1** PROJECT NAME 2345 E. 14th Street, Oakland CA PAGE 1 BY LNH **DATE 4/21/97** SURFACE ELEV. 27 FT PENETRA-LITHO-GROUND WATER LEVELS RECOVERY OVA TION DEPTH IN FT. GRAPHIC DESCRIPTION (FT/FT) (PPM) (BLOWS/FT COLUMN **ASPHALT** AGGREGATE BASE (GW): Brown, dry, no odor. CLAY (CL): Black mottled green, scattered sand, silty, dry, no odor. SAND (SP): Brown, fine-grained, moist to very moist, 1.3/2.0 10 no odor. .50/2.0 1.5/2.0 10 CLAYEY SAND (SC/SP): Brown, medium-grained, dry to moist, no odor. 2.0/2.0 1.5/2.0 Boring terminated at 32 feet. Boring sampled to 32 feet. No water level was obtained due to caving. 2.0/2.0 Drilled using the "GeoProbe method", 2.0 inch REMARKS: diameter boreholes. Samples collected in 1.0-inch

by 6.0-inch acetate tubes.

LOG OF EXPLORATORY BORING

PROJECT NUMBER 267

BORING NO. SB-2

PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 4/21/97

SURFACE ELEV. 27 FT

RECOVERY (FT/FT)	OVA (PPM)	PENETRA- TION (BLOWS/FT	GROUND WATER LEVELS	DEPTH IN FT.	SAMPLES	COLUMN	DESCRIPTION
				····			ASPHALT
							AGGREGRATE BASE (GW): Brown, dry, no odor.
1.3/2.0	8			5			CLAY (CL): Brown, green at 11.5 feet, silty, stiff, dry to moist, hydrocarbon ordor at 11.5.
	·						
2.0/2.0	46		SZ.	10			
							CLAYEY SAND (SC/CL): Green, fine to medium-grained, moist, hydrocarbon odor.
2.0/2.0	340			15			
2.0/2.0	8			20			
							SAND (SP): Brown, clayey, fine-grained, moist
1.0/2.0	. 8			25			SAND (SP): Brown, clayey, fine-grained, moist, no odor.
						7777	CLAYEY SAND (SC/SP): Brown, fine-grained, wet,
				30			no odor.
2.0/2.0	21	-		50			Boring terminated at 32.0 feet. Boring sampled to 32.0 feet.
	· · · · · · · · · · · · · · · · · · ·	1	<u> </u>	35		<u> </u>	

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

by 6.0-inch acetate tubes.

LOG OF EXPLORATORY BORING

PROJECT NUMBER 267

BORING NO. SB-3

PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 5/1/97

SURFACE ELEV. 27 FT

RECOVERY (FT/FT)	OVA (PPM)	PENETRA- TION (BLOWS/FT	GROUND WATER LEVELS	DEPTH IN FT.	SAMPLES	LITHO- GRAPHIC COLUMN	DESCRIPTION
							ASPHALT
							COBBLESTONE: Light brown, hard
							CONCRETE
1.0/2.0	39	-		5	_		CLAY (CL): Grey to black, sandy, stiff to very stiff, moist, no odor.
	•						
			SZ				CLAYEY SAND (SC/CL): Brown, scattered gravel, medium-grained, dry to moist, no odor.
1.0/2.0	40	-	·	10	2 15 1 10 2 1 1 1 1		
1.5/2.0	16	_	:	15			
1.670	EE			20	<u></u>		
1.5/2.0	56	-					**
				25			
1.5/2.0	29			25			
						<i>(-/-/-/</i>	SAND (SP): Brown, scattered gravel, fine-grained, moist to wet, no odor.
2.0/2.0	18			30	_		Boring terminated at 32.0 feet. Boring sampled to 32.0 feet.
							kironenen.
				35			

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

of 1 by 6.0-inch acetate tubes.

LOG OF EXPLORATORY BORING PROJECT NUMBER 267 **BORING NO. SB-4** PROJECT NAME 2345 E. 14th Street, Oakland CA PAGE 1 **DATE 5/1/97** SURFACE ELEV. 27 FT PENETRA-LITHO-TION GRAPHIC DESCRIPTION (BLOWS/F1 COLUMN **ASPHALT** SANDY CLAY (CL/SC): Brown motteled green, stiff, dry, no odor. CLAYEY SAND (SC/CL): Brown, organics, fine to medium grained, dry to moist, no odor. 25. Boring terminated at 27.0 feet. Boring sampled to 27.0 feet.

REMARKS:

BY LNH

OVA

(PPM)

12

RECOVERY

(FT/FT)

2.0/2.0

1.5/2.0

2.0/2.0

1.5/2.0

2.0/2.0

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

by 6.0-inch acetate tubes.

LOG OF EXPLORATORY BORING

PROJECT NUMBER 267

BORING NO. SB-5

PROJECT NAME 2345 E. 14th Street, Oakland CA

PAGE 1

BY LNH

DATE 5/1/97

SURFACE ELEV. 27 FT

RECOVERY (FT/FT)	OVA (PPM)	PENETRA- TION (BLOWS/FT	GROUND WATER LEVELS	DEPTH IN PT.	SAMPLES	LITHO- GRAPHIC COLUMN	DESCRIPTION
				· · · · · · · · · · · · · · · · · · ·			CONCRETE
							AGGREGATE BASE (GW): Brown, dry, no odor.
							CLAY (CL): Grey to black, sandy, soft, no odor.
1.0/2.0	12	-		5			
							•
		-					CLAYEY SAND (SC/CL): Green, fine-grained, dry, hydrocarbon odor.
				10			·
2,0/2.0	67	~					
			\mathbf{z}				
				•			
2.0/2.0	6			15	1		
2.42 -4	•						CLAYEY SAND (SC/CL): Brown, fine-grained, moist, no odor.
							SANDY CLAY (CL/SC): Brown, organics, stiff, dry no odor.
2.0/2.0	11			20	Œ		no odor.
2.0/2.0	11	_					
			:			<u> </u>	
				25			CLAYEY SAND (SC/CL): Brown, fine-grained, wet at 27.0 feet, no odor.
2.0/2.0	6	_		۵	_		·
						<i>7.7.7.</i> 7.	Boring terminated at 27.0 feet. Boring sampled to 27.0 feet. A hydrocarbon sheen on the groundwater
						-	was observed.
				30	 	1	
]	
						-	
						-	
	L	<u> </u>	<u></u>	_35		1	

REMARKS:

Drilled using the "GeoProbe method", 2.0 inch

diameter boreholes. Samples collected in 1.0-inch

by 6.0-inch acetate tubes.

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587 Attn: Lee Huckins

Date:	5/1/97
Date Received:	4/24/97
Date Analyzed:	4/25/97
Project #:	267042197
P.O. #:	1399
Sampled By:	Client

Certified Analytical Report

Soil Sample Analysis:

Test	SB-1 26.5-27.0	SB-2 16.5-17.0	Units	PQL	EPA Method#
Sample Matrix	Soil	Soil			
Sample Date	4/21/97	4/21/97			
Sample Time	1345	1000			
Lab#	D7160	· D7161			
DF-Gas/BTEX	1	1			
TPH-Gas	ND	3.7	mg/kg	1.0 mg/kg	8015M
MTBE	ND	ND	mg/kg	0.05 mg/kg	8020
Benzene	ND	0.012	mg/kg	0.005 mg/kg	8020
Toluene	ND	0.0071	mg/kg	0.005 mg/kg	8020
Ethyl Benzene	ND	0.042	mg/kg	0.005 mg/kg	8020
Xylenes	ND	ND	mg/kg	0.005 mg/kg	8020

- 1. DLR=DF x PQL
- 2. Analysis performed by Entech Analytical Labs, Inc. (CAELAP #2224)

Michael N. Golden, Lab Director

DF=Dilution Factor
DLR=Detection Reporting Limit

PQL=Practical Quantitation Limit ND=None Detected at or above DLR

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587 Attn: Lee Huckins

Date:	5/1/97
Date Received:	4/24/97
Date Analyzed:	4/25-4/28/97
Project #:	267042197
P.O. #:	1399
Sampled By:	Client

Certified Analytical Report

Water Sample Analysis:

Test	SB-1W	SB-2W	Units	PQL	EPA Method #
Sample Matrix	Water	Water			
Sample Date	4/21/97	4/21/97			
Sample Time	1540	1103			
Lab#	D7162	· D7163			
DF-Gas/BTEX	1	20			
TPH-Gas	ND	6,100	μg/liter	50.0 μg/l	8015 M
MTBE	ND	ND	μg/liter	5.0 μ g/ l	8020
Benzene	ND	870	μg/liter	0.5 μg/i	8020
Toluene	ND	35	μg/liter	0.5 μg/l	8020
Ethyl Benzene	ND	17	μg/liter	0.5 μg/l	8020
Xylenes	ND	28	μα/liter	0.5 μg/l	8020

1. DLR=DF x PQL

2. Analysis performed by Entech Analytical Labs, Inc. (CAELAP #2224)

Michael N. Golden, Lab Director

DF=Dilution Factor
DLR=Detection Reporting Limit

PQL=Practical Quantitation Limit ND=None Detected at or above DLR

METHOD: Gas Chromatography

QC Batch #: GBG4970425

Matrix: Soil

Date Analyzed: 04/25/97 Quality Control Sample: Blank Spike

Units:	ug/kg

PARAMETER	Method #	MB ug/kg	SA ug/kg	SR ug/kg	SP ug/kg	SP % R	SPD ug/kg	SPD %R	RPD		LIMITS VISORY) %R
Benzene	8020	i <5.0 i	80	ND	104	130	98	123	5.9	25	50-150
Toluene	8020	<5.0	80	ND	103	129	95	119	8.1	25	50-150
Ethyl Benzene	8020	<5.0	80	ND .	105	131	97	121	7.9	25	50-150
Xylenes	8020	<5.0	240	ND	313	130	289	120	8.0	25	50-150
Gasoline*	8015	<1000.00	1000	0.0	940	94	890	89	5.5	25	50-150

*LCS and LCSD were analyzed for this parameter

Definition of Terms:

na: Not Analyzed in QC batch

MB: Method Blank SA: Spike Added SR: Sample Result

RPD(%): Duplicate Analysis - Relative Percent Difference

SP: Spike Result SP (%R): Spike % Recovery SPD: Spike Duplicate Result

SPD (%R): Spike % Recovery

NC: Not Calculated

METHOD: Gas Chromatography

QC Batch #: GBG2970425

Matrix: Soil

Date Analyzed: 04/25/97

Quality Control Sample: Blank Spike

Units	: ug/kg										
PARAMETER	Method #	MB ug/kg	SA ug/kg	SR ug/kg	SP ug/kg	SP % R	SPD ug/kg	SPD %R	RPD		LIMITS VISORY) %R
Benzene	8020	i <5.0 ∴i	80	0.0	79	99	76	95	3.9	25	50-150
Toluene	8020	\ <5.0 \	80	0.0	77	96	74	93	4.0	25	50-150
Ethyl Benzene	8020	<5.0	80	0.0	77	96	75	94	2.6	25	50-150
Xylenes	8020	<5.0 l	240	0.0	232	97	223	93	4.0	25	50-150
Gasoline*	8015	!<1000.00!	1000	0.0	990	99	1020	102	3.0	1 25 1	50-150

Definition of Terms:

na: Not Analyzed in QC batch

MB: Method Blank SA: Spike Added SR: Sample Result

RPD(%): Duplicate Analysis - Relative Percent Difference

SP: Spike Result

SP (%R): Spike % Recovery

SPD: Spike Duplicate Result

SPD (%R): Spike % Recovery

NC: Not Calculated

^{*}LCS and LCSD were analyzed for this parameter.

METHOD: Gas Chromatography

QC Batch #: GBG2970428

Matrix: Soil

Date Analyzed: 04/28/97 Quality Control Sample: D7377

Units: ug/kg

PARAMETER	Method #	MB ug/kg	SA ug/kg	SR ug/kg	SP ug/kg	SP % R	SPD ug/kg	SPD %R	RPD		LIMITS 'ISORY) %R
Benzene	8020	i <5.0⇒i	80	ND	78	98	76	95	2.6	25	50-150
Toluene	8020	<5.0 ¦	80	ND	77	. 96	75	94	2.6	25	50-150
Ethyl Benzene	8020	. <5.0 i	80	ND	76	95	74 🕏	93	2.7	25	50-150
Xylenes	8020	<5.0 i	240	ND	228	95	225	94	1.3	25	50-150
Gasoline*	8015	<1000.00	1000	0.0	960	96	1000	100	4.1	25	50-150

*LCS and LCSD were analyzed for this parameter.


Definition of Terms:

na: Not Analyzed in QC batch

MB: Method Blank SA: Spike Added SR: Sample Result

RPD(%): Duplicate Analysis - Relative Percent Difference

SP: Spike Result
SP (%R): Spike % Recovery
SPD: Spike Duplicate Result
SPD (%R): Spike % Recovery
NC: Not Calculated



(510) 429-8088 = (800) 523-8088 = Fox (510) 429-8089

LAB: ENVE	eh	
TURNAROUND:	15 day	·

P.O. #: 1399

PAGE ______ OF ______

CHAIN OF CUSTODY

	197 HANE.	ADDRES Ce /-	S AND THE CITY	E 14	: WUMBER 187 (415) 4	29-8088 OCATION	(1) TYPE OF CON- TAINER	13/2						REMARKS
38-1 368-210	4/21	/34r	×		26.5-27	.B	Hube	7	1					D 11 000
53-Z 46-74		1000	1		165-17	, 0	Hube	1	×					07161
J5-/~		1570		፠	1		3-yane	7	~					07162
	4/4,			8	4		z.46m4	7	Y			_	1	07163
		-						+				+	_	
								-		F		+	#	
Relinquish Cho Relinquish	المنا	emo		4/2	to / Time	arll	mg.		1					y: (Signature) Date / Time Received by: (Signature) y: (Signature) Date / Time Received by: (Signature)
Relinquish	ed by	; (Sign	aturo)	Da	to / Time	Received for [Signature]	Laboratory by			D	.to /	Tis	10	Romarks

. 15.1	\TE		
	1 LL	•	
		_	

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587 Attn: Lee Huckins

Date:	5/6/97
Date Received:	5/2/97
Date Analyzed:	5/5/97
Project #:	267050297
P.O. #:	1404
Sampled By:	Client

Certified Analytical Report

Soil Sample Analysis:

Test	SB-3 21.5-22	SB-4 21.5-22	SB-5 11.5-12.0	Units	PQL	EPA Method #
Sample Matrix	Soil	Soil	Soil			
Sample Date	5/1/97	5/1/97	5/1/97			
Sample Time	11:23	13:52	9:10			
Lab#	D7700	D7701	D7702			
DF-Gas/BTEX	1	1	62			
TPH-Gas	ND	ND	91 ²	mg/kg	1.0 mg/kg	8015M
MTBE	· ND	ND	ND	mg/kg	0.05 mg/kg	8020
Benzene	ND	ND	ND	mg/kg	0.005 mg/kg	8020
Toluene	ND	ND	ND	mg/kg	0.005 mg/kg	8020
Ethyl Benzene	ND	ND	ND	mg/kg	0.005 mg/kg	8020
Xylenes	ND	ND	ND	mg/kg	0.005 mg/kg	8020

- 1. DLR=DF x PQL
- 2. TPH-Gas chromatogram for Lab #D7702, although within the reporting range, does not match the typical Gas pattern
- 3. Analysis performed by Entech Analytical Labs, Inc. (CAELAP #2224)

Michael N. Golden, Lab Director

DF=Dilution Factor
DLR=Detection Reporting Limit

PQL=Practical Quantitation Limit ND=None Detected at or above DLR

525 Del Rey Avenue, Suite E • Sunnyvale, CA 94086 • (408) 735-1550 • Fax (408) 735-1554

Tank Protect Engineering 2821 Whipple Road Union City, CA 94587 Attn: Lee Huckins

Date:	5/6/97
Date Received:	5/2/97
Date Analyzed:	5/5/97
Project #:	267050297
P.O. #:	1404
Sampled By:	Client

Certified Analytical Report

Water Sample Analysis:

Test	SB-3W	SB-4W	SB-5W	Units	PQL	EPA Method#
Sample Matrix	Water	Water	Water			
Sample Date	5/1/97	5/1/97	5/1/97			· · · · · · · · · · · · · · · · · · ·
Sample Time	12:20	14:00	10:25			
Lab#	D7703	D7704	D7705			
DF-Gas/BTEX	1	. 1	2			
TPH-Gas	ND	ND	890	μ g /liter	50.0 μg/l	8015M
MTBE	ND	ND	12	μg/liter	5.0 µg/l	8020
Benzene	ND	ND	5.4	μg/liter	0.5 μ g/ l	8020
Toluene	ND	ND	ND	μ g/lite r	0.5 μg/l	8020
Ethyl Benzene	ND	ND	1.4	μ g /liter	0.5 με/l	8020
Xylenes	ND	ND	ND	μg/liter	0.5 μg/l	8020

1. DLR=DF x PQL

2. Analysis performed by Entech Analytical Labs, Inc. (CAELAP #2224)

Michael N. Golden, Lab Director

DF=Dilution Factor DLR=Detection Reporting Limit PQL=Practical Quantitation Limit
ND=None Detected at or above DLR

Environmental Analysis Since 1983

METHOD: Gas Chromatography

QC Batch #: GBG4970505

Date Analyzed: 05/05/97

Matrix: Soil

Quality Control Sample: D7720

Units: ug/kg

PARAMETER	Method #	MB ug/kg	SA ug/kg	SR ug/kg	SP ug/kg	SP % R	SPD ug/kg	SPD %R	RPD	, ,	QC LIMITS (ADVISORY) RPD : %R	
Benzene	8020	<5.0 i	80	ND	102	128	98	123	4.0	25 i	50-150	
Toluene	8020	<5.0	80	ND	100	125	96	120	4.1	25	50-150	
Ethyl Benzene	8020	<5.0	80	ND !	101	126	97	121	4.0	25	50-150	
Xylenes	8020	<5.0	240	ND	302	126	292	122	3.4	25 i	50-150	
Gasoline*	8015	<1000.00	1000	0.0	1000	100	980	98	2.0	25	50-150	

*LCS and LCSD were analyzed for this parameter

Definition of Terms:

na: Not Analyzed in QC batch

MB: Method Blank

SA: Spike Added

SR: Sample Result

RPD(%): Duplicate Analysis - Relative Percent Difference

SP: Spike Result

SP (%R): Spike % Recovery

SPD: Spike Duplicate Result

SPD (%R): Spike % Recovery

NC: Not Calculated

METHOD: Gas Chromatography

QC Batch #: GBG5970505

Date Analyzed: 05/05/97

Matrix: Water

Quality Control Sample: Blank Spike

Units: µg/L

PARAMETER	Method #	MB μg/L	SA μg/L	SR μg/L	SP µg/L	SP % R	SPD µg/L	SPD %R	RPD	_ ~	LIMITS VISORY) %R
Benzene	i 8020	<0.5	i 25	0.0	22	88	23	92	4.4	25	50-150
Toluene	8020	<0.5	25	0.0	24	96	24	96	0.0	25	50-150
Ethyl Benzene	8020	<0.5	25	0.0	25	100	25	100	0.0	25	50-150
Xylenes	8020	<0.5	75	0.0	69	92	69	92	0.0	25	50-150
Gasoline	8015	<50.0	625	0	636	102	656	105	3.1	25	50-150

Definition of Terms:

na: Not Analyzed in QC batch

MB: Method Blank SA: Spike Added SR: Sample Result

RPD(%): Duplicate Analysis - Relative Percent Difference


SP: Spike Result

SP (%R): Spike % Recovery

SPD: Spike Duplicate Result

SPD (%R): Spike % Recovery

NC: Not Calculated



LAB: EnterL

TURNAROUND: 48 hr

P.O. #: 1404


[510] 429-8088 m [800] 523-8088 m Fox (510) 429-8089


CHAIN OF CUSTODY


PAGE ______ OF _____


PROJECT HO. SITE NAME & ADDRESS CANAS ZIGT DE O Z 977 E 3445 E) 444 Stree Colline SAMPLER NAME, ADDRESS AND TELEPHONE NUMBER 2821 UNIPPLE ROAD, UNION CITY, CA 94587 (415) 429-8088 ID NO. DATE TIME SOIL WATER SAMPLING LOCATION					(1) TYPE OF CON- TAINER	13 A								REI	MARKS		
58-3 Zis-W	S),	Irzs	X		21.5-2	7.	1 tube	×	×				ne	<u> </u>	MTBE		D7700
53-4 215-22	5),	1352	¥		Z45-2		1 tube	×	>				,		h		D7701
55-5 1154/20	5.	310	X		11.5-12		1 tube	*	¥				12		,		07702
SB-3W	f		*	1			z-40me	Ŋ	7						6		07703
SB-4W			1	1			2-40ml	¥	X			П	, r	\	41		07704
SB-54			i 	1			5-4ame	×	¥						4		D7705
	_	-				<u> </u>											
		1				7 0											
Rehinspiehod by: (Signature)				711:20	LA	Signature										Received by : (Signature)	
Relinquish	Relinquished by : (Signature) Date /					Rabaiva	Signature (Signature					ed by	; (Sign	(Signature) Date / 1			Received by : (Signature)
Relinquish	Relinquished by : (Signature)				o / Time	Flacelyed for L (Signature)	aboratory by:		Date / Time			Remax	Remarks				


DATE:














BORINGS AND NIMORING AVERES GREET

						•	
Stanley Wong		PRO	JECT N	AME:	Oaktan	d	
PROJECT ADDRESS: 2345 International Boulevard, Oakland, California		(DATE (RILLED: -	May 2	2, 2001	
DRILLING METHOD: Hollow Stem Auger	SAMPL	ER TY	PE:	CA Spli	Spoon :	Sampler	
15 Feet	WIDTH O	BOR	NG:	6 3/4 - ir	nches		
要化を含ませれる。	s	TATIC	WATE	R LEVEL: -	N/A		
ALCO DE LA CALLA DEL CALLA DE LA CALLA DE LA CALLA DEL CALLA DE LA CALLA DEL CALLA DE LA CALLA DEL LA CALLA DEL LA CALLA DE LA CALLA DE LA CALLA DE LA CALLA DEL LA CALLA DE L					N/A		
SCREEN LENGTH: N/A SLOT SIZE:							
CRILLING COMPANY: Bay Area Exploration			RIFE HAN	3 I IC :	C57-	522125	
RILLING COMPANY:							·····
CORE SAMPLE CONDITION LEGEND: Undisturbed	⊠ Dis	turbed			No Rec	очегу	
				'			
					co	NSTRU	CTION.
LOGGED BYTChris Wabuzoh REVIEWED BY: Ola Balogun	DEPTH	SOIL TYPE	PID (ppm)	RECOVER			
ASPHALT covering	UCF III		(PP(1)		SEAL	CASING	SCREEN
						1	
	<u> </u>		-		-[
SANDY CLAY: Brown; about 40% coarse, coarse to line, hard angular to rounded sand about 60% clay, moderate plasticity; dry to moist; no hydrocarbon odor; no reaction with	5	CL	0	2,3,5			
hydrochloric acid (HCL).	5_						
SANDY CLAY: Greenish; about 40% coarse to fine, hard subangular to rounded sand;			264				
about 50% clay, moderate to high plasticity, moist; has hydrocarbon odor; no reaction w		CL					
	10	-		5,11,17			
	ĺ						
At 6.VEV CANIST Segren where ASSE along mindows to blok aboutailor about 5006 announ	a m	CL.					
CLAYEY SAND: Brown; about 40% clay, moderate to high plasticity; about 50% coast fine, hard rounded sand; about 10% gravel size about 1/4 inch; moist to saturated; no	"	١	4				
hydrocarbon eder; Groundwater water encountered.	- 15			5,11,13			
왕화왕(1) 12년 왕화왕(1) 11.							
	_					1	
				1			
	20	1					
	7						
	25	1					

BORING WONDING FROM SERVE CO Oaldand Stanley Wong - PROJECT NAME: · CLEINT: May 22, 2001 2345 International Boulevard, Oaldand, California - DATE DRILLED: PROJECT ADDRESS: CA Split Spoon Sampler Hollow Stem Auger - SAMPLER TYPE: TRILLING METHOD: 20 Feet 6 3/4 - inches - WIDTH OF BORING: TOTAL DEPTH OF BORING:-DEPTH TO GROUNDWATER AT THE TIME OF DRILLING: N/A STATIC WATER LEVEL: . N/A N/A SCREEN DIAMETER:-CASING DIAMETER:---- CASING LENGTH: -N/A -- SLOT SIZE: --SCREEN LENGTH:-C57-522125 DRILLING COMPANY: Bay Area Exploration - DRILLING LIC .:--Disturbed No Recovery CORE SAMPLE CONDITION LEGEND: Undisturbed CONSTRUCTION PID RECOVERY LOGGED BY Chris Wabuzoh REVIEWED BY: Ola Balogun DEPTHTYPE CASING SCREEN (ppm) ASPHALT covering SANDY CLAY: Brown; about 40% coarse to fine, hard angular to subrounded sand; 0 4,6,9 about 60% clay, moderate plasticity; dry to moist; no hydrocarbon odor; no reaction with CL hydrochloric acid (HCL). 5 270 SANDY CLAY: Gray with Iron staining; about 40% coarse to fine, hard subangular to ĊL rounded sand; about 60% clay, moderate to high plasticity, moist; has hydrocarbon odor; no reaction with HCL. 10 4,10,12 SĊ 1 CLAYEY SAND: Brown; about 30% clay, moderate to high plasticity; about 60% coaste to fine, hard rounded sand; about 10% gravel size about 1/4 inch; moist; no hydrocarbon 15 odor, no reaction with HCL. 8,11,15 SANDY CLAY: Brown; about 30% coarse to very fine, hard rounded sand; about 70% clay 0 SC moderate to high plasticity; moist to saturated; no hydrocarbon odor; no reaction with HCL 5,10,15 20

EXOPTING ENGINERAL WELLS LOSS WESTERS

Stanley Wong				ianse.	Oaldand	1	
CLEINT: 2345 International Boulevard, Caldend, California			JECT N	ORILLED:	May Z	2, 2001	
PROJECT ADJRESS:				CA Spit 5	spaon 9	ampier	
20 Fast	- SAMPI			6 3/4 - inc		·	
N/A	MIDTH O				N/A		
DEFINITION OF THE PARK OF PROLUMP,		FTATIC	WATE	r level:	NA		t.a.e./bis-1.7 .
CASING DIAMETER: CASING LENGTH:	, ,			AMETER:			
SCREEN LENGTH: N/A SLOT SIZE: —		N/A				22125	
CRELING COMPANY: Bay Area Exploration		Di	PEELLEN/	9 LIC.;	G97-9	22(27	i
CORE SAMPLE CONCITION LEGENO: Undisturbed	Z 04	turbed			io Reco	very	
					CON	ISTRUC	TION
LOGGED BY: Chris Wabuzoh REVIEWED BY: Ola Balogun	DEPTH	SOIL TYPE	PID (ppm)	RECOVERY		CASING	SCREEN
ASPHALT covering							
NO RECOVERY					:		
	5			4,8,11			
SANDY CLAY: Gray, about 30% coarse to fine, hard subangular to rounded send; about 60% clay, moderate to high plasticity, moist; has hydrocarbon odor, no reaction with HCL.		CL	346				
	10		}	4,8,11			
			,				
		,					
CLAYEY SAND: Gray; about 30% day, moderate to high pleaticity; about 50% cosers to fine, hard rounded sand; about 10% gravel size about 1/4 inoh; moist; has hydrocarbon		sc	400	1			
ador, no reaction with HCL.	15	•		7,11,18			
							[
				—			
SANDY CLAY: Brown; about 35% coarse to very fine, hard rounded sand; about 60% clar moderate to high plasticity; about 5% gravel size about 1/4 inch; moist to saturated; no	Y	sc	5				
hydrocarbon odor; no reaction with HCL.	20			4,18,14			
							1
	7						
	25	ŀ					
Britan Control of the		I		<u> </u>	1	ł	

BORENCESSMONINGENERMER BUSOSESSE CLEINT: Steniey Wong Caldand - PROJECT NAME: May 22, 2001 2345 International Boulevand, Caldend, California - OATE DRELED: -ROJECT ADDRESS: CA Split Spoon Sampler Hollow Stern Auger DRILLING METHOD: SAMPLER TYPE:-6 3/4 - inches TOTAL DEPTH OF BORING:-WIDTH OF BORING: DEPTH TO GROUNDWATER AT THE TIME OF DRILLING:-- STATIC WATER LEVEL: N/A NA ASING DIAMETER: N/A - CASING LENGTH: -SCREEN DIAMETER: N/A N/A SCREEN LENGTH: - SLOT SIZE: --RELING COMPANY: Bay Area Exploration C57-522125 -- DRILLING LIC.:-Disturbed CORE SAMPLE CONDITION LEGEND: No Recovery Undisturbed CONSTRUCTION SOIL PID RECOVERY OGGED SY:Chris Wabuzoh REVIEWED BY: Ola Balogun DEPTHTYPE (ppm) CASING SCREEN ASPHALT covering SANDY CLAY: Dark brown; about 40% coarse to fine, hard, angular to subrounded sand; 0 about 60% clay, moderate plasticity; moist; no hydrocarbon odor; no reaction with HCL. CL 223 5 100 SANDY CLAY: Dark gray, about 30% course to fine, hard autoingular to rounded saint, CL about 70% clay, moderate to high plasticity, melet; has elight hydrocarbon odor; no no reaction with HCL. 4,8,10 10 169 CLAYEY SAND: Greenish gray, about 40% coarse to fine, hard subangular to rounded SC send; about 50% clay, moderate to high plasticity; moist; has hydrocarbon odor, no reaction 15 8,12,15 WITH HCL. CLAYEY SAND: Light brown; about 40% coarse to very fine, hard rounded sand; about Ð SC 60% ctay, moderate to high pleaticity, some gravel size about 1/4 inch; molet to saturated; groundwater encountered; no hydroparbon odor; no reaction with HCL. 3,6,8 20

9

Stanley Wong			· ·	MARKE.	Oaldan	đ _.	
ROJECT ADDRESS: 2345 International Boulevard, California			JECT I	DRILLED:	May 2	2, 2001	1
Linker Ctone Briene		-	7	CA Spit i	Spoon 8	Sampler	
PRELING METHOD: 20 Feet TOTAL DEPTH OF BORING:				6 344 - inc	tres	- 1.4. 1.4. 1.4.	
EPTH TO GROUNDWATER AT THE TIME OF DRIELING: N/A					N/A		
RETIT TO GROUNDWATER AT THE THE OF DRULLING:				ir Level:	N/A		
CASING DIAMETER: N/A CASING LENGTH: N/A				lameter:	}	\	
PUREST LENGTH SUC: -		N/A			C57.4	22125	
ORILLING COMPANY: Bay Area Exploration.	<u></u>	D	PALLIN	G UC.:——	03/3	EXIEU	
CORE SAMPLE CONDITION LEGEND: Undisturbed	⊠ Die	turbed			io Reco	erery.	
					001	··cTDL W	
					COL	VSTRUC	SHORE
		SOIL				1	
OGGED BYTChris Walkszoh REVIEWED BY: Ola Balogun	DEPTH		(ppm)	RECOVERY		CASING	SCREEN
ASPHALT covering							
SANDY CLAY: Dark brown; about 40% course to fine, hard, srigular to subrounded serv	ď;		0	}			
about 60% clay, moderate plasticity; moist; no hydrocarbon odor; no reaction with HCL.	5	CL		2,3,5			
			·				
SANDY CLAY: Dark brown; about 30% coarse to fine, hard subangular to rounded sanc about 70% clay, moderate to high pleaticity, moist; no hydrocarbon odor; no reaction with	et. h	CL	0			1	
HCL	10			45.10			
			۴.				
GLAYEY SAND; Greenish; about 30% course to time, hard subangular to rounded send;		SC.	40				
70% clay; moderate to high plasticity; some gravet; moist; has hydrocarbon odor; no reaction with HCL.	15			5,13,16			
A BOUTH CONTROL OF THE CONTROL OF THE CONTROL OF THE CONTROL OF THE CONTROL OF THE CONTROL OF THE CONTROL OF T MICE AND THE CONTROL OF THE CO							
GRAVELLY SANDY CLAY: Brown; shout 30% coarse to very line; hard rounded send; 50% clay, moderate to high plasticity, about 20% gravet size about 1/4 inch; moist to		CL	7				
saturated, groundwater encountered; no hydrocarbon odor; no reaction with HCL.	20			4,9,11			
	7	1			ĺ	ŀ	
	25						

More than the continue with the continue of th CLERT: Stanley Wong **Oakland** 2345 International Boulevard, Oaldand, California May 22, 2001 Hollow Stern Auger TRILLING METHOD: CA Split Spoon Sampler TOTAL DEPTH OF BORING: 6 3/4 - inches DEPTH TO GROUNDWATER AT THE TIME OF DRILLING:-STATIC WATER LEVEL: ASING DIAMETER: NIA N/A - CASING LENGTH: SCREEN DIAMETER: SCREEN LENGTH:-N/A SLOT SIZE: -RELING COMPANY: BEY Area Exploration C57-522125 CORE SAMPLE CONDITION LEGEND: Disturbed Undisturbed No Recovery CONSTRUCTION **BÖIL** OGGED BY Chris Webuzoh PID RECOVERY REVIEWED BY: Ota Balogun DEPTHTYPE (ppm) CASING SCREEN ASPHALT covering SANDY CLAY: Dark brown; about 40% coarse to fine, hard, angular to subrounded sand; Ð about 60% clay, moderate plasticity; moist, no hydrocarbon edor, no reection with HCL. CL 2,2,2 SANDY CLAY: Dark brown; about 30% coarse to fine, hard subangular to rounded sand; 0 about 70% clay, moderate to high pleaticity, moist; no hydrocarbon odor, no reaction with HCL. CL 10 1,2,2 15 20

Startley World PROJECT NAME: CLEWT:-May 22, 2001 2345 International Boulevard, Caldend, California DATE DRULED: -ROJECT ADDRESS: CA Split Spoon Sumpler Hollow Stem Auger SAMPLER TYPE: WILLING METHOD: 6 3/4 - inches 20 Feet WIDTH OF BORING:-TOTAL DEPTH OF BORING:-NA STATIC WATER LEVEL: EPTH TO GROUNDWATER AT THE TIME OF DRILLING:-4 Inches 15 feet 4 inches SCREEN DIAMETER: - CASMO LENGTH: -CASING DIAMETER:-0.02 Inch 5 feet SLOT SIZE: ---CREEN LENGTH:-C57-522125 DRILLING COMPANY: Bay Area Excitoration DRILLING LIC.:-Distarbed No Recovery Undisturbed CORE SAMPLE CONDITION LEGEND: CONSTRUCTION SOIL PID RECOVERY REVIEWED BY: Olin Ballogun DEPTHITYPE (ppm) OGGED BY Chris Webuzoh CASING SCREEN SEAL, ASPHALT covering SANDY CLAY: Dark brown; about 40% course to fine; hard angular to subrounded sand; 3 CŁ about 60% ctay, moderate pleaticity; moist; no hydrocerbon odor; no reaction with HCL. 2,2,3 CEMENT 5 GROUT 36 SANDY CLAY: Gray, about 30% course to fine, hard subangular to rounded sand; about 80% clay, moderate to high plasticity; moist; has hydrocarbon odor; no seaction with HCL CL 4,5,8 10 370 CLAYEY SAND: Gray: about 30% clay, moderate to high plasticity, about 60% coasts to SC fine, hard rounded sand; about 10% pravel size about 1/4 inch; moist; has hydrocarbon odor; no reaction with HCL. 15 6,10,12 SANDY CLAY: Brown; about 35% course to very fine, hard rounded sand; about 60% clay 2 moderate to high plasticity; about 5% gravel size about 1/4 inch; moist to saturated; no CL hydrocarbon odor; no reaction with HCL. 6,7,8 20 7 25

Sequoia Environmental

Client Project ID: #SW-02; Oakland

Date Sampled: 05/22/01

Date Received: 05/23/01

Client Contact: Chris *Wabuzoh

Date Extracted: 05/23-05/25/01

Client P.O:

Date Analyzed: 05/23-05/25/01

Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline*, with Methyl tert-Butyl Ether* & BTEX*

EPA methods 5030, modified 8015, and 8020 or 602: California EWOCD (SE Bay Range) method (CCEPAGE)

Lab ID	Client ID	Matrix	TPH(g)*	MTBE	Benzene	Toluene	Ethyl- benzene	Xylenes	% Recovery Surrogate
68163	SB1-10	S	240,b.j	ND<0.20	ND<0.04	0.19	0.19	0.45	
68164	SB1-15'	S	3:0,6,	ND	ND	0.005	0.009	0.013	113
68165	SB2-10*	S	89,b,j	ND<0.10	ND	ND .	0.033	0.25	#
68166	SB2-15	S	ND	ND	ND	ND	ND	ND	108
68167	SB2-20*	S	ND	ND	ND	ND	ND	ND	107
68168	SB3-10	s	300,b _. j	ND<0.20	ND<0.01	ND<0.01	0.76	1.2	*
68169	SB3-15'	S	1800,π	ND<2.0	3.3	5.5	48	53	,^
68170	SB3-20	S	8.5,a	ND	0,009	6.023	0.10	0.12	*
68171	SB4-10'	5	ND	ND	ND	ND	ND	ND	103
68172	SB4-15'	S	230,6,	ND<0.10	0.23	ND	1.5	1.1	*
68173	SB4-20'	s	ND /	ND	ND	ND	ND	ND	99
68174	SB5-15'	S	25,a	ND	0.035	ND	0.10	0.11	
68175	SB5-20'	S	1.9,c	ND	0.62	ND	ND	ND	102
68176	SB6-10'	S	ND	ND	ND	מא	, ND	ND	96
68177	SB7-10	Ş	18.j	ND	ND	ND	0.056	0.11	100
68178	SB7-15'	s	68,a	ND<0.10	0.28	0.25	0.36	0.35	
68179	SB7-20'	S	ND	סא	ND	ND	ND	ND	104
otherwis	Limit unless s stated; ND	w	50 ug/L	5.0	0.5	0.5	0.5	0.5	
	detected above orting limit	S	1.0 mg/kg	9.05	0.005	0.005	0.005	0.005	


^{*} water and vapor samples are reported in ug/L, wipe samples in ug/wipe, soil and sludge samples in mg/kg, and all TCLP and SPLP extracts in ug/L.

The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavise gasoline range compounds are significant; aged gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (?); f) one to a few isolated peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible short is present; i) liquid sample that contains greater than ~5 vol. % sediment; j) no geographic pattern.

DHS Certification No. 1644

Edward Hamilton, Lab Director

cuttered chromatogram; sample peak coelules with surrogate peak



110 2nd Ave. South, #D7, Pacheco, CA 94553-5560 Telephone: 925-798-1620 Fax: 925-798-1622 http://www.mccampbell.com E-mail: main@mccampbell.com

QC REPORT

Date:

05/23/01

Matrix

Soil

Extraction:

TTLC

	-	Concent	ration: n	ng/kg	%Rec	covery	
Compound	Sample	MS	MSD	Amount Spiked	MS	MSD	RPD
SampleID: 52201				lnstr	ument	GC	-12
Surrogate1	0.000	95.000	102.000	100.00	95	102	7.1
Xylenes	0.000	0.306	0.316	0.30	102	105	3.2
Ethyl Benzene	0.000	0.100	0.104	0.10	100	104	3.9
Toluene	0.000	0.100	0.107	0.10	100	107	6.8
Benzene	0.000	0.099	0.106	0.10	99	106	6.8
MTBE	0.000	0.107	0.115	0.10	107	115	7.2
GAS	0.000	0.746	0.748	1.00	75	75	0.3
SampleID: 51701				Inst	ument	GC-1	1 A
Surrogate1	0.000	106.000	104.000	100.00	106	104	1.9
TPH (diesel)	0.000	316,000	293.000	300.00	105	98	7.6

25772 zsall.doc /42

	McCAM			, -		LI	NC.					70	T		, .							Cī	JS'	ro	D'	ΥÏ	Œ	ĈĈ	RI)	
	t	PACHE	venue so Co, ca se						•				7	(U)	RN	AI			D T		•		Q		Ç	1			j.		
	et (925) 798	-1620			F	AE:	(925											سجب					USI	!	24	HR		48 B		71 HR	5 DAY
leport To: Chy				M Te):		>	m	1E	-	•••	·	<u> </u>	7	7		1 1	Ans	lysis	Re	ques	t	7			,		Ott	JOE .	Com	nents
ompany: Sequ							Ŧ.	2					-		5			-					ĺ								
San	Hadd	JOHO A	Neru	45.	Q 4	5	15	9_		***	- 		ä		#				-	İ		2								ŧ.	
ele: (SD0 - 6/			F	ax: (14	- 2	9.	23		MATERIAL STATES		3	1					-	28/								0.0	100
roject# 5 h	- 02			rojec] 🖁		ee (5520 EAF/BAF)	ms (418.1)		<u>e</u>		.	1	0153 / 023 / 529							,	Q Ç	1163
reject Location:	Oakl	and		-				•					ļġ		1	8		8	3			8			5				-	8	8164
upler Signature	-CPV	wille		120	/ _	Ţ.				TW	ET)	Ob	18	6	4			3		3	3 .	MA			77.6	. !		r			
		SAMI	LING	"	6		MA'	FRI	<u> </u>	PR	30	VED	ğ	(8015)	8	F		ă		֓֞֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֡֓֓֓֓֡֝֓֡֓֡֡֡֝֡֡֡֡֝֓֡֡֡֝֡֡֡֡֡֡					3			. 1		5	8 165
SAMPLE ID	LOCATION		ŀ	# Costainer							-		#	Ī	Second	1	EPA 601 / 1010	BTEX ONLY (EPA 602 / 8020)	EPA 608 / 8080	15 CA 604 / BAG (CA 604)	EPA 625 / 8270	PAH'S / PNA's by]	LUFT 5 Metals	Lead (72407421/239.246010)					ě	8166
SAMELL IN	LACTURE NOT	Date	Time		12	2			4 5			5 2		2	1	2	3	S	3 3	3	8		2	5 1	Ē				9	4	W FOO
				U *	1	Wat	3		8	3		5 8	BTEXA	THE D	Total	Total Pet	¥	N N	ă ă		マ 記 記	H	CAM-17 MA	3	3	Ü	ૠ	8		6	8167
81-10		5.330	Pm	ľ			7			И			T _v																	6	8 168
81-15'		个	well	1	<u> </u>		4	\perp	4	1			V			<u> </u>										Ŀ					
5B2- /0'			prin	1			4	1		1			Y	+				_		1		$oxed{}$	_		_			 		5	3169
82-15'		<u> </u>	Dan.	<u> </u>			4	4		14			1	1	ļ.,	-			_	_	4	-	-							66	170
582-20	 		and		 		1			11	-		 ~		-	-						4-	-	_	-			 	_	w	, , , ,
5B3-10 5B3-15	·		Ann	1	 	-	M	-		M	-	-	\ <u>\</u>	┪	 	ļ			-	+		+-	-	-	-	-				€	617
583-157 582-20			Am	-	╂	+	1	+		K		-	╀	+	+-	╁╌	-			╬	-	╁	╂	-	-	}	-		\dashv	<u>.</u>	
584-10	, 		Am		 	-	1	+	+	 	-		+"	+	<u> </u>	+-	-			+	+	╁	┿╌	-	-	-	-			. . 5	8172
SB4-15			Ave	╁┼	†	╁	1	\dashv	+	T,			╁		+-	-	-			+			+-	┼	╁	 - -	-	-	f	6	8173
504-20		+	Am	++	1-	+	1	+	十	1	-		۲,	+	十	+	 	 		+	+	+	+	+-	+	╁	t	 	╁╌┼	•	
SB5 - 15		╂┄┼╴	ku	1	+-	1	Ľ	+	1	╎			-4		+	╈	十	-		+	十	+	T	十	+	+	t	-	-	. 6	8174
SB5 - 20		1	Am	1	1	1	V	1	-	-4		_	-1-	7	1	+	1			7	·	1	T	T	T	<u> </u>	1	Ť		Í. t	0048
386-10		17	Ann		1		V	1	1	1,			1,		1	\top	†			1	\top	十	T	T	十	十	1		1 1	∱ 1	6817
5BT- 10		6.20		1	T		V	1		T			*******	/	T	T				7	1	1	T	T	+		1			1	6817
Chys Viv	bush	Date	Time:	M	a f	W	/	16	ih	M	نسند		F	tem	arks	: /	V	577	n a	Z	7	A	7		<u></u>				· ·	1	6817
Relimpulated By:		Date:	Time:	Rec	elved	By:			•		_	THER									-									4	~~ ~ * *
Relinquished By:		Date	Time:		EER			- 2	***				4																		

Taleph	McCAM one: (925) 79	110 2 ^M A' PACRE		OUTH.	#D7 60		(925		8 -16	22			7	U	RIN	AR				IMI			US SUS	ŀ	24	3			RD R	72 HR	SD
	WS THO		٨]	BM Te			Sn	_					1-					Ana	YS	Rec	112			_	,			Oth			ment
Company: Se													1				7	T	Ť	T	T	_	7	T	1			Ť		 	
1111	Made	(in 1	רנסעוצ	ML,	<u>ک</u>	ui	ē	B						,	e (5520 E&F/B&F)				1			1								1	
Sa		ndro		}							<u></u>		IOLSY METBE		4	_			Ì			12									
Tele: (5) 0 -		900		ax: (<u>6</u>	14	_	2	21	3	8		20	3	,				1	18			1				į		
	2 Klar			tolec	t Na	me:					· ~		ā		S	3		ହ	١,			15									
Project Location Sampler Signatu		c/ome		-		,							8			ą		2	1			ä			18					1	
Catarbiet Signate		YIS Y		MY		_				W	12.11	ಗಿಗ	ă	0	3			A 602 / 8020)		e		EPA 625 / 8270 / 8310			Ä					1	
		SAMI	LING	,			MA?	TRUX		FR	esei	RVED	ğ	# (80) 5)	8	n Hydrosebens (418.1)		•		/8260					3					l	
SAMPLE ID	LOCATION	Date	Time	# Coutsing	Type Contain	Water	Sett	Shedge	Other	Jze	HCI	HNO, Offer	124	8		Total Petroleum	EPA 601 / \$010	BTEX ONLY (B	Cara coo / coo	EPA 624 / E240 / 8260	EPA 625 / 1270	PAH'S / PNA'S by	CAM-17 Mends	LUFT 5 Motals	Land (7240/7421/239/26010)	RCI	蛋	S	Specific Conduc	•	
387-15		502-01	ומנפן	1			V			V	-		J					_	+	+	+	+	┿	-					i i	l. 	. ئەر
587-20		7:33.01					V	Τ		V	T		1				T	T	7		T	Τ	1						i f	58	17
																			1	+	1	T	 		-				j		400
																7		十	+	1	+-	+	1-				-		i I	DO	17
					*****			+				-				_	_	-+	+	+	┼┈	十	1-	-			-	\dashv	1	1	••••
			·						† †	1	-			一		_	-	-+	+	+	╫	╁		 			-	+		 	-
	 						_	+	1-1			-				1	-+	\dashv	十	┿	┾╌	┿	┼	-	\vdash			+		ļ	
									┼╌┫	-	+	+				-		-	+	╌	╁╾	┪—	┼					-		 	•
**************************************	·					┫			┼┫		-+	╌	╂╾┥			-+		+	╌┼╴	+-	╂	-	┼	-				-	+	ļ	
						1		- -	┦╼┫		-								+	+	╁	-	1-					_		<u> </u>	
				 	<u> </u>	-			-		-	_	-				_		4	+-	 _	 					ightharpoonup			<u> </u>	<u> </u>
······································	<u> </u>			 		1			1		_	_ _				_	_		4	<u> </u>	<u> </u>				MS	OLG	E	ALS!	OTER		
·					L]						H.	_		1	\perp			ER\								<u> </u>	
·	<u> </u>														200							DPF						\perp			
· · · · · · · · · · · · · · · · · · ·	1													HE	AD:	SPAL	E	SEN	1	1	אסג	AN	ERS.		بب	-1	_				• • •
Relinguished By:	lou zol	Date:	Time:	W	yed B 214	n a	W	en	19	۲.	~		Re	mer	ks:		۸,	bor		ed.		7/	4 /	,					NA.		
Relinquished By:		Date:	Time:		yed B						: •								:		•										
Relinquished By:	a eta eta eta eta eta eta eta eta eta et	Date:	Time:	Recei	yed B	y:~:		, i	· ·		<u>`</u>	-					V.				• • •	:					1				1.11
				Ý				9 (1) 2 (4)	(i j. j.			y.		4.3			.;;/:							##: 	4		•) 1	Arris .		1000	1. J.

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.nccampbell.com E-mail: main@mecampbell.com

Sequoia Environmental	Client Project ID: #SW-02; Oakland	Date Sampled: 05/22/01
1111 Aladdin Ave., Suite B		Date Received: 05/23/01
San Leandro, CA 94577	Client Contact: Chris 'Wabuzoh	Date Extracted: 05/23-05/30/01
	Client P.O:	Date Analyzed: 05/23-05/30/01

Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline*, with Methyl tert-Butyl Ether* & BTEX*


Lab ID	Client ID	Matrix	TPH(g) ⁺	МТВЕ	Benzene	Toluene	Ethyl- benzene	Xylenes	% Recovery Surrogate
68157	SB-1	w	11,000,a	ND<20	8.1	23	81	7.1	"
68158	SB-2	w	1 200, b,j	ND	ND	3.5	5.5	ND	154
68159	SB-3	w	53,000,a,h	ND<200	790	110	2000	2000	102
68160	SB-4	w	170,000,a,h	ND<200	420	ND<45	1500	800	109
68161	SB-5	w	27,000,a	ND<500	8400	99	230	120	106
68162	SB-6	w	ND	ND	ND	ND	ND	ND	104
									
		-							
			-				***************************************		
							. · · · · · · · · · · · · · · · · · · ·		
	:						·····		
			_		·		and the state of t		
							· · ·		
				- · · · · · · · · · · · · · · · · · · ·					
	Limit unless e stated: ND	w	50 ug/L	5.0	0.5	0.5	0.5	0.5	
means not	detocted above ording limit	S	1.0 mg/kg	0.05	0.005	0.005	0.005	0.005	

^{*} water and vapor samples are reported in ug/L, wipe samples in ug/wipe, soil and sludge samples in mg/kg, and all TCLP and SPLP extracts in ug/L.

The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation: a) unmodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that does not appear to be derived from gasoline (?); f) one to a few isolated peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water immiscible sheen is present; j) liquid sample that contains greater than ~5 vol. % acdiment; j) no recognizable pattern.



cluttered chromatogram; sample peak coclutes with surrogate peak



119 2nd Ave. South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com B-meil: main@mccampbell.com

QC REPORT

Date

05/23/01

Matrix:

Water

Extraction:

TTLC

W		Concent	ration:	ug/L	%Rec	covery	
Сотроина	Semple	MS	MSD	Amount Spiked	MS	MSD	RPD
SampleID: 52201				instr	umant:	GC	-12
Surrogate1	0.000	92.0	93.0	100.00	92	93	1.1
Xylenes	0.000	28.2	28.1	30.00	94	94	0.4
Ethyl Benzene	0.000	9.3	9.3	10.00	93	93	0.0
Taluene	0.000	9.3	9.2	10.00	93	92	1.1
Benzene	0.000	9.2	9.1	10.00	92	91	1.1
MTBE	0.000	10.5	10.4	10.00	105	104	1.0
GAS	0.000	92.2	90.9	100.00	92	91	1.5
SampleID: 52101		-		Inatro	ment:	GC-1	1 A
Surrogate1	0.000	114.0	114.0	100.00	114	114	0.0
TPH (diesel)	0.000	7875.0	7800.0	7500.00	105	104	1.0

% Re covery w (#45-Sample)

RPD (MS-MSD)

2597125Q10.da

	ne: (925) 791	PACHE 5-1620	VENUES CO, CAS	(553-55 Bill To	64				798-1	522		-	·		ru)	RN	AI			DT	. ,			RU	SAI	2	4 RI	R	48	HR		73 ER	5 D) MY
The second secon	unas						on	77	L			+=====		-		-	Г.		Ал	llysi	Re	que	st			٠,.		4	0)the	*	Cor	nmen	3
1111	Hada					- 4"	tē	7	>					1		5	1		j	}					Ì							1	•	
Som	Lagy				44			_\$	<u> </u>		-			ш		Ē			}	1.			ا		. 🕴							1		
	614-			Pax: (417	<u>* (</u>	7	11	· · ·	2	2	•		DISY ACTER		at (5520 EAF/BAF)	=				١		2		Í			-				1		
	W-D	2		Projec	t Na	mez	. 42	-7			LC	.		훒	}	3	(418.1)				-		Š					1	1		1	İ		
roject Location:	Out	clar		·				-					-	:		1	ğ		8	2	-		Š		ł	٤		1						
impler Signatui			201	27	OR		-			*****				8		J	ě		2	1	5		404			200		Į		1				
			PLING		ì		MA	T	ΙX	P4	ME	PHO ERV	D ED	8	(3015)	8 00 a	en Hydro		8 4		9	3	ALES A 60% / 1870 / 1831			730		1		Taries.	2			:
Sample ID	LOCATION	Date	Time	# Contains	Type Centain	Water	Soff	Alt	Stadge	ics.	BCI	HNO,	Other	BIEK & IPH = (TPH = Diesel (Total Petroleum	Total Petroleum	EPA 601 / 8010	BTEX ONLY (EPA 602 / 8020)	EPA 508 / 3080	CATA ONE CONTRACTOR SUMPLE	OFFI POR AND AND AND AND AND AND AND AND AND AND	PAW's / PMA's		Trieff Change	מזיראני מפרו נכארומינה לייה ל	J. Janes C. Lances	7	SS1	Specific Conductivity				
B-1		5.12.0	am	2		7		7		₩.	7		-	V		*****					+	+	+	+	-	+	+	-	+	+		Ι.	• • • • •	
B-2		1	und	2		V				v	1	1							\dashv	\dashv	+	-	+	+	~ -	+	╌	╁		+		6	B 15	7
B-3	*		Don	2		1		+		1		 		V				-	┷╅		+	+	┿	╁	┰╂╌	+	+	+	+	+				
B-4			m	2		7		7	_	V	+	 	H	V	-			-	┪	-	十	+-	╁	╁	: .	+	+	-	+-	+	,	58	158).
18-5			am	2		J	-	7	+	1	+			~					+	-	+	┿	┿	╁	+	+-	╁	╬	+	+	1	1 . 1.8 A		e.
B - 6		5.12.0		2		7		7		Ť	1			V					+	+	+	+	+-	+		+-	+	+	+-	+-	<u>.</u>	Df	315	j
								十	_	广	-		H	•				-	+	-	+	+	╬	╫	-	╁	+	╁	+	+	ļ. 4	6	B 16	n
								7										_	7		\dagger	+-	╁	十	+	+-	+		+	+	1			
								1		_			\sqcap					1	1		+	+	+	+	+-	+-	+	+	十	+		6	816	1
	,									-		П							1	1	†	+	†-	+	-	+-	-	+	+	++	1	- :		
	•							1					T					+	+	+	+		+	+	+	+-	╁	╀	+	+-	1	. 0	816	įZ
S. C. S. C.		1						_			Į,		は		-	_			\pm		₩	oks 1	Okç	推	ī/LS	bri	de.	+	┿	+	 	<u> </u>	• • •	 ,
								+	-				某		-	_	\dashv	44	E	ATK Wit	Ł	#	4	H			\pm	-	+-	╪╌	4	ļ	<u> </u>	~~~
	<u> </u>					┝╼	+	+					ACT								+	_	+	-	-	F	Į.	+-		4	4	<u> </u>		
					<u></u>	-	+	+					7	7	-5-14		4	4	M	ERS	*		┿	1	1	_	_	Ļ	1	\bot	igspace	·····		
inquished By:		Deter	Time:	Bern	red By			1	ليل				4	اي	_1				1	\perp	<u> </u>	ŀ	1	<u> L</u>				L	L	L		·		
mobalo	ezek	5.330	1040	M	M	a'	2		24	4	_		_	Ko	mar	KB:	Į.	10	rp	n	Ļ	7	4	7										
nquished By:		Date:	Time:	Receiv	red By	;	,						٦										-		•				-				•	
nquished By:	1		I										!															_				:		

110 2nd Avenue South, #D7, Pacheco, CA 94553-5560
Telephone: 925-798-1620 Fax: 925-798-1622
http://www.mccampbell.com E-mail: main@mccampbell.com

Sequoia Environmental	Client Project ID: #SW-02	Date Sampled: 06/13/01
1111 Aladdin Ave., Suite B		Date Received: 06/14/01
San Leandro, CA 94577	Client Contact: Chris Wabuzoh	Date Extracted: 06/15/01
	Client P.O:	Date Analyzed: 06/15/01

Gasoline Range (C6-C12) Volatile Hydrocarbons as Gasoline*, with Methyl tert-Butyl Ether* & BTEX*

EPA methods 5030, modified 8015, and 8020 or 602: Catifornia PWOCR (SE Par Paris) - charles CERNICONN.

Lab ID	ds 5030, modifie Client ID	Matrix	TPH(g)*	MTBE	Benzene	Toluene	Ethyl- benzene	Xylenes	% Recovery Surrogate
69777	MW-3	w	8400,x	ND<20	1300	25	64	32	110
69778	MW-6	W	7600,a	ND<10	1400	42	. 19	14	
						;			
			· · · · · · · · · · · · · · · · · · ·				·		
			······································						
	· _ :								-
									
				:			· · · · · · · · · · · · · · · · · · ·		
			·						
									·
									
									·
			,	1					
									· · · · · · · · · · · · · · · · · · ·
Reporting Limit unless otherwise stated; ND means not detected above the reporting limit		W .	50 ug/L	5.0	0.5	0.5	0.5	0.5	
		s	1.0 mg/kg	0.05	0.005	0.005	0.005	0.005	

^{*} water and vapor samples are reported in ug/L, wipe samples in ug/wipe, soil and sludge samples in mg/kg, and all TCLP and SPLP extracts in ug/L

[&]quot;The following descriptions of the TPH chromatogram are cursory in nature and McCampbell Analytical is not responsible for their interpretation; a) usemodified or weakly modified gasoline is significant; b) heavier gasoline range compounds are significant(aged gasoline?); c) lighter gasoline range compounds (the most mobile fraction) are significant; d) gasoline range compounds having broad chromatographic peaks are significant; biologically altered gasoline?; e) TPH pattern that gloss not appear to be derived from gasoline (?); f) one to a few isolated peaks present; g) strongly aged gasoline or diesel range compounds are significant; h) lighter than water invariscible above is present; i) liquid sample that contains greater than -5 vol. % sediment; j) no recognizable pattern.



cluttered chromatogram, sample peak coefutes with surrogate peak

CHAIN OF CUSTODY RECORD THE 2" AVENUE SOUTH, #DT TURN AROUND TIME PACHECO, CA 94553-5560 72 HR 5 DAY RUSH 24 HR 48 HR Telephone: (925) 798-1620 Fax: (925) 798-1622 Analysis Request Other Comment Report Tox LAMS / Nabuzo h Bill To: Total Potroleum Oil & Oresse (5520 P&F/B&P) Laddin avenue Stuta B Leander. 94577 EPA 625 / 8270 / 8310 Total Petroleum Hydrocarbons (418.1) Fax: (970-614-2723 Tale: (5)10 - 614 - 1900 Project Name: SW-02 BTEX ONLY (EPA 602 / 8020) Oak Jourd EPA 608 / \$080 PCB's ONLY Project Location! Land (7240/7421/239-2/6010) Chro / walers Sampler Signature: BTEX & TPH as Gas (602) EPA 624 / 8240 / 8260 MRTHOD PRESERVED TPH as Diesed (3015) Specific Conductivity SAMPLING MATRIX PAHPs / PNA's by EPA 625 / 8270 CAM-17 Metals EPA 601 / 9010 EPA 608 / 8080 LURT 5 Month LOCATION SAMPLE ID Stadge 9 Date Time Water 9 HNO, 96 3 HC ¥ 五经 MW-3 413-0 69777 6-13-01 nw- c DM 69778 Remarks: 6-14


sinquiched By:

Dates

Received By:

Appendix B

City of Oakland Subsurface Utility Map



Appendix C

City of Oakland Bench Mark Data from Renner Surveying & Engineering

To:

Bos CLARK Date:

RENNER SURVEYING & ENGINEERING

3270 MENDOCINO AVENUE, SUITE E-2
SANTA ROSA CA, 95403
PHONE 707-569-9757 FAX 707-569-9762
renengl@pacbell.net
(Home Office)

AND
228 LORTON AVENUE, SUITE 4
BURLINGAME, CA 94010
PHONE 650-685-8313 FAX 650-685-8313
(Survey Headquarters)

FAX TRANSMITTAL

Company:		FAX No:	1-510-420-9170
From:	Ernie Renner	Re:	DAWY
Subject:	City OF DAKLAN	10	
NUMBE:	R OF PAGES TRANSMITTED INC IF YOU DO NOT RECEIVE ALL RESPECTIVE HOME OR SURVE ADDITIONAL COMM	THE PAGE	S, PLEASE CALL US @ TELEPHONE NUMBER
	GVD 1929 is 3	.0' he	gher - cald
three	GVD 1929 is 3 feet to our ele	vatio	ous.
		111	
		Mank	Tov
		Jun	i le

RENNER SURVEYING & ENGINEERING

3270 MENDOCINO AVENUE, SUITE E-2 SANTA ROSA CA, 95403 PHONE 707-569-9757 FAX 707-569-9762 renengl@pacbell.net (Home Office)

AND

228 LORTON AVENUE, SUITE 4 BURLINGAME, CA 94010 PHONE 650-685-8131 FAX 650-685-8313 (Survey Headquarters)

FAX TRANSMITTAL

To: Ernie Date: 3/17/03

Company: N/A FAX No: 510-525-1011

From: Robert Shellman Re: 1093-01

Subject: Datum

NUMBER OF PAGES TRANSMITTED INCLUDING TRANSMITTAL SHEET: 2 Ernie: The current datum that the topo is on is a local Oakland city datum. To convert to NGVD29' add 3ft to each elevation.

Robert

1.q

16506858313

207-569-9762

Ernest Renner

Mar 18 03 01:36p Valued Customer Mar 18 03 04:26p

·		Dates
563-17 (6/62) BEi	NCH MARK DATA	Davina D.
Standard Disc in	Designation15 Elevation33.2	105
Tagged Pin In Monument Pin	Field BookBL 43-	_ Page _45 -
Other_cut square	Order	6 - 3
LOCATION:	t return NW corner	مام کے ا
Square out in cont. C Fast 14th Street and	curb centerline return NW corner 27th Avenue.	Don
To Concertition	CARY FAUG	HT Devoise of
161729	510-615-55	97 467
ADD3' correct-	O NED GR WITER	EAR HEGG
14 sw LCNICC	City Engineer's Office	ce, Oakland Calif.