



lube and
waste oil
USTs

SFWD - pump station 11-10-93
605 Paloma WY
03317211124-2
Sunol



west flank of
diesel UST
pit - note
discoloration

11/16/93
SFWD
605 Paloma
Sunol
03317211124-2



10,000 gal UST
being lifted from
pit

11/16/93
SFWD
605 Paloma
Sunol
03317211124-2

Print File
ARCHIVAL PRESERVERS

P.O. BOX 607638 • ORLANDO, FL 32860 • (407) 886-3700

11-10-93 → DATE: 11-16-93

ASSIGNMENT:

SFWO
Sunol Pump plant

INSERT EMULSION SIDE DOWN

STYLE NO. 45-4HS POL

Pump Plant

FILE NO:



10000 gal. UST -
tank rolled onto
side showing
rust

03317211124-2 SFWO
505 Paloma
Sunol

11-16-93



water/product
accumulating
at west end
of concrete
"trough" in pit

03317211124-2 SFWO
505 Paloma
Sunol

11/16/93



lake oil
UST

SPWD - Pump station 11-10-93
505 Paloma Wy
8331721124-2
Suwal



apparent over -
spill stains
on diesel
UST

SPWD - pump plant 11-10-93
505 Paloma Wy
8331721124-2
Suwal