

BLAINE TECH SERVICES INC.

1370 TULLY RD., SUITE 505 SAN JOSE, CA 95122 (408) 995-5535

June 19, 1986

Chevron USA, Inc. 2 Annabel Lane, Suite 200 San Ramon, CA 94583

Attention: Vicki Hobbs

Re: Field sampling at

Chevron Station #1153
Fernside Blvd.
Alameda, CA
on
June 4, 1986

SAMPLING REPORT

Sampling was performed in accordance with approved methodology at the locations shown on the accompanying site diagram. The lab numbers assigned to the samples are given on the site diagram. Samples were collected in appropriate containers, which were sealed, chilled and transported to the laboratory for analysis. Analytical services were provided by Thermo Analytical, Inc/ERG with a separate report and billing invoice referencing their lab numbers.

Tanks

age -- unspecified


type -- one 550 gallon waste oil one 750 gallon waste oil one 3,000 gallon gasoline one 6,000 gallon gasoline one 8,000 gallon gasoline

reason for removal - discontinuation of on site storage

Reportage

Submission to the Regional Water Quality Control Board and the Fire Department should include copies of both the sampling report and the laboratory report. The property owner should attach a cover letter and submit all documents together in a package.

Rpt 86155F1 6-4-86 Chevron Stn. No. 1153, Fernside Blvd. page 1 of 3



PAGE 2

The following addresses have been listed here for your convenience:


Water Quality Control Board San Francisco Bay Region 1111 Jackson Street Room 6040 Oakland, CA 94607 ATTN: Dale Bowyer

Alameda Bureau of Fire Prevention 1300 Park Street Alameda, CA 94504 ATTN: Albert L. Smith

If I can be of any further assistance, please call.

Richard C. Blaine

RCB/tls



() Phone results to () Phone result t

TIVIA Thermo Analytical Inc.

TMA/ERG

1400 West 53rd Street

Suite 460

Emeryville, CA 94608-2946

(415) 652-2300

June 4, 1986

Chevron USA 2 Annabel Lane, Suite #200 San Ramon, CA 94583

Attention: Vicki Hobbs

Report #7920

Release #23

Site Location: Chevron Station #1153, Fernside Dr., Alameda.

RE: Ten (10) soil samples submitted on June 4, 1986 for rush gasoline analysis; also two (2) samples for waste oil analysis; one (1) water for gasoline analysis.

Procedure: The samples are analyzed for gasoline by following the method described in Attachment 2, Analytical Procedures for Fuel Leak Investigations. The samples are concentrated on a Tekmar LSC-2 automatic sample concentrator prior to injection into a gas chromatograph fitted with a flame ionization detector. Quantitation is performed, as total hydrocarbon response, against known concentrations of gasoline. The limit of detection for this method of analysis is one part per million (mg/kg), unless stated otherwise.

The samples are analyzed for waste oil by following a modified EPA Method 3510 extraction procedure. The samples are extracted three times with hexane. The solvent is removed from the combined extracts and carbon disulfide is added. The solution is injected into a gas chromatograph fitted with a flame ionization detector. Quantitation is performed, as total hydrocarbon response, against a solution made from a known concentration of light machine oil. The limit of detection for this method of analysis is eleven parts per million (mg/kg).

The results are summarized in Table I.

Submitted by:

Robert B. Flay

Manager, Organics Department

Mobut B. Flay

RBF:sml

cc: Rich Blaine

Blaine Tech Service

P.O. Box 5745

San Jose, CA 95150

TABLE I

ERG #	CLIENT ID	GASOLINE CONCENTRATION (mg/kg or mg/L)
7920-1	86155 F1 #1	ND(1)
7920-2	86155 F1 #2	ND(1)
7920-3	86155 F1 #3	ND(1)
7920-4	86155 F1 #4	ND(1)
7920-5	86155 F1 #5	130 ppm**
7920-6	86155 F1 #6	ND(11)*
7920-7	86155 F1 #7	1400
7920-8	86155 F1 #8	530
7920-9	86155 F1 #9	150
7920-10	86155 F1 #10	ND(1)
7920-11	86155 F1 #11	ND(1)
7920-12	86155 F1 #12	ND(11)*
7920-13	86155 F1 #13	33

^{*}waste oil, by extraction

^{**}water sample (mg/L)

ND = None detected. The limits of detection are in ().