

# THRIFTY OIL CO.

February 15, 1994

Mr. Scott O. Seary  
Alameda County  
Department of Environmental Health  
Hazardous Materials Program  
80 Swan Way, Room 200  
Oakland, California 94621

94 FEB 22 PH 2:25  
ALCO  
HAZMAT

RE: **Thrifty Oil Co. Station #054**  
*2504 Castro Valley Boulevard*  
*Castro Valley, California*  
***4th. QUARTER REPORT, 1993***

Dear Mr. Seary,

This letter report presents the results of soil/groundwater treatment and site monitoring during the 4th. quarter of 1993 at the subject site. The approximate location of the on- and off-site monitoring wells are shown on **Figure 1**. The engine of the RSI unit was replaced and was operational the first week in May, 1993. All monitoring is conducted by Earth Management Co. (EMC).

### Site Monitoring and Sample Collection

The site was visited on December 14, 1993, by an EMC technician in order to gauge the wells and collect groundwater samples. Water levels were measured in each well from the rim of well cover using a Marine Moisture Tape (nearest 0.01 feet) capable of also measuring the presence of free floating hydrocarbons. *Depth to water* ranged from about 2.75 to 8.75 feet below grade which is consistent with previous data collected, indicating a slight rise. **As of December 14, 1993, only three of wells, RE-3, RE-4 and RE-7, exhibited floating product visible as a sheen or film.** The depth to water data was used in conjunction with the recent survey data to determine groundwater elevations across the site. The interpretation of groundwater flow across the site is depicted on **Figure 1**. In general, the **groundwater flow was to the east at a calculated gradient of about 6.7 feet per 100 feet.**

Prior to collecting groundwater samples from the wells, about 4 well volumes of groundwater was removed using a PVC bailer. **No samples were collected from the recovery wells RE-4 and RE-7.** During the purging process, the pH, conductivity and temperature were checked and recorded to insure formation water was entering the well to be sampled. About 8 to 40 gallons of water were removed from each well and stored in 55 gallon D.O.T approved drums pending



disposal or discharge through the treatment unit. Groundwater samples were collected with a Teflon bailer. Samples were maintained and transported in 40 milliliter vials placed on ice pending delivery to Smith-Emery, a state certified analytical laboratory headquartered in Los Angeles, California. Field monitoring sheets prepared by EMC personnel are included in Appendix A.

### Analytical Results

**Groundwater Monitoring Wells.** Groundwater samples were analyzed for total hydrocarbons (TPH) and volatile aromatic compounds (BETX) using EPA methods 8015 and 8020, respectively. Copies of the laboratory analysis reports are attached in Appendix B. A summary of the results are presented in Table 1. The two down-gradient wells, RS-8 and RS-10 continue to indicate less than detectable or acceptable levels of volatile aromatic compounds. Iso-concentration maps of TPH and benzene based on the December sampling event are presented as Figures 2 and 3.

**Treatment Unit Discharge.** In addition, the inlet and outlet to the groundwater treatment unit was sampled monthly. [REDACTED] at the inlet and [REDACTED] at the outlet. [REDACTED] at the outlet. TPH and BETX was not detected in the outlet.

**Air Sample Collection.** In order to monitor the emissions of the engine, bi-weekly samples of the outlet vapors were collected and analyzed for benzene. Based on the analysis of samples by D&M Laboratories, no detectable concentrations of benzene were noted in the outlet vapor sampled. Copies of complete laboratory reports are included in Appendix B.

### Treatment Unit Operation Status

Based on the data obtained by EMC, the RSI-SAVE unit operated 1440 hours during the reporting period and 7280 hours total. [REDACTED] processed [REDACTED] million gallons of water to date. December 29, 1993. During this time, [REDACTED]

### Closing

Thrifty will continue to conduct quarterly groundwater monitoring at the site. If you have any questions please contact me at (310) 923-9876.

Very truly yours,



Peter D'Amico  
Manager  
Environmental Affairs

Table 1 - Summary of Analytical Results

I.D.	Date	D-Wat.	TPH	Benzene	Toluene	E-Benzene	Xylenes
PW-1 (166.46)	4/11/88	--	NSC				
	4/09/90	5.10	230000	600	2700	1000	16000
	10/30/90	6.17	35000	240	970	240	3580
	1/18/91	6.28	37000	43	140	42	1600
	2/12/91	5.88	45000	99	130	25	700
	3/20/91	4.75	1900	0.43	ND	ND	2.8
	5/22/91	5.10	41000	600	730	250	3800
	6/19/91	5.61	NSC				
	7/17/91	5.53(Film)	NSC				
	8/07/91	5.67(Film)	NSC				
	9/24/91	5.57(Film)	NSC				
	10/23/91	6.53(Film)	NSC				
	11/06/91	5.85(Film)	NSC				
	12/04/91	5.91(Film)	NSC				
	1/29/92	5.43(Film)	NSC				
	2/26/92	5.54(Film)	NSC				
	3/19/92	5.47	ND	ND	ND	ND	ND
	4/22/92	5.62(Film)	NSC				
	5/21/92	6.21	1300	19	2.9	0.7	58
	6/25/92	6.94	NSC				
	7/30/92	5.90(Film)	NSC				
	8/20/92	7.12(Film)	NSC				
	9/30/92	6.42	3400	57	ND	26	240
	12/23/92	5.56(Film)	NSC				
	3/10/93	5.65(Film)	NSC				
	6/09/93	5.30	400	<0.5	1.1	<1.0	<1.0
	09/14/93	5.43	180	3.7	3.2	1.5	14.0
	12/14/93	4.65	<50	<0.3	<0.3	<0.3	<0.5
PW-2 (166.18)	4/11/88	--	NSC				
	4/09/90	5.81	600000	1300	11000	4600	43000
	10/30/90	6.95	48000	310	51	10	480
	1/18/91	6.92	86000	230	1400	350	8300
	2/12/91	6.78	160000	680	1300	250	7000
	3/20/91	5.54	17000	34	50	ND	1100
	5/22/91	6.07	14000	57	2100	500	8200
	6/19/91	6.37(Film)	NSC				
	7/17/91	6.38(Film)	NSC				
	8/07/91	6.63(Film)	NSC				
	9/24/91	6.42(Film)	NSC				
	10/23/91	7.25(Film)	NSC				
	11/06/91	6.44(Film)	NSC				
	12/04/91	6.65(Film)	NSC				
	1/29/92	6.17(Film)	NSC				
	2/26/92	5.90(Film)	NSC				
	3/19/92	5.80(Film)	NSC				
	4/22/92	5.88(Film)	NSC				
	5/21/92	6.03(Film)	NSC				
	6/25/92	6.57(Film)	NSC				
	7/30/92	6.20(Film)	NSC				
	8/20/92	6.64(Film)	NSC				
	9/30/92	6.88(Film)	NSC				
	12/23/92	6.08(Film)	NSC				
	3/10/93	5.95(Film)	NSC				
	6/09/93	5.38	3400	24	2.2	<0.5	240
	09/14/93	6.26	4900	190	15.0	8.8	480
	12/14/93	5.22	1700	42	<0.3	<0.3	<0.5

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.

ND - Not Detected.

TPH - Total Petroleum Hydrocarbons as gasoline.

D-Wat - Depth to Water.

NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

Table 1(CONT.) - Summary of Analytical Results

I.D.	Date	D-Wat	TPH	Benzene	Toluene	E-Benzene	Xylenes
RE-1 (166.82)	4/11/88	--	37000	1900	8400	1200	15000
	4/09/90	4.99	45000	6100	7000	2000	8800
	10/30/90	5.95	72000	7700	5300	1800	8900
	1/18/91	5.17	150000	11000	14000	1800	4300
	2/12/91	4.16	140000	11000	12000	1600	13000
	3/20/91	4.75	53000	3100	4200	400	5500
	5/22/91	4.42	85000	8700	10000	1800	12000
	6/19/91	4.93	110000	8500	9600	2600	16000
	7/17/91	5.19	5500	950	ND	26	ND
	8/07/91	5.12	NA	6700	5000	ND	7100
	9/24/91	5.87	60000	6800	4300	640	6900
	10/23/91	5.81	79000	7900	8300	450	7100
	11/06/91	5.56	130000	14000	15000	1100	8800
	12/04/91	5.35	50000	8000	4700	520	4100
	1/29/92	4.50	21000	10300	11000	780	6000
	2/26/92	5.27	38000	8400	10500	720	7100
	3/19/92	4.47	48000	6200	9700	780	7200
	4/22/92	4.62	NSC				
	5/21/92	4.98	20000	7600	10100	830	6900
	6/25/92	5.14(Film)	NSC				
	7/30/92	5.30(Film)	NSC				
	8/20/92	5.28(Film)	NSC				
	9/30/92	5.66(Film)	NSC				
	12/23/92	4.81(Film)	NSC				
	3/10/93	4.13(Film)	NSC				
	6/09/93	4.48(Film)	NSC				
	09/14/93	5.35	19000	3600	1100	740	4300
	12/14/93	4.38	35000	4300	9300	<6.6	ND
RE-2 (167.19)	4/11/88	--	NSC				
	4/09/90	4.90	850	5.8	0.5	4.8	1.1
	10/30/90	5.34	440	2.8	0.91	13	3.14
	1/18/91	4.90	1100	8.4	3.1	ND	10
	2/12/91	4.94	1100	5.9	ND	0.77	ND
	3/20/91	4.32	550	4.3	ND	ND	ND
	5/22/91	4.43	1000	5.3	3.6	4.4	6.9
	6/19/91	6.43	700	2.1	1.4	3.8	3.5
	7/17/91	4.75	880	12.0	8.0	4.3	28.0
	8/07/91	4.87	NA	3.8	1.6	ND	ND
	9/24/91	5.50	670	7.2	7.1	ND	23
	10/23/91	5.63	2700	52	60	22	130
	11/06/91	5.14	1900	18	61	9.1	83
	12/04/91	5.26	1100	26	47	4.3	42
	1/29/92	5.11	900	14	24	5.3	19
	2/26/92	4.31	500	3.4	3.5	2.7	2.7
	3/19/92	4.45	1200	14	20	15	18
	4/22/92	4.78	200	ND	ND	ND	ND
	5/21/92	5.02	500	7.5	6.8	3.9	7.4
	6/25/92	5.13	ND	ND	0.9	0.7	ND
	7/30/92	5.19	500	7.7	8.6	3.2	1.7
	8/20/92	5.27	1100	6.6	4.5	2.7	2.0
	9/30/92	5.45	500	5.4	2.4	1.8	4.5
	12/23/92	4.60	800	1.9	ND	ND	2.3
	3/10/93	4.18	1200	ND	1.4	ND	2.1
	6/09/93	4.53	200	ND	ND	ND	ND
	09/14/93	5.26	360	1.6	1.1	3.2	8.9
	12/16/93	2.75	2400	5.8	9.9	<0.3	ND

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.

ND - Not Detected.

TPH - Total Petroleum Hydrocarbons as gasoline.

D-Wat - Depth to Water.

NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

Table 1 (CONT.) - Summary of Analytical Results

I.D.	Date	D-Wat	TPH	Benzene	Toluene	Ethyl-Benzenes	Xylenes
RE-3 (167.39)	4/11/88	—	70000	6600	5300	800	13000
	4/09/90	7.15	370000	2300	4900	3200	31000
	10/30/90	7.84	13000	860	660	220	2210
	1/18/91	6.90	42000	4700	4500	21	7700
	2/12/91	6.62	72000	3600	4500	ND	7600
	3/20/91	5.87	65000	2400	9400	50	9800
	5/22/91	5.98(Film)	NSC				
	6/19/91	6.84(Film)	NSC				
	7/17/91	7.10(Film)	NSC				
	8/07/91	7.30(Film)	NSC				
	9/24/91	7.84(Film)	NSC				
	10/23/91	8.07(Film)	NSC				
	11/06/91	7.63(Film)	NSC				
	12/04/91	7.83(Film)	NSC				
	1/29/92	7.17(Film)	NSC				
	2/26/92	5.56(Film)	NSC				
	3/19/92	5.44(Film)	NSC				
	4/22/92	6.56(Film)	NSC				
	5/21/92	6.90(Film)	NSC				
	6/25/92	7.18(Film)	NSC				
	7/30/92	6.80(Film)	NSC				
	8/20/92	7.25(Film)	NSC				
	9/30/92	7.68(Film)	NSC				
	12/23/92	6.07(Film)	NSC				
	3/10/93	5.66(Film)	NSC				
	6/10/93	6.66(Film)	NSC				
	09/14/93	7.30	40000	2900	1500	180	6900
	12/14/93	5.95	NSC				
RE-4 (168.94)	4/11/88	—	150000	12000	8000	1000	27000
	4/09/90	—	NSC				
	10/30/90	7.04	87000	7200	10000	1600	12900
	1/18/91	11.62	70000	5000	5400	790	9900
	2/12/91	11.63	87000	5200	2800	240	11000
	3/20/91	11.61	6500	370	230	17	670
	5/22/91	10.3(Film)	NSC				
	6/19/91	11.1(Film)	NSC				
	7/17/91	6.20(Film)	NSC				
	8/07/91	8.15(Film)	NSC				
	9/24/91	10.4(Film)	NSC				
	10/23/91	11.2(Film)	NSC				
	11/06/91	6.62(Film)	NSC				
	12/04/91	11.2(Film)	NSC				
	1/29/92	7.72(Film)	NSC				
	2/26/92	5.13(Film)	NSC				
	3/19/92	5.00(Film)	NSC				
	4/22/92	5.94(Film)	NSC				
	5/21/92	5.40(Film)	NSC				
	6/25/92	5.71(0.02)	NSC				
	7/30/92	8.33(Film)	NSC				
	8/20/92	5.80(Film)	NSC				
	9/30/92	6.34(Film)	NSC				
	12/23/92	5.50(Film)	NSC				
	3/10/93	4.67(Film)	NSC				
	6/09/93	5.12(Film)	NSC				
	09/14/93	10.44	NSC				
	12/14/93	7.52	NSC				

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.  
 ND - Not Detected.  
 TPH - Total Petroleum Hydrocarbons as gasoline.  
 D-Wat - Depth to Water.  
 NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

Table 1 (CONT.) - Summary of Analytical Results

I.D.	Date	D-Wat.	TPH	Benzene	Toluene	Ethyl-Benzene	Xylenes
RE-5 (166.51)	4/11/88	-	14000	1300	1100	100	2600
	4/09/90	4.79	3000	690	190	40	270
	10/30/90	5.86	3400	910	48	87	249
	1/18/91	4.40	1400	180	8.6	0.52	48
	2/12/91	4.76	1000	ND	ND	0.65	ND
	3/20/91	5.08	3000	250	53	ND	110
	5/22/91	4.52	2500	330	7.8	5.6	200
	6/19/91	4.39	2000	59	1.6	5.1	110
	7/17/91	5.05(Film)	NSC				
	8/07/91	5.02(Film)	NSC				
	9/24/91	5.86(Film)	NSC				
	10/23/91	5.84(Film)	NSC				
	11/06/91	5.48	9900	2300	37	260	160
	12/04/91	5.43	4500	1000	27	ND	180
	1/29/92	5.12	600	6.1	2.3	ND	47
	2/26/92	4.93	500	5.4	2.7	1.2	14
	3/19/92	4.45	ND	1.7	1.1	ND	5.5
	4/22/92	4.63	1600	240	2.2	ND	160
	5/21/92	4.90	1200	410	37	ND	118
	6/25/92	5.15	ND	1.0	0.8	0.8	0.4
	7/30/92	5.30	ND	2.0	1.8	1.9	6.4
	8/20/92	5.44	300	1.7	3.3	0.7	12
	9/30/92	5.73	1900	140	ND	19	35
	12/23/92	4.75	400	8.0	ND	ND	ND
	3/10/93	4.14	1100	290	9.7	ND	75
	6/09/93	5.42	400	1.5	0.5	ND	12
	09/14/93	5.53	240	6.9	8.8	1.4	67
	12/14/93	4.78	18000	510	5.4	<0.3	35
RE-5 (166.51)	4/11/88	-	6000	3000	40	80	140
	4/09/90	5.64	3000	990	ND	70	ND
	10/30/90	6.68	3400	1000	28	ND	ND
	1/18/91	6.61	6300	1200	ND	3	15
	2/12/91	6.20	5200	850	8.4	4.9	41
	3/20/91	5.62	5800	680	12	8	16
	5/22/91	6.05	8500	1700	14	24	6.7
	6/19/91	6.12(Film)	NSC				
	7/17/91	6.20	120000	9300	13000	2400	16000
	8/07/91	6.27	NA	590	5.3	ND	14
	9/24/91	6.63	7000	310	11	5.3	35
	10/23/91	6.36(Film)	NSC				
	11/06/91	6.15	4000	710	18	29	49
	12/04/91	6.19	4100	1100	14	33	39
	1/29/92	6.70	2600	790	14	ND	49
	2/26/92	5.44	3100	950	21	30	33
	3/19/92	5.30	2200	630	14	ND	40
	4/22/92	6.00	NA	730	2.2		
	5/21/92	6.25	1500	840	7.8	7.1	34
	6/25/92	6.38	<2000	740	8	27	28
	7/30/92	6.42(Film)	NSC				
	8/20/92	6.50	2800	630	17	23	22
	9/30/92	6.66	7800	540	ND	12	29
	12/23/92	5.83	1800	350	ND	7.7	11
	3/10/93	5.63	3000	830	5.6	19	18
	6/09/93	6.01	4800	920	6.2	3.2	12
	09/14/93	6.53	3600	660	7.5	11	27
	12/14/93	3.58	18000	280	<0.3	<0.3	35

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.

ND - Not Detected.

TPH - Total Petroleum Hydrocarbons as gasoline.

D-Wat - Depth to Water.

NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

Table 1 (CONT.) - Summary of Analytical Results

ID	Date	E-Wat	TPH	Benzene	Toluene	Ethy-Benzene	Xylenes
RE-7 (166.04)	4/11/88	--	<50000	17000	4400	600	8400
	4/05/90	5.93	16000	7000	1200	640	1600
	10/30/90	8.21	31000	14000	ND	ND	ND
	1/18/91	11.8(Film)	NSC				
	2/12/91	10.8(Film)	NSC				
	3/20/91	9.96	120000	12000	2800	490	6600
	5/22/91	11.7(Film)	NSC				
	6/19/91	11.5(Film)	NSC				
	7/17/91	7.80(Film)	NSC				
	8/07/91	9.88(0.03)	NSC				
	9/24/91	9.85(0.03)	NSC				
	10/23/91	9.96(Film)	NSC				
	11/06/91	6.77(Film)	NSC				
	12/04/91	10.8(Film)	NSC				
	1/29/92	8.64(Film)	NSC				
	2/26/92	6.00(Film)	NSC				
	3/19/92	5.55(Film)	NSC				
	4/22/92	6.12(Film)	NSC				
	5/21/92	6.40(Film)	NSC				
	6/25/92	6.73(0.02)	NSC				
RE-8 (164.32)	7/30/92	6.73(Film)	NSC				
	8/20/92	6.82(Film)	NSC				
	9/30/92	7.26(Film)	NSC				
	12/23/92	6.22(Film)	NSC				
	3/10/93	5.82(Film)	NSC				
	6/09/93	6.17(Film)	NSC				
	09/14/93	11.33	NSC				
	12/14/93	8.40	NSC				
	8/07/91	9.68	ND	ND	ND	ND	ND
	9/27/91	9.89	ND	ND	ND	ND	ND
	10/23/91	10.05	ND	ND	ND	ND	ND
	11/06/91	9.71	ND	ND	ND	ND	ND
	12/04/91	10.00	ND	ND	ND	ND	ND
	1/29/92	9.28	ND	2.1	1.0	2.5	3.6
	2/26/92	7.05	ND	ND	0.7	ND	0.7
	3/19/92	7.30	ND	0.5	1.0	1.5	2.7
	4/22/92	8.60	ND	ND	ND	ND	ND
	5/21/92	9.22	ND	ND	ND	ND	ND
	6/25/92	9.49	ND	ND	ND	ND	ND
	7/30/92	9.55	ND	1.1	4.2	ND	3.0
	8/20/92	9.63	ND	2.0	4.7	ND	5.7
	9/30/92	9.90	ND	ND	ND	ND	ND
	12/23/92	9.96	ND	ND	ND	ND	ND
	3/10/93	8.95	ND	ND	ND	ND	ND
	6/09/93	9.00	ND	ND	ND	ND	ND
	09/14/93	9.50	0.2	0.3	ND	ND	ND
	12/14/93	8.75	ND	ND	ND	ND	ND

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.

ND - Not Detected.

TPH - Total Petroleum Hydrocarbons as gasoline.

D-Wat - Depth to Water.

NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

Table 1 (CONT.) - Summary of Analytical Results

I.D.	Date	E-Wat	TPH	Benzene	Toluene	Ethyl-Benzene	Xylenes
RS-9 (167.51)	8/07/91	2.28	NA	0.5	ND	330	1200
	9/27/91	2.77	13000	3.5	3.0	82	140
	10/23/91	3.53	11000	ND	ND	39	340
	11/06/91	2.51	6800	8.4	0.6	22	230
	12/04/91	3.20	6500	6.5	0.7	87	200
	1/29/92	2.65	8100	22	10	140	260
	2/26/92	3.42	13000	40	16	220	600
	3/19/92	3.12	12000	21	12	100	280
	4/22/92	3.24	8600	ND	ND	20	37
	5/21/92	3.75	6000	21	10	53	210
	6/25/92	2.65	370	2.3	1.5	0.7	4.3
	7/30/92	2.70	3600	20	ND	39	80
	8/20/92	2.83	3000	0.7	5.2	2.0	5.3
	9/30/92	2.80	9200	4.8	6.5	12	91
	12/23/92	2.45	2000	17	ND	8.2	18
	3/10/93	2.40	1500	ND	2.6	21	12
	6/09/93	3.55	1300	0.6	1.7	ND	7.5
	09/14/93	2.81	1500	1.3	7.6	4.1	14.0
	12/14/93	2.63	860	ND	ND	ND	5.5

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.

ND - Not Detected.

TPH - Total Petroleum Hydrocarbons as gasoline.

D-Wat - Depth to Water.

NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

Table 1(CONT.) - Summary of Analytical Results

ID	Date	D-Wat	TPH	Benzene	Toluene	Ethyl-Benzene	Xylenes
RS10 (162.89)	8/07/91	6.16	ND	ND	ND	ND	ND
	9/27/91	6.48	ND	ND	ND	ND	ND
	10/23/91	7.37	ND	ND	ND	ND	ND
	11/06/91	6.44	ND	ND	ND	ND	ND
	12/04/91	7.02	ND	ND	ND	ND	ND
	1/29/92	6.78	ND	ND	ND	ND	ND
	2/26/92	8.33	ND	ND	ND	ND	ND
	3/19/92	8.02	ND	ND	ND	ND	0.6
	4/22/92	7.78	ND	ND	ND	ND	ND
	5/21/92	6.21	ND	ND	0.6	ND	1.2
	6/25/92	7.73	ND	ND	ND	ND	ND
	7/30/92	7.84	ND	ND	0.5	ND	1.0
	8/20/92	7.50	ND	ND	ND	ND	ND
	9/30/92	7.63	ND	ND	ND	ND	ND
	12/23/92	7.24	ND	ND	ND	ND	ND
	3/10/93	6.38	ND	ND	ND	ND	ND
	6/09/93	7.98	ND	ND	ND	ND	ND
	09/14/93	7.35	ND	ND	ND	ND	ND

Results reported in micrograms per liter (ug/L)

NA - Not Analyzed.


ND - Not Detected.

TPH - Total Petroleum Hydrocarbons as gasoline.

D-Wat - Depth to Water.

NSC - No sample collected due to film or sheen of liquid phase hydrocarbons.

## *FIGURES*



**SITE PLAN II**  
**THRIFTY OIL CO. #054**  
**CASTRO VALLEY, CALIFORNIA**  
*\*Prepared for*  
**THRIFTY OIL CO.**  
**DOWNEY, CALIFORNIA**


0 25 50

SCALE IN FEET

✓ GROUNDWATER CONTOUR, 12/14/94

◆ EXISTING MONITORING WELL

FIGURE 1



THRIFTY OIL CO. #054  
CASTRO VALLEY, CALIFORNIA  
Prepared for  
THRIFTY OIL CO.  
DOWNEY, CALIFORNIA


0 25 50  
SCALE IN FEET

TPH ISO-COV. 12/14/94, 1996

♦ EXISTING MONITORING WELL

FIGURE 2

PC



**THRIFTY OIL CO. #054  
CASTRO VALLEY, CALIFORNIA**

A horizontal scale bar with tick marks at 0, 25, and 50. Below it is the text "SCALE IN FEET".

1 BENZENE 150-CON. 12/14/94, ppb

 EXISTING MONITORING WELL

FIGURE 3



## *APPENDIX A*

## SAVE SYSTEM

## OPERATING DATA

## FIELD STATUS REPORT

PARAMETER	U/M	
TIME	AM/PM	10:30
WORKING	YES/NO	YES
RESTARTED	YES/NO	NO
HOURS	#	2960
ENGINE ROT.	RPM	1800
ENGINE VACUUM	IN HG	10
ENG. OIL PRESS.	PSI	40
ENG. WATER TEMP.	°F	160
ENG. ELECTR. TENS.	VOLTS	13
TANK VACUUM	IN HG	12
TK. REC. PRES.	PSI	30
TK. REC. TEMP.	°F	100
AIR TEMPERATURE	°F	65
AIR FLOW	CFM	15
VAPOR FLOW	CFM	17
FUEL FLOW	CFM/H	80
WELL VACUUM	IN H2O	25
L P G TANKS	%	#1: 18 #2:
GAS METER READING		
WATER FLOWMETER	GALL.	3038
CATALYST IN TEMP.	°F	
CATALYST OUT TEMP.	°F	
EXHAUST (See permit and PSR for frequency and limits)	BY C.A.	H-C ppm/% CO %/ppm CO2 % O2 % NOX %/ppm
OUTLET FROM ENGINE	BY	O.V. ppm
INLET TO ENGINE		O.V. ppm

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO). CHECK HERE  WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency). CHECK HERE  O.K.  NO

CHANGE CATALYST (See permit and PSR for limits). CHECK HERE  WHEN REPLACED

VAPOR WELLS ON: HLL

WATER WELLS ON: RE 4 + RE 7

SERVICE TECH: E GRISMAN

DATE: 10-7-93 THRIFTY OIL CO. ss #: 054

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level		✓		
Coolant, Check Level		✓		
Fuel, Oil, Coolant, Check for Leaks		✓		
Oil, Engine, Change		✓		
Oil, Filter, Change		✓		
Battery, Check Charge and Fluid		✓		
Battery Cables, Clean		✓		
P.T.O. Bearings, Lubricate		✓		
Fan, Alternator Belts, Check and Adjust		✓		
Idle Speed, Check		✓		
Idle Mixture, Check		✓		
Radiator, Inspect and Clean Exterior				✓
Distributor, Clean and Check Points				✓
Ignition Timing, Check and Adjust				✓
PCV Valve, Replace				✗
PCV Hoses and Fitting, Check				✓
Spark Plugs, Replace				✓
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				✓
All Nuts and Bolts, Check				✓

Comments:

---



---



---



---

## SAVE SYSTEM

## OPERATING DATA

## FIELD STATUS REPORT

PARAMETER		U/M	
TIME		AM/PM	
WORKING		YES/NO	
RESTARTED		YES/NO	
HOURS		#	2972
ENGINE ROT.		R P M	1800
ENGINE VACUUM		IN HG	10
ENG. OIL PRESS.		PSI	40
ENG. WATER TEMP.		°F	160
ENG. ELECTR. TENS.		VOLTS	13
TANK VACUUM		IN HG	12
TK. REC. PRES.		PSI	25
TK. REC. TEMP.		°F	90
AIR TEMPERATURE		°F	63
AIR FLOW		C F M	15
VAPOR FLOW		C F M	18
FUEL FLOW		C F M/H	80
WELL VACUUM		IN H2O	2.6
L P G TANKS		%	#190 #2:
GAS METER READING			
WATER FLOWMETER		GALL.	3039
CATALYST IN TEMP.		°F	
CATALYST OUT TEMP.		°F	
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE		O.V.	ppm
INLET TO ENGINE		O.V.	ppm

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).  CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).  CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits).  CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL  WATER WELLS ON: RS-4 ; RS-7

SERVICE TECH: E. GASMAN DATE: 10.14.93 THRIFTY OIL CO. ss #: 054

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level	✓			
Coolant, Check Level	✓			
Fuel, Oil, Coolant, Check for Leaks	✓			
Oil, Engine, Change				
Oil, Filter, Change				
Battery, Check Charge and Fluid				
Battery Cables, Clean				
P.T.O. Bearings, Lubricate				
Fan, Alternator Belts, Check and Adjust				
Idle Speed, Check				
Idle Mixture, Check				
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

SAVE SYSTEM

OPERATING DATA

## FIELD STATUS REPORT

PARAMETER		U/M	
TIME	AM/PM	18.00	
WORKING	YES/NO	No	
RESTARTED	YES/NO	YES	
HOURS	#	3089	
ENGINE ROT.	R P M	1800	
ENGINE VACUUM	IN HG	10	
ENG. OIL PRESS.	P S I	40	
ENG. WATER TEMP.	°F	160	
ENG. ELECTR. TENS.	VOLTS	13	
TANK VACUUM	IN HG	11	
TK. REC. PRES.	PSI	25	
TK. REC. TEMP.	°F	90	
AIR TEMPERATURE	°F	62	
AIR FLOW	C F M	16	
VAPOR FLOW	C F M	18	
FUEL FLOW	C F M/H	80	
WELL VACUUM	IN H2O	24	
LPG TANKS	%	#188 #2:	
GAS METER READING			
WATER FLOWMETER	GALL.	3039	
CATALYST IN TEMP.	°F		
CATALYST OUT TEMP.	°F		
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE	O.V.	ppm	
INLET TO ENGINE	O.V.	ppm	

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO). CHECK HERE  WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency). CHECK HERE  O.K.  NO

CHANGE CATALYST (See permit and PSR for limits). CHECK HERE  WHEN REPLACED

VAPOR WELLS ON: ALC WATER WELLS ON: RS-4, RS-7

SERVICE TECH: E-GAS MAN DATE: 10/21/93 THRIFTY OIL CO. ss #: 054

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level	✓			
Coolant, Check Level	✓			
Fuel, Oil, Coolant, Check for Leaks	✓			
Oil, Engine, Change				
Oil, Filter, Change				
Battery, Check Charge and Fluid				
Battery Cables, Clean				
P.T.O. Bearings, Lubricate				
Fan, Alternator Belts, Check and Adjust				
Idle Speed, Check				
Idle Mixture, Check				
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: On arrival the engine was stop. For restart ~~██████████~~ replaced the coil.

PARAMETER	U/M	
TIME	AM/PM	
WORKING	YES/NO	YES
RESTARTED	YES/NO	YES
HOURS	#	
ENGINE ROT.	R P M	2000
ENGINE VACUUM	IN HG	10
ENG. OIL PRESS.	P S I	42
ENG. WATER TEMP.	°F	160
ENG. ELECTR. TENS.	VOLTS	13
TANK VACUUM	IN HG	12
TK. REC. PRES.	PSI	0
TK. REC. TEMP.	°F	120
AIR TEMPERATURE	°F	65
AIR FLOW	C F M	14
VAPOR FLOW	C F M	18
FUEL FLOW	C F M/H	80
WELL VACUUM	IN H2O	24
L P G TANKS	%	#1: 85 #2:
GAS METER READING		
WATER FLOWMETER	GALL.	3047
CATALYST IN TEMP.	°F	
CATALYST OUT TEMP.	°F	
EXHAUST (See permit and PSR for frequency and limits)	BY C.A.	H-C ppm/% CO %/ppm CO2 % O2 % NOX %/ppm
OUTLET FROM ENGINE	BY	O.V. ppm
INLET TO ENGINE		O.V. ppm

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits).      CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL

WATER WELLS ON: N.

SERVICE TECH: E. GASMAN DATE: 10/28/93 THRIFTY OIL CO. ss #: SS # 054

PARAMETER		U/M	
TIME	AM/PM	15:40	
WORKING	YES/NO	YES	
RESTARTED	YES/NO	YES	
HOURS	#	3381	
ENGINE ROT.	R P M	1900	
ENGINE VACUUM	IN HG	10	
ENG. OIL PRESS.	P S I	45	
ENG. WATER TEMP.	°F	160	
ENG. ELECTR. TENS.	VOLTS	13	
TANK VACUUM	IN HG	0	
TK. REC. PRES.	PSI	40	
TK. REC. TEMP.	°F	100	
AIR TEMPERATURE	°F	70	
AIR FLOW	C F M	14	
VAPOR FLOW	C F M	18	
FUEL FLOW	C F M/H	80	
WELL VACUUM	IN H2O	25	
L P G TANKS	%	#1:25 #2:	
GAS METER READING			
WATER FLOWMETER	GALL.	3047	
CATALYST IN TEMP.	°F		
CATALYST OUT TEMP.	°F		
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE	O.V.	ppm	
INLET TO ENGINE	O.V.	ppm	

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE (  ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE (  ) O.K. (  ) NO

CHANGE CATALYST (See permit and PSR for limits).      CHECK HERE (  ) WHEN REPLACED

VAPOR WELLS ON: ALL      WATER WELLS ON: NO

SERVICE TECH: E. GASMAN      DATE: 11/03/93      THRIFTY OIL CO. ss #: 054

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level				
Coolant, Check Level				
Fuel, Oil, Coolant, Check for Leaks				
Oil, Engine, Change	✓			
Oil, Filter, Change	✓			
Battery, Check Charge and Fluid	✓			
Battery Cables, Clean	✓			
P.T.O. Bearings, Lubricate	✓			
Fan, Alternator Belts, Check and Adjust	✓			
Idle Speed, Check	✓			
Idle Mixture, Check	✓			
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: \_\_\_\_\_

PARAMETER	U/M	
TIME	AM/PM	11:00
WORKING	YES/NO	YES
RESTARTED	YES/NO	NO
HOURS	#	3526
ENGINE ROT.	R P M	1700
ENGINE VACUUM	IN HG	10
ENG. OIL PRESS.	P S I	45
ENG. WATER TEMP.	°F	160
ENG. ELECTR. TENS.	VOLTS	13
TANK VACUUM	IN HG	11
TK. REC. PRES.	PSI	20
TK. REC. TEMP.	°F	100
AIR TEMPERATURE	°F	65
AIR FLOW	C F M	14
VAPOR FLOW	C F M	17
FUEL FLOW	C F M/H	70
WELL VACUUM	IN H2O	25
L P G TANKS	%	#1: #2:
GAS METER READING		
WATER FLOWMETER	GALL.	3050
CATALYST IN TEMP.	°F	
CATALYST OUT TEMP.	°F	

EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%	
		CO	%/ppm	
		CO2	%	
		O2	%	
		NOX	%/ppm	
	BY	O.V.	ppm	
OUTLET FROM ENGINE	O.V.	ppm		
INLET TO ENGINE	O.V.	ppm		

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO). CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency). CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits). CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL

WATER WELLS ON: RJ-4 + RJ-7

SERVICE TECH: E. CABANAL

DATE: 11/10/93 THRIFTY OIL CO. ss #: 054

### MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level				
Coolant, Check Level				
Fuel, Oil, Coolant, Check for Leaks				
Oil, Engine, Change			✓	
Oil, Filter, Change			✓	
Battery, Check Charge and Fluid			✓	
Battery Cables, Clean			✓	
P.T.O. Bearings, Lubricate			✓	
Fan, Alternator Belts, Check and Adjust			✓	
Idle Speed, Check			✓	
Idle Mixture, Check			✓	
Radiator, Inspect and Clean Exterior			✓	
Distributor, Clean and Check Points			✓	
Ignition Timing, Check and Adjust			✓	
PCV Valve, Replace				
PCV Hoses and Fitting, Check			✓	
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque			✓	
All Nuts and Bolts, Check			✓	

Comments: The recovery well is very slow in RS-4 and RJ-7

PARAMETER	U/M	
TIME	AM/PM	15:00
WORKING	YES/NO	N.
RESTARTED	YES/NO	YES
HOURS	#	3546
ENGINE ROT.	R P M	1900
ENGINE VACUUM	IN HG	10
ENG. OIL PRESS.	P S I	40
ENG. WATER TEMP.	°F	160
ENG. ELECTR. TENS.	VOLTS	13
TANK VACUUM	IN HG	12
TK. REC. PRES.	PSI	30
TK. REC. TEMP.	°F	90
AIR TEMPERATURE	°F	63
AIR FLOW	C F M	16
VAPOR FLOW	C F M	18
FUEL FLOW	C F M/H	80
WELL VACUUM	IN H2O	26
L P G TANKS	%	#190 #2:
GAS METER READING		
WATER FLOWMETER	GALL.	3053
CATALYST IN TEMP.	°F	
CATALYST OUT TEMP.	°F	
EXHAUST (See permit and PSR for frequency and limits)	BY C.A.	H-C ppm/% CO %/ppm CO2 % O2 % NOX %/ppm
OUTLET FROM ENGINE	O.V.	ppm
INLET TO ENGINE	O.V.	ppm

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).  CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).  CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits).  CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL	WATER WELLS ON: RE-4 ; RE-7
SERVICE TECH: E. GASMAN	DATE: 11/17/93 THRIFTY OIL CO. ss #: 054

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level	✓			
Coolant, Check Level	✓			
Fuel, Oil, Coolant, Check for Leaks	✓			
Oil, Engine, Change				
Oil, Filter, Change				
Battery, Check Charge and Fluid				
Battery Cables, Clean				
P.T.O. Bearings, Lubricate				
Fan, Alternator Belts, Check and Adjust				
Idle Speed, Check				
Idle Mixture, Check				
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: L/W air system sampling  
Monthly water system sampling



# EARTH MANAGEMENT CO.

Environmental Remediation

PROJECT STATUS REPORT

THRIFTY OIL CO. S.S. #054

2504 CASTRO VALLEY BLVD.

CASTRO VALLEY, CA 94546

DATE: 11/17/1993

F R E Q .	MONITORING				ODORS			FREE PRODUCT	WELLS CONNECTED TO SYSTEM (W)									
	OBSERVATION WELLS				(S=SLIGHT)				CONNECT	INTEGRITY		VAPOR		WATER				
	NO.	DTW	DTP	PT	YES	NO	S			YES	NO	YES	NO	OK	NO	ON	OFF	ON
M	PW-1	6.56					Y		X	X	-							
M	PW-2	6.40					Y		X	X	-							
M	RE-1	5.25					Y		X	X	-							
M	RE-2	5.12					Y		X	X	-							
M	RE-3	7.65	Film		Y				X	X	-							
M	RE-4	6.15	Film		Y				X	X	-							
M	RE-5	5.43			Y				X	X	-							
M	RE-6	6.32			Y				X	X	-							
M	RE-7	7.57	Film		Y				X	X	-							
M	RS-8	9.68			Y				X	-	X							
M	RS-9	3.20			Y				X	-	X							
M	RS-10	7.82			Y				X	-	X							
SAVE SYSTEM WEEKLY																		
PARAMETER		U/M		DATA		PARAMETER		U/M		DATA								
TIME		AM/PM		15:00		AIR FLOW		CFM		16								
WORKING		YES/NO		No		VAPOR FLOW		CFM		18								
RESTARTED		YES/NO		YES		FUEL FLOW		CFM/H		80								
HOURS		#		3546		WELL VACUUM		IN H2O		26								
ENGINE ROT.		RPM		1900		LPG TANKS		#1:		90								
ENGINE VACUUM		IN HG		10		GAS METER READING		-		N/A								
TANK VACUUM		IN HG		12		WATER FLOWMETER		GALL.		3053								
EXHAUST (By others)																		
INLET TO ENGINE																		
MAINTENANCE		ES/100/400/800				FOR SPECIFIC OPERATIONS SEE FIELD RECORD												
WATER SAMPLING - CHECK <input checked="" type="checkbox"/> WHEN DONE																		
EFFLUENT						INFLUENT				WELLS								
<input checked="" type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>				<input type="checkbox"/> Q.-SEE C.CUST.								
REMARKS: _____																		
FREE PRODUCT REMOVED: APPROX. ____ GALLONS										WATER REMOVED: APPROX. ____ GALLONS								
DATA RECORDED BY : E-GASMAN										INPUT BY: M.M. >\FF\054rsirt								

PARAMETER		U/M	
TIME		AM/PM	10:30
WORKING		YES/NO	YES
RESTARTED		YES/NO	
HOURS		#	3692
ENGINE ROT.		R P M	1900
ENGINE VACUUM		IN HG	10
ENG. OIL PRESS.		P S I	45
ENG. WATER TEMP.		°F	150
ENG. ELECTR. TENS.		VOLTS	13
TANK VACUUM		IN HG	12
TK. REC. PRES.		PSI	40
TK. REC. TEMP.		°F	110
AIR TEMPERATURE		°F	60
AIR FLOW		C F M	15
VAPOR FLOW		C F M	17
FUEL FLOW		C F M/H	20
WELL VACUUM		IN H2O	26
L P G TANKS		%	#1: 10 #2:
GAS METER READING			
WATER FLOWMETER		GALL.	3091
CATALYST IN TEMP.		°F	
CATALYST OUT TEMP.		°F	
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE		O.V.	ppm
INLET TO ENGINE		O.V.	ppm

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE  WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE  O.K.  NO

CHANGE CATALYST (See permit and PSR for limits).      CHECK HERE  WHEN REPLACED

VAPOR WELLS ON: ALL

WATER WELLS ON: RE-4; RE-7

SERVICE TECH: E. GASMAN

DATE: 11/24/1993 THRIFTY OIL CO. ss #: 054

PARAMETER		U/M	
TIME	AM/PM	11	
WORKING	YES/NO	No	
RESTARTED	YES/NO	YES	
HOURS	#	3705	
ENGINE ROT.	R P M	1900	
ENGINE VACUUM	IN HG	10	
ENG. OIL PRESS.	P S I	45	
ENG. WATER TEMP.	°F	160	
ENG. ELECTR. TENS.	VOLTS	13	
TANK VACUUM	IN HG	12	
TK. REC. PRES.	PSI	25	
TK. REC. TEMP.	°F	80	
AIR TEMPERATURE	°F	53	
AIR FLOW	C F M	15	
VAPOR FLOW	C F M	18	
FUEL FLOW	C F M/H	80	
WELL VACUUM	IN H2O	25	
L P G TANKS	%	#187 #2:	
GAS METER READING			
WATER FLOWMETER	GALL.	3093	
CATALYST IN TEMP.	°F		
CATALYST OUT TEMP.	°F		
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE	O.V.	ppm	
INLET TO ENGINE	O.V.	ppm	

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level	✓			
Coolant, Check Level	✓			
Fuel, Oil, Coolant, Check for Leaks	✓			
Oil, Engine, Change				
Oil, Filter, Change				
Battery, Check Charge and Fluid				
Battery Cables, Clean				
P.T.O. Bearings, Lubricate				
Fan, Alternator Belts, Check and Adjust				
Idle Speed, Check				
Idle Mixture, Check				
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: \_\_\_\_\_

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC &amp; CO). CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency). CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits). CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL WATER WELLS ON: RE 4 + RE 7

SERVICE TECH: E. GASMA N DATE: 12.01.93 THRIFTY OIL CO. ss #: 054

## SAVE SYSTEM OPERATING DATA

## FIELD STATUS REPORT

PARAMETER	U/M	
TIME	AM/PM	11:45
WORKING	YES/NO	No
RESTARTED	YES/NO	Yes
HOURS	#	3850
ENGINE ROT.	R P M	1800
ENGINE VACUUM	IN HG	11
ENG. OIL PRESS.	P S I	45
ENG. WATER TEMP.	°F	150
ENG. ELECTR. TENS.	VOLTS	13
TANK VACUUM	IN HG	12
TK. REC. PRES.	PSI	25
TK. REC. TEMP.	°F	100
AIR TEMPERATURE	°F	50
AIR FLOW	C F M	15
VAPOR FLOW	C F M	17
FUEL FLOW	C F M/H	80
WELL VACUUM	IN H2O	27
L P G TANKS	%	#135 #2:
GAS METER READING		31
WATER FLOWMETER	GALL.	3145
CATALYST IN TEMP.	°F	
CATALYST OUT TEMP.	°F	

EXHAUST (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%	
		CO	%/ppm	
		CO2	%	
		O2	%	
		NOX	%/ppm	
	BY	O.V.	ppm	
OUTLET FROM ENGINE	O.V.	ppm		
INLET TO ENGINE	O.V.	ppm		

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits).      CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL      WATER WELLS ON: RE-4, RE-7

SERVICE TECH: E. GASMAN      DATE: 12/07/93      THRIFTY OIL CO. ss #: 054

MAINTENANCE RECORD				
Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level		✓		
Coolant, Check Level		✓		
Fuel, Oil, Coolant, Check for Leaks		✓		
Oil, Engine, Change		✓		
Oil, Filter, Change		✓		
Battery, Check Charge and Fluid		✓		
Battery Cables, Clean		✓		
P.T.O. Bearings, Lubricate		✓		
Fan, Alternator Belts, Check and Adjust		✓		
Idle Speed, Check		✓		
Idle Mixture, Check		✓		
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments:  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## SAVE SYSTEM

## OPERATING DATA

## FIELD STATUS REPORT

PARAMETER		U/M	
TIME	AM/PM	12:10	
WORKING	YES/NO	YES	
RESTARTED	YES/NO	No	
HOURS	#	4022	
ENGINE ROT.	R P M	2000	
ENGINE VACUUM	IN HG	11	
ENG. OIL PRESS.	P S I	45	
ENG. WATER TEMP.	°F	150	
ENG. ELECTR. TENS.	VOLTS	13	
TANK VACUUM	IN HG	13	
TK. REC. PRES.	P S I	35	
TK. REC. TEMP.	°F	90	
AIR TEMPERATURE	°F	54	
AIR FLOW	C F M	16	
VAPOR FLOW	C F M	18	
FUEL FLOW	C F M/H	85	
WELL VACUUM	IN H2O	27	
L P G TANKS	%	#1:25 #2:	
GAS METER READING			
WATER FLOWMETER	GALL.	3246	
CATALYST IN TEMP.	°F		
CATALYST OUT TEMP.	°F		
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE	O.V.	ppm	
INLET TO ENGINE	O.V.	ppm	

MAINTENANCE RECORD					
Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly	
Oil, Engine, Check Level					
Coolant, Check Level					
Fuel, Oil, Coolant, Check for Leaks					
Oil, Engine, Change	✓				
Oil, Filter, Change	✓				
Battery, Check Charge and Fluid	✓				
Battery Cables, Clean	✓				
P.T.O. Bearings, Lubricate	✓				
Fan, Alternator Belts, Check and Adjust	✓				
Idle Speed, Check	✓				
Idle Mixture, Check	✓				
Radiator, Inspect and Clean Exterior					
Distributor, Clean and Check Points					
Ignition Timing, Check and Adjust					
PCV Valve, Replace					
PCV Hoses and Fitting, Check					
Spark Plugs, Replace					
Points, Replace					
Oil, Vacuum Pump, Change					
Intake Manifold Bolts, Torque					
All Nuts and Bolts, Check					

Comments: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE ( ) WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE ( ) O.K. ( ) NO

CHANGE CATALYST (See permit and PSR for limits).      CHECK HERE ( ) WHEN REPLACED

VAPOR WELLS ON: ALL      WATER WELLS ON: RE 7, RE 4

SERVICE TECH: E. CASMAN      DATE: 12/15/1993 THRIFTY OIL CO. ss #: 059



# EARTH MANAGEMENT CO.

Environmental Remediation

PROJECT STATUS REPORT  
THRIFTY OIL CO. S.S. #054  
2504 CASTRO VALLEY BLVD.  
CASTRO VALLEY, CA 94546  
DATE: 12/14/1993

F R E Q .	MONITORING				ODORS			FREE PRODUCT		WELLS CONNECTED TO SYSTEM (W)							
	OBSERVATION WELLS				(S=SLIGHT)			YES	NO	CONNECT	INTEGRITY	VAPOR		WATER			
	NO.	DTW	DTP	PT	YES	NO	S					YES	NO	ON	OFF	ON	OFF
M	PW-1	4.65				X			X	X	-	X					
M	PW-2	5.22				X			X	X	-	X					
M	RE-1	4.58				X			X	X	-	X					
M	RE-2	2.75				X			X	X	-	X					
M	RE-3	5.95	Felix			Y			X	X	-	X					
M	RE-4	7.52	Felix			Y			X	X	-	X				X	
M	RE-5	4.78				X			X	X	-	X					
M	RE-6	3.58				Y			X	X	-	X					
M	RE-7	8.40	Stew			X			Y	X	-	X				X	X
M	RS-8	8.75				Y			X	-	X						
M	RS-9	2.65				Y			X	-	X						
M	RS-10	7.38				Y			X	-	X						

## SAVE SYSTEM WEEKLY

PARAMETER	U/M	DATA	PARAMETER	U/M	DATA
TIME	AM/PM	13:00	AIR FLOW	C F M	16
WORKING	YES/NO	YES	VAPOR FLOW	C F M	18
RESTARTED	YES/NO	No	FUEL FLOW	C F M/H	80
HOURS	#	4002	WELL VACUUM	IN H2O	27
ENGINE ROT.	RPM	1900	L P G TANKS	#	#1: 29
ENGINE VACUUM	IN HG	11	GAS METER READING	-	N/A
TANK VACUUM	IN HG	45	WATER FLOWMETER	GALL.	3146

EXHAUST (By others)					
INLET TO ENGINE					

MAINTENANCE	ES/100/400/800	—	FOR SPECIFIC OPERATIONS SEE FIELD RECORD
			WATER SAMPLING - CHECK ( ) WHEN DONE

EFFLUENT	INFLUENT	WELLS
( )	( )	( ) Q.-SEE C.CUST.

REMARKS:	
FREE PRODUCT REMOVED: APPROX. GALLONS	WATER REMOVED: APPROX. 184 GALLONS
DATA RECORDED BY: E. GASMAN	INPUT BY: M.M. >FF\054rsirt



# EARTH MANAGEMENT CO.

Environmental Remediation

## FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 054  
PERSONNEL E. CARMAN, T. ROW  
WELL NO. R.S. 9 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAILER

### Before Sampling

Total Well Depth 15 Ft. Well Diameter 2"  
Depth to Water 2.63 Ft. Purge Volume 8 gallons

### Sampling Data

Time	<u>8:02</u>	<u>8:03</u>	<u>8:04</u>	<u>8:05</u>	<u>8:06</u>	<u>8:07</u>	
EC	<u>794</u>	<u>798</u>	<u>812</u>	<u>814</u>	<u>820</u>	<u>819</u>	
pH	<u>7.20</u>	<u>7.40</u>	<u>7.40</u>	<u>7.40</u>	<u>7.40</u>	<u>7.41</u>	
Temp	<u>65.5</u>	<u>66.3</u>	<u>67</u>	<u>67.9</u>	<u>68</u>	<u>68</u>	
Gal.	<u>3</u>	<u>4</u>	<u>5</u>	<u>6</u>	<u>7</u>	<u>8</u>	

Time							
EC							
pH							
Temp							
Gal.							

### After Sampling

Depth to Water 3.10 Ft. Total Well Depth 15 Ft.



# EARTH MANAGEMENT CO.

Environmental Remediation

## FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 054  
PERSONNEL E. CALMAN, T. ROH  
WELL NO. RJ 8 WEATHER SUNNY  
SAMPLE EQUIPMENT \_\_\_\_\_

### Before Sampling

Total Well Depth 27.20 Ft. Well Diameter 2"  
Depth to Water 8.75 Ft. Purge Volume 10 gallons

### Sampling Data

Time	<u>8:09</u>	<u>8:10</u>	<u>8:11</u>	<u>8:12</u>	<u>8:13</u>	<u>8:14</u>	
EC	<u>1130</u>	<u>980</u>	<u>980</u>	<u>1020</u>	<u>1020</u>	<u>1020</u>	
pH	<u>7.50</u>	<u>7.47</u>	<u>7.40</u>	<u>7.33</u>	<u>7.35</u>	<u>7.35</u>	
Temp	<u>66.7</u>	<u>67.5</u>	<u>68.2</u>	<u>68.2</u>	<u>68.1</u>	<u>68.2</u>	
Gal.	<u>3</u>	<u>4</u>	<u>5</u>	<u>6</u>	<u>8</u>	<u>10</u>	

Time	_____	_____	_____	_____	_____	_____	_____
EC	_____	_____	_____	_____	_____	_____	_____
pH	_____	_____	_____	_____	_____	_____	_____
Temp	_____	_____	_____	_____	_____	_____	_____
Gal.	_____	_____	_____	_____	_____	_____	_____

### After Sampling

Depth to Water 9.20 Ft. Total Well Depth 27.20 Ft.



# EARTH MANAGEMENT CO.

Environmental Remediation

## FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 054  
PERSONNEL E. GAFMAN, T. ROSE  
WELL NO. RS-10 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAILER

### Before Sampling

Total Well Depth 24.45 Ft. Well Diameter 2"  
Depth to Water 7.38 Ft. Purge Volume 11 gallons

### Sampling Data

Time	<u>8:16</u>	<u>8:15</u>	<u>8:16</u>	<u>8:17</u>	<u>8:18</u>	<u>8:19</u>	<u>8:20</u>
EC	<u>4530</u>	<u>4520</u>	<u>4560</u>	<u>4620</u>	<u>4620</u>	<u>4620</u>	<u>4620</u>
pH	<u>7.55</u>	<u>7.18</u>	<u>7.07</u>	<u>7.07</u>	<u>7.08</u>	<u>7.08</u>	<u>7.08</u>
Temp	<u>68.4</u>	<u>67.1</u>	<u>67.9</u>	<u>68.3</u>	<u>68.4</u>	<u>69</u>	<u>69</u>
Gal.	<u>1</u>	<u>3</u>	<u>5</u>	<u>7</u>	<u>9</u>	<u>10</u>	<u>11</u>

Time \_\_\_\_\_  
EC \_\_\_\_\_  
pH \_\_\_\_\_  
Temp \_\_\_\_\_  
Gal. \_\_\_\_\_

### After Sampling

Depth to Water 8.35 Ft. Total Well Depth 24.45 Ft.



# EARTH MANAGEMENT CO.

Environmental Remediation

## FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 054

PERSONNEL E. GAMAN, T. ROSE

WELL NO. R-2 WEATHER SUNNY

SAMPLE EQUIPMENT TETLON BAGLER

### Before Sampling

Total Well Depth 17.10 Ft. Well Diameter 4"

Depth to Water 2.75 Ft. Purge Volume 37 gallons

### Sampling Data

Time	<u>8:30</u>	<u>8:32</u>	<u>8:34</u>	<u>8:35</u>	<u>8:38</u>	<u>8:40</u>	<u>8:42</u>
EC	<u>650</u>	<u>400</u>	<u>400</u>	<u>398</u>	<u>397</u>	<u>400</u>	<u>400</u>
pH	<u>7.45</u>	<u>7.60</u>	<u>7.60</u>	<u>7.58</u>	<u>7.59</u>	<u>7.59</u>	<u>7.59</u>
Temp	<u>66.8</u>	<u>67.5</u>	<u>67.8</u>	<u>67.8</u>	<u>67.6</u>	<u>67.7</u>	<u>67.8</u>
Gal.	<u>10</u>	<u>15</u>	<u>20</u>	<u>25</u>	<u>30</u>	<u>33</u>	<u>37</u>

Time \_\_\_\_\_

EC \_\_\_\_\_

pH \_\_\_\_\_

Temp \_\_\_\_\_

Gal. \_\_\_\_\_

### After Sampling

Depth to Water 4.10 Ft. Total Well Depth 17.10 Ft.



# EARTH MANAGEMENT CO.

Environmental Remediation

## FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 057  
PERSONNEL E. CARMAN, T. ROTH  
WELL NO. R-5 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAGGER

### Before Sampling

Total Well Depth 18.25 Ft. Well Diameter 4"  
Depth to Water 4.78 Ft. Purge Volume 35 gallons

### Sampling Data

Time	<u>8:59</u>	<u>9:02</u>	<u>9:05</u>	<u>9:08</u>	<u>9:10</u>		
EC	<u>950</u>	<u>990</u>	<u>1010</u>	<u>1010</u>	<u>1010</u>		
pH	<u>7.30</u>	<u>7.26</u>	<u>7.27</u>	<u>7.26</u>	<u>7.28</u>		
Temp	<u>64.5</u>	<u>66.3</u>	<u>67.5</u>	<u>67.5</u>	<u>67.5</u>		
Gal.	<u>15</u>	<u>20</u>	<u>25</u>	<u>30</u>	<u>35</u>		

Time							
EC							
pH							
Temp							
Gal.							

### After Sampling

Depth to Water 6.10 Ft. Total Well Depth 18.25 Ft.



**EARTH MANAGEMENT CO.**

Environmental Remediation

FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 054  
PERSONNEL E-CASMAN, T. ROSE  
WELL NO. R E 6 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAILEY

Before Sampling

Total Well Depth 13.25 Ft. Well Diameter 4"  
Depth to Water 3.58 Ft. Purge Volume 25 gallons

Sampling Data

Time	<u>9:30</u>	<u>9:33</u>	<u>9:36</u>	<u>9:40</u>	<u>9:43</u>	<u>9:46</u>	
EC	<u>1080</u>	<u>1120</u>	<u>1140</u>	<u>1130</u>	<u>1120</u>	<u>1130</u>	
pH	<u>7.63</u>	<u>7.56</u>	<u>7.53</u>	<u>7.53</u>	<u>7.55</u>	<u>7.53</u>	
Temp	<u>64.5</u>	<u>67.6</u>	<u>68.5</u>	<u>68.5</u>	<u>68.6</u>	<u>68.6</u>	
Gal.	<u>5</u>	<u>8</u>	<u>10</u>	<u>15</u>	<u>20</u>	<u>25</u>	

Time							
EC							
pH							
Temp							
Gal.							

After Sampling

Depth to Water 4.27 Ft. Total Well Depth 13.25 Ft.



**EARTH MANAGEMENT CO.**

Environmental Remediation

FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/93 STATION NO. 054  
PERSONNEL E. GASMAN, T. Roto  
WELL NO. RE 1 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAILEY

Before Sampling

Total Well Depth 19.85 Ft. Well Diameter 4"  
Depth to Water 4.38 Ft. Purge Volume 40 gallons

Sampling Data

Time	<u>9:55</u>	<u>9:58</u>	<u>10:01</u>	<u>10:04</u>	<u>10:07</u>	<u>10:10</u>	<u>10:14</u>
EC	<u>1130</u>	<u>980</u>	<u>860</u>	<u>770</u>	<u>760</u>	<u>780</u>	<u>780</u>
pH	<u>7.26</u>	<u>7.14</u>	<u>7.21</u>	<u>7.24</u>	<u>7.25</u>	<u>7.25</u>	<u>7.26</u>
Temp	<u>68</u>	<u>69.3</u>	<u>69.4</u>	<u>69.3</u>	<u>69.2</u>	<u>69.3</u>	<u>69.3</u>
Gal.	<u>10</u>	<u>15</u>	<u>20</u>	<u>25</u>	<u>30</u>	<u>35</u>	<u>40</u>

Time	_____	_____	_____	_____	_____	_____	_____
EC	_____	_____	_____	_____	_____	_____	_____
pH	_____	_____	_____	_____	_____	_____	_____
Temp	_____	_____	_____	_____	_____	_____	_____
Gal.	_____	_____	_____	_____	_____	_____	_____

After Sampling

Depth to Water \_\_\_\_\_ Ft. Total Well Depth \_\_\_\_\_ Ft.



# EARTH MANAGEMENT CO.

Environmental Remediation

## FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1995 STATION NO. 054  
PERSONNEL E.GARLAW, T.RO FU  
WELL NO. RW 1 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAILEY

### Before Sampling

Total Well Depth 14.10 Ft. Well Diameter 4"  
Depth to Water 4.65 Ft. Purge Volume 25 gallons

### Sampling Data

Time	<u>10:23</u>	<u>10:25</u>	<u>10:28</u>	<u>10:30</u>	<u>10:33</u>	_____	_____
EC	<u>150</u>	<u>150</u>	<u>148</u>	<u>148</u>	<u>148</u>	_____	_____
pH	<u>7.76</u>	<u>7.69</u>	<u>7.65</u>	<u>7.59</u>	<u>7.59</u>	_____	_____
Temp	<u>66.9</u>	<u>67</u>	<u>67.2</u>	<u>67.3</u>	<u>67.3</u>	_____	_____
Gal.	<u>5</u>	<u>10</u>	<u>15</u>	<u>20</u>	<u>25</u>	_____	_____

Time	_____	_____	_____	_____	_____	_____	_____
EC	_____	_____	_____	_____	_____	_____	_____
pH	_____	_____	_____	_____	_____	_____	_____
Temp	_____	_____	_____	_____	_____	_____	_____
Gal.	_____	_____	_____	_____	_____	_____	_____

### After Sampling

Depth to Water 5.28 Ft. Total Well Depth 14.10 Ft.



**EARTH MANAGEMENT CO.**

Environmental Remediation

FIELD DATA - GROUNDWATER WELL SAMPLING PROGRAM

DATE 12/14/1993 STATION NO. 054  
PERSONNEL F. CARMAN, T. ROTH  
WELL NO. PW 2 WEATHER SUNNY  
SAMPLE EQUIPMENT TEFLON BAGGER

Before Sampling

Total Well Depth 14.40 Ft. Well Diameter 4"  
Depth to Water 5.22 Ft. Purge Volume 24 gallons

Sampling Data

Time	<u>10:47</u>	<u>10:50</u>	<u>10:53</u>	<u>10:57</u>	<u>11:00</u>		
EC	<u>165</u>	<u>170</u>	<u>172</u>	<u>172</u>	<u>172</u>		
pH	<u>7.55</u>	<u>7.46</u>	<u>7.45</u>	<u>7.43</u>	<u>7.43</u>		
Temp	<u>66.9</u>	<u>68</u>	<u>69.6</u>	<u>69.6</u>	<u>69.7</u>		
Gal.	<u>5</u>	<u>10</u>	<u>15</u>	<u>20</u>	<u>24</u>		

Time							
EC							
pH							
Temp							
Gal.							

After Sampling

Depth to Water 6.40 Ft. Total Well Depth 14.40 Ft.

PARAMETER		U/M	
TIME	AM/PM	15:05	
WORKING	YES/NO	No	
RESTARTED	YES/NO	YES	
HOURS	#	4028	
ENGINE ROT.	R P M	1800	
ENGINE VACUUM	IN HG	10	
ENG. OIL PRESS.	P S I	45	
ENG. WATER TEMP.	°F	150	
ENG. ELECTR. TENS.	VOLTS	13	
TANK VACUUM	IN HG	12	
TK. REC. PRES.	PSI	40	
TK. REC. TEMP.	°F	70	
AIR TEMPERATURE	°F	45	
AIR FLOW	C F M	15	
VAPOR FLOW	C F M	19	
FUEL FLOW	C F M/H	80	
WELL VACUUM	IN H2O	26	
L P G TANKS	%	#1: 87 #2:	
GAS METER READING			
WATER FLOWMETER	GALL.	3250	
CATALYST IN TEMP.	°F		
CATALYST OUT TEMP.	°F		
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE	O.V.	ppm	
INLET TO ENGINE	O.V.	ppm	

READJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE  WHEN DONE

INSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE  O.K.  NO

CHANGE CATALYST (See permit and PSR for limits).      CHECK HERE  WHEN REPLACED

VAPOR WELLS ON: ALL

WATER WELLS ON: RE-4 + RE-7

SERVICE TECH: E. CASMAN

DATE: 12/22/93 THRIFTY OIL CO. ss #: 054

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level	✓			
Coolant, Check Level	✓			
Fuel, Oil, Coolant, Check for Leaks	✓			
Oil, Engine, Change	✓			
Oil, Filter, Change	✓			
Battery, Check Charge and Fluid	✓			
Battery Cables, Clean	✓			
P.T.O. Bearings, Lubricate	✓			
Fan, Alternator Belts, Check and Adjust	✓			
Idle Speed, Check	✓			
Idle Mixture, Check	✓			
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: Upon arrival the RSI was shut off. (Reheat) because no more propane. Restart.

PARAMETER		U/M	
TIME	AM/PM	10:40	
WORKING	YES/NO	YES	
RESTARTED	YES/NO	NO	
HOURS	#	4196	
ENGINE ROT.	R P M	1800	
ENGINE VACUUM	IN HG	10	
ENG. OIL PRESS.	P S I	40	
ENG. WATER TEMP.	°F	160	
ENG. ELECTR. TENS.	VOLTS	13	
TANK VACUUM	IN HG	11	
TK. REC. PRES.	PSI	25	
TK. REC. TEMP.	°F	100	
AIR TEMPERATURE	°F	60	
AIR FLOW	C F M	14	
VAPOR FLOW	C F M	17	
FUEL FLOW	C F M/H	80	
WELL VACUUM	IN H2O	26	
L P G TANKS	%	#1:23 #2:	
GAS METER READING			
WATER FLOWMETER	GALL.	3421	
CATALYST IN TEMP.	°F		
CATALYST OUT TEMP.	°F		
EXHAUST  (See permit and PSR for frequency and limits)	BY C.A.	H-C	ppm/%
		CO	%/ppm
		CO2	%
		O2	%
		NOX	%/ppm
	BY	O.V.	ppm
OUTLET FROM ENGINE	O.V.	ppm	
INLET TO ENGINE	O.V.	ppm	

## MAINTENANCE RECORD

Operation	Each Stop	100 Hours Week	400 Hours 2 Weeks	800 Hours Monthly
Oil, Engine, Check Level				
Coolant, Check Level				
Fuel, Oil, Coolant, Check for Leaks				
Oil, Engine, Change	✓			
Oil, Filter, Change	✓			
Battery, Check Charge and Fluid	✓			
Battery Cables, Clean	✓			
P.T.O. Bearings, Lubricate	✓			
Fan, Alternator Belts, Check and Adjust	✓			
Idle Speed, Check	✓			
Idle Mixture, Check	✓			
Radiator, Inspect and Clean Exterior				
Distributor, Clean and Check Points				
Ignition Timing, Check and Adjust				
PCV Valve, Replace				
PCV Hoses and Fitting, Check				
Spark Plugs, Replace				
Points, Replace				
Oil, Vacuum Pump, Change				
Intake Manifold Bolts, Torque				
All Nuts and Bolts, Check				

Comments: B/W air samplingREADJUST ENGINE PARAMETERS AT LEAST ONCE PER MONTH (IGNITION TIMING, AIR TO FUEL RATIO, EXHAUST O2 AND TEMP., NOX, HC & CO).      CHECK HERE  WHEN DONEINSPECT CATALYST (See permit and PSR for frequency).      CHECK HERE  O.K.  NOCHANGE CATALYST (See permit and PSR for limits).      CHECK HERE  WHEN REPLACED

VAPOR WELLS ON: ALL

WATER WELLS ON: RE-5 - RE-7

SERVICE TECH: E. GASMAN

DATE: 12.29.93 THRIFTY OIL CO. ss #: 054

## *APPENDIX B*

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

10/29/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C. # 054  
Chain of custody

Sample #: 3300105001  
Received: 10/27/93  
Type: Water

Collector: Client  
Sampling Date & Time: 10/21/93, 1805  
Method: Submitted By Client

I.D.: Effluent

T.O.C. # 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	10/27/93		
Analysis Date		10/27/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	99 Percent		

Page: 1 (cont.)

[ND = None Detected; MDL = Method Detection Limit]

33001050



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021
- San Francisco, California 94188
- Anaheim, California 92807
- (213) 749-3411
- (415) 330-3000
- (714) 693-1026
- Fax: (213) 746-7228
- Fax: (415) 822-5864
- Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

10/29/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C. # 054  
Chain of custody

Sample #: 3300105002  
Received: 10/27/93  
Type: Water

Collector: Client  
Sampling Date & Time: 10/21/93, 1820  
Method: Submitted By Client

I.D.: Influent

T.O.C. # 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	10/27/93		
Analysis Date		10/27/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	38000	ug/l	440 ug/l
Benzene	EPA 602	7900	ug/l	2.6 ug/l
Toluene	EPA 602	610	ug/l	2.6 ug/l
Ethylbenzene	EPA 602	110	ug/l	2.6 ug/l
Xylenes	EPA 602	2800	ug/l	4.4 ug/l
Surrogate		*		
Trifluorotoluene	EPA 602	84	Percent	

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

10/29/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C. # 054  
Chain of custody

Sample #: 3300105003  
Received: 10/27/93  
Type: Water

Collector: Client  
Sampling Date & Time: 10/21/93, 0700  
Method: Submitted By Client

I.D.: Trip Blank

T.O.C. # 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	10/27/93		
Analysis Date		10/27/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	98 Percent		

Respectfully Submitted,

Shahid Noori  
Shahid Noori, Manager Chemical Lab

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021
- (213) 749-3411
- Fax: (213) 746-7228
- San Francisco, California 94188
- (415) 330-3000
- Fax: (415) 822-5864
- Anaheim, California 92807
- (714) 693-1026
- Fax: (714) 693-1034

December 3, 1993

**Quality Control Report**  
**Matrix Spike and Duplicate Spike**

Client: Thrifty Oil  
File No: 72546  
Report No: 33001050  
Matrix: Water  
Method: EPA 602  
Lab No: 3298115901  
Batch No: 3300602-1  
Date Analyzed: 10/27/93

<u>PARAMETER</u>	<u>SAMPLE RESULTS (ug/l)</u>	<u>AMOUNT SPIKED (ug/l)</u>	<u>AMOUNT RECOVERED (ug/l)</u>	<u>% REC</u>	<u>SPIKE RECOVERY ACCEPTANCE RANGE(%)</u>		<u>R.P.D.</u>
					77-120	5%	
Benzene	(S)	ND	22.7	22.3	98		
Benzene	(DS)	ND	13.6	14.9	109	77-120	10%
Toluene	(S)	ND	22.7	23.4	103		
Toluene	(DS)	ND	13.6	14.7	108	75-115	5%
Ethyl Benzene	(S)	ND	22.7	24.1	106		
Ethyl Benzene	(DS)	ND	13.6	14.8	109	60-130	2%
Xylene	(S)	ND	68.1	69.9	103		
Xylene	(DS)	ND	40.8	43.8	107	50-130	4%

S = Spike

DS = Duplicate Spike

R.P.D. = Relative Percent Difference

ND = None Detected





# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021
- San Francisco, California 94188
- Anaheim, California 92807
- (213) 749-3411
- (415) 330-3000
- (714) 693-1026
- Fax: (213) 746-7228
- Fax: (415) 822-5864
- Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

11/29/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C. # 054  
Chain of custody

Sample #: 3322150101  
Received: 11/18/93  
Type: Water

Collector: Client  
Sampling Date & Time: 11/17/93, 1510  
Method: Submitted By Client

I.D.: Effluent

T.O.C. # 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	11/23/93		
Analysis Date		11/23/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	91 Percent		



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

11/29/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C. # 054  
Chain of custody

Sample #: 3322150102  
Received: 11/18/93  
Type: Water

Collector: Client  
Sampling Date & Time: 11/17/93, 1525  
Method: Submitted By Client

I.D.: Influent

T.O.C. # 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	11/23/93		
Analysis Date		11/23/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	53000	ug/l	1100 ug/l
Benzene	EPA 602	6700	ug/l	6.6 ug/l
Toluene	EPA 602	250	ug/l	6.6 ug/l
Ethylbenzene	EPA 602	ND	ug/l	6.6 ug/l
Xylenes	EPA 602	3200	ug/l	11 ug/l
Surrogate		*		
Trifluorotoluene	EPA 602	91	Percent	



**SMITH-EMERY COMPANY**  
The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

11/29/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C. # 054  
Chain of custody

Sample #: 3322150103  
Received: 11/18/93  
Type: Water

Collector: Client  
Sampling Date & Time: 11/17/93, 0630  
Method: Submitted By Client

I.D.: Trip Blank

T.O.C. # 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	11/23/93		
Analysis Date		11/23/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	93 Percent		

Respectfully Submitted,

*Shahid Noori*

Shahid Noori, Manager Chemical Lab



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

December 3, 1993

## Quality Control Report Matrix Spike and Duplicate Spike

Client: Thrifty Oil  
File No: 72546  
Report No: 33221501  
Matrix: Water  
Method: EPA 602/8015  
Lab No: 3320155107  
Batch No: 3327602/8015-1  
Date Analyzed: 11/23/93

PARAMETER	SAMPLE RESULTS		AMOUNT SPIKED (ug/l)	AMOUNT RECOVERED (ug/l)	% REC	SPIKE RECOVERY ACCEPTANCE RANGE (%)		R.P.D.
	(S)	(DS)						
Benzene	(S)	ND	4.5	4.2	92			
Benzene	(DS)	ND	4.5	4.9	109	77-120		17%
Toluene	(S)	ND	4.5	4.4	97			
Toluene	(DS)	ND	4.5	5.0	112	75-115		14%
Ethyl Benzene	(S)	ND	4.5	4.3	96			
Ethyl Benzene	(DS)	ND	4.5	5.0	111	60-130		15%
Xylene	(S)	ND	13.5	14.1	104			
Xylene	(DS)	ND	13.5	15.7	117	50-130		11%

S = Spike

DS = Duplicate Spike

R.P.D. = Relative Percent Difference

ND = None Detected





# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104801  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1210  
Method: Submitted By Client

I.D.: RE - 2

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	260 ug/l	50 ug/l	
Benzene	EPA 602	5.6 ug/l	0.3 ug/l	
Toluene	EPA 602	3.9 ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	21 ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	94 Percent		

# RECEIVED

DEC 11 1994

EARTH MANAGEMENT CO.

Page: 1 (cont.)

[ND = None Detected; MDL = Method Detection Limit]

33501048

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021     ● (213) 749-3411     ● Fax: (213) 746-7228
- San Francisco, California 94188     ● (415) 330-3000     ● Fax: (415) 822-5864
- Anaheim, California 92807     ● (714) 693-1026     ● Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104802  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1135  
Method: Submitted By Client

I.D.: RS - 9

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	560 ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	5.5 ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	93 Percent		

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104803  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1150  
Method: Submitted By Client

I.D.: RS - 8

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	98 Percent		

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104804  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1200  
Method: Submitted By Client

I.D.: RS - 10

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93		
EPA 8015M/602, Combination		*		
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	96 Percent		



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 ● (213) 749-3411 ● Fax: (213) 746-7228
- San Francisco, California 94188 ● (415) 330-3000 ● Fax: (415) 822-5864
- Anaheim, California 92807 ● (714) 693-1026 ● Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104805  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1225  
Method: Submitted By Client

I.D.: RE - 5

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	3300	ug/l	50 ug/l
Benzene	EPA 602	510	ug/l	0.3 ug/l
Toluene	EPA 602	5.4	ug/l	0.3 ug/l
Ethylbenzene	EPA 602	4.1	ug/l	0.3 ug/l
Xylenes	EPA 602	55	ug/l	0.5 ug/l
Surrogate		*		
Trifluorotoluene	EPA 602	105	Percent	

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 314  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104806  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1235  
Method: Submitted By Client

I.D.: RE - 1

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	38000	ug/l	1100 ug/l
Benzene	EPA 602	4300	ug/l	6.6 ug/l
Toluene	EPA 602	1300	ug/l	6.6 ug/l
Ethylbenzene	EPA 602	ND	ug/l	6.6 ug/l
Xylenes	EPA 602	6500	ug/l	11 ug/l
Surrogate		*		
Trifluorotoluene	EPA 602	94	Percent	



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104807  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1245  
Method: Submitted By Client

I.D.: RS - 6

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	1500 ug/l	50 ug/l	
Benzene	EPA 602	200 ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	8.8 ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	108 Percent		



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 ● (213) 749-3411 ● Fax: (213) 746-7228
- San Francisco, California 94188 ● (415) 330-3000 ● Fax: (415) 822-5864
- Anaheim, California 92807 ● (714) 693-1026 ● Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104808  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1255  
Method: Submitted By Client

I.D.: PW - 1

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	97 Percent		

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021
- San Francisco, California 94188
- Anaheim, California 92807
- (213) 749-3411
- (415) 330-3000
- (714) 693-1026
- Fax: (213) 746-7228
- Fax: (415) 822-5864
- Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104809  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1255  
Method: Submitted By Client

I.D.: PW - 2

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93		
EPA 8015M/602, Combination		*		
TPH-Gasoline	EPA 8015M	1700 ug/l	50 ug/l	
Benzene	EPA 602	4.2 ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	49 ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	90 Percent		

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021
- (213) 749-3411
- Fax: (213) 746-7228
- San Francisco, California 94188
- (415) 330-3000
- Fax: (415) 822-5864
- Anaheim, California 92807
- (714) 693-1026
- Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104810  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/15/93, 1230  
Method: Submitted By Client

I.D.: Effluent

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	95 Percent		

**SMITH-EMERY COMPANY**

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104811  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1310  
Method: Submitted By Client

I.D.: Influent

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93	*	
EPA 8015M/602, Combination				
TPH-Gasoline	EPA 8015M	27000	ug/l	730 ug/l
Benzene	EPA 602	2300	ug/l	4.4 ug/l
Toluene	EPA 602	950	ug/l	4.4 ug/l
Ethylbenzene	EPA 602	42	ug/l	4.4 ug/l
Xylenes	EPA 602	4300	ug/l	7.3 ug/l
Surrogate		*		
Trifluorotoluene	EPA 602	95	Percent	



**SMITH-EMERY COMPANY**  
The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021
- San Francisco, California 94188
- Anaheim, California 92807
- (213) 749-3411
- (415) 330-3000
- (714) 693-1026
- Fax: (213) 746-7228
- Fax: (415) 822-5864
- Fax: (714) 693-1034

Thrifty Oil Co.  
File# 72546  
10000 Lakewood Blvd.  
Downey, CA 90240

12/21/93

Attn: Michael S. Cosby  
310/923/9876

T.O.C# 054  
Chain of custody

Sample #: 3350104812  
Received: 12/16/93  
Type: Water

Collector: Client  
Sampling Date & Time: 12/14/93, 1900  
Method: Submitted By Client

I.D.: Trip Blank

T.O.C# 054

CONSTITUENT	METHOD	RESULT	UNIT	MDL
Extraction Method/Date	EPA 5030	12/17/93		
Analysis Date		12/17/93		
EPA 8015M/602, Combination		*		
TPH-Gasoline	EPA 8015M	ND ug/l	50 ug/l	
Benzene	EPA 602	ND ug/l	0.3 ug/l	
Toluene	EPA 602	ND ug/l	0.3 ug/l	
Ethylbenzene	EPA 602	ND ug/l	0.3 ug/l	
Xylenes	EPA 602	ND ug/l	0.5 ug/l	
Surrogate		*		
Trifluorotoluene	EPA 602	99 Percent		

Respectfully Submitted,

*Shahid Noori*

Shahid Noori, Manager Chemical Lab



# SMITH-EMERY COMPANY

The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. J14  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 746-7228
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

December 28, 1993

## Quality Control Report Matrix Spike and Duplicate Spike

Client: Thrifty Oil  
File No: 72546  
Report No: 33501048  
Matrix: Water  
Method: EPA 602/8015  
Lab No: 3350081902  
Batch No: 3351602/8015-1  
Date Analyzed: 12/17/93

PARAMETER		SAMPLE RESULTS (ug/l)	AMOUNT SPIKED (ug/l)	AMOUNT RECOVERED (ug/l)	% REC	SPIKE RECOVERY ACCEPTANCE RANGE(%)	R.P.D.
Benzene	(S)	ND	22.7	24.8	109		
Benzene	(DS)	ND	22.7	24.0	106	77-120	3%
Toluene	(S)	ND	22.7	25.1	110		
Toluene	(DS)	ND	22.7	25.3	111	75-115	1%
Ethyl Benzene	(S)	ND	22.7	27.5	121		
Ethyl Benzene	(DS)	ND	22.7	26.8	118	60-130	3%
Xylene	(S)	ND	68.1	84.2	123		
Xylene	(DS)	ND	68.1	81.8	120	50-130	3%

S = Spike

DS = Duplicate Spike

R.P.D. = Relative Percent Difference

ND = None Detected



**SMITH-EMERY COMPANY**  
The Full Service Independent Testing Laboratory, Established 1904

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 745-6372
- San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
- Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

**CHAIN OF CUSTODY AND  
ANALYSIS REQUEST**

DATE: 12/15/93 PAGE 1 OF 2  
FILE NO. 72546 LAB NO. 3350104201

CLIENT NAME: <u>THRIFTY OIL CO</u>								ANALYSES REQUESTED:				REMARKS:	
PROJECT NAME: PROJECT NO. <u>S3 #054</u> P.O. NO.													
ADDRESS:													
PROJECT MANAGER: <u>MICHAEL COSBY</u> PHONE #: <u>FAX #:</u>													
SAMPLER NAME: <u>EUGENIUS GASMAN</u> <u>Eugenius Gasman</u> (Printed) (Signature)													
TAT (Analytical Turn Around Time) 0 = Same Day; 1 = 24 Hour; 2 = 48 Hour; (Etc.)													
CONTAINER TYPES: B = Brass, G = Glass, P = Plastic, V = Voa Vial, O = Other:													
SAMPLE NO.	DATE SAMPLED	TIME SAMPLED	SAMPLE DESCRIPTION	MATRIX			TAT	CONTAINER		SAMPLE CONDITION/COMMENTS:			
				WATER	SOIL	SLUDGE		OTHER	#				
RE-2	12/14/93	12:10		X				2	V	X	X		
RS-9	12/14/93	11:35		X				2	V	X	X		
RS-8	12/14/93	11:50		X				2	V	X	X		
RS-10	12/14/93	12:00		X				2	V	X	X		
RE-5	12/14/93	12:25		X				2	V	X	X		
RE-1	12/14/93	12:35		X				2	V	X	X		
RE-6	12/14/93	12:45		X				2	V	X	X		
RE-1	12/14/93	12:55		X				2	V	X	X		
PW-2	12/14/93	12:55		X				2	V	X	X		
EFFLUENT	12/15/93	12:30		X				2	V	X	X		
Relinquished By: (Signature and Printed Name) <u>E. GASMAN</u> <u>Eugenius Gasman</u>				Received By: (Signature and Printed Name) <u>Fed X</u>				Date: <u>12/15/93</u>	Time: _____	SAMPLE DISPOSITION:			
Relinquished By: (Signature and Printed Name) <u>Fed X</u>				Received By: (Signature and Printed Name) <u>M. D. O'Farrell</u>				Date: <u>12/16/93</u>	Time: <u>10:51</u>	1. Samples returned to client? YES NO			
Relinquished By: (Signature and Printed Name)				Received By: (Signature and Printed Name)				Date: _____	Time: _____	2. Samples will not be stored over 30 days, unless additional storage time is requested.			
SPECIAL INSTRUCTIONS:								3. Storage time requested: _____ days					
								By: _____ Date: _____					



**SMITH-EMERY COMPANY**  
*The Full Service Independent Testing Laboratory, Established 1904*

781 East Washington Boulevard  
P.O. Box 880550, Hunter's Point Shipyard Bldg. 114  
5427 East La Palma Avenue

- Los Angeles, California 90021 • (213) 749-3411 • Fax: (213) 745-6372
  - San Francisco, California 94188 • (415) 330-3000 • Fax: (415) 822-5864
  - Anaheim, California 92807 • (714) 693-1026 • Fax: (714) 693-1034

**CHAIN OF CUSTODY AND  
ANALYSIS REQUEST**

DATE: 12/15/93 PAGE 2 OF 2  
FILE NO. 72546 LAB NO. 3350104901

CLIENT NAME: THRIFTY OIL CO

PROJECT NAME: PROJECT NO. SS #054 P.O. NO.

**ADDRESS**

PROJECT MANAGER: MICHAEL COSTA PHONE #: FAX #:

**SAMPLER NAME:** \_\_\_\_\_ **(Printed)** \_\_\_\_\_ **(Signature)** \_\_\_\_\_

TAT (Analytical Turn Around Time) : 0 = Same Day; 1 = 24 Hour; 2 = 48 Hour; [Etc.]

**CONTAINER TYPES:** B = Brass, G = Glass, P = Plastic, V = Voa Vial, O = Other

**Relinquished By: (Signature and Printed Name)**

Received By: (Signature and Printed Name)

Date: \_\_\_\_\_ Time: \_\_\_\_\_

**SAMPLE DISPOSITION:**

**YES**      **NO**

**Relinquished By: (Signature and Printed Name)**

Received By: (Signature and Printed Name)

Date: / Time: .

2. Samples will not be stored over 30 days, unless additional storage time is requested.

Belinquished By: (Signature and Printed Name)

**Received By: (Signature and Printed Name)**

Date: \_\_\_\_\_ Time: \_\_\_\_\_

3. Storage time requested: \_\_\_\_\_ days

**SPECIAL INSTRUCTIONS:**

By \_\_\_\_\_ Date \_\_\_\_\_



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

---

Karl Kerner  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

September 23, 1993

Customer Project: T.O.C. SS#054  
Laboratory Job: L9309085

On September 10, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene by GC (Niosh 1501)

Project Manager

Laboratory Director  
Robert Peak

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: T.O.C. SS#054  
Sample Id: EFFLUENT  
Lab Id: L9309085-1

Collected: 08-SEP-93  
Received: 10-SEP-93  
Reported: 22-SEP-93

Parameter	Value	Limit	Units	Diffusion	Extracted	Analyzed
NIOSH 1501: BENZENE						
AIR VOLUME	1.00	-	L	1	17-SEP-93	20-SEP-93
Front	<	0.0075	mg	1	17-SEP-93	20-SEP-93
Back	<	0.0075	mg	1	17-SEP-93	20-SEP-93
Total	<	0.0075	mg	1	17-SEP-93	20-SEP-93
mg/m <sup>3</sup>	<	7.5	mg/m <sup>3</sup>	1	17-SEP-93	20-SEP-93
BENZENE	<	2.3	ppm	1	17-SEP-93	20-SEP-93

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: T.O.C. SS#054  
Sample Id: TRIP BLANK  
Lab Id: L9309085-2

Collected: 08-SEP-93  
Received: 10-SEP-93  
Reported: 22-SEP-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>						
AIR VOLUME	BLANK	-	L	1	17-SEP-93	20-SEP-93
Front	<	0.0075	mg	1	17-SEP-93	20-SEP-93
Back	<	0.0075	mg	1	17-SEP-93	20-SEP-93
Total	<	0.0075	mg	1	17-SEP-93	20-SEP-93



**3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245 Fax: (707) 763-4065**

L9309085

## **SAMPLE CHAIN OF CUSTODY / WORK ORDER**

Client's Name JHRF / JLE

Address 10000 LAKEWOOD

Address DAWNEY CA 90240  
City, State, Zip

City, State, Zip \_\_\_\_\_ Client's or Representative's Signature EUGENIU GARMAN Dyugeni Ugarman

(signature authorizes the work and terms listed below)

(signature authorizes the work and to the listed company)

(signature authorizes the work and terms listed below)  
**All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.**



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

---

Karl Kerner  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

October 1, 1993

Customer Project: TOS SS#054  
Laboratory Job: L9309208

On September 23, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene by GC (Niosh 1501)

Project Manager

Laboratory Director  
Robert Peak

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: TOS SS#054  
Sample Id: EFFLUENT  
Lab Id: L9309208-1

Collected: 21-SEP-93  
Received: 23-SEP-93  
Reported: 30-SEP-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>						
AIR VOLUME	1.00	-	L	1	27-SEP-93	27-SEP-93
Front	<	0.0075	mg	1	27-SEP-93	27-SEP-93
Back	<	0.0075	mg	1	27-SEP-93	27-SEP-93
Total	<	0.0075	mg	1	27-SEP-93	27-SEP-93
mg/m <sup>3</sup>	<	7.5	mg/m <sup>3</sup>	1	27-SEP-93	27-SEP-93
BENZENE	<	2.3	ppm	1	27-SEP-93	27-SEP-93


## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: TOS SS#054  
Sample Id: TRIP BLANK  
Lab Id: L9309208-2

Collected: 21-SEP-93  
Received: 23-SEP-93  
Reported: 30-SEP-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>						
AIR VOLUME	BLANK	<	L	1	27-SEP-93	27-SEP-93
Front		0.0075	mg	1	27-SEP-93	27-SEP-93
Back		<	mg	1	27-SEP-93	27-SEP-93
Total		<	0.0075	mg	1	27-SEP-93



3700 Lakeview Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 783-8245 Fax: (707) 783-4065

L 9309208

## **SAMPLE CHAIN OF CUSTODY / WORK ORDER**

Client's Name THRIFTY OIL CO Phone (310) 923-4816

Client's Name : 10000 LAKEWOOD BLVD  
Address : DOWNEY CA 90240  
City, State, Zip : 90240

City, State, Zip DOWNEY CA 90240

**City, State, Zip**

Client's or Representative's Signature EUGENIU GAVRAN

(signature authorizes the work and terms listed below)

All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails

All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.

SAMPLES RECEIVED IN GOOD CONDITION  
NO BROKEN OR LEAKING CONTAINERS

Fed. Ex - 2ct

Relinquished by: (Signature)

DATE  
9-22-93

TIME  
9

~~Received by: (Signature)~~

Relinquished by: (Signature)

DATE

TIME

Received by: (Signature)

*Distinguished by:* (Signature)

DATE

TIME

**Received by: (Signature)**

General Remarks: + ANALIZE RESULT  
BEND BILL TO: KARL KERNER  
10000 LAKEWOOD BLVD  
DOWNEY CA 90240  
PLEASE SEND COOLER + A COPY  
ANALIZE RESULT TO:  
1250 N WILSON WAY  
STOCKTON CA 95205



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

October 18, 1993

Customer Project: SS #054  
Laboratory Job: L9310071

On October 8, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene by GC (Niosh 1501)

*Villa Hanb*

Project Manager

*Laura Kunkel*

Laboratory Director  
Robert Peak

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS #054  
Sample Id: EFFLUENT  
Lab Id: L9310071-1

Collected: 07-OCT-93  
Received: 08-OCT-93  
Reported: 18-OCT-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>						
AIR VOLUME	1.00	-	L	1	13-OCT-93	13-OCT-93
Front	<	0.0075	mg	1	13-OCT-93	13-OCT-93
Back	<	0.0075	mg	1	13-OCT-93	13-OCT-93
Total	<	0.0075	mg	1	13-OCT-93	13-OCT-93
mg/m <sup>3</sup>	<	7.5	mg/m <sup>3</sup>	1	13-OCT-93	13-OCT-93
BENZENE	<	2.3	ppm	1	13-OCT-93	13-OCT-93

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS #054  
Sample Id: TRIP BLANK  
Lab Id: L9310071-2

Collected: 07-OCT-93  
Received: 08-OCT-93  
Reported: 18-OCT-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>						
AIR VOLUME	BLANK	-	L	1	13-OCT-93	13-OCT-93
Front	<	0.0075	mg	1	13-OCT-93	13-OCT-93
Back	<	0.0075	mg	1	13-OCT-93	13-OCT-93
Total	<	0.0075	mg	1	13-OCT-93	13-OCT-93



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 783-8245 Fax: (707) 783-4085

## **SAMPLE CHAIN OF CUSTODY / WORK ORDER**

Client's Name THRIFTY OIL CO  
Address 10000 LAKEWOOD BLVD  
City, State, Zip BONNEY CA 90240

Phone (310) 923-9876

**Client's or Representative's Signature**

(signature authorizes the work and terms listed below)

All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.

Relinquished by: (Signature) 

**DATE** | **TIME**

Received by (Signature)

**Renting** by: (Signature)

**DATE**      **TIME**

Received by: (Signature)

**Distinguished by:** (Signature)

DATE	TIME
------	------

Received by: (Signature)

General Remarks:  
SEARCH RESULT OF ANALYZES TO  
KARL KERNER 10000 LAKWOOD AL  
DOWNEY CA 90240  
PLEASE PEND COLOR + COPY OF  
ANALYSIS TO  
1250 N VILLAGE WAY  
WICKETON CA 95205  
THANK YOU



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240


October 29, 1993

Customer Project: SS #054  
Laboratory Job: L9310209

On October 22, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene by GC (Niosh 1501)

  
Stella Hanb  
Project Manager

  
Robert Peak  
Laboratory Director  
Robert Peak

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS #054  
Sample Id: EFFLUENT  
Lab Id: L9310209-1

Collected: 21-OCT-93  
Received: 22-OCT-93  
Reported: 29-OCT-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
NIOSH 1501: BENZENE						
AIR VOLUME	1.00	-	L	1	28-OCT-93	28-OCT-93
Front	<	0.0075	mg	1	28-OCT-93	28-OCT-93
Back	<	0.0075	mg	1	28-OCT-93	28-OCT-93
Total	<	0.0075	mg	1	28-OCT-93	28-OCT-93
mg/m <sup>3</sup>	<	7.5	mg/m <sup>3</sup>	1	28-OCT-93	28-OCT-93
BENZENE	<	2.3	ppm	1	28-OCT-93	28-OCT-93

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS #054  
Sample Id: TRIP BLANK  
Lab Id: L9310209-2

Collected: 21-OCT-93  
Received: 22-OCT-93  
Reported: 29-OCT-93

Parameter	Value	Limit	Units	Dilution	Extracted	Analyzed
NIOSH 1501: BENZENE						
AIR VOLUME	BLANK	L	1	28-OCT-93	28-OCT-93	
Front	<	0.0075	mg	1	28-OCT-93	28-OCT-93
Back	<	0.0075	mg	1	28-OCT-93	28-OCT-93
Total	<	0.0075	mg	1	28-OCT-93	28-OCT-93



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245 Fax: (707) 763-4065

L9310209

## **SAMPLE CHAIN OF CUSTODY / WORK ORDER**

**Client's Name**

THRIFTY OIL CO

Phone (310) 923-4816

Address 10000 LAKEWOOD BLVD

City, State, Zip BOWNEY CA 90240

City, State, Zip \_\_\_\_\_ Client's or Representative's Signature EUGENE GOODMAN (signature authorizes the work and terms listed below)

(signature authorizes the work and terms listed below)

All samples remain the property of the clinician.

**All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.**

RECEIVED  
LIBRARY  
UNIVERSITY OF TORONTO LIBRARIES  
1933 001 22 M 9 35

COOLER CUSTODY SEALS INTACT  NOT INTACT

COOLER TEMPERATURE COLD °C

2 CHAR TUBES FEDEX AIR.

~~cooler not  
typical:  
Rec. opera  
S.P.~~

Reinquished by: (Signature)

**DATE** | **TIME**

Received by (Signature)

### General Remarks:

RElinquished by: (Signature)

DATE	TIME
------	------

Received by: (Signature)

*Relinquished by: (Signature)*

**DATE** | **TIME**

**Received by:** (Signature)



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

November 16, 1993

Customer Project: SS#054  
Laboratory Job: L9311048

On November 4, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene - Niosh 1501 (Niosh 1501)

*Stella Hanks*  
Project Manager

*Daudia Kea for  
Robert Peak*  
Laboratory Director

**RECEIVED**

NOV 19 1993

EARTH MANAGEMENT CO.

## DEM Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS#054  
Sample Id: EFFLUENT  
Lab Id: L9311048-1

Collected: 03-NOV-93  
Received: 04-NOV-93  
Reported: 16-NOV-93

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
AIR	1.00	-	L	08-NOV-93	10-NOV-93
FRONT	<	0.0040	mg	08-NOV-93	10-NOV-93
BACK	<	0.0040	mg	08-NOV-93	10-NOV-93
TOTAL	<	0.0040	mg	08-NOV-93	10-NOV-93
mg/M3	<	4.0	mg/m3	08-NOV-93	10-NOV-93
BENZENE	<	1.3	ppm	08-NOV-93	10-NOV-93

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS#054  
Sample Id: TRIP BLANK  
Lab Id: L9311048-2

Collected: 03-NOV-93  
Received: 04-NOV-93  
Reported: 16-NOV-93

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
FRONT	<	0.0040	mg	08-NOV-93	10-NOV-93
BACK	<	0.0040	mg	08-NOV-93	10-NOV-93
TOTAL	<	0.0040	mg	08-NOV-93	10-NOV-93



4311048

3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245 Fax: (707) 763-4065

**SAMPLE CHAIN OF CUSTODY / WORK ORDER**

**Client's Name** THRIFTY OIL CO. **Phone** (219) 923-8116

### Phone

(210) 923-9876

Address 10000 LAKEWOOD BLVD.  
City, State, Zip BOWMEY CA 90240

**Client's or Representative's Signature**

(Signature authorizes the work and terms listed below)

**All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.**

**PART ONE - CLIENT COPY**



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

---

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

November 29, 1993

Customer Project: SS # 054  
Laboratory Job: L9311174

On November 18, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene (Niosh 1501)

*Nilla Harris*

Project Manager

*Robert Peak*

Laboratory Director  
Robert Peak

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS # 054  
Sample Id: EFFLUENT  
Lab Id: L9311174-1

Collected: 22-NOV-93  
Received: 18-NOV-93  
Reported: 29-NOV-93

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
AIR	1.00	-	L	22-NOV-93	24-NOV-93
FRONT	<	0.0040	mg	22-NOV-93	24-NOV-93
BACK	<	0.0040	mg	22-NOV-93	24-NOV-93
TOTAL	<	0.0040	mg	22-NOV-93	24-NOV-93
mg/m <sup>3</sup>	<	4.0	mg/m <sup>3</sup>	22-NOV-93	24-NOV-93
BENZENE	<	1.3	ppm	22-NOV-93	24-NOV-93

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS # 054  
Sample Id: TRIP BLANK  
Lab Id: L9311174-2

Collected: 22-NOV-93  
Received: 18-NOV-93  
Reported: 29-NOV-93

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
FRONT	<	0.0040	mg	22-NOV-93	24-NOV-93
BACK	<	0.0040	mg	22-NOV-93	24-NOV-93
TOTAL	<	0.0040	mg	22-NOV-93	24-NOV-93



L9311174

3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245 Fax: (707) 763-4065

## **SAMPLE CHAIN OF CUSTODY / WORK ORDER**

Client's Name THRIFTY OIL CO Phone (310) 423-1816  
Address 1000 LAKEWOOD BLVD

Address 1000 Linewood Blvd  
BALTIMORE MD 21205

City, State, Zip BROWNSVILLE TX 78562

EUGENIU GASNI

Client's or Representative's Signature EUGENIU GASMAN

(signature authorizes the work and terms listed below)

All samples remain the property of the client.

All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

---

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

December 16, 1993

Customer Project: SS # 054  
Laboratory Job: L9312025

On December 2, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene - Niosh 1501 (Niosh 1501)

*Stella Hanks*

Project Manager

*Robert Peak*

Laboratory Director  
Robert Peak

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS # 054  
Sample Id: EFFLUENT  
Lab Id: L9312025-1

Collected: 01-DEC-93  
Received: 02-DEC-93  
Reported: 14-DEC-93

Parameter	Value	Unit	Units	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>					
AIR VOLUME	1.0	-	L	08-DEC-93	10-DEC-93
Front	<	0.0040	mg	08-DEC-93	10-DEC-93
Back	<	0.0040	mg	08-DEC-93	10-DEC-93
Total	<	0.0040	mg	08-DEC-93	10-DEC-93
mg/m <sup>3</sup>	<	4.0	mg/m <sup>3</sup>	08-DEC-93	10-DEC-93
BENZENE	<	1.3	ppm	08-DEC-93	10-DEC-93

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS # 054  
Sample Id: TRIP BLANK  
Lab Id: L9312025-2

Collected: 01-DEC-93  
Received: 02-DEC-93  
Reported: 14-DEC-93

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501: BENZENE</b>					
Front	<	0.0040	mg	08-DEC-93	10-DEC-93
Back	<	0.0040	mg	08-DEC-93	10-DEC-93
Total	<	0.0040	mg	08-DEC-93	10-DEC-93



~~3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024~~  
Telephone: (707) 763-8245 Fax: (707) 763-4085

**SAMPLE CHAIN OF CUSTODY / WORK ORDER**

Phone (310) 923-9876

Client's Name THRIFTY OIL CO.  
18000 LAKEWOOD BLVD

Address 18000 E. 10th Street, Downey, CA 90240  
City State Zip

City, State, Zip STATE EUGENIU GAFMAN Eugeniu Gafman  
 Representative's Signature

**Client's or Representative's Signature** \_\_\_\_\_

(signature authorizes the work and terms listed below)

Items remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails

All samples remain the property of the client who is responsible for  
to pick up samples.

SAMPLES RECEIVED IN GOOD CONDITION  
NO BROKEN OR LEAKING CONTAINERS

CODER CUSTODY SEALS INTACT  NOT INTACT

COLDER TEMPERATURE COLD °C

2 CHAR. TUBES - FedEx

Relinquished by: (Signature)

34

TIME

**Received by:** (Signature)

Enclosed herewith by: (Signature)

Da

TIME

Received by: (Signature)

*(Signature)*

DA

TIME

Received by: (Signature)

General Remarks: SEND RESULT OF ANALYZES TO:  
KARL KERNER 10000 LAKEWOOD DR.  
BOWNEY CA 90221  
PLEASE SEND COPIER + 1 COPY OF  
ANALYZES TO:  
1250 N WILSON WAY  
SACRAMENTO CA 95205  
TAKLE YC



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

January 3, 1994

Customer Project: SS # 054  
Laboratory Job: L9312165

On December 16, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene - Niosh 1501 (Niosh 1501)

Stella Hanus  
Project Manager

Robert Peak  
Laboratory Director  
Robert Peak

**RECEIVED**

DEC 6 1994

EARTH MANAGEMENT CO

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS # 054  
Sample Id: EFFLUENT  
Lab Id: L9312165-1

Collected: 15-DEC-93  
Received: 16-DEC-93  
Reported: 30-DEC-93

Parameter	Value	Unit	Unit	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
AIR	1.00	-	L	28-DEC-93	30-DEC-93
FRONT	▲	0.0050	mg	28-DEC-93	30-DEC-93
BACK	▲	0.0050	mg	28-DEC-93	30-DEC-93
TOTAL	▲	0.0050	mg	28-DEC-93	30-DEC-93
mg/M <sup>3</sup>	▲	5.0	mg/m <sup>3</sup>	28-DEC-93	30-DEC-93
BENZENE	▲	1.6	ppm	28-DEC-93	30-DEC-93

## DBM Laboratories


## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS # 054  
Sample Id: TRIP BLANK  
Lab Id: L9312165-2

Collected: 15-DEC-93  
Received: 16-DEC-93  
Reported: 30-DEC-93

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
FRONT	<	0.0050	mg	28-DEC-93	30-DEC-93
BACK	<	0.0050	mg	28-DEC-93	30-DEC-93
TOTAL	<	0.0050	mg	28-DEC-93	30-DEC-93





3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245  
FAX (707) 763-4065

---

Michael Cosby  
Thrifty Oil Company  
10,000 Lakewood Blvd.  
Downey, CA 90240

January 5, 1994

Customer Project: SS#054  
Laboratory Job: L9312258

On December 30, 1993 we received 2 sample(s) for analysis.  
Samples were analyzed by the following method(s):

Benzene - Niosh 1501 (Niosh 1501)

Project Manager

Laboratory Director  
Robert Peak

**RECEIVED**

DEC 7 1994

EARTH MANAGEMENT CO.

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS#054  
Sample Id: EFFLUENT  
Lab Id: L9312258-1

Collected: 29-DEC-93  
Received: 30-DEC-93  
Reported: 05-JAN-94

Parameter	Value	Unit	Unit	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
AIR	1.00	-	L	03-JAN-94	03-JAN-94
FRONT	<	0.0050	mg	03-JAN-94	03-JAN-94
BACK	<	0.0050	mg	03-JAN-94	03-JAN-94
TOTAL	<	0.0050	mg	03-JAN-94	03-JAN-94
mg/M3	<	5.0	mg/m3	03-JAN-94	03-JAN-94
BENZENE	<	1.6	ppm	03-JAN-94	03-JAN-94

## D&amp;M Laboratories

## ANALYTICAL DATA REPORT

Prepared for: Thrifty Oil Company  
Project Id: SS#054  
Sample Id: TRIP BLANK  
Lab Id: L9312258-2

Collected: 29-DEC-93  
Received: 30-DEC-93  
Reported: 05-JAN-94

Parameter	Value	Limit	Units	Extracted	Analyzed
<b>NIOSH 1501-BENZENE</b>					
FRONT	<	0.0050	mg	03-JAN-94	03-JAN-94
BACK	<	0.0050	mg	03-JAN-94	03-JAN-94
TOTAL	<	0.0050	mg	03-JAN-94	03-JAN-94



3700 Lakeville Highway, Petaluma, CA 94954  
P.O. Box 808024, Petaluma, CA 94975-8024  
Telephone: (707) 763-8245 Fax: (707) 763-4085

Telephone: (707) 783-8245 Fax: (707) 783-4085

*Review by ...*

## **SAMPLE CHAIN OF CUSTODY / WORK ORDER**

Client's Name 7HRIFTY OIL CO Phone (310) 923-9876

Phone (310) 923-9876

Client's Name 10000 LAKEWOOD BLVD  
Address 10000 LAKEWOOD BLVD

Address 1000  
City, State, Zip DOWNEY CA 90240

Client's or Representative's Signature E. GASMAN Josephine Hartney

**Client's or Representative's Signature**  
(signature authorizes the work and terms listed below)

All samples remain the property of the client who is responsible for disposal. A disposal fee may be imposed if client fails to pick up samples.

Relinquished by: (Signature) DATE TIME Received by: (Signature)  
RELEASER CUSTODY SEALS INTACT  NOT INTACT

Angie Horning 12/27/93 12:30 Chesty Cockeyham COOLER CUSTODY SEALS INTRODUCED NOT INVOLVED  
TEMPERATURE COLD °C

Relinquished by: (Signature) DATE TIME Received by: (Signature) COOLER TEMPERATURE 100.5

~~REASON FOR ROAD CONSTRUCTION~~

SAMPLES RECEIVED IN GOOD CONDITION  
NO BROKEN OR LEAKING CONTAINERS